# PHASE I ENVIRONMENTAL SITE ASSESSMENT

# for

# 1 Vine Street
# Larchmont, New York

***Prepared for:***

**One Vine LLC**
**402 Halstead Avenue, Suite 505**
**Harrison, New York 10528**

***Prepared by:***

**Langan Engineering, Environmental, Surveying,**
**Landscape Architecture and Geology, D.P.C.**
**201 Old Country Road, Suite 208**
**Melville, New York 11747**

**Matthew Del Balzo**
**Senior Project Manager**

**Robert Kovacs, PG, LSRP**
**Senior Associate**

**Report Date:** **28 April 2026**
**180-Day Viability Date:** **3 October 2026**
**192019101**

LANGAN

# TABLE OF CONTENTS

**EXECUTIVE SUMMARY** **i**

**1. Introduction** **1**

1.1 PURPOSE 1

1.2 SCOPE OF SERVICES 1

1.3 USER RESPONSIBILITIES 2

1.4 LIMITING CONDITIONS/DEVIATIONS 3

1.5 DATA GAPS 3

**2. Subject Property Description and Current Use** **4**

2.1 LOCATION, LEGAL DESCRIPTION, AND OWNERSHIP 4

2.2 PHYSICAL SETTING 4

2.3 SUBJECT PROPERTY DESCRIPTION 5

2.4 CURRENT SUBJECT PROPERTY USE 5

2.5 HAZARDOUS SUBSTANCES AND PETROLEUM PRODUCTS 5

2.6 AIR EMISSIONS 7

2.7 WASTE MANAGEMENT 8

2.8 WASTEWATER 8

2.9 STORMWATER 9

**3. Subject Property History and Records Review** **10**

3.1 HISTORICAL SUMMARY 10

3.2 REGULATORY DATABASE REVIEW 10

3.3 PRIOR REPORT REVIEW 12

**4. Adjoining Properties and Surrounding Area** **15**

4.1 CURRENT USE OF ADJOINING PROPERTIES AND SURROUNDING AREA 15

4.2 ADJOINING PROPERTIES AND SURROUNDING AREA HISTORY 15

4.3 REGULATORY DATABASE REVIEW 16

**5. Conclusions, Findings and Opinions** **18**

**6. Environmental Professional Statement** **20**

**7. References** **21**

**8. Limitations and Definitions** **22**

8.1 ASTM DEFINITIONS 22

8.2 STANDARD ENVIRONMENTAL RECORD SOURCES 25

## TABLES

Table ES-1 Conclusions, Findings and Opinions
Table 2-1 Utility Providers
Table 3-1 Subject Property History
Table 4-1 Current Use of Adjoining Properties and Surrounding Area
Table 4-2 Historical Use of Adjoining Properties
Table 5-1 Conclusions, Findings and Opinions
Table 7-1 Dates of Assessment Components

## APPENDICES

Appendix A Figures
Figure 1 Subject Property Location Map
Figure 2 Subject Property Layout
Figure 3 Nearby Properties Map
Appendix B Agency Records and Other Reports
Appendix C Site Reconnaissance Checklist and Photographs
Appendix D User Provided Information
Appendix E Historical Resources
Appendix F Environmental Database Report
Appendix G Resumes of Environmental Professionals

## EXECUTIVE SUMMARY

Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C. (Langan) completed a Phase I Environmental Site Assessment (ESA) of the property located at 1 Vine Street, Larchmont, in the Town of Mamaroneck, Westchester County, New York (the "subject property") under the written authorization of One Vine LLC ("Client" and the "user").

The Phase I ESA was completed following the guidelines of ASTM International Standard Practice E1527-21 (ASTM E1527-21), the United States Environmental Protection Agency's (US EPA) All Appropriate Inquiries (AAI) Rule, and industry standard practice. The user requested this ESA as part of their environmental due diligence related to a potential transaction involving the subject property.

*Subject Property Layout*

The subject property is about 0.34 acres and occupied with a single-story building, with a three partial basements, and an asphalt- and concrete-paved parking lot on the southern side of the site. The building is primarily utilized as an autobody garage, with the parking lot also utilized by the garage. The autobody shop occupied the eastern and central areas of the building and contains repair bays, storage areas, a paint booth, offices, and restrooms. The western side of the building is developed as a separate commercial unit and was formerly operated as a drycleaner and is partially utilized by an artist as a private workspace.

*Subject Property Current Use*

The subject property is presently utilized as an autobody garage. Operations consist of general automotive service, repair, and maintenance, including painting operations. Various chemicals are utilized on-site in association with automotive services, including motor oil, brake cleaners, lubricants, antifreeze, and solvents among others.

*Subject Property History*

The subject property was partially developed with a shed in the 1911 fire insurance map and appeared to be otherwise undeveloped or utilized for agricultural purposes through the 1920s. The subject property was fully developed by 1930 with the current building, which was depicted as an auto repair garage and retail stores, along with two gasoline underground storage tanks (USTs) in the present area of Vine Street, to the south of the subject property. The building was modified to the present layout by 1947: The central retail stores were removed and redeveloped as the central parking lot, which was then utilized for two fuel dispensers and was depicted with three gasoline USTs in the 1950 fire insurance map. Per the city directories, the western retail unit was occupied by a drycleaner between 1963 and 2022 and was vacant since about 2024. The fuel dispensers and associated USTs were removed in 2015 and the fuel dispenser area was converted to the present parking lot.

*Adjoining Properties and Surrounding Area*

The surrounding area was developed with a railroad and train station to the east and was otherwise mainly undeveloped in the topographic maps in the late 1800s and early 1900s. During the 1910's some small dwellings and sheds were present, per the 1919 fire insurance map; however, these structures were removed by the 1930s. The area to the south was developed as a municipal park by 1934, now known as Memorial Park, based on the fire insurance maps. The New England Thruway (Interstate-95) was constructed to the east by 1955 according to the

topographic maps. The areas to the north and west of the subject property were developed with a municipal parking lot by the 1960s based on the aerial photographs. By 1962, the surrounding areas appear generally similar to the present day, and were developed with residences, additional parking lots, and parks.

*Conclusions*

Langan completed a Phase I ESA of the subject property using the scope guidelines and inherent limitations of ASTM E1527-21. Table ES-1 presents the conclusions of the Phase I ESA.

**Table ES-1 Conclusions, Findings and Opinions**

| **ASTM E1527-21 Scope Items** |
|---|
| **Recognized Environmental Conditions (RECs)** |
| *Underground Storage Tanks (USTs) and Petroleum Bulk Storage:* The subject property was registered for six closed and removed USTs, including five gasoline tanks and one diesel tank. Separately, an abandoned UST is reported to exist in the central area of the autobody garage. A sample was collected near this location by Pennoni Associates Inc. (PAI) which identified impacts of volatile organic compounds (VOCs), semivolatile organic compounds (SVOCs), and metals. It is unclear if a UST remains in this area and if the tank is related to the impacts in this area. Furthermore, there two additional USTs were identified on the 1934 fire insurance map, just outside of the subject property boundary, and three more gasoline USTs in the central parking lot area in the 1963 fire insurance map. While the USTs in the parking lot have likely been removed, it is unclear if any of the other USTs have been removed and if any of the USTs have impacted the subsurface. The potential USTs and associated impacts pose a REC. |
| *Contamination from automotive-related operations and historic drycleaning:* The subject property has been utilized for automotive repair, service, and maintenance since the 1930s and has also operated as a gasoline station and carwash during part of that time. The western commercial unit in the building operated as a drycleaner from about 1963 through 2024. Langan observed a cloudy to white sheen on standing water in the basement beneath the former drycleaner, which may be attributed to former drycleaning operations. In a previous Phase II ESA by PAI, impacts related to automotive-related chemicals were identified in soil and groundwater and impacts from drycleaning-related chemicals were identified in soil, soil vapor, and groundwater. The on-going and former operations at the subject property have been documented to have impacted the subsurface. Therefore, due to the documented impacts to the subsurface, the historical operations at the subject property pose a REC. |
| **Controlled Recognized Environmental Conditions (CRECs)** |
| Langan did not identify CRECs. |
| **Historical Recognized Environmental Conditions (HRECs)** |
| Langan did not identify HRECs. |
| **De Minimis Conditions** |
| *Staining and housekeeping*: Apparent petroleum and paint staining was observed throughout the autobody garage. Absorbents were inconsistently applied to stained areas and absorbents were observed left out on the floor. Poor housekeeping, including staining throughout the garage and unremoved absorbents, poses a de minimis condition. |

| **ASTM E1527-21 Scope Items** |
|---|
| **Non-ASTM E1527-21 Scope Items** |
| **Business Environmental Risks (BERs)** |
| *Non-Native Fill*: Based on previous investigation, the subject property is underlain by a layer of non-native fill. Non-native fill found in urban environments typically contains ash, demolition debris, and/or municipal waste products and may contain contaminants (e.g., SVOCs or metals) at concentrations above applicable regulatory standards. The occurrence of non-native fill may require implementation of soil handling and management procedures during site redevelopment to address excavation, re-use, handling, and off-site disposal, and may result in incremental costs above the baseline development value, specifically associated with transportation and disposal of excess soil generated during foundation excavation. |

# 1. INTRODUCTION

Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C. (Langan) completed a Phase I Environmental Site Assessment (ESA) of the property located at 1 Vine Street, Larchmont, in the Town of Mamaroneck, Westchester County, New York (the "subject property") under the written authorization of One Vine LLC (the "Client" and the "user"). A Subject Property Location Map is provided in Appendix A (Figure 1).

The Phase I ESA was completed following the guidelines of ASTM International Standard Practice E1527-21 (ASTM E1527-21), the United States Environmental Protection Agency's (US EPA) All Appropriate Inquiries (AAI) Rule, and industry standard practice. The user requested this ESA as part of their environmental due diligence associated with a potential transaction involving the subject property.

## 1.1 Purpose

The purpose of this Phase I ESA is to identify recognized environmental conditions (REC) associated with the subject property. This purpose also includes identifying controlled recognized environmental conditions (CREC), historical recognized environmental conditions (HREC), de minimis conditions, and significant data gaps. The definitions of REC, CREC, HREC, de minimis condition and other select ASTM terms used in this report are in Section 8.

## 1.2 Scope of Services

Langan's scope of services consisted of the completion of a Phase I ESA following the guidelines of ASTM E1527-21. Langan's scope of services as it pertains to the elements of a Phase I ESA as specified in ASTM E1527-21 is described below.

CERCLA hazardous substances and petroleum products have been detected in background environmental samples across the globe, including in areas removed from specific recognized sources. This Phase I ESA was not intended to evaluate background concentrations of CERCLA hazardous substances or petroleum products, regardless of whether the source is naturally occurring or anthropogenic. The objective of Langan's scope of services was to identify the presence, likely presence, and/or material threat of a release of CERCLA hazardous substances and petroleum products related to specific property uses that are generally recognized as known or potential sources of such substances and products.

### *1.2.1 Records Review and Local Government Interviews*

Langan contracted a third-party provider to search environmental regulatory databases and provide historical records. The database search included select federal, state, local and tribal standard source environmental databases within the approximate search radii specified by ASTM E1527-21.

Langan submitted public records requests to supplement environmental database listing information. The public records requests were submitted to the Westchester County Department of Health, Town of Mamaroneck Town Supervisor, the New York State Department of Health (NYSDOH), and the New York State Department of Environmental Conservation (NYSDEC). Langan also reviewed online records including the Town of Mamaroneck Real Property Open Search tool, United States Geological Survey (USGS) mapping, and US EPA databases. Agency-

requested information, where received and applicable, is discussed in relevant sections of this report and referenced in Section 7. Pertinent documents are provided in Appendix B.

Langan supplemented the third-party-provided historical records with review of online historical record sources including Google Earth Pro and the Town of Mamaroneck Assessor Property Record Online System.

#### *1.2.2 Site Reconnaissance and Owner/Operator/Occupant Interviews*

Langan completed the site reconnaissance on 13 April 2026. Vincent Sparano (property owner and manager for J&F Chadsworth; the "key site manager") accompanied Olivia Miller of Langan during the site reconnaissance. Mr. Sparano is the owner and occupant of the subject property. Mr. Sparano has been associated with the subject property since the 1980s.

Langan walked the periphery of the subject property, observed the subject property from adjoining public thoroughfares, and walked the accessible interiors of structures at the subject property. Langan observed the adjoining properties and the surrounding area from the periphery of the subject property and from public thoroughfares adjoining to or traveled on to access the subject property. The weather at the time of the site reconnaissance was approximately 63°F and sunny. Photographs from the site reconnaissance are provided in Appendix C.

Langan interviewed Mr. Sparano during the site reconnaissance, and was provided a complete User Questionnaire from Gary Hirsch. Langan also requested that Mr. Hirsch provide copies of available documents pertinent to environmental conditions at the subject property. Langan did not identify past owners, operators, or occupants of the subject property likely to have material, non-duplicative information regarding the subject property, and did not interview any past owners, operators, or occupants of the subject property.

#### *1.2.3 Evaluation, Report and Parts Used in Concert*

Langan evaluated the information obtained from the records reviews, site reconnaissance and interviews described above, and from the user as described in Section 1.3 in concert with each other. Langan's findings, opinions, and conclusions are discussed throughout this report. Significant assumptions, or deletions, deviations or exceptions to ASTM E1527-21 are noted in Section 1.4.

#### *1.2.4 Non-ASTM Scope Services*

The scope of services for the Phase I ESA did not include non-scope ASTM considerations.

### 1.3 User Responsibilities

Langan requested that the user provide the results of tasks the user is responsible for completing to satisfy the requirements of AAI. The tasks include: searching for known environmental liens and activity and use limitations (AULs) filed or recorded against the subject property, and provision of information related to specialized knowledge or experience of the user or the degree of obviousness relative to conditions indicative of releases or threatened releases; actual knowledge of the user regarding environmental liens or AULs related to the subject property; specialized knowledge or experience of the user; reasons for significantly lower purchase prices, and commonly known or reasonably ascertainable information within the local community about the subject property. Langan also requested that the user state the reason the Phase I ESA was requested. A summary of the user's responses is provided in Appendix D and relevant

information provided by the user is discussed in applicable sections of this report.

Unless specifically included in the scope of services, Langan did not complete a title search or a search for environmental liens or AULs, as that is the responsibility of the user. If the user requested that Langan complete such searches on the user's behalf, the information was supplied to Langan by a vendor, and to the vendor by government sources; therefore, neither Langan nor the vendor can verify the completeness or accuracy of the title search, or AUL searches.

## 1.4 Limiting Conditions/Deviations

Langan was unable to observe the full basement due to standing water in the basement area. Portions of the basement were observed from the ground-level area. This limiting condition did not appear to impact Langan's conclusions based on information from the key site manager, who reported that the basement was empty and only contained access to plumbing for the restrooms. Therefore, this limiting condition did not impact Langan's conclusions.

Langan did not delete or deviate from the ASTM E1527-21 guidelines during this Phase I ESA.

## 1.5 Data Gaps

Several anomalies were observed in the concrete floor during the Phase I site reconnaissance. The key site manager was asked about these but was not familiar with their original purpose or what existed beneath the anomalies. This did not appear to impact the conclusions of the report based on other information obtained regarding the site. Significant data gaps, if any, are summarized in Section 5.0.

# 2. SUBJECT PROPERTY DESCRIPTION AND CURRENT USE

The following sections describe the subject property location, ownership, physical setting, and current layout and operations.

## 2.1 Location, Legal Description, and Ownership

The about 0.34-acre subject property is located to the north of Vine Street, to the east of the New England Thruway (Interstate-95) and approximately 150 feet east of Myrtle Boulevard. The subject property is described by the Town of Mamaroneck Assessor with Parcel ID 1-26-730 and is associated with the addresses of 1 to 5 Vine Street. A legal description of the subject property is provided on the property record card in Appendix E. The subject property is owned by Mansisbro Inc.

## 2.2 Physical Setting

The physical setting that includes the geologic, hydrogeologic, hydrologic, and topographic characteristics of the subject property and surrounding area is discussed below.

### *2.2.1 Topography*

The 2023 USGS 7.5-minute quadrangle topographic map for Mount Vernon, New York depicts the subject property at an elevation of approximately 41 feet above mean sea level (amsl) with a gentle slope downward toward the south-southeast. The regional topography slopes downward toward the southeast and Monroe Inlet and into the Long Island Sound, which is located approximately 1 mile southeast of the subject property.

### *2.2.2 Geology*

According to the U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) Soil Survey Geographic (SSURGO) data for Westchester County, soils at the subject property consist primarily of urban land. Urban land has typically been mixed with anthropogenic materials, such as brick, concrete, and demolition debris of unknown origin. well-drained sands and gravels with high infiltration rates.

According to the Geologic Map of New York, Lower Hudson Sheet, the subject property is in the Hartland Formation, which consists of basal amphibolite overlain by pelitic schists. An apparent rock outcrop was observed about 400 feet to the southwest and is likely shallow in the area of the subject property.

### *2.2.3 Hydrogeology*

Surface water bodies are not present within the boundary of the subject property. The nearest surface water bodies are the Premium River, about 1 mile to the south, and Monroe Inlet and the Long Island Sound about 1 mile to the southeast. Information regarding subject property-specific groundwater flow direction is unavailable. Groundwater flow can be influenced by several factors such as surface water bodies, wetlands, hydrogeologic and anthropogenic variables. However, based on topographic gradient and proximity to Monroe Inlet and the Long Island Sound, it is expected that groundwater generally flows to the southeast.

A review of the Geocheck section of the LightBox Environmental Data Resources (EDR) Regulatory Database Report (Appendix F) and site reconnaissance observations identified two

monitoring wells on the subject property. One well was located along the southern perimeter, near the southern corner of the subject property, and was reported to have been there for about 20 years. The other well was located on the western side of the central parking lot and was reportedly installed during a Phase II investigation from earlier in 2026. The EDR report did not identify any wells within 0.5-mile radius of the subject property.

## 2.3 Subject Property Description

The subject property is improved with an about 12,000-square-foot building, with a partial basement. The eastern and central area of the building are developed with an autobody garage and contain repair bays, offices, storage areas, a spray booth, and restrooms. The western part of the building is developed with a separate commercial unit, which is partially utilized by an artist as a private workshop and was formerly utilized as a drycleaner. The partial basement is located under both units of the building and was reported to contain utility rooms. The central and southern area of the subject property is developed with a concrete- and asphalt-paved parking lot.

The subject property is fully occupied by the building and inner parking lot and accessed from Vine Street to the south.

A Subject Property Layout Map is provided in Figure 2 of Appendix A. Photographs of the subject property and a checklist documenting Langan's observations relative to the features, activities, uses and conditions outlined in Section 9.4 of ASTM E1527-21 are in Appendix C.

## 2.4 Current Subject Property Use

The autobody garage currently does automotive service, repairs, and maintenance, including painting operations. Various chemicals are utilized on-site in association with the automotive services, including primarily motor oil, as well as brake cleaners, lubricants, antifreeze, and solvents. The western commercial unit is partially utilized by an artist as a private workshop and was most recently utilized as a drycleaner.

The following table summarizes subject property utility providers.

**Table 2-1 Utility Providers**

| Utility | Providers |
|---|---|
| Electricity (used for cooling) | Con Edison |
| Natural gas (used for heating) | Con Edison |
| Water | Westchester Joint Water Works |
| Sewer | Town of Mamaroneck Highway Department |

## 2.5 Hazardous Substances and Petroleum Products

Hazardous substance and petroleum product use at the subject property is primarily related to equipment maintenance and service. Langan observed hazardous substances and petroleum products stored in dedicated areas in the maintenance building. Langan did not observe evidence of leaks, spills, pools of liquid or releases such as staining, or sheens, other than as described below.

### *2.5.1 Underground Storage Tanks (USTs)*

The key site manager reported that there was an abandoned UST in the central garage space. An apparent sealed fill port was observed in the area described by the key site manager. It was unknown what the tank previously contained and if the tank was properly closed.

The EDR database report identified the subject property as an active PBS site under PBS No.-3-174394 and was registered for six closed-removed USTs: Two 4,000-gallon gasoline tanks installed in 1995 and removed in 2015; three 2,000-gallon gasoline tanks and a 2,000-gallon diesel tank, all installed in 1981 and removed in 1995. The cut-down vent pipes were observed along the southern exterior of the garage, on the northern side of the parking lot. A closure report was provided for the 2015 removal of the two 4,000-gallon USTs. An NYSDEC Spill incident was reported due to elevated photoionization detector (PID) readings from soil in the excavation; however, the USTs were reported to be in good condition and were contained within a previous concrete foundation. No closure documentation was provided regarding the four USTs removed in 1995.

Additional USTs were identified in the fire insurance maps: The 1919 fire insurance map noted two underground gasoline tanks in the area of Vine Street, just south of the subject property, which were associated with the autobody garage. These tanks were not present in the 1934 fire insurance map; however, no removal documentation was provided. Furthermore, the fire insurance maps from 1950 through 1963 depicted three underground gasoline USTs in the central parking lot area. These USTs have likely been replaced by the previously mentioned closed-removed USTs; however, no closure documentation was available.

The potential of existing USTs and impacts from present or former USTs the subject poses a REC.

### *2.5.2 Aboveground Storage Tanks (ASTs)*

Langan observed four petroleum ASTs at the subject property. An active 250-gallon motor oil AST was present in the eastern part of the autobody garage. An active 250-gallon waste oil AST and second active 250-gallon motor oil AST were present along the rear wall of the autobody garage and are surrounded by a concrete berm for secondary containment. A fourth AST, an about 75-gallon hydraulic oil AST was observed along the rear wall of the autobody garage. The hydraulic oil AST is out-of-service and previously supplied the in-ground lifts in the autobody garage.

Langan did not observe significant staining in the areas of the ASTs.

### *2.5.3 Drums, Totes, and Intermediate Bulk Containers*

Langan observed the following in the autobody garage:

- Automotive chemicals, in retail size (about 1-gallon or less) to five (5) gallon totes or drums, including antifreeze-coolant, lubricant, compressed air, motor oil, battery cleaner, brake cleaner, hydraulic fluid, windshield washer fluid, spray wax, water-based dressing, rubbing compound, rubberized undercoat paint, degreaser, compressor fluid, uniform finish blender, paint protectant, spray paint, paint thinner, topcoat, topcoat hardener, and isopropyl alcohol
- Several empty 5-gallon gasoline cans

- Two partially full 55-gallon steel waste paint drums
- Seventeen 55-gallon plastic drums for waste oil, all empty except for three drums which were partially full
- Three 150-cubic-foot cylinders of acetylene
- Two 25-pound cylinders of refrigerant

Langan observed the following in the drycleaning unit:

- Empty 30-gallon tote of unspecified toxic material, presumably for drycleaning chemicals or related dry-cleaning materials like machine filters

Langan observed the drums and containers to be intact, without obvious indications of a release or material threat of a future release. Drums containing hazardous waste are discussed in Section 2.7.1.

### *2.5.4 Other Chemical Storage, Containers, or Equipment*

Langan observed shelves and storage cabinets containing retail-size containers of maintenance-related products and janitorial products in the offices, drycleaning unit, and around the autobody garage.

Langan observed the following fluid-containing equipment:

- A ceiling-vaulted waste oil-fired boiler in the northern and central area of the autobody garage
- Two former in-ground hydraulic lifts were present in the autobody garage, one in the southern and eastern area of the garage and one in the northern and central area of the garage.
- Multiple above-ground hydraulic lifts were present in the autobody garage
- A parts washer was present in the eastern area of the autobody garage
- A drycleaning machine was present on the northern side of the drycleaning unit.

Additionally, a spray booth was present in the northern and western area of the autobody garage.

No significant staining was observed near maintenance or janitorial products, the above-mentioned fluid-containing equipment, or the spray booth. However, apparent petroleum and paint staining was observed throughout the autobody garage. Absorbents were inconsistently applied to stained areas and absorbents were observed left out on the floor. Poor housekeeping, including staining throughout the garage and unremoved absorbents, pose a de minimis condition.

## 2.6 Air Emissions

Air emission sources at the subject property include a paint booth with filtration system and natural gas and fuel oil-fired boiler units. Langan did not identify obvious impacts, such as visible emissions or odors, from air emission sources at the subject property.

Langan does not consider the air emissions an environmental concern for the subject property.

## 2.7 Waste Management

The following sections describe current hazardous and non-hazardous waste streams, and observations of fill areas or other solid waste throughout the subject property.

### *2.7.1 Hazardous Waste*

Waste automotive paints are stored in 55-gallon steel drums on the western side of the autobody garage. Two drums were present on the western side of the garage and are picked up for off-site disposal by a waste hauler. Langan observed the drums to be intact without obvious indications of a release or material threat of a future release. Historical hazardous waste generation is discussed further in Section 3.2.

### *2.7.2 Non-Hazardous Waste*

Non-hazardous waste generated at the subject property includes used oil, filters for the paint booth, and general refuse. According to the key site manager, general refuse is collected in typical trash cans and picked up twice a week through the Town of Mamaroneck. Langan observed the 250-gallon AST for waste oil and several 55-gallon drums stored near the AST for storing extra waste oil. This waste oil is used in the waste oil-fired boiler in the autobody garage. If any additional waste oil is leftover after the winter, it will be picked up by Safety Kleen. Filters for the paint booth are stored in garbage bags until pickup by a waste contractor for off-site disposal. A parts washer was present in the eastern area of the autobody garage and was reportedly serviced by Safety Kleen about every three months. Langan observed the non-hazardous waste containers to be intact without obvious indications of a release or material threat of a future release.

### *2.7.3 Fill Areas or Solid Waste*

Langan did not observe areas that were apparently filled or graded by non-natural causes (or filled with material of unknown origin) that suggest the presence of garbage, construction debris, demolition debris, or other solid waste disposal, or mounds or depressions suggesting solid waste disposal.

## 2.8 Wastewater

Sanitary and process wastewater are discharged to the Town of Mamaroneck municipal sanitary sewer system. The key site manager stated that, to the best of his knowledge, the building was connected to the sewer at the time of their construction. Langan observed two drains, one in the eastern bay of the autobody garage and one in a utility closet in the drycleaning unit. No stains or odors were observed in or near the floor drains. A system of apparent former floor drains was observed in the autobody garage which had been filled with concrete. It was unknown where these drains previously discharged to. The key site manager reported that they had been that way since his family was affiliated with the property in the 1980s.

Langan did not observe or identify evidence of septic systems or cesspools at the subject property.

## 2.9 Stormwater

Stormwater at the subject property sheet flows to the adjoining roadways into the municipal storm sewer system. Langan did not observe evidence of impact (e.g., sheens, staining) to stormwater pathways.

# 3. SUBJECT PROPERTY HISTORY AND RECORDS REVIEW

The following sections provide summaries of the historical uses of the subject property, and available information regarding documented environmental conditions associated with the historical uses.

## 3.1 Historical Summary

Langan compiled the following summary of the subject property history based on a review of readily available and reasonably ascertainable sources and interviews. Historical resources are provided in Appendix E.

**Table 3-1 Subject Property History**

| Time Period | Historical Discussion |
|---|---|
| 1890 – 1920s | The subject property is depicted as undeveloped on topographic maps or the earliest fire insurance map from 1911. The subject property was depicted with part of a shed in the 1919 fire insurance map. The subject property was possibly undeveloped or utilized for agricultural purposes. |
| 1930 – 1942 | According to the property records from the Town of Mamaroneck, the building at the subject property was constructed in 1930 and was present on the 1934 fire insurance map. The building was depicted as an auto repair garage and with seven commercial store units along Vine Street. Additionally, two gasoline USTs were depicted in the area of Vine Street, to the south of the subject property. These gasoline tanks were not present on the proceeding fire insurance maps. |
| 1947 – 2013 | The subject property building observed in the 1947 aerial photograph and 1947 topographic map and had been modified to the current layout: Six of the inner store units were removed and converted into the central parking lot, which was utilized for two fuel dispensers. The western store unit remained and was depicted as office space. Three underground gasoline tanks were depicted on the fire insurance maps in the parking lot area from 1950 through 1963. According to the city directories, an auto repair garage was present at 1 Vine Street between 1963 and 2024 and a drycleaner was present at 5 Vine Street between 1963 and 2022. The drycleaner was noted on the 1988 fire insurance map, which also noted the auto garage as a car wash. |
| 2015 to Present | Per records from the NYSDEC, fuel dispensers and USTs were removed in 2015. The fuel dispenser area was utilized as a parking lot in the aerial photographs from 2017 through 2024. |

Environmental concerns related to historical operations are discussed further in Section 3.3.

## 3.2 Regulatory Database Review

The subject property was identified in the EDR Database Report under multiple entities (J & F Chatsworth Auto Body/Magic Touch Cleaners/Chatsworth Garage Inc./Masiero Inc./JS Chadworths, J&F Chatsworth Gas Station/J&FChatsworth Ltd./JF Chatsworth/Kim Kwung) and was identified on the Resource Conservation and Recovery Act (RCRA) Small Quantity Generator (SQG), RCRA Non Generator/No Longer Regulated (Non Gen/NLR), Electronic (E) Manifest, NY Manifest, NJ Manifest, Manifest, EDR Historical (Hist) Cleaner, EDR Hist Automotive center (Auto), NY Spills, UST Finder Release, UST, AST, Leaking Storage Tanks (LTANKS), Air Facility System (US AIRS), Federal Index System (FINDS), Environmental Compliance History Online

(ECHO), Air Emissions Data (AIRS), Integrated Compliance Information System (ICIS), and Drycleaners databases.

The RCRA generator listings and manifest listings were associated with the generation and transfer of hazardous waste, including tetrachloroethylene (PCE), trichloroethylene (TCE), lead, chromium, ignitable waste, spent halogenated solvents, non-halogenated solvents, methyl ethyl ketone, and waste fuel oil. These were reportedly generated and transferred between the years of 1988 and 2025. This waste generation was affiliated with the historic and on-going autobody garage operations and the former drycleaning operations at the subject property.

The EDR Hist Cleaner and Drycleaner listings noted a drycleaner at the subject property in 1971 through 2014, and noted the drycleaner utilizing an alternative solvent, CAS 541-02-6, decamethylcyclopentasiloxane, around 2000 through 2002.

The EDR Hist Auto listing noted a gasoline station at the subject property between 1969 and 1985 and a general automotive repair shop at the subject property between 1992 through 2014.

The UST and AST listings were related to an active PBS listing under PBS No. 3-174394:

- Registered for six closed-removed USTs: Two (2) 4,000-gallon gasoline tanks installed in 1995 and removed in 2015; three 2,000-gallon gasoline tanks and a 2,000-gallon diesel tank, all installed in 1981 and removed in 1995.
- Registered for two active ASTs: An active 250-gallon motor oil tank and an active 250-gallon waste oil tank.

The spill incidents are related to the following:

- NYSDEC Spill No. 9102813 was reported on 10 June 1991 when a waste oil tank released 30 gallons of product to the basement of the building. The waste oil was discharged to the sewers through a sump pump in the basement and was reportedly addressed with absorbent pads and barriers. It was noted that an outside company was hired to address the release and facilitate the cleanup. The spill was reported closed on 14 November 1997.
- NYSDEC Spill No. 9410303 was reported on 2 November 1994 for a release of gasoline. The database listing included limited details; however, this spill appeared to be related to a tank overfill, based on the LTANKS listing status and the language in the spill details. The spill noted a "Contractor (Luzon) enroute to clean up" and that the spill was "reportedly completely cleaned up". The spill was reported closed on 2 December 2003.
- NYSDEC Spill No. 9413519 was reported on 10 January 1995 for a release of gasoline due to fuel delivery driver error. A reported quantity of 4 gallons of product was released and cleaned up. No details regarding the cleanup were provided. The spill was reportedly closed on 23 January 1995.
- NYSDEC Spill No. 1501291 was reported on 5 May 2015 for gasoline contamination discovered during the removal of two USTs. The USTs were reported to be in good condition; however, elevated PID levels were detected in the excavation area. The contractor removed 11 tons of impacted soil. The USTs were discovered to be installed within the foundation of a former building in this area and sidewall and endpoint samples were unable to be collected. The spill was reported to be closed on 8 July 2015.

Based on a previous environmental investigation performed at the subject property, contamination associated with the on-going usage of the subject property as an autobody garage, historical usage of the subject property as a gasoline station, and the extensive historical operations as a drycleaner have impacted soil, soil vapor, and groundwater at the subject property. Due to the documented contamination, the on-going and historical operations at the subject property represent a REC. The environmental investigation is discussed in Section 3.3.

## 3.3 Prior Report Review

Langan was provided with prior reports related to UST closure, a Phase I ESA, and a Phase II Environmental Site Investigation (ESI)/ESA, completed in 2015, 2022, and 2026, respectively. The reports are referenced in Section 7 and summarized below.

*Phase II ESA, dated 17 March 2026, by Pennoni Associates Inc. (PAI)*

In 2026, PAI completed a Phase II ESA to address concerns identified in the Phase I ESA from 2022 by American Petroleum (AP). The Phase II ESA investigated soil, installing seven borings around the property, soil vapor, collected three sub-slab gas samples around the property, and groundwater, installing one temporary monitoring well and collecting from an existing well at the subject property.

The soil samples identified exceedances above NYS Part 375 criteria and NYS CP-51 Soil Cleanup Levels for gasoline and fuel oil related compounds, including exceedances in volatile organic compounds (VOCs), including PCE, semi-volatile organic compounds (SVOCs), chromium, and nickel. Only one of the two soil samples collected in the drycleaning unit were evaluated for VOCs. The evaluated sample was collected from a depth of 8.5-10 feet below grade and had an exceedance in PCE.

The soil vapor samples identified "low levels" of VOCs at all three locations; however, the soil samples were limited to 30-minute collection periods. PAI concluded that "There does not appear to be significant soil vapor concern in the locations where soil gas samples were collected." However, PAI did not collect an ambient air sample and a recommendation for soil vapor mitigation cannot be adequately determined from the limited samples collected.

The groundwater sample collected from the temporary monitoring well contained exceedances in PCE, TCE, and other compounds. PAI concluded "Based on the data collected and the presence of the drycleaning VOCs tetrachloroethane, trichloroethene and vinyl chloride at the concentrations detected, we suspect a release may have occurred. Additional data would be necessary to quantify the suspected release condition and determine reporting obligations."

PAI also concluded "Given the presence of VOC and SVOC-PAH [Polyaromatic hydrocarbons] contamination in the groundwater at MW-1, standing water in the basement should be characterized and managed in accordance with NYS DEC discharge requirements."

Based on the detections of drycleaning compounds in soil, soil vapor, and groundwater and various fuel oil constituents in soil and groundwater at the site, the on-going and historical operations at the subject property represent a REC.

Phase I ESA, dated 30 November 2022, by AP

A Phase I ESA was conducted in November 2022 by AP "to evaluate the present environmental status of the site." The Phase I was conducted under similar condition to present; however, the drycleaners was still in operation. The following findings were issued:

- *Duration of Auto Repair: The current structure was constructed in 1930 and has been used as an auto repair shop since construction. The property was also used as a car wash for approximately 50 years.*
- *Floor anomalies in the auto repair shop show evidence of previous auto repair pits.*
- *Three (3) underground lifts within the auto repair shop are not utilized and are reported to be drained.*
- *A reported closed-in place UST is located within the building footprint in the eastern portion of the auto repair shop. No documentation was found or provided.*
- *Floor drains within the auto repair shop have been filled with concrete prior to current ownership. The previous discharge point is unknown. The presence of an oil/water separator is unknown.*
- *Duration of Gas Station: UST removal and remedial activities associated with the gas station were completed in 2015 by American Petroleum.*
- *Duration of Dry Cleaning: Sanborn maps and city directories determine dry cleaning was on site from at least 1979 to the time of inspection. According to the historic property card, the dry cleaner was converted to Green Earth Cleaning Products in 2001.*
- *Significant standing fluid was observed throughout the basement.*

AP issued the following conclusions and recommendations:

***1) An interior ground penetrating radar (GPR) survey is recommended to determine the extent and characteristics of the flooring anomalies within the auto repair shop****. The GPR should include the area of the "closed in-place" UST, as well as all suspected floor drains and any additional undetermined anomalies.*

*3 [2]) Due to the size of the building relative to the size of the property,* ***a vapor intrusion test is warranted to assess the environmental conditions on-site due to historic operations.***

*2 [3]) Further investigation that would discover or characterize contamination of the subject property by hazardous or toxic substances is warranted. Due to the nature of historic operations as an auto repair shop, dry cleaner, and gasoline station, the potential exists for localized areas of impact.* ***A subsurface (Phase II) study is warranted to assess the environmental conditions on-site due to such historic operations.*** *The Phase II should include the area of the lifts. Alternatively, the lifts could be removed. If the Phase II identifies a concern, further work would be required.*

*3 [4]) To maximize sub-surface investigation with minimal obtrusion, preliminary water sampling can be taken from the basement and the active monitoring well on site. APECCP [AP] recommends the discontinued use of basement sump pump until water mixture in basement is analyzed through laboratory sampling. Pump out remaining water mixture within the basement and monitor for intrusion points. Secondary water sampling should occur when/if the basement refills.*

*4 [5]) A full asbestos inspection was not completed. Based on APECCO's [AP's] observations, as suspected ACMs [asbestos-containing materials] were not friable or greatly damaged, the materials can remain in-place. However, should significant renovations or demolition be anticipated, state and federal regulations require an asbestos survey and proper handling and disposal of ACMs.*

*5 [6]) A full lead-based paint inspection was not completed. Based on APECCO's [AP's] limited observations, suspect lead-based paint surfaces were not considered to be peeling or chipping at the time of the site investigation. However, caution is recommended if renovations and/or remodeling of this facility are to take place.*

*6 [7]) A cursory visual assessment for suspect mold was undertaken as a part of this environmental screen. A full mold inspection was not requested nor completed as part of this assessment. Based on APECCO's [AP's] limited observations, visible evidence of possible mold growth and mold related odors were observed in the basement. Visual evidence of mold should be addressed immediately. It is recommended that professional remediation contractors be hired to properly address such issues.*

Langan maintains the first four conclusions: 1, 3 [2], 2 [3], and 3 [4]. The Phase II by PAI did not satisfy all of the concerns addressed in these conclusions.

*UST Removal Report, dated 7 July 2015, by AP*

AP completed a UST Removal Summary Report for the NYSDEC in 2015, regarding the removal of two 4,000-gallon USTs. In May 2015, the two USTs were emptied, cleaned, excavated, inspected, and removed. While the tanks were in good condition, soil in the excavation was reported to have elevated PID levels so the NYSDEC was contacted and a spill number was issued (Spill No. 1501291). The impacted soil was stockpiled and exported off-site. The tanks were discovered to have been installed in the foundation of the previous building in this area and were contained within the foundation and four concrete walls. Due to this, it was reported that no sidewall or endpoint samples could be collected. AP concluded that no further action was warranted and moved to close NYSDEC Spill No. 1501291.

Since the excavated material was reportedly removed, the spill does not pose an environmental concern at this time.

Copies of these reports are provided in Appendix B.

# 4. ADJOINING PROPERTIES AND SURROUNDING AREA

The following sections describe current and historical uses of and database listings for adjoining properties and the surrounding area.

## 4.1 Current Use of Adjoining Properties and Surrounding Area

The current use of adjoining and surrounding properties is summarized in Table 4-1.

**Table 4-1 Current Use of Adjoining Properties and Surrounding Area**

| Direction | Adjoining Properties | Surrounding Area |
|---|---|---|
| **North** | Municipal parking lot (Myrtle Boulevard) (Parcel 1-26-716) | Municipal parking lot and residences |
| **East** | New England Thruway (Interstate-95) and Municipal elevated parking and pedestrian walkway (Railroad Way) (Parcel 6-3-509) | Larchmont Metro North Railroad station, parking lots |
| **South** | Vine Steet, followed by Memorial Park (Vine Street) (Parcel 1-26-624) | Park land |
| **West** | Municipal parking lot (Myrtle Boulevard) (Parcel 1-26-716) | Municipal parking lot, park, and residences |

Langan did not observe obvious conditions likely to represent environmental concerns for the subject property from current uses of adjoining or surrounding properties.

## 4.2 Adjoining Properties and Surrounding Area History

Langan compiled the following summaries of the adjoining properties and surrounding area history based on a review of historical resources and interviews. Historical resources are provided in Appendix E.

**Table 4-2 Historical Use of Adjoining Properties**

| Direction | Adjoining Properties |
|---|---|
| **North** | The northern adjoining property is depicted as undeveloped and vegetated on topographic maps, fire insurance maps, and aerial photographs in the early 1900s. The northern adjoining property appeared in the current configuration by 1962 and was developed with a parking lot. No significant changes were observed after 1962.<br><br>Langan does not consider the historical use of the northern adjoining property an environmental concern for the subject property. |
| **East** | The eastern adjoining property is depicted with a railroad line, now known as the Metro North railroad in the topographic maps from the 1890s through present. The fire insurance maps, beginning in 1911, show an elevated platform, with parking areas, for Larchmont Station. The New England Thruway is also present along the area of the railroad beginning around 1955, which runs underneath the elevated platform, observed in the 1962 aerial photograph. No significant changes were observed after 1962.<br><br>Langan does not consider the historical use of the eastern adjoining property an environmental concern for the subject property. |

| Direction | Adjoining Properties |
|---|---|
| **South** | The southern adjoining property was depicted in the 1919 fire insurance map as a dwelling and stable, which was removed and redeveloped as part of a town park, now known as Memorial Park, by the 1934 fire insurance map.<br><br>Langan does not consider the historical use of the southern adjoining property an environmental concern for the subject property. |
| **West** | The western adjoining property is depicted as developed with a dwelling and shed in the 1919 fire insurance map and was cleared and vacant in the 1934 fire insurance map. The property was observed as vacant and mostly vegetated in the aerial photographs from 1947 through 1953. The western adjoining property appeared in the current configuration by 1962 and was developed with a parking lot with No significant changes were observed after 1962.<br><br>Langan does not consider the historical use of the western adjoining property an environmental concern for the subject property. |

The surrounding area was depicted as developed with a railroad and train station to the east and was otherwise mainly undeveloped in the topographic maps in the late 1800s and early 1900s. Around the 1910's some small dwellings and sheds were present, per the 1919 fire insurance map; however, these structures were removed by the 1930s. The area to the south was developed as a municipal park by 1934, now known as Memorial Park, based on the fire insurance maps. The New England Thruway (Interstate-95) was constructed to the east by 1955 according to the topographic maps. The areas to the north and west of the subject property were developed with a municipal parking lot by the 1960s based on the aerial photographs. By 1962, the surrounding areas appear generally similar to the present day, and were developed with residences, additional parking lots, and parks.

Langan does not consider the historical uses of the surrounding area properties an environmental concern for the subject property.

## 4.3 Regulatory Database Review

Langan reviewed the environmental database report to evaluate if adjoining or surrounding area properties identified in the database report are suspected to represent an environmental concern for the subject property (see Section 8.2). Langan did not consider request and review of the associated regulatory agency files necessary to evaluate potential RECs for the subject property unless discussed in Section 4.3.1 or 4.3.2 below.

### *4.3.1 Adjoining Properties*

Database listings for adjoining properties are summarized as follows.

New York State Authority-Larchmont Station Plaza Over I-95 - Bin 5514610 – 1 Railroad Way (eastern adjoining, inferred downgradient)

This facility was identified on the RCRA SQG and ECHO databases for the generation of ignitable waste, corrosive waste, chromium, lead, benzene, methyl ethyl ketone, and spent nonhalogenated solvents. No violations were associated with this facility.

Since no spills or violations were associated with this facility, it does not pose an environmental concern for the subject property.

The adjoining properties to the north, west, and south were not identified on the database report.

### *4.3.2 Surrounding Area*

Langan evaluated each of the database listings for surrounding area properties (see Section 8.2). Due to the distance and hydraulic location from the subject property or other details from the EDR Database Report, no listings for the surrounding properties pose an environmental concern to the subject property at this time.

# 5. CONCLUSIONS, FINDINGS AND OPINIONS

Langan completed a Phase I ESA consistent with the scope and limitations of ASTM E1527-21 for the subject property at 1 Vine Street, Larchmont, in the Town of Mamaroneck, Westchester County, New York. Exceptions to, or deletions from, ASTM E1527-21 are described in Section 8 of this report.

This assessment has revealed the following RECs, CRECs, HRECs, de minimis conditions, and significant data gaps in connection with the subject property as presented in Table 5-1.

**Table 5-1 Conclusions, Findings and Opinions**

| **ASTM E1527-21 Scope Items** |
|---|
| **Recognized Environmental Conditions (RECs)** |
| *USTs and Petroleum Bulk Storage:* The subject property was registered for six closed and removed USTs, including five gasoline tanks and one diesel tank. Separately, an abandoned UST is reported to exist in the central area of the autobody garage. A sample was collected near this location by PAI which identified impacts of VOCs, SVOCs, and metals. It is unclear if a UST remains in this area and if the tank is related to the impacts in this area. Furthermore, there two additional USTs were identified on the 1934 fire insurance map, just outside of the subject property boundary, and three more gasoline USTs in the central parking lot area in the 1963 fire insurance map. While the USTs in the parking lot have likely been removed, it is unclear if any of the other USTs have been removed and if any of the USTs have impacted the subsurface. The potential USTs and associated impacts pose a REC. |
| *Contamination from automotive-related operations and historic drycleaning:* The subject property has been utilized for automotive repair, service, and maintenance since the 1930s and has also operated as a gasoline station and carwash during part of that time. The western commercial unit in the building operated as a drycleaner from about 1963 through 2024. Langan observed a cloudy to white sheen on standing water in the basement beneath the former drycleaner, which may be attributed to former drycleaning operations. In a previous Phase II ESA by PAI, impacts related to automotive-related chemicals were identified in soil and groundwater and impacts from drycleaning-related chemicals were identified in soil, soil vapor, and groundwater. The on-going and former operations at the subject property have been documented to have impacted the subsurface. Therefore, due to the documented impacts to the subsurface, the historical operations at the subject property pose a REC. |
| **Controlled Recognized Environmental Conditions (CRECs)** |
| Langan did not identify CRECs. |
| **Historical Recognized Environmental Conditions (HRECs)** |
| Langan did not identify HRECs. |
| **De Minimis Conditions** |
| *Staining and housekeeping*: Apparent petroleum and paint staining was observed throughout the autobody garage. Absorbents were inconsistently applied to stained areas and absorbents were observed left out on the floor. Poor housekeeping, including staining throughout the garage and unremoved absorbents, poses a de minimis condition. |

| **ASTM E1527-21 Scope Items** |
|---|
| **Non-ASTM E1527-21 Scope Items** |
| **Business Environmental Risks (BERs)** |
| *Non-Native Fill*: Based on previous investigation, the subject property is underlain by a layer of non-native fill. Non-native fill found in urban environments typically contains ash, demolition debris, and/or municipal waste products and may contain contaminants (e.g., SVOCs or metals) at concentrations above applicable regulatory standards. The occurrence of non-native fill may require implementation of soil handling and management procedures during site redevelopment to address excavation, re-use, handling, and off-site disposal, and may result in incremental costs above the baseline development value, specifically associated with transportation and disposal of excess soil generated during foundation excavation. |

## 6. ENVIRONMENTAL PROFESSIONAL STATEMENT

I declare that to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in Section 312.10 of 40 CFR Part 312 and I have the specific qualifications based on my education, training, and experience to assess a property of the nature, history, and setting of the subject property. I have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Robert Kovacs, PG, LSRP
Senior Associate (Environmental Professional)

Resumes outlining the qualifications of the project team and the Environmental Professional are included in Appendix G.

## 7. REFERENCES

Langan used the following sources to complete this Phase I ESA.


- American Petroleum, Phase I Environmental Site Assessment, 1-5 Vine Street, Larchmont, New York, 30 November 2022
- American Petroleum, Underground Storage Tank Removal Report, 1 Vine Street, Larchmont, New York, 7 July 2015
- ASTM E1527-21, Standard Practice for Environmental Property Assessments: Phase I Environmental Property Assessment Process, published 16 November 2021
- EDR, Inc., Radius Map Report with GeoCheck, 6 April 2026
- EDR, Inc., City Directory Image Report, 6 April 2026
- EDR, Inc., Aerial Photographs, 6 April 2026
- EDR, Inc., Historical Topographic Map Report, 6 April 2026
- EDR, Inc., Sanborn Map Report, 6 April 2026
- New York State Museum and Science Service, Geologic Map of New York, Lower Hudson Sheet, 1995.
- Pennoni Associates, Inc., Phase II Environmental Site Assessment, 1 Vine Street, Larchmont, New York, 17 March 2026
- PFAS Exchange GIS Webviewer: https://experience.arcgis.com/experience/12412ab41b3141598e0bb48523a7c940/ searched 27 April 2026
- Town of Mamaroneck Assessor, Property Record Online System: https://townofmamaroneck.prosgar.com/PROSSearch/SearchFilters, accessed 17 April 2026
- US EPA ECHO database: http://echo.epa.gov/facilities searched 27 April 2026
- US EPA ECHO: PFAS Analytic Tools: https://echo.epa.gov/trends/pfas-tools searched 27 April 2026
- US EPA ENVIROFACTS database: https://www3.epa.gov/enviro/ searched 27 April 2026
- US EPA MyProperty database: https://www3.epa.gov/enviro/facts/myproperty/ searched 27 April 2026


**Table 7-1 Dates of Assessment Components**

| COMPONENT | DATE |
|---|---|
| Interviews | 13 April 2026 |
| Review of government records | 6 April 2026 |
| Site reconnaissance | 13 April 2026 |
| Declaration by Environmental Professional | 28 April 2026 |

# 8. LIMITATIONS AND DEFINITIONS

This Phase I ESA report was prepared for Client and is intended to be used in its entirety. Excerpts taken from this report are not necessarily representative of the assessment findings. The Client is the sole intended beneficiary of the report. The Client/user requested no special terms or conditions regarding this Phase I ESA.

Langan's scope of services, which is described in Section 1.2 and in the contract executed between Langan and the Client, was limited to that agreed to with the Client/user and no other services beyond those explicitly stated are implied. To the extent possible, the services performed and agreed upon for this Phase I ESA are consistent with the guidelines of ASTM E1527-21.

Reliance upon or reuse of this Phase I ESA report by third parties without Langan's prior written authorization is strictly prohibited. Langan, in its sole discretion, may agree to grant reliance to third parties subject to acceptance of Langan's standard reliance letter by the relying party. If provided, reliance is in accordance with terms and conditions established in the contract between Langan and the Client. The limitation of liability defined in the Contract is the aggregate limit of Langan's liability to the Client and all relying parties.

This report is not intended to be an exhaustive assessment of the subject property. The purpose of the Phase I ESA is to reduce uncertainty about unknown conditions at the subject property. No environmental site assessment can wholly eliminate uncertainty regarding the potential for RECs in connection with a subject property. Therefore, Langan cannot "verify", "insure", "certify", or "guarantee" that the subject property is free of environmental concerns.

No expressed or implied representation or warranty is included or intended in this report, except that our services were completed using the care and skill ordinarily followed by professionals providing similar services under similar circumstances in similar locations at the same point in time.

The conclusions provided in this report are based solely on information obtained through completing the standard activities required by ASTM E1527-21 and are intended exclusively for the purpose stated herein, at the specified subject property, as it existed at the point in time the assessment was completed. The conclusions provided in this report do not apply to conditions and features of which Langan was not made aware of through good faith efforts to complete the activities required by ASTM E1527-21 and did not have the opportunity to evaluate.

## 8.1 ASTM Definitions

The following definitions are provided in ASTM E1527-21 and presented below for reference. This section is not a comprehensive list of definitions provided in ASTM E1527-21 and is intended to summarize those pertinent to this Phase I ESA report.

Activity and use limitations (AULs): legal or physical restrictions or limitations on the use of, or access to, a site or facility: (1) to reduce or eliminate potential exposure to hazardous substances or petroleum products in the soil, soil vapor, groundwater, and/or surface water on the property, or (2) to prevent activities that could interfere with the effective-ness of a response action, in order to ensure maintenance of a condition of no significant risk to public health or the environment. These legal or physical restrictions, which may include institutional and/or engineering controls, are intended to prevent adverse impacts to individuals or populations that

may be exposed to hazardous substances and petroleum products in the soil, soil vapor, groundwater, and/or surface water on a property.

Adjoining properties: any real property or properties the border of which is contiguous or partially contiguous with that of the subject property, or that would be contiguous or partially contiguous with that of the subject property but for a street, road, or other public thoroughfare separating them.

All Appropriate Inquiries: that inquiry constituting all appropriate inquiries into the previous ownership and uses of the subject property consistent with good commercial and customary practice as defined in CERCLA, 42 U.S.C.§ 9601(35)(B) and 40 C.F.R. Part 312, that will qualify a party to a commercial real estate transaction for one of the threshold criteria for satisfying the LLPs to CERCLA liability (42U.S.C. §§ 9601(35)(A) & (B), § 9607(b)(3), § 9607(q), and§ 9607(r)), assuming compliance with other elements of the defense.

Approximate minimum search distance: the area for which records must be obtained and reviewed pursuant to ASTM E1527-21 Section 8 subject to the limitations provided in that section. This may include areas outside the subject property and shall be measured from the nearest subject property boundary. This term is used in lieu of radius to include irregularly shaped properties.

Business environmental risk (BER): a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of commercial real estate, not necessarily related to those environmental issues required to be investigated in this practice. Consideration of BER issues may involve addressing one or more non-scope considerations.

Controlled recognized environmental condition (CREC): recognized environmental condition affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to implementation of required controls (for example, activity and use limitations or other property use limitations).

Data gap: a lack of or inability to obtain information required by this practice despite good faith efforts by the environmental professional to gather such information. Data gaps may result from incompleteness in any of the activities required by this practice, including, but not limited to, site reconnaissance (for example, an inability to conduct the site visit), and interviews (for example, an inability to interview the key site manager, regulatory officials, etc.).

De minimis condition: a condition related to a release that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. A condition determined to be a de minimis condition is not a recognized environmental condition nor a controlled recognized environmental condition.

Engineering controls: physical modifications to a site or facility (for example, capping, slurry walls, or point of use water treatment) to reduce or eliminate the potential for exposure to hazardous substances or petroleum products in the soil or groundwater on a property. Engineering controls are a type of activity and use limitation (AUL).

Environment: environment shall have the same meaning as the definition of environment in CERCLA 42 U.S.C. § 9601(8).

Historical recognized environmental condition (HREC): previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls (for example, activity and use limitations or other property use limitations). A historical recognized environmental condition is not a recognized environmental condition.

Institutional controls (IC): a legal or administrative mechanism (for example, "deed restrictions," restrictive covenants, easements, or zoning) on the use of, or access to, a site or facility to (1) reduce or eliminate potential exposure to hazardous substances or petroleum products in the soil or groundwater on the property, or (2) to prevent activities that could interfere with the effectiveness of a response action, in order to ensure maintenance of a condition of no significant risk to public health or the environment. An institutional control is a type of activity and use limitation (AUL).

Key site manager: the person identified by the owner or operator of a subject property as having good knowledge of the uses and physical characteristics of the subject property.

Material threat: obvious threat which is likely to lead to a release and that, in the opinion of the environmental professional, would likely result in impact to public health or the environment.

Obvious: that which is plain or evident; a condition or fact that could not be ignored or overlooked by a reasonable observer.

Property use limitation: limitation or restriction on current or future use of a property in connection with a response to a release, in accordance with the applicable regulatory authority or authorities that allows hazardous sub-stances or petroleum products to remain in place at concentrations exceeding unrestricted use criteria.

Reasonably ascertainable: information that is (1) publicly available, (2) obtainable from its source within reasonable time and cost constraints, and (3) practically reviewable.

Recognized environmental conditions: (1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment. For the purposes of this definition, "likely" is that which is neither certain nor proved, but can be expected or believed by a reasonable observer based on the logic and/or experience of the environmental professional, and/or available evidence, as stated in the report to support the opinions given therein.

Release: a release of any hazardous substance or petroleum product shall have the same meaning as the definition of "release" in CERCLA 42 U.S.C. § 9601(22). There are a number of statutory exclusions from the definition of release that may impact the environmental professional's opinions and conclusions, such as the normal application of fertilizer.

Significant data gap: a data gap that affects the ability of the environmental professional to identify a recognized environmental condition.

Site reconnaissance: that part that is contained in Section 9 of ASTM E1527-21 and addresses what should be done in connection with the site visit. The site reconnaissance includes, but is

not limited to, the site visit done in connection with such a Phase I Environmental Site Assessment.

Site visit: the visit of the subject property during which observations are made constituting the site reconnaissance section of this practice.

Subject property: the property that is the subject of the environmental site assessment described in this practice.

User: the party seeking to use ASTM E1527-21 to complete an environmental site assessment of the subject property.

### 8.2 Standard Environmental Record Sources

Langan reviewed an environmental database search report prepared by an environmental database search provider for the subject property and surrounding area. The database search report includes a listing of properties identified on select federal, state, local and tribal standard source environmental databases within the approximate minimum search radii outlined in ASTM E1527-21. This information was supplied to Langan by the environmental database search provider, and to the environmental database search provider by government sources; therefore, neither Langan nor the environmental database search provider can verify the completeness and accuracy of the database information. Appendix F contains a copy of the report, with specific source and property descriptions, and the dates of the last update for each database searched. Langan reviewed the database search report on a record-by-record basis to evaluate if certain properties identified in the database report are likely to represent an environmental concern for the subject property. The evaluation criteria included factors such as distance, groundwater gradient, nature of the listing, and regulatory status. Unless specifically discussed in the body of this report, the facilities listed on the database do not appear to represent an environmental concern to the subject property.

# Appendix A Figures




NOTES:
1. USGS TOPOGRAPHIC BASEMAP IS PROVIDED THROUGH LANGAN'S ESRI ARCGIS SOFTWARE LICENSING AND ARCGIS ONLINE COPYRIGHT: © 2013 NATIONAL GEOGRAPHIC SOCIETY, I-CUBED.
**WARNING:** IT IS A VIOLATION OF THE NYS EDUCATION LAW ARTICLE 145 FOR ANY PERSON, UNLESS HE IS ACTING UNDER THE DIRECTION OF A LICENSED PROFESSIONAL ENGINEER, TO ALTER THIS ITEM IN ANY WAY.


LANGAN
Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C.
368 Ninth Avenue, 8th Floor
New York, NY 10001-2727
T: 212.479.5400 F: 212.479.5444
www.langan.com


| | |
|---|---|
| Project | 1 VINE STREET<br>PARCEL No. 1-26-730<br>LARCHMONT<br>WESTCHESTER COUNTY NEW YORK |
| Figure Title | SUBJECT PROPERTY LOCATION MAP |
| Project No. | 192019101 |
| Date | 4/22/2026 |
| Scale | 1"=2,000' |
| Drawn By | IHB |
| Figure No. | 1 |

© 2023 Langan

Path: \\langan.com\data\LIM\data1\192019101\Project Data\ArcGIS\APRX\192019101\192019101.aprx Date: 4/22/2026 User: ibaker Time: 4:56 PM




Notes:
1. Imagery provided through Langan's subscription to Nearmap.com. Flown on 04/07/2026.
2. All locations of site reconnaissance observations are approximate.
3. Parcel data provided by the New York State GIS Data Clearinghouse.
4. Groundwater flow direction inferred from review of topographic maps.
5. Three additional localized closed spill incidents, NYSDEC Spill Nos. 9102813, 9410303, and 9413519 occurred at the subject property but specific location details are unknown.


LANGAN
Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C.
368 Ninth Avenue, 8th Floor
New York, NY 10001-2727
T: 212.479.5400 F: 212.479.5444
www.langan.com


| | |
|---|---|
| Project | 1 VINE STREET<br>PARCEL No. 1-26-730<br>LARCHMONT<br>WESTCHESTER COUNTY NEW YORK |
| Figure Title | SUBJECT PROPERTY LAYOUT |
| Project No. | 192019101 |
| Date | 5/27/2026 |
| Scale | 1"=40' |
| Drawn By | IHB |
| Figure No. | 2 |

© 2023 Langan

Path: \\langan.com\data\LIM\data1\192019101\Project Data\ArcGIS\APRX\192019101\192019101.aprx Date: 5/27/2026 User: ibaker Time: 4:51 PM




Notes:
1. Imagery provided through Langan's subscription to Nearmap.com. Flown on 04/07/2026.
2. All locations of site reconnaissance observations are approximate.
3. Parcel data provided by the New York State GIS Data Clearinghouse.
4. Groundwater flow direction inferred from review of topographic maps.


LANGAN
Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C.
368 Ninth Avenue, 8th Floor
New York, NY 10001-2727
T: 212.479.5400 F: 212.479.5444
www.langan.com


| | |
|---|---|
| Project | 1 VINE STREET<br>PARCEL No. 1-26-730<br>LARCHMONT<br>WESTCHESTER COUNTY NEW YORK |
| Figure Title | NEARBY PROPERTIES MAP |
| Project No. | 192019101 |
| Date | 5/27/2026 |
| Scale | 1"=100' |
| Drawn By | IHB |
| Figure No. | 3 |

© 2023 Langan

Path: \\langan.com\data\LIM\data1\192019101\Project Data\ArcGIS\APRX\192019101\192019101.aprx Date: 5/27/2026 User: ibaker Time: 5:09 PM

# Appendix B Agency Records and Other Reports

Freedom of Information Request (FOIL)

**FOIL-26-130**

**Your Submission**

Attachments

Guests (0)

5 Day Letter

Clerk Initial Review

FOIL For Processing - TMFD

Upload Documents

Clerk Document Review

## Your submission

Submitted Apr 28, 2026 at 6:41am

### Contact Information

**Olivia Miller**

Email address

omiller@langan.com

Phone Number

212-479-5400

Mailing Address

208 Old Country Rd, Suite 208 , Melville, NY 11747

### Locations

1 location total

PRIMARY LOCATION

**1-5 Vine St**

Larchmont, NY 10538

### FOIL: Important Information

- Full text for Public Officer's Law, Article 6, which governs Freedom Of Information Requests,.

(https://dos.ny.gov/coog/foil2.html)

- Please be as specific as possible when requesting documents and provide a date or date ranges when appropriate.

- **If you are requesting information on multiple properties, but not a list** of any kind, please submit separate FOIL requests. (For example, if you would like surveys on multiple properties, submit one FOIL for each property)

I have read and acknowledge the above information. *

☑

---

**Public Information**

Are you requesting Septic Information, a Current Property Card, or Tax Related Information? *

NO

Are you requesting a Title Search or Zoning Verification? *

NO

Are you looking for Police related information? *

No

Are you looking for Fire department related information? *

Yes

---

**Lists**

Are you requesting a list of any kind? *

No

---

**Common Property Information**

- "Common" property information includes Violations, Certificates of Occupancy, Permits and Surveys.

- If you wish to submit for **BOTH** "Common" Property Related Items as well as other documents, answer "NO" and enter your request manually.

Are you requesting Violations, Surveys, Certificates of Occupancy or Permits ONLY? *

No

Please explain your FOIL request *

Phase I ESA - Envionmental Due Diligence: Pursuant to the Federal Freedom of Information Act (5 U.S.C 552 et seq.) dealing with the examination and duplication of documents

maintained by public agencies, Langan is requesting any information or copies of files regarding environmental conditions on the above property, such as environmental permits, notices of violations, spill/discharge incidents, storage or disposal of hazardous substances, Underground Storage Tanks (USTs), Leaking Underground Storage Tanks (LTANKs), asbestos abatement, and any other environmental reports that your department may have.

The Subject Property is located at **1 to 5 Vine Street** in **Larchmont, New York** and is identified as Tax **Parcel 1-26-730**. The site is bounded by Town of Mamaroneck – Lot A (Myrtle Avenue) to the north and west, Vine Street to the south, followed by Memorial Park (Vine Street), and by the New England Thruway/Larchmont Station overpass (1 Railroad Way) to the east.

---

**Delivery Information**

Please select your type of delivery *

I acknowledge that my documents will be delivered electronically

---

**Town of Mamaroneck**

**Your Profile**

Your Records (/dashboard/records)

**Resources**

Claim a Record (/claimRecord)

Employee Login (https://mamaroneckny.workflow.op

Portal powered by **OpenGov**

Contact Us

Contact Us

E-Mail the CE

Email Community Assistance

Elected Officials

Commissioners and Directors

Other Appointed Officials

Advisory Boards

- Board of Ethics
- Asian American Advisory Board

Ad Hoc Advisory Boards

- Police Reform Task Force
- CyberSecurity Task Force

EN



**Thank you for submitting!**

You submitted:

Full Name: **Olivia Miller**

E-mail Address: **omiller@langan.com**

Street Address: **201 Old Country Road, Suite 208**

City: **Melville**

State: **11747**

Comments: **Pursuant to the Federal Freedom of Information Act (5 U.S.C 552 et seq.) dealing with the examination and duplication of documents maintained by public agencies, Langan is requesting any information or copies of files regarding environmental conditions on the above property, such as environmental permits, notices of violations, spill/discharge incidents, storage or disposal of hazardous substances, Underground Storage Tanks (USTs), Leaking Underground Storage Tanks (LTANKs), asbestos abatement, and any other environmental reports that your department may have.**

**The Subject Property is located at 1 to 5 Vine Street in Larchmont, New York and is identified as Tax Parcel 1-26-730. The site is bounded by Town of Mamaroneck – Lot A (Myrtle Avenue) to the north and west, Vine Street to the south, followed by Memorial Park (Vine Street), and by the New England Thruway/Larchmont Station overpass (1 Railroad Way) to the east.**

Department: **FOIL-DOH@westchestercountyny.gov**

Gun Violence Prevention Task Force

Directions

Subscribe

FOIL

Westchester County © 2026
148 Martine Avenue, White Plains, NY 10601
(914) 995-2000
Privacy / Disclaimer
Digital Content Accessibility Policy

Subscribe to the MyWestchester Newsletter

ENTER YOUR EMAIL

Sign Up

EN

LANGAN

Technical Excellence
Practical Experience
Client Responsiveness

28 April 2026

Records Access Office
New York State Department of Health
Corning Tower, Room 2364
Albany, New York 12237-0044
foil@health.ny.gov

**Re: Freedom of Information Request**
**1-5 Vine Street**
**Parcel No. 1-26-730**
**Larchmont, New York 10538**
**Langan Project No. 192019101**

Dear Sir or Madam:

Pursuant to the Federal Freedom of Information Act (5 U.S.C 552 et seq.) dealing with the examination and duplication of documents maintained by public agencies, Langan is requesting any information or copies of files regarding environmental conditions on the above property, such as environmental permits, notices of violations, spill/discharge incidents, storage or disposal of hazardous substances, Underground Storage Tanks (USTs), Leaking Underground Storage Tanks (LTANKs), asbestos abatement, and any other environmental reports that your department may have.

The Subject Property is located at **1 to 5 Vine Street** in **Larchmont, New York** and is identified as Tax **Parcel 1-26-730**. The site is bounded by Town of Mamaroneck – Lot A (Myrtle Avenue) to the north and west, Vine Street to the south, followed by Memorial Park (Vine Street), and by the New England Thruway/Larchmont Station overpass (1 Railroad Way) to the east.

Please contact me at 845-978-3734 with any questions or send your response to my attention at omiller@langan.com or at the below address:

Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C.
368 Ninth Avenue, 8th Floor
New York, New York 10001-2727

Thank you in advance for your cooperation.

Sincerely,

**Langan Engineering, Environmental, Surveying**
**Landscape Architecture, and Geology, D.P.C.**

Olivia Miller

Olivia Miller
Staff Geologist

LANGAN

Technical Excellence
Practical Experience
Client Responsiveness

28 April 2026

New York State Department of Environmental Conservation
Region 2 Office
47-40 21st Street
Long Island City, New York 11101

**Re: Freedom of Information Request**
**1-5 Vine Street**
**Parcel No. 1-26-730**
**Larchmont, New York 10538**
**Langan Project No. 192019101**

Dear Sir or Madam:

Pursuant to the Federal Freedom of Information Act (5 U.S.C 552 et seq.) dealing with the examination and duplication of documents maintained by public agencies, Langan is requesting any information or copies of files regarding environmental conditions on the above property, such as environmental permits, notices of violations, spill/discharge incidents, storage or disposal of hazardous substances, Underground Storage Tanks (USTs), Leaking Underground Storage Tanks (LTANKs), asbestos abatement, and any other environmental reports that your department may have.

The Subject Property is located at **1 to 5 Vine Street** in **Larchmont, New York** and is identified as Tax **Parcel 1-26-730**. The site is bounded by Town of Mamaroneck – Lot A (Myrtle Avenue) to the north and west, Vine Street to the south, followed by Memorial Park (Vine Street), and by the New England Thruway/Larchmont Station overpass (1 Railroad Way) to the east.

Please contact me at 845-978-3734 with any questions or send your response to my attention at omiller@langan.com or at the below address:

Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C.
368 Ninth Avenue, 8th Floor
New York, New York 10001-2727

Thank you in advance for your cooperation.

Sincerely,

**Langan Engineering, Environmental, Surveying**
**Landscape Architecture, and Geology, D.P.C.**

Olivia Miller

Olivia Miller
Staff Geologist

# Property Details - 1-5 Vine St, 10538 - 1-26-730 - SWIS: 553289 (Mamaroneck)

### Structure

| Building 1 | |
|---|---|
| **Number of Identical Buildings** | 1 |
| **Actual Year Built** | 1930 |
| **Effective Year Built** | 1990 |
| **Construction Quality** | 2.0 |
| **Condition** | 3 - Normal |
| **Building Perimeter** | 533 |
| **Gross Floor Area** | 11958 |
| **Number of Stories** | 1.0 |
| **Story Height** | 12 |
| **Air Conditioning %** | 0% |
| **Sprinkler %** | 0% |
| **Number of Elevators** | |
| **Basement Perimeter** | |
| **Basement Sq. Ft** | |




### View Photos and Other Parcel Files

### 2025 Final Assessment Information

| | |
|---|---|
| **Land Assessed Value** | $340,000 |
| **Total Assessed Value** | $1,870,000 |
| **Equalization Rate** | 100.00% |
| **Full Market Value** | $1,870,000 |
| **County Taxable** | $1,870,000 |
| **Municipal Taxable** | $1,870,000 |
| **School Taxable** | $1,870,000 |
| **Roll Section** | 1 |

### Property Description

| | |
|---|---|
| **Property Location** | 1-5 Vine St |
| **Property Type** | 433 - Auto body |
| **Neighborhood Code** | 55005 comm town |
| **SWIS** | Unincorporated Town |
| **Water Supply** | 3 - Comm/public |
| **Utilities** | 4 - Gas & elec |
| **Sewer Type** | 3 - Comm/public |
| **Zoning** | B Business |
| **School** | |
| **Grid East** | 658720 |
| **Grid North** | 341290 |
| **Acres** | 0.34 |
| **Front** | 0.00 |
| **Depth** | 0.00 |
| **Account Number** | 103800 |

### Last Property Sale

No Sales Data Found

| Owner Information | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| **Owner Name** | **Address 1** | **Address 2** | **PO Box** | **City** | **State** | **Zip** | **Unit Name** | **Unit Number** |
| Mansisbro Inc | 1-5 Vine St | | | Larchmont | NY | 10538 | | |

| Sales | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| Deed Date | Deed Book | Deed Page | Contract Date | Sale Date | Last Physical Inspection Date | Sale Price | Net Sale Price | Prior Owner |
| No data available in table | | | | | | | | |

No Exemption Data Found

| Land | | | | | | |
|---|---|---|---|---|---|---|
| Site # | Land Type | Acres | Front | Depth | Sq Ft | Soil Rating |
| 1 | 01 - Primary | 0.34 | | | | |

| Commercial Site Uses | | | |
|---|---|---|---|
| Site # | Commercial Use | Total Units | Total Rentable Area (sqft.) |
| 1 | G03 - Body shop | 0 | 10958 |
| 1 | D10 - Row retail | 0 | 1000 |

No Improvement Data Found

Have a project #?

Step 2 of 6 ·

Save Draft and Exit

## Location for Freedom of Information Request (FOIL)

**PRIMARY LOCATION**

The main location associated with the record.

**1-5 Vine St**
Larchmont, NY 10538

Change Location

**Unit**

No Unit

### Property Owner Information

**Name**

Mansisbro  Inc,

**Phone Number**

**Email**

Street #

Street Name

Vine St

Unit

City

Larchmont

State

NY

Zip Code

105

**Property Data**

**Year built**
1930

**MBL**
1-26-730

**Lot Area**
0.34

**Zoning**
B

**Occupancy**

**Book Page**

**Water**
Comm/public

**Building Type**
Commercial

**Sewage**
Comm/public

Back

Next

**Town of Mamaroneck**

**Your Profile**

Your Records (/dashboard/records)

**Resources**

Claim a Record (/claimRecord)

Employee Login (https://mamaroneckny.workflow.op

Portal powered by **OpenGov**

An official website of New York State.
Here's how you know



# Search Results from Bulk Storage Database

No search results found for the following criteria:

**Site Name:**
**Program Type:** All Program Types
**County:** Westchester
**City:**
**Street:** vine
**Zipcode:**
**Region:** 3
**Facility Status:** All Status
**Expiration Date:**

Refine This Search

An official website of New York State.
Here's how you know



# Search Results from Environmental Remediation Databases

No search results found for the following criteria:

**Site Name:**
**Program:** All Programs
**Site Class:** All Classes
**County:** Westchester
**Region:** 3
**City:**
**Street:** vine
**Control Type:** All
**Engineering Controls:** All
**Institutional Controls:** All

Refine This Search

An official website of New York State.
Here's how you know



# Details from Spill Incidents Database Search

## Spill Record

### Administrative Information

**DEC Region:** 3
**Spill Number:** 1501291

### Spill Date/Time

**Spill Date:** 05/05/2015
**Spill Time:** 02:00:00 PM
**Call Received Date:** 05/05/2015
**Call Received Time:** 03:11:00 PM

### Location

**Spill Name:** JS CHADWORTHS
**Address:** 1 VINE ST
**City:** LARCHMONT
**County:** Westchester

## Spill Description

| Material Spilled | Amount Spilled | Resource Affected |
|---|---|---|
| gasoline | Unknown | Soil |

**Cause:** Equipment Failure
**Source:** Commercial/Industrial
**Waterbody:**

## Record Close

**Date Spill Closed:** 07/08/2015
"Date Spill Closed" means the date the spill case was closed by the case manager in the Department of Environmental Conservation (the Department). The spill case was closed because either; a) the records and data submitted indicate that the necessary cleanup and removal actions have been completed and no further remedial activities are necessary, or b) the case was closed for administrative reasons (e.g., multiple reports of a single spill consolidated into a single spill number). The Department however reserves the right to require additional remedial work in relation to the spill, if in the future it determines that further action is necessary.

If you have questions about this reported incident, please contact the Regional Office where the incident occurred.

An official website of New York State.
Here's how you know



# Details from Spill Incidents Database Search

## Spill Record

### Administrative Information

**DEC Region:** 3
**Spill Number:** 9102813

### Spill Date/Time

**Spill Date:** 06/10/1991
**Spill Time:** 05:00:00 AM
**Call Received Date:** 06/10/1991
**Call Received Time:** 09:50:00 AM

### Location

**Spill Name:** MARISIERO INC.
**Address:** 1-5 VINE STREET
**City:** LARCHMONT
**County:** Westchester

## Spill Description

| Material Spilled | Amount Spilled | Resource Affected |
|---|---|---|
| waste oil/used oil | 30 Gal. | Sewer |

**Cause:** Tank Failure
**Source:** Commercial/Industrial
**Waterbody:**

## Record Close

**Date Spill Closed:** 11/14/1997
"Date Spill Closed" means the date the spill case was closed by the case manager in the Department of Environmental Conservation (the Department). The spill case was closed because either; a) the records and data submitted indicate that the necessary cleanup and removal actions have been completed and no further remedial activities are necessary, or b) the case was closed for administrative reasons (e.g., multiple reports of a single spill consolidated into a single spill number). The Department however reserves the right to require additional remedial work in relation to the spill, if in the future it determines that further action is necessary.

If you have questions about this reported incident, please contact the Regional Office where the incident occurred.

An official website of New York State.
Here's how you know



# Details from Spill Incidents Database Search

## Spill Record

### Administrative Information

**DEC Region:** 3
**Spill Number:** 9410303

### Spill Date/Time

**Spill Date:** 11/02/1994
**Spill Time:** 02:15:00 PM
**Call Received Date:** 11/02/1994
**Call Received Time:** 02:18:00 PM

### Location

**Spill Name:** J & F CHATSWORTH GAS STA
**Address:** 1 VINE STREET
**City:** LARCHMONT
**County:** Westchester

## Spill Description

| Material Spilled | Amount Spilled | Resource Affected |
|---|---|---|
| gasoline | Unknown | Soil |

**Cause:** Tank Failure
**Source:** Gasoline Station or other PBS Facility
**Waterbody:**

## Record Close

**Date Spill Closed:** 02/27/2005
"Date Spill Closed" means the date the spill case was closed by the case manager in the Department of Environmental Conservation (the Department). The spill case was closed because either; a) the records and data submitted indicate that the necessary cleanup and removal actions have been completed and no further remedial activities are necessary, or b) the case was closed for administrative reasons (e.g., multiple reports of a single spill consolidated into a single spill number). The Department however reserves the right to require additional remedial work in relation to the spill, if in the future it determines that further action is necessary.

If you have questions about this reported incident, please contact the Regional Office where the incident occurred.

An official website of New York State.
Here's how you know



# Spill Record

## Administrative Information

**DEC Region:** 3
**Spill Number:** 9413519

## Spill Date/Time

**Spill Date:** 01/10/1995
**Spill Time:** 02:00:00 PM
**Call Received Date:** 01/10/1995
**Call Received Time:** 04:00:00 PM

## Location

**Spill Name:** JF CHATSWORTH
**Address:** 1 VINE STREET
**City:** LARCHMONT
**County:** Westchester

## Spill Description

| Material Spilled | Amount Spilled | Resource Affected |
|---|---|---|
| gasoline | 4 Gal. | Soil |

**Cause:** Human Error
**Source:** Tank Truck
**Waterbody:**

## Record Close

**Date Spill Closed:** 01/23/1995
"Date Spill Closed" means the date the spill case was closed by the case manager in the Department of Environmental Conservation (the Department). The spill case was closed because either; a) the records and data submitted indicate that the necessary cleanup and removal actions have been completed and no further remedial activities are necessary, or b) the case was closed for administrative reasons (e.g., multiple reports of a single spill consolidated into a single spill number). The Department however reserves the right to require additional remedial work in relation to the spill, if in the future it determines that further action is necessary.

If you have questions about this reported incident, please contact the Regional Office where the incident occurred.

# Detailed Facility Report

Facility Summary

**CHATSWORTH AUTO BODY**

**ONE VINE ST, MAMARONECK, NY 10543**

**FRS (Facility Registry Service) ID:** 110019367898

**EPA Region:** 02

**Latitude:** 40.93532

**Longitude:** -73.75858

**Locational Data Source:** FRS

**Industries:** Gasoline Stations

**Indian Country:** N

# Enforcement and Compliance Summary

| Statute | RCRA |
|---|---|
| Compliance Monitoring Activities (5 years) | -- |
| Date of Last Compliance Monitoring Activity | 09/13/2012 |
| Compliance Status | No Violation Identified |
| Qtrs in Noncompliance (of 12) | 0 |
| Qtrs with Significant Violation | 0 |
| Informal Enforcement Actions (5 years) | -- |
| Formal Enforcement Actions (5 years) | -- |
| Penalties from Formal Enforcement Actions (5 years) | -- |
| EPA Cases (5 years) | -- |
| Penalties from EPA Cases (5 years) | -- |

# Regulatory Information

**Clean Air Act (CAA):** No Information

**Clean Water Act (CWA):** No Information

**Resource Conservation and Recovery Act (RCRA):** Active SQG, (NYD982718272)

**Safe Drinking Water Act (SDWA):** No Information

Go To Enforcement/Compliance Details

Known Data Problems <https://epa.gov/resources/echo-data/known-data-problems>

# Other Regulatory Reports

**Air Emissions Inventory (EIS):** No Information

**Greenhouse Gas Emissions (eGGRT):** No Information

**Toxic Releases (TRI):** No Information

**Compliance and Emissions Data Reporting Interface (CEDRI):** No Information

Facility/System Characteristics

# Facility/System Characteristics

| System | Statute | Identifier | Universe | Status | Areas | Permit Expiration Date | Indian Country | Latitude | Longitude |
|---|---|---|---|---|---|---|---|---|---|
| FRS | | 110019367898 | | | | | N | 40.93532 | -73.75858 |

| System | Statute | Identifier | Universe | Status | Areas | Permit Expiration Date | Indian Country | Latitude | Longitude |
|---|---|---|---|---|---|---|---|---|---|
| RCRAInfo | RCRA | NYD982718272 | SQG | Active (H ) | | | N | 40.934805 | -73.758938 |

## Facility Address

| System | Statute | Identifier | Facility Name | Facility Address | Facility County |
|---|---|---|---|---|---|
| FRS | | 110019367898 | CHATSWORTH AUTO BODY | ONE VINE ST, MAMARONECK, NY 10543 | Westchester County |
| RCRAInfo | RCRA | NYD982718272 | J & F CHATSWORTH LTD | 1 VINE ST, LARCHMONT, NY 10538 | Westchester County |

## Facility SIC (Standard Industrial Classification) Codes

| System | Identifier | SIC Code | SIC Description |
|---|---|---|---|

No data records returned

## Facility NAICS (North American Industry Classification System) Codes

| System | Identifier | NAICS Code | NAICS Description |
|---|---|---|---|
| RCRAInfo | NYD982718272 | 44711 | Gasoline Stations with Convenience Stores |
| RCRAInfo | NYD982718272 | 811111 | General Automotive Repair |
| RCRAInfo | NYD982718272 | 811121 | Automotive Body, Paint, and Interior Repair and Maintenance |

## Facility Tribe Information

| Reservation Name | Tribe Name | EPA Tribal ID | Distance to Tribe (miles) |
|---|---|---|---|

No data records returned

---

Enforcement and Compliance

## Compliance Monitoring History

Last 5 Years

| Statute | Source ID | System | Activity Type | Compliance Monitoring Type | Lead Agency | Date | Finding (if applicable) |
|---|---|---|---|---|---|---|---|

No data records returned

*Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy* <https://www.epa.gov/compliance/compliance-monitoring-programs> *activities or because they are not counted as inspections within EPA's Annual Results* <https://www.epa.gov/enforcement/enforcement-data-and-results>.

## Compliance Summary Data

| Statute | Source ID | Current SNC (Significant Noncompliance)/HPV (High Priority Violation) | Current As Of | Qtrs with NC (Noncompliance) (of 12) | Data Last Refreshed |
|---|---|---|---|---|---|
| RCRA | NYD982718272 | No | 04/25/2026 | 0 | 04/24/2026 |

## Three-Year Compliance History by Quarter

| Statute | Program/Pollutant/Violation Type | | QTR 1 | QTR 2 | QTR 3 | QTR 4 | QTR 5 | QTR 6 | QTR 7 | QTR 8 | QTR 9 | QTR 10 | QTR 11 | QTR 12+ |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RCRA (Source ID: NYD982718272) | | | 07/01-09/30/23 | 10/01-12/31/23 | 01/01-03/31/24 | 04/01-06/30/24 | 07/01-09/30/24 | 10/01-12/31/24 | 01/01-03/31/25 | 04/01-06/30/25 | 07/01-09/30/25 | 10/01-12/31/25 | 01/01-03/31/26 | 04/01-06/30/26 |
| | Facility-Level Status | | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified |
| | Violation | Agency | | | | | | | | | | | | |

# Informal Enforcement Actions

Last 5 Years

| Statute | System | Source ID | Type of Action | Lead Agency | Date |
|---|---|---|---|---|---|

No data records returned

*Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.*

# Formal Enforcement Actions

Last 5 Years

| Statute | System | Law/ Section | Source ID | Type of Action | Case No. | Lead Agency | Case Name | Issued/ Filed Date | Settlements/ Actions | Settlement/ Action Date | Federal Penalty Assessed | State/ Local Penalty Assessed | Penalty Amount Collected | SEP Value | Comp Action Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|

No data records returned

Environmental Conditions

# Watersheds

| 12-Digit WBD (Watershed Boundary Dataset) HUC (RAD (Reach Address Database)) | WBD (Watershed Boundary Dataset) Subwatershed Name (RAD (Reach Address Database)) | State Water Body Name (ICIS (Integrated Compliance Information System)) | Beach Closures Within Last Year | Beach Closures Within Last Two Years | Pollutants Potentially Related to Impairment | Watershed with ESA (Endangered Species Act)-listed Aquatic Species? |
|---|---|---|---|---|---|---|

No data records returned

# Assessed Waters From Latest State Submission (ATTAINS)

| State | Report Cycle | Assessment Unit ID | Assessment Unit Name | Water Condition | Cause Groups Impaired | Drinking Water Use | Ecological Use | Fish Consumption Use | Recreation Use | Other Use |
|---|---|---|---|---|---|---|---|---|---|---|

No data records returned

# Air Quality Nonattainment Areas

| Pollutant | Within Nonattainment Status Area? | Nonattainment Status Applicable Standard(s) | Within Maintenance Status Area? | Maintenance Status Applicable Standard(s) |
|---|---|---|---|---|
| Ozone | Yes | 1-Hour Ozone (1979); 8-Hour Ozone (2008); 8-Hour Ozone (2015) | No | -- |
| Lead | No | -- | No | -- |

| Pollutant | Within Nonattainment Status Area? | Nonattainment Status Applicable Standard(s) | Within Maintenance Status Area? | Maintenance Status Applicable Standard(s) |
|---|---|---|---|---|
| Particulate Matter | No | -- | Yes | PM-2.5 (1997); PM-2.5 (2006) |
| Carbon Monoxide | No | -- | Yes | Carbon Monoxide (1971) |
| Sulfur Dioxide | No | -- | No | -- |

Pollutants

# Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

| TRI Facility ID | Year | Air Emissions | Surface Water Discharges | Off-Site Transfers to POTWs (Publicly Owned Treatment Works) | Underground Injections | Disposal to Land | Total On-Site Releases | Total Off-Site Transfers |
|---|---|---|---|---|---|---|---|---|

No data records returned

# Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

| Chemical Name |
|---|

No data records returned

# e-Manifest Hazardous Waste History (Public)

## Hazardous Waste Shipped in Kilograms by Year (Through 1/24/2026)

| Source ID | Waste Description | 2023 | 2024 | 2025 | 2026 |
|---|---|---|---|---|---|
| NYD982718272 | Hazardous Waste | -- | -- | 208 | -- |
| NYD982718272 | Acute Hazardous Waste | -- | -- | 0 | -- |
| NYD982718272 | Pharmaceutical Hazardous Waste | -- | -- | 0 | -- |

“Pharmaceutical Hazardous Waste” refers to quantities managed under 40 CFR part 266 subpart P and thus excluded from the Hazardous and Acute Hazardous Waste quantities shown above.

Community

# Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2023 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <https://epa.gov/help/reports/dfr-data-dictionary#demographic>.

| General Statistics (ACS (American Community Survey)) | |
|---|---|
| Total Persons | 20,774 |
| Population Density | 7,840/sq.mi. |
| Housing Units in Area | 7,399 |
| Percent People of Color | 66% |
| Households in Area | 7,090 |
| Households on Public Assistance | 273 |
| Persons With Low Income | 5,200 |
| Percent With Low Income | 25% |

| Geography | |
|---|---|
| Radius of Selected Area | 1 mi. |
| Center Latitude | 40.93532 |
| Center Longitude | -73.75858 |
| Total Area | 3.14 sq.mi. |
| Land Area | 84% |
| Water Area | 16% |

| Income Breakdown (ACS (American Community Survey)) - Households (%) | |
|---|---|
| Less than $15,000 | 798 (11.27%) |
| $15,000 - $25,000 | 298 (4.21%) |
| $25,000 - $50,000 | 854 (12.06%) |
| $50,000 - $75,000 | 832 (11.75%) |
| Greater than $75,000 | 4,300 (60.72%) |

| Age Breakdown (ACS (American Community Survey)) - Persons (%) | |
|---|---|
| Children 5 years and younger | 1,461 (7%) |
| Minors 17 years and younger | 4,501 (22%) |
| Adults 18 years and older | 16,271 (78%) |
| Seniors 65 years and older | 2,900 (14%) |

| Race Breakdown (ACS (American Community Survey)) - Persons (%) | |
|---|---|
| White | 9,025 (43%) |
| African-American | 1,438 (7%) |
| Hispanic-Origin | 11,077 (53%) |
| Asian | 726 (3%) |
| Hawaiian/Pacific Islander | 0 (0%) |
| American Indian | 143 (1%) |
| Other/Multiracial | 5,367 (26%) |

| Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%) | |
|---|---|
| Less than 9th Grade | 1,676 (11.49%) |
| 9th through 12th Grade | 1,104 (7.57%) |
| High School Diploma | 3,377 (23.14%) |
| Some College/2-year | 1,623 (11.12%) |
| B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More | 5,722 (39.21%) |

**Related Topics:** Envirofacts

FRS

# FRS Facility Detail Report

## CHATSWORTH AUTO BODY

**EPA Registry Id:** 110019367898
ONE VINE ST
MAMARONECK, NY 10543




**Legend**

- Selected Facility
- EPA Facility of Interest
- State/Tribe Facility of Interest

The facility locations displayed come from the FRS Spatial Coordinates tables. They are the best representative locations for the displayed facilities based on the accuracy of the collection method and quality assurance checks performed against each location. The North American Datum of 1983 is used to display all coordinates.

## Facility Registry Service Links:

- Facility Registry Service (FRS) Overview
- FRS Facility Query
- FRS Organization Query
- EZ Query
- FRS Physical Data Model
- FRS Geospatial Model

# Environmental Interests

| Information System | System Facility Name | Information System Id/Report Link | Environmental Interest Type | Data Source | Last Updated Date | Supplemental Environmental Interests: |
|---|---|---|---|---|---|---|
| RESOURCE CONSERVATION AND RECOVERY ACT INFORMATION SYSTEM | J & F CHATSWORTH LTD | NYD982718272 | SQG (Y) | RCRAINFO | | |
| NEW YORK - FACILITY INFORMATION SYSTEM | CHATSWORTH AUTO BODY | 3-5532-00133 | STATE MASTER | FIS | | |

**Additional EPA Reports:** MyEnvironment Enforcement and Compliance Facility Coordinates Viewer Watershed Report

### Standard Industrial Classification Codes (SIC)

No SIC Codes returned.

### Facility Codes and Flags

| | |
|---|---|
| **EPA Region:** | 02 |
| **Duns Number:** | |
| **Congressional District Number:** | 16 |
| **Legislative District Number:** | NY |
| **HUC Code/Watershed:** | 02030102 / BRONX |
| **US Mexico Border Indicator:** | |
| **Federal Facility:** | NO |
| **Tribal Land:** | NO |

### Alternative Names

| Alternative Name | Source of Data |
|---|---|
| J & F CHATSWORTH LTD | RCRAINFO |

### Organizations

No Organizations returned.

### National Industry Classification System Codes (NAICS)

| Data Source | NAICS Code | Description | Primar |
|---|---|---|---|
| RCRAINFO | 811111 | GENERAL AUTOMOTIVE REPAIR. | |
| RCRAINFO | 44711 | GASOLINE STATIONS WITH CONVENIENCE STORES | |
| RCRAINFO | 811121 | AUTOMOTIVE BODY, PAINT, AND INTERIOR REPAIR AND MAINTENANCE. | |

### Facility Mailing Addresses

| Affiliation Type | Delivery Point | City Name | State | Postal Code | Information System |
|---|---|---|---|---|---|
| REGULATORY CONTACT | 1 VINE ST | LARCHMONT | NY | 10538 | RCRAINFO |
| FACILITY MAILING ADDRESS | 1 VINE ST | LARCHMONT | NY | 10538 | RCRAINFO |

### Contacts

No Contacts returned.

Query executed on: APR-28-2026

**Last updated on September 24, 2015**

United States Environmental Protection Agency

# Multisystem Summary Report



**CHATSWORTH AUTO BODY**
**ONE VINE ST**
**MAMARONECK, NY 10543**
**You can navigate within the map with your mouse.*

## ACRES

**No ACRES report found.**

## BR

**No BR report found.**

## SEMS

**No SEMS report found.**

## GHG

**No GHG report found.**

## ICIS-AIR

**No ICIS-AIR report found.**

## ICIS-NPDES

**No ICIS-NPDES report found.**

# RCRAInfo

Handler ID: NYD982718272 —

**Handler ID:** <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_handler/handler_id> NYD982718272

## List of Naics Codes and Descriptions

| **Naics Code** <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_naics/naics_code> | **Naics Description** <https://epa.gov/envirofacts/metadata/column/rcra/rcr_h |
|---|---|
| 4471 | GASOLINE STATIONS |
| 44711 | GASOLINE STATIONS WITH CONVENIENCE ST |
| 811111 | GENERAL AUTOMOTIVE REPAIR |
| 811121 | AUTOMOTIVE BODY, PAINT, AND INTERIOR RE MAINTENANCE |

### Handler / Facility Classification

**Unspecified Universe for the facility listed above.**

| Handler Type <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_reporting/in_a_universe> |
| --- |
| Small Quantity Generator |

Additional information can be obtained from Resource Conservation and Recovery Information (RCRAInfo) Search.

# TRI

**No TRI report found.**

Contact Us <https://www.epa.gov/enviro/forms/contact-us-about-envirofacts> to ask a question, provide feedback, or report a problem.

Last updated on April 22, 2026

# Detailed Facility Report

Facility Summary

**J & F CHATSWORTH AUTO BODY**

**3 VINE ST, LARCHMONT, NY 10538**

**FRS (Facility Registry Service) ID:** 110019224409

**EPA Region:** 02

**Latitude:** 40.935722

**Longitude:** -73.759215

**Locational Data Source:** FRS

**Industries:** Repair and Maintenance

**Indian Country:** N

# Enforcement and Compliance Summary

| Statute | CAA |
|---|---|
| Compliance Monitoring Activities (5 years) | -- |
| Date of Last Compliance Monitoring Activity | -- |
| Compliance Status | No Violation Identified |
| Qtrs in Noncompliance (of 12) | 0 |
| Qtrs with Significant Violation | 0 |
| Informal Enforcement Actions (5 years) | -- |
| Formal Enforcement Actions (5 years) | -- |
| Penalties from Formal Enforcement Actions (5 years) | -- |
| EPA Cases (5 years) | -- |
| Penalties from EPA Cases (5 years) | -- |

# Regulatory Information

**Clean Air Act (CAA):** Operating Minor (NY0000003553200136)

**Clean Water Act (CWA):** No Information

**Resource Conservation and Recovery Act (RCRA):** No Information

**Safe Drinking Water Act (SDWA):** No Information

# Other Regulatory Reports

**Air Emissions Inventory (EIS):** No Information

**Greenhouse Gas Emissions (eGGRT):** No Information

**Toxic Releases (TRI):** No Information

**Compliance and Emissions Data Reporting Interface (CEDRI):** No Information

Go To Enforcement/Compliance Details

Known Data Problems <https://epa.gov/resources/echo-data/known-data-problems>

Facility/System Characteristics

# Facility/System Characteristics

| System | Statute | Identifier | Universe | Status | Areas | Permit Expiration Date | Indian Country | Latitude | Longitude |
|---|---|---|---|---|---|---|---|---|---|
| FRS | | 110019224409 | | | | | N | 40.935722 | -73.759215 |
| ICIS-Air | CAA | NY0000003553200136 | Minor Emissions | Operating | CAAMACT, CAASIP | | N | 40.93573 | -73.759227 |

# Facility Address

| System | Statute | Identifier | Facility Name | Facility Address | Facility County |
|---|---|---|---|---|---|
| FRS | | 110019224409 | J & F CHATSWORTH AUTO BODY | 3 VINE ST, LARCHMONT, NY 10538 | Westchester County |
| ICIS-Air | CAA | NY0000003553200136 | J & F CHATSWORTH AUTO BODY | 3 VINE ST, LARCHMONT, NY 10538 | Westchester County |

# Facility SIC (Standard Industrial Classification) Codes

| System | Identifier | SIC Code | SIC Description |
|---|---|---|---|
| ICIS-Air | NY0000003553200136 | 7532 | Top & Body Repair & Paint Shops |

# Facility NAICS (North American Industry Classification System) Codes

| System | Identifier | NAICS Code | NAICS Description |
|---|---|---|---|
| ICIS-Air | NY0000003553200136 | 811121 | Automotive Body, Paint, and Interior Repair and Maintenance |

# Facility Tribe Information

| Reservation Name | Tribe Name | EPA Tribal ID | Distance to Tribe (miles) |
|---|---|---|---|

No data records returned

Enforcement and Compliance

# Compliance Monitoring History

Last 5 Years

| Statute | Source ID | System | Activity Type | Compliance Monitoring Type | Lead Agency | Date | Finding (if applicable) |
|---|---|---|---|---|---|---|---|

No data records returned

*Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy* <https://www.epa.gov/compliance/compliance-monitoring-programs> *activities or because they are not counted as inspections within EPA's Annual Results* <https://www.epa.gov/enforcement/enforcement-data-and-results>.

# Compliance Summary Data

| Statute | Source ID | Current SNC (Significant Noncompliance)/HPV (High Priority Violation) | Current As Of | Qtrs with NC (Noncompliance) (of 12) | Data Last Refreshed |
|---|---|---|---|---|---|
| CAA | NY0000003553200136 | No | 04/25/2026 | 0 | 04/24/2026 |

# Three-Year Compliance History by Quarter

| Statute | Program/Pollutant/Violation Type | QTR 1 | QTR 2 | QTR 3 | QTR 4 | QTR 5 | QTR 6 | QTR 7 | QTR 8 | QTR 9 | QTR 10 | QTR 11 | QTR 12+ |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CAA (Source ID: NY0000003553200136) | | 07/01-09/30/23 | 10/01-12/31/23 | 01/01-03/31/24 | 04/01-06/30/24 | 07/01-09/30/24 | 10/01-12/31/24 | 01/01-03/31/25 | 04/01-06/30/25 | 07/01-09/30/25 | 10/01-12/31/25 | 01/01-03/31/26 | 04/01-06/30/26 |
| | Facility-Level Status | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified |
| | HPV History | | | | | | | | | | | | |

| Statute | Program/Pollutant/Violation Type | | | | QTR 1 | QTR 2 | QTR 3 | QTR 4 | QTR 5 | QTR 6 | QTR 7 | QTR 8 | QTR 9 | QTR 10 | QTR 11 | QTR 12+ |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Violation Type | Agency | Programs | Pollutants | | | | | | | | | | | | |

# Informal Enforcement Actions

Last 5 Years

| Statute | System | Source ID | Type of Action | Lead Agency | Date |
|---|---|---|---|---|---|

No data records returned

*Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.*

# Formal Enforcement Actions

Last 5 Years

| Statute | System | Law/ Section | Source ID | Type of Action | Case No. | Lead Agency | Case Name | Issued/ Filed Date | Settlements/ Actions | Settlement/ Action Date | Federal Penalty Assessed | State/ Local Penalty Assessed | Penalty Amount Collected | SEP Value | Comp Action Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|

No data records returned

Environmental Conditions

# Watersheds

| 12-Digit WBD (Watershed Boundary Dataset) HUC (RAD (Reach Address Database)) | WBD (Watershed Boundary Dataset) Subwatershed Name (RAD (Reach Address Database)) | State Water Body Name (ICIS (Integrated Compliance Information System)) | Beach Closures Within Last Year | Beach Closures Within Last Two Years | Pollutants Potentially Related to Impairment | Watershed with ESA (Endangered Species Act)-listed Aquatic Species? |
|---|---|---|---|---|---|---|

No data records returned

# Assessed Waters From Latest State Submission (ATTAINS)

| State | Report Cycle | Assessment Unit ID | Assessment Unit Name | Water Condition | Cause Groups Impaired | Drinking Water Use | Ecological Use | Fish Consumption Use | Recreation Use | Other Use |
|---|---|---|---|---|---|---|---|---|---|---|

No data records returned

# Air Quality Nonattainment Areas

| Pollutant | Within Nonattainment Status Area? | Nonattainment Status Applicable Standard(s) | Within Maintenance Status Area? | Maintenance Status Applicable Standard(s) |
|---|---|---|---|---|
| Ozone | Yes | 1-Hour Ozone (1979); 8-Hour Ozone (2008); 8-Hour Ozone (2015) | No | -- |
| Lead | No | -- | No | -- |
| Particulate Matter | No | -- | Yes | PM-2.5 (1997); PM-2.5 (2006) |
| Carbon Monoxide | No | -- | Yes | Carbon Monoxide (1971) |
| Sulfur Dioxide | No | -- | No | -- |

Pollutants

## Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

| TRI Facility ID | Year | Air Emissions | Surface Water Discharges | Off-Site Transfers to POTWs (Publicly Owned Treatment Works) | Underground Injections | Disposal to Land | Total On-Site Releases | Total Off-Site Transfers |
|---|---|---|---|---|---|---|---|---|

No data records returned

## Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

| Chemical Name |
|---|

No data records returned

Community

## Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2023 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <https://epa.gov/help/reports/dfr-data-dictionary#demographic>.

| General Statistics (ACS (American Community Survey)) | |
|---|---|
| Total Persons | 20,875 |
| Population Density | 7,758/sq.mi. |
| Housing Units in Area | 7,458 |
| Percent People of Color | 65% |
| Households in Area | 7,142 |
| Households on Public Assistance | 268 |
| Persons With Low Income | 5,166 |
| Percent With Low Income | 25% |

| Geography | |
|---|---|
| Radius of Selected Area | 1 mi. |
| Center Latitude | 40.935722 |
| Center Longitude | -73.759215 |
| Total Area | 3.14 sq.mi. |
| Land Area | 86% |
| Water Area | 14% |

| Age Breakdown (ACS (American Community Survey)) - Persons (%) | |
|---|---|
| Children 5 years and younger | 1,456 (7%) |
| Minors 17 years and younger | 4,537 (22%) |
| Adults 18 years and older | 16,341 (78%) |
| Seniors 65 years and older | 2,918 (14%) |

| Race Breakdown (ACS (American Community Survey)) - Persons (%) | |
|---|---|
| White | 9,167 (44%) |
| African-American | 1,433 (7%) |
| Hispanic-Origin | 11,016 (53%) |
| Asian | 745 (4%) |
| Hawaiian/Pacific Islander | 0 (0%) |
| American Indian | 131 (1%) |
| Other/Multiracial | 5,315 (25%) |

| Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%) | |
|---|---|
| Less than 9th Grade | 1,653 (11.29%) |

| Income Breakdown (ACS (American Community Survey)) - Households (%) | |
|---|---|
| Less than $15,000 | 800 (11.2%) |
| $15,000 - $25,000 | 294 (4.12%) |
| $25,000 - $50,000 | 866 (12.13%) |
| $50,000 - $75,000 | 846 (11.85%) |
| Greater than $75,000 | 4,335 (60.71%) |

| Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%) | |
|---|---|
| 9th through 12th Grade | 1,096 (7.48%) |
| High School Diploma | 3,365 (22.98%) |
| Some College/2-year | 1,622 (11.08%) |
| B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More | 5,823 (39.77%) |

United States Environmental Protection Agency

# ICIS-Air Detailed Plant View



## Plant Information

| | |
|---|---|
| **J & F CHATSWORTH AUTO BODY**<br>3 VINE ST<br>LARCHMONT, NY 10538 | |

| | | | |
|---|---|---|---|
| **Operating Status** | OPR | **Operating Status Desc.** | Operating |

| | | | |
|---|---|---|---|
| **Facility ID** | NY0000003553200136 | **State Registration Number** | |
| **Facility Type Code** | POF | **Facility Type Desc.** | Privately Owned Facility |
| **Government Facility Code** | | **Government Facility Description** | |

## NAICS Information

| NAICS Code | NAICS Description |
|---|---|
| 811121 | Automotive Body, Paint, and Interior Repair and Maintenance |

## SIC Information

| SIC Code | SIC Description |
|---|---|
| 7532 | Top & Body Repair & Paint Shops |

## Air Program Information

| Program Code | Program Description | Operating Status | Subpart Code | Subpart Description |
|---|---|---|---|---|
| CAAMACT | MACT Standards (40 CFR Part 63) | Operating | | |
| CAASIP | State Implementation Plan for National Primary and Secondary Ambient Air Quality | Operating | | |

## Air Pollutant Information

| Pollutant Code | Pollutant Description | Chemical Abstract Service (CAS) Number | SRS ID | AIR Pollutant Class Code | AIR Pollutant Class Description |
|---|---|---|---|---|---|
| 300000329 | FACIL | | | MIN | Minor Emissions |

Contact Us <https://www.epa.gov/enviro/forms/contact-us-about-envirofacts> to ask a question, provide feedback, or report a problem.

Last updated on April 22, 2026

United States Environmental Protection Agency

# Multisystem Summary Report



**J & F CHATSWORTH AUTO BODY**
**3 VINE ST**
**LARCHMONT, NY 10538**
**You can navigate within the map with your mouse.*

## ACRES

**No ACRES report found.**

## BR

**No BR report found.**

## SEMS

**No SEMS report found.**

## GHG

**No GHG report found.**

## ICIS-AIR

Facility ID: NY0000003553200136 —

**NAICS Information**

| NAICS Code <https://epa.gov/envirofacts/metadata/column/icis/ref_naics/naics_code> | NAICS Description <https://epa.gov/envirofacts/metadata/column/icis/ref_na |
|---|---|

## SIC Information

| SIC Code <https://epa.gov/envirofacts/metadata/column/icis/ref_sic/sic_code> | SIC Description <https://epa.gov/envirofacts/metadata/column/icis/ref_sic/sic_des |
|---|---|
| 7532 | Top & Body Repair & Paint Shops |

## Air Program Information

| Program Code <https://epa.gov/envirofacts/metadata/column/icis/ref_program/program_code> | Program Description <https://epa.gov/envirofacts/metadata/column/icis/ref |
|---|---|
| CAASIP | State Implementation Plan for National Prir Ambient Air Quality Standards |
| CAAMACT | MACT Standards (40 CFR Part 63) |

## Air Pollutant Information

| Pollutant Code | Pollutant Description | Chemical Abstract Service (CAS) Number | SRS ID | AIR Pollutant Class Code | AIR Pollutant Class Description |
|---|---|---|---|---|---|
| 300000329 | FACIL | | | MIN | Minor Emissions |
| 300000329 | FACIL | | | MIN | Minor Emissions |

### Air Compliance Monitoring Information

No data found.

### Formal Enforcement Information

No data found.

### Informal Enforcement Information

No data found.

### Title V Annual Compliance Certificate (TVACC) Information

No data found.

### Air Stack Test Information

No data found.

# ICIS-NPDES

**No ICIS-NPDES report found.**

# RCRAInfo

**No RCRAInfo report found.**

# TRI

**No TRI report found.**

Contact Us <https://www.epa.gov/enviro/forms/contact-us-about-envirofacts> to ask a question, provide feedback, or report a problem.

Last updated on April 22, 2026

# Detailed Facility Report

Facility Summary

**MAGIC TOUCH CLEANERS**

**5 VINE STREET, LARCHMONT, NY 10538**

**FRS (Facility Registry Service) ID:** 110004313975

**EPA Region:** 02

**Latitude:** 40.93532

**Longitude:** -73.75858

**Locational Data Source:** FRS

**Industries:** Personal and Laundry Services

**Indian Country:** N

# Enforcement and Compliance Summary

| Statute | CAA |
|---|---|
| Compliance Monitoring Activities (5 years) | -- |
| Date of Last Compliance Monitoring Activity | -- |
| Compliance Status | No Violation Identified |
| Qtrs in Noncompliance (of 12) | 0 |
| Qtrs with Significant Violation | 0 |
| Informal Enforcement Actions (5 years) | -- |
| Formal Enforcement Actions (5 years) | -- |
| Penalties from Formal Enforcement Actions (5 years) | -- |
| EPA Cases (5 years) | -- |
| Penalties from EPA Cases (5 years) | -- |

| Statute | RCRA |
|---|---|
| Compliance Monitoring Activities (5 years) | -- |
| Date of Last Compliance Monitoring Activity | -- |
| Compliance Status | No Violation Identified |
| Qtrs in Noncompliance (of 12) | 0 |
| Qtrs with Significant Violation | 0 |
| Informal Enforcement Actions (5 years) | -- |
| Formal Enforcement Actions (5 years) | -- |
| Penalties from Formal Enforcement Actions (5 years) | -- |
| EPA Cases (5 years) | -- |
| Penalties from EPA Cases (5 years) | -- |

## Regulatory Information

**Clean Air Act (CAA):** Operating Minor (NY0000003553200313)

**Clean Water Act (CWA):** No Information

**Resource Conservation and Recovery Act (RCRA):** Inactive Other, (NY0000204958)

**Safe Drinking Water Act (SDWA):** No Information

Go To Enforcement/Compliance Details

Known Data Problems <https://epa.gov/resources/echo-data/known-data-problems>

## Other Regulatory Reports

**Air Emissions Inventory (EIS):** No Information

**Greenhouse Gas Emissions (eGGRT):** No Information

**Toxic Releases (TRI):** No Information

**Compliance and Emissions Data Reporting Interface (CEDRI):** No Information

Facility/System Characteristics

## Facility/System Characteristics

| System | Statute | Identifier | Universe | Status | Areas | Permit Expiration Date | Indian Country | Latitude | Longitude |
|---|---|---|---|---|---|---|---|---|---|
| FRS | | 110004313975 | | | | | N | 40.93532 | -73.75858 |
| ICIS-Air | CAA | NY0000003553200313 | Minor Emissions | Operating | CAAMACT, CAASIP | | N | 40.935512 | -73.758465 |
| RCRAInfo | RCRA | NY0000204958 | Other | Inactive ( ) | | | N | 40.935512 | -73.758465 |

## Facility Address

| System | Statute | Identifier | Facility Name | Facility Address | Facility County |
|---|---|---|---|---|---|
| FRS | | 110004313975 | MAGIC TOUCH CLEANERS | 5 VINE STREET, LARCHMONT, NY 10538 | Westchester County |
| ICIS-Air | CAA | NY0000003553200313 | MAGIC TOUCH CLEANERS | 5 VINE ST, LARCHMONT, NY 105382328 | Westchester County |
| RCRAInfo | RCRA | NY0000204958 | MAGIC TOUCH | 5 VINE ST, LARCHMONT, NY 10538 | Westchester County |

## Facility SIC (Standard Industrial Classification) Codes

| System | Identifier | SIC Code | SIC Description |
|---|---|---|---|
| ICIS-Air | NY0000003553200313 | 7216 | Drycleaning Plants, Except Rug |

## Facility NAICS (North American Industry Classification System) Codes

| System | Identifier | NAICS Code | NAICS Description |
|---|---|---|---|
| ICIS-Air | NY0000003553200313 | 812320 | Drycleaning and Laundry Services (except Coin-Operated) |

## Facility Tribe Information

| Reservation Name | Tribe Name | EPA Tribal ID | Distance to Tribe (miles) |
|---|---|---|---|

No data records returned

Enforcement and Compliance

# Compliance Monitoring History

Last 5 Years

| Statute | Source ID | System | Activity Type | Compliance Monitoring Type | Lead Agency | Date | Finding (if applicable) |
|---|---|---|---|---|---|---|---|

No data records returned

*Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy* <https://www.epa.gov/compliance/compliance-monitoring-programs> *activities or because they are not counted as inspections within EPA's Annual Results* <https://www.epa.gov/enforcement/enforcement-data-and-results>.

# Compliance Summary Data

| Statute | Source ID | Current SNC (Significant Noncompliance)/HPV (High Priority Violation) | Current As Of | Qtrs with NC (Noncompliance) (of 12) | Data Last Refreshed |
|---|---|---|---|---|---|
| CAA | NY0000003553200313 | No | 04/25/2026 | 0 | 04/24/2026 |
| RCRA | NY0000204958 | No | 04/25/2026 | 0 | 04/24/2026 |

# Three-Year Compliance History by Quarter

| Statute | Program/Pollutant/Violation Type | QTR 1 | QTR 2 | QTR 3 | QTR 4 | QTR 5 | QTR 6 | QTR 7 | QTR 8 | QTR 9 | QTR 10 | QTR 11 | QTR 12+ |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CAA (Source ID: NY0000003553200313) | | 07/01-09/30/23 | 10/01-12/31/23 | 01/01-03/31/24 | 04/01-06/30/24 | 07/01-09/30/24 | 10/01-12/31/24 | 01/01-03/31/25 | 04/01-06/30/25 | 07/01-09/30/25 | 10/01-12/31/25 | 01/01-03/31/26 | 04/01-06/30/26 |
| | Facility-Level Status | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified |
| | HPV History | | | | | | | | | | | | |

| | Violation Type | Agency | Programs | Pollutants |
|---|---|---|---|---|

| Statute | Program/Pollutant/Violation Type | QTR 1 | QTR 2 | QTR 3 | QTR 4 | QTR 5 | QTR 6 | QTR 7 | QTR 8 | QTR 9 | QTR 10 | QTR 11 | QTR 12+ |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RCRA (Source ID: NY0000204958) | | 07/01-09/30/23 | 10/01-12/31/23 | 01/01-03/31/24 | 04/01-06/30/24 | 07/01-09/30/24 | 10/01-12/31/24 | 01/01-03/31/25 | 04/01-06/30/25 | 07/01-09/30/25 | 10/01-12/31/25 | 01/01-03/31/26 | 04/01-06/30/26 |
| | Facility-Level Status | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified | No Violation Identified |

| | Violation | Agency |
|---|---|---|

# Informal Enforcement Actions

Last 5 Years

| Statute | System | Source ID | Type of Action | Lead Agency | Date |
|---|---|---|---|---|---|

No data records returned

*Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.*

## Formal Enforcement Actions

Last 5 Years

| Statute | System | Law/ Section | Source ID | Type of Action | Case No. | Lead Agency | Case Name | Issued/ Filed Date | Settlements/ Actions | Settlement/ Action Date | Federal Penalty Assessed | State/ Local Penalty Assessed | Penalty Amount Collected | SEP Value | Comp Action Cost |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|

No data records returned

Environmental Conditions

## Watersheds

| 12-Digit WBD (Watershed Boundary Dataset) HUC (RAD (Reach Address Database)) | WBD (Watershed Boundary Dataset) Subwatershed Name (RAD (Reach Address Database)) | State Water Body Name (ICIS (Integrated Compliance Information System)) | Beach Closures Within Last Year | Beach Closures Within Last Two Years | Pollutants Potentially Related to Impairment | Watershed with ESA (Endangered Species Act)-listed Aquatic Species? |
|---|---|---|---|---|---|---|

No data records returned

## Assessed Waters From Latest State Submission (ATTAINS)

| State | Report Cycle | Assessment Unit ID | Assessment Unit Name | Water Condition | Cause Groups Impaired | Drinking Water Use | Ecological Use | Fish Consumption Use | Recreation Use | Other Use |
|---|---|---|---|---|---|---|---|---|---|---|

No data records returned

## Air Quality Nonattainment Areas

| Pollutant | Within Nonattainment Status Area? | Nonattainment Status Applicable Standard(s) | Within Maintenance Status Area? | Maintenance Status Applicable Standard(s) |
|---|---|---|---|---|
| Ozone | Yes | 1-Hour Ozone (1979); 8-Hour Ozone (2008); 8-Hour Ozone (2015) | No | -- |
| Lead | No | -- | No | -- |
| Particulate Matter | No | -- | Yes | PM-2.5 (1997); PM-2.5 (2006) |
| Carbon Monoxide | No | -- | Yes | Carbon Monoxide (1971) |
| Sulfur Dioxide | No | -- | No | -- |

Pollutants

## Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

| TRI Facility ID | Year | Air Emissions | Surface Water Discharges | Off-Site Transfers to POTWs (Publicly Owned Treatment Works) | Underground Injections | Disposal to Land | Total On-Site Releases | Total Off-Site Transfers |
|---|---|---|---|---|---|---|---|---|

No data records returned

## Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

| Chemical Name |
|---|

No data records returned

Community

# Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2023 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <https://epa.gov/help/reports/dfr-data-dictionary#demographic>.

| General Statistics (ACS (American Community Survey)) | |
|---|---|
| Total Persons | 20,774 |
| Population Density | 7,840/sq.mi. |
| Housing Units in Area | 7,399 |
| Percent People of Color | 66% |
| Households in Area | 7,090 |
| Households on Public Assistance | 273 |
| Persons With Low Income | 5,200 |
| Percent With Low Income | 25% |

| Geography | |
|---|---|
| Radius of Selected Area | 1 mi. |
| Center Latitude | 40.93532 |
| Center Longitude | -73.75858 |
| Total Area | 3.14 sq.mi. |
| Land Area | 84% |
| Water Area | 16% |

| Income Breakdown (ACS (American Community Survey)) - Households (%) | |
|---|---|
| Less than $15,000 | 798 (11.27%) |
| $15,000 - $25,000 | 298 (4.21%) |
| $25,000 - $50,000 | 854 (12.06%) |
| $50,000 - $75,000 | 832 (11.75%) |
| Greater than $75,000 | 4,300 (60.72%) |

| Age Breakdown (ACS (American Community Survey)) - Persons (%) | |
|---|---|
| Children 5 years and younger | 1,461 (7%) |
| Minors 17 years and younger | 4,501 (22%) |
| Adults 18 years and older | 16,271 (78%) |
| Seniors 65 years and older | 2,900 (14%) |

| Race Breakdown (ACS (American Community Survey)) - Persons (%) | |
|---|---|
| White | 9,025 (43%) |
| African-American | 1,438 (7%) |
| Hispanic-Origin | 11,077 (53%) |
| Asian | 726 (3%) |
| Hawaiian/Pacific Islander | 0 (0%) |
| American Indian | 143 (1%) |
| Other/Multiracial | 5,367 (26%) |

| Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%) | |
|---|---|
| Less than 9th Grade | 1,676 (11.49%) |
| 9th through 12th Grade | 1,104 (7.57%) |
| High School Diploma | 3,377 (23.14%) |
| Some College/2-year | 1,623 (11.12%) |
| B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More | 5,722 (39.21%) |

**Related Topics:** Envirofacts

FRS

# FRS Facility Detail Report

## MAGIC TOUCH CLEANERS

**EPA Registry Id:** 110004313975
5 VINE STREET
LARCHMONT, NY 10538-2328




**Legend**

- Selected Facility
- EPA Facility of Interest
- State/Tribe Facility of Interest

The facility locations displayed come from the FRS Spatial Coordinates tables. They are the best representative locations for the displayed facilities based on the accuracy of the collection method and quality assurance checks performed against each location. The North American Datum of 1983 is used to display all coordinates.

## Facility Registry Service Links:

- Facility Registry Service (FRS) Overview
- FRS Facility Query
- FRS Organization Query
- EZ Query
- FRS Physical Data Model
- FRS Geospatial Model

# Environmental Interests

| Information System | System Facility Name | Information System Id/Report Link | Environmental Interest Type | Data Source | Last Updated Date | Supplemental Environmental Interests: |
|---|---|---|---|---|---|---|
| AIR FACILITY SYSTEM | MAGIC TOUCH CLEANERS | 36119R2320 | AIR MINOR (OPERATING) | AIRS/AFS | 05/07/2014 | |
| ICIS-AIR (AIR) | MAGIC TOUCH CLEANERS | NY0000003553200313 | AIR MINOR | ICIS | 10/19/2014 | |
| NEW YORK - FACILITY INFORMATION SYSTEM | MAGIC TOUCH CLEANERS | 3-5532-00313 | STATE MASTER | FIS | | **FIS**-3-5532-00313/00001 AIR PROGRAM **FIS**-R2320 AIR PROGRAM |
| RESOURCE CONSERVATION AND RECOVERY ACT INFORMATION SYSTEM | MAGIC TOUCH | NY0000204958 | UNSPECIFIED UNIVERSE (N) | RCRAINFO | | |

**Additional EPA Reports:** MyEnvironment Enforcement and Compliance Facility Coordinates Viewer Watershed Report

### Standard Industrial Classification Codes (SIC)

| Data Source | SIC Code | Description | Primary |
|---|---|---|---|
| AIRS/AFS | 7216 | DRYCLEANING PLANTS, EXCEPT RUG CLEANING | |
| FIS | 7216 | DRYCLEANING PLANTS, EXCEPT RUG CLEANING | |

### Facility Codes and Flags

| | |
|---|---|
| **EPA Region:** | 02 |
| **Duns Number:** | |
| **Congressional District Number:** | 16 |
| **Legislative District Number:** | NY |
| **HUC Code/Watershed:** | 02030102 / BRONX |
| **US Mexico Border Indicator:** | |
| **Federal Facility:** | NO |
| **Tribal Land:** | NO |

### Alternative Names

| Alternative Name | Source of Data |
|---|---|
| MAGIC TOUCH | NOTIFICATION (RCRA) |

### Organizations

| Affiliation Type | Name | DUNS Number | Information System | Mailing Address |
|---|---|---|---|---|
| OWNER | KWANG JIN KIM | | RCRAINFO | View |
| OWNER | YOON S KIM | | RCRAINFO | View |
| OPERATOR | KWANG JIN KIM | | RCRAINFO | View |
| OPERATOR | YOON S KIM | | RCRAINFO | View |

### National Industry Classification System Codes (NAICS)

| Data Source | NAICS Code | Description | Primar |
|---|---|---|---|
| FIS | 81232 | DRYCLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED) | |
| AIRS/AFS | 812320 | DRYCLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED). | |

### Facility Mailing Addresses

| Affiliation Type | Delivery Point | City Name | State | Postal Code | Information Systen |
|---|---|---|---|---|---|
| OPERATOR | 330 FORT LEE RD | LEONIA | NJ | 07605 | RCRAINFO |
| OWNER | 175 HALSTEAD AVE | HARRISON | NY | 10528 | RCRAINFO |
| OPERATOR | 175 HALSTEAD AVE | HARRISON | NY | 10528 | RCRAINFO |
| REGULATORY CONTACT | 5 VINE ST | LARCHMONT | NY | 10538 | RCRAINFO |
| REGULATORY CONTACT | 7-11 NORTH AVE | LARCHMONT | NY | 10504 | RCRAINFO |
| FACILITY MAILING ADDRESS | 5 VINE ST | LARCHMONT | NY | 10538 | RCRAINFO |
| OWNER | 330 FORT LEE RD | LEONIA | NJ | 07605 | RCRAINFO |

### Contacts

| Affiliation Type | Full Name | Office Phone | Information System | Mailing Address |
|---|---|---|---|---|
| FEES/BILLING CONTACT | KWANG JIN KIM | 9148348880 | FIS | |
| REGULATORY CONTACT | KWANG KIM | 917-834-8880 | RCRAINFO | View |
| REGULATORY CONTACT | KWANG KIM | 917-834-8880 | RCRAINFO | View |

Query executed on: APR-28-2026

United States Environmental Protection Agency

# Multisystem Summary Report



**MAGIC TOUCH CLEANERS**
**5 VINE STREET**
**LARCHMONT, NY 10538-2328**
**You can navigate within the map with your mouse.*

## ACRES

**No ACRES report found.**

## BR

**No BR report found.**

## SEMS

**No SEMS report found.**

## GHG

**No GHG report found.**

## ICIS-AIR

Facility ID: NY0000003553200313 —

**Operating Status Code:** OPR

**Operating Status Desc:** Operating

**Facility ID:** NY0000003553200313

**State Registration Number:** 3553200313

**Facility Type Code:** POF

**Facility Type Desc:** Privately Owned Facility

**Government Facility Code:**

**Government Facility Description:**

### NAICS Information

| NAICS Code <https://epa.gov/envirofacts/metadata/column/icis/ref_naics/naics_code> | NAICS Description <https://epa.gov/envirofacts/metadata/column/icis/ref_na |
|---|---|
| 812320 | Drycleaning and Laundry Services [except Coi |

## SIC Information

| SIC Code <https://epa.gov/envirofacts/metadata/column/icis/ref_sic/sic_code> | SIC Description <https://epa.gov/envirofacts/metadata/column/icis/ref_sic/sic_des |
|---|---|
| 7216 | Drycleaning Plants, Except Rug |

## Air Program Information

| Program Code <https://epa.gov/envirofacts/metadata/column/icis/ref_program/program_code> | Program Description <https://epa.gov/envirofacts/metadata/column/icis/ref |
|---|---|
| CAAMACT | MACT Standards (40 CFR Part 63) |
| CAASIP | State Implementation Plan for National Prir Ambient Air Quality Standards |

## Air Pollutant Information

| Pollutant Code | Pollutant Description | Chemical Abstract Service (CAS) Number | SRS ID | AIR Pollutant Class Code | AIR Pollutant Class Description |
|---|---|---|---|---|---|
| 300000074 | Tetrachloroethylene | 127184 | 34157 | MIN | Minor Emissions |
| 300000074 | Tetrachloroethylene | 127184 | 34157 | MIN | Minor Emissions |
| 300000242 | TOTAL HAZARDOUS AIR POLLUTANTS (HAPS) | | 761502 | MIN | Minor Emissions |
| 300000242 | TOTAL HAZARDOUS AIR POLLUTANTS (HAPS) | | 761502 | MIN | Minor Emissions |
| 300000329 | FACIL | | | MIN | Minor Emissions |
| 300000329 | FACIL | | | MIN | Minor Emissions |

### Air Compliance Monitoring Information

No data found.

### Formal Enforcement Information

No data found.

### Informal Enforcement Information

No data found.

### Title V Annual Compliance Certificate (TVACC) Information

No data found.

### Air Stack Test Information

No data found.

## ICIS-NPDES

**No ICIS-NPDES report found.**

# RCRAInfo

Handler ID: NY0000204958 —

**Handler ID:** <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_handler/handler_id> NY0000204958

## List of Naics Codes and Descriptions

**No NAICS Codes are available for the facility listed above.**

### Handler / Facility Classification

**Unspecified Universe for the facility listed above.**

| **Handler Type** <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_reporting/in_a_universe> |
| --- |
| Not in a universe |

Additional information can be obtained from Resource Conservation and Recovery Information (RCRAInfo) Search.

# TRI

**No TRI report found.**

Contact Us <https://www.epa.gov/enviro/forms/contact-us-about-envirofacts> to ask a question, provide feedback, or report a problem.

Last updated on April 22, 2026

No selections applied

# PFAS Analytic Tools

More Information

Legend and Layers

**Scope of Drinking Water Samples for Public Water Systems (PWSs):**

Most Recent Sample at PWS

All Samples at PWS

**PWS-Reported Potential PFAS Sources:**

All

**Filters:**

EPA Region

State Territory or Tribe

**Include Non-Detects:**

No



No selections applied

**Scope of Drinking Water Samples for Public Water Systems (PWSs):**

**PWS-Reported Potential PFAS Sources:**

**Filters:**

**EPA Region**

**State Territory or Tribe**

## Include Non-Detects:

No

No selections applied

# PFAS Analytic Tools

More Information

Legend and Layers

**Scope of Drinking Water Samples for Public Water Systems (PWSs):**

(https://echo.epa.gov/trends/pfas-tools-faqs)

Most Recent Sample at PWS

PFAS Monitoring Data (https://echo.epa.gov/trends/pfas-tools)

All Samples at PWS

**PWS-Reported Potential PFAS Sources:**

All

**Filters:**

EPA Region

State Territory or Tribe

**Include Non-Detects:**

No



No selections applied

**Scope of Drinking Water Samples for Public Water Systems (PWSs):**

**PWS-Reported Potential PFAS Sources:**

**Filters:**

**EPA Region**

**State Territory or Tribe**

## Include Non-Detects:

No

United States Environmental Protection Agency

# MyProperty Search Results



## No Information Found for the Submitted Address

No records were found within the EPA's Facility Registry System (FRS) list of address records for the provided search location. The No Records <https://epa.gov/envirofacts/embed/myproperty/certificate/1%20vine%20street/larchmont/ny> is a link to a printable document stating that no record(s) were found for the provided search location.

You searched on:
**Address Searched**: 1 Vine Street
**City Searched**: Larchmont
**State Searched**: NY

**WARNING:**

The address entered could not be matched exactly against the EPA's Facility Registry System (FRS) list of address records. Please make sure you have entered the address correctly for the location you are interested in.

If you would like to utilize additional search tools to investigate areas of interest, please visit the Envirofacts Multisystem Search <https://epa.gov/envirofacts/multisystem/search> or the Facility Registry System <https://www.epa.gov/frs/frs-query>

---

**Disclaimer:** The MyProperty reports are provided solely for informational purposes. They do not provide legal advice, have legally binding effect, or expressly or implicitly create, expand, or limit any legal rights, obligations, responsibilities, expectations, or benefits in regard to any person. EPA maintains the application to enhance public access to environmental information. This service has continual data updates, and we will correct errors brought to our attention, as appropriate.

Contact Us <https://www.epa.gov/enviro/forms/contact-us-about-envirofacts> to ask a question, provide feedback, or report a problem.

Last updated on April 22, 2026

United States Environmental Protection Agency

# MyProperty Search Results



## Information Found for the Submitted Address

The entered address was found within the EPA Facility Registry System (FRS) list of address records.

You searched on:
**Address Searched**: 5 Vine Street
**City Searched**: Larchmont
**State Searched**: NY

| Facility Name | Address | City | State | Postal Code |
|---|---|---|---|---|
| MAGIC TOUCH CLEANERS Facility Report Summary Report | 5 VINE | LARCHMONT | NY | 10538 |

**Note:** Click on the above Facility Report link to view a detailed list of known EPA and State Environmental Interests.
Click on the above Summary Report link to view environmental activities by this facility that may affect air, water, and land.
Click on the above Compliance Report link to view the current and past compliance history of this facility.

---

**Disclaimer:** The MyProperty reports are provided solely for informational purposes. They do not provide legal advice, have legally binding effect, or expressly or implicitly create, expand, or limit any legal rights, obligations, responsibilities, expectations, or benefits in regard to any person. EPA maintains the application to enhance public access to environmental information. This service has continual data updates, and we will correct errors brought to our attention, as appropriate.

Contact Us <https://www.epa.gov/enviro/forms/contact-us-about-envirofacts> to ask a question, provide feedback, or report a problem.

Last updated on April 22, 2026

# Phase I Environmental Site Assessment

**1-5 Vine Street**
**Larchmont, New York 10538**

APECCO Project #221011E

Prepared For
Mr. Vincent Sparano
1-5 Vine Street
Larchmont, New York

Prepared By

63 Orange Avenue,
Walden, New York 12586

November 30, 2022

# Table of Contents

**1.0 INTRODUCTION ..... 5**

1.1 Purpose ..... 5

1.2 Scope of Services ..... 5

1.3 Qualifications ..... 6

1.4 Significant Assumptions ..... 6

1.5 Limitations and Exceptions of Assessment ..... 6

1.6 Deviations ..... 7

1.7 Reliance ..... 7

**2.0 SITE DESCRIPTION ..... 7**

2.1 Site Location ..... 7

2.2 Current Site Operations ..... 7

2.3 General Site Configuration ..... 8

2.4 Site Utilities ..... 8

2.5 Topographic Description ..... 8

2.6 Site Soils and Geology ..... 8

2.7 Site Hydrology ..... 8

2.8 Adjacent Land Uses ..... 8

**3.0 USER PROVIDED INFORMATION ..... 8**

3.1 Title records ..... 9

3.2 Environmental Liens or Activity and Use Limitations (AULs) ..... 9

3.3 Specialized Knowledge ..... 9

3.4 Reasonably Ascertainable Information ..... 9

3.5 Valuation Reduction for Environmental Issues ..... 9

3.6 Reason for Performing the Phase I ESA ..... 9

**4.0 SITE AND SURROUNDING AREA HISTORICAL REVIEW ..... 9**

4.1 Summary ..... 9

4.1.1 Site ..... 10

4.1.2 Adjoining/Surrounding Properties ..... 10

4.2 Title Search Information ..... 10

4.3 Sanborn Fire Insurance Maps ..... 10

4.4 Aerial Photographs ....10
4.5 USGS Topography Maps ....11
4.6 Municipal Records/ Local Government Interviews ....11
4.6.1 Assessor's Office ....11
4.6.2 Building Department....11
4.6.3 Town Clerk....11
4.7 Owner, Operator and Occupant Interviews ....11
4.7.1 Property Owner/Key Site Representative ....12
4.7.2 Current Operators and/or Site Occupants....12
4.7.3 Past Owners, Occupants, and Operators....12
4.8 Previous Environmental Investigations ....12
4.8.1 Tank Removal Report/ Spill Closure Report……..……12
**5.0 ENVIRONMENTAL REGULATORY AGENCY RECORD REVIEW....12**
5.1 Standard ASTM Environmental Record Review....14
5.2 Information from Regulatory Agency Officials ....14
5.2.1 County Department of Health ....14
5.2.2 New York State Department of Environmental Conservation ....14
**6.0 SITE RECONNAISSANCE ....14**
6.1 Conditions of Reconnaissance ....14
6.2 Site Waste Profile....16
6.3 Site Drainage....16
**7.0 OBSERVATIONS OF MOLD AND POTENTIAL WATER INTRUSION....17**
**8.0 REPORT FINDINGS, OPINIONS AND CONCLUSIONS....17**
8.1 Findings and Opinions....17
8.2 Conclusions and Recommendations ....17
**9.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS ....18**

**APPENDICES**

Appendix A: Site Photographs
Appendix B: Site Maps
- Figure 1: Site Location Map
- Figure 2: Tax Map
- Figure 3: State Wetland Map
- Figure 4: Federal Wetland Map
- Figure 5: Soil Map

Appendix C: Historical Resources
- Historic Aerial Photographs
- Historic Topographic Maps

Appendix D: Environmental Database Report
- EDR Radius Map Report with GeoCheck
- Sanborn Fire Insurance Maps
- City Directories

Appendix E: Interview Documentation
- Owner Questionnaire
- Municipal FOIL
- DEC FOIL

Appendix E: Previous Studies

## 1.0 INTRODUCTION

American Petroleum was retained by Mr. Vincent Sparano to conduct a Phase I Environmental Site Assessment (ESA), in conformance with the scope and limitations of ASTM Standard Practice E1527-21 and the Environmental Protection Agency and Standards and Practices for all Appropriate Inquiries (40 CFR Part 312) for the property located at 1-5 Vine Street in the Town of Mamaroneck, Westchester County, New York ("the Site"). The Site's postal address is listed in the Town of Larchmont, Westchester County, New York. The Site is a 0.34-acre property developed with a commercial building.

### 1.1 Purpose

The purpose of this Phase I ESA is to investigate and identify recognized environmental conditions (RECs) and controlled recognized environmental conditions (CRECs) associated with the subject property and/or surrounding properties.

ASTM Standard Practice E1527-21 defines **REC**s as: (1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment. A de minimis condition is not a REC. De minimis conditions relate to a release that generally do not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies.

ASTM Standard Practice E1527-21 defines **CREC**s as: REC affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to implementation of required controls.

ASTM Standard Practice E1527-21 defines **HREC**s as: a previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls (for example, activity and use limitations or other property use limitations). A HREC is not a REC.

### 1.2 Scope of Service

The scope of this Phase I Environmental Assessment included the following sources of information.

A) Historical Sanborn fire insurance maps, historic aerial photographs, historic topographic maps, city directories and local municipal information to assess historic site uses.

B) Reasonably ascertainable federal and state Standard Environmental Record Sources to approximate
minimum search distances as defined by ASTM E1527-21 as provided by EDR Lightbox
C) Interviews with the site owner and local regulators
D) A visual site reconnaissance of the subject property and facilities and improvements on the subject property, including: review of on-site topography; assessment of chemical use, hazardous waste handling/disposal practices on the subject property; assessment of the presence or likely presence of a release or threatened release of hazardous substances and/or non-hazardous waste; review of suspect PCBs; review of bulk storage tanks including ASTs and USTs; and a visual review of immediately adjacent properties from the subject property.
E) While not included in the ASTM standard, American Petroleum's site reconnaissance also included a cursory visual inspection of the subject property, facilities and improvements for suspect mold, ACMs and lead-based painted surfaces. Such should not be considered a complete inspection for these items.

### 1.3 Qualifications

This Phase I ESA has been conducted under the supervision of a qualified environmental professional with the required level of education in an environmental field of study and experience in the performance of Phase I ESAs and ASTM Standard requirements. These qualifications are consistent with environmental professional requirements referenced in the ASTM E 1527-21 standard.

### 1.4 Significant Assumptions

American Petroleum (APECCO) relied on information derived from the secondary sources including governmental agencies, the client, the owner, computer databases, and personal interviews. APECCO has reviewed and evaluated the depth and reliability of the information derived from secondary sources. Although all information appears to be reliable, APECCO cannot guarantee the thoroughness or reliability of this information.

### 1.5 Limitations and Exceptions of Assessment

As regulations and site conditions change significantly over time, the recommendations and conclusions presented in this study apply directly to on site conditions at the time at which the inspection was performed.

In addition to the limitations set forth in the ASTM E 1527-21 protocol, the accuracy and completeness of this report may be limited by the following: on-site access limitations, physical obstructions, outstanding information requests, historical data source failure, or any other factors.

It should be noted that this assessment did not include a review or audit of operational environmental compliance issues, or of any environmental management systems (EMS) that may

exist on the property. Although attempts were made, whenever possible, to obtain a minimum of two confirmatory sources of information, American Petroleum in certain instances has been required to assume that the information provided is accurate.

The information and conclusions contained in this report represent the best judgment of American Petroleum based on the data obtained from the work. Due to the nature of investigation and the limited data available, American Petroleum cannot warrant against undiscovered environmental liabilities. Conclusions and recommendations presented in this report should not be construed as legal advice. Should additional information become available which differs significantly from our understanding of conditions presented in this report, we request that this information be brought to our attention so that we may reassess the conclusions provided herein.

Responses received from local, state, or federal agencies or other secondary sources of information after the issuance of this report may change certain findings and therefore the conclusions and recommendations.

### 1.6 Deviations

No deviations from the recommended scope of ASTM Standard E 1527-21 were performed as part of this Phase I ESA with the exception of any additions noted in Detailed Scope of Services.

### 1.7 Reliance

This report has been prepared for the sole benefit of the client. The report may not be relied upon by any other person or entity without the express written consent of American Petroleum and the client.

## 2.0 SITE DECRIPTION

### 2.1 Site Location

The Subject Property is located on the northern side of Vine Street in a predominantly residential neighborhood. The property totals approximately 0.34 acres and is improved by one single-story building with two partial basements totaling approximately 11,958 square feet. The property is further identified as Tax ID 1-26-730 on the Town of Mamaroneck tax map **(Appendix B Figure 2**). A Site Location Map is attached **(Appendix B Figure 2)**.

### 2.2 Current Site Operations

Current on-site tenants include J&F Chatsworth Auto Repair, J&F Chatsworth Auto Body Ltd., and Magic Touch Dry Cleaning and Tailoring. On-site operations include auto repair, auto body repair, and dry cleaning. In addition to the subject building, the property is improved with an asphalt paved parking area south of the subject building. Site reconnaissance photographs depicting property conditions are attached **(Appendix A)**.

### 2.3 General Site Configuration

The Site is a predominantly rectangular-shaped parcel substantially covered by the commercial structure. The site is accessed via Vine Street on the southern side of the property.

### 2.4 Site Utilities

The subject property was provided with all public utilities, including natural gas and electricity from Con Edison, municipal water from Westchester Joint Waterwork, and municipal sanitary sewer from the Town of Mamaroneck. Supplemental heat is provided by a waste oil burner within the auto repair shop.

### 2.5 Topographic Description

The area topography was used to estimate surface and groundwater flow directions in order to judge the likelihood of contaminate migration onto, or from, the subject property. Site topography is relatively flat with a gradual downward slope to the southwest. Site elevation varies form 12-15 meters above sea-level. Based on a review of surface topography, groundwater is estimated to flow to the southeast towards The Little Harbor Sound.

### 2.6 Site Soils and Geology

A review of the Surficial Geologic Map of New York (Lower Hudson Sheet, 1995) indicates that surficial soils in the area of the Site are mapped as Urban Land predominantly composed of till **(Appendix B Figure 5)**. Site bedrock is mapped on the Geologic Map of New York (Lower Hudson Sheet, 1995) as the Hartland Formation – basal amphibolite overlain by pelitic schists.

### 2.7 Site Hydrology

The subject property does not appear to have any open water bodies or surficial water bodies located on-site. Surface drainage appears to flow in a direction toward the lowest elevated points on-site and/or toward the closest storm drains off-site. Groundwater flow direction would be presumed to flow down the local topographic gradient.

### 2.8 Adjacent Land Uses

| Adjacent Property | Property Description |
|---|---|
| North | Town of Mamaroneck Public Parking Lot |
| East | New England Thruway (Interstate 95) |
| South | Memorial Park |
| West | Town of Mamaroneck Public Parking Lot |

## 3.0 USER PROVIDED INFORMATION

American Petroleum submitted a Phase I Owner Questionnaire to Mr. Vincent Sparano, owner representative and tenant of the subject property, to complete on behalf of the owner. A copy of the owner questionnaire is attached **(Appendix E)**.

### 3.1 Title Records

Title Records were not provided to American Petroleum.

### 3.2 Environmental Liens or Activity and Use Limitations (AULs)

Mr. Sparano is unaware of any environmental liens and AULs associated with subject property.

### 3.3 Specialized Knowledge

The owner representative provided information on an air emissions permit from the Westchester County Board of Heath for the Spray Booth located within J&F Chatsworth Autobody. The permit was not provided.

No additional specialized knowledge was provided.

### 3.4 Reasonably Ascertainable Information

The owner indicated that the property was previously used as a gasoline fueling station, auto repair shop, and a tailor. He is aware of one NYSDEC spill regarding the previous fueling station USTs in the 1990's. Remediation was completed and the spill was closed.

### 3.5 Valuation Reduction for Environmental Issues

American Petroleum has not conducted an analysis of potential purchase price.

### 3.6 Reason for Performing the Phase I ESA

The Phase I ESA is being performed to evaluate the present environmental status of the Site.

## 4.0 SITE AND SURROUNDING AREA HISTORICAL REVIEW

### 4.1 Summary

4.1.1 Site

Based on historical resources reviewed, including historic aerial photographs and local agencies, the current subject building was constructed in 1930 and originally used as a garage. Between 1942 and 1950, a southern portion of the building was modified and removed. Prior to construction of the current building, the property appeared to be undeveloped. Historic property uses prior to 1911 were not reasonably ascertainable.

4.1.2 Adjoining/Surrounding Properties

Based on the historical sources reviewed, the surrounding area has historically been commercial and residential. According to Sanborn maps, the southwestern adjacent property has been used as a town park since 1934.

### 4.2 Title Search Information

Information provided by the Town of Mamaroneck PROS Property Search indicates that the property has been owned by Mansisbro Inc. since 1979. From at least 1969 to 1978, the subject property was owned by Sarah and Arnold Mancini. No prior ownership records were provided.

### 4.3 Sanborn Fire Insurance Maps

Environmental Data Resources, Inc. (EDR), owner of the historic Sanborn Fire Insurance Map collection, was contacted to provide Sanborn Fire Insurance Maps **(Appendix D).** Fire insurance maps indicate the historic property uses of the subject property and the adjacent properties.

Provided below is a summary of the information obtained from the analysis of these maps.

| Date | Subject Property | Adjacent Properties |
|---|---|---|
| 1911 | Not listed | Not listed |
| 1919 | Vacant lot | Commercial & Railroad |
| 1934 | Current structure - garage | Vacant and Railroad |
| 1942 | Current structure - car wash | Vacant and Railroad |
| 1950 | Current structure – garage & fueling station | Vacant and Railroad |
| 1963 | Current structure – garage & fueling station | Vacant and Interstate |
| 1988 | Current structure – garage, car wash, & dry cleaning | Parking Lot and Interstate |
| 1992 | Current structure – garage, car wash, & dry cleaning | Parking Lot and Interstate |
| 1994 | Current structure – garage, car wash, & dry cleaning | Parking Lot and Interstate |
| 1995 | Current structure – garage, car wash, & dry cleaning | Parking Lot and Interstate |
| 1996 | Current structure – garage, car wash, & dry cleaning | Parking Lot and Interstate |
| 2003 | Current structure – garage, car wash, & dry cleaning | Parking Lot and Interstate |

### 4.4 Aerial Photographs

Aerial photographs were obtained from EDR. Analysis of photographs from 1951, 1953, 1962, 1964, 1974, 1980, 1985, 1994, 2006, 2009, 2013, and 2017 was completed **(Appendix D).** The current structure has been on site since 1951. Adjacent properties include a municipal park, a train station, public parking lot and wooded land from 1951 to 1953. Between the years 1963 and 2017, adjacent properties include a municipal park, public parking lots, and a raised highway.

## 4.5 USGS Topography Maps

Topographic maps were obtained from EDR **(Appendix C)**. The maps indicates that the subject property was developed with one structure (presumably the existing commercial building) since 1947.

## 4.6 Municipal Records/ Local Government Interviews

4.6.1 Assessor's Office

Assessment information and the historic property card was provided by the Town of Mamaroneck assessor's office on November 15, 2022 **(Appendix E)**.

4.6.2 Building Department

A request for information was sent to the Town of Mamaroneck Building Department on November 29, 2022. As of date, no response has been received.

4.6.3 Town of Mamaroneck Clerk

A request for information was sent to the Town of Mamaroneck Town Clerk on November 25, 2022. As of date, no response has been received.

## 4.7 Owner, Operator and Occupant Interviews

4.7.1 Property Owner/Key Site Representative

Mr. Vincent Sparano, owner representative and current tenant, accompanied American Petroleum during the site investigation. According to Mr. Sparano, the property was purchased by his parents in the early 1980's. At the time of purchase, the property was used as a gas station, an auto repair shop, and a tailor. In the 1990's, a spill reported to the DEC associated with the gas station USTs. During remedial work, the owner encountered additional unregistered USTs. Mr. Sparano stated that the spill was remediated and the tanks were removed. Database listing provided by EDR record the tank removals.

4.7.2 Current Operators and/or Site Occupants

Magic Touch Cleaners currently occupies the westernmost tenant space in the building, 1 Vine Street. The remaining portions of the building are occupied by J&F Chatsworth Autobody and J&F Chatsworth Auto Repair. According to Mr. Sparano, Magic Touch Cleaners holds a monthly lease.

4.7.3 Past Owners, Occupants, and Operators

ASTM E 1527-21 states that interviews be conducted with past owners, operators, and occupants who are likely to have material information regarding the potential for contamination at the property to the extent that 1) they have been identified and 2) the information likely to be obtained is not duplicative of information already obtained from other sources.

The previous owners, Sarah and Arnold Mancini, were identified through the historic property card provided by the Town of Mamaroneck. No contact information was found or provided.

### 4.8 Previous Environmental Investigations

4.8.1 Tank Removal Report/ Spill Closure Report

A July 2015 report, *Underground Storage Tank Removal Report (NYSDEC PBS #3-174394, Spill #15-01291)* completed by American Petroleum Equipment & Construction Company Inc. sent to the NYSDEC, was reviewed. On May 7, 2015, American Petroleum completed the removal of two (2) 4,000-gallon double-walled, steel gasoline USTs. Groundwater was encountered during UST removal. The tanks were removed in "good" condition. Based upon elevated PID levels of the excavation soils, the NYSDEC was called and Spill #15-01291 was assigned. Roughly 11-tons of petroleum impacted soil was remediated form the site. Due to the presence of a historic foundation, the spill was concluded to be contained within the interior of the foundation walls. APECCO completed the removal of both 4,000-gallon USTs and recommended the closing of NYSDEC Spill #15-01291.

## 5.0 ENVIRONMENTAL REGULATORY AGENCY RECORD REVIEW

### 5.1 Standard ASTM Environmental Record Review

A review of the EDR Radius Map Report with GeoCheck is summarized below, **(Appendix D).**

Subject Property Listings

| Address | Database | Details |
|---|---|---|
| 1 Vine Street | NYSPILLS | Spill #1501291<br>Closed: 07-08-2015 |
| 1 Vine Street | LTANKS<br><br><br>NYSPILLS | Spill # 9410303<br>Closed: 02-27-2005<br><br>Spill # 9413519<br>Closed: 01-23-1995 |
| 1 Vine Street | UST | Tank 1: closed-removed (2015)<br>Tank 1old: closed-removed (1995)<br>Tank 2: closed-removed (2015)<br>Tank 2old: closed-removed (1995)<br>Tank 3old: closed-removed (1995)<br>Tank 4old: closed-removed (1995)<br>Tank5old: closed-removed (1995) |

| | | |
|---|---|---|
| | AST | Tank 3: Active-Motor Oil<br>Tank 4: Active-Waste Oil |
| 1 Vine Street | EDR HIST AUTO | General Automotive Repair (1969-2014) |
| 1 Vine Street | EDR HIST CLEANER | Magic Touch Cleaners (1995) |
| 1 Vine Street | RCRA-SQG<br>MANIFEST<br>MANIFEST | J&F CHATSWORTH LTD<br>-IGNITABLE WASTE<br>NAICS Code: 4471, 44711, 811111, 811121 |
| 1-5 Vine Street | LTANKS | Spill #9102813<br>Closed: 11-14-1997 |
| 5 Vine Street | EDU HIST CLEANER | MICHELS FRENCY DRY CLEANING (1971-1988)<br>ANNA MARIAS CLEANERS (1989-1993)<br>MAGIC TOUCH CLEANERS (1996-2002)<br>KIM KWUNG Dry Cleaning (2003-2014) |
| 5 Vine Street | RCRA NONGEN / NLR<br><br><br><br><br>ICIS<br><br><br>US AIRS<br><br><br>DRYCLEANERS<br><br><br>NY MANIFEST | MAGIC TOUCH CLNRS<br>-IGNITABLE WASTE, TETRACHLOROETHYLENE<br><br>Notice of Violation – Air<br>NAICS Code: 812320<br><br>Facility Registry ID: 110004313975<br>04-27-2006 Inspection<br><br>Magic Touch Cleaners<br>Expiration Date: 05/03/2029<br><br>MAGIC TOUCH CLNRS |

Adjacent Property Listings

| Address | Database | Details |
|---|---|---|
| Interstate 95 | NYSPILLS | Spill #9407990<br>Closed: 09-22-1994 |
| 19 Cabot Road | NYSPILLS | Spill #2202138<br>Closed: 07/14/2022 |

## 5.2 Information from Regulatory Agency Officials

5.2.1 County Department of Health

Under the Freedom of Information Law (FOIL), a request for information was sent to the Westchester County Department of Health for information regarding the Site. As of date, no response has been received.

5.2.2 New York State Department of Environmental Conservation

Under the Freedom of Information Law (FOIL), a request for information was sent to the Westchester County Department of Health for information regarding the Site. As of date, no response has been received.

## 6.0 SITE RECONNAISSANCE

6.1 Conditions of Reconnaissance

Access to the site was granted by Mr. Vincent Sparano. Mr. Sparano was present during the interior site reconnaissance. Interior investigation was limited due to stored materials in Magic Touch Dry Cleaners, tenant language barrier, limited lighting in basements, significant standing fluids in the basements, and stored materials in the auto repair shop. Exterior investigation was limited due to car coverage.

The following summarizes APECCO's observations.

| Item | Identified On-Site | Description |
|---|---|---|
| Hazardous Substances and/or Petroleum Products | Yes | Roughly (20) 6-gallon motor fluid containers were noted throughout the auto repair shop. |
| Storage Tanks | Yes | 1 UST was noted sub-slab within the auto repair shop and is reported to be "closed in-place.' 2 motor oil ASTs, 2 waste oil ASTs |
| Odors | Yes | Significant paint odors were noted in the paint booth closet of the auto body shop. |
| Pools of liquid | Yes | 4-6 inches of an unknown water mixture was noted in the basement. |
| Drums | Yes | Approximately 30 drums were noted within the auto repair shop connected to waste oil storage and waste oil filters. |

| | | |
|---|---|---|
| Dry Cleaning Substance Containers | Yes | Four 1-gallon spot cleaning containers were noted on site in fair condition. |
| Suspects PCBs | Yes | Three underground hydraulic lifts were noted in the auto repair shop. |
| Heating/Cooling | Yes | The property is currently heating with natural gas through hanging heating units and waste oil in the auto repair shop. |
| Interior Staining or Corrosion | Yes | Minor floor corrosion was noted surrounding the main dry-cleaning machine |
| Drains and Sumps | Yes | Several floor drains were filled within the auto repair shop prior to current ownership (1980).<br>A sump pump was noted in the basement under the dry cleaner and discharges to the municipal sewer system |
| Pits, Ponds, Lagoons, | Yes | It appears that a filled pit in connection with auto repair was located within the auto repair shop. |
| Stained Soil or Pavement | No | None |
| Wastewater | No | None |
| Wells | Yes | One monitoring well was noted in the southeastern portion of the parking lot.<br>Evidence of an additional monitoring well was noted in the southwestern portion of the parking lot |
| Septic Systems | No | None |
| Suspect ACMs | Yes | Minor amounts of damaged friable pipe wrap were noted in the dry cleaner space. |
| Suspect LBP | No | None |
| Suspect Mold | No | None |

6.2 Site Waste Profile

| Item | Identified On-Site | Description |
|---|---|---|
| Solid Waste | Yes | General refuse generated on-site is stored in one garbage can and transported off-site by the municipality. |
| Waste Oil | Yes | Waste oil is stored in 55-gallon drums within the auto repair shop. Waste oil is burned in the waste-oil burned. Any additional waste oil is transported off-site by Safety Kleen. Waste oil burner provides supplemental heat. |
| Waste Oil Filters | Yes | (2) 55-gallon drums of waste oil filters were noted on site. Drums are transported off-site by Safety Kleen on an as needed basis. |
| Solvents | Yes | 1 parts-washer with a 30-gallon drum was noted on site. Drums are transported off-site by Safety Kleen on an as needed basis. |
| Batteries | Yes | Approximately 10 auto batteries were noted on site. Batteries are transported off-site by Advanced Auto Parts on a weekly basis. |
| Tires | Yes | Approximately 15 tires were noted on site. Tires are transported off-site by Welden Tire. |
| Wastewater | No | None |
| Paint | Yes | Paint booth waste is stored in two 55-gallon drums and transported off-site by Viola. |

6.3 Site Drainage

No catch basins were noted on site. The nearest catch basin is located southeast of the subject property owned and maintained by the Town of Mamaroneck.

Floor drains were noted throughout the auto repair shops. All floor drains were inactive and filled with concrete. The tenant was unaware of the previous discharge point.

A sump pump was noted in the basement of the dry-cleaning tenant. The sump pump discharges to the municipal sewer system.

## 7.0 OBSERVATIONS OF MOLD AND POTENTIAL WATER INTRUSION

American Petroleum did not conduct a mold investigation as part of this assessment. American Petroleum observed some areas of possible mold growth in the basement during the Site visit. Approximately 2-6 inches of standing a water mixture was noted throughout the basement. The liquid had an orange coloring. A white sheen was noted in the basement under the drycleaning tenant. Several holes and cracks were noted in the foundation during the exterior inspection.

## 8.0 REPORT FINDINGS, OPINIONS AND CONCLUSIONS

### 8.1 Findings and Opinions

Provided below is a summary of the findings identified through the assessment and opinions as to the potential impact of said findings.

- Duration of Auto Repair: The current structure was constructed in 1930 and has been used as an auto repair shop since construction. The property was also used as a car wash for approximately 50 years.
- Floor anomalies in the auto repair shop show evidence of previous auto repair pits.
- Three (3) underground lifts within the auto repair shop are not utilized and are reported to be drained.
- A reported closed-in place UST is located within the building footprint in the eastern portion of the auto repair shop. No documentation was found or provided.
- Floor drains within the auto repair shop have been filled with concrete prior to current ownership. The previous discharge point is unknown. The presence of an oil/water separator is unknown.
- Duration of Gas Station: UST removal and remedial activities associated with the gas station were completed in 2015 by American Petroleum.
- Duration of Dry Cleaning: Sanborn maps and city directories determine dry cleaning was on site from at least 1979 to the time of inspection. According to the historic property card, the dry cleaner was converted to Green Earth Cleaning Products in 2001.
- Significant standing fluid was observed throughout the basement.

### 8.2 Conclusions and Recommendations

**1) An interior ground penetrating radar (GPR) survey is recommended to determine the extent and characteristics of the flooring anomalies within the auto repair shop**. The GPR

should include the area of the "closed in-place" UST, as well as all suspected floor drains and any additional undetermined anomalies.

3) Due to the size of the building relative to the size of the property, **a vapor intrusion test is warranted to assess the environmental conditions on-site due to historic operations.**

2) Further investigation that would discover or characterize contamination of the subject property by hazardous or toxic substances is warranted. Due to the nature of historic operations as an auto repair shop, dry cleaner, and gasoline station, the potential exists for localized areas of impact. **A subsurface (Phase II) study is warranted to assess the environmental conditions on-site due to such historic operations.** The Phase II should include the area of the lifts. Alternatively, the lifts could be removed. If the Phase II identifies a concern, further work would be required.

3) To maximize sub-surface investigation with minimal obtrusion, preliminary water sampling can be taken from the basement and the active monitoring well on site. APECCP recommends the discontinued use of basement sump pump until water mixture in basement is analyzed through laboratory sampling. Pump out remaining water mixture within the basement and monitor for intrusion points. Secondary water sampling should occur when/if the basement refills.

4) A full asbestos inspection was not completed. Based on APECCO's observations, as suspected ACMs were not friable or greatly damaged, the materials can remain in-place. However, should significant renovations or demolition be anticipated, state and federal regulations require an asbestos survey and proper handling and disposal of ACMs.

5) A full lead-based paint inspection was not completed. Based on APECCO's limited observations, suspect lead-based paint surfaces were not considered to be peeling or chipping at the time of the site investigation. However, caution is recommended if renovations and/or remodeling of this facility are to take place.

6) A cursory visual assessment for suspect mold was undertaken as a part of this environmental screen. A full mold inspection was not requested nor completed as part of this assessment. Based on APECCO's limited observations, visible evidence of possible mold growth and mold related odors were observed in the basement. Visual evidence of mold should be addressed immediately. It is recommended that professional remediation contractors be hired to properly address such issues.

## 9.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

We declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in Section 312.10 of 40 CFR 312.

We have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Site. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Michelle Nowak
Staff Geologist

Jim Lantowski
Project Manager

## Appendix A: Site Photographs

P.1 Northern façade of subject building

P.2 Eastern façade of subject building

P.3 Southern façade of subject building

P.4 Western façade of subject building

P. 5 Magic Touch Cleaners - Damaged Floor Tiles

P.6 Magic Touch Cleaners - Damaged Ceiling Tiles

P.7 Magic Touch Cleaners - Main Dry Cleaner

P.8 Magic Touch Cleaners - Main Dry Cleaner & Containment

P.9 Magic Touch Cleaners - Main Dry Cleaner Cleaning Fluid Containment

P.10 Magic Touch Cleaners – Man Dry Cleaner Fluids

P.11 Magic Touch Cleaners- Spot Treatment Fluids

P.12 Magic Touch Cleaners – Spot Treatment Fluids

P.13 Magic Touch Cleaners – Secondary Dry-Cleaning Machine



P.14 Magic Touch Cleaners – Pipe Wrap

P. 15 Magic Touch Cleaners Sump Pump

P.16 Magic Touch Cleaners – Sump Pump Piping

P.17 Magic Touch Cleaners – Basement

P. 18 Magic Touch Cleaners – Basement Mechanical



P.19 Garage

P.20 Garage Floor Drain




P.21 Garage Stored Auto Fluids

P.22 Garage Waste Oil Filter Drums




P.23 Auto Repair Shop – Parts Washer

P.24 Auto Repair Shop – Motor Oil AST

P.25 Auto Repair Shop – Motor Oil Containers

P.26 Auto Repair Shop – Motor Oil Containers




P.27 Auto Repair Shop - Waste Oil ASTs and Containment

P.28 Auto Repair Shop - Waste Oil Drums

P.29 Auto Repair Shop – Waste Oil Burner

P.30 Auto Repair Shop – Inground Lift

P.31 Auto Repair shop – Inground Lift AST

P.32 Auto Repair Shop – Filled Floor Drains

P.33 Auto Repair Shop – Filled Floor Drains

P.34 Auto Repair Shop – Suggested UST Location and Fill Port



P.35 Auto Repair Shop – Suggested UST Location

P.36 Auto Repair Shop – Floor Anomaly

P.37 Auto Repair Shop – Floor Anomaly

P. 38 Auto Repair Shop – Floor Anomaly (Possible Previous Pit)

P.39 Auto Repair Shop – Floor Anomaly (Possible Previous Pit)

P.40 Auto Repair Shop – Paint Booth

P.41 Auto Repair Shop – Paint Booth Interior

P.42 Auto Repair Shop – Paint Booth Waste Drums

P.43 Auto Repair Shop – Paint Booth Closet Stored Paint

P.44 Auto Repair Shop – Paint Booth Closet Stored Paint

P.45 Auto Repair Shop – Paint Booth Closet Stored Paint

P.46 Southern Parking Lot

P.47 Southern Parking Lot

P.48 Monitoring Well Located in Southeastern Parking Lot

P.49 Northern adjacent property – Municipal Parking Lot

P. 50 Eastern Adjacent Property – Interstate 95

P.51 Southern Adjacent Property – Municipal Park

P. 52 Western Adjacent Property – Municipal Parking Lot

**Appendix B: Site Maps**

Figure 1: Site Location Map
Figure 2: Tax Map
Figure 3: State Wetland Map
Figure 4: Federal Wetland Map
Figure 5: Soil Map

Map Scale: 1:431 if printed on A landscape (11" x 8.5") sheet.

N

Meters
0 5 10 20 30

Feet
0 20 40 80 120

Map projection: Web Mercator Corner coordinates: WGS84 Edge tics: UTM Zone 18N WGS84

## MAP LEGEND

**Area of Interest (AOI)**

- Area of Interest (AOI)

**Soils**

- Soil Map Unit Polygons
- Soil Map Unit Lines
- Soil Map Unit Points

**Special Point Features**

- Blowout
- Borrow Pit
- Clay Spot
- Closed Depression
- Gravel Pit
- Gravelly Spot
- Landfill
- Lava Flow
- Marsh or swamp
- Mine or Quarry
- Miscellaneous Water
- Perennial Water
- Rock Outcrop
- Saline Spot
- Sandy Spot
- Severely Eroded Spot
- Sinkhole
- Slide or Slip
- Sodic Spot
- Spoil Area
- Stony Spot
- Very Stony Spot
- Wet Spot
- Other
- Special Line Features

**Water Features**

- Streams and Canals

**Transportation**

- Rails
- Interstate Highways
- US Routes
- Major Roads
- Local Roads

**Background**

- Aerial Photography

## MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:12,000.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed scale.

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service
Web Soil Survey URL:
Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: Westchester County, New York
Survey Area Data: Version 18, Sep 10, 2022

Soil map units are labeled (as space allows) for map scales 1:50,000 or larger.

Date(s) aerial images were photographed: Jul 21, 2014—Aug 27, 2014

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

# Map Unit Legend

| Map Unit Symbol | Map Unit Name | Acres in AOI | Percent of AOI |
|---|---|---|---|
| Uf | Urban land | 0.4 | 100.0% |
| **Totals for Area of Interest** | | **0.4** | **100.0%** |

U.S. Fish and Wildlife Service
National Wetlands Inventory

# Federal Wetlands

December 2, 2022

**Wetlands**

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

# State Wetlands

November 30, 2022

1:4,514

0 0.03 0.06 0.11 mi

0 0.04 0.09 0.18 km

Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

https://gisservices.dec.ny.gov/

NYS Department of Environmental Conservation
Not a legal document

# Vine St. ID: 1-26-730 (Mamaroneck Town )




November 15, 2022

1:1,500

0 70 140 280 ft

N

Tax parcel data was provided by local municipality. This map is generated as a public service to Westchester County residents for general information and planning purposes only, and should not be relied upon as a sole informational source. The County of Westchester hereby disclaims any liability from the use of this GIS mapping system by any person or entity. Tax parcel boundaries represent approximate property line location and should NOT be interpreted as or used in lieu of a survey or property boundary description. Property descriptions must be obtained from surveys or deeds. For more information please contact local municipality assessor's office.

**Westchester County GIS**
GIS
http://giswww.westchestergov.com
Michaelian Office Building
148 Martine Avenue Rm 214
White Plains, New York 10601

# Vine St. ID: 1-26-730 (Mamaroneck Town )

November 15, 2022

1:500

0 20 40 80 ft

N

Tax parcel data was provided by local municipality. This map is generated as a public service to Westchester County residents for general information and planning purposes only, and should not be relied upon as a sole informational source. The County of Westchester hereby disclaims any liability from the use of this GIS mapping system by any person or entity. Tax parcel boundaries represent approximate property line location and should NOT be interpreted as or used in lieu of a survey or property boundary description. Property descriptions must be obtained from surveys or deeds. For more information please contact local municipality assessor's office.

**Westchester County GIS**
GIS
http://giswww.westchestergov.com
Michaelian Office Building
148 Martine Avenue Rm 214
White Plains, New York 10601

**Appendix C: Historical Resources**
Historic Aerial Photographs
Historic Topographic Maps

**15 VINE ST**

15 VINE ST

LARCHMONT, NY 10538

Inquiry Number: 7180742.8

November 16, 2022

# The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

# EDR Aerial Photo Decade Package

11/16/22

**Site Name:**

15 VINE ST
15 VINE ST
LARCHMONT, NY 10538
EDR Inquiry # 7180742.8

**Client Name:**

American Petroleum
63 Orange Avenue
Walden, NY 12586
Contact: Michelle Nowak

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

***Search Results:***

| *Year* | *Scale* | *Details* | *Source* |
|---|---|---|---|
| 2017 | 1"=500' | Flight Year: 2017 | USDA/NAIP |
| 2013 | 1"=500' | Flight Year: 2013 | USDA/NAIP |
| 2009 | 1"=500' | Flight Year: 2009 | USDA/NAIP |
| 2006 | 1"=500' | Flight Year: 2006 | USDA/NAIP |
| 1994 | 1"=500' | Flight Date: April 08, 1994 | USGS |
| 1985 | 1"=500' | Flight Date: March 16, 1985 | USDA |
| 1980 | 1"=500' | Flight Date: July 25, 1980 | NOAA |
| 1974 | 1"=500' | Flight Date: October 24, 1974 | USDA |
| 1964 | 1"=500' | Flight Date: March 23, 1964 | USGS |
| 1962 | 1"=500' | Flight Date: January 16, 1962 | EDR Proprietary Aerial Viewpoint |
| 1953 | 1"=500' | Flight Date: December 17, 1953 | USGS |
| 1951 | 1"=500' | Flight Date: April 20, 1951 | EDR Proprietary Aerial Viewpoint |

**When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.**


**Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.

Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.


INQUIRY #: 7180742.8
YEAR: 2017
= 500'
N
EDR


INQUIRY #: 7180742.8
YEAR: 2013
= 500'
N
EDR


INQUIRY #: 7180742.8
YEAR: 2009
= 500'
N
EDR

INQUIRY #: 7180742.8
YEAR: 2006
= 500'
N
EDR

INQUIRY #: 7180742.8
YEAR: 1994
= 500'
N
EDR

INQUIRY #: 7180742.8
YEAR: 1985
= 500'
N
EDR

INQUIRY #: 7180742.8
YEAR: 1980
= 500'
N
EDR

INQUIRY #: 7180742.8
YEAR: 1974
= 500'
N
EDR

INQUIRY #: 7180742.8

YEAR: 1964

= 500'

N

EDR

INQUIRY #: 7180742.8
YEAR: 1962
= 500'
N
EDR

INQUIRY #: 7180742.8
YEAR: 1953
= 500'
N
EDR

INQUIRY #: 7180742.8
YEAR: 1951
= 500'
N
EDR

15 VINE ST

15 VINE ST

LARCHMONT, NY 10538

Inquiry Number: 7180742.4

November 16, 2022

# EDR Historical Topo Map Report

## with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

# EDR Historical Topo Map Report

11/16/22

**Site Name:**

15 VINE ST
15 VINE ST
LARCHMONT, NY 10538
EDR Inquiry # 7180742.4

**Client Name:**

American Petroleum
63 Orange Avenue
Walden, NY 12586
Contact: Michelle Nowak

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by American Petroleum were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

***Search Results:***

**P.O.#** NA

**Project:** Vine Street Phase I

***Coordinates:***

| | |
|---|---|
| **Latitude:** | 40.935478 40° 56' 8" North |
| **Longitude:** | -73.758432 -73° 45' 30" West |
| **UTM Zone:** | Zone 18 North |
| **UTM X Meters:** | 604520.70 |
| **UTM Y Meters:** | 4532336.60 |
| **Elevation:** | 41.00' above sea level |

**Maps Provided:**

| | |
|---|---|
| 2019 | 1900 |
| 2016 | 1898 |
| 2013 | 1897 |
| 1995 | |
| 1975, 1979 | |
| 1966, 1967 | |
| 1955, 1956 | |
| 1947 | |

**Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

## *Topo Sheet Key*

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

### 2019 Source Sheets

Mount Vernon
2019
7.5-minute, 24000

Mamaroneck
2019
7.5-minute, 24000

### 2016 Source Sheets

Mount Vernon
2016
7.5-minute, 24000

Mamaroneck
2016
7.5-minute, 24000

### 2013 Source Sheets

Mount Vernon
2013
7.5-minute, 24000

Mamaroneck
2013
7.5-minute, 24000

### 1995 Source Sheets

Mount Vernon
1995
7.5-minute, 24000
Aerial Photo Revised 1977

## *Topo Sheet Key*

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

### 1975, 1979 Source Sheets

Mamaroneck
1975
7.5-minute, 24000
Aerial Photo Revised 1966

Mount Vernon
1979
7.5-minute, 24000
Aerial Photo Revised 1977

### 1966, 1967 Source Sheets

Mount Vernon
1966
7.5-minute, 24000
Aerial Photo Revised 1966

Mamaroneck
1967
7.5-minute, 24000
Aerial Photo Revised 1966

### 1955, 1956 Source Sheets

Mamaroneck
1955
7.5-minute, 24000
Aerial Photo Revised 1941

Mount Vernon
1956
7.5-minute, 24000
Aerial Photo Revised 1954

### 1947 Source Sheets

Mamaroneck
1947
7.5-minute, 24000
Aerial Photo Revised 1941

Mt Vernon
1947
7.5-minute, 24000
Aerial Photo Revised 1941

## *Topo Sheet Key*

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

### 1900 Source Sheets

Harlem
1900
15-minute, 62500

Oyster Bay
1900
15-minute, 62500

### 1898 Source Sheets

Oyster Bay
1898
15-minute, 62500

Harlem
1898
15-minute, 62500

### 1897 Source Sheets

Harlem
1897
15-minute, 62500

Oyster Bay
1897
15-minute, 62500

# Historical Topo Map

2019




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 2019, 7.5-minute
E, Mamaroneck, 2019, 7.5-minute

SITE NAME: 15 VINE ST
ADDRESS: 15 VINE ST
LARCHMONT, NY 10538
CLIENT: American Petroleum

N

# Historical Topo Map

2016




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 2016, 7.5-minute
E, Mamaroneck, 2016, 7.5-minute

SITE NAME: 15 VINE ST
ADDRESS: 15 VINE ST
LARCHMONT, NY 10538
CLIENT: American Petroleum

N

# Historical Topo Map

2013




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 2013, 7.5-minute
E, Mamaroneck, 2013, 7.5-minute

SITE NAME: 15 VINE ST
ADDRESS: 15 VINE ST
LARCHMONT, NY 10538
CLIENT: American Petroleum

N




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1995, 7.5-minute

SITE NAME: 15 VINE ST
ADDRESS: 15 VINE ST
LARCHMONT, NY 10538
CLIENT: American Petroleum

N




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5




TP, Mount Vernon, 1979, 7.5-minute
E, Mamaroneck, 1975, 7.5-minute

SITE NAME: 15 VINE ST
ADDRESS: 15 VINE ST
LARCHMONT, NY 10538
CLIENT: American Petroleum

N




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1966, 7.5-minute
E, Mamaroneck, 1967, 7.5-minute

SITE NAME: 15 VINE ST
ADDRESS: 15 VINE ST
LARCHMONT, NY 10538
CLIENT: American Petroleum

N




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5




TP, Mount Vernon, 1956, 7.5-minute
E, Mamaroneck, 1955, 7.5-minute

SITE NAME: 15 VINE ST
ADDRESS: 15 VINE ST
LARCHMONT, NY 10538
CLIENT: American Petroleum

N




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5




TP, Mt Vernon, 1947, 7.5-minute
E, Mamaroneck, 1947, 7.5-minute

SITE NAME: 15 VINE ST
ADDRESS: 15 VINE ST
LARCHMONT, NY 10538
CLIENT: American Petroleum

N




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1900, 15-minute
SE, Oyster Bay, 1900, 15-minute

SITE NAME: 15 VINE ST
ADDRESS: 15 VINE ST
LARCHMONT, NY 10538
CLIENT: American Petroleum

N




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1898, 15-minute
SE, Oyster Bay, 1898, 15-minute

SITE NAME: 15 VINE ST
ADDRESS: 15 VINE ST
LARCHMONT, NY 10538
CLIENT: American Petroleum

N




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1897, 15-minute
SE, Oyster Bay, 1897, 15-minute

SITE NAME: 15 VINE ST
ADDRESS: 15 VINE ST
LARCHMONT, NY 10538
CLIENT: American Petroleum

N

**Appendix D: Environmental Database Report**
EDR Radius Map Report with GeoCheck
Sanborn Fire Insurance Maps
City Directories

**15 VINE ST**
15 VINE ST
LARCHMONT, NY  10538

Inquiry Number: 7180742.2s
November 16, 2022

# The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

# TABLE OF CONTENTS


| SECTION | PAGE |
|---|---|
| Executive Summary | ES1 |
| Overview Map | 2 |
| Detail Map | 3 |
| Map Findings Summary | 4 |
| Map Findings | 8 |
| Orphan Summary | 300 |
| Government Records Searched/Data Currency Tracking | GR-1 |

**GEOCHECK ADDENDUM**

| | |
|---|---|
| Physical Setting Source Addendum | A-1 |
| Physical Setting Source Summary | A-2 |
| Physical Setting SSURGO Soil Map | A-5 |
| Physical Setting Source Map | A-10 |
| Physical Setting Source Map Findings | A-12 |
| Physical Setting Source Records Searched | PSGR-1 |


***Thank you for your business.***
Please contact EDR at 1-800-352-0050
with any questions or comments.


**Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2022 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

# EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527-21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

## TARGET PROPERTY INFORMATION

### ADDRESS

15 VINE ST
LARCHMONT, NY 10538

### COORDINATES

| | |
|---|---|
| Latitude (North): | 40.9354780 - 40ˆ 56' 7.72'' |
| Longitude (West): | 73.7584320 - 73ˆ 45' 30.35'' |
| Universal Tranverse Mercator: | Zone 18 |
| UTM X (Meters): | 604523.5 |
| UTM Y (Meters): | 4532125.0 |
| Elevation: | 41 ft. above sea level |

### USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

| | |
|---|---|
| Target Property Map: | 14105990 MOUNT VERNON, NY |
| Version Date: | 2019 |
| East Map: | 14105988 MAMARONECK, NY |
| Version Date: | 2019 |

### AERIAL PHOTOGRAPHY IN THIS REPORT

| | |
|---|---|
| Portions of Photo from: | 20150522, 20150624 |
| Source: | USDA |

## MAPPED SITES SUMMARY

Target Property Address:
15 VINE ST
LARCHMONT, NY 10538

Click on Map ID to see full detail.

| MAP ID | SITE NAME | ADDRESS | DATABASE ACRONYMS | RELATIVE ELEVATION | DIST (ft. & mi.) DIRECTION |
|---|---|---|---|---|---|
| 1 | TRAFFIC ACCIDENT | I-95 MP 7.7 | NY Spills | Higher | 237, 0.045, SSW |
| A2 | KIM KWUNG | 5 VINE ST | EDR Hist Cleaner | Higher | 240, 0.045, WNW |
| A3 | MAGIC TOUCH CLEANERS | 5 VINE ST | RCRA NonGen / NLR, ICIS, US AIRS, NY DRYCLEANERS,... | Higher | 240, 0.045, WNW |
| A4 | JS CHADWORTHS | 1 VINE ST | NY Spills | Lower | 251, 0.048, WNW |
| A5 | JF CHATSWORTH | 1 VINE STREET | NY LTANKS, NY Spills | Lower | 251, 0.048, WNW |
| A6 | J & F CHATSWORTH LTD | 1 VINE STREET | NY UST, NY AST | Lower | 251, 0.048, WNW |
| A7 | CHATSWORTH GARAGE IN | 1 VINE ST | EDR Hist Auto | Lower | 251, 0.048, WNW |
| A8 | MARISIERO INC. | 1-5 VINE STREET | NY LTANKS | Lower | 251, 0.048, WNW |
| A9 | MAGIC TOUCH CLEANERS | 1 VINE ST | EDR Hist Cleaner | Lower | 251, 0.048, WNW |
| A10 | J & F CHATSWORTH LTD | 1 VINE ST | RCRA-SQG, NY MANIFEST, NJ MANIFEST | Lower | 251, 0.048, WNW |
| 11 | DECABIA - UST | 19 CABOT RD | NY Spills | Lower | 431, 0.082, NNE |
| B12 | GLOBE RESTAURANT | 1879 PALMER AVE | NY LTANKS | Higher | 674, 0.128, South |
| C13 | CON EDISON SERVICE B | PALMER AVE & E DEPOT | RCRA NonGen / NLR, FINDS | Higher | 679, 0.129, SSE |
| C14 | REAR OF 1880 PALMER | FRANKLYN AVE | NY LTANKS | Higher | 699, 0.132, SSE |
| C15 | HOFFMANS | 1850 PALMER AVE. | NY LTANKS | Higher | 709, 0.134, SSE |
| D16 | PATRICIA GARDENS OWN | 1825 PALMER AVENUE | NY UST | Lower | 721, 0.137, ESE |
| D17 | PATRICIA GARDENS OWN | 1825 PALMER AVENUE | NY AST | Lower | 721, 0.137, ESE |
| D18 | RESIDENCE | 1825 PALMER AVENUE | NY LTANKS, NY Spills | Lower | 721, 0.137, ESE |
| B19 | BROMPTON APTS. | 1880 PALMER AVE. | NY LTANKS | Higher | 723, 0.137, South |
| B20 | THE BROMPTON | 1880 PALMER AVENUE | NY AST | Higher | 723, 0.137, South |
| E21 | CON EDISON | MYRTLE BLVD & MURRAY | NJ MANIFEST | Higher | 744, 0.141, SW |
| E22 | CON EDISON | MYRTLE BLVD & MURRAY | RCRA NonGen / NLR, FINDS, ECHO | Higher | 744, 0.141, SW |
| E23 | CON EDISON | MYRTLE BLVD & MURRAY | NY MANIFEST | Higher | 744, 0.141, SW |
| F24 | EMBASSY CLEANERS | 1908 PALMER AVE | RCRA-SQG, ICIS, US AIRS, FINDS, ECHO, NY... | Higher | 794, 0.150, South |
| F25 | HOFFMAN INVESTORS CO | 1890 PALMER AVENUE | NY LTANKS, NY LIENS | Higher | 796, 0.151, South |
| 26 | COLONY TENANTS CORP. | 1815 PALMER AVENUE | NY UST | Lower | 804, 0.152, ESE |
| F27 | BANK OF NY | 124 CHASWORTH AVE | NY LTANKS | Higher | 855, 0.162, South |
| G28 | SPILL NUMBER 8906916 | 132 CHATSWORTH AVE | NY LTANKS | Higher | 926, 0.175, SSW |
| G29 | HOWELL ASSOCIATES | 132 CHATSWORTH AVENU | NY AST | Higher | 926, 0.175, SSW |
| H30 | CON EDISON | MYRTLE AVE & CHATSWO | RCRA NonGen / NLR, FINDS, ECHO | Higher | 929, 0.176, SW |
| H31 | CON EDISON | MYRTLE AVE & CHATSWO | NY MANIFEST | Higher | 929, 0.176, SW |
| H32 | CON EDISON | MYRTLE AVE & CHATSWO | NJ MANIFEST | Higher | 929, 0.176, SW |
| 33 | NYS THRUWAY MAINTENA | I-95 EXIT 17 OFF NEW | RCRA NonGen / NLR | Higher | 935, 0.177, SSW |
| 34 | PRESTO RESIDNECE | 130 LAUREL AVE | NY LTANKS | Higher | 942, 0.178, NE |
| I35 | CON EDISON MANHOLE: | CHATSWORTH AVE & PAL | RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST | Higher | 947, 0.179, South |
| I36 | CON EDISON | PALMER AVE & CHATSWO | NY MANIFEST | Higher | 947, 0.179, South |
| I37 | BANK OF NEW YORK | 124 CHATSWORTH AVE. | NY LTANKS | Higher | 965, 0.183, South |
| I38 | CHATSWORTH CLEANERS | 120 CHATSWORTH AVE | RCRA-VSQG, US AIRS, FINDS, NY DRYCLEANERS, NY... | Higher | 979, 0.185, South |
| J39 | VERIZON NEW YORK INC | 5 FRANKLIN AVENUE | NY UST | Higher | 980, 0.186, South |

## MAPPED SITES SUMMARY

Target Property Address:
15 VINE ST
LARCHMONT, NY 10538

Click on Map ID to see full detail.

| MAP ID | SITE NAME | ADDRESS | DATABASE ACRONYMS | RELATIVE ELEVATION | DIST (ft. & mi.) DIRECTION |
|---|---|---|---|---|---|
| J40 | BELL ATLANTIC | 5 FRANKLIN ST | NY LTANKS, NY Spills | Higher | 980, 0.186, South |
| 41 | LARCHMONT PALMER | 1299 PALMER AVENUE | NY UST, NY AST | Higher | 989, 0.187, East |
| K42 | CHATSWORTH GARDENS C | 14 NORTH CHATSWORTH | NY AST | Higher | 1011, 0.191, WSW |
| I43 | EMBASSY CLEANERS | 1908 PALMER AVE | RCRA NonGen / NLR, US AIRS, NY MANIFEST | Higher | 1013, 0.192, South |
| I44 | EMBASSY CLEANERS | 1908 PALMER AVENUE | NY DRYCLEANERS | Higher | 1013, 0.192, South |
| K45 | APARTMENT | 16 NORTH CHATSWORTH | NY LTANKS | Higher | 1020, 0.193, WSW |
| K46 | 16 NORTH CHATSWORTH | 16 NORTH CHATSWORTH | NY UST, NY AST | Higher | 1020, 0.193, WSW |
| K47 | CON EDISON | CHATSWORTH AVE & WAS | NY MANIFEST | Higher | 1032, 0.195, WSW |
| K48 | CONSOLIDATED EDISON | WASHINGTON & N CHATS | NY MANIFEST | Higher | 1032, 0.195, WSW |
| J49 | 06-D3M DOM'S CAR CAR | 107 CHATSWORTH | RCRA-LQG, FINDS, ECHO, NY MANIFEST | Higher | 1033, 0.196, South |
| K50 | LARCHMONT HILLS OWNE | 17 NORTH CHATSWORTH | NY AST | Higher | 1045, 0.198, WSW |
| 51 | CON EDISON POLE W10 | HALL AVE & CONCORD A | RCRA NonGen / NLR, NY MANIFEST | Lower | 1060, 0.201, ESE |
| I52 | DUTCH GIRL PROFESSIO | 1912 PALMER AVE | RCRA NonGen / NLR, FINDS, ECHO | Higher | 1064, 0.202, South |
| 53 | DONALD RITACCO & CO | 7-11 NORTH AVE | RCRA NonGen / NLR, NY MANIFEST | Higher | 1076, 0.204, SSW |
| 54 | 172 MYRTLE BLVD. APT | 172 MYRTLE BOULEVARD | NY AST | Higher | 1099, 0.208, SW |
| 55 | LARCH REALTY CORP PR | 1925 PALMER AVE | NY LTANKS | Higher | 1135, 0.215, SSW |
| 56 | FORLANI | 15-17 HILLCREST AVE | NY LTANKS | Higher | 1166, 0.221, North |
| L57 | LARCHMONT TERRACE CO | 2 WASHINGTON SQUARE | NY UST | Higher | 1270, 0.241, SW |
| 58 | THE KEYSTONE | 76 WENDT AVENUE | NY AST | Higher | 1273, 0.241, South |
| M59 | VERIZON | 15 EMERSON RD | NY MANIFEST | Higher | 1276, 0.242, NNW |
| L60 | CARLSHIRE TENANTS IN | 1-3 WASHINGTON SQUAR | NY AST | Higher | 1287, 0.244, SW |
| L61 | CARLSHIRE TENANTS IN | 1-3 WASHINGTON SQUAR | NY UST | Higher | 1287, 0.244, SW |
| 62 | CON EDISON | 6 OVERLOOK TER | RCRA NonGen / NLR, NY MANIFEST | Higher | 1304, 0.247, West |
| 63 | UNKNOWN RESIDENCE | 35 NORTH CHATSWORTH | NY LTANKS | Lower | 1336, 0.253, WSW |
| M64 | RESIDENCE | 60 MAPLE HILL DR | NY LTANKS | Higher | 1353, 0.256, NNW |
| 65 | SPILL NUMBER 0107991 | 21 EDGEWOOD AVE | NY LTANKS | Higher | 1360, 0.258, NNE |
| N66 | SPILL NUMBER 9910464 | 116 LAUREL AVE | NY LTANKS | Higher | 1384, 0.262, NE |
| 67 | WACHOVIA BANK | 1940 PALMER AVE | NY LTANKS | Higher | 1394, 0.264, SSW |
| 68 | VALKENBURGH HOME | 47 MAPLE HILL DRIVE | NY LTANKS | Higher | 1396, 0.264, NNW |
| 69 | RESI:BISNO | 53 HILLSIDE RD | NY LTANKS | Higher | 1417, 0.268, WNW |
| 70 | REISMAN RESIDENCE | 24 EDGEWOOD AVE | NY LTANKS | Higher | 1419, 0.269, NNE |
| 71 | RESIDENCE | 9 SUMMIT AVE | NY LTANKS | Higher | 1426, 0.270, SE |
| N72 | SPILL NUMBER 9910463 | 114 LAUREL AVE | NY LTANKS | Higher | 1448, 0.274, NE |
| 73 | CARRIER RESIDENCE | 45 CARLEON AV | NY LTANKS | Higher | 1476, 0.280, East |
| 74 | PRIVATE RESIDENCE | 125 MURRAY AVE | NY LTANKS | Higher | 1516, 0.287, NW |
| 75 | SPILL NUMBER 9903173 | 26 SUMMITT AVE | NY LTANKS | Higher | 1523, 0.288, SSE |
| O76 | BLONDIE'S TREEHOUSE | 21 NORTH AVE | NY LTANKS | Higher | 1543, 0.292, SSW |
| O77 | SPILL NUMBER 9914491 | 21 NORTH AVE | NY LTANKS | Higher | 1543, 0.292, SSW |
| P78 | RESIDENCE | 8 ORSINI DRIVE | NY LTANKS | Higher | 1553, 0.294, NNW |

## MAPPED SITES SUMMARY

Target Property Address:
15 VINE ST
LARCHMONT, NY 10538

Click on Map ID to see full detail.

| MAP ID | SITE NAME | ADDRESS | DATABASE ACRONYMS | RELATIVE ELEVATION | DIST (ft. & mi.) DIRECTION |
|---|---|---|---|---|---|
| 79 | SPILL NUMBER 9806441 | 26 HILLSIDE ROAD | NY LTANKS | Higher | 1572, 0.298, WNW |
| Q80 | YAHIA RESIDENCE | 17 HALL AVE | NY LTANKS | Lower | 1587, 0.301, SE |
| P81 | PHIL LEBOWITZ | 12 ORSINI DRIVE | NY LTANKS | Higher | 1644, 0.311, NNW |
| 82 | ALPERT HOME | 80 LOOKOUT CIRCLE | NY LTANKS | Higher | 1669, 0.316, NW |
| Q83 | SPILL NUMBER 0011319 | 14 HALL AVE | NY LTANKS | Lower | 1685, 0.319, SE |
| 84 | YOUNG HOME | 6 ROCKHILL TERRACE | NY LTANKS | Higher | 1685, 0.319, South |
| 85 | UNITED ARTISTS THEAT | 1975 PALMER AVE. | NY LTANKS, NY Spills | Higher | 1719, 0.326, SSW |
| 86 | LEVY | 7 ROOSEVELT AV | NY LTANKS | Higher | 1754, 0.332, SE |
| 87 | DILIETO HOME | 104 LAUREL AVE | NY LTANKS | Higher | 1755, 0.332, NE |
| R88 | PRIVATE DWELLING | 212 LARCHMONT AVE | NY LTANKS | Higher | 1766, 0.334, South |
| R89 | GRECO DWELLING | 212 LARCHMONT AVE | NY LTANKS | Higher | 1766, 0.334, South |
| 90 | LARCHMONT AUTO GARAG | 5TH AV & MADISON | NY LTANKS | Lower | 1794, 0.340, WSW |
| 91 | LARCHMONT/MAMARONECK | 41 MAXWELL AVENUE(LO | NY SWF/LF | Lower | 1798, 0.341, SW |
| 92 | VERNER RES | 46 ECHO LN | NY LTANKS | Higher | 1807, 0.342, NW |
| 93 | BEN BEDERSON TTF | 8 HALL AVE | NY LTANKS | Lower | 1810, 0.343, SE |
| S94 | MOCCIA - TTF | 23 DANTE ST | NY LTANKS | Higher | 1840, 0.348, North |
| 95 | CONDON HOME | 16 ORSINI DRIVE | NY LTANKS | Higher | 1869, 0.354, NNW |
| 96 | SPILL NUMBER 9913035 | 54 LOOKOUT CIRCLE | NY LTANKS | Higher | 1875, 0.355, WNW |
| S97 | SLATTERY RESIDENCE | 25 DANTE ST | NY LTANKS | Higher | 1880, 0.356, North |
| 98 | SPILL NUMBER 0205284 | 60 CHATSWORTH AVE | NY LTANKS | Higher | 1891, 0.358, SSE |
| 99 | RESIDENCE | 41 MYRTLE BLVD | NY LTANKS | Higher | 1907, 0.361, NNE |
| 100 | MAUGUE HOME | 23 MAPLEWOOD STREET | NY LTANKS | Higher | 1921, 0.364, NW |
| 101 | SPRINGER RESIDENCE | 200 LARCHMONT AVE | NY LTANKS | Higher | 1963, 0.372, South |
| 102 | GLASS RESIDENCE | 5 IDEN AVE | NY LTANKS | Higher | 1971, 0.373, South |
| 103 | ST. JOHN'S | 280 WEAVER ST. | NY LTANKS | Higher | 2009, 0.380, NNE |
| 104 | MOSER RESIDENCE | 161 MURRAY AVE | NY LTANKS | Higher | 2020, 0.383, NW |
| 105 | BIRDVELL RESIDENCE | 4 FOREST PARK AVE | NY LTANKS | Lower | 2024, 0.383, ESE |
| T106 | MARTIN RES | 16 FOREST PARK AVE | NY LTANKS | Lower | 2028, 0.384, SE |
| 107 | RESIDENCE | 1 FRANCE PLACE | NY LTANKS | Higher | 2054, 0.389, West |
| T108 | RESIDENCE | 15 FOREST PARK AVE | NY LTANKS | Lower | 2068, 0.392, SE |
| 109 | BEZ - TTF | 72 HOWELL AVE | NY LTANKS | Lower | 2083, 0.395, ENE |
| 110 | GARRY RESIDENCE | 7 MEADOW PL | NY LTANKS | Lower | 2101, 0.398, East |
| 111 | SPILL NUMBER 0106394 | 110 CARLEON AVE | NY LTANKS | Lower | 2117, 0.401, East |
| 112 | PRIVATE RES | 41 MAPLEWOOD ST | NY LTANKS | Higher | 2123, 0.402, NW |
| 113 | TTF | 12 COOPER LANE | NY LTANKS | Higher | 2218, 0.420, NNE |
| 114 | SPILL NUMBER 8900768 | 4 WAKEMAN PLACE | NY LTANKS | Higher | 2259, 0.428, South |
| U115 | SPILL NUMBER 9911157 | 10 ROCHELLE RD | NY LTANKS | Higher | 2263, 0.429, West |
| 116 | RESIDENCE | 2 CAMBRIDGE COURT | NY LTANKS | Lower | 2274, 0.431, ESE |
| V117 | ESTATE OF LANDES | 10 CAMBRIDGE COURT | NY LTANKS | Lower | 2280, 0.432, SE |

## MAPPED SITES SUMMARY

Target Property Address:
15 VINE ST
LARCHMONT, NY 10538

Click on Map ID to see full detail.

| MAP ID | SITE NAME | ADDRESS | DATABASE ACRONYMS | RELATIVE ELEVATION | DIST (ft. & mi.) DIRECTION |
|---|---|---|---|---|---|
| U118 | SPILL NUMBER 9905950 | 10 ROCHELLE RD | NY LTANKS | Higher | 2297, 0.435, West |
| 119 | DALEY RESIDENCE | 2 HEATHER LANE | NY LTANKS | Higher | 2297, 0.435, NNE |
| U120 | PVT DWELLING | 13 ROCHELLE ROAD | NY LTANKS | Higher | 2298, 0.435, West |
| V121 | RESIDENCE | 3 CAMBRIDGE CT | NY LTANKS | Lower | 2315, 0.438, ESE |
| 122 | LARCHMONT AVE CHURCH | 60 FOREST PARK AVE | NY LTANKS, NY Spills | Higher | 2342, 0.444, SSE |
| 123 | SPILL NUMBER 0201523 | 101 NORTH CHATSWORTH | NY LTANKS | Higher | 2362, 0.447, NW |
| 124 | SUTIN RESIDENCE | 21 COPLEY RD | NY LTANKS, NY Spills | Lower | 2369, 0.449, East |
| 125 | FORECLOSURE - TTF | 18 ALDEN RD | NY LTANKS | Higher | 2385, 0.452, ESE |
| 126 | 104 NORTH CHATSWORTH | 104 NORTH CHATSWORTH | NY LTANKS | Higher | 2425, 0.459, NW |
| W127 | SPILL NUMBER 0313036 | 7 HARMONY DRIVE | NY LTANKS | Lower | 2439, 0.462, ESE |
| 128 | DURON RESIDENCE | 174 LARCHMONT AVE | NY LTANKS | Lower | 2447, 0.463, SSE |
| 129 | CENTRAL SCHOOL | PALMER AVE | NY LTANKS | Lower | 2455, 0.465, ENE |
| X130 | TOWN OF MAMARONECK D | MAXWELL AVE - DPW YA | NY LTANKS, NY Spills | Lower | 2476, 0.469, SW |
| X131 | MAMARONECK DPW | MAXWELL ST | NY LTANKS | Lower | 2476, 0.469, SW |
| X132 | DEPT PUBLIC WORKS | MAXWELL AVE | NY LTANKS | Lower | 2476, 0.469, SW |
| 133 | RESIDENCE | 10 NASSAU RD | NY LTANKS | Lower | 2513, 0.476, ESE |
| Y134 | IKEA | 10 VALLEY PL | NY LTANKS | Higher | 2518, 0.477, WNW |
| 135 | FITCH RESIDENCE | 3 WILDWOOD ROAD | NY LTANKS | Higher | 2523, 0.478, WNW |
| W136 | APT BLD | 11 ALDEN RD | NY LTANKS | Lower | 2524, 0.478, ESE |
| Y137 | ATLAS PARTY RENTALS | 4 VALLEY PLACE | NY LTANKS | Higher | 2546, 0.482, WNW |
| Y138 | SPILL NUMBER 9812365 | 1 SETON RD | NY LTANKS | Higher | 2570, 0.487, WNW |
| 139 | WEBERS HOME | 76 PINEBROOK DRIVE | NY LTANKS | Lower | 2573, 0.487, SSW |
| 140 | KUNREUTHER - TTF | 17 BONNETT AVENUE | NY LTANKS | Higher | 2619, 0.496, SE |

# EXECUTIVE SUMMARY

## TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

## DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

## STANDARD ENVIRONMENTAL RECORDS

### *Lists of Federal NPL (Superfund) sites*

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

### *Lists of Federal Delisted NPL sites*

Delisted NPL ---------- National Priority List Deletions

### *Lists of Federal sites subject to CERCLA removals and CERCLA orders*

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

### *Lists of Federal CERCLA sites with NFRAP*

SEMS-ARCHIVE ---------- Superfund Enterprise Management System Archive

### *Lists of Federal RCRA facilities undergoing Corrective Action*

CORRACTS ---------- Corrective Action Report

### *Lists of Federal RCRA TSD facilities*

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

### *Federal institutional controls / engineering controls registries*

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

### *Federal ERNS list*

ERNS ---------- Emergency Response Notification System

### *Lists of state- and tribal hazardous waste facilities*

NY SHWS ---------- Inactive Hazardous Waste Disposal Sites in New York State

# EXECUTIVE SUMMARY

***Lists of state and tribal leaking storage tanks***

INDIAN LUST - Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS - Listing of Leaking Storage Tanks

***Lists of state and tribal registered storage tanks***

FEMA UST - Underground Storage Tank Listing
NY CBS UST - Chemical Bulk Storage Database
NY MOSF UST - Major Oil Storage Facilities Database
NY MOSF - Major Oil Storage Facility Site Listing
NY CBS - Chemical Bulk Storage Site Listing
NY CBS AST - Chemical Bulk Storage Database
NY MOSF AST - Major Oil Storage Facilities Database
INDIAN UST - Underground Storage Tanks on Indian Land
NY TANKS - Storage Tank Faciliy Listing

***State and tribal institutional control / engineering control registries***

NY RES DECL - Restrictive Declarations Listing
NY ENG CONTROLS - Registry of Engineering Controls
NY INST CONTROL - Registry of Institutional Controls

***Lists of state and tribal voluntary cleanup sites***

NY VCP - Voluntary Cleanup Agreements
INDIAN VCP - Voluntary Cleanup Priority Listing

***Lists of state and tribal brownfield sites***

NY BROWNFIELDS - Brownfields Site List
NY ERP - Environmental Restoration Program Listing

**ADDITIONAL ENVIRONMENTAL RECORDS**

***Local Brownfield lists***

US BROWNFIELDS - A Listing of Brownfields Sites

***Local Lists of Landfill / Solid Waste Disposal Sites***

NY SWTIRE - Registered Waste Tire Storage & Facility List
NY SWRCY - Registered Recycling Facility List
INDIAN ODI - Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 - Torres Martinez Reservation Illegal Dump Site Locations
ODI - Open Dump Inventory
IHS OPEN DUMPS - Open Dumps on Indian Land

***Local Lists of Hazardous waste / Contaminated Sites***

US HIST CDL - Delisted National Clandestine Laboratory Register
NY DEL SHWS - Delisted Registry Sites
US CDL - National Clandestine Laboratory Register

# EXECUTIVE SUMMARY

***Local Lists of Registered Storage Tanks***

| | |
|---|---|
| NY HIST UST | Historical Petroleum Bulk Storage Database |
| NY HIST AST | Historical Petroleum Bulk Storage Database |

***Local Land Records***

| | |
|---|---|
| LIENS 2 | CERCLA Lien Information |

***Records of Emergency Release Reports***

| | |
|---|---|
| HMIRS | Hazardous Materials Information Reporting System |
| NY Hist Spills | SPILLS Database |
| NY SPILLS 90 | SPILLS 90 data from FirstSearch |
| NY SPILLS 80 | SPILLS 80 data from FirstSearch |

***Other Ascertainable Records***

| | |
|---|---|
| FUDS | Formerly Used Defense Sites |
| DOD | Department of Defense Sites |
| SCRD DRYCLEANERS | State Coalition for Remediation of Drycleaners Listing |
| US FIN ASSUR | Financial Assurance Information |
| EPA WATCH LIST | EPA WATCH LIST |
| 2020 COR ACTION | 2020 Corrective Action Program List |
| TSCA | Toxic Substances Control Act |
| TRIS | Toxic Chemical Release Inventory System |
| SSTS | Section 7 Tracking Systems |
| ROD | Records Of Decision |
| RMP | Risk Management Plans |
| RAATS | RCRA Administrative Action Tracking System |
| PRP | Potentially Responsible Parties |
| PADS | PCB Activity Database System |
| FTTS | FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act) |
| MLTS | Material Licensing Tracking System |
| COAL ASH DOE | Steam-Electric Plant Operation Data |
| COAL ASH EPA | Coal Combustion Residues Surface Impoundments List |
| PCB TRANSFORMER | PCB Transformer Registration Database |
| RADINFO | Radiation Information Database |
| HIST FTTS | FIFRA/TSCA Tracking System Administrative Case Listing |
| DOT OPS | Incident and Accident Data |
| CONSENT | Superfund (CERCLA) Consent Decrees |
| INDIAN RESERV | Indian Reservations |
| FUSRAP | Formerly Utilized Sites Remedial Action Program |
| UMTRA | Uranium Mill Tailings Sites |
| LEAD SMELTERS | Lead Smelter Sites |
| US MINES | Mines Master Index File |
| ABANDONED MINES | Abandoned Mines |
| UXO | Unexploded Ordnance Sites |
| DOCKET HWC | Hazardous Waste Compliance Docket Listing |
| FUELS PROGRAM | EPA Fuels Program Registered Listing |
| PFAS NPL | Superfund Sites with PFAS Detections Information |
| PFAS FEDERAL SITES | Federal Sites PFAS Information |
| PFAS TSCA | PFAS Manufacture and Imports Information |

PFAS RCRA MANIFEST PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR PFAS Contamination Site Location Listing
PFAS WQP Ambient Environmental Sampling for PFAS
PFAS NPDES Clean Water Act Discharge Monitoring Information
PFAS ECHO Facilities in Industries that May Be Handling PFAS Listing
PFAS ECHO FIRE TRAINING Facilities in Industries that May Be Handling PFAS Listing
PFAS PART 139 AIRPORT All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC Aqueous Foam Related Incidents Listing
NY PFAS PFAS Contamination Site Location Listing
NY AIRS Air Emissions Data
NY COAL ASH Coal Ash Disposal Site Listing
NY E DESIGNATION E DESIGNATION SITE LISTING
NY Financial Assurance Financial Assurance Information Listing
NY HSWDS Hazardous Substance Waste Disposal Site Inventory
NY SPDES State Pollutant Discharge Elimination System
NY VAPOR REOPENED Vapor Intrusion Legacy Site List
NY UIC Underground Injection Control Wells
NY COOLING TOWERS Registered Cooling Towers
NY LEAD Lead-based Paint Testing Results
MINES MRDS Mineral Resources Data System

**EDR HIGH RISK HISTORICAL RECORDS**

***EDR Exclusive Records***

EDR MGP EDR Proprietary Manufactured Gas Plants

**EDR RECOVERED GOVERNMENT ARCHIVES**

***Exclusive Recovered Govt. Archives***

NY RGA HWS Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF Recovered Government Archive Solid Waste Facilities List

**SURROUNDING SITES: SEARCH RESULTS**

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

**STANDARD ENVIRONMENTAL RECORDS**

***Lists of Federal RCRA generators***

# EXECUTIVE SUMMARY

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 06/20/2022 has revealed that there is 1 RCRA-LQG site within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***06-D3M DOM'S CAR CAR*** | ***107 CHATSWORTH*** | ***S 1/8 - 1/4 (0.196 mi.)*** | ***J49*** | ***160*** |
| EPA ID:: NYD986958171 | | | | |

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 06/20/2022 has revealed that there are 2 RCRA-SQG sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***EMBASSY CLEANERS*** | ***1908 PALMER AVE*** | ***S 1/8 - 1/4 (0.150 mi.)*** | ***F24*** | ***58*** |
| EPA ID:: NYD986995249 | | | | |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***J & F CHATSWORTH LTD*** | ***1 VINE ST*** | ***WNW 0 - 1/8 (0.048 mi.)*** | ***A10*** | ***30*** |
| EPA ID:: NYD982718272 | | | | |

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 06/20/2022 has revealed that there is 1 RCRA-VSQG site within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***CHATSWORTH CLEANERS*** | ***120 CHATSWORTH AVE*** | ***S 1/8 - 1/4 (0.185 mi.)*** | ***I38*** | ***127*** |
| EPA ID:: NY0000363101 | | | | |

# EXECUTIVE SUMMARY

***Lists of state and tribal landfills and solid waste disposal facilities***

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the  list.

A review of the NY SWF/LF list, as provided by EDR, and dated 06/29/2022 has revealed that there is 1 NY SWF/LF site  within approximately  0.5 miles of the target property.

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| LARCHMONT/MAMARONECK | 41 MAXWELL AVENUE(LO | SW 1/4 - 1/2 (0.341 mi.) | 91 | 226 |

***Lists of state and tribal leaking storage tanks***

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 08/08/2022 has revealed that there are 93 NY LTANKS sites within approximately  0.5 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| GLOBE RESTAURANT<br>Spill Number/Closed Date: 0511734 / 2006-02-21<br>Site ID: 357947<br>Spill Date: 2006-01-11 | 1879 PALMER AVE | S 1/8 - 1/4 (0.128 mi.) | B12 | 41 |
| REAR OF 1880 PALMER<br>Spill Number/Closed Date: 9602833 / 1996-05-29<br>Site ID: 292396<br>Spill Date: 1996-05-29 | FRANKLYN AVE | SSE 1/8 - 1/4 (0.132 mi.) | C14 | 45 |
| HOFFMANS<br>Spill Number/Closed Date: 9211944 / 1993-01-21<br>Site ID: 111285<br>Spill Date: 1993-01-19 | 1850 PALMER AVE. | SSE 1/8 - 1/4 (0.134 mi.) | C15 | 46 |
| BROMPTON APTS.<br>Spill Number/Closed Date: 9112775 / 1992-03-17<br>Site ID: 93770<br>Spill Date: 1992-03-16 | 1880 PALMER AVE. | S 1/8 - 1/4 (0.137 mi.) | B19 | 50 |
| ***HOFFMAN INVESTORS CO***<br>Spill Number/Closed Date: 9211942 / 2000-03-09<br>Site ID: 104436<br>Spill Date: 1993-01-19 | ***1890 PALMER AVENUE*** | ***S 1/8 - 1/4 (0.151 mi.)*** | ***F25*** | ***102*** |
| BANK OF NY<br>Spill Number/Closed Date: 8800277 / 1997-12-01<br>Site ID: 80193<br>Spill Date: 1988-04-08 | 124 CHASWORTH AVE | S 1/8 - 1/4 (0.162 mi.) | F27 | 105 |
| SPILL NUMBER 8906916<br>Spill Number/Closed Date: 8906577 / 1992-07-30<br>Spill Number/Closed Date: 8906916 / 1992-07-30 | 132 CHATSWORTH AVE | SSW 1/8 - 1/4 (0.175 mi.) | G28 | 106 |

Site ID: 275785
Site ID: 275786
Spill Date: 1989-10-04
Spill Date: 1989-10-09

| | | | | |
|---|---|---|---|---|
| PRESTO RESIDNECE | 130 LAUREL AVE | NE 1/8 - 1/4 (0.178 mi.) | 34 | 118 |
| Spill Number/Closed Date: 1100421 / 2011-09-15 | | | | |
| Site ID: 447824 | | | | |
| Spill Date: 2011-04-12 | | | | |
| BANK OF NEW YORK | 124 CHATSWORTH AVE. | S 1/8 - 1/4 (0.183 mi.) | I37 | 125 |
| Spill Number/Closed Date: 9011938 / 1993-02-23 | | | | |
| Site ID: 276370 | | | | |
| Spill Date: 1991-02-14 | | | | |
| ***BELL ATLANTIC*** | ***5 FRANKLIN ST*** | ***S 1/8 - 1/4 (0.186 mi.)*** | ***J40*** | ***143*** |
| Spill Number/Closed Date: 9810030 / 1998-11-09 | | | | |
| Site ID: 245767 | | | | |
| Spill Date: 1998-11-06 | | | | |
| APARTMENT | 16 NORTH CHATSWORTH | WSW 1/8 - 1/4 (0.193 mi.) | K45 | 155 |
| Spill Number/Closed Date: 0506407 / 2005-11-27 | | | | |
| Site ID: 351623 | | | | |
| Spill Date: 2005-08-24 | | | | |
| LARCH REALTY CORP PR | 1925 PALMER AVE | SSW 1/8 - 1/4 (0.215 mi.) | 55 | 180 |
| Spill Number/Closed Date: 8801114 / 1997-12-01 | | | | |
| Site ID: 108260 | | | | |
| Spill Date: 1988-02-07 | | | | |
| FORLANI | 15-17 HILLCREST AVE | N 1/8 - 1/4 (0.221 mi.) | 56 | 181 |
| Spill Number/Closed Date: 9804871 / 2004-12-07 | | | | |
| Site ID: 120774 | | | | |
| Spill Date: 1998-07-20 | | | | |
| RESIDENCE | 60 MAPLE HILL DR | NNW 1/4 - 1/2 (0.256 mi.) | M64 | 192 |
| Spill Number/Closed Date: 9904648 / 1999-09-28 | | | | |
| Site ID: 254123 | | | | |
| Spill Date: 1999-07-19 | | | | |
| SPILL NUMBER 0107991 | 21 EDGEWOOD AVE | NNE 1/4 - 1/2 (0.258 mi.) | 65 | 193 |
| Spill Number/Closed Date: 0107991 / 2002-02-28 | | | | |
| Site ID: 220664 | | | | |
| Spill Date: 2001-11-06 | | | | |
| SPILL NUMBER 9910464 | 116 LAUREL AVE | NE 1/4 - 1/2 (0.262 mi.) | N66 | 194 |
| Spill Number/Closed Date: 9910464 / 2000-02-10 | | | | |
| Site ID: 283585 | | | | |
| Spill Date: 1999-12-01 | | | | |
| WACHOVIA BANK | 1940 PALMER AVE | SSW 1/4 - 1/2 (0.264 mi.) | 67 | 196 |
| Spill Number/Closed Date: 0401512 / 2004-11-18 | | | | |
| Site ID: 173845 | | | | |
| Spill Date: 2004-05-12 | | | | |
| VALKENBURGH HOME | 47 MAPLE HILL DRIVE | NNW 1/4 - 1/2 (0.264 mi.) | 68 | 197 |
| Spill Number/Closed Date: 0606523 / 2007-01-04 | | | | |
| Site ID: 369884 | | | | |
| Spill Date: 2006-09-07 | | | | |
| RESI:BISNO | 53 HILLSIDE RD | WNW 1/4 - 1/2 (0.268 mi.) | 69 | 198 |
| Spill Number/Closed Date: 0003197 / 2005-04-03 | | | | |
| Site ID: 257812 | | | | |

| | | | | |
|---|---|---|---|---|
| Spill Date: 2000-06-14 | | | | |
| REISMAN RESIDENCE<br>Spill Number/Closed Date: 0800763 / 2008-07-08<br>Site ID: 396571<br>Spill Date: 2008-04-18 | 24 EDGEWOOD AVE | NNE 1/4 - 1/2 (0.269 mi.) | 70 | 199 |
| RESIDENCE<br>Spill Number/Closed Date: 9702679 / 1997-08-08<br>Site ID: 229293<br>Spill Date: 1997-06-02 | 9 SUMMIT AVE | SE 1/4 - 1/2 (0.270 mi.) | 71 | 201 |
| SPILL NUMBER 9910463<br>Spill Number/Closed Date: 9910463 / 2000-02-10<br>Site ID: 171857<br>Spill Date: 1999-12-01 | 114 LAUREL AVE | NE 1/4 - 1/2 (0.274 mi.) | N72 | 202 |
| CARRIER RESIDENCE<br>Spill Number/Closed Date: 0307038 / 2003-11-20<br>Site ID: 174655<br>Spill Date: 2003-10-03 | 45 CARLEON AV | E 1/4 - 1/2 (0.280 mi.) | 73 | 203 |
| PRIVATE RESIDENCE<br>Spill Number/Closed Date: 0400156 / 2004-06-16<br>Site ID: 158874<br>Spill Date: 2004-04-06 | 125 MURRAY AVE | NW 1/4 - 1/2 (0.287 mi.) | 74 | 204 |
| SPILL NUMBER 9903173<br>Spill Number/Closed Date: 9903173 / 1999-07-27<br>Site ID: 66265<br>Spill Date: 1999-06-18 | 26 SUMMITT AVE | SSE 1/4 - 1/2 (0.288 mi.) | 75 | 205 |
| BLONDIE'S TREEHOUSE<br>Spill Number/Closed Date: 0000712 / 2000-08-08<br>Site ID: 175577<br>Spill Date: 2000-04-18 | 21 NORTH AVE | SSW 1/4 - 1/2 (0.292 mi.) | O76 | 207 |
| SPILL NUMBER 9914491<br>Spill Number/Closed Date: 9914491 / 2002-06-29<br>Site ID: 175578<br>Spill Date: 2000-03-22 | 21 NORTH AVE | SSW 1/4 - 1/2 (0.292 mi.) | O77 | 208 |
| RESIDENCE<br>Spill Number/Closed Date: 9312714 / 1995-01-19<br>Site ID: 99667<br>Spill Date: 1994-01-28 | 8 ORSINI DRIVE | NNW 1/4 - 1/2 (0.294 mi.) | P78 | 209 |
| SPILL NUMBER 9806441<br>Spill Number/Closed Date: 9806441 / 1998-09-08<br>Site ID: 107995<br>Spill Date: 1998-08-25 | 26 HILLSIDE ROAD | WNW 1/4 - 1/2 (0.298 mi.) | 79 | 210 |
| PHIL LEBOWITZ<br>Spill Number/Closed Date: 1309250 / 2014-03-17<br>Site ID: 490038<br>Spill Date: 2013-12-18 | 12 ORSINI DRIVE | NNW 1/4 - 1/2 (0.311 mi.) | P81 | 213 |
| ALPERT HOME<br>Spill Number/Closed Date: 0713708 / 2009-08-31<br>Site ID: 395508<br>Spill Date: 2008-03-27 | 80 LOOKOUT CIRCLE | NW 1/4 - 1/2 (0.316 mi.) | 82 | 214 |
| YOUNG HOME | 6 ROCKHILL TERRACE | S 1/4 - 1/2 (0.319 mi.) | 84 | 217 |

| | | | | |
|---|---|---|---|---|
| Spill Number/Closed Date: 0606153 / 2012-08-17<br>Site ID: 369457<br>Spill Date: 2006-08-29 | | | | |
| ***UNITED ARTISTS THEAT***<br>Spill Number/Closed Date: 9401111 / 2001-03-12<br>Site ID: 323532<br>Spill Date: 1994-04-22 | ***1975 PALMER AVE.*** | ***SSW 1/4 - 1/2 (0.326 mi.)*** | ***85*** | ***218*** |
| LEVY<br>Spill Number/Closed Date: 9601585 / 1996-06-12<br>Site ID: 215731<br>Spill Date: 1996-04-30 | 7 ROOSEVELT AV | SE 1/4 - 1/2 (0.332 mi.) | 86 | 221 |
| DILIETO HOME<br>Spill Number/Closed Date: 0502224 / 2006-08-11<br>Site ID: 346541<br>Spill Date: 2005-05-25 | 104 LAUREL AVE | NE 1/4 - 1/2 (0.332 mi.) | 87 | 222 |
| PRIVATE DWELLING<br>Spill Number/Closed Date: 1201667 / 2012-08-20<br>Site ID: 464390<br>Spill Date: 2012-05-21 | 212 LARCHMONT AVE | S 1/4 - 1/2 (0.334 mi.) | R88 | 223 |
| GRECO DWELLING<br>Spill Number/Closed Date: 1201664 / 2012-08-20<br>Site ID: 464387<br>Spill Date: 2012-05-21 | 212 LARCHMONT AVE | S 1/4 - 1/2 (0.334 mi.) | R89 | 224 |
| VERNER RES<br>Spill Number/Closed Date: 9802021 / 1998-06-15<br>Site ID: 160747<br>Spill Date: 1998-05-15 | 46 ECHO LN | NW 1/4 - 1/2 (0.342 mi.) | 92 | 227 |
| MOCCIA - TTF<br>Spill Number/Closed Date: 9906899 / 2000-01-10<br>Site ID: 299008<br>Spill Date: 1999-09-09 | 23 DANTE ST | N 1/4 - 1/2 (0.348 mi.) | S94 | 230 |
| CONDON HOME<br>Spill Number/Closed Date: 0612662 / 2007-03-29<br>Site ID: 377553<br>Spill Date: 2007-02-22 | 16 ORSINI DRIVE | NNW 1/4 - 1/2 (0.354 mi.) | 95 | 231 |
| SPILL NUMBER 9913035<br>Spill Number/Closed Date: 9913035 / 2000-06-01<br>Site ID: 289288<br>Spill Date: 2000-02-16 | 54 LOOKOUT CIRCLE | WNW 1/4 - 1/2 (0.355 mi.) | 96 | 233 |
| SLATTERY RESIDENCE<br>Spill Number/Closed Date: 0705870 / 2007-09-25<br>Site ID: 386276<br>Spill Date: 2007-08-23 | 25 DANTE ST | N 1/4 - 1/2 (0.356 mi.) | S97 | 234 |
| SPILL NUMBER 0205284<br>Spill Number/Closed Date: 0205284 / 2002-09-11<br>Site ID: 98006<br>Spill Date: 2002-08-20 | 60 CHATSWORTH AVE | SSE 1/4 - 1/2 (0.358 mi.) | 98 | 235 |
| RESIDENCE<br>Spill Number/Closed Date: 0507572 / 2006-08-09<br>Site ID: 353041<br>Spill Date: 2005-09-23 | 41 MYRTLE BLVD | NNE 1/4 - 1/2 (0.361 mi.) | 99 | 236 |
| MAUGUE HOME | 23 MAPLEWOOD STREET | NW 1/4 - 1/2 (0.364 mi.) | 100 | 238 |

Spill Number/Closed Date: 0400048 / 2004-06-04
Spill Number/Closed Date: 0509152 / 2005-10-31
Site ID: 316083
Site ID: 354880
Spill Date: 2004-04-02
Spill Date: 2005-10-13

SPRINGER RESIDENCE — 200 LARCHMONT AVE — S 1/4 - 1/2 (0.372 mi.) — 101 — 240
Spill Number/Closed Date: 0404212 / 2004-10-28
Site ID: 328692
Spill Date: 2004-07-20

GLASS RESIDENCE — 5 IDEN AVE — S 1/4 - 1/2 (0.373 mi.) — 102 — 241
Spill Number/Closed Date: 0200914 / 2002-05-29
Site ID: 174074
Spill Date: 2002-04-24

ST. JOHN'S — 280 WEAVER ST. — NNE 1/4 - 1/2 (0.380 mi.) — 103 — 242
Spill Number/Closed Date: 1205086 / 2013-05-07
Spill Number/Closed Date: 0310652 / 2004-01-16
Spill Number/Closed Date: 8705481 / 1988-07-27
Site ID: 468002
Site ID: 123833
Site ID: 246329
Spill Date: 2012-08-20
Spill Date: 2003-12-16
Spill Date: 1987-09-29

MOSER RESIDENCE — 161 MURRAY AVE — NW 1/4 - 1/2 (0.383 mi.) — 104 — 246
Spill Number/Closed Date: 0907297 / 2009-12-22
Site ID: 419812
Spill Date: 2009-09-29

RESIDENCE — 1 FRANCE PLACE — W 1/4 - 1/2 (0.389 mi.) — 107 — 249
Spill Number/Closed Date: 9812530 / 2000-01-13
Site ID: 220361
Spill Date: 1999-01-11

PRIVATE RES — 41 MAPLEWOOD ST — NW 1/4 - 1/2 (0.402 mi.) — 112 — 254
Spill Number/Closed Date: 0402017 / 2004-09-15
Site ID: 321600
Spill Date: 2004-05-24

TTF — 12 COOPER LANE — NNE 1/4 - 1/2 (0.420 mi.) — 113 — 256
Spill Number/Closed Date: 0013697 / 2009-12-30
Spill Number/Closed Date: 0301842 / 2003-06-17
Spill Number/Closed Date: 0713255 / 2008-05-28
Site ID: 165408
Site ID: 125348
Site ID: 394981
Spill Date: 2001-03-31
Spill Date: 2003-05-21
Spill Date: 2008-03-14

SPILL NUMBER 8900768 — 4 WAKEMAN PLACE — S 1/4 - 1/2 (0.428 mi.) — 114 — 259
Spill Number/Closed Date: 8900768 / 1989-11-29
Site ID: 89508
Spill Date: 1989-04-15

SPILL NUMBER 9911157 — 10 ROCHELLE RD — W 1/4 - 1/2 (0.429 mi.) — U115 — 260
Spill Number/Closed Date: 9911157 / 2000-10-17

Site ID: 215427
Spill Date: 1999-12-21

SPILL NUMBER 9905950 — 10 ROCHELLE RD — W 1/4 - 1/2 (0.435 mi.) — U118 — 264
Spill Number/Closed Date: 9905950 / 2000-10-17
Site ID: 215426
Spill Date: 1999-08-18

DALEY RESIDENCE — 2 HEATHER LANE — NNE 1/4 - 1/2 (0.435 mi.) — 119 — 265
Spill Number/Closed Date: 0400710 / 2004-06-04
Site ID: 130559
Spill Date: 2004-04-21

PVT DWELLING — 13 ROCHELLE ROAD — W 1/4 - 1/2 (0.435 mi.) — U120 — 266
Spill Number/Closed Date: 0913558 / 2010-06-08
Site ID: 426508
Spill Date: 2010-03-23

***LARCHMONT AVE CHURCH — 60 FOREST PARK AVE — SSE 1/4 - 1/2 (0.444 mi.) — 122 — 268***
Spill Number/Closed Date: 1114153 / 2013-03-28
Site ID: 462194
Spill Date: 2012-03-21

SPILL NUMBER 0201523 — 101 NORTH CHATSWORTH — NW 1/4 - 1/2 (0.447 mi.) — 123 — 271
Spill Number/Closed Date: 0200579 / 2005-02-09
Spill Number/Closed Date: 0201523 / 2002-06-07
Site ID: 82904
Site ID: 314806
Spill Date: 2002-04-16
Spill Date: 2002-05-10

FORECLOSURE - TTF — 18 ALDEN RD — ESE 1/4 - 1/2 (0.452 mi.) — 125 — 275
Spill Number/Closed Date: 1512394 / 2016-07-27
Site ID: 525209
Spill Date: 2016-03-28

104 NORTH CHATSWORTH — 104 NORTH CHATSWORTH — NW 1/4 - 1/2 (0.459 mi.) — 126 — 277
Spill Number/Closed Date: 0306408 / 2004-03-23
Site ID: 168951
Spill Date: 2003-09-17

IKEA — 10 VALLEY PL — WNW 1/4 - 1/2 (0.477 mi.) — Y134 — 289
Spill Number/Closed Date: 0303396 / 2005-07-05
Site ID: 164849
Spill Date: 2003-07-01

FITCH RESIDENCE — 3 WILDWOOD ROAD — WNW 1/4 - 1/2 (0.478 mi.) — 135 — 290
Spill Number/Closed Date: 1103135 / 2011-08-25
Site ID: 450687
Spill Date: 2011-06-20

ATLAS PARTY RENTALS — 4 VALLEY PLACE — WNW 1/4 - 1/2 (0.482 mi.) — Y137 — 293
Spill Number/Closed Date: 0210744 / 2006-01-30
Site ID: 199114
Spill Date: 2003-01-27

SPILL NUMBER 9812365 — 1 SETON RD — WNW 1/4 - 1/2 (0.487 mi.) — Y138 — 294
Spill Number/Closed Date: 9812365 / 1999-03-09
Site ID: 319993
Spill Date: 1999-01-06

KUNREUTHER - TTF — 17 BONNETT AVENUE — SE 1/4 - 1/2 (0.496 mi.) — 140 — 297
Spill Number/Closed Date: 9902354 / 2000-07-19

Spill Number/Closed Date: 1007092 / 2010-10-27
Site ID: 243264
Site ID: 440479
Spill Date: 1999-06-01
Spill Date: 2010-10-01

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***JF CHATSWORTH*** | ***1 VINE STREET*** | ***WNW 0 - 1/8 (0.048 mi.)*** | ***A5*** | ***21*** |
| Spill Number/Closed Date: 9410303 / 2005-02-27<br>Site ID: 64161<br>Spill Date: 1994-11-02 | | | | |
| MARISIERO INC. | 1-5 VINE STREET | WNW 0 - 1/8 (0.048 mi.) | A8 | 28 |
| Spill Number/Closed Date: 9102813 / 1997-11-14<br>Site ID: 88022<br>Spill Date: 1991-06-10 | | | | |
| ***RESIDENCE*** | ***1825 PALMER AVENUE*** | ***ESE 1/8 - 1/4 (0.137 mi.)*** | ***D18*** | ***49*** |
| Spill Number/Closed Date: 9802511 / 1999-02-08<br>Site ID: 200510<br>Spill Date: 1998-05-26 | | | | |
| UNKNOWN RESIDENCE | 35 NORTH CHATSWORTH | WSW 1/4 - 1/2 (0.253 mi.) | 63 | 190 |
| Spill Number/Closed Date: 0513382 / 2006-07-30<br>Site ID: 359767<br>Spill Date: 2006-02-20 | | | | |
| YAHIA RESIDENCE | 17 HALL AVE | SE 1/4 - 1/2 (0.301 mi.) | Q80 | 211 |
| Spill Number/Closed Date: 0601851 / 2007-01-03<br>Spill Number/Closed Date: 0602686 / 2007-01-03<br>Site ID: 364200<br>Site ID: 365228<br>Spill Date: 2006-05-19<br>Spill Date: 2006-05-22 | | | | |
| SPILL NUMBER 0011319 | 14 HALL AVE | SE 1/4 - 1/2 (0.319 mi.) | Q83 | 216 |
| Spill Number/Closed Date: 0011319 / 2001-04-11<br>Site ID: 184309<br>Spill Date: 2001-01-17 | | | | |
| LARCHMONT AUTO GARAG | 5TH AV & MADISON | WSW 1/4 - 1/2 (0.340 mi.) | 90 | 225 |
| Spill Number/Closed Date: 9611599 / 1996-12-23<br>Site ID: 249760<br>Spill Date: 1996-12-21 | | | | |
| BEN BEDERSON TTF | 8 HALL AVE | SE 1/4 - 1/2 (0.343 mi.) | 93 | 228 |
| Spill Number/Closed Date: 9410735 / 1995-02-13<br>Site ID: 146635<br>Spill Date: 1994-11-11 | | | | |
| BIRDVELL RESIDENCE | 4 FOREST PARK AVE | ESE 1/4 - 1/2 (0.383 mi.) | 105 | 247 |
| Spill Number/Closed Date: 0208984 / 2003-02-27<br>Site ID: 249561<br>Spill Date: 2002-12-02 | | | | |
| MARTIN RES | 16 FOREST PARK AVE | SE 1/4 - 1/2 (0.384 mi.) | T106 | 248 |
| Spill Number/Closed Date: 0111809 / 2002-05-03<br>Site ID: 206085<br>Spill Date: 2002-03-14 | | | | |
| RESIDENCE | 15 FOREST PARK AVE | SE 1/4 - 1/2 (0.392 mi.) | T108 | 250 |

Spill Number/Closed Date: 9505787 / 1996-09-10
Site ID: 120940
Spill Date: 1995-08-10

| | | | | |
|---|---|---|---|---|
| BEZ - TTF | 72 HOWELL AVE | ENE 1/4 - 1/2 (0.395 mi.) | 109 | 251 |
| Spill Number/Closed Date: 0000190 / 2000-04-18<br>Site ID: 231198<br>Spill Date: 2000-04-05 | | | | |
| GARRY RESIDENCE | 7 MEADOW PL | E 1/4 - 1/2 (0.398 mi.) | 110 | 252 |
| Spill Number/Closed Date: 0109734 / 2002-02-04<br>Site ID: 324496<br>Spill Date: 2002-01-08 | | | | |
| SPILL NUMBER 0106394 | 110 CARLEON AVE | E 1/4 - 1/2 (0.401 mi.) | 111 | 253 |
| Spill Number/Closed Date: 0106394 / 2002-01-03<br>Site ID: 314780<br>Spill Date: 2001-09-18 | | | | |
| RESIDENCE | 2 CAMBRIDGE COURT | ESE 1/4 - 1/2 (0.431 mi.) | 116 | 262 |
| Spill Number/Closed Date: 0311004 / 2003-12-31<br>Site ID: 293841<br>Spill Date: 2003-12-26 | | | | |
| ESTATE OF LANDES | 10 CAMBRIDGE COURT | SE 1/4 - 1/2 (0.432 mi.) | V117 | 263 |
| Spill Number/Closed Date: 0401701 / 2004-09-14<br>Site ID: 217696<br>Spill Date: 2004-05-17 | | | | |
| RESIDENCE | 3 CAMBRIDGE CT | ESE 1/4 - 1/2 (0.438 mi.) | V121 | 267 |
| Spill Number/Closed Date: 9800085 / 1998-05-01<br>Site ID: 161347<br>Spill Date: 1998-04-02 | | | | |
| ***SUTIN RESIDENCE*** | ***21 COPLEY RD*** | ***E 1/4 - 1/2 (0.449 mi.)*** | ***124*** | ***273*** |
| Spill Number/Closed Date: 0307108 / 2003-12-03<br>Site ID: 62335<br>Spill Date: 2003-10-06 | | | | |
| SPILL NUMBER 0313036 | 7 HARMONY DRIVE | ESE 1/4 - 1/2 (0.462 mi.) | W127 | 278 |
| Spill Number/Closed Date: 0311429 / 2004-04-26<br>Spill Number/Closed Date: 0313036 / 2004-04-22<br>Site ID: 260818<br>Site ID: 260819<br>Spill Date: 2004-01-09<br>Spill Date: 2004-02-26 | | | | |
| DURON RESIDENCE | 174 LARCHMONT AVE | SSE 1/4 - 1/2 (0.463 mi.) | 128 | 280 |
| Spill Number/Closed Date: 9909450 / 2000-04-11<br>Site ID: 299475<br>Spill Date: 1999-11-03 | | | | |
| CENTRAL SCHOOL | PALMER AVE | ENE 1/4 - 1/2 (0.465 mi.) | 129 | 282 |
| Spill Number/Closed Date: 9305290 / 1994-05-24<br>Site ID: 63916<br>Spill Date: 1993-07-27 | | | | |
| ***TOWN OF MAMARONECK D*** | ***MAXWELL AVE - DPW YA*** | ***SW 1/4 - 1/2 (0.469 mi.)*** | ***X130*** | ***283*** |
| Spill Number/Closed Date: 8708513 / 1988-11-25<br>Site ID: 62756<br>Spill Date: 1987-12-22 | | | | |
| MAMARONECK DPW | MAXWELL ST | SW 1/4 - 1/2 (0.469 mi.) | X131 | 285 |

Spill Number/Closed Date: 9906831 / 2005-09-20
Site ID: 217177
Spill Date: 1999-09-08

DEPT PUBLIC WORKS — MAXWELL AVE — SW 1/4 - 1/2 (0.469 mi.) — X132 — 287
Spill Number/Closed Date: 9907873 / 2003-12-05
Site ID: 197874
Spill Date: 1999-09-29

RESIDENCE — 10 NASSAU RD — ESE 1/4 - 1/2 (0.476 mi.) — 133 — 288
Spill Number/Closed Date: 0403388 / 2004-10-28
Site ID: 138656
Spill Date: 2004-06-29

APT BLD — 11 ALDEN RD — ESE 1/4 - 1/2 (0.478 mi.) — W136 — 291
Spill Number/Closed Date: 0602133 / 2006-09-22
Spill Number/Closed Date: 1011710 / 2011-05-20
Site ID: 364540
Site ID: 445598
Spill Date: 2006-05-26
Spill Date: 2011-02-23

WEBERS HOME — 76 PINEBROOK DRIVE — SSW 1/4 - 1/2 (0.487 mi.) — 139 — 296
Spill Number/Closed Date: 0505197 / 2005-09-26
Site ID: 350147
Spill Date: 2005-07-29

***Lists of state and tribal registered storage tanks***

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 8 NY UST sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| VERIZON NEW YORK INC | 5 FRANKLIN AVENUE | S 1/8 - 1/4 (0.186 mi.) | J39 | 142 |
| Database: WESTCHESTER CO. UST, Date of Government Version: 07/20/2022 | | | | |
| ***LARCHMONT PALMER*** | ***1299 PALMER AVENUE*** | ***E 1/8 - 1/4 (0.187 mi.)*** | ***41*** | ***146*** |
| Database: WESTCHESTER CO. UST, Date of Government Version: 07/20/2022 | | | | |
| Status: 3a. Closed - Prior to 04/1991 | | | | |
| Status: 3. Closed - Removed | | | | |
| Id/Status:: 3-504467 | | | | |
| Site Status: Active | | | | |
| ***16 NORTH CHATSWORTH*** | ***16 NORTH CHATSWORTH*** | ***WSW 1/8 - 1/4 (0.193 mi.)*** | ***K46*** | ***156*** |
| Database: WESTCHESTER CO. UST, Date of Government Version: 07/20/2022 | | | | |
| Status: 3. Closed - Removed | | | | |
| Status: 4. Closed - in place | | | | |
| Id/Status:: 3-167819 | | | | |
| Site Status: Active | | | | |
| LARCHMONT TERRACE CO | 2 WASHINGTON SQUARE | SW 1/8 - 1/4 (0.241 mi.) | L57 | 183 |
| Database: WESTCHESTER CO. UST, Date of Government Version: 07/20/2022 | | | | |

Status: 1. In-Service
Status: 3. Closed - Removed
Id/Status:: 3-166146
Site Status: Active

CARLSHIRE TENANTS IN — 1-3 WASHINGTON SQUAR — SW 1/8 - 1/4 (0.244 mi.) — L61 — 186
Database: WESTCHESTER CO. UST, Date of Government Version: 07/20/2022
Status: 3. Closed - Removed
Id/Status:: 3-167185
Site Status: Active

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***J & F CHATSWORTH LTD*** | ***1 VINE STREET*** | ***WNW 0 - 1/8 (0.048 mi.)*** | ***A6*** | ***23*** |

Database: WESTCHESTER CO. UST, Date of Government Version: 07/20/2022
Status: 3. Closed - Removed
Id/Status:: 3-174394
Site Status: Active

PATRICIA GARDENS OWN — 1825 PALMER AVENUE — ESE 1/8 - 1/4 (0.137 mi.) — D16 — 47
Database: WESTCHESTER CO. UST, Date of Government Version: 07/20/2022
Status: 4. Closed - in place
Id/Status:: 3-048429
Site Status: Active

COLONY TENANTS CORP. — 1815 PALMER AVENUE — ESE 1/8 - 1/4 (0.152 mi.) — 26 — 104
Database: WESTCHESTER CO. UST, Date of Government Version: 07/20/2022
Status: 1. In-Service
Status: 3. Closed - Removed
Id/Status:: 3-104590
Site Status: Active

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 11 NY AST sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| THE BROMPTON | 1880 PALMER AVENUE | S 1/8 - 1/4 (0.137 mi.) | B20 | 51 |

Database: WESTCHESTER CO. AST, Date of Government Version: 07/20/2022
Status: 4. Closed - in place
Status: 1. In-Service
PBS Number: 3-800888

HOWELL ASSOCIATES — 132 CHATSWORTH AVENU — SSW 1/8 - 1/4 (0.175 mi.) — G29 — 109
Database: WESTCHESTER CO. AST, Date of Government Version: 07/20/2022
Status: 1. In-Service
PBS Number: 3-049565

***LARCHMONT PALMER*** — ***1299 PALMER AVENUE*** — ***E 1/8 - 1/4 (0.187 mi.)*** — ***41*** — ***146***
Database: WESTCHESTER CO. AST, Date of Government Version: 07/20/2022
Status: 1. In-Service
PBS Number: 3-504467

CHATSWORTH GARDENS C — 14 NORTH CHATSWORTH — WSW 1/8 - 1/4 (0.191 mi.) — K42 — 147
Database: WESTCHESTER CO. AST, Date of Government Version: 07/20/2022

Status: 1. In-Service
PBS Number: 3-506788

***16 NORTH CHATSWORTH*** ***16 NORTH CHATSWORTH*** ***WSW 1/8 - 1/4 (0.193 mi.)*** ***K46*** ***156***
Database: WESTCHESTER CO. AST, Date of Government Version: 07/20/2022
Status: 1. In-Service
PBS Number: 3-167819

LARCHMONT HILLS OWNE 17 NORTH CHATSWORTH WSW 1/8 - 1/4 (0.198 mi.) K50 166
Database: WESTCHESTER CO. AST, Date of Government Version: 07/20/2022
Status: 3. Closed - Removed
Status: 1. In-Service
PBS Number: 3-048488

172 MYRTLE BLVD. APT 172 MYRTLE BOULEVARD SW 1/8 - 1/4 (0.208 mi.) 54 179
Database: WESTCHESTER CO. AST, Date of Government Version: 07/20/2022
Status: 1. In-Service
PBS Number: 3-800128

THE KEYSTONE 76 WENDT AVENUE S 1/8 - 1/4 (0.241 mi.) 58 184
Database: WESTCHESTER CO. AST, Date of Government Version: 07/20/2022
Status: 1. In-Service
PBS Number: 3-801206

CARLSHIRE TENANTS IN 1-3 WASHINGTON SQUAR SW 1/8 - 1/4 (0.244 mi.) L60 185
Database: WESTCHESTER CO. AST, Date of Government Version: 07/20/2022
Status: 1. In-Service
PBS Number: 3-167185

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***J & F CHATSWORTH LTD*** | ***1 VINE STREET*** | ***WNW 0 - 1/8 (0.048 mi.)*** | ***A6*** | ***23*** |

Database: WESTCHESTER CO. AST, Date of Government Version: 07/20/2022
Status: 1. In-Service
PBS Number: 3-174394

PATRICIA GARDENS OWN 1825 PALMER AVENUE ESE 1/8 - 1/4 (0.137 mi.) D17 48
Database: WESTCHESTER CO. AST, Date of Government Version: 07/20/2022
Status: 1. In-Service
PBS Number: 3-048429

## ADDITIONAL ENVIRONMENTAL RECORDS

### *Records of Emergency Release Reports*

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 08/08/2022 has revealed that there are 4 NY Spills sites within approximately 0.125 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| TRAFFIC ACCIDENT | I-95 MP 7.7 | SSW 0 - 1/8 (0.045 mi.) | 1 | 8 |

Spill Number/Closed Date: 9407990 / 1994-09-22

Site ID: 154341
Spill Date: 1994-09-15

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| JS CHADWORTHS<br>Spill Number/Closed Date: 1501291 / 2015-07-08<br>Site ID: 507486<br>Spill Date: 2015-05-05 | 1 VINE ST | WNW 0 - 1/8 (0.048 mi.) | A4 | 20 |
| ***JF CHATSWORTH***<br>Spill Number/Closed Date: 9413519 / 1995-01-23<br>Site ID: 64162<br>Spill Date: 1995-01-10 | ***1 VINE STREET*** | ***WNW 0 - 1/8 (0.048 mi.)*** | ***A5*** | ***21*** |
| DECABIA - UST<br>Spill Number/Closed Date: 2202138 / 2022-07-14<br>Site ID: 637212<br>Spill Date: 2022-06-08 | 19 CABOT RD | NNE 0 - 1/8 (0.082 mi.) | 11 | 40 |

***Other Ascertainable Records***

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 06/20/2022 has revealed that there are 11 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***MAGIC TOUCH CLEANERS***<br>EPA ID:: NY0000204958 | ***5 VINE ST*** | ***WNW 0 - 1/8 (0.045 mi.)*** | ***A3*** | ***9*** |
| ***CON EDISON SERVICE B***<br>EPA ID:: NYP004486809 | ***PALMER AVE & E DEPOT*** | ***SSE 1/8 - 1/4 (0.129 mi.)*** | ***C13*** | ***42*** |
| ***CON EDISON***<br>EPA ID:: NYP004777850 | ***MYRTLE BLVD & MURRAY*** | ***SW 1/8 - 1/4 (0.141 mi.)*** | ***E22*** | ***54*** |
| ***CON EDISON***<br>EPA ID:: NYP004766622 | ***MYRTLE AVE & CHATSWO*** | ***SW 1/8 - 1/4 (0.176 mi.)*** | ***H30*** | ***110*** |
| NYS THRUWAY MAINTENA<br>EPA ID:: NY0000198762 | I-95 EXIT 17 OFF NEW | SSW 1/8 - 1/4 (0.177 mi.) | 33 | 115 |
| ***CON EDISON MANHOLE:***<br>EPA ID:: NYP004309225 | ***CHATSWORTH AVE & PAL*** | ***S 1/8 - 1/4 (0.179 mi.)*** | ***I35*** | ***119*** |
| ***EMBASSY CLEANERS***<br>EPA ID:: NYD012815395 | ***1908 PALMER AVE*** | ***S 1/8 - 1/4 (0.192 mi.)*** | ***I43*** | ***149*** |
| ***DUTCH GIRL PROFESSIO***<br>EPA ID:: NYD106797061 | ***1912 PALMER AVE*** | ***S 1/8 - 1/4 (0.202 mi.)*** | ***I52*** | ***171*** |
| ***DONALD RITACCO & CO***<br>EPA ID:: NYD982718249 | ***7-11 NORTH AVE*** | ***SSW 1/8 - 1/4 (0.204 mi.)*** | ***53*** | ***174*** |
| ***CON EDISON*** | ***6 OVERLOOK TER*** | ***W 1/8 - 1/4 (0.247 mi.)*** | ***62*** | ***187*** |

EPA ID:: NYP004162822

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***CON EDISON POLE W10*** EPA ID:: NYP004145074 | ***HALL AVE & CONCORD A*** | ***ESE 1/8 - 1/4 (0.201 mi.)*** | ***51*** | ***167*** |

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 08/30/2022 has revealed that there are 4 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***MAGIC TOUCH CLEANERS*** Facility Id: 3-5532-00313 | ***5 VINE ST*** | ***WNW 0 - 1/8 (0.045 mi.)*** | ***A3*** | ***9*** |
| ***EMBASSY CLEANERS*** Facility Id: 3-5532-00266 | ***1908 PALMER AVE*** | ***S 1/8 - 1/4 (0.150 mi.)*** | ***F24*** | ***58*** |
| ***CHATSWORTH CLEANERS*** Facility Id: 3-5532-00305 | ***120 CHATSWORTH AVE*** | ***S 1/8 - 1/4 (0.185 mi.)*** | ***I38*** | ***127*** |
| EMBASSY CLEANERS Facility Id: 3-5532-00189 | 1908 PALMER AVENUE | S 1/8 - 1/4 (0.192 mi.) | I44 | 155 |

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there are 16 NY MANIFEST sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***MAGIC TOUCH CLEANERS*** EPA ID: NYD000204958 EPA ID: NY0000204958 | ***5 VINE ST*** | ***WNW 0 - 1/8 (0.045 mi.)*** | ***A3*** | ***9*** |
| CON EDISON EPA ID: NYP004777850 | MYRTLE BLVD & MURRAY | SW 1/8 - 1/4 (0.141 mi.) | E23 | 56 |
| ***EMBASSY CLEANERS*** EPA ID: NYD986995249 | ***1908 PALMER AVE*** | ***S 1/8 - 1/4 (0.150 mi.)*** | ***F24*** | ***58*** |
| CON EDISON EPA ID: NYP004766622 | MYRTLE AVE & CHATSWO | SW 1/8 - 1/4 (0.176 mi.) | H31 | 112 |
| ***CON EDISON MANHOLE:*** EPA ID: NYP004309225 | ***CHATSWORTH AVE & PAL*** | ***S 1/8 - 1/4 (0.179 mi.)*** | ***I35*** | ***119*** |
| CON EDISON EPA ID: NYP004699658 | PALMER AVE & CHATSWO | S 1/8 - 1/4 (0.179 mi.) | I36 | 124 |
| ***CHATSWORTH CLEANERS*** EPA ID: NY0000363101 | ***120 CHATSWORTH AVE*** | ***S 1/8 - 1/4 (0.185 mi.)*** | ***I38*** | ***127*** |
| ***EMBASSY CLEANERS*** EPA ID: NYD012815395 | ***1908 PALMER AVE*** | ***S 1/8 - 1/4 (0.192 mi.)*** | ***I43*** | ***149*** |
| CON EDISON | CHATSWORTH AVE & WAS | WSW 1/8 - 1/4 (0.195 mi.) | K47 | 158 |

| | | | | |
|---|---|---|---|---|
| EPA ID: NYP004682852 | | | | |
| CONSOLIDATED EDISON<br>EPA ID: NYP004093696 | WASHINGTON & N CHATS | WSW 1/8 - 1/4 (0.195 mi.) | K48 | 160 |
| ***06-D3M DOM'S CAR CAR***<br>EPA ID: NYD986958171 | ***107 CHATSWORTH*** | ***S 1/8 - 1/4 (0.196 mi.)*** | ***J49*** | ***160*** |
| ***DONALD RITACCO & CO***<br>EPA ID: NYD982718249 | ***7-11 NORTH AVE*** | ***SSW 1/8 - 1/4 (0.204 mi.)*** | ***53*** | ***174*** |
| VERIZON<br>EPA ID: NYP000951301 | 15 EMERSON RD | NNW 1/8 - 1/4 (0.242 mi.) | M59 | 184 |
| ***CON EDISON***<br>EPA ID: NYP004162822 | ***6 OVERLOOK TER*** | ***W 1/8 - 1/4 (0.247 mi.)*** | ***62*** | ***187*** |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***J & F CHATSWORTH LTD***<br>EPA ID: NYD982718272 | ***1 VINE ST*** | ***WNW 0 - 1/8 (0.048 mi.)*** | ***A10*** | ***30*** |
| ***CON EDISON POLE W10***<br>EPA ID: NYP004145074 | ***HALL AVE & CONCORD A*** | ***ESE 1/8 - 1/4 (0.201 mi.)*** | ***51*** | ***167*** |

RI MANIFEST: Hazardous waste manifest information

A review of the RI MANIFEST list, as provided by EDR, and dated 12/31/2020 has revealed that there is 1 RI MANIFEST site within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***EMBASSY CLEANERS***<br>EPA Id: NYD986995249<br>Manifest Document Number: 002496373SKS | ***1908 PALMER AVE*** | ***S 1/8 - 1/4 (0.150 mi.)*** | ***F24*** | ***58*** |

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 3 NJ MANIFEST sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| CON EDISON<br>EPA Id: NYP004777850 | MYRTLE BLVD & MURRAY | SW 1/8 - 1/4 (0.141 mi.) | E21 | 53 |
| CON EDISON<br>EPA Id: NYP004766622 | MYRTLE AVE & CHATSWO | SW 1/8 - 1/4 (0.176 mi.) | H32 | 114 |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***J & F CHATSWORTH LTD***<br>EPA Id: NYD982718272 | ***1 VINE ST*** | ***WNW 0 - 1/8 (0.048 mi.)*** | ***A10*** | ***30*** |

# EXECUTIVE SUMMARY

## EDR HIGH RISK HISTORICAL RECORDS

### *EDR Exclusive Records*

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there is 1 EDR Hist Auto site within approximately 0.125 miles of the target property.

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| CHATSWORTH GARAGE IN | 1 VINE ST | WNW 0 - 1/8 (0.048 mi.) | A7 | 28 |

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 2 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| KIM KWUNG | 5 VINE ST | WNW 0 - 1/8 (0.045 mi.) | A2 | 9 |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| MAGIC TOUCH CLEANERS | 1 VINE ST | WNW 0 - 1/8 (0.048 mi.) | A9 | 30 |

# EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 5 records.

| Site Name | Database(s) |
|---|---|
| MEARL CORP. | NY SHWS |
| SPILL NUMBER 8601246 | NY LTANKS |
| N.SHORE LONG ISLAND SOUND | NY LTANKS |
| MM 5.4 LEFT LANE | NY LTANKS |
| PINEBROOK TENNIS COURTS | NY VCP |

# OVERVIEW MAP - 7180742.2S




Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

0 1/4 1/2 1 Miles

Indian Reservations BIA

Special Flood Hazard Area (1%)

0.2% Annual Chance Flood Hazard

National Wetland Inventory

State Wetlands

N

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

| | | | |
|---|---|---|---|
| SITE NAME: | 15 VINE ST | CLIENT: | American Petroleum |
| ADDRESS: | 15 VINE ST<br>LARCHMONT NY 10538 | CONTACT: | Michelle Nowak |
| | | INQUIRY #: | 7180742.2s |
| LAT/LONG: | 40.935478 / 73.758432 | DATE: | November 16, 2022 3:18 pm |

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

# DETAIL MAP - 7180742.2S

Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

Sensitive Receptors

National Priority List Sites

Dept. Defense Sites

Indian Reservations BIA

0 1/16 1/8 1/4 Miles

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

| | | | |
|---|---|---|---|
| SITE NAME: | 15 VINE ST | CLIENT: | American Petroleum |
| ADDRESS: | 15 VINE ST<br>LARCHMONT NY 10538 | CONTACT: | Michelle Nowak |
| LAT/LONG: | 40.935478 / 73.758432 | INQUIRY #: | 7180742.2s |
| | | DATE: | November 16, 2022 3:19 pm |

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

# MAP FINDINGS SUMMARY

| Database | Search Distance (Miles) | Target Property | < 1/8 | 1/8 - 1/4 | 1/4 - 1/2 | 1/2 - 1 | > 1 | Total Plotted |
|---|---|---|---|---|---|---|---|---|
| **STANDARD ENVIRONMENTAL RECORDS** | | | | | | | | |
| ***Lists of Federal NPL (Superfund) sites*** | | | | | | | | |
| NPL | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| Proposed NPL | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| NPL LIENS | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| ***Lists of Federal Delisted NPL sites*** | | | | | | | | |
| Delisted NPL | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| ***Lists of Federal sites subject to CERCLA removals and CERCLA orders*** | | | | | | | | |
| FEDERAL FACILITY | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| SEMS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Lists of Federal CERCLA sites with NFRAP*** | | | | | | | | |
| SEMS-ARCHIVE | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Lists of Federal RCRA facilities undergoing Corrective Action*** | | | | | | | | |
| CORRACTS | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| ***Lists of Federal RCRA TSD facilities*** | | | | | | | | |
| RCRA-TSDF | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Lists of Federal RCRA generators*** | | | | | | | | |
| RCRA-LQG | 0.250 | | 0 | 1 | NR | NR | NR | 1 |
| RCRA-SQG | 0.250 | | 1 | 1 | NR | NR | NR | 2 |
| RCRA-VSQG | 0.250 | | 0 | 1 | NR | NR | NR | 1 |
| ***Federal institutional controls / engineering controls registries*** | | | | | | | | |
| LUCIS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| US ENG CONTROLS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| US INST CONTROLS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Federal ERNS list*** | | | | | | | | |
| ERNS | TP | | NR | NR | NR | NR | NR | 0 |
| ***Lists of state- and tribal hazardous waste facilities*** | | | | | | | | |
| NY SHWS | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| ***Lists of state and tribal landfills and solid waste disposal facilities*** | | | | | | | | |
| NY SWF/LF | 0.500 | | 0 | 0 | 1 | NR | NR | 1 |
| ***Lists of state and tribal leaking storage tanks*** | | | | | | | | |
| INDIAN LUST | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |

# MAP FINDINGS SUMMARY

| Database | Search Distance (Miles) | Target Property | < 1/8 | 1/8 - 1/4 | 1/4 - 1/2 | 1/2 - 1 | > 1 | Total Plotted |
|---|---|---|---|---|---|---|---|---|
| NY LTANKS | 0.500 | | 2 | 14 | 77 | NR | NR | 93 |
| NY HIST LTANKS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Lists of state and tribal registered storage tanks*** | | | | | | | | |
| FEMA UST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY UST | 0.250 | | 1 | 7 | NR | NR | NR | 8 |
| NY CBS UST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY MOSF UST | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| NY MOSF | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| NY CBS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY AST | 0.250 | | 1 | 10 | NR | NR | NR | 11 |
| NY CBS AST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY MOSF AST | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| INDIAN UST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY TANKS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***State and tribal institutional control / engineering control registries*** | | | | | | | | |
| NY RES DECL | 0.125 | | 0 | NR | NR | NR | NR | 0 |
| NY ENG CONTROLS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| NY INST CONTROL | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Lists of state and tribal voluntary cleanup sites*** | | | | | | | | |
| NY VCP | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| INDIAN VCP | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Lists of state and tribal brownfield sites*** | | | | | | | | |
| NY BROWNFIELDS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| NY ERP | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| **ADDITIONAL ENVIRONMENTAL RECORDS** | | | | | | | | |
| ***Local Brownfield lists*** | | | | | | | | |
| US BROWNFIELDS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Local Lists of Landfill / Solid Waste Disposal Sites*** | | | | | | | | |
| NY SWTIRE | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| NY SWRCY | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| INDIAN ODI | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| DEBRIS REGION 9 | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ODI | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| IHS OPEN DUMPS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Local Lists of Hazardous waste / Contaminated Sites*** | | | | | | | | |
| US HIST CDL | TP | | NR | NR | NR | NR | NR | 0 |
| NY DEL SHWS | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| US CDL | TP | | NR | NR | NR | NR | NR | 0 |
| ***Local Lists of Registered Storage Tanks*** | | | | | | | | |
| NY HIST UST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |

# MAP FINDINGS SUMMARY

| Database | Search Distance (Miles) | Target Property | < 1/8 | 1/8 - 1/4 | 1/4 - 1/2 | 1/2 - 1 | > 1 | Total Plotted |
|---|---|---|---|---|---|---|---|---|
| NY HIST AST | TP | | NR | NR | NR | NR | NR | 0 |
| ***Local Land Records*** | | | | | | | | |
| NY LIENS | TP | | NR | NR | NR | NR | NR | 0 |
| LIENS 2 | TP | | NR | NR | NR | NR | NR | 0 |
| ***Records of Emergency Release Reports*** | | | | | | | | |
| HMIRS | TP | | NR | NR | NR | NR | NR | 0 |
| NY Spills | 0.125 | | 4 | NR | NR | NR | NR | 4 |
| NY Hist Spills | 0.125 | | 0 | NR | NR | NR | NR | 0 |
| NY SPILLS 90 | 0.125 | | 0 | NR | NR | NR | NR | 0 |
| NY SPILLS 80 | 0.125 | | 0 | NR | NR | NR | NR | 0 |
| ***Other Ascertainable Records*** | | | | | | | | |
| RCRA NonGen / NLR | 0.250 | | 1 | 10 | NR | NR | NR | 11 |
| FUDS | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| DOD | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| SCRD DRYCLEANERS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| US FIN ASSUR | TP | | NR | NR | NR | NR | NR | 0 |
| EPA WATCH LIST | TP | | NR | NR | NR | NR | NR | 0 |
| 2020 COR ACTION | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| TSCA | TP | | NR | NR | NR | NR | NR | 0 |
| TRIS | TP | | NR | NR | NR | NR | NR | 0 |
| SSTS | TP | | NR | NR | NR | NR | NR | 0 |
| ROD | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| RMP | TP | | NR | NR | NR | NR | NR | 0 |
| RAATS | TP | | NR | NR | NR | NR | NR | 0 |
| PRP | TP | | NR | NR | NR | NR | NR | 0 |
| PADS | TP | | NR | NR | NR | NR | NR | 0 |
| ICIS | TP | | NR | NR | NR | NR | NR | 0 |
| FTTS | TP | | NR | NR | NR | NR | NR | 0 |
| MLTS | TP | | NR | NR | NR | NR | NR | 0 |
| COAL ASH DOE | TP | | NR | NR | NR | NR | NR | 0 |
| COAL ASH EPA | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| PCB TRANSFORMER | TP | | NR | NR | NR | NR | NR | 0 |
| RADINFO | TP | | NR | NR | NR | NR | NR | 0 |
| HIST FTTS | TP | | NR | NR | NR | NR | NR | 0 |
| DOT OPS | TP | | NR | NR | NR | NR | NR | 0 |
| CONSENT | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| INDIAN RESERV | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| FUSRAP | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| UMTRA | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| LEAD SMELTERS | TP | | NR | NR | NR | NR | NR | 0 |
| US AIRS | TP | | NR | NR | NR | NR | NR | 0 |
| US MINES | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ABANDONED MINES | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| FINDS | TP | | NR | NR | NR | NR | NR | 0 |
| UXO | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| ECHO | TP | | NR | NR | NR | NR | NR | 0 |
| DOCKET HWC | TP | | NR | NR | NR | NR | NR | 0 |
| FUELS PROGRAM | 0.250 | | 0 | 0 | NR | NR | NR | 0 |

# MAP FINDINGS SUMMARY

| Database | Search Distance (Miles) | Target Property | < 1/8 | 1/8 - 1/4 | 1/4 - 1/2 | 1/2 - 1 | > 1 | Total Plotted |
|---|---|---|---|---|---|---|---|---|
| PFAS NPL | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS FEDERAL SITES | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS TSCA | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS RCRA MANIFEST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS ATSDR | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS WQP | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS NPDES | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS ECHO | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS ECHO FIRE TRAINING | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS PART 139 AIRPORT | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| AQUEOUS FOAM NRC | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY PFAS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY AIRS | TP | | NR | NR | NR | NR | NR | 0 |
| NY COAL ASH | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| NY DRYCLEANERS | 0.250 | | 1 | 3 | NR | NR | NR | 4 |
| NY E DESIGNATION | 0.125 | | 0 | NR | NR | NR | NR | 0 |
| NY Financial Assurance | TP | | NR | NR | NR | NR | NR | 0 |
| NY HSWDS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| NY MANIFEST | 0.250 | | 2 | 14 | NR | NR | NR | 16 |
| RI MANIFEST | 0.250 | | 0 | 1 | NR | NR | NR | 1 |
| NJ MANIFEST | 0.250 | | 1 | 2 | NR | NR | NR | 3 |
| NY SPDES | TP | | NR | NR | NR | NR | NR | 0 |
| NY VAPOR REOPENED | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| NY UIC | TP | | NR | NR | NR | NR | NR | 0 |
| NY COOLING TOWERS | TP | | NR | NR | NR | NR | NR | 0 |
| NY LEAD | TP | | NR | NR | NR | NR | NR | 0 |
| MINES MRDS | TP | | NR | NR | NR | NR | NR | 0 |
| **EDR HIGH RISK HISTORICAL RECORDS** | | | | | | | | |
| ***EDR Exclusive Records*** | | | | | | | | |
| EDR MGP | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| EDR Hist Auto | 0.125 | | 1 | NR | NR | NR | NR | 1 |
| EDR Hist Cleaner | 0.125 | | 2 | NR | NR | NR | NR | 2 |
| **EDR RECOVERED GOVERNMENT ARCHIVES** | | | | | | | | |
| ***Exclusive Recovered Govt. Archives*** | | | | | | | | |
| NY RGA HWS | TP | | NR | NR | NR | NR | NR | 0 |
| NY RGA LF | TP | | NR | NR | NR | NR | NR | 0 |
| - Totals -- | | 0 | 17 | 64 | 78 | 0 | 0 | 159 |

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

**1**
**SSW**
**< 1/8**
**0.045 mi.**
**237 ft.**

**TRAFFIC ACCIDENT**
**I-95 MP 7.7**
**LARCHMONT, NY**

**NY Spills** **S102109878**
**N/A**

**Relative:**
**Higher**

**Actual:**
**44 ft.**

SPILLS:

| | |
|---|---|
| Name: | TRAFFIC ACCIDENT |
| Address: | I-95 MP 7.7 |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9407990 / 1994-09-22 |
| Facility ID: | 9407990 |
| Facility Type: | ER |
| DER Facility ID: | 130891 |
| Site ID: | 154341 |
| DEC Region: | 3 |
| Spill Cause: | Traffic Accident |
| Spill Class: | C3 |
| SWIS: | 6000 |
| Spill Date: | 1994-09-15 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1994-09-15 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Police Department |
| Cleanup Ceased: | 1994-09-22 |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-12-02 |
| Spill Record Last Update: | 2003-12-02 |
| Spiller Name: | Not reported |
| Spiller Company: | ELIAS STOLTZSUN |
| Spiller Address: | 435 BEACHDALE ROAD |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: | "TANK RUPTURED DRIVER INJURED LARCHMONT & MAMARONECK F.D. ON SCENE T-WAY AUTHORITY ON SCENE & PERFORMING CLEAN UP" |

All Materials:

| | |
|---|---|
| Site ID: | 154341 |
| Operable Unit ID: | 1002173 |
| Operable Unit: | 01 |
| Material ID: | 377444 |
| Material Code: | 0008 |
| Material Name: | diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 20.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**A2** **KIM KWUNG** **EDR Hist Cleaner** **1018463930**
**WNW** **5 VINE ST** **N/A**
**< 1/8** **LARCHMONT, NY 10538**
**0.045 mi.**
**240 ft.** **Site 1 of 9 in cluster A**

**Relative:** EDR Hist Cleaner
**Higher**

**Actual:** **41 ft.**

| Year: | Name: | Type: |
|---|---|---|
| 1971 | MICHELS FRENCY DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1972 | MICHELS FRENCY DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1973 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1974 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1976 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1977 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1978 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1979 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1980 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1982 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1983 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1985 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1986 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1987 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1988 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1989 | ANNA MARIAS CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1990 | ANNA MARIAS CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1991 | ANNA MARIAS CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1992 | ANNA MARIAS CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1993 | ANNA MARIAS CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1996 | MAGIC TOUCH CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1997 | MAGIC TOUCH CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1998 | MAGIC TOUCH CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1999 | MAGIC TOUCH CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 2000 | MAGIC TOUCH CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 2001 | MAGIC TOUCH CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 2002 | MAGIC TOUCH CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 2003 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2004 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2005 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2006 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2007 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2008 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2009 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2010 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2011 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2012 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2013 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2014 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |

---

**A3** **MAGIC TOUCH CLEANERS** **RCRA NonGen / NLR** **1000890004**
**WNW** **5 VINE ST** **ICIS** **NY0000204958**
**< 1/8** **LARCHMONT, NY 10538** **US AIRS**
**0.045 mi.** **NY DRYCLEANERS**
**240 ft.** **Site 2 of 9 in cluster A** **NY MANIFEST**

**Relative:** RCRA Listings:
**Higher**

**Actual:** **41 ft.**

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20070101 |
| Handler Name: | MAGIC TOUCH | |
| Handler Address: | | 5 VINE ST |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | | |
|---|---|---|
| EPA ID: | | NY0000204958 |
| Contact Name: | | KWANG KIM |
| Contact Address: | | VINE ST |
| Contact City,State,Zip: | | LARCHMONT, NY 10538 |
| Contact Telephone: | | 917-834-8880 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | NY |
| State District: | | NYSDEC R3 |
| Mailing Address: | | VINE ST |
| Mailing City,State,Zip: | | LARCHMONT, NY 10538 |
| Owner Name: | YOON S KIM | |
| Owner Type: | | Private |
| Operator Name: | YOON S KIM | |
| Operator Type: | | Private |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site Fed-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site Converter Treatment storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| Commercial TSD Indicator: | | No |
| Treatment Storage and Disposal Type: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| Permit Renewals Workload Universe: | | Not reported |
| Permit Workload Universe: | | Not reported |
| Permit Progress Universe: | | Not reported |
| Post-Closure Workload Universe: | | Not reported |
| Closure Workload Universe: | | Not reported |
| 202 GPRA Corrective Action Baseline: | | No |
| Corrective Action Workload Universe: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: | | No |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

TSDFs Only Subject to CA under Discretionary Auth Universe: No
Corrective Action Priority Ranking: No NCAPS ranking
Environmental Control Indicator: No
Institutional Control Indicator: No
Human Exposure Controls Indicator: N/A
Groundwater Controls Indicator: N/A
Operating TSDF Universe: Not reported
Full Enforcement Universe: Not reported
Significant Non-Complier Universe: No
Unaddressed Significant Non-Complier Universe: No
Addressed Significant Non-Complier Universe: No
Significant Non-Complier With a Compliance Schedule Universe: No
Financial Assurance Required: Not reported
Handler Date of Last Change: 20150414
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D007
Waste Description: CHROMIUM

Waste Code: D008
Waste Description: LEAD

Waste Code: D039
Waste Description: TETRACHLOROETHYLENE

Waste Code: D040
Waste Description: TRICHLORETHYLENE

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: YOON S KIM

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Legal Status: | Private |
| Date Became Current: | 19961101 |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 330 FORT LEE RD |
| Owner/Operator City,State,Zip: | LEONIA, NJ 07605 |
| Owner/Operator Telephone: | 201-944-4638 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |
| | |
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: KWANG JIN KIM | |
| Legal Status: | Private |
| Date Became Current: | 20010101 |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 175 HALSTEAD AVE |
| Owner/Operator City,State,Zip: | HARRISON, NY 10528 |
| Owner/Operator Telephone: | 914-834-8880 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |
| | |
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: YOON S KIM | |
| Legal Status: | Private |
| Date Became Current: | 19961101 |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 330 FORT LEE RD |
| Owner/Operator City,State,Zip: | LEONIA, NJ 07605 |
| Owner/Operator Telephone: | 201-944-4638 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |
| | |
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: KWANG JIN KIM | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 175 HALSTEAD AVE |
| Owner/Operator City,State,Zip: | HARRISON, NY 10528 |
| Owner/Operator Telephone: | 914-834-8880 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |
| | |
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: YOON S KIM | |
| Legal Status: | Private |
| Date Became Current: | 19961101 |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 330 FORT LEE RD |
| Owner/Operator City,State,Zip: | LEONIA, NJ 07605 |
| Owner/Operator Telephone: | 201-944-4638 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

Owner/Operator Indicator: Operator
Owner/Operator Name: KWANG JIN KIM
Legal Status: Private
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 175 HALSTEAD AVE
Owner/Operator City,State,Zip: HARRISON, NY 10528
Owner/Operator Telephone: 914-834-8880
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990714
Handler Name: MAGIC TOUCH
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: MAGIC TOUCH
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MAGIC TOUCH
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19961114
Handler Name: MAGIC TOUCH
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |
| Receive Date: | 20001122 |
| Handler Name: MAGIC TOUCH | |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ICIS:

| | |
|---|---|
| Enforcement Action ID: | NY000A0000355320031300308 |
| FRS ID: | 110004313975 |
| Action Name: | MAGIC TOUCH CLEANERS 36119R232000308 |
| Facility Name: | MAGIC TOUCH CLEANERS |
| Facility Address: | 5 VINE ST<br>LARCHMONT, NY 105382328 |
| Enforcement Action Type: | Notice of Violation |
| Facility County: | WESTCHESTER |
| Program System Acronym: | AIR |
| Enforcement Action Forum Desc: | Administrative - Informal |
| EA Type Code: | NOV |
| Facility SIC Code: | 7216 |
| Federal Facility ID: | Not reported |
| Latitude in Decimal Degrees: | 40.935512 |
| Longitude in Decimal Degrees: | -73.758465 |
| Permit Type Desc: | Not reported |
| Program System Acronym: | NY0000003553200313 |
| Facility NAICS Code: | 812320 |
| Tribal Land Code: | Not reported |

US AIRS MINOR:
Envid: 1000890004

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

Region Code: 02
Programmatic ID: AIR NY0000003553200313
Facility Registry ID: 110004313975
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000003553200313
Facility Registry ID: 110004313975
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-12-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200313
Facility Registry ID: 110004313975
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2006-04-27 00:00:00
Activity Status Date: 2006-04-27 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000003553200313
Facility Registry ID: 110004313975
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-12-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

DRYCLEANERS:
Name: MAGIC TOUCH CLEANERS
Address: 5 VINE ST
City,State,Zip: LARCHMONT, NY 10538 2328
Facility ID: 3-5532-00313
Phone Number: 9148348880
Region: Not reported
Registration Effective Date: 2000-12-11 14:22:09

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Inspection Date: | 2000-12-06 08:30:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2003 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 2004-03-10 10:21:44 |
| Inspection Date: | 2002-12-13 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/03/2019 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 2003-05-29 09:12:41 |
| Inspection Date: | 2002-12-13 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 06/11/2003 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 2000-12-11 14:22:09 |
| Inspection Date: | 2002-12-13 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2003 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 2019-05-03 11:25:25 |
| Inspection Date: | 2001-12-14 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/03/2029 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 2004-03-10 10:21:44 |
| Inspection Date: | 2001-12-14 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/03/2019 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 2003-05-29 09:12:41 |
| Inspection Date: | 2001-12-14 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 06/11/2003 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 2000-12-11 14:22:09 |
| Inspection Date: | 2001-12-14 08:00:00 |
| Install Date: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Expiration Date: | 05/29/2003 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 2019-05-03 11:25:25 |
| Inspection Date: | 2000-12-06 08:30:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/03/2029 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 2004-03-10 10:21:44 |
| Inspection Date: | 2000-12-06 08:30:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/03/2019 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 2003-05-29 09:12:41 |
| Inspection Date: | 2000-12-06 08:30:00 |
| Install Date: | Not reported |
| Expiration Date: | 06/11/2003 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

City,State,Zip: LARCHMONT, NY 10538 2328
Facility ID: 3-5532-00313
Phone Number: 9148348880
Region: Not reported
Registration Effective Date: 2019-05-03 11:25:25
Inspection Date: 2002-12-13 08:00:00
Install Date: Not reported
Expiration Date: 05/03/2029
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec.
Current Business: Not reported

NY MANIFEST:
Name: MAGIC TOUCH
Address: 5 VINE STREET
City,State,Zip: LARCHMONT, NY 10538
Country: USA
EPA ID: NYD000204958
Facility Status: Not reported
Location Address 1: 5 VINE STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: LARCHMONT
Location State: NY
Location Zip: 10538
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD000204958
Mailing Name: MAGIC TOUCH
Mailing Contact: STACEY KIM
Mailing Address 1: 5 VINE STREET
Mailing Address 2: Not reported
Mailing City: LARCHMONT
Mailing State: NY
Mailing Zip: 10538
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9148348880

Name: MAGIC TOUCH CLNRS
Address: 5 VINE ST
City,State,Zip: LARCHMONT, NY 10538
Country: USA
EPA ID: NY0000204958
Facility Status: Not reported
Location Address 1: 5 VINE ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: LARCHMONT
Location State: NY
Location Zip: 10538

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NY0000204958
Mailing Name: MAGIC TOUCH CLNRS
Mailing Contact: YOON KIM
Mailing Address 1: 5 VINE ST
Mailing Address 2: Not reported
Mailing City: LARCHMONT
Mailing State: NY
Mailing Zip: 10538
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9148348880

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

---

**A4** **JS CHADWORTHS** **NY Spills** **S117852880**
**WNW** **1 VINE ST** **N/A**
**< 1/8** **LARCHMONT, NY**
**0.048 mi.**
**251 ft.** **Site 3 of 9 in cluster A**

**Relative:** **Lower**
**Actual:** **40 ft.**

SPILLS:
Name: JS CHADWORTHS
Address: 1 VINE ST
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 1501291 / 2015-07-08
Facility ID: 1501291
Facility Type: ER
DER Facility ID: 462241
Site ID: 507486
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 6032
Spill Date: 2015-05-05
Investigator: RDBENDEL
Referred To: Not reported
Reported to Dept: 2015-05-05
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2015-05-05
Spill Record Last Update: 2015-09-01
Spiller Name: Not reported
Spiller Company: CHADSWORTH
Spiller Address: Not reported
Spiller Company: 999

**JS CHADWORTHS (Continued)** **S117852880**

Contact Name: MIKE CARR
DEC Memo: "Received an email from C Lalak, WCDOH. American Petroleum has a permit to pull tanks, Denise, WCDOH, is on site...mm From WCHD 2 UST s (DW Steel with Sac. Anode installed 1995)removed at this former gas station 3-174394 (now repair shop) on 5/5 & 5/7/15. Spill called in due to elevated PID reading s during excavation. Upon removal both tanks sound no leaks. APECCO removed 11 tons impacted soil. Discovered that tanks were actually installed inside lower level of building s foundation & surrounded by 4 concrete walls & bottom no end point samples available. Any excavation beyond foundation would comprise structure & roadway. 07-08-15 TCR, NFA RDB"
Remarks: "cleanup in progress"

All Materials:
Site ID: 507486
Operable Unit ID: 1256819
Operable Unit: 01
Material ID: 2259781
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

---

**A5** **JF CHATSWORTH** **NY LTANKS S102110180**
**WNW** **1 VINE STREET** **NY Spills N/A**
**< 1/8** **LARCHMONT, NY**
**0.048 mi.**
**251 ft.** **Site 4 of 9 in cluster A**

**Relative:** LTANKS:
**Lower**
**Actual:** Name: J & F CHATSWORTH GAS STA
**40 ft.** Address: 1 VINE STREET
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 9410303 / 2005-02-27
Facility ID: 9410303
Site ID: 64161
Spill Date: 1994-11-02
Spill Cause: Tank Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 6000
Investigator: WXWADSWO
Referred To: Not reported
Reported to Dept: 1994-11-02
CID: Not reported
Water Affected: Not reported
Spill Notifier: Health Department
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0

**JF CHATSWORTH (Continued)** **S102110180**

| | |
|---|---|
| Date Entered In Computer: | 2003-12-02 |
| Spill Record Last Update: | 2005-02-27 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 61873 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 02/27/05 LUZON REPORTEDLY COMPLETED CLEAN UP. FILE ADMINISTRATIVELY CLOSED. jod" |
| Remarks: | "CONTRACTOR (LUZON) ENROUTE TO CLEAN UP" |

All Materials:

| | |
|---|---|
| Site ID: | 64161 |
| Operable Unit ID: | 1008064 |
| Operable Unit: | 01 |
| Material ID: | 376176 |
| Material Code: | 0009 |
| Material Name: | gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | Not reported |
| Recovered: | .00 |
| Oxygenate: | Not reported |

SPILLS:

| | |
|---|---|
| Name: | JF CHATSWORTH |
| Address: | 1 VINE STREET |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9413519 / 1995-01-23 |
| Facility ID: | 9413519 |
| Facility Type: | ER |
| DER Facility ID: | 61873 |
| Site ID: | 64162 |
| DEC Region: | 3 |
| Spill Cause: | Human Error |
| Spill Class: | C3 |
| SWIS: | 6000 |
| Spill Date: | 1995-01-10 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1995-01-10 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Tank Truck |
| Spill Notifier: | Fire Department |
| Cleanup Ceased: | 1995-01-23 |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |

**JF CHATSWORTH (Continued)** **S102110180**

| | |
|---|---|
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-12-02 |
| Spill Record Last Update: | 2003-12-02 |
| Spiller Name: | Not reported |
| Spiller Company: | BARNER OIL |
| Spiller Address: | Not reported |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: | "FILL HOSE SLIPPED OUT OF DRIVER HAND SPILL HAS BEEN CLEANED UP" |

All Materials:

| | |
|---|---|
| Site ID: | 64162 |
| Operable Unit ID: | 1011074 |
| Operable Unit: | 01 |
| Material ID: | 372268 |
| Material Code: | 0009 |
| Material Name: | gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 4.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**A6** **J & F CHATSWORTH LTD.** **NY UST U003884522**
**WNW** **1 VINE STREET** **NY AST N/A**
**< 1/8** **LARCHMONT, NY 10538**
**0.048 mi.**
**251 ft.** **Site 5 of 9 in cluster A**

**Relative:** **Lower**

**Actual:** **40 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | J & F CHATSWORTH LTD. |
| Address: | 1 VINE STREET |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-174394 / Active |
| Operator Name: | Giuseppe Sparano |
| Owner Name: | Giuseppe Sparano |
| Owner Street: | 1 Vine Street |
| Owner Address2: | Not reported |
| Owner City: | Larchmont |
| Owner State: | NY |
| Owner Zipcode: | 10538 |
| GDS Number: | 3553200241 |
| Tank Number: | 1 |
| Status: | 3. Closed - Removed |
| Capacity: | 4000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 1. Electronic Interstitial Monitoring |
| Date Installation: | 04/01/1995 |
| Date Perm Closure: | 05/05/2015 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |

**J & F CHATSWORTH LTD. (Continued)** **U003884522**

| | |
|---|---|
| Tank External Protection: | 2. Original sacrificial anode |
| Tank Secondary Containment: | 4. Double-Walled (underground only) |
| Piping Location: | 2. Underground/on Ground |
| Piping Type: | 6. Fiberglass Reinforced Plastic (FRP) |
| Piping External Protection: | 4. Fiberglass |
| Overfill Prevention: | 2. High Level Alarm |
| Piping Secondary Containment: | 0. None |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 1old |
| Status: | 3. Closed - Removed |
| Capacity: | 2000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 08/01/1981 |
| Date Perm Closure: | 04/01/1995 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 2 |
| Status: | 3. Closed - Removed |
| Capacity: | 4000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 1. Electronic Interstitial Monitoring |
| Date Installation: | 04/01/1995 |
| Date Perm Closure: | 05/07/2015 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 2. Original sacrificial anode |
| Tank Secondary Containment: | 4. Double-Walled (underground only) |
| Piping Location: | 2. Underground/on Ground |
| Piping Type: | 6. Fiberglass Reinforced Plastic (FRP) |
| Piping External Protection: | 4. Fiberglass |
| Overfill Prevention: | 2. High Level Alarm |
| Piping Secondary Containment: | 0. None |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 2 old |
| Status: | 3. Closed - Removed |

**J & F CHATSWORTH LTD. (Continued)** **U003884522**

| | |
|---|---|
| Capacity: | 2000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 08/01/1981 |
| Date Perm Closure: | 04/01/1995 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 3 old |
| Status: | 3. Closed - Removed |
| Capacity: | 2000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 08/01/1981 |
| Date Perm Closure: | 04/01/1995 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 4 old |
| Status: | 3. Closed - Removed |
| Capacity: | 2000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 08/01/1981 |
| Date Perm Closure: | 04/01/1995 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |

**J & F CHATSWORTH LTD. (Continued)** **U003884522**

| | |
|---|---|
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 5 old |
| Status: | 3. Closed - Removed |
| Capacity: | 2000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 08/01/1981 |
| Date Perm Closure: | 04/01/1995 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 6 old |
| Status: | 3. Closed - Removed |
| Capacity: | 2000 |
| Product Stored: | 0008. Diesel |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 08/01/1981 |
| Date Perm Closure: | 04/01/1995 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | J & F CHATSWORTH LTD. |
| Address: | 1 VINE STREET |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-174394 |
| Site Status: | Active |
| GDS Number: | 3553200241 |

**J & F CHATSWORTH LTD. (Continued)** **U003884522**

| | |
|---|---|
| Operator Name: | Giuseppe Sparano |
| Owner Name: | Giuseppe Sparano |
| Owner Street: | 1 Vine Street |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | Larchmont, NY 10538 |
| | |
| Tank Number: | 3 |
| Status: | 1. In-Service |
| Date Installation: | 01/01/1999 |
| Capacity: | 250 |
| Product Stored: | 0015. Motor Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 2. Aboveground (contact w/ impervious barrier) |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | 1. Diking (aboveground only) |
| Piping Location: | 0. No Piping |
| Piping Type: | 0. No Piping |
| Piping External Protection: | 0. None |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only) |
| Spill Prevention: | 0. None |
| Dispenser: | 1. Submersible |
| | |
| Tank Number: | 4 |
| Status: | 1. In-Service |
| Date Installation: | 01/01/1996 |
| Capacity: | 250 |
| Product Stored: | 0022. Waste/Used Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 2. Aboveground (contact w/ impervious barrier) |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | 1. Diking (aboveground only) |
| Piping Location: | 0. No Piping |
| Piping Type: | 0. No Piping |
| Piping External Protection: | 0. None |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only) |
| Spill Prevention: | 0. None |
| Dispenser: | 1. Submersible |

**A7** **CHATSWORTH GARAGE INC** **EDR Hist Auto** **1021470908**
**WNW** **1 VINE ST** **N/A**
**< 1/8** **LARCHMONT, NY 10538**
**0.048 mi.**
**251 ft.** **Site 6 of 9 in cluster A**

**Relative:** EDR Hist Auto
**Lower**

**Actual:**
**40 ft.**

| Year: | Name: | Type: |
|---|---|---|
| 1969 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1970 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1971 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1972 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1973 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1974 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1975 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1976 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1977 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1978 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1979 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1980 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1982 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1983 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1985 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1992 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 1993 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 1994 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 1995 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 1996 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 1997 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 1998 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 1999 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2000 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2001 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2002 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2003 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2004 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2005 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2006 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2007 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2008 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2009 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2010 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2011 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2012 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2013 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2014 | J & F CHATSWORTH LTD | General Automotive Repair Shops |

---

**A8** **MARISIERO INC.** **NY LTANKS** **S100153891**
**WNW** **1-5 VINE STREET** **N/A**
**< 1/8** **LARCHMONT, NY**
**0.048 mi.**
**251 ft.** **Site 7 of 9 in cluster A**

**Relative:** LTANKS:
**Lower**

**Actual:**
**40 ft.**

| | |
|---|---|
| Name: | MARISIERO INC. |
| Address: | 1-5 VINE STREET |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9102813 / 1997-11-14 |
| Facility ID: | 9102813 |

**MARISIERO INC. (Continued)** **S100153891**

| | |
|---|---|
| Site ID: | 88022 |
| Spill Date: | 1991-06-10 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1991-06-10 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Health Department |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1991-06-13 |
| Spill Record Last Update: | 1997-12-01 |
| Spiller Name: | Not reported |
| Spiller Company: | JOE SPERANO |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 80580 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: | "TANK LEAKED IN BASEMENT OIL IN SUMP PUMP AND PUMPED TO SEWER PADS APPLIED AND BARRIER HIRED TO CLEAN UP SPILL" |

All Materials:

| | |
|---|---|
| Site ID: | 88022 |
| Operable Unit ID: | 956692 |
| Operable Unit: | 01 |
| Material ID: | 425300 |
| Material Code: | 0022 |
| Material Name: | waste oil/used oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 30.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**A9** **MAGIC TOUCH CLEANERS** **EDR Hist Cleaner** **1020032815**
**WNW** **1 VINE ST** **N/A**
**< 1/8** **LARCHMONT, NY 10538**
**0.048 mi.**
**251 ft.** **Site 8 of 9 in cluster A**

**Relative:** EDR Hist Cleaner
**Lower**

**Actual:** Year: Name: Type:
**40 ft.** 1995 MAGIC TOUCH CLEANERS Drycleaning Plants, Except Rugs, NEC

---

**A10** **J & F CHATSWORTH LTD** **RCRA-SQG** **1000113677**
**WNW** **1 VINE ST** **NY MANIFEST** **NYD982718272**
**< 1/8** **LARCHMONT, NY 10538** **NJ MANIFEST**
**0.048 mi.**
**251 ft.** **Site 9 of 9 in cluster A**

**Relative:** RCRA Listings:
**Lower**

**Actual:**
**40 ft.**

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20070101 |
| Handler Name: | J & F CHATSWORTH LTD | |
| Handler Address: | | 1 VINE ST |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYD982718272 |
| Contact Name: | | JOSEPH SPARANO |
| Contact Address: | | VINE ST |
| Contact City,State,Zip: | | LARCHMONT, NY 10538 |
| Contact Telephone: | | 914-834-0008 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Small Quantity Generator |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Handler Activities |
| State District Owner: | | NY |
| State District: | | NYSDEC R3 |
| Mailing Address: | | VINE ST |
| Mailing City,State,Zip: | | LARCHMONT, NY 10538 |
| Owner Name: | J&F CHATSWORTH LTD | |
| Owner Type: | | Private |
| Operator Name: | J&F CHATSWORTH LTD | |
| Operator Type: | | Private |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site Fed-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site Converter Treatment storage and Disposal Facility: | | Not reported |

**J & F CHATSWORTH LTD (Continued)** **1000113677**

| | |
|---|---|
| Active Site State-Reg Treatment Storage and Disposal Facility: | Not reported |
| Active Site State-Reg Handler: | --- |
| Federal Facility Indicator: | Not reported |
| Hazardous Secondary Material Indicator: | NN |
| Sub-Part K Indicator: | Not reported |
| Commercial TSD Indicator: | No |
| Treatment Storage and Disposal Type: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| Permit Renewals Workload Universe: | Not reported |
| Permit Workload Universe: | Not reported |
| Permit Progress Universe: | Not reported |
| Post-Closure Workload Universe: | Not reported |
| Closure Workload Universe: | Not reported |
| 202 GPRA Corrective Action Baseline: | No |
| Corrective Action Workload Universe: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: | No |
| TSDFs Only Subject to CA under Discretionary Auth Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Operating TSDF Universe: | Not reported |
| Full Enforcement Universe: | Not reported |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: Not reported | |
| Handler Date of Last Change: | 20150414 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | Not reported |
| Manifest Broker: | Not reported |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | D000 |
| Waste Description: | Not Defined |
| Waste Code: | D001 |
| Waste Description: | IGNITABLE WASTE |

Handler - Owner Operator:

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: J&F CHATSWORTH LTD | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | NOT REQUIRED |

**J & F CHATSWORTH LTD (Continued)** **1000113677**

Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: J&F CHATSWORTH LTD
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: J&F CHATSWORTH LTD
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: J & F CHATSWORTH LTD
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: J & F CHATSWORTH LTD
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

**J & F CHATSWORTH LTD (Continued)** **1000113677**

| | |
|---|---|
| Receive Date: | 19881208 |
| Handler Name: J & F CHATSWORTH LTD | |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 19960122 |
| Handler Name: J & F CHATSWORTH | |
| Federal Waste Generator Description: | Large Quantity Generator |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

List of NAICS Codes and Descriptions:

| | |
|---|---|
| NAICS Code: | 4471 |
| NAICS Description: | GASOLINE STATIONS |

| | |
|---|---|
| NAICS Code: | 44711 |
| NAICS Description: | GASOLINE STATIONS WITH CONVENIENCE STORES |

| | |
|---|---|
| NAICS Code: | 811111 |
| NAICS Description: | GENERAL AUTOMOTIVE REPAIR |

| | |
|---|---|
| NAICS Code: | 811121 |
| NAICS Description: | AUTOMOTIVE BODY, PAINT, AND INTERIOR REPAIR AND MAINTENANCE |

Facility Has Received Notices of Violation:

| | |
|---|---|
| Found Violation: | No |
| Agency Which Determined Violation: | Not reported |
| Violation Short Description: | Not reported |
| Date Violation was Determined: | Not reported |
| Actual Return to Compliance Date: | Not reported |
| Return to Compliance Qualifier: | Not reported |
| Violation Responsible Agency: | Not reported |
| Scheduled Compliance Date: | Not reported |
| Enforcement Identifier: | Not reported |
| Date of Enforcement Action: | Not reported |
| Enforcement Responsible Agency: | Not reported |
| Enforcement Docket Number: | Not reported |
| Enforcement Attorney: | Not reported |
| Corrective Action Component: | Not reported |
| Appeal Initiated Date: | Not reported |
| Appeal Resolution Date: | Not reported |

**J & F CHATSWORTH LTD (Continued)** **1000113677**

| | |
|---|---|
| Disposition Status Date: | Not reported |
| Disposition Status: | Not reported |
| Disposition Status Description: | Not reported |
| Consent/Final Order Sequence Number: | Not reported |
| Consent/Final Order Respondent Name: | Not reported |
| Consent/Final Order Lead Agency: | Not reported |
| Enforcement Type: | Not reported |
| Enforcement Responsible Person: | Not reported |
| Enforcement Responsible Sub-Organization: | Not reported |
| SEP Sequence Number: | Not reported |
| SEP Expenditure Amount: | Not reported |
| SEP Scheduled Completion Date: | Not reported |
| SEP Actual Date: | Not reported |
| SEP Defaulted Date: | Not reported |
| SEP Type: | Not reported |
| SEP Type Description: | Not reported |
| Proposed Amount: | Not reported |
| Final Monetary Amount: | Not reported |
| Paid Amount: | Not reported |
| Final Count: | Not reported |
| Final Amount: | Not reported |

Evaluation Action Summary:

| | |
|---|---|
| Evaluation Date: | 20120913 |
| Evaluation Responsible Agency: | State |
| Found Violation: | No |
| Evaluation Type Description: | COMPLIANCE EVALUATION INSPECTION ON-SITE |
| Evaluation Responsible Person Identifier: | NYFKY |
| Evaluation Responsible Sub-Organization: | R3 |
| Actual Return to Compliance Date: | Not reported |
| Scheduled Compliance Date: | Not reported |
| Date of Request: | Not reported |
| Date Response Received: | Not reported |
| Request Agency: | Not reported |
| Former Citation: | Not reported |

NY MANIFEST:

| | |
|---|---|
| Name: | J & F CHATSWORTH |
| Address: | 1 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Country: | USA |
| EPA ID: | NYD982718272 |
| Facility Status: | Not reported |
| Location Address 1: | 1 VINE ST. ATTN: BODY SHOP MGR |
| Code: | BP |
| Location Address 2: | Not reported |
| Total Tanks: | Not reported |
| Location City: | LARCHMONT |
| Location State: | NY |
| Location Zip: | 10538 |
| Location Zip 4: | Not reported |

NY MANIFEST:

| | |
|---|---|
| EPAID: | NYD982718272 |
| Mailing Name: | J & F CHATSWORTH |
| Mailing Contact: | J & F CHATSWORTH |

**J & F CHATSWORTH LTD (Continued)** **1000113677**

| | |
|---|---|
| Mailing Address 1: | 1 VINE ST. ATTN;BODY SHOP MGR |
| Mailing Address 2: | Not reported |
| Mailing City: | LARCHMONT |
| Mailing State: | NY |
| Mailing Zip: | 10538 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 9148340008 |

NY MANIFEST:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| seq: | Not reported |
| Year: | 2018 |
| Trans1 State ID: | NJD080631369 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 12/28/2011 |
| Trans1 Recv Date: | 12/28/2011 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/29/2011 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982718272 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD980536593 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 000530807VES |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H141 |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Quantity: | 450 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 1 |
| Waste Code: | F003 |
| Waste Code 1_2: | D001 |
| Waste Code 1_3: | Not reported |
| Waste Code 1_4: | F005 |
| Waste Code 1_5: | D035 |
| Waste Code 1_6: | Not reported |

**J & F CHATSWORTH LTD (Continued)** **1000113677**

NJ MANIFEST:

| | |
|---|---|
| EPA Id: | NYD982718272 |
| Mail Address: | Not reported |
| Mail City/State/Zip: | Not reported |
| Facility Phone: | 9148340008 |
| Emergency Phone: | Not reported |
| Contact: | Not reported |
| Comments: | Not reported |
| SIC Code: | Not reported |
| County: | 00 |
| Municipal: | 00 |
| Previous EPA Id: | Not reported |
| Gen Flag: | X |
| Trans Flag: | Not reported |
| TSDF Flag: | Not reported |
| Name Change: | Not reported |
| Date Change: | 000000 |

Manifest:

| | |
|---|---|
| Manifest Number: | 000530807VES |
| EPA ID: | NYD982718272 |
| Date Shipped: | 12/28/2011 |
| TSDF EPA ID: | NJD980536593 |
| Transporter EPA ID: | NJD080631369 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |

**J & F CHATSWORTH LTD (Continued)** **1000113677**

| | |
|---|---|
| Was Load Rejected: | Not reported |
| Reason Load Was Rejected: | Not reported |

Waste:

| | |
|---|---|
| Manifest Year: | Not reported |
| Waste Code: | F003 |
| Hand Code: | H141 |
| Quantity: | 450.00 Pounds |

| | |
|---|---|
| Manifest Number: | 000564725VES |
| EPA ID: | NYD982718272 |
| Date Shipped: | 9/14/2011 |
| TSDF EPA ID: | NJD980536593 |
| Transporter EPA ID: | NJD080631369 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Was Load Rejected: | Not reported |
| Reason Load Was Rejected: | Not reported |

Waste:

| | |
|---|---|
| Manifest Year: | Not reported |
| Waste Code: | F003 |
| Hand Code: | H141 |
| Quantity: | 800.00 Pounds |

**J & F CHATSWORTH LTD (Continued)** **1000113677**

| | |
|---|---|
| Manifest Number: | NJA5320339 |
| EPA ID: | NYD982718272 |
| Date Shipped: | 08/29/2006 |
| TSDF EPA ID: | NJD980536593 |
| Transporter EPA ID: | NJD080631369 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 08/29/2006 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 08/29/2006 |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | 09280622 |
| Was Load Rejected: | No |
| Reason Load Was Rejected: | Not reported |

| | |
|---|---|
| Manifest Number: | 000431611VES |
| EPA ID: | NYD982718272 |
| Date Shipped: | 08/16/2010 |
| TSDF EPA ID: | NJD980536593 |
| Transporter EPA ID: | NJD080631369 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 08/16/2010 |
| Date Trans2 Transported Waste: | Not reported |

**J & F CHATSWORTH LTD (Continued)** **1000113677**

| | |
|---|---|
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 08/16/2010 |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Was Load Rejected: | No |
| Reason Load Was Rejected: | Not reported |

Waste:

| | |
|---|---|
| Manifest Year: | Not reported |
| Waste Code: | F003 |
| Hand Code: | H141 |
| Quantity: | 800 P |

| | |
|---|---|
| Manifest Number: | 000807409VES |
| EPA ID: | NYD982718272 |
| Date Shipped: | 8/27/2013 |
| TSDF EPA ID: | NJD980536593 |
| Transporter EPA ID: | NJD080631369 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| TSDF EPA Facility Name: | Not reported |

**J & F CHATSWORTH LTD (Continued)** **1000113677**

| | |
|---|---|
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Was Load Rejected: | Not reported |
| Reason Load Was Rejected: | Not reported |

Waste:

| | |
|---|---|
| Manifest Year: | Not reported |
| Waste Code: | F003 D001 F005 D035 |
| Hand Code: | Not reported |
| Quantity: | 400.00 Pounds |
| Manifest Year: | Not reported |
| Waste Code: | F003 D001 F005 D035 |
| Hand Code: | Not reported |
| Quantity: | 400.00 Pounds |

---

**11** **DECABIA - UST** **NY Spills** **S128911954**
**NNE** **19 CABOT RD** **N/A**
**< 1/8** **LARCHMONT, NY**
**0.082 mi.**
**431 ft.**

**Relative:** **Lower**

**Actual:** **40 ft.**

SPILLS:

| | |
|---|---|
| Name: | DECABIA - UST |
| Address: | 19 CABOT RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 2202138 / 2022-07-14 |
| Facility ID: | 2202138 |
| Facility Type: | ER |
| DER Facility ID: | 583872 |
| Site ID: | 637212 |
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | C3 |
| SWIS: | 6032 |
| Spill Date: | 2022-06-08 |
| Investigator: | JBODEE |
| Referred To: | Not reported |
| Reported to Dept: | 2022-06-08 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |

**DECABIA - UST (Continued)** **S128911954**

| | |
|---|---|
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2022-06-08 |
| Spill Record Last Update: | 2022-07-14 |
| Spiller Name: | Joanne Decabia |
| Spiller Company: | Decabia |
| Spiller Address: | 19 CABOT RD |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| DEC Memo: | "6/8/22 Tank removal at residence. Multiple holes found in the tank. Staining and odor in soil. 550 UST. Homeowner is in contact with Elite for cleanup. EKT 7/14/2022: Elite Environmental removed the leaking UST and disposed of a total of 42.11 tons of petroleum contaminated soil. Post excavation soil sample results were below CP-51 Guidance values. Report has been reviewed and entered in DecDocs. Based upon the information provided, no further action is required at this time. jod" |
| Remarks: | "TANK REMOVAL 550GAL UST. UNK AMOUNT OF PRODUCT RELEASED TO SOIL. CLEAN UP PENDING." |

All Materials:

| | |
|---|---|
| Site ID: | 637212 |
| Operable Unit ID: | 1384272 |
| Operable Unit: | 01 |
| Material ID: | 2398815 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**B12** **GLOBE RESTAURANT** **NY LTANKS** **S107523363**
**South** **1879 PALMER AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.128 mi.**
**674 ft.** **Site 1 of 3 in cluster B**

**Relative:** **Higher**
**Actual:** **60 ft.**

LTANKS:

| | |
|---|---|
| Name: | GLOBE RESTAURANT |
| Address: | 1879 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0511734 / 2006-02-21 |
| Facility ID: | 0511734 |
| Site ID: | 357947 |
| Spill Date: | 2006-01-11 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | Not reported |

**GLOBE RESTAURANT (Continued)** **S107523363**

| | |
|---|---|
| Reported to Dept: | 2006-01-11 |
| CID: | 44 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2006-01-11 |
| Spill Record Last Update: | 2006-02-21 |
| Spiller Name: | GERARD TUNNEY |
| Spiller Company: | GLOBE RESTERAUNT |
| Spiller Address: | 1879 PALMER AVE |
| Spiller County: | 001 |
| Spiller Contact: | GERARD TUNNEY |
| Spiller Phone: | (914) 921-3422 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 307980 |
| DEC Memo: | "1/11/06 Vaulted AST removed- NES to Contact J. O'Dee for guidance February 21, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF TANK AND 2 DRUMSOF CONTAMINATED SOIL. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod" |
| Remarks: | "550 GALLON AST, IN VAULT AND SAND INSIDE IS CONTAMINATED:" |

All Materials:

| | |
|---|---|
| Site ID: | 357947 |
| Operable Unit ID: | 1115213 |
| Operable Unit: | 01 |
| Material ID: | 2105269 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**C13** **CON EDISON SERVICE BOX: 01375** **RCRA NonGen / NLR** **1017771736**
**SSE** **PALMER AVE & E DEPOT WAY** **FINDS** **NYP004486809**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.129 mi.**
**679 ft.** **Site 1 of 3 in cluster C**

**Relative:**
**Higher**

**Actual:**
**52 ft.**

RCRA Listings:

| | |
|---|---|
| Date Form Received by Agency: | 20140502 |
| Handler Name: | CON EDISON SERVICE BOX: 01375 |
| Handler Address: | PALMER AVE & E DEPOT WAY |
| Handler City,State,Zip: | LARCHMONT, NY 10538 |
| EPA ID: | NYP004486809 |
| Contact Name: | THOMAS TEELING |
| Contact Address: | Not reported |
| Contact City,State,Zip: | Not reported |
| Contact Telephone: | 212-460-3770 |
| Contact Fax: | Not reported |

**CON EDISON SERVICE BOX: 01375 (Continued)** **1017771736**

| | | |
|---|---|---|
| Contact Email: | | Not reported |
| Contact Title: | | SENIOR SCIENTIST |
| EPA Region: | | 02 |
| Land Type: | | Private |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | NY |
| State District: | | NYSDEC R2 |
| Mailing Address: | | IRVING PL, 15TH FL NE |
| Mailing City,State,Zip: | | NEW YORK, NY 10003 |
| Owner Name: | Not reported | |
| Owner Type: | | Not reported |
| Operator Name: | Not reported | |
| Operator Type: | | Not reported |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site Fed-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site Converter Treatment storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | NN |
| Sub-Part K Indicator: | | Not reported |
| Commercial TSD Indicator: | | No |
| Treatment Storage and Disposal Type: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| Permit Renewals Workload Universe: | | Not reported |
| Permit Workload Universe: | | Not reported |
| Permit Progress Universe: | | Not reported |
| Post-Closure Workload Universe: | | Not reported |
| Closure Workload Universe: | | Not reported |
| 202 GPRA Corrective Action Baseline: | | No |
| Corrective Action Workload Universe: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: | | No |
| TSDFs Only Subject to CA under Discretionary Auth Universe: | | No |
| Corrective Action Priority Ranking: | | No NCAPS ranking |
| Environmental Control Indicator: | | No |
| Institutional Control Indicator: | | No |
| Human Exposure Controls Indicator: | | N/A |
| Groundwater Controls Indicator: | | N/A |

**CON EDISON SERVICE BOX: 01375 (Continued)** **1017771736**

Operating TSDF Universe: Not reported
Full Enforcement Universe: Not reported
Significant Non-Complier Universe: No
Unaddressed Significant Non-Complier Universe: No
Addressed Significant Non-Complier Universe: No
Significant Non-Complier With a Compliance Schedule Universe: No
Financial Assurance Required: Not reported
Handler Date of Last Change: 20150211
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:

Receive Date: 20140402
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140402
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140502
Handler Name: CON EDISON SERVICE BOX: 01375
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

**CON EDISON SERVICE BOX: 01375 (Continued)** **1017771736**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063796183

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

**C14** **REAR OF 1880 PALMER AVE** **NY LTANKS** **S102675195**
**SSE** **FRANKLYN AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.132 mi.**
**699 ft.** **Site 2 of 3 in cluster C**

**Relative:**
**Higher**

**Actual:**
**51 ft.**

LTANKS:

| | |
|---|---|
| Name: | REAR OF 1880 PALMER AVE |
| Address: | FRANKLYN AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9602833 / 1996-05-29 |
| Facility ID: | 9602833 |
| Site ID: | 292396 |
| Spill Date: | 1996-05-29 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Tank Truck |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1996-05-29 |
| CID: | 233 |
| Water Affected: | Not reported |
| Spill Notifier: | Fire Department |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1996-05-29 |

**REAR OF 1880 PALMER AVE (Continued)** **S102675195**

| | |
|---|---|
| Spill Record Last Update: | 1996-06-14 |
| Spiller Name: | JIM CAREY |
| Spiller Company: | CASTLE OIL |
| Spiller Address: | 290 LOCUST AVE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 236741 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: | "tank overfill fd used 2 bags of speddy dri eastmond spill recovery on scene now " |

All Materials:

| | |
|---|---|
| Site ID: | 292396 |
| Operable Unit ID: | 1034129 |
| Operable Unit: | 01 |
| Material ID: | 349071 |
| Material Code: | 0003A |
| Material Name: | #6 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 15.00 |
| Units: | G |
| Recovered: | 15.00 |
| Oxygenate: | Not reported |

---

**C15** **HOFFMANS** **NY LTANKS** **S100492358**
**SSE** **1850 PALMER AVE.** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.134 mi.**
**709 ft.** **Site 3 of 3 in cluster C**

**Relative:**
**Higher**

**Actual:**
**51 ft.**

LTANKS:

| | |
|---|---|
| Name: | HOFFMANS |
| Address: | 1850 PALMER AVE. |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9211944 / 1993-01-21 |
| Facility ID: | 9211944 |
| Site ID: | 111285 |
| Spill Date: | 1993-01-19 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C3 |
| Cleanup Ceased: | 1993-01-21 |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1993-01-19 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |

**HOFFMANS (Continued)** **S100492358**

| | |
|---|---|
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1993-01-21 |
| Spill Record Last Update: | 1993-03-19 |
| Spiller Name: | Not reported |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 97345 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: | "50,000 GAL UST LEAKING PUMPING OUT TANK TO DETERMINE CAUSE CALL BACK # NOT USABLE SAME AS SPILL # 9211942" |

All Materials:

| | |
|---|---|
| Site ID: | 111285 |
| Operable Unit ID: | 978846 |
| Operable Unit: | 01 |
| Material ID: | 405327 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | Not reported |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**D16** **PATRICIA GARDENS OWNERS, INC.** **NY UST** **U004333700**
**ESE** **1825 PALMER AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.137 mi.**
**721 ft.** **Site 1 of 3 in cluster D**

**Relative:** **Lower**
**Actual:** **40 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | PATRICIA GARDENS OWNERS, INC. |
| Address: | 1825 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-048429 / Active |
| Operator Name: | Juan Soto |
| Owner Name: | Patricia Gardens Owners, Inc. |
| Owner Street: | 7 Bryant Crescent, Suite 1C |
| Owner Address2: | Not reported |
| Owner City: | White Plains |
| Owner State: | NY |
| Owner Zipcode: | 10605 |
| GDS Number: | Not reported |
| Tank Number: | 825 |
| Status: | 4. Closed - in place |
| Capacity: | 10000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |

**PATRICIA GARDENS OWNERS, INC. (Continued)** **U004333700**

| | |
|---|---|
| Tank Leak Detection: | 0. None |
| Date Installation: | Not reported |
| Date Perm Closure: | 07/03/2002 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 2. Underground/on ground |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Overfill Prevention: | 5. Vent Whistle |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 2. Suction |

---

**D17** **PATRICIA GARDENS OWNERS, INC.** **NY AST** **A100276801**
**ESE** **1825 PALMER AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.137 mi.**
**721 ft.** **Site 2 of 3 in cluster D**

**Relative:** WESTCHESTER CO. AST:
**Lower**

**Actual:**
**40 ft.**

| | |
|---|---|
| Name: | PATRICIA GARDENS OWNERS, INC. |
| Address: | 1825 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-048429 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | Juan Soto |
| Owner Name: | Patricia Gardens Owners, Inc. |
| Owner Street: | 7 Bryant Crescent, Suite 1C |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | White Plains, NY 10605 |
| | |
| Tank Number: | 1 |
| Status: | 1. In-Service |
| Date Installation: | 08/01/2002 |
| Capacity: | 8000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 6. Aboveground in subterranean vault with access for inspections |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | 5. Synthetic Liner |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

**D18**
**ESE**
**1/8-1/4**
**0.137 mi.**
**721 ft.**

**RESIDENCE**
**1825 PALMER AVENUE**
**LARCHMONT, NY**

**Site 3 of 3 in cluster D**

**NY LTANKS** **U003645239**
**NY Spills** **N/A**

**Relative:**
**Lower**

**Actual:**
**40 ft.**

LTANKS:

| | |
|---|---|
| Name: | PATRICIA GARDENS |
| Address: | 1825 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9802511 / 1999-02-08 |
| Facility ID: | 9802511 |
| Site ID: | 200510 |
| Spill Date: | 1998-05-26 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1998-05-27 |
| CID: | 351 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-05-27 |
| Spill Record Last Update: | 1999-03-01 |
| Spiller Name: | ROBERT ORLOFSKI |
| Spiller Company: | PATRICIA GARDENS |
| Spiller Address: | 1825 PALMER AVE |
| Spiller County: | 001 |
| Spiller Contact: | ROBERT ORLOFSKI |
| Spiller Phone: | (914) 328-6962 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 166857 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE " |
| Remarks: | "SITE IS AN APARTMENT COMPLEX - RECOMMEND ISOLATE EXCAVATE AND RETEST" Not reported |

SPILLS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 1825 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9515259 / 1996-02-27 |
| Facility ID: | 9515259 |
| Facility Type: | ER |
| DER Facility ID: | 67799 |
| Site ID: | 71681 |
| DEC Region: | 3 |
| Spill Cause: | Unknown |
| Spill Class: | C4 |
| SWIS: | 6000 |

**RESIDENCE (Continued)** **U003645239**

| | |
|---|---|
| Spill Date: | 1996-02-27 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1996-02-27 |
| CID: | 204 |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1996-02-27 |
| Spill Record Last Update: | 1996-03-06 |
| Spiller Name: | JIM CAREY |
| Spiller Company: | CASTLE OIL |
| Spiller Address: | 290 LOCUST AVE |
| Spiller Company: | 001 |
| Contact Name: | JIM CAREY |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 02/27/96 CASTLE OIL DID CLEAN UP AND WILL PROVIDE CLEAN FILL" |
| Remarks: | "WHILE FILLING TANK OIL CAME OUT OF VENT PIPE" |

All Materials:

| | |
|---|---|
| Site ID: | 71681 |
| Operable Unit ID: | 1026370 |
| Operable Unit: | 01 |
| Material ID: | 355382 |
| Material Code: | 0002A |
| Material Name: | #4 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 20.00 |
| Units: | G |
| Recovered: | 20.00 |
| Oxygenate: | Not reported |

---

**B19** **BROMPTON APTS.** **NY LTANKS** **S102673824**
**South** **1880 PALMER AVE.** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.137 mi.**
**723 ft.** **Site 2 of 3 in cluster B**

**Relative:** **Higher**
**Actual:** **60 ft.**

LTANKS:

| | |
|---|---|
| Name: | BROMPTON APTS. |
| Address: | 1880 PALMER AVE. |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9112775 / 1992-03-17 |
| Facility ID: | 9112775 |
| Site ID: | 93770 |
| Spill Date: | 1992-03-16 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Commercial/Industrial |
| Spill Class: | D3 |
| Cleanup Ceased: | 1992-03-17 |

**BROMPTON APTS. (Continued)** **S102673824**

| | |
|---|---|
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1992-03-16 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1992-03-17 |
| Spill Record Last Update: | 1995-10-20 |
| Spiller Name: | Not reported |
| Spiller Company: | CASTLE OIL |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 84034 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: | "SPILL ON PAVEMENT SPILL TO BE CLEANED AND DISPOSED" |

All Materials:

| | |
|---|---|
| Site ID: | 93770 |
| Operable Unit ID: | 963250 |
| Operable Unit: | 01 |
| Material ID: | 414331 |
| Material Code: | 0003A |
| Material Name: | #6 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 15.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**B20** **THE BROMPTON** **NY AST** **A100112006**
**South** **1880 PALMER AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.137 mi.**
**723 ft.** **Site 3 of 3 in cluster B**

**Relative:**
**Higher**

**Actual:**
**60 ft.**

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | THE BROMPTON |
| Address: | 1880 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-800888 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | Edvin Sanahaim |
| Owner Name: | County Estates,LLC |
| Owner Street: | 7 Bryant Crescent, Suite 1C |

**THE BROMPTON (Continued)** **A100112006**

| | |
|---|---|
| Owner Address2: | Not reported |
| Owner City/State/Zip: | White Plains, NY 10605 |
| | |
| Tank Number: | 1 |
| Status: | 4. Closed - in place |
| Date Installation: | 10/01/1950 |
| Capacity: | 5000 |
| Product Stored: | 0003. #6 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 03/01/2009 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 6. Impervious Barrier/Concrete Pad (Aboveground Only) |
| Tank Secondary Containment: | 2. Vault (w/ access),10. Impervious Underlayment (AST Only) |
| Piping Location: | 1. Aboveground |
| Piping Type: | 0. No Piping |
| Piping External Protection: | 0. None |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 2. Transfer Station Containment |
| Dispenser: | 1. Submersible |
| | |
| Tank Number: | 2 |
| Status: | 1. In-Service |
| Date Installation: | 03/01/2009 |
| Capacity: | 5000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | 0 |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 6. Aboveground in subterranean vault with access for inspections |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 6. Impervious Barrier/Concrete Pad (Aboveground Only) |
| Tank Secondary Containment: | 2. Vault (w/ access),10. Impervious Underlayment (AST Only) |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 1. Submersible |

**E21**
**SW**
**1/8-1/4**
**0.141 mi.**
**744 ft.**

**CON EDISON**
**MYRTLE BLVD & MURRAY AVE**
**LARCHMONT, NY 10538**

**Site 1 of 3 in cluster E**

**NJ MANIFEST** **S120671354**
**N/A**

**Relative:**
**Higher**

**Actual:**
**48 ft.**

NJ MANIFEST:

| | |
|---|---|
| EPA Id: | NYP004777850 |
| Mail Address: | IRVING PL 15TH FL NE |
| Mail City/State/Zip: | NEW YORK, NY 10003 |
| Facility Phone: | Not reported |
| Emergency Phone: | Not reported |
| Contact: | THOMAS TEELING |
| Comments: | Not reported |
| SIC Code: | Not reported |
| County: | NY119 |
| Municipal: | Not reported |
| Previous EPA Id: | Not reported |
| Gen Flag: | Not reported |
| Trans Flag: | Not reported |
| TSDF Flag: | Not reported |
| Name Change: | Not reported |
| Date Change: | Not reported |

Manifest:

| | |
|---|---|
| Manifest Number: | 014454351JJK |
| EPA ID: | NYP004777850 |
| Date Shipped: | 5/1/2015 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NYD006982359 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |

**CON EDISON (Continued)** **S120671354**

| | |
|---|---|
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Was Load Rejected: | NEW YORK, NY 10003 |
| Reason Load Was Rejected: | Not reported |

---

**E22** **CON EDISON** **RCRA NonGen / NLR** **1019902790**
**SW** **MYRTLE BLVD & MURRAY AVE** **FINDS** **NYP004777850**
**1/8-1/4** **LARCHMONT, NY 10538** **ECHO**
**0.141 mi.**
**744 ft.** **Site 2 of 3 in cluster E**

**Relative:** **Higher**
**Actual:** **48 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20150501 |
| Handler Name: | CON EDISON | |
| Handler Address: | | MYRTLE BLVD & MURRAY AVE |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYP004777850 |
| Contact Name: | | THOMAS TEELING |
| Contact Address: | | Not reported |
| Contact City,State,Zip: | | Not reported |
| Contact Telephone: | | 212-460-3770 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Private |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | NY |
| State District: | | NYSDEC R2 |
| Mailing Address: | | IRVING PL 15TH FL NE |
| Mailing City,State,Zip: | | NEW YORK, NY 10003 |
| Owner Name: | Not reported | |
| Owner Type: | | Not reported |
| Operator Name: | Not reported | |
| Operator Type: | | Not reported |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site Fed-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site Converter Treatment storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Treatment Storage and Disposal Facility: | | Not reported |

**CON EDISON (Continued)** **1019902790**

| | |
|---|---|
| Active Site State-Reg Handler: | --- |
| Federal Facility Indicator: | Not reported |
| Hazardous Secondary Material Indicator: | NN |
| Sub-Part K Indicator: | Not reported |
| Commercial TSD Indicator: | No |
| Treatment Storage and Disposal Type: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| Permit Renewals Workload Universe: | Not reported |
| Permit Workload Universe: | Not reported |
| Permit Progress Universe: | Not reported |
| Post-Closure Workload Universe: | Not reported |
| Closure Workload Universe: | Not reported |
| 202 GPRA Corrective Action Baseline: | No |
| Corrective Action Workload Universe: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: | No |
| TSDFs Only Subject to CA under Discretionary Auth Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Operating TSDF Universe: | Not reported |
| Full Enforcement Universe: | Not reported |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: Not reported | |
| Handler Date of Last Change: | 20160909 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | Not reported |
| Manifest Broker: | Not reported |
| Sub-Part P Indicator: | No |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20150501 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20150501 |
| Handler Name: CON EDISON | |

**CON EDISON (Continued)** **1019902790**

| | |
|---|---|
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069694726

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

| | |
|---|---|
| Envid: | 1019902790 |
| Registry ID: | 110069694726 |
| DFR URL: | http://echo.epa.gov/detailed-facility-report?fid=110069694726 |
| Name: | CON EDISON |
| Address: | MYRTLE BLVD & MURRAY AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |

---

**E23** **CON EDISON** **NY MANIFEST** **S119075037**
**SW** **MYRTLE BLVD & MURRAY AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.141 mi.**
**744 ft.** **Site 3 of 3 in cluster E**

**Relative:**
**Higher**

**Actual:**
**48 ft.**

NY MANIFEST:

| | |
|---|---|
| Name: | CON EDISON |
| Address: | MYRTLE BLVD & MURRAY AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Country: | USA |
| EPA ID: | NYP004777850 |

**CON EDISON (Continued)** **S119075037**

| | |
|---|---|
| Facility Status: | Not reported |
| Location Address 1: | MYRTLE BLVD & MURRAY |
| Code: | BP |
| Location Address 2: | SB 273 |
| Total Tanks: | Not reported |
| Location City: | LARCHMONT |
| Location State: | NY |
| Location Zip: | 10538 |
| Location Zip 4: | Not reported |

NY MANIFEST:

| | |
|---|---|
| EPAID: | NYP004777850 |
| Mailing Name: | CON EDISON |
| Mailing Contact: | DENNIS HUACON |
| Mailing Address 1: | 4 IRVING PL 15TH FL |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 2124603770 |

NY MANIFEST:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| seq: | Not reported |
| Year: | 2018 |
| Trans1 State ID: | NYD006982359 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 05/01/2015 |
| Trans1 Recv Date: | 05/01/2015 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 05/05/2015 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004777850 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD002200046 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 014454351JJK |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H110 |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |

**CON EDISON (Continued)** **S119075037**

| | |
|---|---|
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Quantity: | 50 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Waste Code: | Not reported |
| Waste Code 1_2: | Not reported |
| Waste Code 1_3: | Not reported |
| Waste Code 1_4: | D008 |
| Waste Code 1_5: | Not reported |
| Waste Code 1_6: | Not reported |

---

**F24** **EMBASSY CLEANERS** **RCRA-SQG** **1000708538**
**South** **1908 PALMER AVE** **ICIS** **NYD986995249**
**1/8-1/4** **LARCHMONT, NY 10538** **US AIRS**
**0.150 mi.** **FINDS**
**794 ft.** **Site 1 of 3 in cluster F** **ECHO**
**NY DRYCLEANERS**
**Relative:** **RI MANIFEST**
**Higher** **NY MANIFEST**

**Actual:**
**60 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20070101 |
| Handler Name: | EMBASSY CLEANERS | |
| Handler Address: | | 1895 PALMER AVE |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYD986995249 |
| Contact Name: | | BILL STERN |
| Contact Address: | | PALMER AVE |
| Contact City,State,Zip: | | LARCHMONT, NY 10538 |
| Contact Telephone: | | 914-834-2700 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Small Quantity Generator |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Handler Activities |
| State District Owner: | | NY |
| State District: | | NYSDEC R3 |
| Mailing Address: | | PALMER AVE |
| Mailing City,State,Zip: | | LARCHMONT, NY 10538 |
| Owner Name: | BILL STERN | |
| Owner Type: | | Private |
| Operator Name: | BILL STERN | |
| Operator Type: | | Private |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Recycler Activity with Storage: | No |
| Small Quantity On-Site Burner Exemption: | No |
| Smelting Melting and Refining Furnace Exemption: | No |
| Underground Injection Control: | No |
| Off-Site Waste Receipt: | No |
| Universal Waste Indicator: | No |
| Universal Waste Destination Facility: | No |
| Federal Universal Waste: | No |
| Active Site Fed-Reg Treatment Storage and Disposal Facility: | Not reported |
| Active Site Converter Treatment storage and Disposal Facility: | Not reported |
| Active Site State-Reg Treatment Storage and Disposal Facility: | Not reported |
| Active Site State-Reg Handler: | --- |
| Federal Facility Indicator: | Not reported |
| Hazardous Secondary Material Indicator: | NN |
| Sub-Part K Indicator: | Not reported |
| Commercial TSD Indicator: | No |
| Treatment Storage and Disposal Type: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| Permit Renewals Workload Universe: | Not reported |
| Permit Workload Universe: | Not reported |
| Permit Progress Universe: | Not reported |
| Post-Closure Workload Universe: | Not reported |
| Closure Workload Universe: | Not reported |
| 202 GPRA Corrective Action Baseline: | No |
| Corrective Action Workload Universe: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: | No |
| TSDFs Only Subject to CA under Discretionary Auth Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Operating TSDF Universe: | Not reported |
| Full Enforcement Universe: | Not reported |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: Not reported | |
| Handler Date of Last Change: | 20150414 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | Not reported |
| Manifest Broker: | Not reported |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | F002 |
| Waste Description: | THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, |

**EMBASSY CLEANERS (Continued)** **1000708538**

ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: BILL STERN | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 1895 PALMER AVE |
| Owner/Operator City,State,Zip: | LARCHMONT, NY 10538 |
| Owner/Operator Telephone: | 914-834-2700 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

| | |
|---|---|
| Owner/Operator Indicator: | Operator |
| Owner/Operator Name: BILL STERN | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 1895 PALMER AVE |
| Owner/Operator City,State,Zip: | LARCHMONT, NY 10538 |
| Owner/Operator Telephone: | 914-834-2700 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: BILL STERN | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 1895 PALMER AVE |
| Owner/Operator City,State,Zip: | LARCHMONT, NY 10538 |
| Owner/Operator Telephone: | 914-834-2700 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20060101 |
| Handler Name: EMBASSY CLEANERS | |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: EMBASSY CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920324
Handler Name: EMBASSY CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20101210
Actual Return to Compliance Date: 20101210
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20101223
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20110211
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHBR

**EMBASSY CLEANERS (Continued)** **1000708538**

Enforcement Responsible Sub-Organization: R4
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Preparedness and Prevention
Date Violation was Determined: 20101210
Actual Return to Compliance Date: 20101220
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20101223
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20110211
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHBR
Enforcement Responsible Sub-Organization: R4
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20101210
Actual Return to Compliance Date: 20101222

**EMBASSY CLEANERS (Continued)** **1000708538**

Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20101223
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20110211
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHBR
Enforcement Responsible Sub-Organization: R4
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20101210
Actual Return to Compliance Date: 20101210
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20101223
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20110211
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHBR

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Enforcement Responsible Sub-Organization: | R4 |
| SEP Sequence Number: | Not reported |
| SEP Expenditure Amount: | Not reported |
| SEP Scheduled Completion Date: | Not reported |
| SEP Actual Date: | Not reported |
| SEP Defaulted Date: | Not reported |
| SEP Type: | Not reported |
| SEP Type Description: | Not reported |
| Proposed Amount: | Not reported |
| Final Monetary Amount: | Not reported |
| Paid Amount: | Not reported |
| Final Count: | Not reported |
| Final Amount: | Not reported |

| | |
|---|---|
| Found Violation: | Yes |
| Agency Which Determined Violation: | State |
| Violation Short Description: | Permits - Application |
| Date Violation was Determined: | 20101210 |
| Actual Return to Compliance Date: | 20110207 |
| Return to Compliance Qualifier: | Documented |
| Violation Responsible Agency: | State |
| Scheduled Compliance Date: | Not reported |
| Enforcement Identifier: | 001 |
| Date of Enforcement Action: | 20101223 |
| Enforcement Responsible Agency: | State |
| Enforcement Docket Number: | Not reported |
| Enforcement Attorney: | Not reported |
| Corrective Action Component: | No |
| Appeal Initiated Date: | Not reported |
| Appeal Resolution Date: | Not reported |
| Disposition Status Date: | 20110211 |
| Disposition Status: | AS |
| Disposition Status Description: | ACTION SATISFIED (CASE CLOSED) |
| Consent/Final Order Sequence Number: | Not reported |
| Consent/Final Order Respondent Name: | Not reported |
| Consent/Final Order Lead Agency: | Not reported |
| Enforcement Type: | WRITTEN INFORMAL |
| Enforcement Responsible Person: | NYHBR |
| Enforcement Responsible Sub-Organization: | R4 |
| SEP Sequence Number: | Not reported |
| SEP Expenditure Amount: | Not reported |
| SEP Scheduled Completion Date: | Not reported |
| SEP Actual Date: | Not reported |
| SEP Defaulted Date: | Not reported |
| SEP Type: | Not reported |
| SEP Type Description: | Not reported |
| Proposed Amount: | Not reported |
| Final Monetary Amount: | Not reported |
| Paid Amount: | Not reported |
| Final Count: | Not reported |
| Final Amount: | Not reported |

| | |
|---|---|
| Found Violation: | Yes |
| Agency Which Determined Violation: | State |
| Violation Short Description: | Generators - Pre-transport |
| Date Violation was Determined: | 20101210 |
| Actual Return to Compliance Date: | 20101210 |

**EMBASSY CLEANERS (Continued)** **1000708538**

Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20101223
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20110211
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHBR
Enforcement Responsible Sub-Organization: R4
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20101210
Actual Return to Compliance Date: 20101210
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20101223
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20110211
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHBR

**EMBASSY CLEANERS (Continued)** **1000708538**

Enforcement Responsible Sub-Organization: R4
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20101210
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYFKY
Evaluation Responsible Sub-Organization: R3
Actual Return to Compliance Date: 20101210
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20101210
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYFKY
Evaluation Responsible Sub-Organization: R3
Actual Return to Compliance Date: 20101220
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20101210
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYFKY
Evaluation Responsible Sub-Organization: R3
Actual Return to Compliance Date: 20101222
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20101210
Evaluation Responsible Agency: State
Found Violation: Yes

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Evaluation Type Description: | COMPLIANCE EVALUATION INSPECTION ON-SITE |
| Evaluation Responsible Person Identifier: | NYFKY |
| Evaluation Responsible Sub-Organization: | R3 |
| Actual Return to Compliance Date: | 20101210 |
| Scheduled Compliance Date: | Not reported |
| Date of Request: | Not reported |
| Date Response Received: | Not reported |
| Request Agency: | Not reported |
| Former Citation: | Not reported |

| | |
|---|---|
| Evaluation Date: | 20101210 |
| Evaluation Responsible Agency: | State |
| Found Violation: | Yes |
| Evaluation Type Description: | COMPLIANCE EVALUATION INSPECTION ON-SITE |
| Evaluation Responsible Person Identifier: | NYFKY |
| Evaluation Responsible Sub-Organization: | R3 |
| Actual Return to Compliance Date: | 20110207 |
| Scheduled Compliance Date: | Not reported |
| Date of Request: | Not reported |
| Date Response Received: | Not reported |
| Request Agency: | Not reported |
| Former Citation: | Not reported |

| | |
|---|---|
| Evaluation Date: | 20101210 |
| Evaluation Responsible Agency: | State |
| Found Violation: | Yes |
| Evaluation Type Description: | COMPLIANCE EVALUATION INSPECTION ON-SITE |
| Evaluation Responsible Person Identifier: | NYFKY |
| Evaluation Responsible Sub-Organization: | R3 |
| Actual Return to Compliance Date: | 20101210 |
| Scheduled Compliance Date: | Not reported |
| Date of Request: | Not reported |
| Date Response Received: | Not reported |
| Request Agency: | Not reported |
| Former Citation: | Not reported |

| | |
|---|---|
| Evaluation Date: | 20101210 |
| Evaluation Responsible Agency: | State |
| Found Violation: | Yes |
| Evaluation Type Description: | COMPLIANCE EVALUATION INSPECTION ON-SITE |
| Evaluation Responsible Person Identifier: | NYFKY |
| Evaluation Responsible Sub-Organization: | R3 |
| Actual Return to Compliance Date: | 20101210 |
| Scheduled Compliance Date: | Not reported |
| Date of Request: | Not reported |
| Date Response Received: | Not reported |
| Request Agency: | Not reported |
| Former Citation: | Not reported |

ICIS:

| | |
|---|---|
| Enforcement Action ID: | NY000A0000355320026600337 |
| FRS ID: | 110001601516 |
| Action Name: | EMBASSY CLEANERS 36119R208800337 |
| Facility Name: | EMBASSY CLEANERS |
| Facility Address: | 1895 PALMER AVE<br>LARCHMONT, NY 105383035 |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Enforcement Action Type: | Notice of Violation |
| Facility County: | WESTCHESTER |
| Program System Acronym: | AIR |
| Enforcement Action Forum Desc: | Administrative - Informal |
| EA Type Code: | NOV |
| Facility SIC Code: | 7216 |
| Federal Facility ID: | Not reported |
| Latitude in Decimal Degrees: | 40.93337 |
| Longitude in Decimal Degrees: | -73.75856 |
| Permit Type Desc: | Not reported |
| Program System Acronym: | NY0000003553200266 |
| Facility NAICS Code: | 812320 |
| Tribal Land Code: | Not reported |

| | |
|---|---|
| Enforcement Action ID: | NY000A0000355320026600330 |
| FRS ID: | 110001601516 |
| Action Name: | EMBASSY CLEANERS 36119R208800330 |
| Facility Name: | EMBASSY CLEANERS |
| Facility Address: | 1895 PALMER AVE<br>LARCHMONT, NY 105383035 |
| Enforcement Action Type: | Administrative Order |
| Facility County: | WESTCHESTER |
| Program System Acronym: | AIR |
| Enforcement Action Forum Desc: | Administrative - Formal |
| EA Type Code: | SCAAAO |
| Facility SIC Code: | 7216 |
| Federal Facility ID: | Not reported |
| Latitude in Decimal Degrees: | 40.93337 |
| Longitude in Decimal Degrees: | -73.75856 |
| Permit Type Desc: | Not reported |
| Program System Acronym: | NY0000003553200266 |
| Facility NAICS Code: | 812320 |
| Tribal Land Code: | Not reported |

| | |
|---|---|
| Enforcement Action ID: | NY000A0000355320026600323 |
| FRS ID: | 110001601516 |
| Action Name: | EMBASSY CLEANERS 36119R208800323 |
| Facility Name: | EMBASSY CLEANERS |
| Facility Address: | 1895 PALMER AVE<br>LARCHMONT, NY 105383035 |
| Enforcement Action Type: | Notice of Violation |
| Facility County: | WESTCHESTER |
| Program System Acronym: | AIR |
| Enforcement Action Forum Desc: | Administrative - Informal |
| EA Type Code: | NOV |
| Facility SIC Code: | 7216 |
| Federal Facility ID: | Not reported |
| Latitude in Decimal Degrees: | 40.93337 |
| Longitude in Decimal Degrees: | -73.75856 |
| Permit Type Desc: | Not reported |
| Program System Acronym: | NY0000003553200266 |
| Facility NAICS Code: | 812320 |
| Tribal Land Code: | Not reported |

| | |
|---|---|
| Enforcement Action ID: | NY000A0000355320026600305 |
| FRS ID: | 110001601516 |
| Action Name: | EMBASSY CLEANERS 36119R208800305 |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Facility Name: | EMBASSY CLEANERS |
| Facility Address: | 1895 PALMER AVE |
| | LARCHMONT, NY 105383035 |
| Enforcement Action Type: | Notice of Violation |
| Facility County: | WESTCHESTER |
| Program System Acronym: | AIR |
| Enforcement Action Forum Desc: | Administrative - Informal |
| EA Type Code: | NOV |
| Facility SIC Code: | 7216 |
| Federal Facility ID: | Not reported |
| Latitude in Decimal Degrees: | 40.93337 |
| Longitude in Decimal Degrees: | -73.75856 |
| Permit Type Desc: | Not reported |
| Program System Acronym: | NY0000003553200266 |
| Facility NAICS Code: | 812320 |
| Tribal Land Code: | Not reported |

| | |
|---|---|
| Enforcement Action ID: | NY000A0000355320018900309 |
| FRS ID: | 110004345361 |
| Action Name: | EMBASSY CLEANERS 361190021300309 |
| Facility Name: | EMBASSY CLEANERS |
| Facility Address: | 1908 PALMER AVE |
| | LARCHMONT, NY 105382408 |
| Enforcement Action Type: | Notice of Violation |
| Facility County: | WESTCHESTER |
| Program System Acronym: | AIR |
| Enforcement Action Forum Desc: | Administrative - Informal |
| EA Type Code: | NOV |
| Facility SIC Code: | 7212 |
| Federal Facility ID: | Not reported |
| Latitude in Decimal Degrees: | 40.93337 |
| Longitude in Decimal Degrees: | -73.75856 |
| Permit Type Desc: | Not reported |
| Program System Acronym: | NY0000003553200189 |
| Facility NAICS Code: | 812320 |
| Tribal Land Code: | Not reported |

| | |
|---|---|
| Enforcement Action ID: | NY000A0000355320018900305 |
| FRS ID: | 110004345361 |
| Action Name: | EMBASSY CLEANERS 361190021300305 |
| Facility Name: | EMBASSY CLEANERS |
| Facility Address: | 1908 PALMER AVE |
| | LARCHMONT, NY 105382408 |
| Enforcement Action Type: | Notice of Violation |
| Facility County: | WESTCHESTER |
| Program System Acronym: | AIR |
| Enforcement Action Forum Desc: | Administrative - Informal |
| EA Type Code: | NOV |
| Facility SIC Code: | 7212 |
| Federal Facility ID: | Not reported |
| Latitude in Decimal Degrees: | 40.93337 |
| Longitude in Decimal Degrees: | -73.75856 |
| Permit Type Desc: | Not reported |
| Program System Acronym: | NY0000003553200189 |
| Facility NAICS Code: | 812320 |
| Tribal Land Code: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

US AIRS MINOR:
Envid: 1000708538
Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-12-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2010-12-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-09-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2012-08-07 00:00:00

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Activity Status Date: | 2012-08-07 00:00:00 |
| Activity Group: | Enforcement Action |
| Activity Type: | Administrative - Formal |
| Activity Status: | Final Order Issued |
| | |
| Region Code: | 02 |
| Programmatic ID: | AIR NY0000003553200266 |
| Facility Registry ID: | 110001601516 |
| Air Operating Status Code: | OPR |
| Default Air Classification Code: | MIN |
| Air Program: | MACT Standards (40 CFR Part 63) |
| Activity Date: | 2002-07-18 00:00:00 |
| Activity Status Date: | 2002-07-18 00:00:00 |
| Activity Group: | Enforcement Action |
| Activity Type: | Administrative - Informal |
| Activity Status: | Achieved |
| | |
| Region Code: | 02 |
| Programmatic ID: | AIR NY0000003553200266 |
| Facility Registry ID: | 110001601516 |
| Air Operating Status Code: | OPR |
| Default Air Classification Code: | MIN |
| Air Program: | MACT Standards (40 CFR Part 63) |
| Activity Date: | 2012-06-22 00:00:00 |
| Activity Status Date: | 2012-06-22 00:00:00 |
| Activity Group: | Enforcement Action |
| Activity Type: | Administrative - Informal |
| Activity Status: | Achieved |
| | |
| Region Code: | 02 |
| Programmatic ID: | AIR NY0000003553200266 |
| Facility Registry ID: | 110001601516 |
| Air Operating Status Code: | OPR |
| Default Air Classification Code: | MIN |
| Air Program: | MACT Standards (40 CFR Part 63) |
| Activity Date: | 2014-02-13 00:00:00 |
| Activity Status Date: | 2014-02-13 00:00:00 |
| Activity Group: | Enforcement Action |
| Activity Type: | Administrative - Informal |
| Activity Status: | Achieved |
| | |
| Region Code: | 02 |
| Programmatic ID: | AIR NY0000003553200266 |
| Facility Registry ID: | 110001601516 |
| Air Operating Status Code: | OPR |
| Default Air Classification Code: | MIN |
| Air Program: | State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards |
| Activity Date: | 2000-12-20 00:00:00 |
| Activity Status Date: | Not reported |
| Activity Group: | Compliance Monitoring |
| Activity Type: | Inspection/Evaluation |
| Activity Status: | Not reported |
| | |
| Region Code: | 02 |
| Programmatic ID: | AIR NY0000003553200266 |
| Facility Registry ID: | 110001601516 |
| Air Operating Status Code: | OPR |

**EMBASSY CLEANERS (Continued)** **1000708538**

Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-12-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-09-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-08-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-07-18 00:00:00
Activity Status Date: 2002-07-18 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

FINDS:
Registry ID: 110004345361

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**EMBASSY CLEANERS (Continued)** **1000708538**

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

| | |
|---|---|
| Envid: | 1000708538 |
| Registry ID: | 110004345361 |
| DFR URL: | http://echo.epa.gov/detailed-facility-report?fid=110004345361 |
| Name: | EMBASSY CLEANERS |
| Address: | 1908 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |

DRYCLEANERS:

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2010-12-22 00:10:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2010-12-22 00:10:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2011-09-19 00:00:00 |

**EMBASSY CLEANERS (Continued)** **1000708538**

Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2018-05-30 00:00:00
Inspection Date: 2011-09-19 00:00:00
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2002-06-13 14:32:39
Inspection Date: 2011-12-12 07:10:00
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2018-05-30 00:00:00
Inspection Date: 2011-12-12 07:10:00
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2012-12-17 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2012-12-17 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2013-12-16 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2013-12-16 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2015-02-27 09:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2015-02-27 09:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2015-12-17 11:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2015-12-17 11:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2001-12-14 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2001-12-14 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2000-12-20 12:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2018-05-30 00:00:00
Inspection Date: 2000-12-20 12:00:00
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2002-06-13 14:32:39
Inspection Date: 2002-12-11 08:00:00
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2018-05-30 00:00:00
Inspection Date: 2002-12-11 08:00:00
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2003-12-11 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2003-12-11 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2004-12-08 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2004-12-08 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Current Business: | Not reported |
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2005-12-15 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2005-12-15 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2006-12-19 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Inspection Date: | 2006-12-19 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2007-12-19 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2007-12-19 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2008-12-16 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2008-12-16 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2009-12-23 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2009-12-23 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2010-12-22 00:10:00 |
| Install Date: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2010-12-22 00:10:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2011-09-19 00:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2011-09-19 00:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |

**EMBASSY CLEANERS (Continued)** **1000708538**

City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2002-06-13 14:32:39
Inspection Date: 2011-12-12 07:10:00
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2018-05-30 00:00:00
Inspection Date: 2011-12-12 07:10:00
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2002-06-13 14:32:39
Inspection Date: 2012-12-17 08:00:00
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2018-05-30 00:00:00
Inspection Date: 2012-12-17 08:00:00
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported

**EMBASSY CLEANERS (Continued)** **1000708538**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2002-06-13 14:32:39
Inspection Date: 2013-12-16 08:00:00
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2018-05-30 00:00:00
Inspection Date: 2013-12-16 08:00:00
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2002-06-13 14:32:39
Inspection Date: 2015-02-27 09:00:00
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2015-02-27 09:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2015-12-17 11:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2015-12-17 11:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2001-12-14 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2018-05-30 00:00:00
Inspection Date: 2001-12-14 08:00:00
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2002-06-13 14:32:39
Inspection Date: 2000-12-20 12:00:00
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2018-05-30 00:00:00
Inspection Date: 2000-12-20 12:00:00
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported

**EMBASSY CLEANERS (Continued)** **1000708538**

Registration Effective Date: 2002-06-13 14:32:39
Inspection Date: 2002-12-11 08:00:00
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2018-05-30 00:00:00
Inspection Date: 2002-12-11 08:00:00
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2002-06-13 14:32:39
Inspection Date: 2003-12-11 08:00:00
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2018-05-30 00:00:00
Inspection Date: 2003-12-11 08:00:00
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2004-12-08 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2004-12-08 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2005-12-15 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2005-12-15 08:00:00 |
| Install Date: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2006-12-19 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2018-05-30 00:00:00 |
| Inspection Date: | 2006-12-19 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 2002-06-13 14:32:39 |
| Inspection Date: | 2007-12-19 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |

**EMBASSY CLEANERS (Continued)** **1000708538**

City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2018-05-30 00:00:00
Inspection Date: 2007-12-19 08:00:00
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2002-06-13 14:32:39
Inspection Date: 2008-12-16 08:00:00
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2018-05-30 00:00:00
Inspection Date: 2008-12-16 08:00:00
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2002-06-13 14:32:39
Inspection Date: 2009-12-23 08:00:00
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported

**EMBASSY CLEANERS (Continued)** **1000708538**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 2018-05-30 00:00:00
Inspection Date: 2009-12-23 08:00:00
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

RI MANIFEST:
Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538
EPA Id: NYD986995249
GEN Cert Date: 11/23/2010
Manifest Document Number: 002496373SKS
Waste Description: TOXIC LIQUIDS ORGANIC NOS
TSDF Id: RID084802842
TSDF Name: SAFETY KLEEN
Qty: 240
WT/Vol Units: P
TSDF Date: 12/3/2010
Transporter 2 Id: NJD071629976
Item Number: 1
Transporter 2 Name: 12/3/2010
Transporter Name 2: SAFETY KLEEN
Transporter EPAID: TXR000050930
Transporter Receipt Date: 11/23/2010
Number Of Containers: 2
Container Type: DF
Waste Code1: D007
Waste Code2: D029
Waste Code3: D039
Waste Code4: Not reported
Waste Code5: Not reported
Waste Code6: Not reported
Fee Exempt Code: Not reported
Comment: Not reported
Transporter Name 2: SJ TRANSPORTATION CO INC
Company Permit Number: Not reported
Year: Not reported
Quarter: Not reported
Transporter Contact Name: Not reported
Transporter Contact Email: Not reported
Filing Date: Not reported

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Total Fee: | Not reported |
| Billing Name: | Not reported |
| Paid Date: | Not reported |
| Paid Time: | Not reported |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Manifest Created Date: | Not reported |
| Manifest Updated Date: | Not reported |

RI MANIFEST:

| | |
|---|---|
| Transporter Receipt Date: | 8/29/2012 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 003575801SKS |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 200 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 8/29/2012 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 9/7/2012 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 9/7/2012 |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |

| | |
|---|---|
| Transporter Receipt Date: | 3/26/2012 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 002740089SKS |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 200 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 3/26/2012 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 4/7/2012 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 4/7/2012 |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 2/21/2011 |
| Number Of Containers: | 3 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 003591202FLE |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 300 |
| Transporter Contact Email: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 2/21/2011 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 2/25/2011 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 2/25/2011 |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 2/21/2011 |
| Number Of Containers: | 3 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 003591202FLE |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 300 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 2/21/2011 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 2/25/2011 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 2/25/2011 |
| Transporter 2 ID: | NJD071629976 |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 7/8/2011 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 004246318FLE |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 200 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 7/8/2011 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 7/15/2011 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 7/15/2011 |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 7/8/2011 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 004246318FLE |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 200 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 7/8/2011 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 7/15/2011 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 7/15/2011 |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 9/17/2010 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | Not reported |
| TSDF Id: | Not reported |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 003869495FLE |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 240 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 9/17/2010 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 9/29/2010 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | Not reported |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 11/23/2010 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 002496373SKS |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 240 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 11/23/2010 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 12/3/2010 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 12/3/2010 |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 8/17/2010 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | Not reported |
| TSDF Id: | Not reported |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 003860185FLE |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 240 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 8/17/2010 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 8/24/2010 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | Not reported |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 11/23/2010 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 002496373SKS |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Quantity: | 240 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 11/23/2010 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 12/3/2010 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 12/3/2010 |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 8/17/2010 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | Not reported |
| TSDF Id: | Not reported |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 003860185FLE |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 240 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 8/17/2010 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 8/24/2010 |
| Manifest Created Date: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| TSDF Receipt Date: | Not reported |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |

Click this hyperlink while viewing on your computer to access
2 additional RI_MANIFEST: record(s) in the EDR Site Report.

NY MANIFEST:

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Country: | USA |
| EPA ID: | NYD986995249 |
| Facility Status: | Not reported |
| Location Address 1: | 1895 PALMER AVENUE |
| Code: | BP |
| Location Address 2: | Not reported |
| Total Tanks: | Not reported |
| Location City: | LARCHMONT |
| Location State: | NY |
| Location Zip: | 10538 |
| Location Zip 4: | Not reported |

NY MANIFEST:

| | |
|---|---|
| EPAID: | NYD986995249 |
| Mailing Name: | EMBASSY CLEANERS |
| Mailing Contact: | BRIAN |
| Mailing Address 1: | 1895 PALMER AVENUE |
| Mailing Address 2: | Not reported |
| Mailing City: | LARCHMONT |
| Mailing State: | NY |
| Mailing Zip: | 10538 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 9148342700 |

NY MANIFEST:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| seq: | Not reported |
| Year: | 2018 |
| Trans1 State ID: | TXR000081205 |
| Trans2 State ID: | MAD039322250 |
| Generator Ship Date: | 12/30/2016 |
| Trans1 Recv Date: | 12/30/2016 |
| Trans2 Recv Date: | 01/04/2017 |
| TSD Site Recv Date: | 01/24/2017 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986995249 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | TXD055141378 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 005645104SKS |
| Import Indicator: | N |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H040 |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Quantity: | 250 |
| Units: | P - Pounds |
| Number of Containers: | 5 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 1 |
| Waste Code: | F002 |
| Waste Code 1_2: | D007 |
| Waste Code 1_3: | D030 |
| Waste Code 1_4: | D033 |
| Waste Code 1_5: | Not reported |
| Waste Code 1_6: | Not reported |

---

**F25** **HOFFMAN INVESTORS CORP.** **NY LTANKS** **S100492356**
**South** **1890 PALMER AVENUE** **NY LIENS** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.151 mi.**
**796 ft.** **Site 2 of 3 in cluster F**

**Relative:**
**Higher**

**Actual:**
**60 ft.**

LTANKS:

| | |
|---|---|
| Name: | EAST RIVER SAVINGS BANK |
| Address: | 1890 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9211942 / 2000-03-09 |
| Facility ID: | 9211942 |
| Site ID: | 104436 |
| Spill Date: | 1993-01-19 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1993-01-19 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Affected Persons |
| Last Inspection: | Not reported |
| Recommended Penalty: | True |
| Meets Standard: | True |

**HOFFMAN INVESTORS CORP. (Continued)** **S100492356**

| | |
|---|---|
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1993-01-21 |
| Spill Record Last Update: | 2005-11-23 |
| Spiller Name: | Not reported |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 92263 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/28/99 CLEANUP COMPLETED. ISR COMPLETED 6/23/99." |
| Remarks: | "UNDERGROUND STORAGE TANK AT BANK LEAKING PETROLEUM LEAKING INTO BASEMENT BLDG. NEXT DOOR NOTIFIED HD & HAZMAT ON SCENE CONTRACTOR CALLED TO CLEAN UP" |

All Materials:

| | |
|---|---|
| Site ID: | 104436 |
| Operable Unit ID: | 976512 |
| Operable Unit: | 01 |
| Material ID: | 405325 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

LIENS:

| | |
|---|---|
| Name: | HOFFMAN INVESTORS CORP. |
| Address: | 1890 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY |
| Region: | 3 |
| Spill No: | 92-11942 |
| Tax Map Id: | 6-3-6 |
| Lien Request Received: | 06/26/2001 |
| Request Sent To APA Or Vendor: | 07/09/2001 |
| Draft Lien Received From Vendor: | 08/13/2001 |
| Approved Lien To Administrator: | Not reported |
| Signed By Administrator: | Not reported |
| Received From Administrator: | Not reported |
| Sent For Filing: | Not reported |
| Resent For Filing: | Not reported |
| Proof Of Service Received: | Not reported |
| Sent To OAG: | 08/15/2001 |
| Amount: | 25,322.07 |
| Release Required: | 06/28/2002 |
| Sent To Administrator: | Not reported |
| Signed By Adminstrator: | Not reported |
| Received From Adminsitrator: | Not reported |
| Release Sent To OAG: | 06/30/2002 |

**HOFFMAN INVESTORS CORP. (Continued)** **S100492356**

Complete: True
Release: True
Withdrawn: False

---

**26**
**ESE**
**1/8-1/4**
**0.152 mi.**
**804 ft.**

**COLONY TENANTS CORP.** **NY UST** **U003855870**
**1815 PALMER AVENUE** **N/A**
**LARCHMONT, NY 10538**

**Relative:**
**Lower**

**Actual:**
**38 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | COLONY TENANTS CORP. |
| Address: | 1815 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-104590 / Active |
| Operator Name: | Archer Property Management |
| Owner Name: | Colony Tenants Corp., c/o Archer Property Mgmt. |
| Owner Street: | 105 Calvert Street |
| Owner Address2: | Not reported |
| Owner City: | Harrison |
| Owner State: | NY |
| Owner Zipcode: | 10528 |
| GDS Number: | Not reported |
| | |
| Tank Number: | 002 |
| Status: | 1. In-Service |
| Capacity: | 5000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 2. Manual Interstitial Monitoring |
| Date Installation: | 06/01/1999 |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 10. Urethane clad steel |
| Tank Internal Protection: | 4. Glass liner |
| Tank External Protection: | 2. Original sacrificial anode,9. Urethane |
| Tank Secondary Containment: | 4. Double-Walled (underground only) |
| Piping Location: | 2. Underground/on Ground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 4. Fiberglass |
| Overfill Prevention: | 2. High Level Alarm,5. Vent Whistle |
| Piping Secondary Containment: | 4. Double-Walled (underground only) |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 2. Suction |
| | |
| Tank Number: | 1 |
| Status: | 3. Closed - Removed |
| Capacity: | 5000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | Not reported |
| Date Perm Closure: | 12/14/1999 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |

**COLONY TENANTS CORP. (Continued)** **U003855870**

| | |
|---|---|
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | Not reported |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 2. Suction |

---

**F27** **BANK OF NY** **NY LTANKS** **S100140326**
**South** **124 CHASWORTH AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.162 mi.**
**855 ft.** **Site 3 of 3 in cluster F**

**Relative:**
**Higher**

**Actual:**
**59 ft.**

LTANKS:

| | |
|---|---|
| Name: | BANK OF NY |
| Address: | 124 CHASWORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 8800277 / 1997-12-01 |
| Facility ID: | 8800277 |
| Site ID: | 80193 |
| Spill Date: | 1988-04-08 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | B3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jghardy |
| Referred To: | Not reported |
| Reported to Dept: | 1988-04-08 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1988-04-21 |
| Spill Record Last Update: | 2003-08-27 |
| Spiller Name: | Not reported |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 74353 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 04/22/97 HARD COPY FILE IN TARRYTOWN FOR REVIEW BY TODD G. " |
| Remarks: | "1 PUMP RECOVERY SYSTEM TO O/W SEPARATOR THEN THROUGH CARBON. SANITARY SEWER DISCHARGE." |

All TTF:

| | |
|---|---|
| Facility ID: | 8800277 |
| Spill Number: | 8800277 |

**BANK OF NY (Continued)** **S100140326**

| | |
|---|---|
| Spill Tank Test: | 1533611 |
| Site ID: | 80193 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 80193 |
| Operable Unit ID: | 915906 |
| Operable Unit: | 01 |
| Material ID: | 462996 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | 404.00 |
| Oxygenate: | Not reported |

---

**G28** **SPILL NUMBER 8906916** **NY LTANKS** **S100140639**
**SSW** **132 CHATSWORTH AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.175 mi.**
**926 ft.** **Site 1 of 2 in cluster G**

**Relative:**
**Higher**

**Actual:**
**55 ft.**

LTANKS:

| | |
|---|---|
| Name: | ORLOFSKY APT. BLDG. |
| Address: | 132 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 8906577 / 1992-07-30 |
| Facility ID: | 8906577 |
| Site ID: | 275785 |
| Spill Date: | 1989-10-04 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C4 |
| Cleanup Ceased: | 1992-07-30 |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1989-10-04 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | 1989-10-04 |

**SPILL NUMBER 8906916 (Continued)** **S100140639**

| | |
|---|---|
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1989-10-11 |
| Spill Record Last Update: | 1992-07-30 |
| Spiller Name: | Not reported |
| Spiller Company: | ORLOFSKY MANAGEMENT |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 224219 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: | "2K TANK. PETROTITE EIR TODD G ON SITE FOR INITIAL TEST" |

All TTF:

| | |
|---|---|
| Facility ID: | 8906577 |
| Spill Number: | 8906577 |
| Spill Tank Test: | 1536152 |
| Site ID: | 275785 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 275785 |
| Operable Unit ID: | 931594 |
| Operable Unit: | 01 |
| Material ID: | 559430 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | Not reported |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | SPILL NUMBER 8906916 |
| Address: | 132 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 8906916 / 1992-07-30 |

**SPILL NUMBER 8906916 (Continued)** **S100140639**

| | |
|---|---|
| Facility ID: | 8906916 |
| Site ID: | 275786 |
| Spill Date: | 1989-10-09 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | C4 |
| Cleanup Ceased: | 1992-07-30 |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1989-10-10 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1989-11-01 |
| Spill Record Last Update: | 2003-09-26 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 224219 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: | "PETRO, 2K, TODD GHIOSAY ON SITE PIPING PROBLEM, TANK TO BE REMOVED. TANK IS BEING REMOVED TODAY 10/16/89" |

All TTF:

| | |
|---|---|
| Facility ID: | 8906916 |
| Spill Number: | 8906916 |
| Spill Tank Test: | 1536232 |
| Site ID: | 275786 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 275786 |
| Operable Unit ID: | 934694 |

**SPILL NUMBER 8906916 (Continued)** **S100140639**

| | |
|---|---|
| Operable Unit: | 01 |
| Material ID: | 443724 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**G29** **HOWELL ASSOCIATES** **NY AST** **A100359836**
**SSW** **132 CHATSWORTH AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.175 mi.**
**926 ft.** **Site 2 of 2 in cluster G**

**Relative:**
**Higher**

**Actual:**
**55 ft.**

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | HOWELL ASSOCIATES |
| Address: | 132 CHATSWORTH AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-049565 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | Juan Soto |
| Owner Name: | Howell Associates, c/o Robert Orlofsky Realty Inc. |
| Owner Street: | 7 Bryant Crescent, Suite 1C |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | White Plains, NY 10605 |
| | |
| Tank Number: | 880 |
| Status: | 1. In-Service |
| Date Installation: | 10/01/1990 |
| Capacity: | 2000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | 2. Vault (w/ access) |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 6. Wrapped (Piping) |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 5. Vent Whistle |
| Spill Prevention: | 0. None |
| Dispenser: | 1. Submersible |

**H30** **CON EDISON** **RCRA NonGen / NLR** **1019901839**
**SW** **MYRTLE AVE & CHATSWORTH AVE** **FINDS** **NYP004766622**
**1/8-1/4** **LARCHMONT, NY 10538** **ECHO**
**0.176 mi.**
**929 ft.** **Site 1 of 3 in cluster H**

**Relative:** **Higher**
**Actual:** **50 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20150412 |
| Handler Name: | CON EDISON | |
| Handler Address: | | MYRTLE AVE & CHATSWORTH AVE |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYP004766622 |
| Contact Name: | | THOMAS TEELING |
| Contact Address: | | Not reported |
| Contact City,State,Zip: | | Not reported |
| Contact Telephone: | | 212-460-3770 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Private |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | NY |
| State District: | | NYSDEC R2 |
| Mailing Address: | | IRVING PL 15TH FL NE |
| Mailing City,State,Zip: | | NEW YORK, NY 10003 |
| Owner Name: | Not reported | |
| Owner Type: | | Not reported |
| Operator Name: | Not reported | |
| Operator Type: | | Not reported |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site Fed-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site Converter Treatment storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | NN |
| Sub-Part K Indicator: | | Not reported |
| Commercial TSD Indicator: | | No |
| Treatment Storage and Disposal Type: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| Permit Renewals Workload Universe: | | Not reported |

**CON EDISON (Continued)** **1019901839**

| | |
|---|---|
| Permit Workload Universe: | Not reported |
| Permit Progress Universe: | Not reported |
| Post-Closure Workload Universe: | Not reported |
| Closure Workload Universe: | Not reported |
| 202 GPRA Corrective Action Baseline: | No |
| Corrective Action Workload Universe: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: | No |
| TSDFs Only Subject to CA under Discretionary Auth Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Operating TSDF Universe: | Not reported |
| Full Enforcement Universe: | Not reported |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: Not reported | |
| Handler Date of Last Change: | 20160909 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | Not reported |
| Manifest Broker: | Not reported |
| Sub-Part P Indicator: | No |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20150412 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Large Quantity Generator |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20150412 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |

**CON EDISON (Continued)** **1019901839**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069661976

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

| | |
|---|---|
| Envid: | 1019901839 |
| Registry ID: | 110069661976 |
| DFR URL: | http://echo.epa.gov/detailed-facility-report?fid=110069661976 |
| Name: | CON EDISON |
| Address: | MYRTLE AVE & CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |

---

**H31** **CON EDISON** **NY MANIFEST** **S119074367**
**SW** **MYRTLE AVE & CHATSWORTH AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.176 mi.**
**929 ft.** **Site 2 of 3 in cluster H**

**Relative:**
**Higher**

**Actual:**
**50 ft.**

NY MANIFEST:

| | |
|---|---|
| Name: | CON EDISON |
| Address: | MYRTLE AVE & CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Country: | USA |
| EPA ID: | NYP004766622 |
| Facility Status: | Not reported |
| Location Address 1: | N CHATSWORTH AVE & MYRTLE BLVD |
| Code: | BP |
| Location Address 2: | TM 259 |
| Total Tanks: | Not reported |
| Location City: | LARCHMONT |
| Location State: | NY |
| Location Zip: | 10538 |
| Location Zip 4: | Not reported |

**CON EDISON (Continued)** **S119074367**

NY MANIFEST:

| | |
|---|---|
| EPAID: | NYP004766622 |
| Mailing Name: | CON EDISON |
| Mailing Contact: | TOM TEELING |
| Mailing Address 1: | 4 IRVING PLACE - 15TH FLOOR |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | Not reported |

NY MANIFEST:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| seq: | Not reported |
| Year: | 2018 |
| Trans1 State ID: | NYD006982359 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 04/12/2015 |
| Trans1 Recv Date: | 04/12/2015 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 04/15/2015 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004766622 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD002200046 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 014085125JJK |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H110 |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Quantity: | 150 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Waste Code: | D008 |

**CON EDISON (Continued)** **S119074367**

| | |
|---|---|
| Waste Code 1_2: | Not reported |
| Waste Code 1_3: | Not reported |
| Waste Code 1_4: | Not reported |
| Waste Code 1_5: | Not reported |
| Waste Code 1_6: | Not reported |

---

**H32** **CON EDISON** **NJ MANIFEST** **S120670369**
**SW** **MYRTLE AVE & CHATSWORTH AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.176 mi.**
**929 ft.** **Site 3 of 3 in cluster H**

**Relative:**
**Higher**

**Actual:**
**50 ft.**

NJ MANIFEST:

| | |
|---|---|
| EPA Id: | NYP004766622 |
| Mail Address: | IRVING PL 15TH FL NE |
| Mail City/State/Zip: | NEW YORK, NY 10003 |
| Facility Phone: | Not reported |
| Emergency Phone: | Not reported |
| Contact: | THOMAS TEELING |
| Comments: | Not reported |
| SIC Code: | Not reported |
| County: | NY119 |
| Municipal: | Not reported |
| Previous EPA Id: | Not reported |
| Gen Flag: | Not reported |
| Trans Flag: | Not reported |
| TSDF Flag: | Not reported |
| Name Change: | Not reported |
| Date Change: | Not reported |

Manifest:

| | |
|---|---|
| Manifest Number: | 014085125JJK |
| EPA ID: | NYP004766622 |
| Date Shipped: | 4/12/2015 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NYD006982359 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| TSDF EPA Facility Name: | Not reported |

**CON EDISON (Continued)** **S120670369**

| | |
|---|---|
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Was Load Rejected: | NEW YORK, NY 10003 |
| Reason Load Was Rejected: | Not reported |

---

**33** **NYS THRUWAY MAINTENANCE CENTER** **RCRA NonGen / NLR** **1000889946**
**SSW** **I-95 EXIT 17 OFF NEW ENGLAND** **NY0000198762**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.177 mi.**
**935 ft.**

**Relative:**
**Higher**

**Actual:**
**46 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20070101 |
| Handler Name: | NYS THRUWAY MAINTENANCE CENTER | |
| Handler Address: | | I-95 EXIT 17 OFF NEW ENGLAND |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NY0000198762 |
| Contact Name: | | Not reported |
| Contact Address: | | I-95 EXIT 17 OFF NEW ENGLAND |
| Contact City,State,Zip: | | LARCHMONT, NY 10538 |
| Contact Telephone: | | Not reported |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | NY |
| State District: | | NYSDEC R3 |
| Mailing Address: | | I-95 EXIT 17 OFF NEW ENGLAND |
| Mailing City,State,Zip: | | LARCHMONT, NY 10538 |
| Owner Name: | NYS THRUWAY AUTH | |
| Owner Type: | | State |
| Operator Name: | NYS THRUWAY AUTH | |
| Operator Type: | | State |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |

**NYS THRUWAY MAINTENANCE CENTER (Continued)** **1000889946**

| | |
|---|---|
| Smelting Melting and Refining Furnace Exemption: | No |
| Underground Injection Control: | No |
| Off-Site Waste Receipt: | No |
| Universal Waste Indicator: | No |
| Universal Waste Destination Facility: | No |
| Federal Universal Waste: | No |
| Active Site Fed-Reg Treatment Storage and Disposal Facility: | Not reported |
| Active Site Converter Treatment storage and Disposal Facility: | Not reported |
| Active Site State-Reg Treatment Storage and Disposal Facility: | Not reported |
| Active Site State-Reg Handler: | --- |
| Federal Facility Indicator: | Not reported |
| Hazardous Secondary Material Indicator: | NN |
| Sub-Part K Indicator: | Not reported |
| Commercial TSD Indicator: | No |
| Treatment Storage and Disposal Type: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| Permit Renewals Workload Universe: | Not reported |
| Permit Workload Universe: | Not reported |
| Permit Progress Universe: | Not reported |
| Post-Closure Workload Universe: | Not reported |
| Closure Workload Universe: | Not reported |
| 202 GPRA Corrective Action Baseline: | No |
| Corrective Action Workload Universe: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: | No |
| TSDFs Only Subject to CA under Discretionary Auth Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Operating TSDF Universe: | Not reported |
| Full Enforcement Universe: | Not reported |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: Not reported | |
| Handler Date of Last Change: | 20150414 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | Not reported |
| Manifest Broker: | Not reported |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Handler - Owner Operator:
Owner/Operator Indicator: Owner

**NYS THRUWAY MAINTENANCE CENTER (Continued)** **1000889946**

Owner/Operator Name: NYS THRUWAY AUTH
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 200 SOUTHERN BLVD
Owner/Operator City,State,Zip: ALBANY, NY 12209
Owner/Operator Telephone: 518-436-2700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYS THRUWAY AUTH
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 200 SOUTHERN BLVD
Owner/Operator City,State,Zip: ALBANY, NY 12209
Owner/Operator Telephone: 518-436-2700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYS THRUWAY AUTH
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 200 SOUTHERN BLVD
Owner/Operator City,State,Zip: ALBANY, NY 12209
Owner/Operator Telephone: 518-436-2700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: NYS THRUWAY MAINTENANCE CENTER
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NYS THRUWAY MAINTENANCE CENTER
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

**NYS THRUWAY MAINTENANCE CENTER (Continued)** **1000889946**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYS THRUWAY MAINTENANCE CENTER
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940406
Handler Name: NYS THRUWAY MAINTENANCE CENTER
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

---

**34**
**NE**
**1/8-1/4**
**0.178 mi.**
**942 ft.**

**PRESTO RESIDNECE**
**130 LAUREL AVE**
**LARCHMONT, NY**

**NY LTANKS** **S111012254**
**N/A**

**Relative:**
**Higher**

**Actual:**
**48 ft.**

LTANKS:
Name: PRESTO RESIDNECE
Address: 130 LAUREL AVE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 1100421 / 2011-09-15
Facility ID: 1100421
Site ID: 447824
Spill Date: 2011-04-12
Spill Cause: Tank Test Failure

**PRESTO RESIDNECE (Continued)** **S111012254**

| | |
|---|---|
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2011-04-12 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2011-04-12 |
| Spill Record Last Update: | 2011-09-15 |
| Spiller Name: | Not reported |
| Spiller Company: | PRESTO |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | PRESTO |
| Spiller Phone: | (914) 834-8344 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 402415 |
| DEC Memo: | "4-12-11 Spoke with Paul. Tank will be removed. They have given homeowner a list of contractors to choose from for this work. jm 09/06/11 Northeast environkmental reported that they removed the tank along with 82.14 tons of impacted soil. NFA Tg" |
| Remarks: | "550gal ust" |

All Materials:

| | |
|---|---|
| Site ID: | 447824 |
| Operable Unit ID: | 1198056 |
| Operable Unit: | 01 |
| Material ID: | 2194303 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**I35 South 1/8-1/4 0.179 mi. 947 ft.** **CON EDISON MANHOLE: 263**
**CHATSWORTH AVE & PALMER AVE**
**LARCHMONT, NY 10538**
**Site 1 of 7 in cluster I**

**RCRA NonGen / NLR 1016677341**
**FINDS NYP004309225**
**ECHO**
**NY MANIFEST**

**Relative: Higher**
**Actual: 58 ft.**

RCRA Listings:

| | |
|---|---|
| Date Form Received by Agency: | 20130608 |
| Handler Name: | CON EDISON MANHOLE: 263 |
| Handler Address: | CHATSWORTH AVE & PALMER AVE |
| Handler City,State,Zip: | LARCHMONT, NY 10538 |

**CON EDISON MANHOLE: 263 (Continued)** **1016677341**

| | | |
|---|---|---|
| EPA ID: | | NYP004309225 |
| Contact Name: | | DONALD SENNO |
| Contact Address: | | Not reported |
| Contact City,State,Zip: | | Not reported |
| Contact Telephone: | | 914-925-6219 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | SR SPECIALIST |
| EPA Region: | | 02 |
| Land Type: | | Private |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | NY |
| State District: | | NYSDEC R2 |
| Mailing Address: | | VING PL, RM 828 |
| Mailing City,State,Zip: | | NEW YORK, NY 10003 |
| Owner Name: | Not reported | |
| Owner Type: | | Not reported |
| Operator Name: | Not reported | |
| Operator Type: | | Not reported |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site Fed-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site Converter Treatment storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | NN |
| Sub-Part K Indicator: | | Not reported |
| Commercial TSD Indicator: | | No |
| Treatment Storage and Disposal Type: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| Permit Renewals Workload Universe: | | Not reported |
| Permit Workload Universe: | | Not reported |
| Permit Progress Universe: | | Not reported |
| Post-Closure Workload Universe: | | Not reported |
| Closure Workload Universe: | | Not reported |
| 202 GPRA Corrective Action Baseline: | | No |
| Corrective Action Workload Universe: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: | | No |

**CON EDISON MANHOLE: 263 (Continued)** **1016677341**

| | |
|---|---|
| TSDFs Only Subject to CA under Discretionary Auth Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Operating TSDF Universe: | Not reported |
| Full Enforcement Universe: | Not reported |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: Not reported | |
| Handler Date of Last Change: | 20140402 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | Not reported |
| Manifest Broker: | Not reported |
| Sub-Part P Indicator: | No |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20130508 |
| Handler Name: CON EDISON MANHOLE: 263 | |
| Federal Waste Generator Description: | Conditionally Exempt Small Quantity Generator |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20130608 |
| Handler Name: CON EDISON MANHOLE: 263 | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

List of NAICS Codes and Descriptions:

| | |
|---|---|
| NAICS Codes: | No NAICS Codes Found |

Facility Has Received Notices of Violations:

| | |
|---|---|
| Violations: | No Violations Found |

**CON EDISON MANHOLE: 263 (Continued)** **1016677341**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110058872171

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

| | |
|---|---|
| Envid: | 1016677341 |
| Registry ID: | 110058872171 |
| DFR URL: | http://echo.epa.gov/detailed-facility-report?fid=110058872171 |
| Name: | CON EDISON MANHOLE: 263 |
| Address: | CHATSWORTH AVE & PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |

NY MANIFEST:

| | |
|---|---|
| Name: | CON EDISON |
| Address: | CHATSWORTH AVE & PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Country: | USA |
| EPA ID: | NYP004309225 |
| Facility Status: | Not reported |
| Location Address 1: | PALMER AVE & CHATSWORTH AVE |
| Code: | BP |
| Location Address 2: | Not reported |
| Total Tanks: | Not reported |
| Location City: | LARCHMONT |
| Location State: | NY |
| Location Zip: | 10538 |
| Location Zip 4: | Not reported |

NY MANIFEST:

| | |
|---|---|
| EPAID: | NYP004309225 |
| Mailing Name: | CON EDISON |
| Mailing Contact: | CON EDISON |
| Mailing Address 1: | 4 IRVING PLACE 15TH FLOOR |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 2124603770 |

**CON EDISON MANHOLE: 263 (Continued)** **1016677341**

NY MANIFEST:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| seq: | Not reported |
| Year: | 2018 |
| Trans1 State ID: | NYD006982359 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 05/08/2013 |
| Trans1 Recv Date: | 05/08/2013 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 05/14/2013 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004309225 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD002200046 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 007655517JJK |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H110 |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Quantity: | 55 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Waste Code: | D008 |
| Waste Code 1_2: | Not reported |
| Waste Code 1_3: | Not reported |
| Waste Code 1_4: | Not reported |
| Waste Code 1_5: | Not reported |
| Waste Code 1_6: | Not reported |

**I36** **CON EDISON** **NY MANIFEST** **S117537406**
**South** **PALMER AVE & CHATSWORTH AV** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.179 mi.**
**947 ft.** **Site 2 of 7 in cluster I**

**Relative:**
**Higher**

**Actual:**
**58 ft.**

NY MANIFEST:

| | |
|---|---|
| Name: | CON EDISON |
| Address: | PALMER AVE & CHATSWORTH AV |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Country: | USA |
| EPA ID: | NYP004699658 |
| Facility Status: | Not reported |
| Location Address 1: | PALMER AVE & CHATSWORTH AV |
| Code: | BP |
| Location Address 2: | TM267 |
| Total Tanks: | Not reported |
| Location City: | LARCHMONT |
| Location State: | NY |
| Location Zip: | 10538 |
| Location Zip 4: | Not reported |

NY MANIFEST:

| | |
|---|---|
| EPAID: | NYP004699658 |
| Mailing Name: | CON EDISON |
| Mailing Contact: | CON EDISON |
| Mailing Address 1: | 4 IRVING PL |
| Mailing Address 2: | 15TH FL |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | Not reported |

NY MANIFEST:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| seq: | Not reported |
| Year: | 2018 |
| Trans1 State ID: | NYD006982359 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 11/25/2014 |
| Trans1 Recv Date: | 11/25/2014 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 11/26/2014 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004699658 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD002200046 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 012772403JJK |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |

**CON EDISON (Continued)** **S117537406**

| | |
|---|---|
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H110 |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Quantity: | 800 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Waste Code: | D008 |
| Waste Code 1_2: | Not reported |
| Waste Code 1_3: | Not reported |
| Waste Code 1_4: | Not reported |
| Waste Code 1_5: | Not reported |
| Waste Code 1_6: | Not reported |

---

**I37** **BANK OF NEW YORK** **NY LTANKS** **S100166446**
**South** **124 CHATSWORTH AVE.** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.183 mi.**
**965 ft.** **Site 3 of 7 in cluster I**

**Relative:** **Higher**
**Actual:** **58 ft.**

LTANKS:

| | |
|---|---|
| Name: | BANK OF NEW YORK |
| Address: | 124 CHATSWORTH AVE. |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9011938 / 1993-02-23 |
| Facility ID: | 9011938 |
| Site ID: | 276370 |
| Spill Date: | 1991-02-14 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | B3 |
| Cleanup Ceased: | 1993-02-23 |
| SWIS: | 6000 |
| Investigator: | WXWADSWO |
| Referred To: | Not reported |
| Reported to Dept: | 1991-02-14 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1991-02-19 |
| Spill Record Last Update: | 1993-04-02 |

**BANK OF NEW YORK (Continued)** **S100166446**

| | |
|---|---|
| Spiller Name: | Not reported |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 224685 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST." |
| Remarks: | "TANK IS FIVE YEARS OLD SUSPECT AIR POCKET OIL SITE ASSESMENT DONE AT SERVICE STATION BEHIND BANK OIL RECOVERY 30 FT.AWAY WILL EIR WCHD NOTIFIED SYSTEM-PETRO -.124" |

All TTF:

| | |
|---|---|
| Facility ID: | 9011938 |
| Spill Number: | 9011938 |
| Spill Tank Test: | 1538257 |
| Site ID: | 276370 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 276370 |
| Operable Unit ID: | 948945 |
| Operable Unit: | 01 |
| Material ID: | 428447 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | Not reported |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**I38** **CHATSWORTH CLEANERS INC** **RCRA-VSQG** **1000890429**
**South** **120 CHATSWORTH AVE** **US AIRS** **NY0000363101**
**1/8-1/4** **LARCHMONT, NY 10538** **FINDS**
**0.185 mi.** **NY DRYCLEANERS**
**979 ft.** **Site 4 of 7 in cluster I** **NY MANIFEST**

**Relative:** **Higher**
**Actual:** **58 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20070101 |
| Handler Name: | CHATSWORTH CLEANERS | |
| Handler Address: | | 120 CHATSWORTH AVE |
| Handler City,State,Zip: | | LARCHMONT, NY 10538-2901 |
| EPA ID: | | NY0000363101 |
| Contact Name: | | JIMMY KIM |
| Contact Address: | | CHATSWORTH AVE |
| Contact City,State,Zip: | | LARCHMONT, NY 10538-2901 |
| Contact Telephone: | | 914-834-7203 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Conditionally Exempt Small Quantity Generator |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Handler Activities |
| State District Owner: | | NY |
| State District: | | NYSDEC R3 |
| Mailing Address: | | CHATSWORTH AVE |
| Mailing City,State,Zip: | | LARCHMONT, NY 10538-2901 |
| Owner Name: | JIMMY KIM | |
| Owner Type: | | Private |
| Operator Name: | JIMMY KIM | |
| Operator Type: | | Private |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site Fed-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site Converter Treatment storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | NN |
| Sub-Part K Indicator: | | Not reported |
| Commercial TSD Indicator: | | No |
| Treatment Storage and Disposal Type: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| Permit Renewals Workload Universe: | | Not reported |

**CHATSWORTH CLEANERS INC (Continued)** **1000890429**

| | |
|---|---|
| Permit Workload Universe: | Not reported |
| Permit Progress Universe: | Not reported |
| Post-Closure Workload Universe: | Not reported |
| Closure Workload Universe: | Not reported |
| 202 GPRA Corrective Action Baseline: | No |
| Corrective Action Workload Universe: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: | No |
| TSDFs Only Subject to CA under Discretionary Auth Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Operating TSDF Universe: | Not reported |
| Full Enforcement Universe: | Not reported |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: Not reported | |
| Handler Date of Last Change: | 20150414 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | Not reported |
| Manifest Broker: | Not reported |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

Waste Code: D000
Waste Description: Not Defined

Waste Code: D039
Waste Description: TETRACHLOROETHYLENE

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator: Owner
Owner/Operator Name: JIMMY KIM
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported

**CHATSWORTH CLEANERS INC (Continued)** **1000890429**

Owner/Operator Address: 120 CHATSWORTH AVE
Owner/Operator City,State,Zip: LARCHMONT, NY 10538
Owner/Operator Telephone: 914-834-7203
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: JIMMY KIM
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 120 CHATSWORTH AVE
Owner/Operator City,State,Zip: LARCHMONT, NY 10538
Owner/Operator Telephone: 914-834-7203
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JIMMY KIM
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 120 CHATSWORTH AVE
Owner/Operator City,State,Zip: LARCHMONT, NY 10538
Owner/Operator Telephone: 914-834-7203
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: CHATSWORTH CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CHATSWORTH CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

**CHATSWORTH CLEANERS INC (Continued)** **1000890429**

| | |
|---|---|
| Receive Date: | 19981218 |
| Handler Name: | CHATSWORTH CLEANERS |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

List of NAICS Codes and Descriptions:

| | |
|---|---|
| NAICS Codes: | No NAICS Codes Found |

Facility Has Received Notices of Violation:

| | |
|---|---|
| Found Violation: | No |
| Agency Which Determined Violation: | Not reported |
| Violation Short Description: | Not reported |
| Date Violation was Determined: | Not reported |
| Actual Return to Compliance Date: | Not reported |
| Return to Compliance Qualifier: | Not reported |
| Violation Responsible Agency: | Not reported |
| Scheduled Compliance Date: | Not reported |
| Enforcement Identifier: | Not reported |
| Date of Enforcement Action: | Not reported |
| Enforcement Responsible Agency: | Not reported |
| Enforcement Docket Number: | Not reported |
| Enforcement Attorney: | Not reported |
| Corrective Action Component: | Not reported |
| Appeal Initiated Date: | Not reported |
| Appeal Resolution Date: | Not reported |
| Disposition Status Date: | Not reported |
| Disposition Status: | Not reported |
| Disposition Status Description: | Not reported |
| Consent/Final Order Sequence Number: | Not reported |
| Consent/Final Order Respondent Name: | Not reported |
| Consent/Final Order Lead Agency: | Not reported |
| Enforcement Type: | Not reported |
| Enforcement Responsible Person: | Not reported |
| Enforcement Responsible Sub-Organization: | Not reported |
| SEP Sequence Number: | Not reported |
| SEP Expenditure Amount: | Not reported |
| SEP Scheduled Completion Date: | Not reported |
| SEP Actual Date: | Not reported |
| SEP Defaulted Date: | Not reported |
| SEP Type: | Not reported |
| SEP Type Description: | Not reported |
| Proposed Amount: | Not reported |
| Final Monetary Amount: | Not reported |
| Paid Amount: | Not reported |
| Final Count: | Not reported |
| Final Amount: | Not reported |

**CHATSWORTH CLEANERS INC (Continued)** **1000890429**

Evaluation Action Summary:

| | |
|---|---|
| Evaluation Date: | 20170516 |
| Evaluation Responsible Agency: | State |
| Found Violation: | No |
| Evaluation Type Description: | COMPLIANCE EVALUATION INSPECTION ON-SITE |
| Evaluation Responsible Person Identifier: | NYMOC |
| Evaluation Responsible Sub-Organization: | R3 |
| Actual Return to Compliance Date: | Not reported |
| Scheduled Compliance Date: | Not reported |
| Date of Request: | Not reported |
| Date Response Received: | Not reported |
| Request Agency: | Not reported |
| Former Citation: | Not reported |

US AIRS MINOR:

| | |
|---|---|
| Envid: | 1000890429 |
| Region Code: | 02 |
| Programmatic ID: | AIR NY0000003553200305 |
| Facility Registry ID: | 110004316204 |
| D and B Number: | Not reported |
| Primary SIC Code: | 7216 |
| NAICS Code: | 812320 |
| Default Air Classification Code: | MIN |
| Facility Type of Ownership Code: | POF |
| Air CMS Category Code: | Not reported |
| HPV Status: | Not reported |

US AIRS MINOR:

| | |
|---|---|
| Region Code: | 02 |
| Programmatic ID: | AIR NY0000003553200305 |
| Facility Registry ID: | 110004316204 |
| Air Operating Status Code: | OPR |
| Default Air Classification Code: | MIN |
| Air Program: | State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards |
| Activity Date: | 2014-08-26 00:00:00 |
| Activity Status Date: | Not reported |
| Activity Group: | Compliance Monitoring |
| Activity Type: | Inspection/Evaluation |
| Activity Status: | Not reported |

FINDS:

Registry ID: 110004316204

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major

**CHATSWORTH CLEANERS INC (Continued)** **1000890429**

redesign to support facility operating permits required under Title V of the Clean Air Act.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

DRYCLEANERS:

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2017-07-05 11:26:11 |
| Inspection Date: | 2009-06-17 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/04/2027 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2000-03-02 07:57:03 |
| Inspection Date: | 2012-06-20 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2017-07-05 11:26:11 |
| Inspection Date: | 2012-06-20 08:00:00 |
| Install Date: | Not reported |

**CHATSWORTH CLEANERS INC (Continued)** **1000890429**

| | |
|---|---|
| Expiration Date: | 07/04/2027 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2000-03-02 07:57:03 |
| Inspection Date: | 2010-06-16 07:30:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2017-07-05 11:26:11 |
| Inspection Date: | 2010-06-16 07:30:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/04/2027 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2000-03-02 07:57:03 |
| Inspection Date: | 2011-06-20 07:30:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |

**CHATSWORTH CLEANERS INC (Continued)** **1000890429**

| | |
|---|---|
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2017-07-05 11:26:11 |
| Inspection Date: | 2011-06-20 07:30:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/04/2027 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2000-03-02 07:57:03 |
| Inspection Date: | 2014-06-25 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2017-07-05 11:26:11 |
| Inspection Date: | 2014-06-25 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/04/2027 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2000-03-02 07:57:03 |
| Inspection Date: | 2013-06-28 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |

**CHATSWORTH CLEANERS INC (Continued)** **1000890429**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: CHATSWORTH CLEANERS INC
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347203
Region: Not reported
Registration Effective Date: 2017-07-05 11:26:11
Inspection Date: 2013-06-28 08:00:00
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: CHATSWORTH CLEANERS INC
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347203
Region: Not reported
Registration Effective Date: 2000-03-02 07:57:03
Inspection Date: 2015-06-24 08:00:00
Install Date: Not reported
Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: CHATSWORTH CLEANERS INC
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347203
Region: Not reported
Registration Effective Date: 2017-07-05 11:26:11
Inspection Date: 2015-06-24 08:00:00
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: CHATSWORTH CLEANERS INC
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305

**CHATSWORTH CLEANERS INC (Continued)** **1000890429**

| | |
|---|---|
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2000-03-02 07:57:03 |
| Inspection Date: | 2016-06-22 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2017-07-05 11:26:11 |
| Inspection Date: | 2016-06-22 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/04/2027 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2000-03-02 07:57:03 |
| Inspection Date: | 2002-07-10 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2017-07-05 11:26:11 |
| Inspection Date: | 2002-07-10 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/04/2027 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |

**CHATSWORTH CLEANERS INC (Continued)** **1000890429**

Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: CHATSWORTH CLEANERS INC
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347203
Region: Not reported
Registration Effective Date: 2000-03-02 07:57:03
Inspection Date: 2009-06-17 08:00:00
Install Date: Not reported
Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: CHATSWORTH CLEANERS INC
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347203
Region: Not reported
Registration Effective Date: 2017-07-05 11:26:11
Inspection Date: 2008-06-19 08:00:00
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: CHATSWORTH CLEANERS INC
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347203
Region: Not reported
Registration Effective Date: 2000-03-02 07:57:03
Inspection Date: 2008-06-19 08:00:00
Install Date: Not reported
Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: CHATSWORTH CLEANERS INC
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347203
Region: Not reported

**CHATSWORTH CLEANERS INC (Continued)** **1000890429**

| | |
|---|---|
| Registration Effective Date: | 2017-07-05 11:26:11 |
| Inspection Date: | 2007-06-20 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/04/2027 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2000-03-02 07:57:03 |
| Inspection Date: | 2007-06-20 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2017-07-05 11:26:11 |
| Inspection Date: | 2006-06-21 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/04/2027 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2000-03-02 07:57:03 |
| Inspection Date: | 2006-06-21 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

**CHATSWORTH CLEANERS INC (Continued)** **1000890429**

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2017-07-05 11:26:11 |
| Inspection Date: | 2005-06-23 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/04/2027 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2000-03-02 07:57:03 |
| Inspection Date: | 2005-06-23 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2017-07-05 11:26:11 |
| Inspection Date: | 2004-06-30 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/04/2027 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2000-03-02 07:57:03 |
| Inspection Date: | 2004-06-30 08:00:00 |
| Install Date: | Not reported |

**CHATSWORTH CLEANERS INC (Continued)** **1000890429**

| | |
|---|---|
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2017-07-05 11:26:11 |
| Inspection Date: | 2003-07-02 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/04/2027 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2000-03-02 07:57:03 |
| Inspection Date: | 2001-07-12 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2017-07-05 11:26:11 |
| Inspection Date: | 2001-07-12 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/04/2027 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | CHATSWORTH CLEANERS INC |
| Address: | 120 CHATSWORTH AVE |

**CHATSWORTH CLEANERS INC (Continued)** **1000890429**

| | |
|---|---|
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347203 |
| Region: | Not reported |
| Registration Effective Date: | 2000-03-02 07:57:03 |
| Inspection Date: | 2003-07-02 08:00:00 |
| Install Date: | Not reported |
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

NY MANIFEST:

| | |
|---|---|
| Name: | CHATSWORTH CLNRS |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538-2901 |
| Country: | USA |
| EPA ID: | NY0000363101 |
| Facility Status: | Not reported |
| Location Address 1: | 120 CHATSWORTH AVE |
| Code: | BP |
| Location Address 2: | Not reported |
| Total Tanks: | Not reported |
| Location City: | LARCHMONT |
| Location State: | NY |
| Location Zip: | 10538 |
| Location Zip 4: | Not reported |

NY MANIFEST:

| | |
|---|---|
| EPAID: | NY0000363101 |
| Mailing Name: | CHATSWORTH CLNRS |
| Mailing Contact: | YOUNG KIM |
| Mailing Address 1: | 120 CHATSWORTH AVE |
| Mailing Address 2: | Not reported |
| Mailing City: | LARCHMONT |
| Mailing State: | NY |
| Mailing Zip: | 10538 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 9148347203 |

NY MANIFEST:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| seq: | Not reported |
| Year: | 2018 |
| Trans1 State ID: | TXR000050930 |
| Trans2 State ID: | MOD095038998 |
| Generator Ship Date: | 08/31/2006 |
| Trans1 Recv Date: | 08/31/2006 |
| Trans2 Recv Date: | 09/12/2006 |
| TSD Site Recv Date: | 09/13/2006 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000363101 |

**CHATSWORTH CLEANERS INC (Continued)** **1000890429**

| | |
|---|---|
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | NYC7849440 |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Quantity: | 300 |
| Units: | P - Pounds |
| Number of Containers: | 2 |
| Container Type: | DF - Fiberboard or plastic drums (glass) |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 1 |
| Waste Code: | F002 |
| Waste Code 1_2: | Not reported |
| Waste Code 1_3: | Not reported |
| Waste Code 1_4: | Not reported |
| Waste Code 1_5: | Not reported |
| Waste Code 1_6: | Not reported |

---

**J39** **VERIZON NEW YORK INC. (NY96242)** **NY UST** **U004334169**
**South** **5 FRANKLIN AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.186 mi.**
**980 ft.** **Site 1 of 3 in cluster J**

**Relative:** NY UST:
**Higher** No Details: No Details

**Actual:**
**57 ft.**

**J40** **BELL ATLANTIC** **NY LTANKS** **U003648326**
**South** **5 FRANKLIN ST** **NY Spills** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.186 mi.**
**980 ft.** **Site 2 of 3 in cluster J**

**Relative:**
**Higher**

**Actual:**
**57 ft.**

LTANKS:

| | |
|---|---|
| Name: | BELL ATLANTIC |
| Address: | 5 FRANKLIN ST |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9810030 / 1998-11-09 |
| Facility ID: | 9810030 |
| Site ID: | 245767 |
| Spill Date: | 1998-11-06 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1998-11-09 |
| CID: | 281 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-11-09 |
| Spill Record Last Update: | 1998-11-20 |
| Spiller Name: | Not reported |
| Spiller Company: | CASTLE FUELS |
| Spiller Address: | UNKNOWN |
| Spiller County: | 001 |
| Spiller Contact: | JANE ARMSTRONG |
| Spiller Phone: | (914) 834-9994 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 201824 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: | "CALLER RESPONDED TO ABOVE LOCATION FOR CLEANUP OF ABOVE MATERIAL. MATERIAL HAS BEEN CONTAINED AND CLEANUP EXPECTED TO BE COMPLETED THIS DATE. SPILL CAUSE IS TANK OVERFILL BY OIL COMPANY. NO FURTHER INFO ON OIL COMPANY AT THIS TIME. NO CALL BACK REQUESTED." |

All Materials:

| | |
|---|---|
| Site ID: | 245767 |
| Operable Unit ID: | 1067301 |
| Operable Unit: | 01 |
| Material ID: | 313917 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 50.00 |
| Units: | G |
| Recovered: | .00 |

**BELL ATLANTIC (Continued)** **U003648326**

Oxygenate: Not reported

SPILLS:

| | |
|---|---|
| Name: | BELL ATLANTIC |
| Address: | 5 FRANKLIN AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9712641 / 1998-02-18 |
| Facility ID: | 9712641 |
| Facility Type: | ER |
| DER Facility ID: | 139540 |
| Site ID: | 165557 |
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | C4 |
| SWIS: | 6000 |
| Spill Date: | 1998-02-11 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1998-02-11 |
| CID: | 252 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-02-11 |
| Spill Record Last Update: | 2003-08-27 |
| Spiller Name: | UNK |
| Spiller Company: | CASTLE FUEL OIL CO |
| Spiller Address: | 290 LOCUST AVE |
| Spiller Company: | 001 |
| Contact Name: | FARNK YAZZETTA |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 02/18/98 C.BADOLATO; OIL IN BASEMENT; CLEANED BY COOK CO. NO OIL ON FLOOR OF TANK ROOM; NO DRAINS IN ROOM; " |
| Remarks: | "SPILL HAS BEEN CONTAINED-WILL MAKE THEIR OWN ARRANGEMENTS FOR CLEANUP" |

All Materials:

| | |
|---|---|
| Site ID: | 165557 |
| Operable Unit ID: | 1055509 |
| Operable Unit: | 01 |
| Material ID: | 327241 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 200.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**BELL ATLANTIC (Continued)** **U003648326**

| | |
|---|---|
| Name: | SPILL NUMBER 9811748 |
| Address: | 5 FRANKLIN AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9811748 / 1998-12-23 |
| Facility ID: | 9811748 |
| Facility Type: | ER |
| DER Facility ID: | 139540 |
| Site ID: | 165558 |
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | C4 |
| SWIS: | 6000 |
| Spill Date: | 1998-12-17 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1998-12-17 |
| CID: | 322 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-12-17 |
| Spill Record Last Update: | 1999-01-20 |
| Spiller Name: | FRANK |
| Spiller Company: | BELL ATLANTIC |
| Spiller Address: | 5 FRANKLIN AVE |
| Spiller Company: | 001 |
| Contact Name: | FRANK YAZZETTA |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: | "Defective high level alarm caused spill - chemtel was hired to do clean up " |

All Materials:

| | |
|---|---|
| Site ID: | 165558 |
| Operable Unit ID: | 1072541 |
| Operable Unit: | 01 |
| Material ID: | 312034 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1000.00 |
| Units: | G |
| Recovered: | 1000.00 |
| Oxygenate: | Not reported |

**41**
**East**
**1/8-1/4**
**0.187 mi.**
**989 ft.**

**LARCHMONT PALMER**
**1299 PALMER AVENUE**
**MAMARONECK, NY 10538**

**NY UST** **U003994687**
**NY AST** **N/A**

**Relative:**
**Higher**

**Actual:**
**47 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | LARCHMONT PALMER |
| Address: | 1299 PALMER AVENUE |
| City,State,Zip: | MAMARONECK, NY 10538 |
| Id/Status: | 3-504467 / Active |
| Operator Name: | Larchmont Palmer Owners, Inc. |
| Owner Name: | Larchmont Palmer Owners, Inc. |
| Owner Street: | 1299 Palmer Avenue |
| Owner Address2: | Not reported |
| Owner City: | Larchmont |
| Owner State: | NY |
| Owner Zipcode: | 10538 |
| GDS Number: | Not reported |
| | |
| Tank Number: | 001 |
| Status: | 3a. Closed - Prior to 04/1991 |
| Capacity: | 10000 |
| Product Stored: | 0003. #6 Fuel Oil |
| Product Stored Percent: | 0 |
| Tank Leak Detection: | 0. None |
| Date Installation: | 01/01/1900 |
| Date Perm Closure: | 09/01/1990 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 1. Epoxy liner |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | Not reported |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | Not reported |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 2. Suction |
| | |
| Tank Number: | 002 |
| Status: | 3. Closed - Removed |
| Capacity: | 10000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | 0 |
| Tank Leak Detection: | 2. Manual Interstitial Monitoring |
| Date Installation: | 09/01/1990 |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 2. Original sacrificial anode |
| Tank Secondary Containment: | 4. Double-Walled (underground only) |
| Piping Location: | 2. Underground/on ground |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 2. Original sacrificial anode |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only) |

**LARCHMONT PALMER (Continued)** **U003994687**

Piping Secondary Containment: Not reported
Spill Prevention: 1. Catch Basin
Dispenser: 2. Suction

WESTCHESTER CO. AST:
Name: LARCHMONT PALMER
Address: 1299 PALMER AVENUE
City,State,Zip: MAMARONECK, NY 10538
PBS Number: 3-504467
Site Status: Active
GDS Number: Not reported
Operator Name: Larchmont Palmer Owners, Inc.
Owner Name: Larchmont Palmer Owners, Inc.
Owner Street: 1299 Palmer Avenue
Owner Address2: Not reported
Owner City/State/Zip: Larchmont, NY 10538

Tank Number: 003
Status: 1. In-Service
Date Installation: 12/07/2010
Capacity: 7000
Product Stored: 0001. #2 Fuel Oil
Product Stored Percent: 0
Date Perm Closure: 01/01/1900
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating
Tank Leak Detection: 6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment: 2. Vault (w/ access)
Piping Location: 1. Aboveground
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 1. Painted/Asphalt Coating
Piping Leak Detection: Not reported
Piping Secondary Containment: Not reported
Overfill Prevention: 4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention: 1. Catch Basin
Dispenser: 2. Suction

---

**K42** **CHATSWORTH GARDENS CONDO** **NY AST** **A100276647**
**WSW** **14 NORTH CHATSWORTH AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.191 mi.**
**1011 ft.** **Site 1 of 6 in cluster K**

**Relative:**
**Higher**

**Actual:**
**48 ft.**

WESTCHESTER CO. AST:
Name: CHATSWORTH GARDENS CONDO
Address: 14 NORTH CHATSWORTH AVENUE
City,State,Zip: LARCHMONT, NY 10538
PBS Number: 3-506788
Site Status: Active
GDS Number: Not reported
Operator Name: Chatsworth Gardens Condo
Owner Name: Chatsworth Gardens Condo
Owner Street: 14 North Chatsworth Avenue
Owner Address2: Not reported
Owner City/State/Zip: Larchmont, NY 10538

**CHATSWORTH GARDENS CONDO (Continued)** **A100276647**

| | |
|---|---|
| Tank Number: | 1 |
| Status: | 1. In-Service |
| Date Installation: | 01/01/1928 |
| Capacity: | 5000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 1. Aboveground (contact w/ soil) |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 1. Epoxy liner |
| Tank External Protection: | 0. None |
| Tank Leak Detection: | 4. Groundwater Well |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 3. Aboveground/Underground Combination |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | Not reported |
| Piping Secondary Containment: | Not reported |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 2 |
| Status: | 1. In-Service |
| Date Installation: | 01/01/1928 |
| Capacity: | 1500 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 1. Aboveground (contact w/ soil) |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 1. Epoxy liner |
| Tank External Protection: | 0. None |
| Tank Leak Detection: | 4. Groundwater Well |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 3. Aboveground/Underground Combination |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | Not reported |
| Piping Secondary Containment: | Not reported |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 3 |
| Status: | 1. In-Service |
| Date Installation: | 01/01/1958 |
| Capacity: | 275 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 1. Aboveground (contact w/ soil) |
| Tank Type: | Not reported |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |

**CHATSWORTH GARDENS CONDO (Continued)** **A100276647**

| | |
|---|---|
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | Not reported |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 0. None |
| Piping Leak Detection: | Not reported |
| Piping Secondary Containment: | Not reported |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 4 |
| Status: | 1. In-Service |
| Date Installation: | 01/01/1958 |
| Capacity: | 275 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 1. Aboveground (contact w/ soil) |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | Not reported |
| Piping Location: | Not reported |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 0. None |
| Piping Leak Detection: | Not reported |
| Piping Secondary Containment: | Not reported |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 2. Suction |

---

**I43** **EMBASSY CLEANERS** **RCRA NonGen / NLR** **1000158278**
**South** **1908 PALMER AVE** **US AIRS** **NYD012815395**
**1/8-1/4** **LARCHMONT, NY 10538** **NY MANIFEST**
**0.192 mi.**
**1013 ft.** **Site 5 of 7 in cluster I**

**Relative:** **Higher**
**Actual:** **59 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20070101 |
| Handler Name: | EMBASSY CLEANERS | |
| Handler Address: | | 1908 PALMER AVE |
| Handler City,State,Zip: | | LARCHMONT, NY 10538-2408 |
| EPA ID: | | NYD012815395 |
| Contact Name: | | Not reported |
| Contact Address: | | PALMER AVE |
| Contact City,State,Zip: | | LARCHMONT, NY 10538 |
| Contact Telephone: | | Not reported |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |

**EMBASSY CLEANERS (Continued)** **1000158278**

| | | |
|---|---|---|
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | NY |
| State District: | | NYSDEC R3 |
| Mailing Address: | | PALMER AVE |
| Mailing City,State,Zip: | | LARCHMONT, NY 10538 |
| Owner Name: | OWNERNAME | |
| Owner Type: | | Private |
| Operator Name: | OWNERNAME | |
| Operator Type: | | Private |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site Fed-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site Converter Treatment storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| Commercial TSD Indicator: | | No |
| Treatment Storage and Disposal Type: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| Permit Renewals Workload Universe: | | Not reported |
| Permit Workload Universe: | | Not reported |
| Permit Progress Universe: | | Not reported |
| Post-Closure Workload Universe: | | Not reported |
| Closure Workload Universe: | | Not reported |
| 202 GPRA Corrective Action Baseline: | | No |
| Corrective Action Workload Universe: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: | | No |
| TSDFs Only Subject to CA under Discretionary Auth Universe: | | No |
| Corrective Action Priority Ranking: | | No NCAPS ranking |
| Environmental Control Indicator: | | No |
| Institutional Control Indicator: | | No |
| Human Exposure Controls Indicator: | | N/A |
| Groundwater Controls Indicator: | | N/A |
| Operating TSDF Universe: | | Not reported |
| Full Enforcement Universe: | | Not reported |
| Significant Non-Complier Universe: | | No |
| Unaddressed Significant Non-Complier Universe: | | No |
| Addressed Significant Non-Complier Universe: | | No |
| Significant Non-Complier With a Compliance Schedule Universe: | | No |
| Financial Assurance Required: | Not reported | |

**EMBASSY CLEANERS (Continued)** **1000158278**

| | |
|---|---|
| Handler Date of Last Change: | 20150414 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | F002 |
| Waste Description: | THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES. |

Handler - Owner Operator:

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: OWNERNAME | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | NOT REQUIRED |
| Owner/Operator City,State,Zip: | NOT REQUIRED, WY 99999 |
| Owner/Operator Telephone: | 212-555-1212 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: OWNERNAME | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | NOT REQUIRED |
| Owner/Operator City,State,Zip: | NOT REQUIRED, WY 99999 |
| Owner/Operator Telephone: | 212-555-1212 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

| | |
|---|---|
| Owner/Operator Indicator: | Operator |
| Owner/Operator Name: OWNERNAME | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | NOT REQUIRED |
| Owner/Operator City,State,Zip: | NOT REQUIRED, WY 99999 |
| Owner/Operator Telephone: | 212-555-1212 |
| Owner/Operator Telephone Ext: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000158278**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990708
Handler Name: EMBASSY CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: EMBASSY CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: EMBASSY CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19850506
Handler Name: EMBASSY CLEANERS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

**EMBASSY CLEANERS (Continued)** **1000158278**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

US AIRS MINOR:
Envid: 1000158278
Region Code: 02
Programmatic ID: AIR NY0000003553200189
Facility Registry ID: 110004345361
D and B Number: Not reported
Primary SIC Code: 7212
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000003553200189
Facility Registry ID: 110004345361
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1997-06-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200189
Facility Registry ID: 110004345361
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-12-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200189
Facility Registry ID: 110004345361
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-08-05 00:00:00
Activity Status Date: 2002-08-05 00:00:00

**EMBASSY CLEANERS (Continued)** **1000158278**

Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000003553200189
Facility Registry ID: 110004345361
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-07-11 00:00:00
Activity Status Date: 2008-07-11 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000003553200189
Facility Registry ID: 110004345361
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-12-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200189
Facility Registry ID: 110004345361
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-08-05 00:00:00
Activity Status Date: 2002-08-05 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

NY MANIFEST:
Name: EMBASSY CLEANERS
Address: 1908 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538-2408
Country: USA
EPA ID: NYD012815395
Facility Status: Not reported
Location Address 1: 120 CHATSWORTH AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: LARCHMONT
Location State: NY
Location Zip: 10538
Location Zip 4: Not reported

**EMBASSY CLEANERS (Continued)** **1000158278**

NY MANIFEST:

| | |
|---|---|
| EPAID: | NYD012815395 |
| Mailing Name: | EMBASSY CLEANERS |
| Mailing Contact: | EMBASSY CLEANERS |
| Mailing Address 1: | 120 CHATSWORTH AVENUE |
| Mailing Address 2: | Not reported |
| Mailing City: | LARCHMONT |
| Mailing State: | NY |
| Mailing Zip: | 10538 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 9143342700 |

---

**I44** **EMBASSY CLEANERS** **NY DRYCLEANERS** **S110246512**
**South** **1908 PALMER AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.192 mi.**
**1013 ft.** **Site 6 of 7 in cluster I**

**Relative:**
**Higher**

**Actual:**
**59 ft.**

DRYCLEANERS:

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1908 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Facility ID: | 3-5532-00189 |
| Phone Number: | NOT LISTED |
| Region: | Not reported |
| Registration Effective Date: | N/A |
| Inspection Date: | 2016-01-07 00:00:00 |
| Install Date: | -/07 |
| Expiration Date: | Not reported |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Y |
| Alternate Solvent: | Not reported |
| Current Business: | Not reported |

---

**K45** **APARTMENT** **NY LTANKS** **S107410399**
**WSW** **16 NORTH CHATSWORTH AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.193 mi.**
**1020 ft.** **Site 2 of 6 in cluster K**

**Relative:**
**Higher**

**Actual:**
**48 ft.**

LTANKS:

| | |
|---|---|
| Name: | APARTMENT |
| Address: | 16 NORTH CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0506407 / 2005-11-27 |
| Facility ID: | 0506407 |
| Site ID: | 351623 |
| Spill Date: | 2005-08-24 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |

**APARTMENT (Continued)** **S107410399**

| | |
|---|---|
| Investigator: | WCHD |
| Referred To: | WCDOH |
| Reported to Dept: | 2005-08-24 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2005-08-24 |
| Spill Record Last Update: | 2006-03-08 |
| Spiller Name: | DWAYNE MONACO |
| Spiller Company: | APARTMENT |
| Spiller Address: | 16 NORTH CHASWORTH AVE |
| Spiller County: | 001 |
| Spiller Contact: | DWAYNE MONACO |
| Spiller Phone: | (914) 777-1930 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 298897 |
| DEC Memo: | "11/27/05 Spill closed by Fred Beck of the Westchester County Health Dept. No further action required. jod" |
| Remarks: | "6000 GALLON TANK HAD HOLES IN IT FOUND WHILE REMOVING: IN PROCESS OF BEING CLEANED UP:" |

All Materials:

| | |
|---|---|
| Site ID: | 351623 |
| Operable Unit ID: | 1109123 |
| Operable Unit: | 01 |
| Material ID: | 2099109 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**K46** **16 NORTH CHATSWORTH AVENUE CORP** **NY UST U004175921**
**WSW** **16 NORTH CHATSWORTH AVENUE** **NY AST N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.193 mi.**
**1020 ft.** **Site 3 of 6 in cluster K**

**Relative:**
**Higher**

**Actual:**
**48 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | 16 NORTH CHATSWORTH AVENUE CORP |
| Address: | 16 NORTH CHATSWORTH AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-167819 / Active |
| Operator Name: | Archer Property Management |
| Owner Name: | 16 North Chatsworth Ave Corp, c/o Archer Property |
| Owner Street: | 16 North Chatsworth Avenue |
| Owner Address2: | Not reported |
| Owner City: | Larchmont |

**16 NORTH CHATSWORTH AVENUE CORP (Continued)** **U004175921**

| | |
|---|---|
| Owner State: | NY |
| Owner Zipcode: | 10538 |
| GDS Number: | Not reported |
| | |
| Tank Number: | 016 |
| Status: | 3. Closed - Removed |
| Capacity: | 6000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 02/01/1972 |
| Date Perm Closure: | 09/01/2005 |
| Tank Location: | 6. Underground, vaulted, with access |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | Not reported |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |
| | |
| Tank Number: | 160 |
| Status: | 4. Closed - in place |
| Capacity: | 6000 |
| Product Stored: | 9999. Other |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 02/01/1972 |
| Date Perm Closure: | 07/01/1999 |
| Tank Location: | 6. Underground, vaulted, with access |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | Not reported |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 2. Suction |

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | 16 NORTH CHATSWORTH AVENUE CORP |
| Address: | 16 NORTH CHATSWORTH AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-167819 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | Archer Property Management |
| Owner Name: | 16 North Chatsworth Ave Corp, c/o Archer Property |
| Owner Street: | 16 North Chatsworth Avenue |

**16 NORTH CHATSWORTH AVENUE CORP (Continued)** **U004175921**

| | |
|---|---|
| Owner Address2: | Not reported |
| Owner City/State/Zip: | Larchmont, NY 10538 |
| | |
| Tank Number: | 01 |
| Status: | 1. In-Service |
| Date Installation: | 09/01/2005 |
| Capacity: | 5500 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 0. None |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 5. Vent Whistle |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

---

**K47** **CON EDISON** **NY MANIFEST** **S117535866**
**WSW** **CHATSWORTH AVE & WASHINGTON SQ** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.195 mi.**
**1032 ft.** **Site 4 of 6 in cluster K**

**Relative:**
**Higher**

**Actual:**
**48 ft.**

NY MANIFEST:

| | |
|---|---|
| Name: | CON EDISON |
| Address: | CHATSWORTH AVE & WASHINGTON SQ |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Country: | USA |
| EPA ID: | NYP004682852 |
| Facility Status: | Not reported |
| Location Address 1: | CHATSWORTH AVE & WASHINGTON SQ |
| Code: | BP |
| Location Address 2: | SB232 |
| Total Tanks: | Not reported |
| Location City: | LARCHMONT |
| Location State: | NY |
| Location Zip: | 10538 |
| Location Zip 4: | Not reported |

NY MANIFEST:

| | |
|---|---|
| EPAID: | NYP004682852 |
| Mailing Name: | CON EDISON |
| Mailing Contact: | CON EDISON |
| Mailing Address 1: | 4 IRVING PL |
| Mailing Address 2: | 15TH FLOOR |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |

**CON EDISON (Continued)** **S117535866**

Mailing Phone: Not reported

NY MANIFEST:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| seq: | Not reported |
| Year: | 2018 |
| Trans1 State ID: | NYD006982359 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 10/23/2014 |
| Trans1 Recv Date: | 10/23/2014 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 10/24/2014 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004682852 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD002200046 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 012773175JJK |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H110 |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Quantity: | 85 |
| Units: | P - Pounds |
| Number of Containers: | 1 |
| Container Type: | TT - Cargo tank, tank trucks |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Waste Code: | D008 |
| Waste Code 1_2: | Not reported |
| Waste Code 1_3: | Not reported |
| Waste Code 1_4: | Not reported |
| Waste Code 1_5: | Not reported |
| Waste Code 1_6: | Not reported |

**K48** **CONSOLIDATED EDISON TM4093** **NY MANIFEST** **1009241052**
**WSW** **WASHINGTON & N CHATSWORTH** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.195 mi.**
**1032 ft.** **Site 5 of 6 in cluster K**

**Relative:**
**Higher**

**Actual:**
**48 ft.**

NY MANIFEST:

| | |
|---|---|
| Name: | CONSOLIDATED EDISON TM4093 |
| Address: | WASHINGTON & N CHATSWORTH |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Country: | USA |
| EPA ID: | NYP004093696 |
| Facility Status: | Not reported |
| Location Address 1: | WASHINGTON & N CHATSWORTH |
| Code: | BP |
| Location Address 2: | Not reported |
| Total Tanks: | Not reported |
| Location City: | LARCHMONT |
| Location State: | NY |
| Location Zip: | 10538 |
| Location Zip 4: | Not reported |

NY MANIFEST:

| | |
|---|---|
| EPAID: | NYP004093696 |
| Mailing Name: | CONSOLIDATED EDISON TM4093 |
| Mailing Contact: | FRANKLIN MURRAY |
| Mailing Address 1: | 4 IRVING PLACE RM 828 |
| Mailing Address 2: | Not reported |
| Mailing City: | NEW YORK |
| Mailing State: | NY |
| Mailing Zip: | 10003 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 2124602808 |

---

**J49** **06-D3M DOM'S CAR CARE** **RCRA-LQG** **1000553397**
**South** **107 CHATSWORTH** **FINDS** **NYD986958171**
**1/8-1/4** **LARCHMONT, NY 10538** **ECHO**
**0.196 mi.** **NY MANIFEST**
**1033 ft.** **Site 3 of 3 in cluster J**

**Relative:**
**Higher**

**Actual:**
**57 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20070101 |
| Handler Name: | MOBIL OIL CORP SS D3M | |
| Handler Address: | | 107 CHATSWORTH AVE |
| Handler City,State,Zip: | | LARCHMONT, NY 10538-2923 |
| EPA ID: | | NYD986958171 |
| Contact Name: | | Not reported |
| Contact Address: | | GALLOWS RD - MKTG ENVIRON |
| Contact City,State,Zip: | | FAIRFAX, NY 22037 |
| Contact Telephone: | | Not reported |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Large Quantity Generator |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |

**06-D3M DOM'S CAR CARE (Continued)** **1000553397**

| | | |
|---|---|---|
| Accessibility: | | Not reported |
| Active Site Indicator: | | Handler Activities |
| State District Owner: | | NY |
| State District: | | NYSDEC R3 |
| Mailing Address: | | GALLOWS RD - MKTG ENVIRON |
| Mailing City,State,Zip: | | FAIRFAX, NY 22037 |
| Owner Name: | MOBIL OIL CORP | |
| Owner Type: | | Private |
| Operator Name: | MOBIL OIL CORP | |
| Operator Type: | | Private |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site Fed-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site Converter Treatment storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | NN |
| Sub-Part K Indicator: | | Not reported |
| Commercial TSD Indicator: | | No |
| Treatment Storage and Disposal Type: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| Permit Renewals Workload Universe: | | Not reported |
| Permit Workload Universe: | | Not reported |
| Permit Progress Universe: | | Not reported |
| Post-Closure Workload Universe: | | Not reported |
| Closure Workload Universe: | | Not reported |
| 202 GPRA Corrective Action Baseline: | | No |
| Corrective Action Workload Universe: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: | | No |
| TSDFs Only Subject to CA under Discretionary Auth Universe: | | No |
| Corrective Action Priority Ranking: | | No NCAPS ranking |
| Environmental Control Indicator: | | No |
| Institutional Control Indicator: | | No |
| Human Exposure Controls Indicator: | | N/A |
| Groundwater Controls Indicator: | | N/A |
| Operating TSDF Universe: | | Not reported |
| Full Enforcement Universe: | | Not reported |
| Significant Non-Complier Universe: | | No |
| Unaddressed Significant Non-Complier Universe: | | No |
| Addressed Significant Non-Complier Universe: | | No |
| Significant Non-Complier With a Compliance Schedule Universe: | | No |
| Financial Assurance Required: | Not reported | |

**06-D3M DOM'S CAR CARE (Continued)** **1000553397**

| | |
|---|---|
| Handler Date of Last Change: | 20150414 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | Not reported |
| Manifest Broker: | Not reported |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | D000 |
| Waste Description: | Not Defined |
| Waste Code: | D001 |
| Waste Description: | IGNITABLE WASTE |
| Waste Code: | D008 |
| Waste Description: | LEAD |

Handler - Owner Operator:

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: MOBIL OIL CORP | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 3225 GALLOWS RD |
| Owner/Operator City,State,Zip: | FAIRFAX, VA 22037 |
| Owner/Operator Telephone: | 703-849-3330 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |
| Owner/Operator Indicator: | Operator |
| Owner/Operator Name: MOBIL OIL CORP | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 3225 GALLOWS RD |
| Owner/Operator City,State,Zip: | FAIRFAX, VA 22037 |
| Owner/Operator Telephone: | 703-849-3330 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: MOBIL OIL CORP | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 3225 GALLOWS RD |
| Owner/Operator City,State,Zip: | FAIRFAX, VA 22037 |
| Owner/Operator Telephone: | 703-849-3330 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

**06-D3M DOM'S CAR CARE (Continued)** **1000553397**

Historic Generators:

| | |
|---|---|
| Receive Date: | 19990708 |
| Handler Name: MOBIL OIL CORP SS D3M | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20060101 |
| Handler Name: MOBIL OIL CORP SS D3M | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20070101 |
| Handler Name: MOBIL OIL CORP SS D3M | |
| Federal Waste Generator Description: | Large Quantity Generator |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 19910410 |
| Handler Name: MOBIL OIL CORP SS D3M | |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

List of NAICS Codes and Descriptions:

| | |
|---|---|
| NAICS Codes: | No NAICS Codes Found |

**06-D3M DOM'S CAR CARE (Continued)** **1000553397**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110019560606

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
Registry ID: 110004469708

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

| | |
|---|---|
| Envid: | 1000553397 |
| Registry ID: | 110004469708 |
| DFR URL: | http://echo.epa.gov/detailed-facility-report?fid=110004469708 |
| Name: | MOBIL OIL CORP SS D3M |
| Address: | 107 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |

NY MANIFEST:

| | |
|---|---|
| Name: | MOBIL OIL CORP SS D3M - FORMER DOM'S AUTO CARE CENTER |
| Address: | 107 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538-2923 |
| Country: | USA |
| EPA ID: | NYD986958171 |
| Facility Status: | Not reported |
| Location Address 1: | 107 CHATSWORTH AVE |
| Code: | BP |
| Location Address 2: | Not reported |
| Total Tanks: | Not reported |
| Location City: | LARCHMONT |
| Location State: | NY |
| Location Zip: | 10538 |
| Location Zip 4: | Not reported |

NY MANIFEST:
EPAID: NYD986958171

**06-D3M DOM'S CAR CARE (Continued)** **1000553397**

| | |
|---|---|
| Mailing Name: | MOBIL OIL CORP SS D3M - FORMER DOM'S AUTO CARE CENTER |
| Mailing Contact: | MOBIL OIL CORP SS D3M - FORMER DOM'S AUTO CARE CENTER |
| Mailing Address 1: | 107 CHATSWORTH AVE |
| Mailing Address 2: | Not reported |
| Mailing City: | LARCHMONT |
| Mailing State: | NY |
| Mailing Zip: | 10538 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 9326131660 |

NY MANIFEST:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| seq: | Not reported |
| Year: | 2018 |
| Trans1 State ID: | NJD986607380 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 12/18/2006 |
| Trans1 Recv Date: | 12/18/2006 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/20/2006 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986958171 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD002200046 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 000307005FLE |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H061 |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Quantity: | 330 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 6 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | B Incineration, heat recovery, burning. |
| Specific Gravity: | 1 |
| Waste Code: | D001 |
| Waste Code 1_2: | D018 |
| Waste Code 1_3: | Not reported |
| Waste Code 1_4: | Not reported |

**06-D3M DOM'S CAR CARE (Continued)** **1000553397**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

---

**K50** **LARCHMONT HILLS OWNERS, CORP.** **NY AST** **A100276756**
**WSW** **17 NORTH CHATSWORTH AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.198 mi.**
**1045 ft.** **Site 6 of 6 in cluster K**

**Relative:** **Higher**
**Actual:** **48 ft.**

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | LARCHMONT HILLS OWNERS, CORP. |
| Address: | 17 NORTH CHATSWORTH AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-048488 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | Larchmont Hills Owners, Corp. |
| Owner Name: | Larchmont Hills Owners Corp. |
| Owner Street: | 17 North Chatsworth Avenue |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | Larchmont, NY 10538 |
| | |
| Tank Number: | 17 |
| Status: | 3. Closed - Removed |
| Date Installation: | 05/01/1948 |
| Capacity: | 5000 |
| Product Stored: | 0002. #4 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 04/21/2021 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | 2. Vault (w/ access) |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |
| | |
| Tank Number: | 18 |
| Status: | 1. In-Service |
| Date Installation: | 07/02/2021 |
| Capacity: | 3500 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | Not reported |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 5. In-Tank System (auto tank gauge),6. Impervious Barrier/Concrete Pad (Aboveground Only) |

**LARCHMONT HILLS OWNERS, CORP. (Continued)** **A100276756**

| | |
|---|---|
| Tank Secondary Containment: | 2. Vault (w/ access) |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | Not reported |
| Piping Secondary Containment: | Not reported |
| Overfill Prevention: | 2. High Level Alarm,4. Product Level Gauge (Aboveground Only) |
| Spill Prevention: | Not reported |
| Dispenser: | Not reported |

---

**51**
**ESE**
**1/8-1/4**
**0.201 mi.**
**1060 ft.**

**CON EDISON POLE W10**
**HALL AVE & CONCORD AVE**
**LARCHMONT, NY 10538**

**RCRA NonGen / NLR** **1010327190**
**NY MANIFEST** **NYP004145074**

**Relative:**
**Lower**

**Actual:**
**35 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20070111 |
| Handler Name: | CON EDISON POLE W10 | |
| Handler Address: | | HALL AVE & CONCORD AVE |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYP004145074 |
| Contact Name: | | MICHAEL D'AGOSTINO |
| Contact Address: | | IRVING PL RM 828 |
| Contact City,State,Zip: | | NEW YORK, NY 10003 |
| Contact Telephone: | | 212-580-8383 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | NY |
| State District: | | NYSDEC R3 |
| Mailing Address: | | IRVING PL RM 828 |
| Mailing City,State,Zip: | | NEW YORK, NY 10003 |
| Owner Name: | Not reported | |
| Owner Type: | | Not reported |
| Operator Name: | Not reported | |
| Operator Type: | | Not reported |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site Fed-Reg Treatment Storage and Disposal Facility: | | Not reported |

**CON EDISON POLE W10 (Continued)** **1010327190**

| | |
|---|---|
| Active Site Converter Treatment storage and Disposal Facility: | Not reported |
| Active Site State-Reg Treatment Storage and Disposal Facility: | Not reported |
| Active Site State-Reg Handler: | --- |
| Federal Facility Indicator: | Not reported |
| Hazardous Secondary Material Indicator: | NN |
| Sub-Part K Indicator: | Not reported |
| Commercial TSD Indicator: | No |
| Treatment Storage and Disposal Type: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| Permit Renewals Workload Universe: | Not reported |
| Permit Workload Universe: | Not reported |
| Permit Progress Universe: | Not reported |
| Post-Closure Workload Universe: | Not reported |
| Closure Workload Universe: | Not reported |
| 202 GPRA Corrective Action Baseline: | No |
| Corrective Action Workload Universe: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: | No |
| TSDFs Only Subject to CA under Discretionary Auth Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Operating TSDF Universe: | Not reported |
| Full Enforcement Universe: | Not reported |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: Not reported | |
| Handler Date of Last Change: | 20150414 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | Not reported |
| Manifest Broker: | Not reported |
| Sub-Part P Indicator: | No |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20070109 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Not reported |
| State District Owner: | Not reported |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

**CON EDISON POLE W10 (Continued)** **1010327190**

| | |
|---|---|
| Receive Date: | 20070110 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Not reported |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20070111 |
| Handler Name: CON EDISON POLE W10 | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

| | |
|---|---|
| Name: | CONED |
| Address: | HALL AVE & CONCORD AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Country: | USA |
| EPA ID: | NYP004145074 |
| Facility Status: | Not reported |
| Location Address 1: | VANDENBURGH AVE & HALL AVE |
| Code: | BP |
| Location Address 2: | Not reported |
| Total Tanks: | Not reported |
| Location City: | LARCHMONT |
| Location State: | NY |
| Location Zip: | 10001 |
| Location Zip 4: | Not reported |

NY MANIFEST:

| | |
|---|---|
| EPAID: | NYP004145074 |
| Mailing Name: | CONED |
| Mailing Contact: | CONED |

**CON EDISON POLE W10 (Continued)** **1010327190**

| | |
|---|---|
| Mailing Address 1: | 31-01 20TH AVE |
| Mailing Address 2: | BLDG 136 |
| Mailing City: | ASTORIA |
| Mailing State: | NY |
| Mailing Zip: | 11105 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 7182044151 |

NY MANIFEST:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| seq: | Not reported |
| Year: | 2018 |
| Trans1 State ID: | NJD003812047 |
| Trans2 State ID: | NJD003812047 |
| Generator Ship Date: | 09/07/2006 |
| Trans1 Recv Date: | 09/07/2006 |
| Trans2 Recv Date: | 09/14/2006 |
| TSD Site Recv Date: | 09/18/2006 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004145074 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD077444263 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 000017408GBF |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H141 |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Quantity: | 70 |
| Units: | K - Kilograms (2.2 pounds) |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | L Landfill. |
| Specific Gravity: | 1 |
| Waste Code: | B007 |
| Waste Code 1_2: | Not reported |
| Waste Code 1_3: | Not reported |
| Waste Code 1_4: | Not reported |
| Waste Code 1_5: | Not reported |
| Waste Code 1_6: | Not reported |

**I52** **DUTCH GIRL PROFESSIONAL CLEANERS** **RCRA NonGen / NLR** **1000169418**
**South** **1912 PALMER AVE** **FINDS** **NYD106797061**
**1/8-1/4** **LARCHMONT, NY 10538** **ECHO**
**0.202 mi.**
**1064 ft.** **Site 7 of 7 in cluster I**

**Relative:** **Higher**

**Actual:** **59 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20070101 |
| Handler Name: | DUTCH GIRL PROFESSIONAL CLEANERS | |
| Handler Address: | | 1912 PALMER AVE |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYD106797061 |
| Contact Name: | | Not reported |
| Contact Address: | | PALMER AVE |
| Contact City,State,Zip: | | LARCHMONT, NY 10538 |
| Contact Telephone: | | Not reported |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | X |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | NY |
| State District: | | NYSDEC R3 |
| Mailing Address: | | PALMER AVE |
| Mailing City,State,Zip: | | LARCHMONT, NY 10538 |
| Owner Name: | TAMES HADDEN | |
| Owner Type: | | Private |
| Operator Name: | TAMES HADDEN | |
| Operator Type: | | Private |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site Fed-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site Converter Treatment storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| Commercial TSD Indicator: | | No |
| Treatment Storage and Disposal Type: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| Permit Renewals Workload Universe: | | Not reported |

**DUTCH GIRL PROFESSIONAL CLEANERS (Continued)** **1000169418**

| | |
|---|---|
| Permit Workload Universe: | Not reported |
| Permit Progress Universe: | Not reported |
| Post-Closure Workload Universe: | Not reported |
| Closure Workload Universe: | Not reported |
| 202 GPRA Corrective Action Baseline: | No |
| Corrective Action Workload Universe: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: | No |
| TSDFs Only Subject to CA under Discretionary Auth Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Operating TSDF Universe: | Not reported |
| Full Enforcement Universe: | Not reported |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: Not reported | |
| Handler Date of Last Change: | 20150414 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | NONE |
| Waste Description: | Not Defined |

Handler - Owner Operator:

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: TAMES HADDEN | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | NOT REQUIRED |
| Owner/Operator City,State,Zip: | NOT REQUIRED, WY 99999 |
| Owner/Operator Telephone: | 212-555-1212 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

| | |
|---|---|
| Owner/Operator Indicator: | Operator |
| Owner/Operator Name: TAMES HADDEN | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | NOT REQUIRED |
| Owner/Operator City,State,Zip: | NOT REQUIRED, WY 99999 |

**DUTCH GIRL PROFESSIONAL CLEANERS (Continued)** **1000169418**

Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TAMES HADDEN
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19791231
Handler Name: DUTCH GIRL PROFESSIONAL CLEANERS
Federal Waste Generator Description: Not reported
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: DUTCH GIRL PROFESSIONAL CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: DUTCH GIRL PROFESSIONAL CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

**DUTCH GIRL PROFESSIONAL CLEANERS (Continued)** **1000169418**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004379324

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

| | |
|---|---|
| Envid: | 1000169418 |
| Registry ID: | 110004379324 |
| DFR URL: | http://echo.epa.gov/detailed-facility-report?fid=110004379324 |
| Name: | DUTCH GIRL PROFESSIONAL CLEANERS |
| Address: | 1912 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |

---

**53**
**SSW**
**1/8-1/4**
**0.204 mi.**
**1076 ft.**

**DONALD RITACCO & CO LTD**
**7-11 NORTH AVE**
**LARCHMONT, NY 10538**

**RCRA NonGen / NLR** **1000148702**
**NY MANIFEST** **NYD982718249**

**Relative:**
**Higher**

**Actual:**
**51 ft.**

RCRA Listings:

| | |
|---|---|
| Date Form Received by Agency: | 20070101 |
| Handler Name: | DONALD RITACCO & CO LTD |
| Handler Address: | 7-11 NORTH AVE |
| Handler City,State,Zip: | LARCHMONT, NY 10538 |
| EPA ID: | NYD982718249 |
| Contact Name: | Not reported |
| Contact Address: | NORTH AVE |
| Contact City,State,Zip: | LARCHMONT, NY 10538 |
| Contact Telephone: | Not reported |
| Contact Fax: | Not reported |
| Contact Email: | Not reported |
| Contact Title: | Not reported |
| EPA Region: | 02 |
| Land Type: | Not reported |
| Federal Waste Generator Description: | Not a generator, verified |
| Non-Notifier: | Not reported |

**DONALD RITACCO & CO LTD (Continued)** **1000148702**

| | |
|---|---|
| Biennial Report Cycle: | Not reported |
| Accessibility: | Not reported |
| Active Site Indicator: | Not reported |
| State District Owner: | NY |
| State District: | NYSDEC R3 |
| Mailing Address: | NORTH AVE |
| Mailing City,State,Zip: | LARCHMONT, NY 10538 |
| Owner Name: | DONALD RITACCO KEYSTONE MGMT BLDG BUS |
| Owner Type: | Private |
| Operator Name: | DONALD RITACCO KEYSTONE MGMT BLDG BUS |
| Operator Type: | Private |
| Short-Term Generator Activity: | No |
| Importer Activity: | No |
| Mixed Waste Generator: | No |
| Transporter Activity: | No |
| Transfer Facility Activity: | No |
| Recycler Activity with Storage: | No |
| Small Quantity On-Site Burner Exemption: | No |
| Smelting Melting and Refining Furnace Exemption: | No |
| Underground Injection Control: | No |
| Off-Site Waste Receipt: | No |
| Universal Waste Indicator: | No |
| Universal Waste Destination Facility: | No |
| Federal Universal Waste: | No |
| Active Site Fed-Reg Treatment Storage and Disposal Facility: | Not reported |
| Active Site Converter Treatment storage and Disposal Facility: | Not reported |
| Active Site State-Reg Treatment Storage and Disposal Facility: | Not reported |
| Active Site State-Reg Handler: | --- |
| Federal Facility Indicator: | Not reported |
| Hazardous Secondary Material Indicator: | N |
| Sub-Part K Indicator: | Not reported |
| Commercial TSD Indicator: | No |
| Treatment Storage and Disposal Type: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| Permit Renewals Workload Universe: | Not reported |
| Permit Workload Universe: | Not reported |
| Permit Progress Universe: | Not reported |
| Post-Closure Workload Universe: | Not reported |
| Closure Workload Universe: | Not reported |
| 202 GPRA Corrective Action Baseline: | No |
| Corrective Action Workload Universe: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: | No |
| TSDFs Only Subject to CA under Discretionary Auth Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Operating TSDF Universe: | Not reported |
| Full Enforcement Universe: | Not reported |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |

**DONALD RITACCO & CO LTD (Continued)** **1000148702**

| | | |
|---|---|---|
| Financial Assurance Required: | Not reported | |
| Handler Date of Last Change: | | 20150414 |
| Recognized Trader-Importer: | | No |
| Recognized Trader-Exporter: | | No |
| Importer of Spent Lead Acid Batteries: | | No |
| Exporter of Spent Lead Acid Batteries: | | No |
| Recycler Activity Without Storage: | | No |
| Manifest Broker: | | No |
| Sub-Part P Indicator: | | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | D001 |
| Waste Description: | IGNITABLE WASTE |
| Waste Code: | F001 |
| Waste Description: | THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES. |
| Waste Code: | F002 |
| Waste Description: | THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES. |
| Waste Code: | F003 |
| Waste Description: | THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES. |
| Waste Code: | F005 |
| Waste Description: | THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES. |

**DONALD RITACCO & CO LTD (Continued)** **1000148702**

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: DONALD RITACCO KEYSTONE MGMT BLDG BUS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: DONALD RITACCO KEYSTONE MGMT BLDG BUS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DONALD RITACCO KEYSTONE MGMT BLDG BUS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: DONALD RITACCO & CO LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: DONALD RITACCO & CO LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No

**DONALD RITACCO & CO LTD (Continued)** **1000148702**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: DONALD RITACCO & CO LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19881208
Handler Name: DONALD RITACCO & CO LTD
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: DONALD RITTACCO COMPANY
Address: 7-11 NORTH AVE
City,State,Zip: LARCHMONT, NY 10538
Country: USA
EPA ID: NYD982718249
Facility Status: Not reported
Location Address 1: 7-11 NORTH AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported

**DONALD RITACCO & CO LTD (Continued)** **1000148702**

Location City: LARCHMONT
Location State: NY
Location Zip: 10538
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD982718249
Mailing Name: DONALD RITTACCO COMPANY
Mailing Contact: DONALD RITTACCO COMPANY
Mailing Address 1: 7-11 NORTH AVENUE
Mailing Address 2: Not reported
Mailing City: LARCHMONT
Mailing State: NY
Mailing Zip: 10538
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9148340441

---

**54** **172 MYRTLE BLVD. APT. CORP.** **NY AST** **A100252288**
**SW** **172 MYRTLE BOULEVARD** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.208 mi.**
**1099 ft.**

**Relative:**
**Higher**

**Actual:**
**47 ft.**

WESTCHESTER CO. AST:
Name: 172 MYRTLE BLVD. APT. CORP.
Address: 172 MYRTLE BOULEVARD
City,State,Zip: LARCHMONT, NY 10538
PBS Number: 3-800128
Site Status: Active
GDS Number: Not reported
Operator Name: 172 Myrtyle Blvd Apt Corp
Owner Name: 172 Myrtle Blvd. Apt. Corp.
Owner Street: 172 Myrtle Boulevard
Owner Address2: Not reported
Owner City/State/Zip: Larchmont, NY 10538

Tank Number: 1
Status: 1. In-Service
Date Installation: 07/01/1999
Capacity: 1500
Product Stored: 0001. #2 Fuel Oil
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 6. Aboveground in subterranean vault with access for inspections
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 1. Epoxy liner
Tank External Protection: 1. Painted/Asphalt Coating
Tank Leak Detection: 6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment: 2. Vault (w/ access)
Piping Location: 1. Aboveground
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 1. Painted/Asphalt Coating
Piping Leak Detection: 0. None
Piping Secondary Containment: 2. Vault (w/ access)
Overfill Prevention: 5. Vent Whistle
Spill Prevention: 1. Catch Basin

**172 MYRTLE BLVD. APT. CORP. (Continued)** **A100252288**

Dispenser: 3. Gravity

---

**55 SSW 1/8-1/4 0.215 mi. 1135 ft.** **LARCH REALTY CORP PROPERT** **NY LTANKS** **S100140337**
**1925 PALMER AVE** **N/A**
**LARCHMONT, NY**

**Relative: Higher**
**Actual: 57 ft.**

LTANKS:

| | |
|---|---|
| Name: | LARCH REALTY CORP PROPERT |
| Address: | 1925 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 8801114 / 1997-12-01 |
| Facility ID: | 8801114 |
| Site ID: | 108260 |
| Spill Date: | 1988-02-07 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | D1 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1988-03-08 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Affected Persons |
| Last Inspection: | 1988-12-14 |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1988-05-13 |
| Spill Record Last Update: | 2005-11-25 |
| Spiller Name: | Not reported |
| Spiller Company: | LARCH REALTY C/O TOMBACK |
| Spiller Address: | 37 CHURCH LANE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 95150 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : PROPERTY OWNER TESTED HIS OWN TANK. TANK WAS A MARGINAL FAILURE. DEC INSPECTED ALL OTHER BUILDINGS IN THE VICINITY. ALL NEARBY FUEL TANKS ARE ABOVE GROUND OR CONTAIN OIL OTHER THAN # 2 FUEL. " |
| Remarks: | "PETROLEUM IS COMING UP THROUGH THE FLOOR OF THE JEWLRY STORE & 4 ADJAENT BUILDING. SPEEDY DRY IS BEING USED." |

All TTF:

| | |
|---|---|
| Facility ID: | 8801114 |
| Spill Number: | 8801114 |
| Spill Tank Test: | 1533838 |
| Site ID: | 108260 |
| Tank Number: | 001 |
| Tank Size: | 0 |

**LARCH REALTY CORP PROPERT (Continued)** **S100140337**

| | |
|---|---|
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 108260 |
| Operable Unit ID: | 916605 |
| Operable Unit: | 01 |
| Material ID: | 460272 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**56**
**North**
**1/8-1/4**
**0.221 mi.**
**1166 ft.**

**FORLANI** **NY LTANKS** **S106703855**
**15-17 HILLCREST AVE** **N/A**
**LARCHMONT, NY**

**Relative:**
**Higher**

**Actual:**
**100 ft.**

LTANKS:

| | |
|---|---|
| Name: | FORLANI |
| Address: | 15-17 HILLCREST AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9804871 / 2004-12-07 |
| Facility ID: | 9804871 |
| Site ID: | 120774 |
| Spill Date: | 1998-07-20 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D5 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | JBODee |
| Referred To: | WESTCHESTER CNTY HEALTH D |
| Reported to Dept: | 1998-07-20 |
| CID: | 266 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |

**FORLANI (Continued)** **S106703855**

| | |
|---|---|
| Date Entered In Computer: | 1998-07-20 |
| Spill Record Last Update: | 2004-12-07 |
| Spiller Name: | KEVIN DOYLE |
| Spiller Company: | KEVIN DOYLE |
| Spiller Address: | 15-17 HILLCREST AVE |
| Spiller County: | 001 |
| Spiller Contact: | KEVIN DOYLE |
| Spiller Phone: | (914) 279-2365 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 104840 |
| DEC Memo: | "12/07/04 TANK TEST FAILURE OF UNREGULATED, RESIDENTIAL HEATING OIL TANK. TANK REPORTEDLY FAILED A RETEST AND WAS ABANDONED IN PLACE BY TAKE PRIDE CONTRACTING. NO CLOSURE INFORMATION RECEIVED BY DEC. ADMINISTRATIVELY CLOSED. jbo" |
| Remarks: | "TANK TO BE UNCOVERED, ISOLATED AND RETESTED." |

All TTF:

| | |
|---|---|
| Facility ID: | 9804871 |
| Spill Number: | 9804871 |
| Spill Tank Test: | 1546083 |
| Site ID: | 120774 |
| Tank Number: | Not reported |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | F |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 120774 |
| Operable Unit ID: | 1062777 |
| Operable Unit: | 01 |
| Material ID: | 319633 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**L57** **LARCHMONT TERRACE CONDOMINIUM ASSOC. INC.** **NY UST** **U003886190**
**SW** **2 WASHINGTON SQUARE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.241 mi.**
**1270 ft.** **Site 1 of 3 in cluster L**

**Relative:** **Higher**

**Actual:** **52 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | LARCHMONT TERRACE CONDOMINIUM ASSOC. INC. |
| Address: | 2 WASHINGTON SQUARE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-166146 / Active |
| Operator Name: | John Zivan |
| Owner Name: | Larchmont Terrace Condominium, Inc. |
| Owner Street: | 2 Washington Square |
| Owner Address2: | PO Box 750 |
| Owner City: | Larchmont |
| Owner State: | NY |
| Owner Zipcode: | 10538 |
| GDS Number: | Not reported |
| | |
| Tank Number: | 01 |
| Status: | 1. In-Service |
| Capacity: | 5000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 1. Electronic Interstitial Monitoring |
| Date Installation: | 04/01/1994 |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 4. Fiberglass coated steel |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 4. Fiberglass |
| Tank Secondary Containment: | 4. Double-Walled (underground only) |
| Piping Location: | 2. Underground/on Ground |
| Piping Type: | 2. Galvanized Steel |
| Piping External Protection: | 4. Fiberglass |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | 4. Double-Walled (underground only) |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |
| | |
| Tank Number: | 1 |
| Status: | 3. Closed - Removed |
| Capacity: | 10000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 10/01/1956 |
| Date Perm Closure: | 04/01/1994 |
| Tank Location: | 6. Underground, vaulted, with access |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 2. Galvanized steel |
| Piping External Protection: | 0. None |
| Overfill Prevention: | Not reported |

**LARCHMONT TERRACE CONDOMINIUM ASSOC. INC. (Continued)** **U003886190**

Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: 2. Suction

---

**58** **THE KEYSTONE** **NY AST** **A100395305**
**South** **76 WENDT AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.241 mi.**
**1273 ft.**

**Relative:** **Higher**
**Actual:** **51 ft.**

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | THE KEYSTONE |
| Address: | 76 WENDT AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-801206 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | Peter Hatzis |
| Owner Name: | Wendt Owners LLC |
| Owner Street: | 76 Wendt Avenue |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | Larchmont, NY 10538 |
| | |
| Tank Number: | 76 |
| Status: | 1. In-Service |
| Date Installation: | 09/01/2004 |
| Capacity: | 2500 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 6. Aboveground in subterranean vault with access for inspections |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Leak Detection: | 6. Impervious Barrier/Concrete Pad (Aboveground Only) |
| Tank Secondary Containment: | 2. Vault (w/ access),10. Impervious Underlayment (AST Only) |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 0. None |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 5. Vent Whistle |
| Spill Prevention: | Not reported |
| Dispenser: | Not reported |

---

**M59** **VERIZON** **NY MANIFEST** **1010206731**
**NNW** **15 EMERSON RD** **N/A**
**1/8-1/4** **NEW ROCHELLE, NY 10801**
**0.242 mi.**
**1276 ft.** **Site 1 of 2 in cluster M**

**Relative:** **Higher**
**Actual:** **92 ft.**

NY MANIFEST:

| | |
|---|---|
| Name: | VERIZON |
| Address: | 15 EMERSON RD |
| City,State,Zip: | NEW ROCHELLE, NY 10801 |
| Country: | USA |

**VERIZON (Continued)** **1010206731**

| | |
|---|---|
| EPA ID: | NYP000951301 |
| Facility Status: | Not reported |
| Location Address 1: | 15 EMERSON RD |
| Code: | BP |
| Location Address 2: | Not reported |
| Total Tanks: | Not reported |
| Location City: | NEW ROCHELLE |
| Location State: | NY |
| Location Zip: | 10801 |
| Location Zip 4: | Not reported |

NY MANIFEST:

| | |
|---|---|
| EPAID: | NYP000951301 |
| Mailing Name: | VERIZON |
| Mailing Contact: | PRISCILLA SEABURG |
| Mailing Address 1: | 225 MARBLEDALE ROAD |
| Mailing Address 2: | Not reported |
| Mailing City: | TUCKAHOE |
| Mailing State: | NY |
| Mailing Zip: | 10707 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 9147797126 |

---

**L60** **CARLSHIRE TENANTS INC.** **NY AST** **U003855728**
**SW** **1-3 WASHINGTON SQUARE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.244 mi.**
**1287 ft.** **Site 2 of 3 in cluster L**

**Relative:**
**Higher**

**Actual:**
**52 ft.**

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | CARLSHIRE TENANTS INC. |
| Address: | 1-3 WASHINGTON SQUARE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-167185 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | Not reported |
| Owner Name: | Carlshire Tenants Inc. |
| Owner Street: | 1-3 Washington Square |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | Larchmont, NY 10538 |
| | |
| Tank Number: | 2 |
| Status: | 1. In-Service |
| Date Installation: | 04/01/1997 |
| Capacity: | 7500 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | 2. Vault (w/ access) |
| Piping Location: | 3. Aboveground/Underground Combination |

**CARLSHIRE TENANTS INC. (Continued)** **U003855728**

| | |
|---|---|
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only) |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

---

**L61** **CARLSHIRE TENANTS INC.** **NY UST** **U004333716**
**SW** **1-3 WASHINGTON SQUARE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.244 mi.**
**1287 ft.** **Site 3 of 3 in cluster L**

**Relative:** **Higher**
**Actual:** **52 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | CARLSHIRE TENANTS INC. |
| Address: | 1-3 WASHINGTON SQUARE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-167185 / Active |
| Operator Name: | Not reported |
| Owner Name: | Carlshire Tenants Inc. |
| Owner Street: | 1-3 Washington Square |
| Owner Address2: | Not reported |
| Owner City: | Larchmont |
| Owner State: | NY |
| Owner Zipcode: | 10538 |
| GDS Number: | Not reported |
| | |
| Tank Number: | 1 |
| Status: | 3. Closed - Removed |
| Capacity: | 15000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 12/01/1955 |
| Date Perm Closure: | 04/01/1997 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 3. Aboveground/underground combination |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | Not reported |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 2. Suction |

**62**
**West**
**1/8-1/4**
**0.247 mi.**
**1304 ft.**

**CON EDISON**
**6 OVERLOOK TER**
**LARCHMONT, NY 10538**

**RCRA NonGen / NLR** **1012185475**
**NY MANIFEST** **NYP004162822**

**Relative:**
**Higher**

**Actual:**
**81 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20160601 |
| Handler Name: | CON EDISON | |
| Handler Address: | | 6 OVERLOOK TER |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYP004162822 |
| Contact Name: | | HERMAN BAKER |
| Contact Address: | | Not reported |
| Contact City,State,Zip: | | Not reported |
| Contact Telephone: | | 718-267-3853 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Private |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | NY |
| State District: | | NYSDEC R3 |
| Mailing Address: | | 4 IRVING PL, RM 828 |
| Mailing City,State,Zip: | | NEW YORK, NY 10003 |
| Owner Name: | Not reported | |
| Owner Type: | | Not reported |
| Operator Name: | Not reported | |
| Operator Type: | | Not reported |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site Fed-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site Converter Treatment storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Treatment Storage and Disposal Facility: | | Not reported |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | NN |
| Sub-Part K Indicator: | | Not reported |
| Commercial TSD Indicator: | | No |
| Treatment Storage and Disposal Type: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| Permit Renewals Workload Universe: | | Not reported |

**CON EDISON (Continued)** **1012185475**

| | |
|---|---|
| Permit Workload Universe: | Not reported |
| Permit Progress Universe: | Not reported |
| Post-Closure Workload Universe: | Not reported |
| Closure Workload Universe: | Not reported |
| 202 GPRA Corrective Action Baseline: | No |
| Corrective Action Workload Universe: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: | No |
| TSDFs Only Subject to CA under Discretionary Auth Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Operating TSDF Universe: | Not reported |
| Full Enforcement Universe: | Not reported |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: Not reported | |
| Handler Date of Last Change: | 20161101 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | Not reported |
| Manifest Broker: | Not reported |
| Sub-Part P Indicator: | No |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20081213 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Conditionally Exempt Small Quantity Generator |
| State District Owner: | Not reported |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20160601 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | NY |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |

**CON EDISON (Continued)** **1012185475**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 6 OVERLOOK TER
City,State,Zip: LARCHMONT, NY 10538
Country: USA
EPA ID: NYP004162822
Facility Status: Not reported
Location Address 1: 6 OVERLOOK TERRACE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: MAMARONECK
Location State: NY
Location Zip: 10538
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004162822
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 12/13/2008
Trans1 Recv Date: 12/13/2008
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/13/2008
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004162822

**CON EDISON (Continued)** **1012185475**

| | |
|---|---|
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000705939 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 002012544FLE |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H135 |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Waste Code: | Not reported |
| Quantity: | 20 |
| Units: | G - Gallons (liquids only)* (8.3 pounds) |
| Number of Containers: | 1 |
| Container Type: | DM - Metal drums, barrels |
| Handling Method: | T Chemical, physical, or biological treatment. |
| Specific Gravity: | 1 |
| Waste Code: | D018 |
| Waste Code 1_2: | Not reported |
| Waste Code 1_3: | Not reported |
| Waste Code 1_4: | Not reported |
| Waste Code 1_5: | Not reported |
| Waste Code 1_6: | Not reported |

---

**63**
**WSW**
**1/4-1/2**
**0.253 mi.**
**1336 ft.**

**UNKNOWN RESIDENCE**
**35 NORTH CHATSWORTH AVE**
**LARCHMONT, NY**

**NY LTANKS** **S107658601**
**N/A**

**Relative:**
**Lower**

**Actual:**
**32 ft.**

LTANKS:

| | |
|---|---|
| Name: | UNKNOWN RESIDENCE |
| Address: | 35 NORTH CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0513382 / 2006-07-30 |
| Facility ID: | 0513382 |
| Site ID: | 359767 |
| Spill Date: | 2006-02-20 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Non Major Facility > 1,100 gal |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | WCDOH |
| Reported to Dept: | 2006-02-20 |

**UNKNOWN RESIDENCE (Continued)** **S107658601**

| | |
|---|---|
| CID: | 409 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2006-02-21 |
| Spill Record Last Update: | 2006-07-30 |
| Spiller Name: | MARLON JOESPH |
| Spiller Company: | UNKNOWN RESIDENE |
| Spiller Address: | 35 NORTH CHATSWORTON AVE |
| Spiller County: | 001 |
| Spiller Contact: | MARLON JOESPH |
| Spiller Phone: | (718) 772-7949 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 309899 |
| DEC Memo: | "Tank Test Failure July 30, 2006: Tank passed a retest after piping was repaired. Based upon information provided to DEC, no further action is required at this time" |
| Remarks: | "ABOVE LIQUID LEAK ." |

All TTF:

| | |
|---|---|
| Facility ID: | 0513382 |
| Spill Number: | 0513382 |
| Spill Tank Test: | 1549742 |
| Site ID: | 359767 |
| Tank Number: | 1 |
| Tank Size: | 15000 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

| | |
|---|---|
| Facility ID: | 0513382 |
| Spill Number: | 0513382 |
| Spill Tank Test: | 1549743 |
| Site ID: | 359767 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |

**UNKNOWN RESIDENCE (Continued)** **S107658601**

Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 359767
Operable Unit ID: 1116960
Operable Unit: 01
Material ID: 2107425
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

**M64** **RESIDENCE** **NY LTANKS** **S104191487**
**NNW** **60 MAPLE HILL DR** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.256 mi.**
**1353 ft.** **Site 2 of 2 in cluster M**

**Relative:** **Higher**
**Actual:** **89 ft.**

LTANKS:
Name: RESIDENCE
Address: 60 MAPLE HILL DR
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 9904648 / 1999-09-28
Facility ID: 9904648
Site ID: 254123
Spill Date: 1999-07-19
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6000
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 1999-07-19
CID: 252
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1999-07-19
Spill Record Last Update: 1999-09-30
Spiller Name: MR THOMAS AMLICKE
Spiller Company: RESIDENCE
Spiller Address: 60 MAPLE HILL DR
Spiller County: 001
Spiller Contact: MR THOMAS AMLICKE
Spiller Phone: (914) 834-6299
Spiller Extention: Not reported

**RESIDENCE (Continued)** **S104191487**

DEC Region: 3
DER Facility ID: 208144
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 9/28/99 NORTHEAST ENVIRONMENTAL DISPOSED OF TANK AND 21.3 TONS OF SOIL. NFA"
Remarks: "RECOMMEND EXCAVATE-ISOLATE AND RE-TEST."

All TTF:
Facility ID: 9904648
Spill Number: 9904648
Spill Tank Test: 1547386
Site ID: 254123
Tank Number: Not reported
Tank Size: 550
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 254123
Operable Unit ID: 1083412
Operable Unit: 01
Material ID: 300977
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

**65**
**NNE**
**1/4-1/2**
**0.258 mi.**
**1360 ft.**

**SPILL NUMBER 0107991** **NY LTANKS** **S105230054**
**21 EDGEWOOD AVE** **N/A**
**MAMARONECK, NY**

**Relative:**
**Higher**

**Actual:**
**70 ft.**

LTANKS:
Name: SPILL NUMBER 0107991
Address: 21 EDGEWOOD AVE
City,State,Zip: MAMARONECK, NY
Spill Number/Closed Date: 0107991 / 2002-02-28
Facility ID: 0107991
Site ID: 220664
Spill Date: 2001-11-06
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: C3

**SPILL NUMBER 0107991 (Continued)** **S105230054**

| | |
|---|---|
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2001-11-06 |
| CID: | 207 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2001-11-06 |
| Spill Record Last Update: | 2002-03-20 |
| Spiller Name: | HAROLD PITTS |
| Spiller Company: | FEIMAN |
| Spiller Address: | 21 EDGEWOOD AVE |
| Spiller County: | 001 |
| Spiller Contact: | HAROLD PITTS |
| Spiller Phone: | (914) 969-1006 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 182529 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/28/2002 TAKE PRIDE DISPOSED OF 19.59 TONS OF SOIL. DEC INSPECTED SITE WITH H2M. NO FURTHER ACTION." |
| Remarks: | "contaminated soil found during tank removal " |

All Materials:

| | |
|---|---|
| Site ID: | 220664 |
| Operable Unit ID: | 845229 |
| Operable Unit: | 01 |
| Material ID: | 529248 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**N66** **SPILL NUMBER 9910464** **NY LTANKS** **S104620682**
**NE** **116 LAUREL AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.262 mi.**
**1384 ft.** **Site 1 of 2 in cluster N**

**Relative:**
**Higher**

**Actual:**
**49 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9910464 |
| Address: | 116 LAUREL AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9910464 / 2000-02-10 |
| Facility ID: | 9910464 |
| Site ID: | 283585 |
| Spill Date: | 1999-12-01 |

**SPILL NUMBER 9910464 (Continued)** **S104620682**

| | |
|---|---|
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-12-01 |
| CID: | 207 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-12-01 |
| Spill Record Last Update: | 2000-02-24 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | ANGELO CARDUCCI |
| Spiller Phone: | (914) 698-2460 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 230016 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/10/2000 TANK PASSED RETEST. NFA" |
| Remarks: | "tank contained #2 fuel no product leaked" |

All TTF:

| | |
|---|---|
| Facility ID: | 9910464 |
| Spill Number: | 9910464 |
| Spill Tank Test: | 1547894 |
| Site ID: | 283585 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

**67**
**SSW**
**1/4-1/2**
**0.264 mi.**
**1394 ft.**

**WACHOVIA BANK**
**1940 PALMER AVE**
**LARCHMONT, NY**

**NY LTANKS** **S106471628**
**N/A**

**Relative:**
**Higher**

**Actual:**
**51 ft.**

LTANKS:

| | |
|---|---|
| Name: | WACHOVIA BANK |
| Address: | 1940 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0401512 / 2004-11-18 |
| Facility ID: | 0401512 |
| Site ID: | 173845 |
| Spill Date: | 2004-05-12 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | WCHD |
| Referred To: | WESTCHESTER CNTY HEALTH D |
| Reported to Dept: | 2004-05-12 |
| CID: | 407 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-05-12 |
| Spill Record Last Update: | 2017-06-26 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | DOUG NEWTON |
| Spiller Phone: | (610) 941-9700 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 146229 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 11/22/04: Letter to Steven A. Colton, Sr. VP, Wachovia Bank, dated 18Nov2004. Spill closed by Stefan Goreau, WCDOH." |
| Remarks: | "Dry leak, they believe its a manhole cover or line problem. They will redo the manhole cover and do a tank only test." |

All TTF:

| | |
|---|---|
| Facility ID: | 0401512 |
| Spill Number: | 0401512 |
| Spill Tank Test: | 1529256 |
| Site ID: | 173845 |
| Tank Number: | 1 |
| Tank Size: | 1500 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |

**WACHOVIA BANK (Continued)** **S106471628**

| | |
|---|---|
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

---

**68**
**NNW**
**1/4-1/2**
**0.264 mi.**
**1396 ft.**

**VALKENBURGH HOME** **NY LTANKS** **S108131410**
**47 MAPLE HILL DRIVE** **N/A**
**LARCHMONT, NY**

**Relative:**
**Higher**

**Actual:**
**87 ft.**

LTANKS:

| | |
|---|---|
| Name: | VALKENBURGH HOME |
| Address: | 47 MAPLE HILL DRIVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0606523 / 2007-01-04 |
| Facility ID: | 0606523 |
| Site ID: | 369884 |
| Spill Date: | 2006-09-07 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | Not reported |
| Reported to Dept: | 2006-09-07 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2006-09-07 |
| Spill Record Last Update: | 2007-01-04 |
| Spiller Name: | MARY ANN VAN VALKENBURGH |
| Spiller Company: | VALKENBURGH HOME |
| Spiller Address: | 47 MAPLE HILL DRIVE |
| Spiller County: | 001 |
| Spiller Contact: | MARY ANN VAN VALKENBURGH |
| Spiller Phone: | (914) 834-3978 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 319747 |
| DEC Memo: | "(v.M.) Tank has been in house since 1988. Approximately 18 years ago (heating) was converted from coil to fuel. January 4, 2007: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 20.71 TONS OF CONTAMINATED SOIL. CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION PROVIDED, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod" |
| Remarks: | "550 GALLON TANK HAD HOLES AND CONTAMINATION" |

All Materials:

| | |
|---|---|
| Site ID: | 369884 |
| Operable Unit ID: | 1127711 |

**VALKENBURGH HOME (Continued)** **S108131410**

| | |
|---|---|
| Operable Unit: | 01 |
| Material ID: | 2117312 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**69**
**WNW**
**1/4-1/2**
**0.268 mi.**
**1417 ft.**

**RESI:BISNO**
**53 HILLSIDE RD**
**LARCHMONT, NY**

**NY LTANKS** **S104621790**
**N/A**

**Relative:**
**Higher**

**Actual:**
**96 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESI:BISNO |
| Address: | 53 HILLSIDE RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0003197 / 2005-04-03 |
| Facility ID: | 0003197 |
| Site ID: | 257812 |
| Spill Date: | 2000-06-14 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C5 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2000-06-14 |
| CID: | 398 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2000-06-14 |
| Spill Record Last Update: | 2005-04-03 |
| Spiller Name: | ALLISON BISNO |
| Spiller Company: | RESI:BISNO |
| Spiller Address: | 53 HILLSIDE RD |
| Spiller County: | 001 |
| Spiller Contact: | ALLISON BISNO |
| Spiller Phone: | (212) 852-3686 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 211096 |
| DEC Memo: | "06/15/00 Letter sent to tank owner by John O'Dee outlining DEC procedures for closing spill and requesting call back. 04/03/05 NON-REGULATED TTF. NO RETEST OR CLOSURE INFORMATION SUBMITTED TO DEC. TANK TEST COMPANY IS NO LONGER IN BUSINESS. SPILL ADMINISTRATIVELY CLOSED AS PER DIRECTIVE FROM CENTRAL OFFICE. jod" |

**RESI:BISNO (Continued)** **S104621790**

Remarks: "GROSS FAILURE ON TANK. HOME OWNER WILL UNCOVER, ISOLATE AND RETEST TANK."

All TTF:

| | |
|---|---|
| Facility ID: | 0003197 |
| Spill Number: | 0003197 |
| Spill Tank Test: | 1525687 |
| Site ID: | 257812 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 257812 |
| Operable Unit ID: | 825400 |
| Operable Unit: | 01 |
| Material ID: | 551524 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**70**
**NNE**
**1/4-1/2**
**0.269 mi.**
**1419 ft.**

**REISMAN RESIDENCE** **NY LTANKS** **S109064266**
**24 EDGEWOOD AVE** **N/A**
**MAMARONECK, NY**

**Relative:**
**Higher**

**Actual:**
**88 ft.**

LTANKS:

| | |
|---|---|
| Name: | REISMAN RESIDENCE |
| Address: | 24 EDGEWOOD AVE |
| City,State,Zip: | MAMARONECK, NY |
| Spill Number/Closed Date: | 0800763 / 2008-07-08 |
| Facility ID: | 0800763 |
| Site ID: | 396571 |
| Spill Date: | 2008-04-18 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |

**REISMAN RESIDENCE (Continued)** **S109064266**

| | |
|---|---|
| Reported to Dept: | 2008-04-18 |
| CID: | 408 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | Not reported |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2008-04-18 |
| Spill Record Last Update: | 2008-07-08 |
| Spiller Name: | MR. PHIL RICEMAN |
| Spiller Company: | PRIVATE HOME |
| Spiller Address: | 24 EDGEWOOD AVE |
| Spiller County: | 001 |
| Spiller Contact: | MR. PHIL RICEMAN |
| Spiller Phone: | (914) 337-6522 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 346050 |
| DEC Memo: | "4/18/08 Tank tested prior to home being put up for sale. House currently vacant. Unknown tank age, at least 25+ years. Tank to be pulled, contractors list given to contact, son-in-law of previous owner. jod 06/27/08 New England Tank Services reported that they abandoned in place one 1,000 gallon tank. They stated that the tank test failure may have been due to a rotted vent pipe. No petroleum contaminated soil was noted and the results of a soil sample were below DEC guidance values. Nfa. TG " |
| Remarks: | "RECOMMEND REMOVAL;" |

All TTF:

| | |
|---|---|
| Facility ID: | 0800763 |
| Spill Number: | 0800763 |
| Spill Tank Test: | 2453548 |
| Site ID: | 396571 |
| Tank Number: | Not reported |
| Tank Size: | 1000 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | True |
| Cause: | 99 |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 396571 |
| Operable Unit ID: | 1153543 |
| Operable Unit: | 01 |
| Material ID: | 2144310 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |

**REISMAN RESIDENCE (Continued)** **S109064266**

| | |
|---|---|
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**71**
**SE**
**1/4-1/2**
**0.270 mi.**
**1426 ft.**

**RESIDENCE** **NY LTANKS** **S102618923**
**9 SUMMIT AVE** **N/A**
**LARCHMONT, NY**

**Relative:**
**Higher**

**Actual:**
**55 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 9 SUMMIT AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9702679 / 1997-08-08 |
| Facility ID: | 9702679 |
| Site ID: | 229293 |
| Spill Date: | 1997-06-02 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1997-06-02 |
| CID: | 233 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1997-06-02 |
| Spill Record Last Update: | 1997-10-14 |
| Spiller Name: | JIM ROOD |
| Spiller Company: | Not reported |
| Spiller Address: | 9 SUMMIT AVE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 189044 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 08/08/97 TTF; NES REMOVED THE TANK AND CONTAMINATED SOIL; ONLY THREE TONS OF SOIL WERE FOUND; " |
| Remarks: | "home heating system was tested and failed jim rood will be contacting nes and will make plans to remove tank " |

All TTF:

| | |
|---|---|
| Facility ID: | 9702679 |
| Spill Number: | 9702679 |
| Spill Tank Test: | 1545143 |

**RESIDENCE (Continued)** **S102618923**

| | |
|---|---|
| Site ID: | 229293 |
| Tank Number: | 1 |
| Tank Size: | 275 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 229293 |
| Operable Unit ID: | 1045404 |
| Operable Unit: | 01 |
| Material ID: | 335612 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**N72** **SPILL NUMBER 9910463** **NY LTANKS** **S104620681**
**NE** **114 LAUREL AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.274 mi.**
**1448 ft.** **Site 2 of 2 in cluster N**

**Relative:**
**Higher**

**Actual:**
**49 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9910463 |
| Address: | 114 LAUREL AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9910463 / 2000-02-10 |
| Facility ID: | 9910463 |
| Site ID: | 171857 |
| Spill Date: | 1999-12-01 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-12-01 |
| CID: | 207 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |

**SPILL NUMBER 9910463 (Continued)** **S104620681**

| | |
|---|---|
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-12-01 |
| Spill Record Last Update: | 2000-02-24 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | ANGELO CARDUCCI |
| Spiller Phone: | (914) 698-2460 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 144634 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/10/2000 TANK PASSED RETEST. NFA" |
| Remarks: | "gross fail tank contained #2" |

All TTF:

| | |
|---|---|
| Facility ID: | 9910463 |
| Spill Number: | 9910463 |
| Spill Tank Test: | 1547893 |
| Site ID: | 171857 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

---

**73** **CARRIER RESIDENCE** **NY LTANKS** **S106000095**
**East** **45 CARLEON AV** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.280 mi.**
**1476 ft.**

**Relative:**
**Higher**

**Actual:**
**43 ft.**

LTANKS:

| | |
|---|---|
| Name: | CARRIER RESIDENCE |
| Address: | 45 CARLEON AV |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0307038 / 2003-11-20 |
| Facility ID: | 0307038 |
| Site ID: | 174655 |
| Spill Date: | 2003-10-03 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |

**CARRIER RESIDENCE (Continued)** **S106000095**

| | |
|---|---|
| Referred To: | Not reported |
| Reported to Dept: | 2003-10-03 |
| CID: | 297 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-10-03 |
| Spill Record Last Update: | 2003-11-20 |
| Spiller Name: | CHRISTINA CARRIER |
| Spiller Company: | Not reported |
| Spiller Address: | 45 CARLEON AV |
| Spiller County: | 001 |
| Spiller Contact: | JENEEN CIANFLONE |
| Spiller Phone: | (914) 741-5472 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 146873 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/20/03 NES DISPOSED OF LUST AND 33.30 TONS OF CONTAMINATED SOIL." |
| Remarks: | "CALLERS COMPANY REMOVING A 550 GALLON INGROUND TANK, SOIL CONTAMINATION AND HOLES IN THE TANK DISCOVERED" |

All Materials:

| | |
|---|---|
| Site ID: | 174655 |
| Operable Unit ID: | 873589 |
| Operable Unit: | 01 |
| Material ID: | 500625 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**74**
**NW**
**1/4-1/2**
**0.287 mi.**
**1516 ft.**

**PRIVATE RESIDENCE** **NY LTANKS** **S106385783**
**125 MURRAY AVE** **N/A**
**LARCHMONT, NY**

**Relative:**
**Higher**

**Actual:**
**94 ft.**

LTANKS:

| | |
|---|---|
| Name: | PRIVATE RESIDENCE |
| Address: | 125 MURRAY AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0400156 / 2004-06-16 |
| Facility ID: | 0400156 |
| Site ID: | 158874 |
| Spill Date: | 2004-04-06 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |

**PRIVATE RESIDENCE (Continued)** **S106385783**

| | |
|---|---|
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-04-06 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-04-06 |
| Spill Record Last Update: | 2004-06-16 |
| Spiller Name: | BRUCE LEBLIN-REALTY |
| Spiller Company: | PRIVATE RESIDENCE |
| Spiller Address: | 125 MURRAY AVE |
| Spiller County: | 001 |
| Spiller Contact: | BRUCE LEBLIN-REALTY |
| Spiller Phone: | (914) 946-7100 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 134259 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 6-10-04 Letter rec'd from Northeast Environmental. They removed the tank and reported that no contamintion was found in the tank excavation. NFA TG" |
| Remarks: | "recommendation: has pedromidator on it they recommend they take it off and retest: " |

All Materials:

| | |
|---|---|
| Site ID: | 158874 |
| Operable Unit ID: | 884578 |
| Operable Unit: | 01 |
| Material ID: | 494945 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**75**
**SSE**
**1/4-1/2**
**0.288 mi.**
**1523 ft.**

**SPILL NUMBER 9903173** **NY LTANKS** **S104620271**
**26 SUMMITT AVE** **N/A**
**LARCHMONT, NY**

**Relative:**
**Higher**

**Actual:**
**58 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9903173 |
| Address: | 26 SUMMITT AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9903173 / 1999-07-27 |

**SPILL NUMBER 9903173 (Continued)** **S104620271**

| | |
|---|---|
| Facility ID: | 9903173 |
| Site ID: | 66265 |
| Spill Date: | 1999-06-18 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-06-18 |
| CID: | 312 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-06-18 |
| Spill Record Last Update: | 1999-08-04 |
| Spiller Name: | OLAFSON |
| Spiller Company: | Not reported |
| Spiller Address: | 26 SUMMITT AVE |
| Spiller County: | 001 |
| Spiller Contact: | OLAFSON |
| Spiller Phone: | (914) 834-5586 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 63479 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 6/18/99 PER NES--DURING TANK REPLACEMENT HOLES WERE NOTED IN A/G 275 GALLON OUTSIDE OF HOUSE. NEW TANK INSTALLED IN BASEMENT. NES DOING CLEANUP. 7/27/99 NES REMOVED TANK AND 70 TONS OF CONTAMINATED SOIL. CLEANUP COMPLETE. NFA" |
| Remarks: | "275GAL UST HAD FAILED - REMOVING THE TANK AND CONTAMINATED SOIL" |

All Materials:

| | |
|---|---|
| Site ID: | 66265 |
| Operable Unit ID: | 1077780 |
| Operable Unit: | 01 |
| Material ID: | 303099 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**O76** **BLONDIE'S TREEHOUSE** **NY LTANKS** **S104621434**
**SSW** **21 NORTH AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.292 mi.**
**1543 ft.** **Site 1 of 2 in cluster O**

**Relative:**
**Higher**

**Actual:**
**43 ft.**

LTANKS:

| | |
|---|---|
| Name: | BLONDIE'S TREEHOUSE |
| Address: | 21 NORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0000712 / 2000-08-08 |
| Facility ID: | 0000712 |
| Site ID: | 175577 |
| Spill Date: | 2000-04-18 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2000-04-18 |
| CID: | 371 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2000-04-18 |
| Spill Record Last Update: | 2000-08-09 |
| Spiller Name: | Not reported |
| Spiller Company: | BLONDIE'S TREEHOUSE |
| Spiller Address: | 21 NORTH AVE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 147611 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE " |
| Remarks: | "FOUND CONTAMINATED SOIL AND HOLES IN TANK WHILE PULLING A 550 GAL UST." |

All Materials:

| | |
|---|---|
| Site ID: | 175577 |
| Operable Unit ID: | 822442 |
| Operable Unit: | 01 |
| Material ID: | 288951 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**O77** **SPILL NUMBER 9914491** **NY LTANKS** **S104620938**
**SSW** **21 NORTH AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.292 mi.**
**1543 ft.** **Site 2 of 2 in cluster O**

**Relative:**
**Higher**

**Actual:**
**43 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9914491 |
| Address: | 21 NORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9914491 / 2002-06-29 |
| Facility ID: | 9914491 |
| Site ID: | 175578 |
| Spill Date: | 2000-03-22 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2000-03-23 |
| CID: | 312 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2000-03-23 |
| Spill Record Last Update: | 2003-08-05 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | 21 NORTH AVE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 147611 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/29/02 NES PULLED TANK AND COMPLETED CLEAN UP. ALSO SPILL 01-10895." |
| Remarks: | "EITHER 550 OR 1000 GAL TANK - TANK IS UNDER CONCRETE" |

All TTF:

| | |
|---|---|
| Facility ID: | 9914491 |
| Spill Number: | 9914491 |
| Spill Tank Test: | 1548155 |
| Site ID: | 175578 |
| Tank Number: | 001 |
| Tank Size: | 550 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 16 |
| Test Method 2: | Tracer Tight |

**SPILL NUMBER 9914491 (Continued)** **S104620938**

| | |
|---|---|
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

---

**P78** **RESIDENCE** **NY LTANKS** **S100878804**
**NNW** **8 ORSINI DRIVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.294 mi.**
**1553 ft.** **Site 1 of 2 in cluster P**

**Relative:** **Higher**

**Actual:** **88 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 8 ORSINI DRIVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9312714 / 1995-01-19 |
| Facility ID: | 9312714 |
| Site ID: | 99667 |
| Spill Date: | 1994-01-28 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | 1995-01-19 |
| SWIS: | 6000 |
| Investigator: | MALONE |
| Referred To: | Not reported |
| Reported to Dept: | 1994-01-28 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Health Department |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1994-02-07 |
| Spill Record Last Update: | 1995-01-19 |
| Spiller Name: | Not reported |
| Spiller Company: | GERARD AUERCIOLI |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 88541 |
| DEC Memo: | "" |
| Remarks: | "OLD U/G TANK TAKING ON WATER AND LEAKING UP THROUGH GROUND CONTRACTOR TO REMOVE U/G TANK WCHD ON SITE AND WILL UPDATE AS NEEDED" |

All Materials:

| | |
|---|---|
| Site ID: | 99667 |
| Operable Unit ID: | 994700 |
| Operable Unit: | 01 |
| Material ID: | 388130 |
| Material Code: | 0066A |
| Material Name: | unknown petroleum |

**RESIDENCE (Continued)** **S100878804**

| | |
|---|---|
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | Not reported |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**79**
**WNW**
**1/4-1/2**
**0.298 mi.**
**1572 ft.**

**SPILL NUMBER 9806441** **NY LTANKS** **S104619658**
**26 HILLSIDE ROAD** **N/A**
**LARCHMONT, NY**

**Relative:**
**Higher**

**Actual:**
**89 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9806441 |
| Address: | 26 HILLSIDE ROAD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9806441 / 1998-09-08 |
| Facility ID: | 9806441 |
| Site ID: | 107995 |
| Spill Date: | 1998-08-25 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1998-08-25 |
| CID: | 266 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-08-25 |
| Spill Record Last Update: | 1998-10-02 |
| Spiller Name: | ARTHUR BLANCO |
| Spiller Company: | ARTHUR BLANCO |
| Spiller Address: | 26 HILLSIDE ROAD |
| Spiller County: | 001 |
| Spiller Contact: | ARTHUR BLANCO |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 94936 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: | "SPILLER'S WORK PHONE NUMBER (914) 381-9700. HOLES FOUND IN 550 GALLON UNDERGROUND STORAGE TANK DURING REMOVAL. TANK STILL BEING REMOVED. SOIL TO BE STOCKPILED AS NECESSARY." |

All Materials:

| | |
|---|---|
| Site ID: | 107995 |
| Operable Unit ID: | 1067629 |

**SPILL NUMBER 9806441 (Continued)** **S104619658**

| | |
|---|---|
| Operable Unit: | 01 |
| Material ID: | 317596 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**Q80** **YAHIA RESIDENCE** **NY LTANKS** **S107789426**
**SE** **17 HALL AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.301 mi.**
**1587 ft.** **Site 1 of 2 in cluster Q**

**Relative:** LTANKS:
**Lower**

**Actual:**
**29 ft.**

| | |
|---|---|
| Name: | YAHIA HOME |
| Address: | 17 HALL AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0601851 / 2007-01-03 |
| Facility ID: | 0601851 |
| Site ID: | 364200 |
| Spill Date: | 2006-05-19 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | Not reported |
| Reported to Dept: | 2006-05-19 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2006-05-19 |
| Spill Record Last Update: | 2007-01-03 |
| Spiller Name: | DORIS YAHIA |
| Spiller Company: | YAHIA HOME |
| Spiller Address: | 17 HALL AVE |
| Spiller County: | 001 |
| Spiller Contact: | DORIS YAHIA |
| Spiller Phone: | (914) 318-2798 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 314413 |
| DEC Memo: | "05/23/06: J. O'DEE TO DISCUSS FINDINGS. SAMPLES WERE TAKEN FROM EXCAVATION AND HOLE WAS BACKFILLED PENDING SIGNATURE OF CONTRACT TO COMPLETE CLEAN UP. ALSO SPILL 06-02686 January 3, 2007: CONNECTICUT TANK REMOVAL DISPOSED OF LUST AND 351.26 TONS OF CONTAMINATED SOIL. GROUND WATER WAS IMPACTED, AND A MONITORING WELL WAS INSTALLED AND |

**YAHIA RESIDENCE (Continued)** **S107789426**

SAMPLED. CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION PROVIDED, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"

Remarks: "1000 GALLON TANK HAD HOLES :"

All Materials:

| | |
|---|---|
| Site ID: | 364200 |
| Operable Unit ID: | 1122234 |
| Operable Unit: | 01 |
| Material ID: | 2111707 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | YAHIA RESIDENCE |
| Address: | 17 HALL AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0602686 / 2007-01-03 |
| Facility ID: | 0602686 |
| Site ID: | 365228 |
| Spill Date: | 2006-05-22 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | Not reported |
| Reported to Dept: | 2006-06-09 |
| CID: | 409 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2006-06-09 |
| Spill Record Last Update: | 2007-01-03 |
| Spiller Name: | TIM FIRLA |
| Spiller Company: | YAHIA RESIDENCE |
| Spiller Address: | 17 HALL AVE |
| Spiller County: | 001 |
| Spiller Contact: | TIM FIRLA |
| Spiller Phone: | (203) 384-6020 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 314413 |
| DEC Memo: | "06/12/06: THERE IS ANOTHER SPILL # FOR THIS SITE 0601851 - J. O'DEE HAS BEEN CALLED VIA THE CALLER. GW HAS BEEN IMPACTED WITH FREE PRODCUT. (#2F/O) - RA January 3, 2007: CONNECTICUT TANK REMOVAL DISPOSED OF LUST AND 351.26 TONS OF CONTAMINATED SOIL. GROUND WATER WAS IMPACTED, AND A MONITORING WELL WAS INSTALLED AND SAMPLED. |

**YAHIA RESIDENCE (Continued)** **S107789426**

| | |
|---|---|
| Remarks: | CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION PROVIDED, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod" |
| | "THE TANK WAS PUMPED AOUT AND THEN REMOVED AND THEN THE SOIL WAS TESTED. THEY WILL DO A REMIDIATION THERE. TIM WOULD LIKE A CALL BACK." |
| | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 365228 |
| Operable Unit ID: | 1123238 |
| Operable Unit: | 01 |
| Material ID: | 2112711 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**P81** **PHIL LEBOWITZ** **NY LTANKS** **S116156779**
**NNW** **12 ORSINI DRIVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.311 mi.**
**1644 ft.** **Site 2 of 2 in cluster P**

**Relative:**
**Higher**

**Actual:**
**88 ft.**

LTANKS:

| | |
|---|---|
| Name: | PHIL LEBOWITZ |
| Address: | 12 ORSINI DRIVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1309250 / 2014-03-17 |
| Facility ID: | 1309250 |
| Site ID: | 490038 |
| Spill Date: | 2013-12-18 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODEE |
| Referred To: | Not reported |
| Reported to Dept: | 2013-12-18 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2013-12-18 |
| Spill Record Last Update: | 2014-03-17 |
| Spiller Name: | PHIL LEBOWITZ |
| Spiller Company: | PHIL LEBOWITZ |
| Spiller Address: | 12 ORSINI DR |
| Spiller County: | 999 |
| Spiller Contact: | PHIL LEBOWITZ |

**PHIL LEBOWITZ (Continued)** **S116156779**

| | |
|---|---|
| Spiller Phone: | (914) 834-6347 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 445128 |
| DEC Memo: | "Tank test failure at private home...mm 3/17/2014: Northeast Environmental removed and disposed of the UST. No evidence of a leak or of petroleum contamination was found. Tank Closure report reviewed and entered into eDocs. Based upon information provided to DEC, no further action is required at this time. jod" |
| Remarks: | "550 test failure" |

All TTF:

| | |
|---|---|
| Facility ID: | 1309250 |
| Spill Number: | 1309250 |
| Spill Tank Test: | 2495195 |
| Site ID: | 490038 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | False |
| UST: | True |
| Cause: | 04 |
| Source: | 04 |
| Test Method: | 21 |
| Test Method 2: | Horner EZY3/EZY3 Locator Plus |
| Leak Rate: | Not reported |
| Gross Fail: | Not reported |
| Modified By: | JBODEE |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 490038 |
| Operable Unit ID: | 1239604 |
| Operable Unit: | 01 |
| Material ID: | 2239652 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**82** **ALPERT HOME** **NY LTANKS** **S109064205**
**NW** **80 LOOKOUT CIRCLE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.316 mi.**
**1669 ft.**

**Relative:**
**Higher**

**Actual:**
**114 ft.**

LTANKS:

| | |
|---|---|
| Name: | ALPERT HOME |
| Address: | 80 LOOKOUT CIRCLE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0713708 / 2009-08-31 |
| Facility ID: | 0713708 |
| Site ID: | 395508 |

**ALPERT HOME (Continued)** **S109064205**

| | |
|---|---|
| Spill Date: | 2008-03-27 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6034 |
| Investigator: | JBODEE |
| Referred To: | Not reported |
| Reported to Dept: | 2008-03-27 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | Not reported |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2008-03-27 |
| Spill Record Last Update: | 2019-11-07 |
| Spiller Name: | RICHARD ALPERT |
| Spiller Company: | ALPERT HOME |
| Spiller Address: | 80 LOOKOUT CIRCLE |
| Spiller County: | 001 |
| Spiller Contact: | RICHARD ALPERT |
| Spiller Phone: | (347) 248-5285 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 345028 |
| DEC Memo: | "8/31/2009 -- No test method provided; likely to be inappropriate. WCDOH would have required further testing. NFA at this time. ELM" |
| Remarks: | "UNCOVER AND RETEST" |

All TTF:

| | |
|---|---|
| Facility ID: | 0713708 |
| Spill Number: | 0713708 |
| Spill Tank Test: | 2384916 |
| Site ID: | 395508 |
| Tank Number: | Not reported |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | True |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 395508 |
| Operable Unit ID: | 1152445 |
| Operable Unit: | 01 |
| Material ID: | 2143222 |
| Material Code: | 0001A |

**ALPERT HOME (Continued)** **S109064205**

| | |
|---|---|
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**Q83** **SPILL NUMBER 0011319** **NY LTANKS** **S104950556**
**SE** **14 HALL AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.319 mi.**
**1685 ft.** **Site 2 of 2 in cluster Q**

**Relative:**
**Lower**

**Actual:**
**28 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 0011319 |
| Address: | 14 HALL AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0011319 / 2001-04-11 |
| Facility ID: | 0011319 |
| Site ID: | 184309 |
| Spill Date: | 2001-01-17 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2001-01-17 |
| CID: | 207 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2001-01-17 |
| Spill Record Last Update: | 2001-04-24 |
| Spiller Name: | JAY LUBIN |
| Spiller Company: | Not reported |
| Spiller Address: | 14 HALL AVE |
| Spiller County: | 001 |
| Spiller Contact: | JAY LUBIN |
| Spiller Phone: | (914) 833-2686 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 154247 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/11/2001 NORTHEAST DISPOSED OF TANK AND 23.63 TONS OF CONTAMINATED SOIL. NO FURTHER ACTION." |
| Remarks: | "contaminated soil found upon tank removal" |

All Materials:

| | |
|---|---|
| Site ID: | 184309 |
| Operable Unit ID: | 832716 |

**SPILL NUMBER 0011319 (Continued)** **S104950556**

| | |
|---|---|
| Operable Unit: | 01 |
| Material ID: | 541639 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**84**
**South**
**1/4-1/2**
**0.319 mi.**
**1685 ft.**

**YOUNG HOME** **NY LTANKS** **S108131336**
**6 ROCKHILL TERRACE** **N/A**
**LARCHMONT, NY**

**Relative:**
**Higher**

**Actual:**
**46 ft.**

LTANKS:

| | |
|---|---|
| Name: | YOUNG HOME |
| Address: | 6 ROCKHILL TERRACE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0606153 / 2012-08-17 |
| Facility ID: | 0606153 |
| Site ID: | 369457 |
| Spill Date: | 2006-08-29 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | UNASSIGNED |
| Referred To: | Not reported |
| Reported to Dept: | 2006-08-29 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2006-08-29 |
| Spill Record Last Update: | 2012-08-17 |
| Spiller Name: | LOU YOUNG |
| Spiller Company: | YOUNG HOME |
| Spiller Address: | 6 ROCKHILL TERRACE |
| Spiller County: | 001 |
| Spiller Contact: | LOU YOUNG |
| Spiller Phone: | (914) 833-7966 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 319337 |
| DEC Memo: | "8/2/10 Homeowner TTF JO'M 8/17/12 Homeomer TTF greater then 5 years old and no indications of contamination will be closed. This was done with consultations between Albany and the Region. NFA JO'M" |
| Remarks: | "UNCOVER REPAIR AND TEST" |

**YOUNG HOME (Continued)** **S108131336**

All TTF:

| | |
|---|---|
| Facility ID: | 0606153 |
| Spill Number: | 0606153 |
| Spill Tank Test: | 1550235 |
| Site ID: | 369457 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 369457 |
| Operable Unit ID: | 1127294 |
| Operable Unit: | 01 |
| Material ID: | 2116886 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**85 SSW 1/4-1/2 0.326 mi. 1719 ft.** **UNITED ARTISTS THEATER** **NY LTANKS** **S101102348**
**1975 PALMER AVE.** **NY Spills** **N/A**
**LARCHMONT, NY**

**Relative: Higher**

**Actual: 50 ft.**

LTANKS:

| | |
|---|---|
| Name: | UNITED ARTISTS THEATER |
| Address: | 1975 PALMER AVE. |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9401111 / 2001-03-12 |
| Facility ID: | 9401111 |
| Site ID: | 323532 |
| Spill Date: | 1994-04-22 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1994-04-22 |
| CID: | Not reported |

**UNITED ARTISTS THEATER (Continued)** **S101102348**

| | |
|---|---|
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1994-05-04 |
| Spill Record Last Update: | 2001-03-27 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 260632 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST. NOVEMBER 1995 - ENSA UST REMOVAL REPORT SUBMITTED DOCUMENTING THAT 2K TANK WAS REMOVED IN OCTOBER OF 1995. NO FURTHER ACTION BASED ON INFO FROM THAT REPORT." |
| Remarks: | "E.I.R. PETRO-TITE -.499" |

All TTF:

| | |
|---|---|
| Facility ID: | 9401111 |
| Spill Number: | 9401111 |
| Spill Tank Test: | 1542643 |
| Site ID: | 323532 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 323532 |
| Operable Unit ID: | 994949 |
| Operable Unit: | 01 |
| Material ID: | 384880 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | L |
| Recovered: | .00 |

**UNITED ARTISTS THEATER (Continued)** **S101102348**

Oxygenate: Not reported

SPILLS:

| | |
|---|---|
| Name: | UNITED ARTISTS THEATER |
| Address: | 1975 PALMER AVE. |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9301021 / 1994-12-08 |
| Facility ID: | 9301021 |
| Facility Type: | ER |
| DER Facility ID: | 260632 |
| Site ID: | 323531 |
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | C3 |
| SWIS: | 6000 |
| Spill Date: | 1993-04-20 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1993-04-21 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | 1994-12-08 |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1993-04-22 |
| Spill Record Last Update: | 1994-12-08 |
| Spiller Name: | Not reported |
| Spiller Company: | SAUCE & VIJAX OIL CO. |
| Spiller Address: | Not reported |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 12/08/94: CONTAM. SOIL REMOVED AND SAMPLES WHERE TAKEN. " |
| Remarks: | "CONTRACT HAULERS MAKING DELIVERIES FOR SOME TIME CUSTOMER CALLED RELIANCE ASSOC. COMPLANING ABOUT THE SPILLS OCCURRING EACH DELIVERY CALLER CLAIMS VENT WHISTLE NOT WORKING NOT SURE IF WHISTLE EXISTS" |

All Materials:

| | |
|---|---|
| Site ID: | 323531 |
| Operable Unit ID: | 979623 |
| Operable Unit: | 01 |
| Material ID: | 561763 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | Not reported |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**86**
**SE**
**1/4-1/2**
**0.332 mi.**
**1754 ft.**

**LEVY**
**7 ROOSEVELT AV**
**LARCHMONT, NY**

**NY LTANKS** **S103939848**
**N/A**

**Relative:**
**Higher**

**Actual:**
**52 ft.**

LTANKS:

| | |
|---|---|
| Name: | LEVY |
| Address: | 7 ROOSEVELT AV |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9601585 / 1996-06-12 |
| Facility ID: | 9601585 |
| Site ID: | 215731 |
| Spill Date: | 1996-04-30 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1996-05-01 |
| CID: | 297 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1996-05-01 |
| Spill Record Last Update: | 2000-03-03 |
| Spiller Name: | RICHARD LEVY |
| Spiller Company: | RICHARD LEVY |
| Spiller Address: | 7 ROOSEVELT AV |
| Spiller County: | 001 |
| Spiller Contact: | THOMAS KUNKEL |
| Spiller Phone: | (914) 762-9223 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 178660 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/12/96 TANK & CONTAMINATED SOIL REMOVED" |
| Remarks: | "COMP'S COMPANY WAS CALLED TO REMOVE A TANK AND DISCOVERED IT WAS LEAKING - COMP'S COMPANY WILL CLEAN UP AREA" |

All Materials:

| | |
|---|---|
| Site ID: | 215731 |
| Operable Unit ID: | 1033139 |
| Operable Unit: | 01 |
| Material ID: | 351387 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 10.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**87**
**NE**
**1/4-1/2**
**0.332 mi.**
**1755 ft.**

**DILIETO HOME**
**104 LAUREL AVE**
**LARCHMONT, NY**

**NY LTANKS** **S106971904**
**N/A**

**Relative:**
**Higher**

**Actual:**
**49 ft.**

LTANKS:

| | |
|---|---|
| Name: | DILIETO HOME |
| Address: | 104 LAUREL AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0502224 / 2006-08-11 |
| Facility ID: | 0502224 |
| Site ID: | 346541 |
| Spill Date: | 2005-05-25 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | Not reported |
| Reported to Dept: | 2005-05-25 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2005-05-25 |
| Spill Record Last Update: | 2006-08-11 |
| Spiller Name: | DILIETO HOME |
| Spiller Company: | DILIETO HOME |
| Spiller Address: | 104 LAUREL AVE |
| Spiller County: | 001 |
| Spiller Contact: | DILIETO HOME |
| Spiller Phone: | (347) 672-0146 |
| Spiller Extention: | CELL |
| DEC Region: | 3 |
| DER Facility ID: | 292801 |
| DEC Memo: | "5/25/05 NES REMOVED ONE 550 GALLON LUST. NES SUBMITTED PROPOSAL FOR REMEDIATION. jod 6/10/05 NES RETURNED TO SITE AND REMOVED AND DISPOSED OF 2.15 TONS OF STOCKPILED CONTAMINATED SOIL. TANK GRAVE HAD ALREADY BEEN BACKFILLED. UNKNOWN IF ALL CONTAMINATION WAS EXCAVATED OR IF ANY EXIT SAMPLES TAKEN AT THIS TIME. KEVIN MOORE OF MAMARONECK BLDG DEPT TO FOLLOW UP. jod August 11, 2006: NES DISPOSED OF LUST AND 2.15 TONS OF CONTAMINATED SOIL. CLOSURE REPORT RECEIVED FROM S.I.T.E.S. REMEDIATION. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod" |
| Remarks: | "550 gallon tank had holes in it found while removing" |

All Materials:

| | |
|---|---|
| Site ID: | 346541 |
| Operable Unit ID: | 1104310 |
| Operable Unit: | 01 |
| Material ID: | 584489 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |

**DILIETO HOME (Continued)** **S106971904**

| | |
|---|---|
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**R88** **PRIVATE DWELLING** **NY LTANKS** **S111836562**
**South** **212 LARCHMONT AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.334 mi.**
**1766 ft.** **Site 1 of 2 in cluster R**

**Relative:** **Higher**

**Actual:** **54 ft.**

LTANKS:

| | |
|---|---|
| Name: | PRIVATE DWELLING |
| Address: | 212 LARCHMONT AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1201667 / 2012-08-20 |
| Facility ID: | 1201667 |
| Site ID: | 464390 |
| Spill Date: | 2012-05-21 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2012-05-21 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2012-05-21 |
| Spill Record Last Update: | 2012-08-20 |
| Spiller Name: | Not reported |
| Spiller Company: | MR GRECO |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | OWNER |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 418780 |
| DEC Memo: | "5-21-12 Refer to 12-01664. NFA jm 8/20/2012: HVEC removed and disposed of tank. No evidence of leak or contamination was found. Closure report entered into eDocs. Closure report mentions a post-ex soil sample, but no sample results were included. Message sent to HVEC requesting they forward a copy of the sample. Based upon information provided to DEC, no further action is required at this time. jod" |
| Remarks: | "1000G TANK -TEST FAIL" |

All Materials:

**PRIVATE DWELLING (Continued)** **S111836562**

| | |
|---|---|
| Site ID: | 464390 |
| Operable Unit ID: | 1214442 |
| Operable Unit: | 01 |
| Material ID: | 2212485 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**R89** **GRECO DWELLING** **NY LTANKS** **S111836561**
**South** **212 LARCHMONT AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.334 mi.**
**1766 ft.** **Site 2 of 2 in cluster R**

**Relative:** **Higher**
**Actual:** **54 ft.**

LTANKS:

| | |
|---|---|
| Name: | GRECO DWELLING |
| Address: | 212 LARCHMONT AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1201664 / 2012-08-20 |
| Facility ID: | 1201664 |
| Site ID: | 464387 |
| Spill Date: | 2012-05-21 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2012-05-21 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2012-05-21 |
| Spill Record Last Update: | 2012-08-20 |
| Spiller Name: | Not reported |
| Spiller Company: | MR GRECO |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | OWNER |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 418780 |
| DEC Memo: | "5-21-12 Spoke with Kathy. Tank test failed with popping sound. This is a real estate transaction and was being performed by potential buyer. Homeowner has ProGuard Insurance which will cover tank removal |

**GRECO DWELLING (Continued)** **S111836561**

so tank will most likely be removed. jm 6-19-12: Kathy/US Tk.Tech. call to Dispt./V.Mc.: UST failed re-test. 8/20/2012: HVEC removed and disposed of tank. No evidence of leak or contamination was found. Closure report entered into eDocs. Closure report mentions a post-ex soil sample, but no sample results were included. Message sent to HVEC requesting they forward a copy of the sample. Based upon information provided to DEC, no further action is required at this time. jod"

Remarks: "1000G TANK -TEST FAIL"

All Materials:

| | |
|---|---|
| Site ID: | 464387 |
| Operable Unit ID: | 1214439 |
| Operable Unit: | 01 |
| Material ID: | 2212481 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**90 WSW 1/4-1/2 0.340 mi. 1794 ft.** **LARCHMONT AUTO GARAGE** **NY LTANKS** **S102619320**
**5TH AV & MADISON** **N/A**
**LARCHMONT, NY**

**Relative: Lower**

**Actual: 29 ft.**

LTANKS:

| | |
|---|---|
| Name: | LARCHMONT AUTO GARAGE |
| Address: | 5TH AV & MADISON |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9611599 / 1996-12-23 |
| Facility ID: | 9611599 |
| Site ID: | 249760 |
| Spill Date: | 1996-12-21 |
| Spill Cause: | Tank Failure |
| Spill Source: | Unknown |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1996-12-21 |
| CID: | 365 |
| Water Affected: | Not reported |
| Spill Notifier: | Police Department |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1996-12-21 |
| Spill Record Last Update: | 1997-06-23 |
| Spiller Name: | Not reported |

**LARCHMONT AUTO GARAGE (Continued)** **S102619320**

| | |
|---|---|
| Spiller Company: | FRANK AVRICCNIO |
| Spiller Address: | 633 FIFTH AVE. |
| Spiller County: | 001 |
| Spiller Contact: | FIRE DEPT |
| Spiller Phone: | (914) 834-2101 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 204743 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 12/23/96 SAME AS SPILL # 9611598 " |
| Remarks: | "SMALL SPILL OF FUEL OIL AND GASOLINE THAT MAY HAVE POSSIBLY GOTTEN INTO THE SEWER FIRE DEPT WOULD LIKE A RESPONSE" |

All Materials:

| | |
|---|---|
| Site ID: | 249760 |
| Operable Unit ID: | 1042970 |
| Operable Unit: | 01 |
| Material ID: | 340259 |
| Material Code: | 0009 |
| Material Name: | gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Site ID: | 249760 |
| Operable Unit ID: | 1042970 |
| Operable Unit: | 01 |
| Material ID: | 340258 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**91**
**SW**
**1/4-1/2**
**0.341 mi.**
**1798 ft.**

**LARCHMONT/MAMARONECK JOINT GARBAGE DISPOSAL COMMIS** **NY SWF/LF** **S117692106**
**41 MAXWELL AVENUE(LOCATION)** **N/A**
**MAMARONECK, NY 10543**

**Relative:**
**Lower**

**Actual:**
**29 ft.**

SWF/LF:

| | |
|---|---|
| Name: | LARCHMONT/MAMARONECK JOINT GARBAGE DISPOSAL COMMISSION |
| Address: | 41 MAXWELL AVENUE(LOCATION) |
| City,State,Zip: | MAMARONECK, NY 10543 |
| Flag: | ACTIVE |
| Region Code: | 3 |
| Phone Number: | 9143817810 |
| Owner Name: | Town of Mamaroneck |
| Owner Type: | Municipal |
| Owner Address: | 123 Mamaroneck Avenue |
| Owner Addr2: | Not reported |

**LARCHMONT/MAMARONECK JOINT GARBAGE DISPOSAL COMMISSION (Continued)** **S117692106**

| | |
|---|---|
| Owner City,St,Zip: | Mamaroneck, NY 10543 |
| Owner Email: | Not reported |
| Owner Phone: | 9147777703 |
| Contact Name: | Steven Altieri |
| Contact Address: | 740 West Boston Post Rd |
| Contact Addr2: | Not reported |
| Contact City,St,Zip: | Mamaroneck, NY 10543 |
| Contact Email: | tiacovelli@vomny.org |
| Contact Phone: | 9147777745 |
| Activity Desc: | Transfer station - registration |
| Activity Number: | [60R36] |
| Active: | Yes |
| East Coordinate: | 604102 |
| North Coordinate: | 4531983 |
| Accuracy Code: | Not reported |
| Regulatory Status: | Registration |
| Waste Type: | Not reported |
| Authorization #: | 60R36 |
| Authorization Date: | Not reported |
| Expiration Date: | Not reported |
| Operator Name: | Not reported |
| Operator Type: | Not reported |
| Laste Date: | Not reported |

---

**92**
**NW**
**1/4-1/2**
**0.342 mi.**
**1807 ft.**

**VERNER RES** **NY LTANKS** **S106703846**
**46 ECHO LN** **N/A**
**LARCHMONT, NY**

**Relative:**
**Higher**

**Actual:**
**98 ft.**

LTANKS:

| | |
|---|---|
| Name: | VERNER RES |
| Address: | 46 ECHO LN |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9802021 / 1998-06-15 |
| Facility ID: | 9802021 |
| Site ID: | 160747 |
| Spill Date: | 1998-05-15 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1998-05-15 |
| CID: | 233 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-05-15 |
| Spill Record Last Update: | 2003-08-27 |
| Spiller Name: | VERNER |
| Spiller Company: | VERNER RES |

**VERNER RES (Continued)** **S106703846**

| | |
|---|---|
| Spiller Address: | 46 ECHO LN |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 135724 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/15/98 TANK TECH TANK PASSED TEST" |
| Remarks: | "tank is u/g at the residence " |

All TTF:

| | |
|---|---|
| Facility ID: | 9802021 |
| Spill Number: | 9802021 |
| Spill Tank Test: | 1545903 |
| Site ID: | 160747 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 160747 |
| Operable Unit ID: | 1059925 |
| Operable Unit: | 01 |
| Material ID: | 323927 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**93** **BEN BEDERSON TTF** **NY LTANKS** **S101340431**
**SE** **8 HALL AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.343 mi.**
**1810 ft.**

**Relative:** **Lower**

**Actual:** **28 ft.**

LTANKS:

| | |
|---|---|
| Name: | BEN BEDERSON TTF |
| Address: | 8 HALL AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9410735 / 1995-02-13 |
| Facility ID: | 9410735 |
| Site ID: | 146635 |

**BEN BEDERSON TTF (Continued)** **S101340431**

| | |
|---|---|
| Spill Date: | 1994-11-11 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | 1995-02-13 |
| SWIS: | 6032 |
| Investigator: | MONACO |
| Referred To: | Not reported |
| Reported to Dept: | 1994-11-11 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1994-11-16 |
| Spill Record Last Update: | 2017-01-06 |
| Spiller Name: | Not reported |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 489163 |
| DEC Memo: | ". 1/6/17: File pulled from archives for FOIL. File scanned to PDF and entered into DecDocs. Hard copy file discarded. jod Also see Spill 1607551" |
| Remarks: | "SHUT OFF BURNER SUSPECT LINE LEAK WILL INVESTIGATE" |

All TTF:

| | |
|---|---|
| Facility ID: | 9410735 |
| Spill Number: | 9410735 |
| Spill Tank Test: | 1543338 |
| Site ID: | 146635 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 146635 |
| Operable Unit ID: | 1004645 |
| Operable Unit: | 01 |
| Material ID: | 376603 |

**BEN BEDERSON TTF (Continued)** **S101340431**

| | |
|---|---|
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | Not reported |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**S94** **MOCCIA - TTF** **NY LTANKS** **S104620453**
**North** **23 DANTE ST** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.348 mi.**
**1840 ft.** **Site 1 of 2 in cluster S**

**Relative:**
**Higher**

**Actual:**
**91 ft.**

LTANKS:

| | |
|---|---|
| Name: | MOCCIA - TTF |
| Address: | 23 DANTE ST |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9906899 / 2000-01-10 |
| Facility ID: | 9906899 |
| Site ID: | 299008 |
| Spill Date: | 1999-09-09 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-09-09 |
| CID: | 270 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-09-09 |
| Spill Record Last Update: | 2016-06-14 |
| Spiller Name: | ALFRED MOCCIA |
| Spiller Company: | Alfred Moccia |
| Spiller Address: | 23 DANTE ST |
| Spiller County: | 001 |
| Spiller Contact: | ALFRED MOCCIA |
| Spiller Phone: | (914) 834-6595 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 241911 |
| DEC Memo: | "01/10/2000 NORTHEAST PULLED TANK AND DISPOSED OF THREE DOT DRUMS OF CONTAMINATED SOIL. NFA" |
| Remarks: | "uncover repair retest" |

All TTF:

| | |
|---|---|
| Facility ID: | 9906899 |
| Spill Number: | 9906899 |

**MOCCIA - TTF (Continued)** **S104620453**

| | |
|---|---|
| Spill Tank Test: | 1547601 |
| Site ID: | 299008 |
| Tank Number: | 1 |
| Tank Size: | 1000 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 299008 |
| Operable Unit ID: | 1085324 |
| Operable Unit: | 01 |
| Material ID: | 560652 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**95**
**NNW**
**1/4-1/2**
**0.354 mi.**
**1869 ft.**

**CONDON HOME**
**16 ORSINI DRIVE**
**LARCHMONT, NY**

**NY LTANKS** **S108467757**
**N/A**

**Relative:**
**Higher**

**Actual:**
**87 ft.**

LTANKS:

| | |
|---|---|
| Name: | CONDON HOME |
| Address: | 16 ORSINI DRIVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0612662 / 2007-03-29 |
| Facility ID: | 0612662 |
| Site ID: | 377553 |
| Spill Date: | 2007-02-22 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2007-02-22 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |

**CONDON HOME (Continued)** **S108467757**

| | |
|---|---|
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2007-02-22 |
| Spill Record Last Update: | 2007-03-29 |
| Spiller Name: | DOROTHY CONDON |
| Spiller Company: | CONDON HOME |
| Spiller Address: | 16 ORSNNIE DRIVE |
| Spiller County: | 001 |
| Spiller Contact: | DOROTHY CONDON |
| Spiller Phone: | (914) 834-0340 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 327092 |
| DEC Memo: | "03/09/07 Northeast Environmental reported that the tank was removed and that no contaminated soil was observed in the tank grave. Confirmed by lab analysis of a soil sample. NFA TG" |
| Remarks: | "removal:" |

All TTF:

| | |
|---|---|
| Facility ID: | 0612662 |
| Spill Number: | 0612662 |
| Spill Tank Test: | 1550648 |
| Site ID: | 377553 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 377553 |
| Operable Unit ID: | 1135083 |
| Operable Unit: | 01 |
| Material ID: | 2124977 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**96**
**WNW**
**1/4-1/2**
**0.355 mi.**
**1875 ft.**

**SPILL NUMBER 9913035**
**54 LOOKOUT CIRCLE**
**LARCHMONT, NY**

**NY LTANKS** **S104620848**
**N/A**

**Relative:**
**Higher**

**Actual:**
**107 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9913035 |
| Address: | 54 LOOKOUT CIRCLE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9913035 / 2000-06-01 |
| Facility ID: | 9913035 |
| Site ID: | 289288 |
| Spill Date: | 2000-02-16 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2000-02-16 |
| CID: | 366 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2000-02-16 |
| Spill Record Last Update: | 2000-06-02 |
| Spiller Name: | Not reported |
| Spiller Company: | BONNIE BECK |
| Spiller Address: | 54 LOOKOUT CIRCLE |
| Spiller County: | 001 |
| Spiller Contact: | BONNIE BECK |
| Spiller Phone: | (911) 483-4170 |
| Spiller Extention: | 6 |
| DEC Region: | 3 |
| DER Facility ID: | 234257 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/01/2000 CASTLTON DISPOSED OF TANK AND 3.96 TONS OF CONTAMINATED SOIL. DORSON ENVIRONMENTAL PROVIDED OVERSITE. DORSON REPORTS NO HOLES WERE FOUND IN TANK, PROBLEM WAS IN PIPING. CLEANUP COMPLETED. NFA" |
| Remarks: | "CALLER REPORTING THAT THEY WERE REMOVING AN UST AND FOUND HOLES IN THAT TANK AND CONTAMINATED SOIL. SAMPLES TAKEN FROM SOIL AND CLEAN UP PENDING RESULTS." |

All Materials:

| | |
|---|---|
| Site ID: | 289288 |
| Operable Unit ID: | 1091751 |
| Operable Unit: | 01 |
| Material ID: | 563422 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |

**SPILL NUMBER 9913035 (Continued)** **S104620848**

Units: G
Recovered: .00
Oxygenate: Not reported

---

**S97** **SLATTERY RESIDENCE** **NY LTANKS** **S108765620**
**North** **25 DANTE ST** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.356 mi.**
**1880 ft.** **Site 2 of 2 in cluster S**

**Relative:**
**Higher**

**Actual:**
**90 ft.**

LTANKS:

| | |
|---|---|
| Name: | SLATTERY RESIDENCE |
| Address: | 25 DANTE ST |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0705870 / 2007-09-25 |
| Facility ID: | 0705870 |
| Site ID: | 386276 |
| Spill Date: | 2007-08-23 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2007-08-23 |
| CID: | 408 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2007-08-23 |
| Spill Record Last Update: | 2007-09-25 |
| Spiller Name: | SUZANNE SLATTERY |
| Spiller Company: | PRIVATE HOME |
| Spiller Address: | 25 DANTE ST |
| Spiller County: | 001 |
| Spiller Contact: | SUZANNE SLATTERY |
| Spiller Phone: | (914) 834-0145 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 335659 |
| DEC Memo: | "08/27/07 Northeast Environmental reported that the tank was removed along with 4 drums of PCS. NFA TG" |
| Remarks: | "DURING TANK REMOVAL HOLES FOUND IN TANK AND CONTAMINATED SOIL DISCOVERED;" |

All TTF:

| | |
|---|---|
| Facility ID: | 0705870 |
| Spill Number: | 0705870 |
| Spill Tank Test: | 1551104 |
| Site ID: | 386276 |
| Tank Number: | Not reported |
| Tank Size: | 1000 |

**SLATTERY RESIDENCE (Continued)** **S108765620**

| | |
|---|---|
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 386276 |
| Operable Unit ID: | 1143514 |
| Operable Unit: | 01 |
| Material ID: | 2133794 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**98**
**SSE**
**1/4-1/2**
**0.358 mi.**
**1891 ft.**

**SPILL NUMBER 0205284** **NY LTANKS** **S105996560**
**60 CHATSWORTH AVE** **N/A**
**LARCHMONT, NY**

**Relative:**
**Higher**

**Actual:**
**56 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 0205284 |
| Address: | 60 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0205284 / 2002-09-11 |
| Facility ID: | 0205284 |
| Site ID: | 98006 |
| Spill Date: | 2002-08-20 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2002-08-20 |
| CID: | 207 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |

**SPILL NUMBER 0205284 (Continued)** **S105996560**

| | |
|---|---|
| Date Entered In Computer: | 2002-08-20 |
| Spill Record Last Update: | 2002-09-12 |
| Spiller Name: | NICK BARNABA |
| Spiller Company: | CUFF |
| Spiller Address: | 60 CHATSWORTH AVE |
| Spiller County: | 001 |
| Spiller Contact: | NICK BARNABA |
| Spiller Phone: | (914) 777-1930 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 87243 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE NORTHEAST COMPLETED CLEANUP. 3-DRUMS OF MATERIAL. NFA" |
| Remarks: | "cleanup in progress " |

All Materials:

| | |
|---|---|
| Site ID: | 98006 |
| Operable Unit ID: | 856736 |
| Operable Unit: | 01 |
| Material ID: | 519484 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 10.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**99**
**NNE**
**1/4-1/2**
**0.361 mi.**
**1907 ft.**

**RESIDENCE**
**41 MYRTLE BLVD**
**LARCHMONT, NY**

**NY LTANKS** **S107410616**
**N/A**

**Relative: Higher**

**Actual: 49 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 41 MYRTLE BLVD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0507572 / 2006-08-09 |
| Facility ID: | 0507572 |
| Site ID: | 353041 |
| Spill Date: | 2005-09-23 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2005-09-23 |
| CID: | 407 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |

**RESIDENCE (Continued)** **S107410616**

| | |
|---|---|
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2005-09-26 |
| Spill Record Last Update: | 2006-08-09 |
| Spiller Name: | ADELE PELELLA |
| Spiller Company: | RESIDENCE |
| Spiller Address: | 41 MYTLE BLVD |
| Spiller County: | 001 |
| Spiller Contact: | ADELE PELELLA |
| Spiller Phone: | (914) 632-5199 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 300340 |
| DEC Memo: | "11/4/05 Ms. Pelella called. NES has been doing the remediation. They pulled 550 gal UST, and installed MW due to GW contamination. NES has used bioremediation on the site. Property is for sale, and owner was inquiring about spill closure. Referred her to John O'Dee. 04/07/06 Scott Tqylor from NES reported that excavation was limited by the location of the tank so all the contaminated soil couldn't be removed. Plans include drilling upgradient wells and injecting Micro Bac 1000H to promote degradation of the residual oil effects. TG 07/27/06 National Environmental Specialists submitted agroundwater remediation report. Based on the reduction of voc in the groundwater, NFA required. TG" |
| Remarks: | "" |

All TTF:

| | |
|---|---|
| Facility ID: | 0507572 |
| Spill Number: | 0507572 |
| Spill Tank Test: | 1549336 |
| Site ID: | 353041 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 353041 |
| Operable Unit ID: | 1110511 |
| Operable Unit: | 01 |
| Material ID: | 2100542 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |

**RESIDENCE (Continued)** **S107410616**

Oxygenate: Not reported

---

**100 NW 1/4-1/2 0.364 mi. 1921 ft.** **MAUGUE HOME** **23 MAPLEWOOD STREET** **LARCHMONT, NY** **NY LTANKS** **S106385747 N/A**

**Relative: Higher**

**Actual: 90 ft.**

LTANKS:

| | |
|---|---|
| Name: | PRIVATE RESIDENCE |
| Address: | 23 MAPLEWOOD STREET |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0400048 / 2004-06-04 |
| Facility ID: | 0400048 |
| Site ID: | 316083 |
| Spill Date: | 2004-04-02 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-04-02 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-04-02 |
| Spill Record Last Update: | 2004-06-04 |
| Spiller Name: | REALTY SMITH |
| Spiller Company: | PRIVATE RESIDENCE |
| Spiller Address: | 23 MAPLEWOOD STREET |
| Spiller County: | 001 |
| Spiller Contact: | REALTY SMITH |
| Spiller Phone: | (914) 834-1070 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 254817 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE Estate of Betzig; Phyllis Jacobs: 834-0270; Bill Betzig: C:716-903-0291 06/04/04 ELITE ENVIRONMENTAL DISPOSED OF LUST AND 87.52 TONS OF CONTAMINATED SOIL. SOME RESIDUAL CONTAMINATION COULD NOT BE EXCAVATED DUE TO STRUCTURAL CONSIDERATIONS. SAMPLE RESULTS WERE BELOW TAGM LEVELS. BASED UPON REPORT SUBMITTED, DEC REQUIRES NO FURTHER ACTION AT THIS TIME. jbo" |
| Remarks: | "RECOMMEND: EXPOSE AND RETEST: " |

All TTF:

| | |
|---|---|
| Facility ID: | 0400048 |
| Spill Number: | 0400048 |
| Spill Tank Test: | 1529120 |
| Site ID: | 316083 |

**MAUGUE HOME (Continued)** **S106385747**

| | |
|---|---|
| Tank Number: | Not reported |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 316083 |
| Operable Unit ID: | 882383 |
| Operable Unit: | 01 |
| Material ID: | 494842 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | MAUGUE HOME |
| Address: | 23 MAPLEWOOD STREET |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0509152 / 2005-10-31 |
| Facility ID: | 0509152 |
| Site ID: | 354880 |
| Spill Date: | 2005-10-13 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | Not reported |
| Reported to Dept: | 2005-10-31 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2005-10-31 |
| Spill Record Last Update: | 2005-11-01 |
| Spiller Name: | LANCE |
| Spiller Company: | TERRICONE FUEL |
| Spiller Address: | 59 MAIN STREET |

**MAUGUE HOME (Continued)** **S106385747**

| | |
|---|---|
| Spiller County: | 001 |
| Spiller Contact: | PAT MAUGUE |
| Spiller Phone: | (914) 834-2027 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 304949 |
| DEC Memo: | "Madison Environmental finished cleanup. NFA." |
| Remarks: | "SAMLL OVERFILL, WAS CLEANED UP AND NOW GOING BACK TO FINISH:" |

All Materials:

| | |
|---|---|
| Site ID: | 354880 |
| Operable Unit ID: | 1112267 |
| Operable Unit: | 01 |
| Material ID: | 2102309 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 5.00 |
| Units: | G |
| Recovered: | 5.00 |
| Oxygenate: | Not reported |

---

**101 South 1/4-1/2 0.372 mi. 1963 ft.**

**SPRINGER RESIDENCE**
**200 LARCHMONT AVE**
**LARCHMONT, NY**

**NY LTANKS** **S106472146**
**N/A**

**Relative: Higher**

**Actual: 48 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPRINGER RESIDENCE |
| Address: | 200 LARCHMONT AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0404212 / 2004-10-28 |
| Facility ID: | 0404212 |
| Site ID: | 328692 |
| Spill Date: | 2004-07-20 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-07-20 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-07-20 |
| Spill Record Last Update: | 2004-10-28 |
| Spiller Name: | PHILIP SPRINGER |
| Spiller Company: | SPRINGER RESIDENCE |

**SPRINGER RESIDENCE (Continued)** **S106472146**

| | |
|---|---|
| Spiller Address: | 200 LARCHMONT AVE |
| Spiller County: | 001 |
| Spiller Contact: | PHILIP SPRINGER |
| Spiller Phone: | (914) 833-0918 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 264526 |
| DEC Memo: | "10/28/04 NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 39.11 TONS OF CONTAMINATED SOIL. GROUND WATER WAS IMPACTED. HES COMPLETED GROUND WATER SAMPLING AND SUBMITTED CLOSURE REPORT. BASED UPON THE INFORMATION SUPPLIED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo" |
| Remarks: | "1000 GALLON TANK HAD HOLES WHILE REMOVING: " |

All Materials:

| | |
|---|---|
| Site ID: | 328692 |
| Operable Unit ID: | 887441 |
| Operable Unit: | 01 |
| Material ID: | 488223 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | L |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**102 South 1/4-1/2 0.373 mi. 1971 ft.**

**GLASS RESIDENCE**
**5 IDEN AVE**
**LARCHMONT, NY**

**NY LTANKS** **S105995703**
**N/A**

**Relative: Higher**

**Actual: 49 ft.**

LTANKS:

| | |
|---|---|
| Name: | GLASS RESIDENCE |
| Address: | 5 IDEN AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0200914 / 2002-05-29 |
| Facility ID: | 0200914 |
| Site ID: | 174074 |
| Spill Date: | 2002-04-24 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2002-04-24 |
| CID: | 196 |
| Water Affected: | Not reported |
| Spill Notifier: | Affected Persons |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |

**GLASS RESIDENCE (Continued)** **S105995703**

| | |
|---|---|
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2002-04-24 |
| Spill Record Last Update: | 2002-06-25 |
| Spiller Name: | MR GLASS |
| Spiller Company: | MR GLASS |
| Spiller Address: | 5 IDEN AVE |
| Spiller County: | 001 |
| Spiller Contact: | KEITH TROCCOLI |
| Spiller Phone: | (914) 278-4067 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 146427 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/24/02 1,000 GAL UST. CONTAMINATION DETECTED BELOW UST. 05/29/02 CLOSURE REPORT RECEIVED FROM JM ASSOCIATES. DUTCHESS DISPOSED OF 77.92 TONS OF CONTAMINATED SOIL. NFA" |
| Remarks: | "found holes inside the tank - unknown amount leaked - plan it to remove the tank at a later date." |

All Materials:

| | |
|---|---|
| Site ID: | 174074 |
| Operable Unit ID: | 854360 |
| Operable Unit: | 01 |
| Material ID: | 522343 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**103** **ST. JOHN'S** **NY LTANKS** **S100139496**
**NNE** **280 WEAVER ST.** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.380 mi.**
**2009 ft.**

**Relative:**
**Higher**

**Actual:**
**74 ft.**

LTANKS:

| | |
|---|---|
| Name: | ST JOHN AND PAUL CATHOLIC CHURCH |
| Address: | 280 WEAVER ST |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1205086 / 2013-05-07 |
| Facility ID: | 1205086 |
| Site ID: | 468002 |
| Spill Date: | 2012-08-20 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2012-08-20 |
| CID: | Not reported |
| Water Affected: | Not reported |

**ST. JOHN'S (Continued)** **S100139496**

| | |
|---|---|
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2012-08-20 |
| Spill Record Last Update: | 2013-05-07 |
| Spiller Name: | JAMES WILSON (RNB SERVICES) |
| Spiller Company: | PROPERTY OWNER |
| Spiller Address: | 280 WEAVER ST |
| Spiller County: | 999 |
| Spiller Contact: | JAMES WILSON (RNB SERVICES) |
| Spiller Phone: | 8453486355 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 422298 |
| DEC Memo: | "8-20-12 Confirmed wet leak. Preparing a proposal for uncover repair. Proposal will include emptying of tank. Advised to empty now. WCHD aware of test, but not on site for it. 3-137065. Other tanks on site also being tested today. jc 5/7/2013: Tank closure report submitted to WCDoH PBS. Wayne Schneider reports: 280 weaver St, Larchmont- ttf. tank and most of contamination removed except for remnant at/under building foundation. Downgradient well borings to bedrock showed no contamination.(nfa letter attached) *Based upon the information provided, DEC requires no further action at this time. See EDocs for WCDoH closure letter. jod " |
| Remarks: | "" |

All Materials:

| | |
|---|---|
| Site ID: | 468002 |
| Operable Unit ID: | 1217936 |
| Operable Unit: | 01 |
| Material ID: | 2216286 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | ST JOHN & PAUL CHARGE |
| Address: | 280 WEAVER STREET |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0310652 / 2004-01-16 |
| Facility ID: | 0310652 |
| Site ID: | 123833 |
| Spill Date: | 2003-12-16 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | WCHD |
| Referred To: | Westchester Cnty Health Dept |

**ST. JOHN'S (Continued)** **S100139496**

| | |
|---|---|
| Reported to Dept: | 2003-12-16 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-12-16 |
| Spill Record Last Update: | 2004-01-26 |
| Spiller Name: | Not reported |
| Spiller Company: | TOWN & COUNTRY OIL |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | SUSAN LUGO |
| Spiller Phone: | (914) 668-5300 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 107326 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-SCHNEIDER 01-14-04 LETTER FROM NORTHEAST RECEIVED. CLEANUP CONSISTED OF EXCAVATING 9 DRUMS OF CONTAMINATED SOIL. NFA TG" |
| Remarks: | "driver noticed the oil came out of pipe, Northeast Enviormental is on scene. Phone # 914-777-1930. it was a spray of oil not a large amount and all contained." |

All Materials:

| | |
|---|---|
| Site ID: | 123833 |
| Operable Unit ID: | 878315 |
| Operable Unit: | 01 |
| Material ID: | 499502 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | L |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | ST. JOHN'S |
| Address: | 280 WEAVER ST. |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 8705481 / 1988-07-27 |
| Facility ID: | 8705481 |
| Site ID: | 246329 |
| Spill Date: | 1987-09-29 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | Not reported |
| Cleanup Ceased: | 1988-01-20 |
| SWIS: | 6000 |
| Investigator: | jeokesso |
| Referred To: | Not reported |
| Reported to Dept: | 1987-09-29 |
| CID: | Not reported |

**ST. JOHN'S (Continued)** **S100139496**

| | |
|---|---|
| Water Affected: | NONE |
| Spill Notifier: | Tank Tester |
| Last Inspection: | 1988-01-20 |
| Recommended Penalty: | True |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1987-10-05 |
| Spill Record Last Update: | 1988-07-27 |
| Spiller Name: | Not reported |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 202304 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : 9/29/87-TO EXCAVATE,ISOLATE AND RETEST. 07/27/88: RETEST PASSED. " |
| Remarks: | "TTTF; -.189 GAL/HR" |

All TTF:

| | |
|---|---|
| Facility ID: | 8705481 |
| Spill Number: | 8705481 |
| Spill Tank Test: | 1531765 |
| Site ID: | 246329 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 246329 |
| Operable Unit ID: | 909320 |
| Operable Unit: | 01 |
| Material ID: | 468080 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**104**
**NW**
**1/4-1/2**
**0.383 mi.**
**2020 ft.**

**MOSER RESIDENCE**
**161 MURRAY AVE**
**LARCHMONT, NY**

**NY LTANKS** **S109943812**
**N/A**

**Relative:**
**Higher**

**Actual:**
**87 ft.**

LTANKS:

| | |
|---|---|
| Name: | MOSER RESIDENCE |
| Address: | 161 MURRAY AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0907297 / 2009-12-22 |
| Facility ID: | 0907297 |
| Site ID: | 419812 |
| Spill Date: | 2009-09-29 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2009-09-29 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2009-09-29 |
| Spill Record Last Update: | 2009-12-22 |
| Spiller Name: | STEPHEN MOSER |
| Spiller Company: | STEPHEN MOSER |
| Spiller Address: | 161 MURRAY AVE |
| Spiller County: | 999 |
| Spiller Contact: | DON PYATT |
| Spiller Phone: | (973) 390-6675 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 368851 |
| DEC Memo: | "9-29-09 Called and left message for Don to return my call. jm 12/22/09: Closure report from Advanced Environmental reviewed and entered into eDocs. Based upon the information provided, no further action is required at this time. jod" |
| Remarks: | "TANK TEST FAILURE ON A 1000 GALLON UST." |

All Materials:

| | |
|---|---|
| Site ID: | 419812 |
| Operable Unit ID: | 1175811 |
| Operable Unit: | 01 |
| Material ID: | 2168447 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

**105**
**ESE**
**1/4-1/2**
**0.383 mi.**
**2024 ft.**

**BIRDVELL RESIDENCE**
**4 FOREST PARK AVE**
**LARCHMONT, NY**

**NY LTANKS** **S105997452**
**N/A**

**Relative:**
**Lower**

**Actual:**
**23 ft.**

LTANKS:

| | |
|---|---|
| Name: | BIRDVELL RESIDENCE |
| Address: | 4 FOREST PARK AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0208984 / 2003-02-27 |
| Facility ID: | 0208984 |
| Site ID: | 249561 |
| Spill Date: | 2002-12-02 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2002-12-02 |
| CID: | 205 |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2002-12-02 |
| Spill Record Last Update: | 2003-09-02 |
| Spiller Name: | CALLER |
| Spiller Company: | BIRDVELL RES |
| Spiller Address: | 4 FOREST PARK AVE |
| Spiller County: | 001 |
| Spiller Contact: | CALLER |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 204580 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/27/03 ENVIROSTAR DISPOSED OF TANK AND 48.88 TONS CONTAMIN SOIL. GW WAS IMPACTED, MON WELL INSTALLED AND SAMPLED. NFA." |
| Remarks: | "PULLED TANK AND ENCOUNTERED CONTAMINATED SOIL. STOCKPILING NOW." |

All Materials:

| | |
|---|---|
| Site ID: | 249561 |
| Operable Unit ID: | 860411 |
| Operable Unit: | 01 |
| Material ID: | 515974 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**T106**
**SE**
**1/4-1/2**
**0.384 mi.**
**2028 ft.**

**MARTIN RES**
**16 FOREST PARK AVE**
**LARCHMONT, NY**

**Site 1 of 2 in cluster T**

**NY LTANKS** **S105995390**
**N/A**

**Relative:**
**Lower**

**Actual:**
**24 ft.**

LTANKS:

| | |
|---|---|
| Name: | MARTIN RES |
| Address: | 16 FOREST PARK AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0111809 / 2002-05-03 |
| Facility ID: | 0111809 |
| Site ID: | 206085 |
| Spill Date: | 2002-03-14 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2002-03-14 |
| CID: | 233 |
| Water Affected: | Not reported |
| Spill Notifier: | Affected Persons |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2002-03-14 |
| Spill Record Last Update: | 2002-06-04 |
| Spiller Name: | Not reported |
| Spiller Company: | MARTIN RES |
| Spiller Address: | 16 FOREST PARK AVE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 171138 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 05/03/02 - CLOSURE REPORT RECEIVED FROM HYDRO ENVIRO SOLUTIONS. LUST AND 25.58 TONS CONTAMIN REMOVED. NFA" |
| Remarks: | "CALLER WAS HIRE TO REMOVE AN U/ OIL TANK WHEN TANK WAS REMOVED CONTAMINATED SOIL WAS DISCOVERED SOIL WAS LEFT ON SITE SOIL SAMPLES HAVE BEEN SENT OUT TO BE TESTED " |

All Materials:

| | |
|---|---|
| Site ID: | 206085 |
| Operable Unit ID: | 848753 |
| Operable Unit: | 01 |
| Material ID: | 525828 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |

**MARTIN RES (Continued)** **S105995390**

Oxygenate: Not reported

---

**107**
**West**
**1/4-1/2**
**0.389 mi.**
**2054 ft.**

**RESIDENCE**
**1 FRANCE PLACE**
**LARCHMONT, NY**

**NY LTANKS** **S103559104**
**N/A**

**Relative:**
**Higher**

**Actual:**
**93 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 1 FRANCE PLACE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9812530 / 2000-01-13 |
| Facility ID: | 9812530 |
| Site ID: | 220361 |
| Spill Date: | 1999-01-11 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | WCHD |
| Referred To: | Westchester Cnty Health Dept |
| Reported to Dept: | 1999-01-11 |
| CID: | 371 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-01-11 |
| Spill Record Last Update: | 2000-02-04 |
| Spiller Name: | ROBERT KIRBY |
| Spiller Company: | RESIDENCE |
| Spiller Address: | 1 FRANCE PLACE |
| Spiller County: | 001 |
| Spiller Contact: | ROBERT KIRBY |
| Spiller Phone: | (914) 834-1453 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 182269 |
| DEC Memo: | "" |
| Remarks: | "TANK FAILED. HOMEOWNER CONTEMPLATING OPTIONS." |

All TTF:

| | |
|---|---|
| Facility ID: | 9812530 |
| Spill Number: | 9812530 |
| Spill Tank Test: | 1546735 |
| Site ID: | 220361 |
| Tank Number: | 1 |
| Tank Size: | 3000 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |

**RESIDENCE (Continued)** **S103559104**

| | |
|---|---|
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 220361 |
| Operable Unit ID: | 1073074 |
| Operable Unit: | 01 |
| Material ID: | 312811 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**T108** **RESIDENCE** **NY LTANKS** **S102234175**
**SE** **15 FOREST PARK AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.392 mi.**
**2068 ft.** **Site 2 of 2 in cluster T**

**Relative:** **Lower**

**Actual:** **24 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 15 FOREST PARK AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9505787 / 1996-09-10 |
| Facility ID: | 9505787 |
| Site ID: | 120940 |
| Spill Date: | 1995-08-10 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1995-08-10 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1995-08-14 |
| Spill Record Last Update: | 2003-08-27 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |

**RESIDENCE (Continued)** **S102234175**

| | |
|---|---|
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 104967 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: | "REMOVING CONTAMINATED SOIL FROM UNDER PORCH SHOULD BE DONE TOMORROW" |

All Materials:

| | |
|---|---|
| Site ID: | 120940 |
| Operable Unit ID: | 1020678 |
| Operable Unit: | 01 |
| Material ID: | 363776 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 30.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**109**
**ENE**
**1/4-1/2**
**0.395 mi.**
**2083 ft.**

**BEZ - TTF**
**72 HOWELL AVE**
**LARCHMONT, NY**

**NY LTANKS** **S128913964**
**N/A**

**Relative:**
**Lower**

**Actual:**
**37 ft.**

LTANKS:

| | |
|---|---|
| Name: | BEZ - TTF |
| Address: | 72 HOWELL AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0000190 / 2000-04-18 |
| Facility ID: | 0000190 |
| Site ID: | 231198 |
| Spill Date: | 2000-04-05 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2000-04-05 |
| CID: | 312 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2000-04-05 |
| Spill Record Last Update: | 2022-07-05 |

**BEZ - TTF (Continued)** **S128913964**

| | |
|---|---|
| Spiller Name: | MR BEZ |
| Spiller Company: | Bez Residence |
| Spiller Address: | 72 HOWELL AVE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 190527 |
| DEC Memo: | "04/18/2000 TANK PASSED RETEST. NFA" |
| Remarks: | "WILL REPAIR PIPING AND RETEST - ULLAGE FAILURE" |

All TTF:

| | |
|---|---|
| Facility ID: | 0000190 |
| Spill Number: | 0000190 |
| Spill Tank Test: | 1525448 |
| Site ID: | 231198 |
| Tank Number: | 001 |
| Tank Size: | 550 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 20 |
| Test Method 2: | USTest 2000/P/LL plus USTest 2000/U |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

---

**110 East 1/4-1/2 0.398 mi. 2101 ft.**

**GARRY RESIDENCE**
**7 MEADOW PL**
**LARCHMONT, NY**

**NY LTANKS** **S105994863**
**N/A**

**Relative: Lower**

**Actual: 38 ft.**

LTANKS:

| | |
|---|---|
| Name: | GARRY RESIDENCE |
| Address: | 7 MEADOW PL |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0109734 / 2002-02-04 |
| Facility ID: | 0109734 |
| Site ID: | 324496 |
| Spill Date: | 2002-01-08 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2002-01-08 |
| CID: | 390 |
| Water Affected: | Not reported |
| Spill Notifier: | Local Agency |
| Last Inspection: | Not reported |

**GARRY RESIDENCE (Continued)** **S105994863**

| | |
|---|---|
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2002-01-08 |
| Spill Record Last Update: | 2002-03-14 |
| Spiller Name: | BOB GARRY |
| Spiller Company: | GARRY RESIDENCE |
| Spiller Address: | 7 MEADOW PL |
| Spiller County: | 001 |
| Spiller Contact: | BOB GARRY |
| Spiller Phone: | (914) 833-1601 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 261376 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 01/08/2002 550 U/G TANK HAD HOLES WHEN REMOVED. STOCKPILING SOIL. STATE FARM INSURANCE TO HANDLE. 02/04/2002 HYDRO ENVIRONMENTAL SOLUTIONS SUBMITTED CLOSURE REPORT. TANK DISPOSED BY DUTCHESS ENVIRONMENTAL. APPROXIMATELY 20 TONS OF CONTAMINATED SOIL DISPOSED OF. NO FURTHER ACTION." |
| Remarks: | "tank failed - clean up in progress" |

All Materials:

| | |
|---|---|
| Site ID: | 324496 |
| Operable Unit ID: | 848097 |
| Operable Unit: | 01 |
| Material ID: | 527384 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**111**
**East**
**1/4-1/2**
**0.401 mi.**
**2117 ft.**

**SPILL NUMBER 0106394** **NY LTANKS** **S105135155**
**110 CARLEON AVE** **N/A**
**LARCHMONT, NY**

**Relative:**
**Lower**

**Actual:**
**39 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 0106394 |
| Address: | 110 CARLEON AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0106394 / 2002-01-03 |
| Facility ID: | 0106394 |
| Site ID: | 314780 |
| Spill Date: | 2001-09-18 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |

**SPILL NUMBER 0106394 (Continued)** **S105135155**

| | |
|---|---|
| Referred To: | Not reported |
| Reported to Dept: | 2001-09-18 |
| CID: | 396 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2001-09-18 |
| Spill Record Last Update: | 2002-01-16 |
| Spiller Name: | ASAFF RES |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | SHAYE SPELLER |
| Spiller Phone: | (203) 778-5552 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 253779 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/03/2002 LETTER SENT TO EARNEST ASAFF BY T. GHIOSAY; BASED ON SPILL CLOSURE REPORT SUBMITTED BY GROUNDWATER INVESTIGATIONS, NO FURTHER ACTION IS REQUIRED AT THIS TIME. SPILL NUMBER CLOSED." |
| Remarks: | "pulling a 550 gal tank and cont. was found." |

All Materials:

| | |
|---|---|
| Site ID: | 314780 |
| Operable Unit ID: | 844685 |
| Operable Unit: | 01 |
| Material ID: | 531253 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**112**
**NW**
**1/4-1/2**
**0.402 mi.**
**2123 ft.**

**PRIVATE RES** **NY LTANKS** **S106471746**
**41 MAPLEWOOD ST** **N/A**
**LARCHMONT, NY**

**Relative:**
**Higher**

**Actual:**
**86 ft.**

LTANKS:

| | |
|---|---|
| Name: | PRIVATE RES |
| Address: | 41 MAPLEWOOD ST |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0402017 / 2004-09-15 |
| Facility ID: | 0402017 |
| Site ID: | 321600 |
| Spill Date: | 2004-05-24 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |

**PRIVATE RES (Continued)** **S106471746**

| | |
|---|---|
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-05-24 |
| CID: | 406 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-05-24 |
| Spill Record Last Update: | 2004-09-15 |
| Spiller Name: | STEVEN MARCUS |
| Spiller Company: | PRIVATE RES |
| Spiller Address: | 41 MAPLEWOOD ST |
| Spiller County: | 001 |
| Spiller Contact: | STEVEN MARCUS |
| Spiller Phone: | (914) 393-5404 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 259063 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 09/15/04 ELITE ENVIRONMENTAL DISPOSED OF LUST AND 1.61 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo" |
| Remarks: | "Removed under ground tank and found holes in it. Soil is contaminated and Elite will be doing the clean up. " |

All TTF:

| | |
|---|---|
| Facility ID: | 0402017 |
| Spill Number: | 0402017 |
| Spill Tank Test: | 1529297 |
| Site ID: | 321600 |
| Tank Number: | Not reported |
| Tank Size: | 275 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 321600 |
| Operable Unit ID: | 883827 |
| Operable Unit: | 01 |
| Material ID: | 493204 |
| Material Code: | 0001A |

**PRIVATE RES (Continued)** **S106471746**

Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

**113** **TTF** **NY LTANKS** **S104950688**
**NNE** **12 COOPER LANE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.420 mi.**
**2218 ft.**

**Relative:**
**Higher**

**Actual:**
**66 ft.**

LTANKS:
Name: TTF
Address: 12 COOPER LANE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 0013697 / 2009-12-30
Facility ID: 0013697
Site ID: 165408
Spill Date: 2001-03-31
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: D4
Cleanup Ceased: Not reported
SWIS: 6032
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2001-03-31
CID: 281
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-03-31
Spill Record Last Update: 2009-12-30
Spiller Name: UNKNOWN
Spiller Company: UNKNOWN
Spiller Address: 12 COOPER LANE
Spiller County: 001
Spiller Contact: DORSON ENVIORNMENTAL
Spiller Phone: (914) 592-3117
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 344779
DEC Memo: "12/30/09: See spills 0301842 and 0713255. Tank was removed in 2007 and no leak or contamination was found. jod"
Remarks: "TANK TEST FAILURE AT ABOVE LOCATION PERFORMED AT REQUEST OF DORSON ENVIORNMENTAL. DORSON HAS BEEN ADVISED OF RESULTS AND TANK TO BE UNCOVERED AND RETESTED."

All TTF:
Facility ID: 0013697

**TTF (Continued)** **S104950688**

| | |
|---|---|
| Spill Number: | 0013697 |
| Spill Tank Test: | 1526177 |
| Site ID: | 165408 |
| Tank Number: | 1 |
| Tank Size: | 1000 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | F |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 165408 |
| Operable Unit ID: | 835792 |
| Operable Unit: | 01 |
| Material ID: | 540396 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | TAYLOR RESIDENCE |
| Address: | 12 COOPER LANE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0301842 / 2003-06-17 |
| Facility ID: | 0301842 |
| Site ID: | 125348 |
| Spill Date: | 2003-05-21 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2003-05-21 |
| CID: | 257 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-05-21 |
| Spill Record Last Update: | 2009-12-30 |

**TTF (Continued)** **S104950688**

| | |
|---|---|
| Spiller Name: | PEGGY TAYLOR |
| Spiller Company: | Not reported |
| Spiller Address: | 12 COOPER LN |
| Spiller County: | 001 |
| Spiller Contact: | PEGGY TAYLOR |
| Spiller Phone: | (914) 391-3722 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 344779 |
| DEC Memo: | "06/17/03 TANK PASSED RETEST BY US TANK TECH. NFA jod 12/30/09: Also see spill 0713255 for tank removal. jod" |
| Remarks: | "" |

All Materials:

| | |
|---|---|
| Site ID: | 125348 |
| Operable Unit ID: | 868407 |
| Operable Unit: | 01 |
| Material ID: | 506328 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | ANASTAS RESIDENCE |
| Address: | 12 COOPER LANE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0713255 / 2008-05-28 |
| Facility ID: | 0713255 |
| Site ID: | 394981 |
| Spill Date: | 2008-03-14 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2008-03-14 |
| CID: | 404 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | Not reported |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2008-03-14 |
| Spill Record Last Update: | 2008-05-28 |
| Spiller Name: | STEVEN ANASTAS |
| Spiller Company: | RESIDANCE |
| Spiller Address: | 12 COOPER LANE |
| Spiller County: | 001 |
| Spiller Contact: | STEVEN ANASTAS |

**TTF (Continued)** **S104950688**

| | |
|---|---|
| Spiller Phone: | (914) 833-3442 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 344779 |
| DEC Memo: | "05/12/08 Northeast Environmental reported that they removed the tank and that no petroleum contaminated soil was observed in the excavation. Post excavation TAGM soil sample results were below DEC guidance values. NFA TG " |
| Remarks: | "method used Mesa 2 D; ullage potion leak" |

All TTF:

| | |
|---|---|
| Facility ID: | 0713255 |
| Spill Number: | 0713255 |
| Spill Tank Test: | 2384849 |
| Site ID: | 394981 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0002 |
| EPA UST: | Not reported |
| UST: | True |
| Cause: | 99 |
| Source: | 99 |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 394981 |
| Operable Unit ID: | 1151928 |
| Operable Unit: | 01 |
| Material ID: | 2142695 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**114**
**South**
**1/4-1/2**
**0.428 mi.**
**2259 ft.**

**SPILL NUMBER 8900768** **NY LTANKS** **S104619260**
**4 WAKEMAN PLACE** **N/A**
**LARCHMONT, NY**

**Relative:**
**Higher**

**Actual:**
**44 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 8900768 |
| Address: | 4 WAKEMAN PLACE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 8900768 / 1989-11-29 |
| Facility ID: | 8900768 |
| Site ID: | 89508 |
| Spill Date: | 1989-04-15 |

**SPILL NUMBER 8900768 (Continued)** **S104619260**

| | |
|---|---|
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | 1989-11-29 |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1989-04-25 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Citizen |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1989-05-01 |
| Spill Record Last Update: | 2004-01-13 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | 4 WAKEMAN PLACE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 81754 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: | "UNDER GROUND 275 GAL. TNAK PRODUCT LEAKING INTO BASEMENT, SMALL PUDDLE IN BACK YARD OF OIL. DEC TO INVESTIGATE, INSURANCE COMPANY TO CHECK OUT." |

All Materials:

| | |
|---|---|
| Site ID: | 89508 |
| Operable Unit ID: | 927339 |
| Operable Unit: | 01 |
| Material ID: | 452096 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**U115** **SPILL NUMBER 9911157** **NY LTANKS** **S104620741**
**West** **10 ROCHELLE RD** **N/A**
**1/4-1/2** **MAMARONECK, NY**
**0.429 mi.**
**2263 ft.** **Site 1 of 3 in cluster U**

**Relative:** LTANKS:
**Higher**

| | |
|---|---|
| Name: | SPILL NUMBER 9911157 |
| Address: | 10 ROCHELLE RD |
| City,State,Zip: | MAMARONECK, NY |

**Actual:**
**107 ft.**

**SPILL NUMBER 9911157 (Continued)** **S104620741**

| | |
|---|---|
| Spill Number/Closed Date: | 9911157 / 2000-10-17 |
| Facility ID: | 9911157 |
| Site ID: | 215427 |
| Spill Date: | 1999-12-21 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-12-21 |
| CID: | 257 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-12-21 |
| Spill Record Last Update: | 2004-07-06 |
| Spiller Name: | MR JARRET |
| Spiller Company: | Not reported |
| Spiller Address: | 10 ROCHELLE RD |
| Spiller County: | 001 |
| Spiller Contact: | MR JARRET |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 283817 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 12/21/99 J. O'DEE SPOKE WITH HOMEOWNER. THIS IS A DUPLICATE SPILL. TANK ALREADY FAILED A TANK TEST IN AUGUST. 10/17/2000 ERS CONSULTANTS HIRED TO COMPLETE WORK. TANK WAS EXCAVATED AND DISPOSED OF BY SUB-CONTRACTOR, TAKE PRIDE EXCAVATING. 36.72 TONS OF CONTAMINATED SOIL WAS DISPOSED OF BY SUB CONTRACTOR, NORTHEAST ENVIRONMENTAL. ALSO REPORTED AS SPILL NUMBER 99-05950. NFA " |
| Remarks: | "CALLER IS REMOVING A 1000GAL TANK AND IT HAS HOLES IN IT AND THERE IS CONTAMINATED SOIL" |

All Materials:

| | |
|---|---|
| Site ID: | 215427 |
| Operable Unit ID: | 1085862 |
| Operable Unit: | 01 |
| Material ID: | 563438 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**116**
**ESE**
**1/4-1/2**
**0.431 mi.**
**2274 ft.**

**RESIDENCE**
**2 CAMBRIDGE COURT**
**LARCHMONT, NY**

**NY LTANKS** **S106124609**
**N/A**

**Relative:**
**Lower**

**Actual:**
**17 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 2 CAMBRIDGE COURT |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0311004 / 2003-12-31 |
| Facility ID: | 0311004 |
| Site ID: | 293841 |
| Spill Date: | 2003-12-26 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Tank Truck |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 2003-12-26 |
| CID: | 402 |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-12-26 |
| Spill Record Last Update: | 2004-01-13 |
| Spiller Name: | ED ALLAN |
| Spiller Company: | ROBISON OIL |
| Spiller Address: | 500 EXECUTIVE BLVD |
| Spiller County: | 001 |
| Spiller Contact: | RAPP |
| Spiller Phone: | (914) 833-7036 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 237796 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: | "OIL COMPANY OVER FILLED TANK. IT HAS BEEN RECOVERED" |

All Materials:

| | |
|---|---|
| Site ID: | 293841 |
| Operable Unit ID: | 878770 |
| Operable Unit: | 01 |
| Material ID: | 499836 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**V117** **ESTATE OF LANDES** **NY LTANKS** **S106471661**
**SE** **10 CAMBRIDGE COURT** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.432 mi.**
**2280 ft.** **Site 1 of 2 in cluster V**

**Relative:** **Lower**
**Actual:** **23 ft.**

LTANKS:

| | |
|---|---|
| Name: | ESTATE OF LANDES |
| Address: | 10 CAMBRIDGE COURT |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0401701 / 2004-09-14 |
| Facility ID: | 0401701 |
| Site ID: | 217696 |
| Spill Date: | 2004-05-17 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-05-17 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-05-17 |
| Spill Record Last Update: | 2004-09-14 |
| Spiller Name: | JENEEN FERRARA |
| Spiller Company: | ESTATE OF LANDES |
| Spiller Address: | 10 CAMBRIDGE COURT |
| Spiller County: | 001 |
| Spiller Contact: | JENEEN FERRARA |
| Spiller Phone: | (914) 741-5472 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 180116 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 09/14/04 NES DISPOSED OF LUST AND 5.13 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo" |
| Remarks: | "REMOVING A 1000 GALLON TANK: HOLES IN TANK: " |

All Materials:

| | |
|---|---|
| Site ID: | 217696 |
| Operable Unit ID: | 885595 |
| Operable Unit: | 01 |
| Material ID: | 492896 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**U118** **SPILL NUMBER 9905950** **NY LTANKS** **S104620379**
**West** **10 ROCHELLE RD** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.435 mi.**
**2297 ft.** **Site 2 of 3 in cluster U**

**Relative:**
**Higher**

**Actual:**
**107 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9905950 |
| Address: | 10 ROCHELLE RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9905950 / 2000-10-17 |
| Facility ID: | 9905950 |
| Site ID: | 215426 |
| Spill Date: | 1999-08-18 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-08-18 |
| CID: | 388 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-08-18 |
| Spill Record Last Update: | 2000-10-20 |
| Spiller Name: | KATE |
| Spiller Company: | KATE JARRETT |
| Spiller Address: | 10 ROCHELLE RD |
| Spiller County: | 001 |
| Spiller Contact: | CALLER |
| Spiller Phone: | (914) 697-7654 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 178438 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/17/2000 DUPLICATE REPORT. SEE SPILL 99-11157 FOR CLOSURE. NFA" |
| Remarks: | "caller reports tested tank and tank failed." |

All TTF:

| | |
|---|---|
| Facility ID: | 9905950 |
| Spill Number: | 9905950 |
| Spill Tank Test: | 1547500 |
| Site ID: | 215426 |
| Tank Number: | 1 |
| Tank Size: | 1000 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |

**SPILL NUMBER 9905950 (Continued)** **S104620379**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 215426
Operable Unit ID: 1084396
Operable Unit: 01
Material ID: 302228
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

**119**
**NNE**
**1/4-1/2**
**0.435 mi.**
**2297 ft.**

**DALEY RESIDENCE** **NY LTANKS** **S106385927**
**2 HEATHER LANE** **N/A**
**MAMARONECK, NY**

**Relative:**
**Higher**

**Actual:**
**79 ft.**

LTANKS:
Name: DALEY RESIDENCE
Address: 2 HEATHER LANE
City,State,Zip: MAMARONECK, NY
Spill Number/Closed Date: 0400710 / 2004-06-04
Facility ID: 0400710
Site ID: 130559
Spill Date: 2004-04-21
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6032
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2004-04-21
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2004-04-21
Spill Record Last Update: 2004-06-04
Spiller Name: ELENOR DALEY
Spiller Company: DALEY RESIDENCE
Spiller Address: 2 HEATHER LANE
Spiller County: 001
Spiller Contact: ELENOR DALEY

**DALEY RESIDENCE (Continued)** **S106385927**

| | |
|---|---|
| Spiller Phone: | (914) 834-8453 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 112499 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/04/04 CASTLTON DISPOSED OF LUST AND 16.18 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDEDED, DEC REQUIRES NO FURTHER ACTION AT THIS TIME. jbo" |
| Remarks: | "" |

All Materials:

| | |
|---|---|
| Site ID: | 130559 |
| Operable Unit ID: | 884910 |
| Operable Unit: | 01 |
| Material ID: | 491956 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**U120** **PVT DWELLING** **NY LTANKS** **S110243973**
**West** **13 ROCHELLE ROAD** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.435 mi.**
**2298 ft.** **Site 3 of 3 in cluster U**

**Relative:** **Higher**

**Actual:** **106 ft.**

LTANKS:

| | |
|---|---|
| Name: | PVT DWELLING |
| Address: | 13 ROCHELLE ROAD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0913558 / 2010-06-08 |
| Facility ID: | 0913558 |
| Site ID: | 426508 |
| Spill Date: | 2010-03-23 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2010-03-23 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2010-03-23 |
| Spill Record Last Update: | 2010-06-08 |
| Spiller Name: | Not reported |

**PVT DWELLING (Continued)** **S110243973**

| | |
|---|---|
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | PAUL SCORZELLI |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 375374 |
| DEC Memo: | "3/23/10 - Left message to return phone call. KAB 6/8/2010: Closure documentation from NES reviewed and entered into eDocs. Based upon the information provided, no further action is required at this time. jod" |
| Remarks: | "550gal ust" |

All Materials:

| | |
|---|---|
| Site ID: | 426508 |
| Operable Unit ID: | 1182187 |
| Operable Unit: | 01 |
| Material ID: | 2176344 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**V121** **RESIDENCE** **NY LTANKS** **S103238674**
**ESE** **3 CAMBRIDGE CT** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.438 mi.**
**2315 ft.** **Site 2 of 2 in cluster V**

**Relative:**
**Lower**

**Actual:**
**21 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 3 CAMBRIDGE CT |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9800085 / 1998-05-01 |
| Facility ID: | 9800085 |
| Site ID: | 161347 |
| Spill Date: | 1998-04-02 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1998-04-02 |
| CID: | 366 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |

**RESIDENCE (Continued)** **S103238674**

| | |
|---|---|
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-04-02 |
| Spill Record Last Update: | 1998-05-13 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | GREGORY HALL |
| Spiller Phone: | (914) 833-0438 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 136232 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 04-25-98 21.95 TONS OF SOIL REMOVED AND DISPOSED OF." |
| Remarks: | "CALLER REPORTING THAT CONTAMINATED SOIL WAS FOUND IN AREA OF OLD UST. SOIL SAMPLES EXCEEDED LIMITS. HOMEOWNERS ADVISED TO HAVE TANK REMOVED." |

All Materials:

| | |
|---|---|
| Site ID: | 161347 |
| Operable Unit ID: | 1057502 |
| Operable Unit: | 01 |
| Material ID: | 325639 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**122**
**SSE**
**1/4-1/2**
**0.444 mi.**
**2342 ft.**

**LARCHMONT AVE CHURCH**
**60 FOREST PARK AVE**
**LARCHMONT, NY**

**NY LTANKS** **S111738889**
**NY Spills** **N/A**

**Relative:**
**Higher**

**Actual:**
**44 ft.**

LTANKS:

| | |
|---|---|
| Name: | LARCHMONT AVE CHURCH |
| Address: | 60 FOREST PARK AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1114153 / 2013-03-28 |
| Facility ID: | 1114153 |
| Site ID: | 462194 |
| Spill Date: | 2012-03-21 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | B3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2012-03-21 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |

**LARCHMONT AVE CHURCH (Continued)** **S111738889**

| | |
|---|---|
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2012-03-21 |
| Spill Record Last Update: | 2013-03-28 |
| Spiller Name: | BILL KINEZLE |
| Spiller Company: | LARCHMONT AVE CHURCH |
| Spiller Address: | 60 FOREST PARK AVE |
| Spiller County: | 999 |
| Spiller Contact: | BILL KINEZLE |
| Spiller Phone: | 914 834-1800 |
| Spiller Extention: | 304 |
| DEC Region: | 3 |
| DER Facility ID: | 416640 |
| DEC Memo: | "3-21-12: V.Mc. call to Bill/Church: Left Mess.: Req.Callbk. to Dispt. 3-21-12: Bill/Church callbk. to V.Mc./Dispt.: For follow up info try: Mr. Ruedi Laager/Church Member @ (914) 262-8886. Tank has been in service for the 20 years Bill has worked for chuch. 3-21-12: V.Mc. call to Ruedi/Church: Mr. Laager to advise the other member of the church board & develop a plan of action. 12/27/12 Tank is being pulled - see open spill # 12-14104...mm 3/28/2013: Remediation completed. Closure report from Madison Environmental entered into eDocs. Based upon information provided, no further action required at this time. jod" |
| Remarks: | "unk retest" |

All TTF:

| | |
|---|---|
| Facility ID: | 1114153 |
| Spill Number: | 1114153 |
| Spill Tank Test: | 2491812 |
| Site ID: | 462194 |
| Tank Number: | 0 |
| Tank Size: | 1000 |
| Material: | 0001 |
| EPA UST: | False |
| UST: | True |
| Cause: | 03 |
| Source: | 01 |
| Test Method: | 21 |
| Test Method 2: | Horner EZY3/EZY3 Locator Plus |
| Leak Rate: | Not reported |
| Gross Fail: | Not reported |
| Modified By: | jbodee |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 462194 |
| Operable Unit ID: | 1212262 |
| Operable Unit: | 01 |
| Material ID: | 2210126 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |

**LARCHMONT AVE CHURCH (Continued)** **S111738889**

Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

SPILLS:
Name: LARCHMONT AVE CHURCH
Address: 60 FOREST PARK AVE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 1214104 / 2013-03-28
Facility ID: 1214104
Facility Type: ER
DER Facility ID: 416640
Site ID: 477324
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 6032
Spill Date: 2012-12-27
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2012-12-27
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-12-27
Spill Record Last Update: 2013-03-28
Spiller Name: JOE THOMASULO
Spiller Company: LARCHMONT AVE CHURCH
Spiller Address: 60 FOREST PARK AVE
Spiller Company: 999
Contact Name: JOE THOMASULO
DEC Memo: "12/27/12 This tank failed a tightness test and spill # 11-14153 was generated. Tank is being removed, contamination discovered and will be removed...mm 3/28/2013: Remediation completed. Closure report from Madison Environmental entered into eDocs. Based upon information provided, no further action required at this time. jod"
Remarks: "soil contamination found during tank removal, c/u pending"

All Materials:
Site ID: 477324
Operable Unit ID: 1227134
Operable Unit: 01
Material ID: 2224355
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported

**LARCHMONT AVE CHURCH (Continued)** **S111738889**

Recovered: Not reported
Oxygenate: Not reported

---

**123**
**NW**
**1/4-1/2**
**0.447 mi.**
**2362 ft.**

**SPILL NUMBER 0201523** **NY LTANKS** **S105995844**
**101 NORTH CHATSWORTH AV** **N/A**
**LARCHMONT, NY**

**Relative:**
**Higher**

**Actual:**
**95 ft.**

LTANKS:

| | |
|---|---|
| Name: | + |
| Address: | 101 NORTH CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0200579 / 2005-02-09 |
| Facility ID: | 0200579 |
| Site ID: | 82904 |
| Spill Date: | 2002-04-16 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2002-04-16 |
| CID: | 205 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2002-04-16 |
| Spill Record Last Update: | 2005-02-09 |
| Spiller Name: | CALLER |
| Spiller Company: | 101 NO CHATSWORTH AVE |
| Spiller Address: | 101 NO CHATSWORTH AVE |
| Spiller County: | 001 |
| Spiller Contact: | CALLER |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 76363 |
| DEC Memo: | "02/09/05 ALSO REPORTED AS 02-01523. SEE THAT SPILL FOR ALL UPDATE INFORMATION. NFA THIS SPILL NUMBER. jbo" |
| Remarks: | "" |

All TTF:

| | |
|---|---|
| Facility ID: | 0200579 |
| Spill Number: | 0200579 |
| Spill Tank Test: | 1527042 |
| Site ID: | 82904 |
| Tank Number: | 1 |
| Tank Size: | 275 |
| Material: | 0001 |
| EPA UST: | Not reported |

**SPILL NUMBER 0201523 (Continued)** **S105995844**

| | |
|---|---|
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 82904 |
| Operable Unit ID: | 854019 |
| Operable Unit: | 01 |
| Material ID: | 522020 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | SPILL NUMBER 0201523 |
| Address: | 101 NORTH CHATSWORTH AV |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0201523 / 2002-06-07 |
| Facility ID: | 0201523 |
| Site ID: | 314806 |
| Spill Date: | 2002-05-10 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2002-05-10 |
| CID: | 365 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2002-05-10 |
| Spill Record Last Update: | 2002-07-08 |
| Spiller Name: | NAUGHTON RESIDENCE |
| Spiller Company: | Not reported |
| Spiller Address: | 101 NORTH CHATSWORTH AV |
| Spiller County: | 001 |
| Spiller Contact: | NAUGHTON RESIDENCE |
| Spiller Phone: | (914) 834-5071 |
| Spiller Extention: | Not reported |

**SPILL NUMBER 0201523 (Continued)** **S105995844**

DEC Region: 3
DER Facility ID: 253801
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/07/02 - NORTHEAST DISPOSED OF TANK AND 11.02 TONS OF CONTAMIN SOIL. NFA"
Remarks: "removed 275 gallon underground tank that had holes in it - they are hand excavating the contaminated soil now"

All Materials:
Site ID: 314806
Operable Unit ID: 852498
Operable Unit: 01
Material ID: 522940
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

**124**
**East**
**1/4-1/2**
**0.449 mi.**
**2369 ft.**

**SUTIN RESIDENCE**
**21 COPLEY RD**
**LARCHMONT, NY**

**NY LTANKS** **S106000106**
**NY Spills** **N/A**

**Relative:**
**Lower**

**Actual:**
**25 ft.**

LTANKS:
Name: SPILL NUMBER 0307108
Address: 21 COPLEY RD
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 0307108 / 2003-12-03
Facility ID: 0307108
Site ID: 62335
Spill Date: 2003-10-06
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: A3
Cleanup Ceased: Not reported
SWIS: 6000
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2003-10-06
CID: 365
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-10-06
Spill Record Last Update: 2003-12-03
Spiller Name: ALLEN SUTIN
Spiller Company: Not reported
Spiller Address: 21 COPLEY RD

**SUTIN RESIDENCE (Continued)** **S106000106**

| | |
|---|---|
| Spiller County: | 001 |
| Spiller Contact: | ALLEN SUTIN |
| Spiller Phone: | (212) 801-9286 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 60445 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/09/03 ALSO SPILL 03-07140. 12/03/03 NORTHEST DISPOSED OF LUST AND 164.78 TONS OF CONTAMINATED SOIL." |
| Remarks: | "odor of hydrocarbons detected in well point soil samples - failed tank test" |

All TTF:

| | |
|---|---|
| Facility ID: | 0307108 |
| Spill Number: | 0307108 |
| Spill Tank Test: | 1528722 |
| Site ID: | 62335 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | F |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 62335 |
| Operable Unit ID: | 873663 |
| Operable Unit: | 01 |
| Material ID: | 500684 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

SPILLS:

| | |
|---|---|
| Name: | SUTIN RESIDENCE |
| Address: | 21 COPLEY RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0307140 / 2003-12-03 |
| Facility ID: | 0307140 |
| Facility Type: | ER |
| DER Facility ID: | 60445 |
| Site ID: | 62336 |
| DEC Region: | 3 |
| Spill Cause: | Unknown |

**SUTIN RESIDENCE (Continued)** **S106000106**

| | |
|---|---|
| Spill Class: | A3 |
| SWIS: | 6000 |
| Spill Date: | 2003-10-07 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2003-10-07 |
| CID: | 390 |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Tank Tester |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-10-07 |
| Spill Record Last Update: | 2005-04-22 |
| Spiller Name: | ALLEN SUTIN |
| Spiller Company: | SUTIN RESIDENCE |
| Spiller Address: | 21 COPLEY RD |
| Spiller Company: | 001 |
| Contact Name: | ALLEN SUTIN |
| DEC Memo: | "10/09/03 ALSO SPILL 03-07108. 12/03/03 NORTHEAST DISPOSED OF LUST AND 164.78 TONS OF CONTAMINATED SOIL." |
| Remarks: | "soil contamination discovered near ust" |

All Materials:

| | |
|---|---|
| Site ID: | 62336 |
| Operable Unit ID: | 873698 |
| Operable Unit: | 01 |
| Material ID: | 552402 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**125 ESE 1/4-1/2 0.452 mi. 2385 ft.** **FORECLOSURE - TTF** **NY LTANKS** **S118638747**
**18 ALDEN RD** **N/A**
**LARCHMONT, NY**

**Relative: Higher**

**Actual: 42 ft.**

LTANKS:

| | |
|---|---|
| Name: | FORECLOSURE - TTF |
| Address: | 18 ALDEN RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1512394 / 2016-07-27 |
| Facility ID: | 1512394 |
| Site ID: | 525209 |
| Spill Date: | 2016-03-28 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |

**FORECLOSURE - TTF (Continued)** **S118638747**

| | |
|---|---|
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODEE |
| Referred To: | Not reported |
| Reported to Dept: | 2016-03-31 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2016-03-31 |
| Spill Record Last Update: | 2016-07-27 |
| Spiller Name: | BANK OWNED |
| Spiller Company: | Bank Owned |
| Spiller Address: | 18 ALDEN RD |
| Spiller County: | 999 |
| Spiller Contact: | PAUL SCORZELLI |
| Spiller Phone: | 9145573491 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 479418 |
| DEC Memo: | "3/31/16 Spoke to Scorzelli, who did not know who the owners are (bank contact). He was doing this for potential buyer. dw 7/27/16: Grazi-1 Environmental disposed of the leaking UST and a total of 11.86 tons of petroleum contaminated soil. Soil sample results were submitted for review. Documents entered into DecDocs. Based upon the information provided, no further action is required at this time. jod" |
| | Not reported |
| Remarks: | "550 gallon tank test failure" |

All Materials:

| | |
|---|---|
| Site ID: | 525209 |
| Operable Unit ID: | 1274169 |
| Operable Unit: | 01 |
| Material ID: | 2278719 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

**126**
**NW**
**1/4-1/2**
**0.459 mi.**
**2425 ft.**

**104 NORTH CHATSWORTH AVE**
**104 NORTH CHATSWORTH AVE**
**LARCHMONT, NY**

**NY LTANKS** **S105999943**
**N/A**

**Relative:**
**Higher**

**Actual:**
**86 ft.**

LTANKS:

| | |
|---|---|
| Name: | 104 NORTH CHATSWORTH AVE |
| Address: | 104 NORTH CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0306408 / 2004-03-23 |
| Facility ID: | 0306408 |
| Site ID: | 168951 |
| Spill Date: | 2003-09-17 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | A3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2003-09-17 |
| CID: | 204 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | 2003-11-05 |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-09-17 |
| Spill Record Last Update: | 2004-03-23 |
| Spiller Name: | REAL ESTATE |
| Spiller Company: | 104 NORTH CHATSWORTH AVE |
| Spiller Address: | 104 NORTH CHATSWORTH AVE |
| Spiller County: | 001 |
| Spiller Contact: | PAOLA CORONEL |
| Spiller Phone: | (914) 747-9741 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 142289 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/31/03 ENVIROSTAR PULLED TANK. CONTAMINATION EXTENSIVE. H2M IS OVERSITE. DEC INSPECTING TODAY. 11/05/03 GROUND WATER MONITORING WELLS BEING INSTALLED. 03/23/04 ENVIROSTAR DISPOSED OF LUST AND 450 TONS OF CONTAMINATED SOIL. FINAL GROUND WATER SAMPLE RESULTS WERE ND. NO FURTHER ACTION REQUIRED AT THIS TIME." |
| Remarks: | "TANK TEST FAILURE " |

All TTF:

| | |
|---|---|
| Facility ID: | 0306408 |
| Spill Number: | 0306408 |
| Spill Tank Test: | 1528691 |
| Site ID: | 168951 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |

**104 NORTH CHATSWORTH AVE (Continued)** **S105999943**

| | |
|---|---|
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 168951 |
| Operable Unit ID: | 875132 |
| Operable Unit: | 01 |
| Material ID: | 503632 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**W127** **SPILL NUMBER 0313036** **NY LTANKS** **S106123947**
**ESE** **7 HARMONY DRIVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.462 mi.**
**2439 ft.** **Site 1 of 2 in cluster W**

**Relative:**
**Lower**

**Actual:**
**35 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 7 HARMONY DRIVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0311429 / 2004-04-26 |
| Facility ID: | 0311429 |
| Site ID: | 260818 |
| Spill Date: | 2004-01-09 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-01-09 |
| CID: | 404 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-01-09 |
| Spill Record Last Update: | 2004-04-26 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |

**SPILL NUMBER 0313036 (Continued)** **S106123947**

| | |
|---|---|
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | RALPH LUCARELLI |
| Spiller Phone: | (914) 834-3068 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 213012 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/22/04 ALSO REPORTED AS SPILL 03-13036. NORTHEAST DISPOSED OF LUST AND 17.43 TONS OF CONTAMINATED SOIL. jbo" |
| Remarks: | "FAILED TEST. RECOMMEND UNCOVER REPAIR AND RETEST." |

All TTF:

| | |
|---|---|
| Facility ID: | 0311429 |
| Spill Number: | 0311429 |
| Spill Tank Test: | 1528903 |
| Site ID: | 260818 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

| | |
|---|---|
| Name: | SPILL NUMBER 0313036 |
| Address: | 7 HARMONY DRIVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0313036 / 2004-04-22 |
| Facility ID: | 0313036 |
| Site ID: | 260819 |
| Spill Date: | 2004-02-26 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-02-26 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-02-26 |
| Spill Record Last Update: | 2004-04-26 |
| Spiller Name: | MARY LUCARELLI |

**SPILL NUMBER 0313036 (Continued)** **S106123947**

| | |
|---|---|
| Spiller Company: | Not reported |
| Spiller Address: | 7 HARMONY DRIVE |
| Spiller County: | 001 |
| Spiller Contact: | MARY LUCARELLI |
| Spiller Phone: | (914) 834-3068 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 213012 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/22/04 ALSO REPORTED AS SPILL 03-11429. NORTHEAST DISPOSED OF LUST AND 17.43 TONS OF CONTAMINATED SOIL. jbo" |
| Remarks: | "WHILE REMOVING TANK FOUND HOLES IN TANK AND CONTAMINATED SOIL: " |

All TTF:

| | |
|---|---|
| Facility ID: | 0313036 |
| Spill Number: | 0313036 |
| Spill Tank Test: | 1529001 |
| Site ID: | 260819 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 260819 |
| Operable Unit ID: | 880222 |
| Operable Unit: | 01 |
| Material ID: | 498205 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**128** **DURON RESIDENCE** **NY LTANKS** **S104278629**
**SSE** **174 LARCHMONT AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.463 mi.**
**2447 ft.**

**Relative:** **Lower**

**Actual:** **39 ft.**

LTANKS:

| | |
|---|---|
| Name: | DURON RESIDENCE |
| Address: | 174 LARCHMONT AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9909450 / 2000-04-11 |

**DURON RESIDENCE (Continued)** **S104278629**

| | |
|---|---|
| Facility ID: | 9909450 |
| Site ID: | 299475 |
| Spill Date: | 1999-11-03 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-11-03 |
| CID: | 390 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-11-03 |
| Spill Record Last Update: | 2003-09-15 |
| Spiller Name: | MR/MRS DURON |
| Spiller Company: | DURON RESIDENCE |
| Spiller Address: | 174 LARCHMONT AVE |
| Spiller County: | 001 |
| Spiller Contact: | MR/MRS DURON |
| Spiller Phone: | (914) 833-0239 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 242263 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/11/2000 TAKE PRIDE DISPOSED OF TANK AND 54.35 TONS OF CONTAMINATED SOIL. NFA" |
| Remarks: | "tank failed underground - causing soil contamination" |

All Materials:

| | |
|---|---|
| Site ID: | 299475 |
| Operable Unit ID: | 1084056 |
| Operable Unit: | 01 |
| Material ID: | 298536 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**129**
**ENE**
**1/4-1/2**
**0.465 mi.**
**2455 ft.**

**CENTRAL SCHOOL**
**PALMER AVE**
**LARCHMONT, NY**

**NY LTANKS**

**U003646706**
**N/A**

**Relative:**
**Lower**

**Actual:**
**31 ft.**

LTANKS:

| | |
|---|---|
| Name: | CENTRAL SCHOOL |
| Address: | PALMER AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9305290 / 1994-05-24 |
| Facility ID: | 9305290 |
| Site ID: | 63916 |
| Spill Date: | 1993-07-27 |
| Spill Cause: | Tank Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | B3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1993-07-29 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1993-07-30 |
| Spill Record Last Update: | 1999-01-16 |
| Spiller Name: | Not reported |
| Spiller Company: | MAMARONECK SCHOOL DIST. |
| Spiller Address: | 1000 WEST BOSTON POST RD. |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 61663 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY CLOSED BY J O'MARA, ASSESSMENT REPORT BELOW STARS" |
| Remarks: | "PIPING LEAK NOTICED IN TANK PULL 500 YARDS SOIL REMOVED VERY LITTLE IN GROUNDWATER BOB SPERONI INSPECTED PULLING SIX OTHER TANKS CONVERTING TO NATURAL GAS WCHD NOTIFIED" |

All Materials:

| | |
|---|---|
| Site ID: | 63916 |
| Operable Unit ID: | 986796 |
| Operable Unit: | 01 |
| Material ID: | 395219 |
| Material Code: | 0002A |
| Material Name: | #4 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | L |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**X130** **TOWN OF MAMARONECK DPW** **NY LTANKS** **S100139795**
**SW** **MAXWELL AVE - DPW YARD** **NY Spills** **N/A**
**1/4-1/2** **MAMARONECK, NY**
**0.469 mi.**
**2476 ft.** **Site 1 of 3 in cluster X**

**Relative:**
**Lower**

**Actual:**
**35 ft.**

LTANKS:

| | |
|---|---|
| Name: | TOWN OF MAMARONECK |
| Address: | MAXWELL AVE |
| City,State,Zip: | MAMARONECK, NY |
| Spill Number/Closed Date: | 8708513 / 1988-11-25 |
| Facility ID: | 8708513 |
| Site ID: | 62756 |
| Spill Date: | 1987-12-22 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | D3 |
| Cleanup Ceased: | 1988-06-02 |
| SWIS: | 6000 |
| Investigator: | jeokesso |
| Referred To: | Not reported |
| Reported to Dept: | 1988-01-05 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | 1988-06-02 |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | True |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1988-01-26 |
| Spill Record Last Update: | 1988-11-25 |
| Spiller Name: | Not reported |
| Spiller Company: | TOWN OF MAMARONECK |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 275811 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON 02/18/88: TO RETEST LR. 2-18-88. 11/25/88: TANK REMOVED. " |
| Remarks: | "1K TANK SYSTEM FAILURE AINLAY TEST AT .07GPH TO EXCAVATE & INVESTAGATE." |

All TTF:

| | |
|---|---|
| Facility ID: | 8708513 |
| Spill Number: | 8708513 |
| Spill Tank Test: | 1532908 |
| Site ID: | 62756 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | 0008 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |

**TOWN OF MAMARONECK DPW (Continued)** **S100139795**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 62756
Operable Unit ID: 913927
Operable Unit: 01
Material ID: 463900
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: TOWN OF MAMARONECK DPW
Address: MAXWELL AVE - DPW YARD
City,State,Zip: MAMARONECK, NY
Spill Number/Closed Date: 0100007 / 2001-04-02
Facility ID: 0100007
Facility Type: ER
DER Facility ID: 197657
Site ID: 240356
DEC Region: 3
Spill Cause: Other
Spill Class: C4
SWIS: 6032
Spill Date: 2001-04-01
Investigator: mbmastro
Referred To: Not reported
Reported to Dept: 2001-04-01
CID: 405
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Health Department
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-04-01
Spill Record Last Update: 2001-04-02
Spiller Name: JOE TUINNO
Spiller Company: TOWN OF MAMARONECK DPW
Spiller Address: MAXWELL AV - DPW YARD
Spiller Company: 001
Contact Name: JOE TUINNO
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MASTRO 04/02/2001 THIS SPILL NUMBER CLOSED. REFER TO SPILL NUMBER

**TOWN OF MAMARONECK DPW (Continued)** **S100139795**

01-00005."
Remarks: "clean up crew enroute is a mixure of gasoline and deisel fuel spill is in the sanitary sewer not the storm sewer"

All Materials:
Site ID: 240356
Operable Unit ID: 837067
Operable Unit: 01
Material ID: 539282
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

**X131** **MAMARONECK DPW** **NY LTANKS** **S104194820**
**SW** **MAXWELL ST** **N/A**
**1/4-1/2** **MAMARONECK, NY**
**0.469 mi.**
**2476 ft.** **Site 2 of 3 in cluster X**

**Relative:** **Lower**
**Actual:** **35 ft.**

LTANKS:
Name: MAMARONECK DPW
Address: MAXWELL ST
City,State,Zip: MAMARONECK, NY
Spill Number/Closed Date: 9906831 / 2005-09-20
Facility ID: 9906831
Site ID: 217177
Spill Date: 1999-09-08
Spill Cause: Tank Failure
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6032
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1999-09-08
CID: 388
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1999-09-08
Spill Record Last Update: 2005-09-20
Spiller Name: SHAIMON GITLITZ
Spiller Company: TOWN OF MAMARONECK
Spiller Address: 740 W BOSTON RD
Spiller County: 001
Spiller Contact: CALLER
Spiller Phone: (914) 561-1512
Spiller Extention: Not reported

**MAMARONECK DPW (Continued)** **S104194820**

DEC Region: 3
DER Facility ID: 179794
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/22/99 LETTER SENT BY T. GHIOSAY; SITE INSPECTION CONDUCTED. A SIGNIFIANT QUANITY OF GASOLINE POSSIBLY MIXED WITH DIESEL PRESENT ON SURFACE OF GROUNDWATER AT BASE OF EXCAVATION. GROUNDWATER INVESTIGATION WORK PLAN MUST BE SUBMITTED TO DEC. 11/19/99 GROUNDWATER INVESTIGATION PROPOSAL RECEIVED FROM EMCON. PROJECT MANAGER IS STEVEN GOLDBERG 201-512-5700. PROPOSAL WAS ACCEPTABLE. 09-23-04 Semi-annual groundwater monitoring report rec'd from Shaw Environmental and Infrastructure. Report includes monitoring data from Dec 03 and March o4 from 3 site wells. Quarterly monitoring and semiannual reporting to continue. 09/15/05 Semi Annula report submitted by Shaw Environmental. Based on the info contained in that report, NFA required. TG"
Remarks: "caller reports they pulled tanks and found contaminted soil and are also pulling dispensers which are probably the source."

All Materials:

Site ID: 217177
Operable Unit ID: 1081132
Operable Unit: 01
Material ID: 575402
Material Code: 2645A
Material Name: BTEX
Case No.: Not reported
Material FA: Oxygenates
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: True

Site ID: 217177
Operable Unit ID: 1081132
Operable Unit: 01
Material ID: 299550
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: True

Site ID: 217177
Operable Unit ID: 1081132
Operable Unit: 01
Material ID: 575401
Material Code: 1213A
Material Name: MTBE (methyl-tert-butyl ether)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: True

**X132** **DEPT PUBLIC WORKS** **NY LTANKS** **S104278291**
**SW** **MAXWELL AVE** **N/A**
**1/4-1/2** **MAMARONECK, NY**
**0.469 mi.**
**2476 ft.** **Site 3 of 3 in cluster X**

**Relative:** **Lower**
**Actual:** **35 ft.**

LTANKS:

| | |
|---|---|
| Name: | DEPT PUBLIC WORKS |
| Address: | MAXWELL AVE |
| City,State,Zip: | MAMARONECK, NY |
| Spill Number/Closed Date: | 9907873 / 2003-12-05 |
| Facility ID: | 9907873 |
| Site ID: | 197874 |
| Spill Date: | 1999-09-29 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | WCHD |
| Referred To: | Westchester Cnty Health Dept |
| Reported to Dept: | 1999-09-29 |
| CID: | 211 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | True |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-09-29 |
| Spill Record Last Update: | 2003-12-05 |
| Spiller Name: | Not reported |
| Spiller Company: | DEPT PUBLIC WORKS |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | JACQUELINE PATT |
| Spiller Phone: | (914) 561-1512 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 164673 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-GOREAU 12/05/03 CLOSED BY STEFAN GOREAU OF WCHD." |
| Remarks: | "CALLER DOING TANK REMOVAL AND FOUND SOIL CONTAMINATION" |

All Materials:

| | |
|---|---|
| Site ID: | 197874 |
| Operable Unit ID: | 1086533 |
| Operable Unit: | 01 |
| Material ID: | 300556 |
| Material Code: | 0009 |
| Material Name: | gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**133**
**ESE**
**1/4-1/2**
**0.476 mi.**
**2513 ft.**

**RESIDENCE**
**10 NASSAU RD**
**LARCHMONT, NY**

**NY LTANKS** **S106472001**
**N/A**

**Relative:**
**Lower**

**Actual:**
**15 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 10 NASSAU RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0403388 / 2004-10-28 |
| Facility ID: | 0403388 |
| Site ID: | 138656 |
| Spill Date: | 2004-06-29 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-06-29 |
| CID: | 405 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-06-29 |
| Spill Record Last Update: | 2004-10-28 |
| Spiller Name: | GEORGE BISCOV |
| Spiller Company: | RESIDENCE |
| Spiller Address: | 10 NASSAU RD |
| Spiller County: | 001 |
| Spiller Contact: | GEORGE BISCOV |
| Spiller Phone: | (917) 667-4501 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 118552 |
| DEC Memo: | " 06/29/04 TANK FAILED TWO TANKS TESTS THAT WERE NOT REPORTED. HOLES FOUND IN TANK, CONTAMINATED SOIL BEING STOCKPILED. REPORT TO FOLLOW. jbo 10/28/04 ELITE ENVIRONMENTAL DISPOSED OF LUST AND 18.87 TONS OF CONTAMINATED SOIL. BASED UPON THE INFORMATION SUPPLIED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo" |
| Remarks: | "TANK REMOVAL, TANK FAILED" |

All Materials:

| | |
|---|---|
| Site ID: | 138656 |
| Operable Unit ID: | 885632 |
| Operable Unit: | 01 |
| Material ID: | 490974 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |

**RESIDENCE (Continued)** **S106472001**

Oxygenate: Not reported

---

**Y134** **IKEA** **NY LTANKS** **S105999323**
**WNW** **10 VALLEY PL** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.477 mi.**
**2518 ft.** **Site 1 of 3 in cluster Y**

**Relative:** **Higher**

**Actual:** **108 ft.**

LTANKS:

| | |
|---|---|
| Name: | IKEA |
| Address: | 10 VALLEY PL |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0303396 / 2005-07-05 |
| Facility ID: | 0303396 |
| Site ID: | 164849 |
| Spill Date: | 2003-07-01 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | WCHD |
| Referred To: | WESTCHESTER CNTY HEALTH D |
| Reported to Dept: | 2003-07-01 |
| CID: | 257 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-07-01 |
| Spill Record Last Update: | 2005-07-11 |
| Spiller Name: | SAME |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | BRAD PREVOST |
| Spiller Phone: | (610) 834-0180 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 138976 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-MAGNUSON 5/11/04: Letter to 10 Valley Place, LLC c/o Charles McGoey, Esq. from Wayne Schneider, WCDOH dated 7May2004. Groundwater sampling report by Advanced Env. Redevelopment, LLC has been reviewed. Many contaminants have decreased, however, some levels still exceed TAGM guidelines. Next round of sampling due July 2004. Result must be submitted by 30Aug2004. 7/08/05: Letter to 10 Valley Place, LLC c/o Charles McGoey, Esq. from Wayne Schneider, WCDOH dated 5Jul2005. Groundwater sampling reports dated May2005 re: Aug2003, Apr2004, Jan2005 and May2005 have been reviewed. WCDOH recommends NFA at this time." |
| Remarks: | "during a tank removal caller found contaminated soil - will stock pile same" |

**IKEA (Continued)** **S105999323**

All Materials:

| | |
|---|---|
| Site ID: | 164849 |
| Operable Unit ID: | 871434 |
| Operable Unit: | 01 |
| Material ID: | 504267 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**135 FITCH RESIDENCE** **NY LTANKS** **S111063883**
**WNW 3 WILDWOOD ROAD** **N/A**
**1/4-1/2 LARCHMONT, NY**
**0.478 mi.**
**2523 ft.**

**Relative:**
**Higher**

**Actual:**
**121 ft.**

LTANKS:

| | |
|---|---|
| Name: | FITCH RESIDENCE |
| Address: | 3 WILDWOOD ROAD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1103135 / 2011-08-25 |
| Facility ID: | 1103135 |
| Site ID: | 450687 |
| Spill Date: | 2011-06-20 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2011-06-20 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2011-06-20 |
| Spill Record Last Update: | 2011-08-25 |
| Spiller Name: | GROVER FITCH |
| Spiller Company: | GROVER FITCH |
| Spiller Address: | 3 WILDWOOD ROAD |
| Spiller County: | 999 |
| Spiller Contact: | GROVER FITCH |
| Spiller Phone: | (914) 834-1146 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 405249 |
| DEC Memo: | "6/20/11: Residential TTF for prospective real estate transaction. |

**FITCH RESIDENCE (Continued)** **S111063883**

Potential buyer and their broker present for the test. Technician heard dripping, probable return line suction problem, oil dripping back into the tank from the line. Plan is to excavate, repair and retest. jod 08/16/11 Northeast Environmental reported that they excavated and removed the tank along with 20.03 tons of contaminated soil. Post excavation soil sample results were below DEC guidance values. NFA. TG"

Remarks: "Tank test failure. Recommend uncover, repair, and retest."

All Materials:

| | |
|---|---|
| Site ID: | 450687 |
| Operable Unit ID: | 1200889 |
| Operable Unit: | 01 |
| Material ID: | 2197340 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**W136** **APT BLD** **NY LTANKS** **S110769599**
**ESE** **11 ALDEN RD** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.478 mi.**
**2524 ft.** **Site 2 of 2 in cluster W**

**Relative:** **Lower**

**Actual:** **36 ft.**

LTANKS:

| | |
|---|---|
| Name: | COMMERCIAL |
| Address: | 11 ALDEN ROAD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0602133 / 2006-09-22 |
| Facility ID: | 0602133 |
| Site ID: | 364540 |
| Spill Date: | 2006-05-26 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | WCDOH |
| Reported to Dept: | 2006-05-26 |
| CID: | 408 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2006-05-26 |
| Spill Record Last Update: | 2006-09-22 |
| Spiller Name: | DONNA HENTSCHEL |
| Spiller Company: | COMMERCIAL |

**APT BLD (Continued)** **S110769599**

| | |
|---|---|
| Spiller Address: | 11 ALDEN ROAD |
| Spiller County: | 001 |
| Spiller Contact: | DONNA HENTSCHEL |
| Spiller Phone: | (914) 793-5610 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 314757 |
| DEC Memo: | "PBS 3-068551 7/31/06 Danielle Jackson from WCHD: 11 Alden Road, Larchmont, NY repaired and retested 6-19-06 and passed, NFA " |
| Remarks: | "" |

All Materials:

| | |
|---|---|
| Site ID: | 364540 |
| Operable Unit ID: | 1122563 |
| Operable Unit: | 01 |
| Material ID: | 2112029 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | APT BLD |
| Address: | 11 ALDEN RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1011710 / 2011-05-20 |
| Facility ID: | 1011710 |
| Site ID: | 445598 |
| Spill Date: | 2011-02-23 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2011-02-23 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2011-02-23 |
| Spill Record Last Update: | 2011-06-01 |
| Spiller Name: | DONNA HENCHELL |
| Spiller Company: | APT BLD |
| Spiller Address: | 11 ALDEN RD |
| Spiller County: | 999 |
| Spiller Contact: | DONNA HENCHELL |
| Spiller Phone: | (718) 796-5022 |
| Spiller Extention: | Not reported |

**APT BLD (Continued)** **S110769599**

DEC Region: 3
DER Facility ID: 400430
DEC Memo: "2-23-11: V.Mc. to Ms.Donna Henchell: Just found out about TTF, left mess with tester & waitingon callbk.,(Ms.Donna H.) To make arrangements for retesting. Results to be submitted to WCHD. 3/3/11: PBS TTF, Wayne Schneider will handle. jod 5/20/11 As per WCDOH 1011710: 11 alden rd, Larchmont- ttf, passed retest 3/11/11 after replacing fitting n return line(aboveground). No contamination NFA JO'M "
Remarks: "vaulted above ground failed tank test. retest pending"

All Materials:
Site ID: 445598
Operable Unit ID: 1195980
Operable Unit: 01
Material ID: 2192111
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

---

**Y137** **ATLAS PARTY RENTALS** **NY LTANKS** **S105998003**
**WNW** **4 VALLEY PLACE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.482 mi.**
**2546 ft.** **Site 2 of 3 in cluster Y**

**Relative:** **Higher**
**Actual:** **112 ft.**

LTANKS:
Name: ATLAS PARTY RENTALS
Address: 4 VALLEY PLACE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 0210744 / 2006-01-30
Facility ID: 0210744
Site ID: 199114
Spill Date: 2003-01-27
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6032
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 2003-01-27
CID: 257
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-01-27
Spill Record Last Update: 2006-02-07

**ATLAS PARTY RENTALS (Continued)** **S105998003**

| | |
|---|---|
| Spiller Name: | GARY SHURE |
| Spiller Company: | ATLIS PARTY RENTALS |
| Spiller Address: | 4 VALLEY PL |
| Spiller County: | 001 |
| Spiller Contact: | GARY SHURE |
| Spiller Phone: | (914) 636-6431 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 165725 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY " |
| Remarks: | "caller took samples - tank is a above ground tank that was in the basement and leaked - caller took sample of soil under the concrete and it has contaminated soil " |

All Materials:

| | |
|---|---|
| Site ID: | 199114 |
| Operable Unit ID: | 861841 |
| Operable Unit: | 01 |
| Material ID: | 552535 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**Y138** **SPILL NUMBER 9812365** **NY LTANKS** **S104619912**
**WNW** **1 SETON RD** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.487 mi.**
**2570 ft.** **Site 3 of 3 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**115 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9812365 |
| Address: | 1 SETON RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9812365 / 1999-03-09 |
| Facility ID: | 9812365 |
| Site ID: | 319993 |
| Spill Date: | 1999-01-06 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-01-06 |
| CID: | 384 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |

**SPILL NUMBER 9812365 (Continued)** **S104619912**

| | |
|---|---|
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-01-06 |
| Spill Record Last Update: | 1999-03-16 |
| Spiller Name: | EDWARD HELWIG |
| Spiller Company: | EDWARD HELWIG |
| Spiller Address: | 1 SETON RD |
| Spiller County: | 001 |
| Spiller Contact: | EDWARD HELWIG |
| Spiller Phone: | (914) 834-4672 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 257809 |
| DEC Memo: | "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 3/3/99 1100 GALLON #2 FUEL TANK PASSED RETEST 3/3/99. NO CONTAMINATION OBSERVED IN AREAS EXCAVATED." |
| Remarks: | "TANK WAS TESTED FOR A REAL ESTATE TRANSACTION." |

All TTF:

| | |
|---|---|
| Facility ID: | 9812365 |
| Spill Number: | 9812365 |
| Spill Tank Test: | 1546716 |
| Site ID: | 319993 |
| Tank Number: | 1 |
| Tank Size: | 1100 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | F |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 319993 |
| Operable Unit ID: | 1069622 |
| Operable Unit: | 01 |
| Material ID: | 563593 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**139**
**SSW**
**1/4-1/2**
**0.487 mi.**
**2573 ft.**

**WEBERS HOME**
**76 PINEBROOK DRIVE**
**LARCHMONT, NY**

**NY LTANKS** **S107410299**
**N/A**

**Relative:**
**Lower**

**Actual:**
**32 ft.**

LTANKS:

| | |
|---|---|
| Name: | WEBERS HOME |
| Address: | 76 PINEBROOK DRIVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0505197 / 2005-09-26 |
| Facility ID: | 0505197 |
| Site ID: | 350147 |
| Spill Date: | 2005-07-29 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | Not reported |
| Reported to Dept: | 2005-07-29 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2005-07-29 |
| Spill Record Last Update: | 2005-09-26 |
| Spiller Name: | WEBERS HOME |
| Spiller Company: | WEBERS HOME |
| Spiller Address: | 76 PINE BROOK DRIVE |
| Spiller County: | 001 |
| Spiller Contact: | WEBERS HOME |
| Spiller Phone: | (914) 882-2559 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 296590 |
| DEC Memo: | "September 26, 2005: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 11.07 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod" |
| Remarks: | "A 550 GALLON TANK HAD HOLES AND CONTAMINATED SOIL" |

All Materials:

| | |
|---|---|
| Site ID: | 350147 |
| Operable Unit ID: | 1107728 |
| Operable Unit: | 01 |
| Material ID: | 2097617 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**140**
**SE**
**1/4-1/2**
**0.496 mi.**
**2619 ft.**

**KUNREUTHER - TTF**
**17 BONNETT AVENUE**
**LARCHMONT, NY**

**NY LTANKS** **S104515603**
**N/A**

**Relative:**
**Higher**

**Actual:**
**41 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENTIAL TTF |
| Address: | 17 BONNETT AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9902354 / 2000-07-19 |
| Facility ID: | 9902354 |
| Site ID: | 243264 |
| Spill Date: | 1999-06-01 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-06-01 |
| CID: | 252 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-06-01 |
| Spill Record Last Update: | 2018-10-10 |
| Spiller Name: | TOM GALLINGER |
| Spiller Company: | RESIDENCE |
| Spiller Address: | 17 BONNET AVE |
| Spiller County: | 001 |
| Spiller Contact: | TOM GALLINGER |
| Spiller Phone: | (914) 592-3117 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 199811 |
| DEC Memo: | "Check Paper Files" |
| Remarks: | "" |

All TTF:

| | |
|---|---|
| Facility ID: | 9902354 |
| Spill Number: | 9902354 |
| Spill Tank Test: | 1547213 |
| Site ID: | 243264 |
| Tank Number: | UST |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | False |
| UST: | True |
| Cause: | 99 |
| Source: | 00 |
| Test Method: | 21 |
| Test Method 2: | Horner EZY3/EZY3 Locator Plus |
| Leak Rate: | Not reported |
| Gross Fail: | Not reported |

**KUNREUTHER - TTF (Continued)** **S104515603**

Modified By: JBODEE
Last Modified Date: Not reported

All Materials:
Site ID: 243264
Operable Unit ID: 1081271
Operable Unit: 01
Material ID: 305860
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Name: KUNREUTHER - TTF
Address: 17 BONNETT AVENUE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 1007092 / 2010-10-27
Facility ID: 1007092
Site ID: 440479
Spill Date: 2010-10-01
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6032
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2010-10-01
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2010-10-01
Spill Record Last Update: 2018-10-10
Spiller Name: Jason Kunreuther
Spiller Company: Kunreuther
Spiller Address: 17 BONNETT LANE
Spiller County: 999
Spiller Contact: JASON KUNREUTHER
Spiller Phone: (914) 330-7899
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 395479
DEC Memo: "10-1-10: V.Mc. to Mr. Kunreuther: UST was installed in 1999, purchessed house in 2004, tank was tested at that time and passed. Mr. Kun.to have tank re-tested and may exc. soil off top of tank for re-test. UST has 30 year warranty. Advised Mr. Kun.to callbk to Dispt.when tank passes the re-test. 10-14-10: V.Mc.: Mr.Kunreuther to

**KUNREUTHER - TTF (Continued)** **S104515603**

Dispt./V.Mc.: UST passed retest, checked J.O'Dee in basket, retest results not recived as of today's mail. 10/27/10: Tank passed a retest after piping was repaired. Report will be entered into eDocs. Based upon the information received, no further action is required at this time. jod"

Remarks: "retest planned"

All Materials:

| | |
|---|---|
| Site ID: | 440479 |
| Operable Unit ID: | 1191093 |
| Operable Unit: | 01 |
| Material ID: | 2186209 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

Count: 5 records. ORPHAN SUMMARY

| City | EDR ID | Site Name | Site Address | Zip | Database(s) |
|---|---|---|---|---|---|
| MAMARONECK | S104619232 | SPILL NUMBER 8601246 | RT I95 ON NEW ENGLAND TWY | | NY LTANKS |
| NEW ROCHELLE | S100153602 | N.SHORE LONG ISLAND SOUND | NEW ROCHELLE TO DANBURY | | NY LTANKS |
| NEW ROCHELLE | S113916612 | MEARL CORP. | PALMER AVE | 10801 | NY SHWS |
| NEW ROCHELLE | S113922056 | PINEBROOK TENNIS COURTS | PINEBROOK BOULEVARD | 10804 | NY VCP |
| NEW ROCHELLE | S117975694 | MM 5.4 LEFT LANE | I-95 SOUTHBOUND | | NY LTANKS |

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

**Number of Days to Update:** Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

**STANDARD ENVIRONMENTAL RECORDS**

***Lists of Federal NPL (Superfund) sites***

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: EPA
Telephone: N/A
Last EDR Contact: 11/01/2022
Next Scheduled EDR Contact: 01/09/2023
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: EPA
Telephone: N/A
Last EDR Contact: 11/01/2022
Next Scheduled EDR Contact: 01/09/2023
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

***Lists of Federal Delisted NPL sites***

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: EPA
Telephone: N/A
Last EDR Contact: 11/01/2022
Next Scheduled EDR Contact: 01/09/2023
Data Release Frequency: Quarterly

***Lists of Federal sites subject to CERCLA removals and CERCLA orders***

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 05/25/2021
Date Data Arrived at EDR: 06/24/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 09/06/2022
Next Scheduled EDR Contact: 01/10/2023
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 11/01/2022
Next Scheduled EDR Contact: 01/23/2023
Data Release Frequency: Quarterly

***Lists of Federal CERCLA sites with NFRAP***

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 11/01/2022
Next Scheduled EDR Contact: 01/23/2023
Data Release Frequency: Quarterly

***Lists of Federal RCRA facilities undergoing Corrective Action***

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

***Lists of Federal RCRA TSD facilities***

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

***Lists of Federal RCRA generators***

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

***Federal institutional controls / engineering controls registries***

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 08/16/2022
Date Data Arrived at EDR: 08/22/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 63

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 11/01/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 08/15/2022
Date Data Arrived at EDR: 08/17/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 68

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/17/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 08/15/2022
Date Data Arrived at EDR: 08/17/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 68

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/17/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: Varies

***Federal ERNS list***

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 06/14/2022
Date Data Arrived at EDR: 06/15/2022
Date Made Active in Reports: 06/21/2022
Number of Days to Update: 6

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 09/20/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

***Lists of state- and tribal hazardous waste facilities***

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Annually

***Lists of state and tribal landfills and solid waste disposal facilities***

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 06/29/2022
Date Data Arrived at EDR: 06/30/2022
Date Made Active in Reports: 09/15/2022
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 09/30/2022
Next Scheduled EDR Contact: 01/09/2023
Data Release Frequency: Quarterly

***Lists of state and tribal leaking storage tanks***

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/14/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/20/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/08/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/11/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/28/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 06/02/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/31/2022
Number of Days to Update: 79

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/28/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/20/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/26/2022
Number of Days to Update: 79

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

***Lists of state and tribal registered storage tanks***

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 10/14/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 02/01/2022
Number of Days to Update: 88

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 09/27/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 06/21/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 09/09/2022
Number of Days to Update: 80

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/20/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 06/21/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 09/09/2022
Number of Days to Update: 80

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/20/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 06/21/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 09/09/2022
Number of Days to Update: 80

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/20/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 06/21/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 09/09/2022
Number of Days to Update: 80

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/20/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/11/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 06/02/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/31/2022
Number of Days to Update: 79

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/08/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/20/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/07/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/20/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/14/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/28/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing
This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 06/21/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 09/09/2022
Number of Days to Update: 80
Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 09/20/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

***State and tribal institutional control / engineering control registries***

RES DECL: Restrictive Declarations Listing
A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 03/22/2022
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 09/02/2022
Number of Days to Update: 80
Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 09/12/2022
Next Scheduled EDR Contact: 12/26/2022
Data Release Frequency: Varies

ENV RES DECL: Environmental Restrictive Declarations
The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 03/22/2022
Date Data Arrived at EDR: 06/17/2022
Date Made Active in Reports: 09/02/2022
Number of Days to Update: 77
Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 09/12/2022
Next Scheduled EDR Contact: 12/26/2022
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls
Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 77
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls
Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 77
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Quarterly

***Lists of state and tribal voluntary cleanup sites***

VCP: Voluntary Cleanup Agreements
New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 09/13/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP NYC: Voluntary Cleanup Program Listing NYC
New York City voluntary cleanup program sites.

Date of Government Version: 06/06/2022
Date Data Arrived at EDR: 06/07/2022
Date Made Active in Reports: 08/25/2022
Number of Days to Update: 79

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 09/06/2022
Next Scheduled EDR Contact: 12/19/2022
Data Release Frequency: Varies

***Lists of state and tribal brownfield sites***

BROWNFIELDS: Brownfields Site List
A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing
In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Quarterly

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

**ADDITIONAL ENVIRONMENTAL RECORDS**

***Local Brownfield lists***

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 03/10/2022
Date Made Active in Reports: 03/10/2022
Number of Days to Update: 0

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 09/09/2022
Next Scheduled EDR Contact: 12/26/2022
Data Release Frequency: Semi-Annually

***Local Lists of Landfill / Solid Waste Disposal Sites***

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 09/06/2022
Next Scheduled EDR Contact: 12/19/2022
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 06/29/2022
Date Data Arrived at EDR: 06/30/2022
Date Made Active in Reports: 09/15/2022
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 09/30/2022
Next Scheduled EDR Contact: 01/09/2023
Data Release Frequency: Quarterly

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 10/20/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 10/11/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 10/28/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Varies

***Local Lists of Hazardous waste / Contaminated Sites***

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 07/29/2022
Date Data Arrived at EDR: 08/18/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 67

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/18/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 07/29/2022
Date Data Arrived at EDR: 08/18/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 67

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/18/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: Quarterly

***Local Lists of Registered Storage Tanks***

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

***Local Land Records***

LIENS: Spill Liens Information
Lien information from the Oil Spill Fund.

Date of Government Version: 07/27/2022
Date Data Arrived at EDR: 07/27/2022
Date Made Active in Reports: 10/12/2022
Number of Days to Update: 77
Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 10/27/2022
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14
Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 11/01/2022
Next Scheduled EDR Contact: 01/09/2023
Data Release Frequency: Semi-Annually

***Records of Emergency Release Reports***

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 09/19/2022
Date Data Arrived at EDR: 09/19/2022
Date Made Active in Reports: 09/30/2022
Number of Days to Update: 11
Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

SPILLS: Spills Information Database
Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/26/2022
Number of Days to Update: 79
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database
This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

***Other Ascertainable Records***

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 06/28/2022
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 08/11/2022
Date Data Arrived at EDR: 08/11/2022
Date Made Active in Reports: 09/30/2022
Number of Days to Update: 50

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 11/10/2022
Next Scheduled EDR Contact: 02/27/2023
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 10/13/2022
Next Scheduled EDR Contact: 01/23/2023
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 10/03/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 11/03/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 06/20/2022
Date Data Arrived at EDR: 06/21/2022
Date Made Active in Reports: 08/31/2022
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 09/20/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 10/28/2022
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 10/28/2022
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Varies

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/17/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 85

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 09/12/2022
Next Scheduled EDR Contact: 12/26/2022
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 08/14/2020
Date Made Active in Reports: 11/04/2020
Number of Days to Update: 82

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 11/01/2022
Next Scheduled EDR Contact: 02/27/2023
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 07/18/2022
Date Data Arrived at EDR: 07/18/2022
Date Made Active in Reports: 07/29/2022
Number of Days to Update: 11

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 10/18/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 11/01/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/04/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 10/27/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 11/01/2022
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 01/20/2022
Date Data Arrived at EDR: 01/20/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 64

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 10/06/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 09/27/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 06/10/2022
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 08/22/2022
Number of Days to Update: 69
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 10/11/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 84
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 08/25/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 08/25/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 11/03/2022
Next Scheduled EDR Contact: 02/13/2023
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 09/21/2022
Next Scheduled EDR Contact: 01/10/2023
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 10/24/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 06/30/2022
Date Data Arrived at EDR: 07/21/2022
Date Made Active in Reports: 09/30/2022
Number of Days to Update: 71

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 09/27/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 23

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 09/19/2022
Next Scheduled EDR Contact: 01/02/2023
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 10/06/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 07/26/2021
Date Data Arrived at EDR: 07/27/2021
Date Made Active in Reports: 10/22/2021
Number of Days to Update: 87

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 10/27/2022
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 11/09/2022
Next Scheduled EDR Contact: 02/27/2023
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 11/01/2022
Next Scheduled EDR Contact: 01/09/2023
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/03/2022
Date Data Arrived at EDR: 08/17/2022
Date Made Active in Reports: 08/31/2022
Number of Days to Update: 14

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 08/17/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: Semi-Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 08/01/2022
Date Data Arrived at EDR: 08/02/2022
Date Made Active in Reports: 09/30/2022
Number of Days to Update: 59

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 10/04/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: Quarterly

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/06/2020
Date Data Arrived at EDR: 05/27/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 78

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/17/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/17/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 06/14/2022
Date Data Arrived at EDR: 06/15/2022
Date Made Active in Reports: 08/22/2022
Number of Days to Update: 68

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 09/13/2022
Next Scheduled EDR Contact: 12/19/2022
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 08/03/2022
Date Data Arrived at EDR: 08/25/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 60

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 08/25/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: Quarterly

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 06/25/2022
Date Data Arrived at EDR: 07/01/2022
Date Made Active in Reports: 09/30/2022
Number of Days to Update: 91

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 09/30/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 01/11/2022
Date Made Active in Reports: 02/14/2022
Number of Days to Update: 34

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 10/05/2022
Next Scheduled EDR Contact: 01/23/2023
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 11/15/2022
Next Scheduled EDR Contact: 03/06/2023
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 08/11/2022
Date Data Arrived at EDR: 08/11/2022
Date Made Active in Reports: 09/30/2022
Number of Days to Update: 50

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 11/10/2022
Next Scheduled EDR Contact: 02/27/2023
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 07/08/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 123

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 10/04/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 10/06/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 01/03/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 10/04/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

Date of Government Version: 01/03/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 10/06/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 06/24/2020
Date Data Arrived at EDR: 03/17/2021
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 601

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 10/28/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 01/03/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 10/06/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits.

Date of Government Version: 01/03/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 10/06/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

Date of Government Version: 01/03/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 10/06/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Varies

PFAS ECHO FIRE TRAINING: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 08/22/2018
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 10/06/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Varies

PFAS PART 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 08/22/2018
Date Data Arrived at EDR: 10/26/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 10/26/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 10/06/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Varies

PFAS 2: New York State Inactive Landfill Initiative

A list of landfills that were investigated and the analytical results for PFOA and PFOS for those landfills. These data represent the landfills from the ILI database that were investigated.

Date of Government Version: 10/29/2021
Date Data Arrived at EDR: 11/19/2021
Date Made Active in Reports: 04/26/2022
Number of Days to Update: 158

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 10/27/2022
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 11/03/2022
Next Scheduled EDR Contact: 02/13/2023
Data Release Frequency: Varies

PFAS 3: PFAS Environmental Site Remediation List

Per- and Polyfluoroalkyl Substances (PFAS) are a group of chemicals used to make fluoropolymer coatings and products that resist heat, oil, stains, grease, and water. Fluoropolymer coatings are blends of resins and lubricants used in products such as water-repellent clothing, furniture, adhesives, paint and varnish, food packaging, heat-resistant non-stick cooking surfaces and insulation of electrical wires. Chemicals in this group include perfluorooctanoic acid (PFOA) and perfluorooctane sulfonic acid (PFOS).

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 99

Source: Department of Environmental Conservation
Telephone: 518-402-9759
Last EDR Contact: 11/07/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Varies

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 07/27/2022
Date Data Arrived at EDR: 07/27/2022
Date Made Active in Reports: 08/04/2022
Number of Days to Update: 8

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 10/11/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 06/23/2022
Date Data Arrived at EDR: 06/23/2022
Date Made Active in Reports: 09/09/2022
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 09/30/2022
Next Scheduled EDR Contact: 01/09/2023
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 08/30/2022
Date Data Arrived at EDR: 08/31/2022
Date Made Active in Reports: 09/07/2022
Number of Days to Update: 7

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 08/30/2022
Next Scheduled EDR Contact: 12/19/2022
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 09/21/2022
Date Data Arrived at EDR: 10/14/2022
Date Made Active in Reports: 10/19/2022
Number of Days to Update: 5

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 09/30/2022
Next Scheduled EDR Contact: 12/26/2022
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 09/29/2022
Date Data Arrived at EDR: 09/30/2022
Date Made Active in Reports: 10/06/2022
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 09/22/2022
Next Scheduled EDR Contact: 01/09/2023
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 06/11/2020
Date Data Arrived at EDR: 06/16/2020
Date Made Active in Reports: 09/02/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 08/30/2022
Next Scheduled EDR Contact: 12/19/2022
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NYC LEAD 2: Recent Lead Paint Violations

Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 08/01/2022
Date Data Arrived at EDR: 08/02/2022
Date Made Active in Reports: 10/18/2022
Number of Days to Update: 77

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 10/31/2022
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Varies

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 10/29/2021
Date Made Active in Reports: 01/19/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 10/28/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 03/25/2022
Date Data Arrived at EDR: 05/05/2022
Date Made Active in Reports: 05/18/2022
Number of Days to Update: 13

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 10/11/2022
Next Scheduled EDR Contact: 01/30/2023
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 11/10/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 08/24/2022
Date Data Arrived at EDR: 08/25/2022
Date Made Active in Reports: 11/14/2022
Number of Days to Update: 81

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 08/25/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 07/05/2022
Date Data Arrived at EDR: 07/12/2022
Date Made Active in Reports: 09/26/2022
Number of Days to Update: 76

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 10/10/2022
Next Scheduled EDR Contact: 01/23/2023
Data Release Frequency: Varies

PCS INACTIVE: Listing of Inactive PCS Permits

An inactive permit is a facility that has shut down or is no longer discharging.

Date of Government Version: 11/05/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 05/06/2015
Number of Days to Update: 120

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/28/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Semi-Annually

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 09/28/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Semi-Annually

MINES MRDS: Mineral Resources Data System

Mineral Resources Data System

Date of Government Version: 04/06/2018
Date Data Arrived at EDR: 10/21/2019
Date Made Active in Reports: 10/24/2019
Number of Days to Update: 3

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 08/17/2022
Next Scheduled EDR Contact: 12/05/2022
Data Release Frequency: Varies

NYC LEAD: Lead-based Paint Testing Results

The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 04/04/2022
Date Data Arrived at EDR: 05/04/2022
Date Made Active in Reports: 07/26/2022
Number of Days to Update: 83

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 10/31/2022
Next Scheduled EDR Contact: 02/16/2023
Data Release Frequency: Varies

PCS ENF: Enforcement data

No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 09/28/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Varies

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## EDR HIGH RISK HISTORICAL RECORDS

### *EDR Exclusive Records*

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

## EDR RECOVERED GOVERNMENT ARCHIVES

### *Exclusive Recovered Govt. Archives*

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

**COUNTY RECORDS**

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 10/20/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 10/20/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 11/02/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 10/20/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35
Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 11/02/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Varies

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35
Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 11/02/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 10/20/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 08/24/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 08/24/2022
Next Scheduled EDR Contact: 12/12/2022
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 10/20/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database

This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 10/20/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 10/20/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 07/20/2022
Date Data Arrived at EDR: 08/23/2022
Date Made Active in Reports: 11/14/2022
Number of Days to Update: 83

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 10/24/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 07/20/2022
Date Data Arrived at EDR: 08/23/2022
Date Made Active in Reports: 11/14/2022
Number of Days to Update: 83

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 10/24/2022
Next Scheduled EDR Contact: 02/06/2023
Data Release Frequency: Semi-Annually

**OTHER DATABASE(S)**

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/08/2022
Date Made Active in Reports: 10/21/2022
Number of Days to Update: 74

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 11/10/2022
Next Scheduled EDR Contact: 02/20/2023
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 10/03/2022
Next Scheduled EDR Contact: 01/16/2023
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 10/05/2022
Next Scheduled EDR Contact: 01/23/2023
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 11/09/2022
Next Scheduled EDR Contact: 02/27/2023
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 10/05/2022
Next Scheduled EDR Contact: 01/23/2023
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 08/29/2022
Next Scheduled EDR Contact: 12/19/2022
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

**STREET AND ADDRESS INFORMATION**

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

# GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

**TARGET PROPERTY ADDRESS**

15 VINE ST
15 VINE ST
LARCHMONT, NY 10538

**TARGET PROPERTY COORDINATES**

| | |
|---|---|
| Latitude (North): | 40.935478 - 40ˆ 56’ 7.72’’ |
| Longitude (West): | 73.758432 - 73ˆ 45’ 30.36’’ |
| Universal Tranverse Mercator: | Zone 18 |
| UTM X (Meters): | 604523.5 |
| UTM Y (Meters): | 4532125.0 |
| Elevation: | 41 ft. above sea level |

**USGS TOPOGRAPHIC MAP**

| | |
|---|---|
| Target Property Map: | 14105990 MOUNT VERNON, NY |
| Version Date: | 2019 |
| East Map: | 14105988 MAMARONECK, NY |
| Version Date: | 2019 |

EDR’s GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

**GROUNDWATER FLOW DIRECTION INFORMATION**

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

**TOPOGRAPHIC INFORMATION**

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

**TARGET PROPERTY TOPOGRAPHY**

General Topographic Gradient: General SSE

**SURROUNDING TOPOGRAPHY: ELEVATION PROFILES**




**Target Property Elevation: 41 ft.**

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

**HYDROLOGIC INFORMATION**

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

**FEMA FLOOD ZONE**

| Flood Plain Panel at Target Property | FEMA Source Type |
|---|---|
| 36119C0342F | FEMA FIRM Flood data |

| Additional Panels in search area: | FEMA Source Type |
|---|---|
| 36119C0334F | FEMA FIRM Flood data |
| 36119C0353F | FEMA FIRM Flood data |
| 36119C0361F | FEMA FIRM Flood data |

**NATIONAL WETLAND INVENTORY**

| NWI Quad at Target Property | NWI Electronic Data Coverage |
|---|---|
| MOUNT VERNON | YES - refer to the Overview Map and Detail Map |

**HYDROGEOLOGIC INFORMATION**

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

***Site-Specific Hydrogeological Data*:***

| | |
|---|---|
| Search Radius: | 1.25 miles |
| Status: | Not found |

**AQUIFLOW®**

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

| MAP ID | LOCATION FROM TP | GENERAL DIRECTION GROUNDWATER FLOW |
|---|---|---|
| Not Reported | | |

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

**GROUNDWATER FLOW VELOCITY INFORMATION**

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

**GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY**

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

**ROCK STRATIGRAPHIC UNIT**

| | |
|---|---|
| Era: | Paleozoic |
| System: | Ordovician |
| Series: | Middle Ordovician (Mohawkian) |
| Code: | O2 *(decoded above as Era, System & Series)* |

**GEOLOGIC AGE IDENTIFICATION**

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

# SSURGO SOIL MAP - 7180742.2s




Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

| | | | |
|---|---|---|---|
| SITE NAME: | 15 VINE ST | CLIENT: | American Petroleum |
| ADDRESS: | 15 VINE ST<br>LARCHMONT NY 10538 | CONTACT: | Michelle Nowak |
| | | INQUIRY #: | 7180742.2s |
| LAT/LONG: | 40.935478 / 73.758432 | DATE: | November 16, 2022 3:20 pm |

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

**DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY**

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

---

**Soil Map ID: 1**

Soil Component Name: Urban land

Soil Surface Texture:
Hydrologic Group: Not reported

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

---

**Soil Map ID: 2**

Soil Component Name: Charlton

Soil Surface Texture: loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 77 inches

Depth to Watertable Min: > 0 inches

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

| Soil Layer Information | | | | | | | |
|---|---|---|---|---|---|---|---|
| | Boundary | | | Classification | | Saturated hydraulic conductivity micro m/sec | Soil Reaction (pH) |
| Layer | Upper | Lower | Soil Texture Class | AASHTO Group | Unified Soil | | |
| 1 | 0 inches | 7 inches | loam | Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils. | COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand. | Max: 42 Min: 4 | Max: 6 Min: 4.5 |
| 2 | 7 inches | 24 inches | sandy loam | Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils. | COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand. | Max: 42 Min: 4 | Max: 6 Min: 4.5 |
| 3 | 24 inches | 59 inches | sandy loam | Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils. | COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand. | Max: 42 Min: 4 | Max: 6 Min: 4.5 |

---

**Soil Map ID: 3**

Soil Component Name: Urban land

Soil Surface Texture: loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 77 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

**Soil Map ID: 4**

Soil Component Name: Urban land

Soil Surface Texture: loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 77 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

**Soil Map ID: 5**

Soil Component Name: Chatfield

Soil Surface Texture: loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 77 inches

Depth to Watertable Min: > 0 inches

| Soil Layer Information | | | | | | | |
|---|---|---|---|---|---|---|---|
| | Boundary | | | Classification | | Saturated hydraulic conductivity micro m/sec | Soil Reaction (pH) |
| Layer | Upper | Lower | Soil Texture Class | AASHTO Group | Unified Soil | | |
| 1 | 0 inches | 7 inches | loam | Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils. | Not reported | Max: 141<br>Min: 0.07 | Max: Min: |

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

| Soil Layer Information | | | | | | | |
|---|---|---|---|---|---|---|---|
| | Boundary | | | Classification | | Saturated hydraulic conductivity micro m/sec | Soil Reaction (pH) |
| Layer | Upper | Lower | Soil Texture Class | AASHTO Group | Unified Soil | | |
| 2 | 7 inches | 24 inches | flaggy silt loam | Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils. | Not reported | Max: 141<br>Min: 0.07 | Max: Min: |
| 3 | 24 inches | 27 inches | unweathered bedrock | Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils. | Not reported | Max: 141<br>Min: 0.07 | Max: Min: |

**LOCAL / REGIONAL WATER AGENCY RECORDS**

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

**WELL SEARCH DISTANCE INFORMATION**

| DATABASE | SEARCH DISTANCE (miles) |
|---|---|
| Federal USGS | 1.000 |
| Federal FRDS PWS | Nearest PWS within 1 mile |
| State Database | 1.000 |

**FEDERAL USGS WELL INFORMATION**

| MAP ID | WELL ID | LOCATION FROM TP |
|---|---|---|
| 1 | USGS40000836249 | 1/2 - 1 Mile NNE |
| 2 | USGS40000835986 | 1/2 - 1 Mile South |
| 3 | USGS40000836175 | 1/2 - 1 Mile ENE |
| 4 | USGS40000836250 | 1/2 - 1 Mile NE |

**FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION**

| MAP ID | WELL ID | LOCATION FROM TP |
|---|---|---|
| No PWS System Found | | |

Note: PWS System location is not always the same as well location.

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

**STATE DATABASE WELL INFORMATION**

| MAP ID | WELL ID | LOCATION FROM TP |
|---|---|---|
| A5 | NYWS40000118481 | 1/2 - 1 Mile NNW |
| A6 | NYWS40000118480 | 1/2 - 1 Mile NNW |
| A7 | NYWS40000118479 | 1/2 - 1 Mile NNW |

# PHYSICAL SETTING SOURCE MAP - 7180742.2s




- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

| | |
|---|---|
| SITE NAME: 15 VINE ST | CLIENT: American Petroleum |
| ADDRESS: 15 VINE ST | CONTACT: Michelle Nowak |
| LARCHMONT NY 10538 | INQUIRY #: 7180742.2s |
| LAT/LONG: 40.935478 / 73.758432 | DATE: November 16, 2022 3:20 pm |

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

# GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

**1**
**NNE**
**1/2 - 1 Mile**
**Lower**

**FED USGS** **USGS40000836249**

| | | | |
|---|---|---|---|
| Organization ID: | USGS-NY | Organization Name: | USGS New York Water Science Center |
| Monitor Location: | WE 28 | Type: | Well |
| Description: | Not Reported | HUC: | 02030102 |
| Drainage Area: | Not Reported | Drainage Area Units: | Not Reported |
| Contrib Drainage Area: | Not Reported | Contrib Drainage Area Unts: | Not Reported |
| Aquifer: | Not Reported | Formation Type: | Bedrock |
| Aquifer Type: | Not Reported | Construction Date: | Not Reported |
| Well Depth: | 100 | Well Depth Units: | ft |
| Well Hole Depth: | Not Reported | Well Hole Depth Units: | Not Reported |

---

**2**
**South**
**1/2 - 1 Mile**
**Lower**

**FED USGS** **USGS40000835986**

| | | | |
|---|---|---|---|
| Organization ID: | USGS-NY | Organization Name: | USGS New York Water Science Center |
| Monitor Location: | WE 282 | Type: | Well |
| Description: | Not Reported | HUC: | 02030102 |
| Drainage Area: | Not Reported | Drainage Area Units: | Not Reported |
| Contrib Drainage Area: | Not Reported | Contrib Drainage Area Unts: | Not Reported |
| Aquifer: | Not Reported | Formation Type: | Bedrock |
| Aquifer Type: | Not Reported | Construction Date: | Not Reported |
| Well Depth: | 72 | Well Depth Units: | ft |
| Well Hole Depth: | Not Reported | Well Hole Depth Units: | Not Reported |

| | | | |
|---|---|---|---|
| Ground water levels,Number of Measurements: | 1 | Level reading date: | 1955 |
| Feet below surface: | 40.00 | Feet to sea level: | Not Reported |
| Note: | Not Reported | | |

---

**3**
**ENE**
**1/2 - 1 Mile**
**Lower**

**FED USGS** **USGS40000836175**

| | | | |
|---|---|---|---|
| Organization ID: | USGS-NY | Organization Name: | USGS New York Water Science Center |
| Monitor Location: | WE 147 | Type: | Well |
| Description: | Not Reported | HUC: | 02030102 |
| Drainage Area: | Not Reported | Drainage Area Units: | Not Reported |
| Contrib Drainage Area: | Not Reported | Contrib Drainage Area Unts: | Not Reported |
| Aquifer: | Not Reported | Formation Type: | Bedrock |
| Aquifer Type: | Not Reported | Construction Date: | Not Reported |
| Well Depth: | 308 | Well Depth Units: | ft |
| Well Hole Depth: | Not Reported | Well Hole Depth Units: | Not Reported |

| | | | |
|---|---|---|---|
| Ground water levels,Number of Measurements: | 1 | Level reading date: | 1955 |
| Feet below surface: | 8.00 | Feet to sea level: | Not Reported |
| Note: | Not Reported | | |

# GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

**4**
**NE**
**1/2 - 1 Mile**
**Higher**

**FED USGS** **USGS40000836250**

| | | | |
|---|---|---|---|
| Organization ID: | USGS-NY | Organization Name: | USGS New York Water Science Center |
| Monitor Location: | WE1077 | Type: | Well |
| Description: | Not Reported | HUC: | 02030102 |
| Drainage Area: | Not Reported | Drainage Area Units: | Not Reported |
| Contrib Drainage Area: | Not Reported | Contrib Drainage Area Unts: | Not Reported |
| Aquifer: | Not Reported | Formation Type: | Bedrock |
| Aquifer Type: | Not Reported | Construction Date: | Not Reported |
| Well Depth: | 100 | Well Depth Units: | ft |
| Well Hole Depth: | Not Reported | Well Hole Depth Units: | Not Reported |

| | | | |
|---|---|---|---|
| Ground water levels,Number of Measurements: | 1 | Level reading date: | 1955 |
| Feet below surface: | 15.00 | Feet to sea level: | Not Reported |
| Note: | Not Reported | | |

---

**A5**
**NNW**
**1/2 - 1 Mile**
**Higher**

**NY WELLS** **NYWS40000118481**

| | | | |
|---|---|---|---|
| DEC Well #: | WE6007 | Well Depth (ft): | 416 |
| Bedrock Depth (ft): | Not Reported | Groundwater Depth (ft): | 0 |
| Casing Depth (ft): | Not Reported | Casing 1 Diameter (in): | 6 |
| Casing 1 Length (ft): | 21 | Casing 2 Diameter (in): | Not Reported |
| Casing 2 Length (ft): | Not Reported | Screened Well: | N |
| Screen Length (ft): | Not Reported | Avg Discharge Rate (gpm): | 0 |
| Well Purpose: | Geothermal | Driller Registration #: | NYRD01695 |

---

**A6**
**NNW**
**1/2 - 1 Mile**
**Higher**

**NY WELLS** **NYWS40000118480**

| | | | |
|---|---|---|---|
| DEC Well #: | WE6006 | Well Depth (ft): | 446 |
| Bedrock Depth (ft): | Not Reported | Groundwater Depth (ft): | 0 |
| Casing Depth (ft): | Not Reported | Casing 1 Diameter (in): | 6 |
| Casing 1 Length (ft): | 10 | Casing 2 Diameter (in): | Not Reported |
| Casing 2 Length (ft): | Not Reported | Screened Well: | N |
| Screen Length (ft): | Not Reported | Avg Discharge Rate (gpm): | 10 |
| Well Purpose: | Geothermal | Driller Registration #: | NYRD01695 |

---

**A7**
**NNW**
**1/2 - 1 Mile**
**Higher**

**NY WELLS** **NYWS40000118479**

| | | | |
|---|---|---|---|
| DEC Well #: | WE6005 | Well Depth (ft): | 4 |
| Bedrock Depth (ft): | Not Reported | Groundwater Depth (ft): | 0 |
| Casing Depth (ft): | Not Reported | Casing 1 Diameter (in): | 6 |
| Casing 1 Length (ft): | 21 | Casing 2 Diameter (in): | Not Reported |

| | | | |
|---|---|---|---|
| Casing 2 Length (ft): | Not Reported | Screened Well: | N |
| Screen Length (ft): | Not Reported | Avg Discharge Rate (gpm): | 1 |
| Well Purpose: | Geothermal | Driller Registration #: | NYRD01695 |

# GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
# RADON

**AREA RADON INFORMATION**

State Database: NY Radon

Radon Test Results

| County | Town | Num Tests | Avg Result | Geo Mean | Max Result |
|---|---|---|---|---|---|
| WESTCHESTER | BEDFORD | 108 | 2.44 | 1.65 | 21.7 |
| WESTCHESTER | CORTLANDT | 169 | 5.15 | 2.22 | 95.4 |
| WESTCHESTER | EASTCHESTER | 76 | 2.89 | 1.75 | 41.9 |
| WESTCHESTER | GREENBURGH | 222 | 2.26 | 1.46 | 21.8 |
| WESTCHESTER | HARRISON | 69 | 3.3 | 2.07 | 42.3 |
| WESTCHESTER | LEWISBORO | 72 | 3.91 | 2.61 | 19.2 |
| WESTCHESTER | MAMARONECK | 123 | 4 | 2.42 | 35.9 |
| WESTCHESTER | MT. KISCO | 38 | 2.33 | 1.72 | 9.3 |
| WESTCHESTER | MT. PLEASANT | 172 | 2.13 | 1.43 | 17.1 |
| WESTCHESTER | MT. VERNON | 53 | 2.82 | 1.65 | 32 |
| WESTCHESTER | NEW CASTLE | 134 | 2.2 | 1.46 | 31.7 |
| WESTCHESTER | NEW ROCHELLE | 127 | 1.92 | 1.31 | 13.8 |
| WESTCHESTER | NO. CASTLE | 64 | 3.49 | 2.25 | 16.5 |
| WESTCHESTER | NO. SALEM | 56 | 3.78 | 2.56 | 25.7 |
| WESTCHESTER | OSSINING | 65 | 2.08 | 1.39 | 10.9 |
| WESTCHESTER | PEEKSKILL | 47 | 3.66 | 2.34 | 19.9 |
| WESTCHESTER | PELHAM | 26 | 2.5 | 1.91 | 9.1 |
| WESTCHESTER | POUND RIDGE | 34 | 3.37 | 2.22 | 18.5 |
| WESTCHESTER | RYE | 98 | 2.24 | 1.63 | 9.5 |
| WESTCHESTER | SCARSDALE | 138 | 2.35 | 1.63 | 22.4 |
| WESTCHESTER | SOMERS | 72 | 3.89 | 2.82 | 21.3 |
| WESTCHESTER | WHITE PLAINS | 132 | 2.76 | 1.48 | 65.2 |
| WESTCHESTER | YONKERS | 153 | 2.23 | 1.37 | 16 |
| WESTCHESTER | YORKTOWN | 181 | 2.7 | 1.72 | 27.2 |

Federal EPA Radon Zone for WESTCHESTER County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

---

Federal Area Radon Information for WESTCHESTER COUNTY, NY

Number of sites tested: 650

| Area | Average Activity | % <4 pCi/L | % 4-20 pCi/L | % >20 pCi/L |
|---|---|---|---|---|
| Living Area | 0.930 pCi/L | 97% | 3% | 0% |
| Basement | 1.730 pCi/L | 84% | 13% | 2% |

# PHYSICAL SETTING SOURCE RECORDS SEARCHED

## TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

## HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

## HYDROGEOLOGIC INFORMATION

AQUIFLOW$^{R}$ Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

## GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

# PHYSICAL SETTING SOURCE RECORDS SEARCHED

## LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

## OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

# PHYSICAL SETTING SOURCE RECORDS SEARCHED

**STREET AND ADDRESS INFORMATION**

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

**1-5 VINE ST**
1 - 5 VINE ST
LARCHMONT, NY 10538

Inquiry Number: 7180742.5
November 29, 2022

# The EDR-City Directory Image Report

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

# TABLE OF CONTENTS

## SECTION

**Executive Summary**

**Findings**

**City Directory Images**

***Thank you for your business.***
Please contact EDR at 1-800-352-0050
with any questions or comments.

**Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

# EXECUTIVE SUMMARY

## DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

## RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

Data by
infoUSA®
Copyright©2008
All Rights Reserved

## RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

| Year | Target Street | Cross Street | Source |
|---|---|---|---|
| 2017 | ☑ | ☐ | EDR Digital Archive |
| 2014 | ☑ | ☐ | EDR Digital Archive |
| 2010 | ☑ | ☐ | EDR Digital Archive |
| 2005 | ☑ | ☐ | EDR Digital Archive |
| 2000 | ☐ | ☐ | EDR Digital Archive |
| 1995 | ☑ | ☐ | EDR Digital Archive |
| 1992 | ☑ | ☐ | EDR Digital Archive |
| 1987 | ☑ | ☐ | Cole Criss-Cross Directory |
| 1982 | ☑ | ☐ | Cole Criss-Cross Directory |
| 1977 | ☑ | ☐ | Cole Criss-Cross Directory |
| 1972 | ☑ | ☐ | Cole Criss-Cross Directory |

# FINDINGS

## TARGET PROPERTY STREET

1 - 5 VINE ST
LARCHMONT, NY 10538

| *Year* | *CD Image* | *Source* | |
|---|---|---|---|
| **VINE ST** | | | |
| 2017 | pg A1 | EDR Digital Archive | |
| 2014 | pg A2 | EDR Digital Archive | |
| 2010 | pg A3 | EDR Digital Archive | |
| 2005 | pg A4 | EDR Digital Archive | |
| 2000 | - | EDR Digital Archive | Target and Adjoining not listed in Source |
| 1995 | pg A5 | EDR Digital Archive | |
| 1992 | pg A6 | EDR Digital Archive | |
| 1987 | pg A7 | Cole Criss-Cross Directory | |
| 1982 | pg A8 | Cole Criss-Cross Directory | |
| 1977 | pg A9 | Cole Criss-Cross Directory | |
| 1972 | pg A10 | Cole Criss-Cross Directory | |

# FINDINGS

## CROSS STREETS

No Cross Streets Identified

# City Directory Images

| Target Street | Cross Street | Source |
| --- | --- | --- |
| ✓ | - | EDR Digital Archive |

# VINE ST 2017

| | |
| --- | --- |
| 1 | AVIS |
| | SOUND SHORE LIMOUSINE SVCE INC |
| 5 | MAGIC TOUCH CLEANING INC |

| Target Street | Cross Street | Source |
| --- | --- | --- |
| ✓ | - | EDR Digital Archive |

## VINE ST 2014

| | |
| --- | --- |
| 1 | AVIS |
| | SOUND SHORE LIMOUSINE SERVICE INCORP |
| 5 | MAGIC TOUCH CLEANING INC |

| Target Street | Cross Street | Source |
| --- | --- | --- |
| ✓ | - | EDR Digital Archive |

## VINE ST 2010

| | |
| --- | --- |
| 1 | AVIS RENT A CAR |
| | CLASSIC CAR SVC OF LARCHMONT |
| | J & F CHATSWORTH LTD |
| 5 | MAGIC TOUCH CLEANERS |

| Target Street | Cross Street | Source |
|---|---|---|
| ✓ | - | EDR Digital Archive |

## VINE ST 2005

| | |
|---|---|
| 1 | AVIS RENT A CAR |
| | CLASSIC CAR SERVICE LARCHMONT |
| | J & F CHATSWORTH GARAGE AUTO BODY |
| | OCCUPANT UNKNOWN, |
| | SOUND SHORE LIMOUSINE SERVICE |
| 5 | MAGIC TOUCH CLEANERS |
| | OCCUPANT UNKNOWN, |
| 38 | SERIO, ROBERT |

| Target Street | Cross Street | Source |
|---|---|---|
| ✓ | - | EDR Digital Archive |

## VINE ST 1995

| | |
|---|---|
| 1 | ANJ AUTO MACHINE SHOP & PARTS |
| | AVIS RENT A CAR-LOCAL RESERVATIONS & INFORMATI-LARCHMONT |
| | J & F CHATSWORTH LTD |
| | SOUND SHORE LIMOUSINE SVCE INC |
| 5 | MAGIC TOUCH CLEANERS |

| Target Street | Cross Street | Source |
|---|---|---|
| ✓ | - | EDR Digital Archive |

## VINE ST 1992

| | |
|---|---|
| 1 | ANJ AUTO MACHINE SHOP & PARTS |
| | AVIS RENT A CAR-LOCAL RESERVATIONS & INFORMATI-LARCHMONT |
| | J & F CHATSWORTH LTD |
| | SOUND SHORE LIMOUSINE SVCE INC |
| 5 | ANNA MARIE DRY CLNRS |

| Target Street | Cross Street | Source |
|---|---|---|
| ✓ | - | Cole Criss-Cross Directory |

**VINE ST 1987**

## VINE RD 10538

Larchmont PO

| | | 1– END CT | 70 | $A..K 5 |
|---|---|---|---|---|
| 1 | ★ | Avis Rent A Car | . . . | 834–8883 |
| | ★ | Chatsworth Auto | . . .73 | 834–9128 |
| | ★ | J&F Chatsworth | . . . .82 | 834–0008 |
| | ★ | No Frll Rent A Car | . . – | 834–8008 |
| | ★ | Sound Shore Limos | . . ⌑ | 834–7311 |
| 2 | | Bruce G McKenzie | . . .78 | 834–5506 |
| 3 | | Thomas P Cawley | . . .75 | 834–2977 |
| 4 | | William M Gips | . . . .55 | 834–3253 |
| 5 | | J R Hendrichs | . . . . ⌑ | 834–0665 |
| | ★ | Michels French Dry | . . | 834–1632 |
| 6 | | C Higgins | . . . . . ⌑ | 834–9605 |
| 8 | | Robert J Sklarew | . . .72 | 834–2423 |
| 22 | | E L Wright | . . . . .72 | 834–2381 |
| | | P T Wright | . . . . .73 | 834–1818 |
| 32 | ★ | Belle Forma Lctns | . . . – | 834–5554 |
| 34 | | Edward G Demartin | . . .83 | 834–0347 |
| 35 | | . . . . . | NP | |
| 36 | | T Jantos | . . . . . .85 | 834–3234 |
| 37 | | Harry Devries | . . . . .69 | 834–0887 |
| 38 | | Ilkka Ruso | . . . . . ⌑ | 834–0786 |
| 39 | | Ralph Best | . . . . . .74 | 834–6619 |
| 40 | | James R McGee | . . . .67 | 834–4476 |
| 41 | | Anita Lev–Gur | . . . . .85 | 834–2276 |
| | ★ | Dr Michael Lev–Gur | . .84 | 834–0988 |
| 42 | | P Shar | . . . . . .83 | 834–1152 |
| 43 | ★ | Dr E Friedman | . . . . – | 834–4166 |
| 44 | | Stuart Moak | . . . . . .61 | 834–3995 |
| 45 | | R Semer | . . . . . .79 | 834–5918 |
| 46 | | Jeff Osborne | . . . . . .79 | 834–1014 |
| 47 | ★ | Dr H C Weinstein | . . .77 | 834–7733 |
| | | Laura Weinstein | . . . .79 | 834–4238 |
| | | R Weinstein | . . . . . .73 | 834–2714 |

| Target Street | Cross Street | Source |
|---|---|---|
| ✓ | - | Cole Criss-Cross Directory |

**VINE ST 1982**

## VINE RD 10538

**Larchmont PO**

**1- END TZ 70 $A..Q 4**

**124070**

| | | | |
|---|---|---|---|
| **1** | **★Avis Rent A Car** | | **834-8883** |
| | **★Chatsworth Auto** | | **834-9128** |
| | **★Chatsworth Garage** | | **834-0008** |
| | **★Diezelcar Inc** | | **834-5000** |
| | **★Sports&Sedn Ato Sv** | | **834-5000** |
| 2 | Bruce G McKenzie | .78 | 834-5506 |
| 3 | Thomas P Cawley | .75 | 834-2977 |
| 4 | William Gips | | 834-3253 |
| **5** | **★Michels French Dry** | | **834-1632** |
| | Joseph W Tiso | .73 | 834-9093 |
| 6 | C B Mahoney | .76 | 834-9427 |
| 8 | Robert J Srlarew | .72 | 834-2423 |
| 22 | E L Wright | .72 | 834-2381 |
| | S B Wright | .73 | 834-1818 |
| 32 | Edward T Brandt Jr | .71 | 834-4007 |
| 34 | | NP | |
| 35 | Joachim J Heik | .75 | 834-0044 |
| | J J Schulz-Heik | .75 | 834-7999 |
| 36 | Michael L Domecq | .77 | 834-3234 |
| 37 | Harry Devries | .69 | 834-0887 |
| 38 | Leonard Rosenberg | .69 | 834-0786 |
| 39 | Ralph S Best | .71 | 834-6619 |
| 40 | James R McGee | .67 | 834-4476 |
| 41 | Richard Young | .79 | 834-3081 |
| 42 | Michael Hyland Jr | .77 | 834-7064 |
| 43 | Marvin Friedman | .74 | 834-4166 |
| 44 | Stuart Moak | | 834-3995 |
| 45 | Margaret Rodgers | .78 | 834-0846 |
| | R Semer | .79 | 834-5918 |
| 46 | Jeff Osborne | .79 | 834-1014 |
| **47** | **★Dr H C Weinstein** | | **834-7733** |
| | Laura Weinstein | .79 | 834-4238 |
| | R Weinstein | .73 | 834-2714 |

| Target Street | Cross Street | Source |
|---|---|---|
| ✓ | - | Cole Criss-Cross Directory |

# VINE ST 1977

## VINE RD 10538

Larchmont PO

1- END TZ 70 $A..Q 4

| | | | |
|---|---|---|---|
| 1 | ★Avis Rent A Car | | TE4-8883 |
| | ★Chatsworth Auto | | 834-9128 |
| | ★Chatswrth Garage | | 834-0008 |
| | ★Sports&Sedn Ato Sv | ¤ | 834-5000 |
| 2 | Peter B Shaffer | 2 | 834-9121 |
| 3 | Thomas P Cawley | 5 | 834-2977 |
| 4 | William Gips | | TE4-3253 |
| 5 | ★Michels French Dry | | TE4-1632 |
| | Joseph W Tiso | 3 | 834-9093 |
| 6 | C B Mahoney | ¤ | 834-9427 |
| 8 | Robert J Srlarew | 2 | 834-2423 |
| 22 | E L Wright | 2 | 834-2381 |
| | S B Wright | 3 | TE4-1818 |
| 32 | Edward T Brandt Jr | 1 | 834-4007 |
| 34 | | NP | |
| 35 | Joachim J Heik | | 834-0044 |
| | J J Schulz-Heik | 5 | 834-7999 |
| 36 | Michael G Marks | 1 | 834-9035 |
| 37 | Harry Devries | 9 | 834-0887 |
| 38 | Leonard Rosenberg | 9 | 834-0786 |
| 39 | Ralph S Best | 1 | 834-6619 |
| 40 | James R McGee | 7 | TE4-4476 |
| 41 | John M Delehanty | 4 | 834-6451 |
| 42 | | NP | |
| 43 | Marvin Friedman | 4 | 834-4166 |
| 44 | Stuart Moak | | TE4-3995 |
| 45 | William H Delhagen | | TE4-4767 |
| 46 | Samuel Stein | 0 | 834-9462 |
| | Mrs Samuel Stein | 0 | 834-9261 |
| 47 | ★Dr H Weinstein | | 834-7733 |
| | R Weinstein | 3 | 834-2714 |
| 48 | | NP | |
| 50 | Simon Posner | | TE4-1356 |
| 51 | Gary J Strum | 3 | 834-0863 |
| 53 | | NP | |
| 55 | Emerson White Jr | | 834-8834 |
| 57 | Thomas F Casey | | TE4-5157 |
| 58 | S F Bauer | ¤ | 834-1736 |
| | ★Dr Stephen Bauer | | 834-4702 |

| Target Street | Cross Street | Source |
|---|---|---|
| ✓ | - | Cole Criss-Cross Directory |

**VINE ST 1972**

VINE RD 10538

LARCHMONT PO

1- END T 70 $A..Q 4

| | | | |
|---|---|---|---|
| 2 | RICHARD K HEAVILON | | TE42656 |
| 3 | REYNOLD DREWS | | TE46029 |
| 4 | WILLIAM GIPS | | TE43253 |
| 5 | CLARENCE E MEEK | 0 | TE41572 |
| 6 | HOWARD B LEE | | TE45570 |
| 8 | R D TOBIAS | 5 | TE48599 |
| 22 | WILLIAM WRIGHT III | | TE41818 |
| 32 | EDWARD T BRANDT JR | | -8344007 |
| 34 | THOMAS V CARLEY | | TE45775 |
| 35 | | NP | |
| 36 | MICHAEL G MARKS | | ¤8349035 |
| 37 | HARRY DEVRIES | 9 | 8340887 |
| 38 | LEONARD ROSENBERG | 9 | 8340786 |
| 39 | RALPH S BEST | | ¤8346619 |
| 40 | JAMES R MCGEE | 7 | TE44476 |
| 41 | DAVID MEADOW | 4 | 8342061 |
| 42 | H P CUNNINGHAM | | TE40458 |
| 43 | DR KONRAD H WEIS | | ¤8340429 |
| 44 | STUART MOAK | | TE43995 |
| 45 | WILLIAM H DELHAGEN | | TE44767 |
| 46 | MRS SAMUEL STEIN | 0 | 8349261 |
| 47 | G J CONILL | | -8347708 |
| 48 | ALAN J PECKOLICK | 0 | 8343025 |
| 50 | SIMON POSNER | | TE41356 |
| 51 | HARRY GILBURT | | TE40059 |
| 53 | GEORGE M CLELAND | | TE43794 |
| 55 | EMERSON WHITE JR | 4 | 8348834 |
| 57 | THOMAS F CASEY | 4 | TE45157 |
| 58 | BARBARA BAUER | 9 | 8341736 |
| 59 | SIDNEY C PHILIP | | TE45337 |
| 60 | MRS BARBARA FIELDS | 4 | 8343773 |
| 61 | F P OHARA | 0 | 8347816 |

AS AUTHORIZED IN WRITING BY THE PUBLISHER.

15 VINE ST

15 VINE ST

LARCHMONT, NY 10538

Inquiry Number: 7180742.3

November 17, 2022

# Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

# Certified Sanborn® Map Report

11/17/22

| Site Name: | Client Name: |
|---|---|
| 15 VINE ST | American Petroleum |
| 15 VINE ST | 63 Orange Avenue |
| LARCHMONT, NY 10538 | Walden, NY 12586 |
| EDR Inquiry # 7180742.3 | Contact: Michelle Nowak |

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by American Petroleum were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

## *Certified Sanborn Results:*

**Certification #** BA7D-4600-846B

**PO #** NA

**Project** Vine Street Phase I

**Maps Provided:**

| | |
|---|---|
| 2003 | 1942 |
| 1996 | 1934 |
| 1995 | 1919 |
| 1994 | 1911 |
| 1992 | |
| 1988 | |
| 1963 | |
| 1950 | |

Sanborn® Library search results

Certification #: BA7D-4600-846B

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

*The Sanborn Library LLC Since 1866™*

### Limited Permission To Make Copies

American Petroleum (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.


**Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

## *Sanborn Sheet Key*

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

### 2003 Source Sheets

Volume 1, Sheet 15
2003



Volume 1, Sheet 16
2003

Volume 1, Sheet 2
2003

### 1996 Source Sheets

Volume 1, Sheet 2
1996

Volume 1, Sheet 16
1996

Volume 1, Sheet 15
1996

### 1995 Source Sheets

Volume 1, Sheet 15
1995

Volume 1, Sheet 16
1995

Volume 1, Sheet 2
1995

### 1994 Source Sheets

Volume 1, Sheet 2
1994

Volume 1, Sheet 16
1994

Volume 1, Sheet 15
1994

## *Sanborn Sheet Key*

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

### 1992 Source Sheets

Volume 1, Sheet 15
1992

Volume 1, Sheet 2
1992

Volume 1, Sheet 16
1992

### 1988 Source Sheets

Volume 1, Sheet 2
1988



Volume 1, Sheet 15
1988



Volume 1, Sheet 16
1988

### 1963 Source Sheets

Volume 1, Sheet 15
1963

Volume 1, Sheet 2
1963



Volume 1, Sheet 16
1963

### 1950 Source Sheets



Volume 1, Sheet 16
1950



Volume 1, Sheet 15
1950

## *Sanborn Sheet Key*

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

### 1942 Source Sheets

Volume 1, Sheet 20
1942

Volume 1, Sheet 19
1942

### 1934 Source Sheets

Volume 1, Sheet 15
1934

Volume 1, Sheet 16
1934

### 1919 Source Sheets



Volume 1, Sheet 13
1919

Volume 1, Sheet 3
1919

### 1911 Source Sheets

Volume 1, Sheet 2
1911




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #BA7D-4600-846B

| | |
|---|---|
| Site Name: | 15 VINE ST |
| Address: | 15 VINE ST |
| City, ST, ZIP: | LARCHMONT, NY 10538 |
| Client: | American Petroleum |
| EDR Inquiry: | 7180742.3 |
| Order Date: | 11/17/2022 |
| Certification #: | BA7D-4600-846B |
| Copyright | 2003 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600






Volume 1, Sheet 2
Volume 1, Sheet 16
Volume 1, Sheet 15

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | 15 VINE ST |
| Address: | 15 VINE ST |
| City, ST, ZIP: | LARCHMONT, NY 10538 |
| Client: | American Petroleum |
| EDR Inquiry: | 7180742.3 |
| Order Date: | 11/17/2022 |
| Certification #: | BA7D-4600-846B |
| Copyright | 1996 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600






Volume 1, Sheet 15
Volume 1, Sheet 16
Volume 1, Sheet 2

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | 15 VINE ST |
| Address: | 15 VINE ST |
| City, ST, ZIP: | LARCHMONT, NY 10538 |
| Client: | American Petroleum |
| EDR Inquiry: | 7180742.3 |
| Order Date: | 11/17/2022 |
| Certification #: | BA7D-4600-846B |
| Copyright | 1995 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 2
Volume 1, Sheet 16
Volume 1, Sheet 15

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | 15 VINE ST |
| Address: | 15 VINE ST |
| City, ST, ZIP: | LARCHMONT, NY 10538 |
| Client: | American Petroleum |
| EDR Inquiry: | 7180742.3 |
| Order Date: | 11/17/2022 |
| Certification #: | BA7D-4600-846B |
| Copyright | 1994 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 15
Volume 1, Sheet 16
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | 15 VINE ST |
| Address: | 15 VINE ST |
| City, ST, ZIP: | LARCHMONT, NY 10538 |
| Client: | American Petroleum |
| EDR Inquiry: | 7180742.3 |
| Order Date: | 11/17/2022 |
| Certification #: | BA7D-4600-846B |
| Copyright | 1992 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600






Volume 1, Sheet 16
Volume 1, Sheet 2
Volume 1, Sheet 15

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | 15 VINE ST |
| Address: | 15 VINE ST |
| City, ST, ZIP: | LARCHMONT, NY 10538 |
| Client: | American Petroleum |
| EDR Inquiry: | 7180742.3 |
| Order Date: | 11/17/2022 |
| Certification #: | BA7D-4600-846B |
| Copyright | 1988 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 16
Volume 1, Sheet 15
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | 15 VINE ST |
| Address: | 15 VINE ST |
| City, ST, ZIP: | LARCHMONT, NY 10538 |
| Client: | American Petroleum |
| EDR Inquiry: | 7180742.3 |
| Order Date: | 11/17/2022 |
| Certification #: | BA7D-4600-846B |
| Copyright | 1963 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600






Volume 1, Sheet 16
Volume 1, Sheet 2
Volume 1, Sheet 15

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #BA7D-4600-846B

| | |
|---|---|
| Site Name: | 15 VINE ST |
| Address: | 15 VINE ST |
| City, ST, ZIP: | LARCHMONT, NY 10538 |
| Client: | American Petroleum |
| EDR Inquiry: | 7180742.3 |
| Order Date: | 11/17/2022 |
| Certification #: | BA7D-4600-846B |
| Copyright | 1950 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 15
Volume 1, Sheet 16

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | 15 VINE ST |
| Address: | 15 VINE ST |
| City, ST, ZIP: | LARCHMONT, NY 10538 |
| Client: | American Petroleum |
| EDR Inquiry: | 7180742.3 |
| Order Date: | 11/17/2022 |
| Certification #: | BA7D-4600-846B |
| Copyright | 1942 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600






Volume 1, Sheet 19
Volume 1, Sheet 20

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | 15 VINE ST |
| Address: | 15 VINE ST |
| City, ST, ZIP: | LARCHMONT, NY 10538 |
| Client: | American Petroleum |
| EDR Inquiry: | 7180742.3 |
| Order Date: | 11/17/2022 |
| Certification #: | BA7D-4600-846B |
| Copyright | 1934 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 16
Volume 1, Sheet 15

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | 15 VINE ST |
| Address: | 15 VINE ST |
| City, ST, ZIP: | LARCHMONT, NY 10538 |
| Client: | American Petroleum |
| EDR Inquiry: | 7180742.3 |
| Order Date: | 11/17/2022 |
| Certification # | BA7D-4600-846B |
| Copyright | 1919 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600






Volume 1, Sheet 3
Volume 1, Sheet 13

N

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #BA7D-4600-846B




| | |
|---|---|
| Site Name: | 15 VINE ST |
| Address: | 15 VINE ST |
| City, ST, ZIP: | LARCHMONT, NY 10538 |
| Client: | American Petroleum |
| EDR Inquiry: | 7180742.3 |
| Order Date: | 11/17/2022 |
| Certification #: | BA7D-4600-846B |
| Copyright | 1911 |

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600

Volume 1, Sheet 2






N

**Appendix D: Interview Documentation**
Owner Questionnaire
Municipal FOIL
DEC FOIL

PHASE I OWNER/OPERATOR QUESTIONNAIRE

**1. RESPONDENT INFORMATION**

| Name, title, and business of person completing the questionnaire: Vincent Sparano J & F Chatsworth Ltd<br>General Manager | |
|---|---|
| How are you associated with the property?<br>Property owner Family | Years associated with the property:<br>24 |

**2. PROPERTY INFORMATION**

| Property address: 1 Vine St Larchmont | |
|---|---|
| Acreage of the property: | |
| Number of buildings: 1<br>square footages: 15,000<br>construction dates: | |
| Tenant names and description of current operations:<br>J & F Chatsworth Ltd - Mechanic Shp<br>J & F Chatsworth Autobody - Autobody | Magic Touch Cleaners<br>Dry Cleaner |
| Description of historical operations/site development (provide dates): | |
| Planned future use of the property/buildings: | |

3. **SEWER, WATER, AND HEATING SYSTEMS**

| Public Sewer<br>☒ Yes, describe:<br>☐ No<br>☐ Unknown | *If yes, provide the year the property/buildings were connected to the public sewer:* |
|---|---|

| | |
|---|---|
| Septic Systems<br>☐ Yes, describe:<br>☒ No<br>☐ Unknown | *If yes, provide the date installed and location of the current system:* |
| Previous Septic Systems<br>☐ Yes, describe:<br>☒ No<br>☐ Unknown | *If yes, provide the date installed/removed and location of the former system:* |
| Current Heating Systems<br>☒ Yes, describe: Natural Gas used oil<br>☐ No<br>☐ Unknown | *If yes, provide dates, fuel source, and location of current furnaces/boilers, etc.:* |
| Former Heating Systems<br>☐ Yes, describe:<br>☐ No<br>☒ Unknown | |

## 4. SPECIALIZED KNOWLEDGE

| |
|---|
| Do you have any knowledge that operations on or releases from adjacent or nearby properties impacted the soil or groundwater on the subject property?<br>☐Yes, describe:<br>☒No<br>☐Unknown |
| Have there been or are there any environmental complaints, environmental violations, enforcement actions, or environmental liens associated with the subject property, or have there been any Activity and Use Limitations applied to the subject property?<br>☐Yes, describe:<br>☒No<br>☐Unknown |
| Have there been any community right-to-know plans, safety plans, preparedness and prevention plans, spill prevention plans, countermeasure plans, facility response plans, or safety data documents, etc. prepared for the subject property?<br>☐Yes, describe:<br>☒No |

| |
|---|
| ☐Unknown |
| Are there any environmental permits associated with the subject property or are there other environmental compliance documents that are required to be submitted to any regulatory agency on a regular basis? This may involve solid or hazardous wastes disposal/generation, wastewater discharges, air emissions, stormwater discharges, or underground injection wells, etc.<br>☒Yes, describe: Westchester Cant Board of Health Spray Booth emissions points<br>☐No<br>☐Unknown |
| Are there any aboveground or underground storage tank registrations, underground injection system registrations, or any other registrations associated with the subject property?<br>☒Yes, describe: 2 above ground Oil Tanks<br>☐No<br>☐Unknown |
| Have there been any previous environmental reports completed for the subject property? Previous studies may include Environmental Site Assessments, Phase II ESAs, subsurface investigations, remediation reports, tank closures, groundwater monitoring reports, corrective action reports, Brownfield reports, geotechnical reports, hydrogeological reports, risk assessments, and/or compliance audit reports, etc.<br>☒Yes, describe: Tank Removals<br>☐No<br>☐Unknown |

**5.POTENTIAL DISCHARGES**

| | |
|---|---|
| Floor drains<br>☐Yes, describe:<br>☒No<br>☐Unknown | *(If yes, provide the location of the feature and discharge point)* |
| Sump pumps Basement water<br>☒Yes, describe: | *(If yes, provide the location of the feature and discharge point)* |

| | |
|---|---|
| ☐No<br>☐Unknown | |
| Stormwater<br>☐Yes, describe:<br>☒No<br>☐Unknown | *(If yes, provide the location of the feature and discharge point)* |
| Injection/Dry Wells<br>~~☐Yes, describe:~~ ~~dry well~~<br>☒No<br>☐Unknown | *(If yes, provide the location of the feature and discharge point)* |
| Oil/water separator<br>☐Yes, describe:<br>☒No<br>☐Unknown | *(If yes, provide the location of the feature and discharge point)* |
| Other discharges<br>☐Yes, describe:<br>☒No<br>☐Unknown | |

**6.ABOVEGROUND AND UNDERGROUND STORAGE TANKS**

| | |
|---|---|
| Current Aboveground Tanks<br>☒Yes, describe:<br>☐No<br>☐Unknown | *Provide install dates; size, location, and construction of tanks; and monitoring systems:*<br>250 x 2<br>Oil tanks Neural |
| Current Underground Tanks<br>☒Yes, describe: Decamissioned Oil tank | *Provide install dates; size, location, and construction of tanks; and monitoring systems:* |

| | |
|---|---|
| ☐No<br>☐Unknown | |
| Previous Aboveground or Underground Tanks<br>☐Yes, describe:<br>☐No<br>☐Unknown | |

Printed Name: Vincent Sparano

Signature: 

Date: 11/30/22

**Town of Mamaroneck**
**Building Department**
**740 West Boston Post Road**
**(914) 381-7830 Fax: (914) 381-8473**

**11/16/2022**

# PARCEL HISTORY

**Address:** 1-5 Vine St

**Parcel ID:** 1-26-730

| Issued Date | Item | Status | CO/CC # | CO/CC Date |
|---|---|---|---|---|
| 6/27/1927 | PERMIT #:988 | CLOSED | | |

**Owner:** Archambault

Service garage
Town Board approval 05/06/1927

| | | | | |
|---|---|---|---|---|
| 5/16/1940 | PERMIT #:517 | CLOSED | | |

**Owner:** Mancini

Alteration

| | | | | |
|---|---|---|---|---|
| 11/13/1956 | PERMIT #:4666 | CLOSED | | |

**Owner:** Mancini

Outdoor Telephone Booth

| | | | | |
|---|---|---|---|---|
| 2/6/1958 | APPLICATION #: | VOID | | |

**Owner:**

2000gal UST

| | | | | |
|---|---|---|---|---|
| 4/3/1959 | APPLICATION #: | VOID | | |

**Owner:**

Temporary sign

**Town of Mamaroneck**
**Building Department**
**740 West Boston Post Road**
**(914) 381-7830 Fax: (914) 381-8473**

**11/16/2022**

# PARCEL HISTORY

**Address:** 1-5 Vine St

**Parcel ID:** 1-26-730

| Issued Date | Item | Status | CO/CC # | CO/CC Date |
|---|---|---|---|---|
| 7/15/1969 | APPLICATION #: | WITHDRAWN | | |
| **Owner:** | | | | |
| (1) 6000gal UST | | | | |
| 6/28/1990 | APPLICATION #:986 | APPROVED | | 8/22/1990 |
| **Owner:** | | | | |
| 89-77B; 89-9 and 89-28 | | | | |
| 3/19/1992 | PERMIT #:11599 | CLOSED | 11599 | 5/7/1992 |
| **Owner:** Mansisbro Inc | | | | |
| Gas piping and two gas fixtures | | | | |
| 5/7/1992 | CERT #:11599 | ISSUED | | |
| **Owner:** | | | | |
| Gas piping and two gas fixtures | | | | |
| 4/4/2013 | APPLICATION #:PW-2013- | APPROVED | | |
| **Owner:** | | | | |
| Insertion of customer gas service. | | | | |

**Town of Mamaroneck**
**Building Department**
**740 West Boston Post Road**
**(914) 381-7830 Fax: (914) 381-8473**

**11/16/2022**

# PARCEL HISTORY

**Address:** 1-5 Vine St

**Parcel ID:** 1-26-730

| Issued Date | Item | Status | CO/CC # | CO/CC Date |
|---|---|---|---|---|
| 4/4/2013 | PERMIT #:PW-2013-0023 | CLOSED | | 10/1/2013 |

**Owner:** Mansisbro Inc

Insertion of customer gas service.

8/27/2014 APPLICATION #: APPROVED

**Owner:**

Generator for gas pumps.

4/29/2015 APPLICATION #: APPROVED

**Owner:**

Remove (2) 4,000 gallon UST.

8/2/2022 PERMIT #:PW-2022-0078 OPEN

**Owner:** Mansisbro Inc

Replacing Hydrant (Grass Restoration)

7/8/1963 PERMIT #:5803 CLOSED

**Owner:** Mancini

Wall sign

**Town of Mamaroneck**
**Building Department**
**740 West Boston Post Road**
**(914) 381-7830 Fax: (914) 381-8473**

**11/16/2022**

# PARCEL HISTORY

**Address:** 1-5 Vine St

**Parcel ID:** 1-26-730

| Issued Date | Item | Status | CO/CC # | CO/CC Date |
|---|---|---|---|---|
| 2/25/1966 | PERMIT #:6347 | CLOSED | | |

**Owner:** Mancini

Wall sign

| | | | | |
|---|---|---|---|---|
| 1/18/1966 | PERMIT #:6324 | CLOSED | | |

**Owner:** Mancini

New office room

| | | | | |
|---|---|---|---|---|
| 7/23/1969 | PERMIT #:7012 | CLOSED | | |

**Owner:** Mancini

(1) 6,000gal UST

| | | | | |
|---|---|---|---|---|
| 9/30/1987 | PERMIT #:10192 | CLOSED | | 11/4/1987 |

**Owner:** Mancini

Non-illuminated wall sign

| | | | | |
|---|---|---|---|---|
| 6/19/1991 | PERMIT #:11387 | VOID | | |

**Owner:** Mansisbro Inc

Interior partitions, bathroom and electrical

**Town of Mamaroneck**
**Building Department**
**740 West Boston Post Road**
**(914) 381-7830 Fax: (914) 381-8473**

**11/16/2022**

# PARCEL HISTORY

**Address:** 1-5 Vine St

**Parcel ID:** 1-26-730

| Issued Date | Item | Status | CO/CC # | CO/CC Date |
|---|---|---|---|---|
| 2/24/1995 | PERMIT #:12857 | CLOSED | 12857 | 4/27/1995 |

**Owner:** Mansisbro Inc,

Fill in existing cellar below service bay

| | | | | |
|---|---|---|---|---|
| 3/31/1995 | PERMIT #:12898 | CLOSED | 12898 | 4/27/1995 |

**Owner:** Mansisbro Inc,

(2) 4,000gal UST

| | | | | |
|---|---|---|---|---|
| 4/6/1995 | PERMIT #:12913 | CLOSED | 12913 | 4/27/1995 |

**Owner:** Mansisbro Inc,

Remove (10) UST

| | | | | |
|---|---|---|---|---|
| 4/27/1995 | CERT #:12857 | ISSUED | | |

**Owner:**

Fill in existing cellar below service bay

| | | | | |
|---|---|---|---|---|
| 4/27/1995 | CERT #:12898 | ISSUED | | |

**Owner:**

(2) 4,000gal UST

**Town of Mamaroneck**
**Building Department**
**740 West Boston Post Road**
**(914) 381-7830 Fax: (914) 381-8473**

**11/16/2022**

# PARCEL HISTORY

**Address:** 1-5 Vine St

**Parcel ID:** 1-26-730

| Issued Date | Item | Status | CO/CC # | CO/CC Date |
|---|---|---|---|---|
| 4/27/1995 | CERT #:12913 | ISSUED | | |
| **Owner:** | | | | |
| Remove (10) UST | | | | |
| 8/31/1995 | PERMIT #:13132 | CLOSED | 13132 | 1/15/1998 |
| **Owner:** Mansisbro Inc, | | | | |
| Wall sign | | | | |
| 1/15/1998 | CERT #:13132 | ISSUED | | |
| **Owner:** | | | | |
| Wall sign | | | | |
| 9/13/2001 | PERMIT #:16166 | CLOSED | 16166 | 6/15/2006 |
| **Owner:** Mansisbro Inc, | | | | |
| Spray booth | | | | |
| 10/11/2001 | PERMIT #:16208 | CLOSED | 16208 | 6/15/2006 |
| **Owner:** Mansisbro Inc, | | | | |
| Gas piping for paint booth heater | | | | |

**Town of Mamaroneck**
**Building Department**
**740 West Boston Post Road**
**(914) 381-7830 Fax: (914) 381-8473**

**11/16/2022**

# PARCEL HISTORY

**Address:** 1-5 Vine St

**Parcel ID:** 1-26-730

| Issued Date | Item | Status | CO/CC # | CO/CC Date |
|---|---|---|---|---|
| 6/15/2006 | CO #:16166 | ISSUED | | |

**Owner:**

Spray booth

| | | | | |
|---|---|---|---|---|
| 6/15/2006 | CERT #:16208 | ISSUED | | |

**Owner:**

Gas piping for paint booth heater

| | | | | |
|---|---|---|---|---|
| 9/8/2014 | PERMIT #:2014-0496 | OPEN | | |

**Owner:** Mansisbro Inc

Generator for gas pumps.

| | | | | |
|---|---|---|---|---|
| 4/29/2015 | PERMIT #:2015-0255 | CLOSED | 2015-0255 | 12/3/2015 |

**Owner:** Mansisbro Inc

Remove (2) 4,000 gallon UST.

| | | | | |
|---|---|---|---|---|
| 12/3/2015 | CERT #:2015-0255 | ISSUED | | |

**Owner:**

Remove (2) 4,000 gallon UST.

**Town of Mamaroneck**
**Building Department**
**740 West Boston Post Road**
**(914) 381-7830 Fax: (914) 381-8473**

**11/16/2022**

# PARCEL HISTORY

**Address:** 1-5 Vine St

**Parcel ID:** 1-26-730

| Issued Date | Item | Status | CO/CC # | CO/CC Date |
|---|---|---|---|---|
| 8/20/1993 | PERMIT #:12225 | CLOSED | 12225 | 4/21/1995 |
| **Owner:** Mansisbro Inc | | | | |
| Interior alterations | | | | |
| 9/21/1993 | PERMIT #:12258 | CLOSED | 12258 | 4/21/1995 |
| **Owner:** Mansisbro Inc | | | | |
| Gas and water piping to cleaning appliances | | | | |
| 2/15/1994 | PERMIT #:12411 | CLOSED | 12411 | 4/19/1995 |
| **Owner:** Mansisbro Inc | | | | |
| Wall sign | | | | |
| 8/24/1994 | PERMIT #:12653 | CLOSED | 12653 | 1/18/1995 |
| **Owner:** Mansisbro Inc | | | | |
| Install pressing equipment | | | | |
| 11/15/1994 | PERMIT #:12759 | CLOSED | 12759 | 1/18/1995 |
| **Owner:** Mansisbro Inc | | | | |
| Commercial washing machine | | | | |

**Town of Mamaroneck**
**Building Department**
**740 West Boston Post Road**
**(914) 381-7830 Fax: (914) 381-8473**

**11/16/2022**

# PARCEL HISTORY

**Address:** 1-5 Vine St

**Parcel ID:** 1-26-730

| Issued Date | Item | Status | CO/CC # | CO/CC Date |
|---|---|---|---|---|
| 1/18/1995 | CO #:12653 | ISSUED | | |

**Owner:**

Install pressing equipment

| | | | | |
|---|---|---|---|---|
| 1/18/1995 | CERT #:12759 | ISSUED | | |

**Owner:**

Commercial washing machine

| | | | | |
|---|---|---|---|---|
| 4/19/1995 | CERT #:12411 | ISSUED | | |

**Owner:**

Wall sign

| | | | | |
|---|---|---|---|---|
| 4/21/1995 | CO #:12225 | ISSUED | | |

**Owner:**

Interior alterations

| | | | | |
|---|---|---|---|---|
| 4/21/1995 | CERT #:12258 | ISSUED | | |

**Owner:**

Gas and water piping to cleaning appliances

**Town of Mamaroneck**
**Building Department**
**740 West Boston Post Road**
**(914) 381-7830 Fax: (914) 381-8473**

**11/16/2022**

# PARCEL HISTORY

**Address:** 1-5 Vine St

**Parcel ID:** 1-26-730

| Issued Date | Item | Status | CO/CC # | CO/CC Date |
|---|---|---|---|---|
| 1/28/1999 | PERMIT #:14688 | VOID | | |

**Owner:** Mansisbro Inc

Interior alteration, vapor barrier room

| | | | | |
|---|---|---|---|---|
| 3/20/1967 | PERMIT #:6621 | CLOSED | | |

**Owner:** Mancini

Wall sign

| | | | | |
|---|---|---|---|---|
| 3/20/1967 | PERMIT #:6619 | OPEN | | |

**Owner:** Mancini

Wall sign

| | | | | |
|---|---|---|---|---|
| 3/20/1967 | PERMIT #:6620 | CLOSED | | |

**Owner:** Mancini

Wall sign

| | | | | |
|---|---|---|---|---|
| 3/20/1967 | PERMIT #:6622 | CLOSED | | |

**Owner:** Mancini

Wall sign

Dear Michelle Nowak,

The Town of Mamaroneck has received your Freedom of Information request, received in my Office on 11/15/2022. For information regarding the FOIL process please visit. https://www.townofmamaroneckny.org/254/Freedom-of-Information

Respectfully,
Allison May,
Mamaroneck Town Clerk

Powered by Laserfiche Forms
(http://www.laserfiche.com/forms)

FILED MAP: Laurel Park | SECT. 1 | TAX DISTRICTS | Act # 103800 | 440

BLOCK | BLOCK 126 | 440 | LAND 15,000 | LAND | LAND | LAND 440

LOTS 1-2-3-4 PT OF 5 & 6 | PARCEL 930 | | IMPROVEMENTS | IMPROVEMENTS | IMPROVEMENTS | IMPROVEMENTS

REGISTER'S OFFICE NO. 2289 | ZONED B | 150 X 100 | TOTAL 59,300 | TOTAL | TOTAL | TOTAL

OWNER | NO. 1-5 STREET VINE ST. | 1-5 VINE ST REMARKS

MANCINI, SARAH & ARTURO | PERMIT # 7017 (7/23/66) STORAGE TANKS (UNDERGROUND) NOT IN GROUND As of 1/30/70 MB. | LAND 45,000 | IMPROVEMENTS 79,000 | TOTAL 124,000

MANCINI { RAIMOND, ARNOLD, VICTOR } | (1/22/73) | LAND 20,200 | IMPROVEMENTS 35,500 | TOTAL 55,700 | 1980-09

MANCINI { RAIMOND, ARNOLD, JASPER, VIRGINIA } (TENANTS IN COMMON) | NONE 8/18/73 | LAND 20200 | IMPROVEMENTS 35,500 | TOTAL 55700 | 1980-10

8/31/79 | LIBER 1601 | LAND 20,200 | IMPROVEMENTS 35,500 | TOTAL 55,700 | 1980-11

MANSIS BRO. INC. | PGE 214 (NONE)

6/19/91 # 11387 - NEW INTERIOR PARTITIONS ADD BATHROOM & ELECTRICAL WORK - $5,000 N/C | LAND | IMPROVEMENTS | TOTAL SAME AS 1970 | 1970-71

8/20/93 # 12225 - INTERIOR ALT. $7,000 N/C | LAND | IMPROVEMENTS | TOTAL | 1972-73

8/24/94 # 12653 - Interior Alt. To Provide for new pressing equipment. $10,000.- | SAME AS 1971

2/24/95 # 12857 - Fill existing cellar under service bay to the underside of service bay slab $20,000.- | LAND | IMPROVEMENTS | TOTAL | 1974-75

1/28/(99) # 14688 Vapor barrier rm for dry cleaning machine w/the minimum 2000 CFM exhaust fan $2000 | LAND 15000 | IMPROVEMENTS 20000 | TOTAL 35000 | 1998-99 | C.O. 7/27/00

9/13/01 # 16166 Inst. of Automotive Spray Booth $ 50,000 | LAND 15000 | IMPROVEMENTS 20,000 | TOTAL 35000 | 2000-01

7/15/04 # 17845 Conv Dry Cleaners Machine to Green Earth Cleaning Process Ins 2 Shrink Tubs $15,000 | LAND | IMPROVEMENTS | TOTAL

LAND | BAR 6/98 N/C | LAND | BAR 6/99 N/C | LAND | LAND

IMPROVEMENTS | IMPROVEMENTS | IMPROVEMENTS | IMPROVEMENTS

TOTAL | TOTAL | TOTAL | TOTAL | -20700 | Cert 99

# PROPERTY ASSESSMENT RECORD — TOWN OF MAMARONECK, N. Y.

## MAIN BUILDING CONSTRUCTION

| TYPE | | ROOF SHAPE | | ROOFING | | INTERIOR FINISH | | FLOORS | |
|---|---|---|---|---|---|---|---|---|---|
| ONE FAMILY | | GABLE | | ASPH. SHINGLES | | PLASTER | | CEMENT CELLAR | X |
| FAMILY | | HIP | | WOOD SHINGLES | | WALLBOARD stone | X | DIRT CELLAR | |
| NO. OF ROOMS | | FLAT/undigame thin | X | ASBES. SHINGLES | | PANEL RMS. 15x6 | X | HARDWOOD | |
| BSMT. | 2ND | GAMBREL | | SLATE | | ATTIC ROOMS | | PINE | |
| 1ST. | 3RD | MANSARD | | TILE | | BSMT. ROOMS | | SINGLE | |
| | | DORMERS | | METAL | | FIREPLACE | | CONCRETE | ✓ |
| APARTMENT | | FULL DORMER | | COMP. | X | ACB. CEILING | X | AS.-RUB TILE 15x6 U + stone | X |
| STORE | X | | | BUILT UP | | 15x42 stone | | | |
| FACTORY | | EXTERIOR WALLS | | INSUL. | | under | | | |
| HOTEL | | CLAPBOARDS | | | | PLUMBING | | | |
| OFFICES | | WD. SHINGLE | | | | BATH COMP. 3 FIX | | | |
| WAREHOUSE | | ASP. SHINGLE | | | | BATH TILED 3 FIX. | | | |
| COMM. GARAGE | X | ASB. SHINGLE | | HEATING | | TOILET RM. 2 FIX. | | | |
| GAS STATION | | WD. SIDING | | RADIANT | | T.R. TILED 2 FIX. | 3 | | |
| FOUNDATION | | ASP. SIDING | | HOT WATER | | W.C. | | | |
| CONCRETE | X | ASB. SIDING | | STEAM OR VAPOR oil fired | | SINK | | | |
| CON.-CIN. BLK. | | METAL SIDING AL ET | ✓ | HOT AIR | | URINAL | | | |
| BRICK-STONE | | COMB. BR. VEN. | | FORCED HOT AIR | | BRADLEY | | | |
| POSTS | | FACE BR. VEN. | | ELECTRIC | | SHOWER | | | |
| CELLAR AREA FULL | | SOLID BRICK | | UNIT HEATERS 3 2200 | 5 | NO PLUMBING | | | |
| PART CELLAR 2880 ± | X | STONE ON T-BLK. | | AIR CONDIT. 220 | | EXTRAS | | | |
| NO CELLAR | | STUCCO ON FR. | | O-G BUR. STOKER | X | NO LIGHTING | | | |
| | | STUCCO ON C. BLK. | X | NO HEAT | | SPRINKLER | | | |
| | | STUCCO ON BR.-TILE | | | | ELEVATOR | | | |

| DATE | INSPECTOR |
|---|---|
| 2-1-68 | TFE-JAM |




| BUILDINGS | TYPE | YEAR BUILT | REMOD | CONDITION | REPLACEMENT COST | DEPR. PHYS. | DEPR. OTHER | SOUND VALUE | ASSESSOR'S VALUE |
|---|---|---|---|---|---|---|---|---|---|
| GARAGE | GF | 1928 | YES | GOOD-EX | 97,600 | 10 | 10 | 79,050 | |
| | | 1940 | | | | | | | |

| OUT BLDG | SIZE | AREA | UNIT |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

| FRONT | REAR | AV. DEPTH. | UNIT PRICE | DEPTH FACTOR | ADJ. F. F. PRICE | TOTAL | SOUND VALUE | ASSESSOR'S VALUE |
|---|---|---|---|---|---|---|---|---|
| 150 | | 100 | 300 FF | 1.000 | 300 FF | 45,000 | 45,000 | |
| | | | | | | | | |
| | | | | | | | | |

## RENTAL INFORMATION CONCERNING THIS PROPERTY

| Date | No. of Units | Size of Units | Use | Floor | Monthly Rate | Monthly Total | Services Incl. Rent: Remarks |
|---|---|---|---|---|---|---|---|
| | | 22x44 | DRY CLEANER | 1ST | B/175 | 175 | |
| | | BALANCE | GAR/CARWASH | 1ST | B600 net | 600 | |
| | | | | | | B775 | |

## CAPITALIZATION — GROSS — NET

| Estimated Expenses | Cost or Percent | | |
|---|---|---|---|
| Salaries & Wages | | Gross Annual Income | 9300 |
| Insurance | not | Vacancies | 279 |
| Repairs & Maint. | not | | 9021 |
| Management | 270 | Operating Expense | 270 |
| Heating | not | Net Income before taxes | 8751 |
| Electricity | not | and depreciation | 2700 |
| Other | not | Land-Interest 6 % Taxes net % | 6% 45,000 |
| | 270 | Bldg. Interest 6 % Taxes net % Depr. 2.0 % | 5% |
| | | Computation: 6051 ÷ 8% = 75,600 + 45,000 = 120,600 | |

| STY. | DIMENSIONS | SQ. FT. | UNIT | REPLACEMENT |
|---|---|---|---|---|
| 1+ | 22x44 = (stone) | 968 | 11.70 | 11,325 |
| 1+ | 22x36 = 792 | | | |
| | 26x36 = 936 | | | |
| | 57x144 - 110 = 7378 | | | |
| | 9106 | | | |
| | Masonry 968 | | | |
| | | 8138 | 9.18 | 74,706 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| B'MENT—~~ATTIC ROOMS~~ | | 2880+ | 4.00 | 11,520 |
| INSULATION | | | | |
| FIREPLACE | | | | |
| EARTH CELLAR | | | | |
| HEATING | | | | |
| O -G BUR.—STOKER | | | | |
| PLUMBING—TILING | | | | |
| | | | | 97,551 |
| TOTAL REPLACEMENT COST | | | | call 97,600 |

## Michelle Nowak

**From:** New York DEC FOIL Center <newyorkdec@govqa.us>
**Sent:** Tuesday, November 15, 2022 1:45 PM
**To:** Michelle Nowak
**Subject:** FOIL Request :: W109067-111522

Dear Michelle:

Thank you for your Freedom of Information Law (FOIL) request. Your request has been received and is being processed. Your request was received in this office on 11/15/2022 and given the reference number FOIL #W109067-111522 for tracking purposes. You may expect the Department's response to your request no later than **12/14/2022**.

Record Requested: **Address: 1 Vine Street Larchmont, NY Tax ID: 1-26-730 1. Permits and registrations 2. Environmental Violations 3.Solid and Hazardous Logs 4.Air and water quality violations 5. NYS DEC Site Inspections Reports 6. Bulk Storage Tank removal documentation 7. Spills and spill reports**

You can monitor the progress of your request at the link below and you'll receive an email when your request has been completed. Again, thank you for using the FOIL Center.

Click here to login to the FOIL Center.

New York State Department of Environmental Conservation, Record Access Office

---

Track the issue status and respond at: https://newyorkdec.govqa.us/WEBAPP//_rs/RequestEdit.aspx?rid=109067

https://townofmamaroneck.prosgar.com/PROSParcel/Parcel/5797?swis=553289

### Structure

| Building 1 | |
|---|---|
| Number of Identical Buildings | 1 |
| Actual Year Built | 1930 |
| Effective Year Built | 1990 |
| Construction Quality | 2.0 |
| Condition | 3 - Normal |
| Building Perimeter | 533 |
| Gross Floor Area | 11958 |
| Number of Stories | 1.0 |
| Story Height | 12 |
| Air Conditioning % | 0% |
| Sprinkler % | 0% |
| Number of Elevators | |
| Basement Perimeter | |
| Basement Sq. Ft | |

**View Photos, Sketches, Historical Property Record Cards**

### 2022 Assessment Information

| | |
|---|---|
| Land Assessed Value | $340,000 |
| Total Assessed Value* | $1,870,000 |
| Equalization Rate | 100.00% |
| Full Market Value | $1,870,000 |
| County Taxable | $1,870,000 |
| Municipal Taxable | $1,870,000 |
| School Taxable | $1,870,000 |

### Property Description

| | |
|---|---|
| Property Type | 433 - Auto body |
| Neighborhood Code | 55005 comm town |
| SWIS | Unincorporated Town |
| Water Supply | 3 - Comm/public |
| Utilities | 4 - Gas & elec |
| Sewer Type | 3 - Comm/public |
| Zoning | B Business |

### Last Property Sale

No Sales Data Found

| Owner Information | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| Owner Name | Address 1 | Address 2 | PO Box | City | State | Zip | Unit Name | Unit Number |
| Mansisbro Inc | 1-5 Vine St | | | Larchmont | NY | 10538 | | |

| Sales | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| Deed Date | Deed Book | Deed Page | Contract Date | Sale Date | Last Physical Inspection Date | Sale Price | Net Sale Price | Usable for Valuation | Arms Length | Prior Owner |
| No data available in table | | | | | | | | | | |

No Exemption Data Found

| Land | | | | | | |
|---|---|---|---|---|---|---|
| Site # | Land Type | Acres | Front | Depth | Sq Ft | Soil Rating |
| 1 | 01 - Primary | 0.34 | | | | |

| Commercial Site Uses | | | |
|---|---|---|---|
| **Site #** | **Commercial Use** | **Total Units** | **Total Rentable Area (sqft.)** |
| 1 | G03 - Body shop | 0 | 10958 |
| 1 | D10 - Row retail | 0 | 1000 |

No Improvement Data Found

## Appendix E: Previous Studies

July 7, 2015

Mr. Carlos Torres
Westchester County Department of Health
145 Huguenot Street
New Rochelle, New York 10801

**Re: Underground Storage Tank Removal Report**
**J&F Chatsworth LTD**
**1 Vine Street**
**Larchmont, New York 10538**
**NYSDEC PBS #3-174394**
**NYSDEC Spill #15-01291**

Dear Mr. Torres:

Please find the attached *Underground Storage Tank Removal Summary Report* ("Report") prepared by American Petroleum Equipment & Construction Company, Inc. (American Petroleum), on behalf of J&F Chatsworth LTD, for the property located at 1 Vine Street in Larchmont, New York (the "Site").

Should you have any questions or comments regarding the information provided herein, please contact the undersigned at (845) 778-5110.

Respectfully Submitted,
**American Petroleum Equipment & Construction Company, Inc.**

Brian Weeks
Staff Geologist

Kevin Bradley
Project Manager/Geologist

Enclosure

cc: Giuseppe Sparano, J&F Chatsworth LTD
Dan Bendell, New York State Department of Environmental Conservation

# Underground Storage Tank Removal Report

**J&F Chatsworth LTD**

**1 Vine Street**
**Larchmont, New York**
**NYSDEC PBS #3-174394**
**NYSDEC Spill #15-01291**

*Prepared for:*

J&F Chatsworth
Mr. Giuseppe Sparano
1 Vine Street
Larchmont, New York

*Prepared by:*

**American Petroleum Equipment & Construction Company, Inc.**
63 Orange Avenue
Walden, New York 12586
July 2015

# Underground Storage Tank Removal Report

**J&F Chatsworth LTD**
**1 Vine Street**
**Larchmont, New York**
**NYSDEC PBS #3-174394**
**NYSDEC Spill #15-01291**

*Prepared for:*

J&F Chatsworth
Mr. Giuseppe Sparano
1 Vine Street
Larchmont, New York

July 2015

*Prepared by:*

Brian Weeks
Staff Geologist

*Reviewed by:*

Kevin Bradley
Project Manager/Geologist

# TABLE OF CONTENTS


**1.0 INTRODUCTION ..... 1**

**2.0 UNDERGROUND STORAGE TANK REMOVAL ACTIVITIES ..... 1**

**3.0 CONCLUSION/RECOMMENDATIONS ..... 2**


**Figures**


Figure 1 Site Location Map
Figure 2 Site Map


**Appendix**


Appendix A Waste Disposal Manifests
Appendix B Photographs

## 1.0 INTRODUCTION

American Petroleum Equipment and Construction Company, Inc. (American Petroleum) was contracted by Mr. Giuseppe Sparano of J&F Chatsworth LTD to prepare this report documenting and summarizing the environmental services provided during remedial excavation and underground storage tank (UST) removal activities at the property located at 1 Vine Street in Larchmont, Westchester County, New York (the "Site"). The activities at the Site were performed in accordance with applicable local, state and federal regulations. A Site Location Map and a Site Map are included as **Figures 1** and **2**, respectively.

## 2.0 UNDERGROUND STORAGE TANK REMOVAL ACTIVITIES

On May 7, 2015, American Petroleum completed the removal of two 4,000 gallon double walled steel gasoline USTs from the Site. Groundwater was encountered during UST removal activities and in order to facilitate removal of the USTs a vacuum extraction truck was used to depress the water table. Approximately 730 gallons of groundwater were transported to Global Services of Albany, New York for disposal. The waste disposal manifests are included in **Appendix A**.

Prior to removal the USTs were purged of any residual liquids and product. Following UST removal activities American Petroleum cut, cleaned, and prepared the tanks for disposal. The American Petroleum field geologist inspected the tanks and documented that they were in good condition with no holes or pitting.

During excavation activities, soil samples were screened in the field for the presence of volatile organic compounds (VOCs) utilizing a hand held Mini Rae photo-ionization detector (PID) which was calibrated to 100 parts per million (ppm) isobutylene standard. Soils exhibiting elevated PID field screen readings were removed and stockpiled on-Site until arrangements could be made for disposal. Based upon the elevated PID readings the New York State Department of Environmental Conservation (NYSDEC) Spills Hotline was contacted and Spill #15-01291 was assigned to the Site.

During excavation of petroleum impacted soil it was determined that the USTs had been installed within the foundation of a previous building. The building (above grade) had been previously removed but the foundation remained in place and was constructed of concrete in all directions (four sidewalls and bottom). The foundation acted as a containment barrier which prevented further migration of petroleum to the environment and additionally is a structural footing for Vine Street and for the commercial building adjacent to Vine Street. As such no soil samples were collected due to the complete removal of all impacted soils located within the interior of the foundation walls. Excavation activities were not advanced beyond the foundation limits as the structural integrity of the building and road would likely have been compromised. Photographs of the excavation illustrating the concrete walls and foundation are included as **Appendix B.**

On June 12, 2015 approximately 11-tons of petroleum impacted soil was transported to the Deep Green facility in New Windsor, New York for disposal during remedial excavation activities at the Site. The waste disposal manifests documenting disposal of the petroleum impacted soil are included in **Appendix A**.

## 3.0 CONCLUSION/RECOMMENDATIONS

In May of 2015 American Petroleum completed the removal of two 4,000 USTs from the Site. As required by the NYSDEC, the condition of the UST was observed and documented by a field Geologist. The UST was in good condition with no detectable holes or pitting. American Petroleum excavated and transported approximately 11-tons of petroleum impacted soil to a disposal facility during UST removal activities.

Based on the field observations, the containment barrier (foundation walls), and the complete removal of petroleum impacted soil, American Petroleum recommends that no further action be required regarding Site conditions and requests that NYSDEC Spill #15-01291 be closed.

## FIGURES

Site Location Map
Site Map

**APPENDIX A**

Waste Disposal Manifests

## APPENDIX B

Photographs

March 17, 2026

ELKHO26001

**ELK HOMES**
Attn.: Mr. Joe Forte
402 Halstead Avenue
Harrison, NY 10528
jforte@elkhomes.com

**RE: PHASE II ENVIRONMENTAL SITE ASSESSMENT (ESA)**
**1 VINE STREET**
**LARCHMONT, NEW YORK 10538**

Dear Mr. Forte,

Pennoni Associates (Pennoni) has completed a Phase II Environmental Site Assessment (ESA) for 1 Vine Street, in Larchmont, and presents this report, summarizing the findings. A review of the November 30, 2022 Phase I ESA, completed by American Petroleum, identified a number of environmental conditions, concluding that additional investigations were warranted in the autobody shop area and related underground storage tank, the drycleaner area, the exterior area where several former 4,000-gallon underground tanks existed, and other interior areas potentially at risk from vapor intrusion conditions. Although the basement area was flooded at the time of our investigation and was not accessible, visual observations were made.

**Introduction**
Our Phase II ESA consisted of the collection and analysis of soil, soil gas and groundwater samples. Soil samples were screened for the presence of petroleum contamination with a photoionization detector. A total of seven soil borings were completed, and one temporary monitoring well was installed. A total of three sub slab soil gas samples, nine soil samples and one groundwater sample were collected and analyzed for site specific constituents of concern listed below. Sample locations are depicted on **Figure 1** – Site Drawing.

- Volatile Organic Compounds (VOCs)
- Semi-volatile organic compounds (SVOCs), Poly Aromatic Hydrocarbons (PAHs)
- Total RCRA Metals, plus Copper, Nickel, and Zinc
- TCLP RCRA Metals, plus Copper, Nickel, and Zinc
- Polychlorinated Biphenyls (PCBs)
- Ignitability, Corrosivity and Reactivity

On February 18-19, 2026, soil, soil gas, and groundwater samples were collected into dedicated laboratory bottle ware and transported under chain of custody protocol to Phoenix Laboratories, a New York certified analytical laboratory.

**Soil Gas Sampling**
On February 18, 2026, Pennoni utilized a Hilti concrete drill to install vapor sample points through the base of the interior concrete flooring in the autobody shop-waste storage area (WSA-SG-1), autobody shop- paint spay booth (SB-SG-1) and in the drycleaning area (DC-SG-2).

In accordance with USEPA's Soil Gas Sampling procedure, three temporary sub slab gas sampling ports were installed and soil gas samples, identified as SB-1, WSA-SG-1, and DC-SG-1, were collected to assess the potential for vapor intrusion using 30-minute regulators.

**Soil Sampling**
On February 18 and 19, 2026, a total of nine soil samples were collected from five interior and two exterior soil borings. Interior soil borings are identified as AB-1 (adjacent to the abandoned autobody UST), AB-2 (adjacent to the autobody below grade hydraulic vehicle lift), AB-3 (adjacent to the autobody spray booth), AB-4 adjacent to the autobody waste storage area), and DC-1 in the former drycleaner area. DC-1 was completed by hand by a Pennoni Environmental geologist on February 18th while EnviroShield completed the rest of the borings.

In addition to the interior borings, two exterior borings were completed on February 19, 2026, designated EB-1 in vicinity of the former gasoline USTs, and EB-2, adjacent to the former drycleaner. EB-2 was completed with a one-inch diameter temporary monitoring well, designated as MW-1.

**Groundwater Samples**
Utilizing EPA's low flow sampling method, a Pennoni environmental geologist collected a groundwater sample from the existing well (designed EXMW), located near southeast property boundary. On February 27, 2026, a Pennoni environmental scientist collected a groundwater sample from temporary well MW-1.

**Basement Area**
The basement areas were not illuminated and were flooded at the time of our inspection. No soil vapor, soil or groundwater samples were collected. The surface of the standing water exhibited what appeared to be an oily film and maintained a slight petroleum odor.

**Findings**
*Soil Vapor*
A total of three sub slab soil gas samples were collected using dedicated summa cannisters and 30-minute regulators. Each air sample was analyzed by Method TO-15. Low levels of Volatile Organic Compounds (VOCs) were detected in each sample but below the applicable New York State Department of Health (NYSDOH) Soil Vapor Intrusion Guidance. Refer to **Table 1** for the tabulated soil gas results. The soil gas laboratory report is attached. Refer to Figure 1 for sample locations.

*Soil*
A total of seven soil borings were completed, and a total of nine samples were analyzed for the following contaminants. **Table 2** (attached) presents the tabulated soil results.

- AB-1, in Autobody Shop, Abandoned Waste Oil UST – Total Metals, VOCs, SVOCs-PAHs and PCBs
- AB-2, in Autobody Shop, Vehicle Lift – Total and TCLP Metals, VOCs, SVOCs-PAHs and PCBs
- AB-3, in Autobody Shop, Paint Booth – VOCs
- AB-4, in Autobody Shop, Waste Storage Area – Total Metals, VOCs and SVOCs-PAHs
- DC-1, in Drycleaner – Total Metals
- EB-1, in Former Gasoline UST Area – VOCs
- EB-2, adjacent to Former Drycleaner – VOCs, PCBs and Ignitability/Corrosivity and Reactivity

The data collected indicates there are exceedances of the NYS 375 criteria and the NYS CP-51 Soil Cleanup Levels for gasoline and fuel oil contaminated soils. Contaminants that exceed one or more criteria include VOCs, SVOC-PAHs and chromium. Nickel was also detected slightly below the applicable NYS 375 criteria.

*Groundwater*
Two groundwater samples were collected. one from the existing well (MW Existing), located near the former gasoline USTs, and one from the temporary well (MW-1) installed by EnviroShield adjacent to the former drycleaning business. Groundwater samples were analyzed for the following contaminants. **Table 3** (attached) presents tabulated groundwater data.

DRAFT

- MW Existing, in Former Gasoline UST Area – VOCs, Total Metals, PCBs and SVOCs-PAHs
- MW-1, Adjacent to Former Dry Cleaner – VOCs, Total Metals and SVOCs-PAHs

**Table 3** (attached) presents tabulated groundwater data.

- MW Existing, in Former Gasoline UST area – low levels of VOCs were detected in the groundwater collected from this well. Additionally, vinyl chloride, cis-1,2-dichloroehtene and a number of SVOCs-PAHs were detected above 6 CRR NY 703.5 Water Quality Standards and/or the Water Technical and Operational Guidance (TOGs) pursuant to Article 17 of the Environmental Conservation Law and 6 NYCRR Parts 700-706, Water Quality Regulations.

- MW-1, Temporary Well Adjacent to Dry Cleaner – a number of VOCs, including the aromatic compound benzene, and the halogenated compounds tetrachloroethane, trichloroethene and vinyl chloride were detected at concentrations that exceed 6 CRR NY 703.5 Water Quality Standard and/or the Water Technical and Operational Guidance pursuant to Article 17 of the Environmental Conservation Law and 6 NYCRR Parts 700-706, Water Quality Regulations.

**Conclusions**

*Soil Vapor*

There does not appear to be a significant soil vapor concern in the locations where soil gas samples were collected.

*Soil*

Based on the data collected, it appears that contaminants exist in site soil and fill material (ash and coal) at concentrations that will require special handling and/or some degree of remediation to comply with the certain criteria that will protect human health and the environment during any future site improvements.

*Groundwater*

Similar to site soil, groundwater appears to have been impacted from past land use activities, particularly from former drycleaning operations. Based on the data collected and the presence of the drycleaning VOCs tetrachloroethane, trichloroethene and vinyl chloride at the concentrations detected, we suspect a release may have occurred. Additional data would be necessary to quantify the suspected release condition and determine reporting obligations.

*Basement Area*

Given the presence of VOC and SVOC-PAH contamination in the groundwater at MW-1, standing water in the basement should be characterized and managed in accordance with NYS DEC discharge requirements.

Please reach out to us if you have any questions.

Sincerely,

**PENNONI ASSOCIATES INC**
David T. Williams, RS, CPG, LEP
Environmental Division Manager

**PENNONI ASSOCIATES INC.**
Joseph Trevino, BS, MS
Staff Geologist

Attachments
Figures
Tables
Boring Logs
Laboratory Reports

DRAFT

# FIGURES




Pennoni
350 Fairfield Ave.-Suite 404,
Bridgeport, CT 06604
Phone: (203) 324-2222

| | |
|---|---|
| Figure: | 1 |
| Date: | 3/16/2026 |
| By: | PA |
| Title: | SITE DRAWING |
| Site: | 1 VINE STREET, LARCHMONT, NY |
| Client: | ELK HOMES |
| Project No.: | ELKHO26001 |

# TABLES

**Table 1 - Soil Gas Results**
**1 Vine Road, Larchmont NY**
**PO # : ELKHO26001**

| | | | | Lab Sample Id | Spray Booth | Waste Storage Area | Dry Cleaner |
|---|---|---|---|---|---|---|---|
| | | | | Collection Date | 2/18/2026 | 2/18/2026 | 2/18/2026 |
| | | | | Client Id | SB-SG-1 | WSA-SG-1 | DC-SG-2 |
| | | | | Matrix | Air | Air | Air |
| **Sub-Slab Air Sample** | Constituents of Concern | Soil Vapor (SS)* | Mitigation required* | Units | Result | Result | Result |
| **Volatiles (TO15) By TO15** | Acetone | NR | NR | ug/m3 | **54.6** | **102** | **234** |
| | Cis-1,2-Dichloroethene | 6 | 60 | ug/m3 | < 1.00 | < 1.00 | **1.6** |
| | Ethanol | NR | NR | ug/m3 | **10.9** | **8.85** | **324** |
| | Heptane | 200 | 2000 | ug/m3 | < 5.00 | < 5.00 | **15.6** |
| | Isopropyl alcohol | NR | NR | ug/m3 | **11** | **12.7** | **19.8** |
| | Tetrachloroethene | 100 | 1000 | ug/m3 | **20.4** | **10.9** | **38.2** |
| | Toluene | 300 | 3000 | ug/m3 | **5.88** | < 5.01 | **13.4** |
| | Trichloroethene | 6 | 60 | ug/m3 | < 0.99 | < 0.99 | **2.93** |

NR = Not Regulated

*Values taken from NYSDOH Soil Vapor Matrices (May 2017) referenced from NYSDOH Guidance for Evaluation Soil Vapor Intrusion in the State of New York (October 2006)

$ug/m^3$ = micrograms per $meter^3$

Only those compounds detected above the laboratory reporting limits are presented

**Table 2 - Soil Results**
**1 Vine Road, Larchmont NY**

**PO # : ELKHO26001**
**Subslab Interior and Exterior Soil Samples**

| | | PROJECT LOCATION: 1 VINE STREET, LARCHMONT, NEW YORK | | | | | | | Lab Id | CV35319 | CV35320 | CV35321 | CV35322 | CV35323 | CV35324 | CV35325 | CV35326 | CV34747 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | Date Sample | 2/19/2026 AB-1 (7-8.4`) | 2/19/2026 AB-2 (7-8`) | 2/19/2026 AB-3 (1-1.5`) | 2/19/2026 AB-4 (0.5-1.5`) | 2/19/2026 AB-4 (2.5-5`) | 2/19/2026 AB-4 (5-6.8`) | 2/19/2026 EB-1 (10-12`) | 2/19/2026 EB-2 (8.5-10`) | 2/18/2026 DC-1 (1-3`) |
| | | | | | | | | | Location | Autobody Shop - UST | Autobody Shop - Lift | Autobody Shop - Paint Booth | Autobody Shop - Waste Storage | Autobody Shop - Waste Storage | Autobody Shop - Waste Storage | Former Gasline USTs | DryCleaner | DryCleaner |
| | | Soil Clean Up Objectives | | | | | | | Media | Soil | Soil | Soil | Soil | Soil | Soil | Soil | Soil | Soil |
| | Units | NYS 375* Com. | NYS 375* Ind | NYS 375* Res Res | NYS 375* Res | NYS 375** UnRes | NYS 375** GWP | NYS CP-51, Tables 2 and 3 Soil - Gas/Fuel Oil | NYS CP-51 PGW Table 1 | Result | Result | Result | Result | Result | Result | Result | Result | Result |
| **Metals, Total** | | | | | | | | | | | | | | | | | | |
| Arsenic | mg/Kg | 16 | 16 | 16 | 16 | 13 | 16 | NR | NR | **1.75** | **4.72** | NA | NA | **1.69** | NA | NA | NA | **5.83** |
| Barium | mg/Kg | 410 | 10000 | 410 | 410 | 410 | 820 | NR | NR | **216** | **182** | NA | NA | **112** | NA | NA | NA | **200** |
| Cadmium | mg/Kg | 3.7 | 4.4 | 2.5 | 2.5 | 2.5 | 7.5 | NR | NR | **0.34** | < 0.47 | NA | NA | < 0.43 | NA | NA | NA | **1.47** |
| Total Chromium*** | mg/Kg | 1700 | 2000 | 110 | 30 | 30 | NR | NR | NR | **34** | **8.39** | NA | NA | **52.7** | NA | NA | NA | **48.6** |
| Copper | mg/kg | 280 | 10000 | 280 | 280 | 280 | 1720 | NR | NR | **5** | **16.1** | NA | NA | **48.4** | NA | NA | NA | **46.6** |
| Lead | mg/Kg | 1000 | 3900 | 400 | 400 | 63 | 450 | NR | NR | **5.81** | **33.6** | NA | NA | **12** | NA | NA | NA | **31.3** |
| Mercury | mg/Kg | 1.1 | 1.1 | 0.3 | 0.3 | 0.3 | 0.73 | NR | NR | < 0.03 | < 0.04 | NA | NA | **0.03** | NA | NA | NA | **0.1** |
| Nickel | mg/Kg | 320 | 5900 | 320 | 87 | 30 | 130 | NR | NR | **25.6** | **10.1** | NA | NA | **29.7** | NA | NA | NA | **25** |
| Zinc | mg/Kg | 10000 | 10000 | 6600 | 1300 | 109 | 2480 | NR | NR | **80.2** | **48.6** | NA | NA | **77.5** | NA | NA | NA | **63.7** |
| **Metals, TCLP** | | | | | | | | | | | | | | | | | | |
| TCLP Barium | mg/L | NR | NR | NR | NR | NR | NR | NR | NR | NS | **0.29** | NA | NA | NA | NA | NA | NA | NA |
| TCLP Lead | mg/L | NR | NR | NR | NR | NR | NR | NR | NR | NS | **0.01** | NA | NA | NA | NA | NA | NA | NA |
| **Volatiles By SW8260D** | | | | | | | | | | | | | | | | | | |
| 1,2,4-Trimethylbenzene | mg/Kg | 500 | 1000 | 100 | 41 | 5.9 | 5.9 | 3.6 | NR | **0.68** | **0.48** | < 0.0055 | NA | NA | < 0.0035 | **0.00082** | **0.59** | NA |
| 1,3,5-Trimethylbenzene | mg/Kg | 500 | 1000 | 100 | 41 | 3.1 | 3.1 | 8.4 | NR | **0.21** | **0.17** | < 0.0055 | NA | NA | < 0.0035 | < 0.0048 | **0.17** | NA |
| 2-Isopropyltoluene | mg/Kg | NR | NR | NR | NR | NR | NR | NR | NR | **0.074** | < 0.43 | < 0.0055 | NA | NA | < 0.0035 | **0.00048** | **0.093** | NA |
| Acetone | mg/Kg | 500 | 1000 | 100 | 100 | 0.03 | 0.03 | NR | NR | < 1.5 | < 0.034 | < 0.028 | NA | NA | **0.021** | **0.026** | < 1.7 | NA |
| Benzene | mg/Kg | 20 | 20 | 3.7 | 1.2 | 0.06 | 0.06 | 0.06 | NR | < 0.3 | < 0.43 | < 0.0055 | NA | NA | < 0.0035 | **0.00061** | **0.29** | NA |
| Carbon Disulfide | mg/Kg | NR | NR | NR | NR | NR | NR | NR | 2.7 | < 0.3 | < 0.43 | < 0.0055 | NA | NA | < 0.0035 | **0.0017** | < 0.33 | NA |
| cis-1,2-Dichloroethene | mg/Kg | 500 | 590 | 41 | 8.7 | 0.19 | 0.19 | NR | NR | **0.19** | < 0.0068 | < 0.0055 | NA | NA | < 0.0035 | **0.0068** | **0.11** | NA |
| Ethylbenzene | mg/Kg | 390 | 390 | 76 | 32 | 1 | 1 | 1 | NR | **0.088** | **0.077** | < 0.0055 | NA | NA | < 0.0035 | **0.00059** | **0.4** | NA |
| Isopropylbenzene | mg/Kg | NR | NR | NR | NR | NR | NR | 2.3 | 2.3 | **0.046** | < 0.43 | < 0.0055 | NA | NA | < 0.0035 | < 0.0048 | **0.2** | NA |
| m&p-Xylene | mg/Kg | NR | NR | NR | NR | NR | NR | NR | NR | **0.35** | **0.39** | < 0.0055 | NA | NA | < 0.0035 | **0.0021** | **1.2** | NA |
| Naphthalene | mg/Kg | 500 | 1000 | 100 | 84 | 12 | 12 | 12 | NR | **0.65** | **0.14** | < 0.0055 | NA | NA | < 0.0035 | < 0.0048 | **14** | NA |
| n-Butylbenzene | mg/Kg | 500 | 1000 | 100 | 100 | 18 | 18 | 12 | NR | **0.31** | **0.047** | < 0.0055 | NA | NA | < 0.0035 | **0.0009** | **1.8** | NA |
| n-Propylbenzene | mg/Kg | 500 | 1000 | 100 | 100 | 5 | 5 | 3.9 | NR | **0.12** | **0.094** | < 0.0055 | NA | NA | < 0.0035 | < 0.0048 | **0.89** | NA |
| o-Xylene | mg/Kg | NR | NR | NR | NR | NR | NR | NR | NR | **0.18** | **0.19** | < 0.0055 | NA | NA | < 0.0035 | < 0.0048 | **0.23** | NA |
| p-Isopropyltoluene | mg/Kg | NR | NR | NR | NR | NR | NR | 10 | 10 | **0.091** | < 0.43 | < 0.0055 | NA | NA | < 0.0035 | < 0.0048 | **0.04** | NA |
| sec-Butylbenzene | mg/Kg | 500 | 1000 | 100 | 100 | 25 | 25 | 11 | NR | **0.3** | < 0.43 | < 0.0055 | NA | NA | < 0.0035 | **0.00097** | **0.85** | NA |
| Tetrachloroethene | mg/Kg | 81 | 81 | 18 | 15 | 1.3 | 1.3 | NR | NR | **0.11** | < 0.43 | < 0.0055 | NA | NA | < 0.0035 | < 0.0048 | **0.08** | NA |
| Toluene | mg/Kg | 500 | 1000 | 100 | 100 | 0.7 | 0.7 | 0.7 | NR | **0.15** | **0.093** | < 0.0055 | NA | NA | < 0.0035 | **0.00056** | **0.95** | NA |
| Total Xylenes | mg/Kg | NR | NR | 100 | NR | 0.26 | 1.2 | 0.26 | NR | **0.53** | **0.58** | < 0.0055 | NA | NA | < 0.0035 | < 0.0048 | **1.43** | NA |
| Trichloroethene | mg/Kg | 54 | 54 | 6.4 | 1.7 | 0.47 | 0.47 | NR | NR | < 0.3 | < 0.0068 | < 0.0055 | NA | NA | < 0.0035 | **0.00053** | < 0.33 | NA |
| Vinyl chloride | mg/Kg | 7.1 | 7.1 | 0.48 | 0.099 | 0.03 | 0.03 | NR | NR | < 0.3 | < 0.0068 | < 0.0055 | NA | NA | < 0.0035 | **0.0025** | **0.05** | NA |
| **Polynuclear Aromatic HC By SW8270E** | | | | | | | | | | | | | | | | | | NA |
| 2-Methylnaphthalene | mg/Kg | NR | NR | NR | NR | NR | NR | NR | 36.4 | **11** | < 3.1 | NA | < 0.32 | NA | NA | NA | NA | NA |
| Acenaphthene | mg/Kg | 500 | 1000 | 100 | 100 | 20 | 98 | 20 | NR | **0.92** | < 3.1 | NA | < 0.32 | NA | NA | NA | NA | NA |
| Acenaphthylene | mg/Kg | 500 | 1000 | 100 | 100 | 100 | 365 | 100 | NR | **0.31** | < 3.1 | NA | < 0.32 | NA | NA | NA | NA | NA |
| Anthracene | mg/Kg | 500 | 1000 | 100 | 100 | 100 | 1000 | 100 | NR | **0.4** | < 3.1 | NA | < 0.32 | NA | NA | NA | NA | NA |
| Chrysene | mg/Kg | 47 | 78 | 4.9 | 1.2 | 1 | 1 | 1 | NR | < 0.26 | < 3.1 | NA | **0.17** | NA | NA | NA | NA | NA |
| Fluorene | mg/Kg | 500 | 1000 | 100 | 100 | 30 | 386 | 30 | NR | **1.6** | < 3.1 | NA | < 0.32 | NA | NA | NA | NA | NA |
| Naphthalene | mg/Kg | 500 | 1000 | 100 | 84 | 12 | 12 | 12 | NR | **1.4** | < 3.1 | NA | < 0.32 | NA | NA | NA | NA | NA |
| Phenanthrene | mg/Kg | 47 | 78 | 4.9 | 1.2 | 1.1 | 1000 | 100 | NR | **3.1** | < 3.1 | NA | < 0.32 | NA | NA | NA | NA | NA |

**NOTES:**

NR = Not Regulated; NA = Not Analyzed; PGW = Protection of Groundwater; Com. = Commercial; Ind = Industrial; Res = Residential; SCO = Soil Cleanup Objective; CP = Commissioner's Policy; UnRes = Unrestricted; Res Res = Residential Restricted ; GWP = Groundwater Protection

* = NYDEC Ny Comp. Codes R. & Regs Title 6, Ch 375-subpart 375.6.8(b), Remedial Program Soil Cleanup Objects (SCO), Restricted Use

** = NYDEC Ny Comp. Codes R. & Regs Title 6, Ch 375-subpart 375.6.8(a), Remedial Program Soil Cleanup Objects (SCO), Unrestricted Use

Shaded values indicate regulatory exceedances; Bolded values indicate detections above the laboratory reporting limits.

mg/kg = milligrams per kilograms; mg/l =milligrams per liter

***Referenced criteria is for trivalent chromium. Based on previous land use, total chromium is assumed to be predominantly trivalent.

Only those compounds detected above the laboratory reporting limits are presented

**Table 3 - Groundwater Results**
**1 Vine Road, Larchmont NY**
**PO # : ELKHO26001**

| Location: 1 Vine Road, Larchmont NY<br>PO # : ELKHO26001 | | | Collection Date<br>Client Id<br>Matrix<br>Location | 2/18/2026<br>MW (Existing)<br>Water<br>Exterior | 2/17/2026<br>MW-1<br>Water<br>Exterior |
|---|---|---|---|---|---|
| Constituents of Concern | Class GA* | TOGS 1.1.1** | Units | Result | Result |
| **Volatiles By SW8260D** | | | | | |
| Acetone | NR | 50 | ug/L | **4.6** | **<50** |
| Benzene | 1 | 1 | ug/L | < 0.70 | **2.3** |
| cis-1,2-Dichloroethene | 5 | 5 | ug/L | **43** | **190** |
| Isopropylbenzene | 5 | 5 | ug/L | < 1 | **2.3** |
| Naphthalene | 10 | 10 | ug/L | < 1 | **56** |
| n-Butylbenzene | 5 | 5 | ug/L | < 1 | **3.6** |
| n-Propylbenzene | 5 | 5 | ug/L | < 1 | **4.6** |
| sec-Butylbenzene | 5 | 5 | ug/L | < 1 | **3.9** |
| Tetrachloroethene | 5 | 5 | ug/L | < 1 | **210** |
| Trichloroethene | 5 | 5 | ug/L | < 1 | **81** |
| trans-1,2-Dichloroethene | 5 | 5 | ug/L | **1.6** | **2.4** |
| Vinyl chloride | 2 | 2 | ug/L | **9.3** | **48** |
| **Polynuclear Aromatic HC By SW8270E** | | | | | |
| 2-Methylnaphthalene | | | ug/L | < 0.48 | **5.2** |
| Acenaphthene | NR | 20 | ug/L | < 0.48 | **5.6** |
| Anthracene | NR | 50 | ug/L | < 0.48 | **2.1** |
| Benzo(a)anthracene | NR | 0.002 | ug/L | < 0.02 | **0.17** |
| Benzo(a)pyrene | 0 | 0 | ug/L | < 0.05 | **0.08** |
| Benzo(b)fluoranthene | NR | 0.002 | ug/L | < 0.03 | **0.07** |
| Benzo(k)fluoranthene | NR | 0.002 | ug/L | < 0.03 | **0.06** |
| Chrysene | NR | 0.002 | ug/L | < 0.02 | **0.14** |
| Fluoranthene | NR | 50 | ug/L | < 0.48 | **2.7** |
| Fluorene | NR | 50 | ug/L | < 0.48 | **4.1** |
| Indeno(1,2,3-cd)pyrene | NR | 0.002 | ug/L | < 0.12 | **0.06** |
| Naphthalene | 10 | 10 | ug/L | < 0.48 | **33** |
| Phenanthrene | NR | 50 | ug/L | < 0.48 | **7.5** |
| Pyrene | NR | 50 | ug/L | < 0.48 | **1.7** |
| **Metals, Total** | | | | | |
| Barium | 2000 | 2000 | ug/L | **1790** | **682** |
| Cadmium | 10 | 10 | ug/L | **2** | **<1.0** |
| Copper | 400 | 1000 | ug/L | **5** | **2** |
| Nickel | 200 | 200 | ug/L | **2** | **2** |
| Zinc | 5000 | 5000 | ug/L | **11** | **26** |

NR = Not Regulated

*Values taken from 6 CRR-NY 703.5 Water Quality Standards for Surface Waters and Groundwater

**Division of Water Technical and Operational Guidance Series (1.1.1) AMBIENT WATER QUALITY STANDARDS AND GUIDANCE VALUES AND GROUNDWATER EFFLUENT LIMITATIONS

Only those compounds detected above the laboratory reporting limits are presented

# BORING LOGS

| Pennoni | Hand Auger Test Boring Log | Job Number: | ELKHO26001-6 |
|---|---|---|---|
| | | Job Name: | 1 Vine Street |
| | | Location: | 1Vine St. Larchmont |
| | | Client: | |
| | | Sheet 1 of 1 | |

| Boring ID: | AB-1 | Driller: | EnviroShield | Total Depth: | 8.3' |
|---|---|---|---|---|---|
| Location: | Autobody Shop - Abandoned Waste Oil | Rig Type: | GeoProbe | GW Depth: | 7' |
| Date: | 2/19/2026 | Method: | Direct Push | Time: | |
| Time: | | Rec. by: | Peter Antonucci | Notes: | |

| Depth (ft) | Sample Interval | PID (ppm) | % Rec. | Description | Notes |
|---|---|---|---|---|---|
| 0 | 0-0.5' | ND | | Concrete, Base | Dry |
| | | | | 0.5-1'; ash, dkbrn F-VC sand, silt, coal frags | |
| | 0.5-1' | | | | |
| 1 | | | | | |
| 1 | | | | 1-2': ltbrn f-m sand, silt, pebbles, rx frags | |
| | 1-2' | ND | | | |
| | | | | 2-3'; ltbrn-tan f-c sand, silt, small cobble, pebbles | |
| | 2-3' | | | | |
| 3 | | | | | |
| 3 | | | | 3-4'; tan-dkbrn f-m sand, silt, small cobble, pebble | |
| | 3-4' | ND | | 4-6'; lt-dkbrn, ltgy, f-m sand, silt | |
| | 4-6' | | | | Damp |
| 7 | 6-7' | | | 6-7'; Lt-dk brn f-m sand, silt, gravel | |
| 7 | 7-7.75' | 104 | | 7-7.75'; ltgy-dkbrn vf-m sand, silt; mod-strong petroluem odor | Wet |
| | 7.75-8.3' | | | 7-75-8.3'; ltgy vf-m sand, silt | |
| 8.3 | | | | | |
| | | | | EOB at 8.3' | |

Lt. Brn Drk Brn, Lt. Gry, F-M Sand, Silt

| Pennoni | Hand Auger Test Boring Log | Job Number: | ELKHO26001-6 |
|---|---|---|---|
| | | Job Name: | 1 Vine Street |
| | | Location: | 1Vine St. Larchmont |
| | | Client: | |
| | | Sheet 1 of 1 | |

| Boring ID: | AB-2 | Driller: | EnviroShield | Total Depth: | 12' |
|---|---|---|---|---|---|
| Location: | Autobody Shop - Vehicle Lift | Rig Type: | GeoProbe3000 | GW Depth: | 7' |
| Date: | 2/19/2026 | Method: | Direct Push | Time: | |
| Time: | | Rec. by: | Peter Antonucci | Notes: | |

| Depth (ft) | Sample Interval | PID (ppm) | % Rec. | Description | Notes |
|---|---|---|---|---|---|
| 0 | 0-0.5' | ND | | 0-0.5'; concrete | Dry |
| 1 | 0.5-1' | ND | | 0.5-1'; ash, dkbrn f-s sand, silt, tr coal | |
| 1 | 1-2' | ND | | 1-2'; dkgy-ltbrn f-c sand, gravel, tr wood | Dry |
| 3 | 2-3' | ND | | 2-3'; dkbry-ltbrn f-c sand, silt | |
| 3 | 3-3.25' | ND | | 3-3.25'; ltbrn-tan f-c sand, silt | Dry |
| 4 | 3.25-4' | ND | | 3.25-4'; ltbrn-tan f-c sand, silt, pebbles, some cobbles | |
| 4 | 4-5' | ND | | 4-5'; ltgybrn-tan f-c sand, pebbles, tr cobbles | |
| | 5-7' | ND | | 5-7'; ltgybrn-tan vf-c sand, pebbles | |
| | | ND | | | Damp |
| 8 | 7-8' | 85 | | 7-8'; ltgy-ltbrn, tan, vf-c sand, rx frags, tr pebbles | Wet |
| 8 | 8-9' | | | 8-9'; gy vf-m sand, silt and clay | |
| | 9-11' | | | 9-11'; gy vf-m sand, silt, clay | 9-10' Tr Petroluem Staining |
| 12 | 11-12' | 3.2 | | 11-12'; gy vf-m sand, silt, weathered rx | Petrol Odor (8-12') |
| | | | | EOB at 12' | |

| Pennoni | Hand Auger Test Boring Log | Job Number: | ELKHO26001-6 |
|---|---|---|---|
| | | Job Name: | 1 Vine Street |
| | | Location: | 1Vine St. Larchmont |
| | | Client: | Elk Homes |
| | | Sheet 1 of 1 | |

| Boring ID: | **AB-3** | Driller: | Hand Boring | Total Depth: | 1.5' |
|---|---|---|---|---|---|
| Location: | Autobody - Spray Booth | Rig Type: | Hand Boring | GW Depth: | |
| Date: | 2/19/2026 | Method: | Direct Push | Time: | |
| Time: | | Rec. by: | Peter Antonucci | Notes: | |

| Depth (ft) | Sample Interval | PID (ppm) | % Rec. | Description | Notes |
|---|---|---|---|---|---|
| 0 | 0-0.5' | | | Concrete | |
| | | | | | PID Background @ 3.4 ppm |
| 1 | 0.5-1' | ND | | 0.5-1'; ash, coal frags | |
| 1 | | | | | |
| | 1-1.5' | 2.3 | | 1-1.5'; dk-ltbrn f-m sand, silt | Refusal @1.5' |
| | | | | EOB at 1.5' | |

| Pennoni | Hand Auger Test Boring Log | Job Number: | ELKHO26001 |
|---|---|---|---|
| | | Job Name: | 1 Vine Street |
| | | Location: | 1Vine St. Larchmont |
| | | Client: | |
| | | Sheet 1 of 1 | |

| Boring ID: | AB-4 | Driller: | EnviroShield | Total Depth: | 7' |
|---|---|---|---|---|---|
| Location: | Autobody Shop-Waste Storage | Rig Type: | GeoProbe | GW Depth: | |
| Date: | 2/19/2026 | Method: | Direct Push | Time: | |
| Time: | | Rec. by: | Peter Antonucci | Notes: | |

| Depth (ft) | Sample Interval | PID (ppm) | % Rec. | Description | Notes |
|---|---|---|---|---|---|
| | 0-0.5' | | | 0-0.5'; concrete | |
| | 0.5-1' | ND | | 0.5-1'; ash, dkbrn f-m sand, silt and gravel | |
| 2 | 1-2' | | | 1-2'; ltgy-dkbrn f-m sand, silt, some gravel | |
| 2 | 2-3' | | | 2-3'; gybrn f-m sand, silt, gravel | |
| | 3-4' | | | 3-4'; ltgy-ltbrn f-m sand and silt | Dry |
| | | | | | |
| | 4-5' | ND | | 4-5'; dk-ltbrn m-vc sand, sil and pebbles | |
| 5 | | | | | |
| 5 | 5-6.8' | | | 5-6.8'; ltgy-ltbrn, rdbrn vf-m sand, silt | |
| | | 1.4 | | | Moist |
| 7 | 6.8-7' | | | 6.8-7'; weathered rx | |
| | | | | EOB at 7' | |

| Pennoni | Hand Auger Test Boring Log | Job Number: | ELKHO26001 |
|---|---|---|---|
| | | Job Name: | 1 Vine Street |
| | | Location: | 1 Vine St, Larchmont, NY |
| | | Client: | Elk Homes |
| | | Sheet 1 of 1 | |

| Boring ID: | DC-1 | Driller: | NA | Total Depth: | 5 feet |
|---|---|---|---|---|---|
| Location: | Interior NE | Rig Type: | NA | GW Depth: | NA |
| Date: | 2/18/2026 | Method: | Hand Geoprobe | Time: | |
| Time: | | Rec. by: | J. Trevino | Notes: | |

| Depth (ft) | Sample Interval | PID (ppm) | % Rec. | Description | Notes |
|---|---|---|---|---|---|
| 1 | | | | 0-0.5': Concrete and base<br>0.5-3': Dry dark brown to black, fine to coarse sand, coal, clinkers | |
| 2 | | | | | |
| 3 | | | | 3-5': Dry light brown to tan fine to med. sand, trace coarse sand, some broken rock | |
| 4 | | | | | |
| 5 | | | | EOB 5' | |
| 6 | | | | | |
| 7 | | | | | |
| 8 | | | | | |
| 9 | | | | | |
| 10 | | | | | |
| 22 | | | | | |

| Pennoni | Hand Auger Test Boring Log | Job Number: | ELKHO26001-6 |
|---|---|---|---|
| | | Job Name: | 1 Vine Street |
| | | Location: | 1Vine St. Larchmont |
| | | Client: | |
| | | Sheet 1 of 1 | |

| Boring ID: | EB-1 | Driller: | EnviroShield | Total Depth: | 12.5' |
|---|---|---|---|---|---|
| Location: | Exterior -former gasoline USTs | Rig Type: | GeoProbe3000 | GW Depth: | 7' |
| Date: | 2/19/2026 | Method: | Direct Push | Time: | |
| Time: | | Rec. by: | Peter Antonucci | Notes: | |

| Depth (ft) | Sample Interval | PID (ppm) | % Rec. | Description | Notes |
|---|---|---|---|---|---|
| 0 | | | | | |
| | 0.5-1' | ND | | 0.5-1'; concrete, asphalt | |
| 2 | 1-2' | | | 1-2'; lt-dkbrn f-c sand, silt, pebbles | |
| 2 | | | | 2-3'; ltbrn-dkgy f-c sand, silt, tr coal frags | Dry |
| | 2-3' | ND | | | |
| 4 | 3-4' | | | 3-4'; rdbrn-ltbrn vf-m sand, silt, clay | |
| 4 | 4-6' | | | 4-6'; dkbrn-rdbrn f-c sand, silt, clay | |
| | | ND | | | |
| 8 | 6-8' | | | 6-8'; dk rdbrn f-c sand, silt, clay, tr rx frags | Moist/Wet |
| 8 | | | | 8-9'; dkbrn-rdbrn m-c sand, silt, clay | Wet |
| | 8-9' | | | | |
| | | 124 | | 9-10'; dkgy vf-m sand, silt and clay | |
| | 9-10' | | | | |
| | 10-12.5' | | | 10-12.5'; lt-dkgy f-c sand, silt, clay | |
| | | | | | Wet |
| | | | | | |
| 12.5' | | | | | Refusal @12.5' |
| | | | | EOB at 12.5' | |

| Pennoni | Hand Auger Test Boring Log | Job Number: | ELKHO26001 |
|---|---|---|---|
| | | Job Name: | 1 Vine Street |
| | | Location: | 1Vine St. Larchmont |
| | | Client: | |
| | | Sheet 1 of 1 | |

| Boring ID: | EB-2 | Driller: | EnviroShield | Total Depth: | 11.5' |
|---|---|---|---|---|---|
| Location: | Exterior - adjacent to drycleaner | Rig Type: | GeoProbe3000 | GW Depth: | 7' |
| Date: | 2/19/2026 | Method: | Direct Push | Time: | |
| Time: | | Rec. by: | Peter Antonucci | Notes: | |

| Depth (ft) | Sample Interval | PID (ppm) | % Rec. | Description | Notes |
|---|---|---|---|---|---|
| 0 | 0-0.5' | ND | | 0-0.5'; asphalt and base material | Dry |
| | | | | | |
| | 0.5-4' | | | 0.5-4'; dkbrn-tan, ltgy f-c sand, silt | |
| 4 | | | | | |
| 4 | 4-5' | | | 4-5'; tan-dkbrn f-c sand, silt, pebbles and small cobbles | |
| | | | | | |
| | 5-6' | | | 5-6'; dkgy m-c sand, silt, rx frags | |
| | | | | 6-7'; dkbrn m-c sand, silt | Damp/Wet |
| | 6-7' | | | | |
| 8 | 7-8' | | | 7-8'; dk brn-dkgy m-c sand, silt | Wet |
| 8 | | | | 8-9'; dkgybrn m-c sand, Silt and Clay | |
| | 8-9' | 1,450 | | | Strong Petrol Odor |
| | | | | 9-10'; ltrdbrn-dkgy m-c sand, silt, tr coal frags | Wet |
| | 9-10' | | | | |
| | | | | 10-11.5'; dkrdbrn-ltgy m-c sand, silt and clay | |
| | 10-11.5' | 12 | | | |
| | | | | EOB at 11.5' | 1" PVC OW installed |

| Pennoni | Test Boring/Monitoring Well Construction Log | Job Number: ELKHO26001<br>Job Name:<br>Client: 1 Vine St Larchmont | |
|---|---|---|---|
| **Boring ID:** MW-1 | **EnviroShield** | | **Total Depth:** 10.5' |
| **Elevation:** | **Rig Type:** NA | | **Water Depth:** 7' |
| **Location:** 1 Vine St Larchmont NY | **Method:** Direct Push | | **Well Mount:** Flush |
| **Date:** 2/19/2026 | **Driller:** | | |

| PID | Notes | Depth (ft) | Description | Well Construction Details |
|---|---|---|---|---|
| 0 | | 0 | | |
| 0 | | 2 | | |
| 0 | | 4 | | |
| 0 | | 6 | | 5.5 |
| | Wet | 8 | 1" Diameter PVC<br>5'5' -10.5- 10 slotted screen | |
| 1450 | | 10 | | |
| 12 | | 12 | | 10.5 |
| | | | Terminal Depth 10.5 ' bgs | |
| | | | Filter Pack Grout<br>Seal Well Screen | |

# LABORATORY REPORTS

**Monday, February 23, 2026**

**Attn: Paul Grace**
**Hygenix Division of Pennoni**
**350 Fairfiled Ave 4th Floor #404**
**Bridgeport CT 06604**

**Project ID:** **1 VINE ST LARCHMONT NY**
**SDG ID:** **GCV34749**
**Sample ID#s:** **CV34749 - CV34751**

**This laboratory is in compliance with the NELAC requirements of procedures used except where indicated.**

**This report contains results for the parameters tested, under the sampling conditions described on the Chain Of Custody, as received by the laboratory. This report is incomplete unless all pages indicated in the pagination at the bottom of the page are included.**

**A scanned version of the COC form accompanies the analytical report and is an exact duplicate of the original.**

**The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.**

**Sincerely yours,**

**Phyllis Shiller**
**Laboratory Director**

**NELAC - #NY11301**
**CT Lab Registration #PH-0618**
**MA Lab Registration #M-CT007**
**ME Lab Registration #CT-007**
**NH Lab Registration #213693-A,B**
**NJ Lab Registration #CT-003**
**NY Lab Registration #11301**
**PA Lab Registration #68-03530**
**RI Lab Registration #63**
**VT Lab Registration #VT11301**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

NY # 11301

# Sample Id Cross Reference

February 23, 2026

SDG I.D.: GCV34749

Project ID: 1 VINE ST LARCHMONT NY

| Client Id | Lab Id | Matrix | Col Date |
|---|---|---|---|
| SB-SG-1 | CV34749 | AIR | 02/18/26 13:55 |
| WSA-SG-1 | CV34750 | AIR | 02/18/26 14:16 |
| DC-SG-2 | CV34751 | AIR | 02/18/26 10:35 |

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

NY # 11301

# Analysis Report

February 23, 2026

FOR: Attn: Paul Grace
Hygenix Division of Pennoni
350 Fairfiled Ave 4th Floor #404
Bridgeport CT 06604

| Sample Information | | Custody Information | | Date | Time |
|---|---|---|---|---|---|
| Matrix: | AIR | Collected by: | JT | 02/18/26 | 13:55 |
| Location Code: | PENNONI-CT | Received by: | B | 02/19/26 | 16:10 |
| Rush Request: | Standard | Analyzed by: | see "By" below | | |
| P.O.#: | | | | | |
| Canister Id: | 21359 | | | | |

## Laboratory Data

SDG ID: GCV34749
Phoenix ID: CV34749

Project ID: 1 VINE ST LARCHMONT NY
Client ID: SB-SG-1

| Parameter | ppbv Result | ppbv RL | ug/m3 Result | ug/m3 RL | Date/Time | By | Dilution | |
|---|---|---|---|---|---|---|---|---|
| **Volatiles (TO15)** | | | | | | | | |
| 1,1,1,2-Tetrachloroethane | ND | *0.729* | ND | *5.00* | 02/20/26 | KCA | 5 | 1 |
| 1,1,1-Trichloroethane | ND | *0.917* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,1,2,2-Tetrachloroethane | ND | *0.729* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,1,2-Trichloroethane | ND | *0.917* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,1-Dichloroethane | ND | *1.24* | ND | *5.02* | 02/20/26 | KCA | 5 | |
| 1,1-Dichloroethene | ND | *0.252* | ND | *1.00* | 02/20/26 | KCA | 5 | |
| 1,2,4-Trichlorobenzene | ND | *0.674* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,2,4-Trimethylbenzene | ND | *1.02* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| 1,2-Dibromoethane(EDB) | ND | *0.651* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,2-Dichlorobenzene | ND | *0.832* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,2-Dichloroethane | ND | *1.24* | ND | *5.02* | 02/20/26 | KCA | 5 | |
| 1,2-dichloropropane | ND | *1.08* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| 1,2-Dichlorotetrafluoroethane | ND | *0.716* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,3,5-Trimethylbenzene | ND | *1.02* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| 1,3-Butadiene | ND | *2.26* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,3-Dichlorobenzene | ND | *0.832* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,4-Dichlorobenzene | ND | *0.832* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,4-Dioxane | ND | *1.39* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| 2-Hexanone(MBK) | ND | *1.22* | ND | *4.99* | 02/20/26 | KCA | 5 | 1 |
| 4-Ethyltoluene | ND | *1.02* | ND | *5.01* | 02/20/26 | KCA | 5 | 1 |
| 4-Isopropyltoluene | ND | *0.911* | ND | *5.00* | 02/20/26 | KCA | 5 | 1 |
| 4-Methyl-2-pentanone(MIBK) | ND | *1.22* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Acetone | 23.0 | *2.11* | 54.6 | *5.01* | 02/20/26 | KCA | 5 | |
| Acrylonitrile | ND | *2.31* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Benzene | ND | *1.57* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Benzyl chloride | ND | *0.966* | ND | *5.00* | 02/20/26 | KCA | 5 | |

**Ver 1**

Project ID: 1 VINE ST LARCHMONT NY
Client ID: SB-SG-1

Phoenix I.D.: CV34749

| Parameter | ppbv Result | ppbv RL | ug/m3 Result | ug/m3 RL | Date/Time | By | Dilution | |
|---|---|---|---|---|---|---|---|---|
| Bromodichloromethane | ND | *0.747* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Bromoform | ND | *0.484* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Bromomethane | ND | *1.29* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Carbon Disulfide | ND | *1.61* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Carbon Tetrachloride | ND | *0.159* | ND | *1.00* | 02/20/26 | KCA | 5 | |
| Chlorobenzene | ND | *1.09* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Chloroethane | ND | *1.90* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Chloroform | ND | *1.02* | ND | *4.98* | 02/20/26 | KCA | 5 | |
| Chloromethane | ND | *2.42* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Cis-1,2-Dichloroethene | ND | *0.252* | ND | *1.00* | 02/20/26 | KCA | 5 | |
| cis-1,3-Dichloropropene | ND | *1.10* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Cyclohexane | ND | *1.45* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Dibromochloromethane | ND | *0.587* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Dichlorodifluoromethane | ND | *1.01* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Ethanol | 5.77 | *2.66* | 10.9 | *5.01* | 02/20/26 | KCA | 5 | 1 |
| Ethyl acetate | ND | *1.39* | ND | *5.01* | 02/20/26 | KCA | 5 | 1 |
| Ethylbenzene | ND | *1.15* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Heptane | ND | *1.22* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Hexachlorobutadiene | ND | *0.469* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Hexane | ND | *1.42* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Isooctane | ND | *1.07* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Isopropylalcohol | 4.49 | *2.04* | 11.0 | *5.01* | 02/20/26 | KCA | 5 | |
| Isopropylbenzene | ND | *1.02* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| m,p-Xylene | ND | *1.15* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Methyl Ethyl Ketone | ND | *1.70* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Methyl tert-butyl ether(MTBE) | ND | *1.39* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Methylene Chloride | ND | *4.32* | ND | *15.0* | 02/20/26 | KCA | 5 | |
| Naphthalene | ND | *1.00* | ND | *5.23* | 02/20/26 | KCA | 5 | |
| n-Butylbenzene | ND | *0.911* | ND | *5.00* | 02/20/26 | KCA | 5 | 1 |
| o-Xylene | ND | *1.15* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Propylene | ND | *2.91* | ND | *5.01* | 02/20/26 | KCA | 5 | 1 |
| sec-Butylbenzene | ND | *0.911* | ND | *5.00* | 02/20/26 | KCA | 5 | 1 |
| Styrene | ND | *1.17* | ND | *4.98* | 02/20/26 | KCA | 5 | |
| Tetrachloroethene | 3.01 | *0.184* | 20.4 | *1.25* | 02/20/26 | KCA | 5 | |
| Tetrahydrofuran | ND | *1.70* | ND | *5.01* | 02/20/26 | KCA | 5 | 1 |
| Toluene | 1.56 | *1.33* | 5.88 | *5.01* | 02/20/26 | KCA | 5 | |
| Trans-1,2-Dichloroethene | ND | *1.26* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| trans-1,3-Dichloropropene | ND | *1.10* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Trichloroethene | ND | *0.185* | ND | *0.99* | 02/20/26 | KCA | 5 | |
| Trichlorofluoromethane | ND | *0.891* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Trichlorotrifluoroethane | ND | *0.653* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Vinyl Chloride | ND | *0.390* | ND | *1.00* | 02/20/26 | KCA | 5 | |
| **QA/QC Surrogates/Internals** | | | | | | | | |
| % Bromofluorobenzene (5x) | 105 | *%* | 105 | *%* | 02/20/26 | KCA | 5 | |
| % IS-1,4-Difluorobenzene (5x) | 80 | *%* | 80 | *%* | 02/20/26 | KCA | 5 | |
| % IS-Bromochloromethane (5x) | 83 | *%* | 83 | *%* | 02/20/26 | KCA | 5 | |
| % IS-Chlorobenzene-d5 (5x) | 84 | *%* | 84 | *%* | 02/20/26 | KCA | 5 | |

Project ID: 1 VINE ST LARCHMONT NY
Client ID: SB-SG-1

Phoenix I.D.: CV34749

| Parameter | ppbv Result | ppbv RL | ug/m3 Result | ug/m3 RL | Date/Time | By | Dilution |
|---|---|---|---|---|---|---|---|

1 = This parameter is not certified by the primary accrediting authority (NY NELAC) for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quantitation) ND=Not Detected at RL/PQL
BRL=Below Reporting Level L=Biased Low
QA/QC Surrogates: Surrogates are compounds (preceeded with a %) added by the lab to determine analysis efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

## Comments:

If you are the client above and have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext.200.
The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.



**Phyllis Shiller, Laboratory Director**
**February 23, 2026**
**Reviewed and Released by: Greg Lawrence, Assistant Lab Director**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

NY # 11301

# Analysis Report

February 23, 2026

FOR: Attn: Paul Grace
Hygenix Division of Pennoni
350 Fairfiled Ave 4th Floor #404
Bridgeport CT 06604

| Sample Information | | Custody Information | | Date | Time |
|---|---|---|---|---|---|
| Matrix: | AIR | Collected by: | JT | 02/18/26 | 14:16 |
| Location Code: | PENNONI-CT | Received by: | B | 02/19/26 | 16:10 |
| Rush Request: | Standard | Analyzed by: | see "By" below | | |
| P.O.#: | | | | | |
| Canister Id: | 489 | | | | |

## Laboratory Data

SDG ID: GCV34749
Phoenix ID: CV34750

Project ID: 1 VINE ST LARCHMONT NY
Client ID: WSA-SG-1

| Parameter | ppbv Result | ppbv RL | ug/m3 Result | ug/m3 RL | Date/Time | By | Dilution | |
|---|---|---|---|---|---|---|---|---|
| **Volatiles (TO15)** | | | | | | | | |
| 1,1,1,2-Tetrachloroethane | ND | *0.729* | ND | *5.00* | 02/20/26 | KCA | 5 | 1 |
| 1,1,1-Trichloroethane | ND | *0.917* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,1,2,2-Tetrachloroethane | ND | *0.729* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,1,2-Trichloroethane | ND | *0.917* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,1-Dichloroethane | ND | *1.24* | ND | *5.02* | 02/20/26 | KCA | 5 | |
| 1,1-Dichloroethene | ND | *0.252* | ND | *1.00* | 02/20/26 | KCA | 5 | |
| 1,2,4-Trichlorobenzene | ND | *0.674* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,2,4-Trimethylbenzene | ND | *1.02* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| 1,2-Dibromoethane(EDB) | ND | *0.651* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,2-Dichlorobenzene | ND | *0.832* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,2-Dichloroethane | ND | *1.24* | ND | *5.02* | 02/20/26 | KCA | 5 | |
| 1,2-dichloropropane | ND | *1.08* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| 1,2-Dichlorotetrafluoroethane | ND | *0.716* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,3,5-Trimethylbenzene | ND | *1.02* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| 1,3-Butadiene | ND | *2.26* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,3-Dichlorobenzene | ND | *0.832* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,4-Dichlorobenzene | ND | *0.832* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,4-Dioxane | ND | *1.39* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| 2-Hexanone(MBK) | ND | *1.22* | ND | *4.99* | 02/20/26 | KCA | 5 | 1 |
| 4-Ethyltoluene | ND | *1.02* | ND | *5.01* | 02/20/26 | KCA | 5 | 1 |
| 4-Isopropyltoluene | ND | *0.911* | ND | *5.00* | 02/20/26 | KCA | 5 | 1 |
| 4-Methyl-2-pentanone(MIBK) | ND | *1.22* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Acetone | 42.8 | *2.11* | 102 | *5.01* | 02/20/26 | KCA | 5 | |
| Acrylonitrile | ND | *2.31* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Benzene | ND | *1.57* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Benzyl chloride | ND | *0.966* | ND | *5.00* | 02/20/26 | KCA | 5 | |

**Ver 1**

Project ID: 1 VINE ST LARCHMONT NY
Client ID: WSA-SG-1

Phoenix I.D.: CV34750

| Parameter | ppbv Result | ppbv RL | ug/m3 Result | ug/m3 RL | Date/Time | By | Dilution | |
|---|---|---|---|---|---|---|---|---|
| Bromodichloromethane | ND | *0.747* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Bromoform | ND | *0.484* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Bromomethane | ND | *1.29* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Carbon Disulfide | ND | *1.61* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Carbon Tetrachloride | ND | *0.159* | ND | *1.00* | 02/20/26 | KCA | 5 | |
| Chlorobenzene | ND | *1.09* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Chloroethane | ND | *1.90* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Chloroform | ND | *1.02* | ND | *4.98* | 02/20/26 | KCA | 5 | |
| Chloromethane | ND | *2.42* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Cis-1,2-Dichloroethene | ND | *0.252* | ND | *1.00* | 02/20/26 | KCA | 5 | |
| cis-1,3-Dichloropropene | ND | *1.10* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Cyclohexane | ND | *1.45* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Dibromochloromethane | ND | *0.587* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Dichlorodifluoromethane | ND | *1.01* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Ethanol | 4.70 | *2.66* | 8.85 | *5.01* | 02/20/26 | KCA | 5 | 1 |
| Ethyl acetate | ND | *1.39* | ND | *5.01* | 02/20/26 | KCA | 5 | 1 |
| Ethylbenzene | ND | *1.15* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Heptane | ND | *1.22* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Hexachlorobutadiene | ND | *0.469* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Hexane | ND | *1.42* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Isooctane | ND | *1.07* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Isopropylalcohol | 5.15 | *2.04* | 12.7 | *5.01* | 02/20/26 | KCA | 5 | |
| Isopropylbenzene | ND | *1.02* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| m,p-Xylene | ND | *1.15* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Methyl Ethyl Ketone | ND | *1.70* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Methyl tert-butyl ether(MTBE) | ND | *1.39* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Methylene Chloride | ND | *4.32* | ND | *15.0* | 02/20/26 | KCA | 5 | |
| Naphthalene | ND | *1.00* | ND | *5.23* | 02/20/26 | KCA | 5 | |
| n-Butylbenzene | ND | *0.911* | ND | *5.00* | 02/20/26 | KCA | 5 | 1 |
| o-Xylene | ND | *1.15* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Propylene | ND | *2.91* | ND | *5.01* | 02/20/26 | KCA | 5 | 1 |
| sec-Butylbenzene | ND | *0.911* | ND | *5.00* | 02/20/26 | KCA | 5 | 1 |
| Styrene | ND | *1.17* | ND | *4.98* | 02/20/26 | KCA | 5 | |
| Tetrachloroethene | 1.61 | *0.184* | 10.9 | *1.25* | 02/20/26 | KCA | 5 | |
| Tetrahydrofuran | ND | *1.70* | ND | *5.01* | 02/20/26 | KCA | 5 | 1 |
| Toluene | ND | *1.33* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Trans-1,2-Dichloroethene | ND | *1.26* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| trans-1,3-Dichloropropene | ND | *1.10* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Trichloroethene | ND | *0.185* | ND | *0.99* | 02/20/26 | KCA | 5 | |
| Trichlorofluoromethane | ND | *0.891* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Trichlorotrifluoroethane | ND | *0.653* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Vinyl Chloride | ND | *0.390* | ND | *1.00* | 02/20/26 | KCA | 5 | |
| **QA/QC Surrogates/Internals** | | | | | | | | |
| % Bromofluorobenzene (5x) | 106 | *%* | 106 | *%* | 02/20/26 | KCA | 5 | |
| % IS-1,4-Difluorobenzene (5x) | 84 | *%* | 84 | *%* | 02/20/26 | KCA | 5 | |
| % IS-Bromochloromethane (5x) | 82 | *%* | 82 | *%* | 02/20/26 | KCA | 5 | |
| % IS-Chlorobenzene-d5 (5x) | 82 | *%* | 82 | *%* | 02/20/26 | KCA | 5 | |

Project ID: 1 VINE ST LARCHMONT NY
Client ID: WSA-SG-1

Phoenix I.D.: CV34750

| Parameter | ppbv Result | ppbv RL | ug/m3 Result | ug/m3 RL | Date/Time | By | Dilution |
|---|---|---|---|---|---|---|---|

1 = This parameter is not certified by the primary accrediting authority (NY NELAC) for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quantitation) ND=Not Detected at RL/PQL
BRL=Below Reporting Level L=Biased Low
QA/QC Surrogates: Surrogates are compounds (preceeded with a %) added by the lab to determine analysis efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

## Comments:

If you are the client above and have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext.200.
The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.



**Phyllis Shiller, Laboratory Director**
**February 23, 2026**
**Reviewed and Released by: Greg Lawrence, Assistant Lab Director**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

NY # 11301

# Analysis Report

February 23, 2026

FOR: Attn: Paul Grace
Hygenix Division of Pennoni
350 Fairfiled Ave 4th Floor #404
Bridgeport CT 06604

| Sample Information | | Custody Information | | Date | Time |
|---|---|---|---|---|---|
| Matrix: | AIR | Collected by: | JT | 02/18/26 | 10:35 |
| Location Code: | PENNONI-CT | Received by: | B | 02/19/26 | 16:10 |
| Rush Request: | Standard | Analyzed by: | see "By" below | | |
| P.O.#: | | | | | |
| Canister Id: | 49248 | | | | |

## Laboratory Data

SDG ID: GCV34749
Phoenix ID: CV34751

Project ID: 1 VINE ST LARCHMONT NY
Client ID: DC-SG-2

| Parameter | ppbv Result | ppbv RL | ug/m3 Result | ug/m3 RL | Date/Time | By | Dilution | |
|---|---|---|---|---|---|---|---|---|
| **Volatiles (TO15)** | | | | | | | | |
| 1,1,1,2-Tetrachloroethane | ND | *0.729* | ND | *5.00* | 02/20/26 | KCA | 5 | 1 |
| 1,1,1-Trichloroethane | ND | *0.917* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,1,2,2-Tetrachloroethane | ND | *0.729* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,1,2-Trichloroethane | ND | *0.917* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,1-Dichloroethane | ND | *1.24* | ND | *5.02* | 02/20/26 | KCA | 5 | |
| 1,1-Dichloroethene | ND | *0.252* | ND | *1.00* | 02/20/26 | KCA | 5 | |
| 1,2,4-Trichlorobenzene | ND | *0.674* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,2,4-Trimethylbenzene | ND | *1.02* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| 1,2-Dibromoethane(EDB) | ND | *0.651* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,2-Dichlorobenzene | ND | *0.832* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,2-Dichloroethane | ND | *1.24* | ND | *5.02* | 02/20/26 | KCA | 5 | |
| 1,2-dichloropropane | ND | *1.08* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| 1,2-Dichlorotetrafluoroethane | ND | *0.716* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,3,5-Trimethylbenzene | ND | *1.02* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| 1,3-Butadiene | ND | *2.26* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,3-Dichlorobenzene | ND | *0.832* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,4-Dichlorobenzene | ND | *0.832* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| 1,4-Dioxane | ND | *1.39* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| 2-Hexanone(MBK) | ND | *1.22* | ND | *4.99* | 02/20/26 | KCA | 5 | 1 |
| 4-Ethyltoluene | ND | *1.02* | ND | *5.01* | 02/20/26 | KCA | 5 | 1 |
| 4-Isopropyltoluene | ND | *0.911* | ND | *5.00* | 02/20/26 | KCA | 5 | 1 |
| 4-Methyl-2-pentanone(MIBK) | ND | *1.22* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Acetone | 98.7 | *2.11* | 234 | *5.01* | 02/20/26 | KCA | 5 | |
| Acrylonitrile | ND | *2.31* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Benzene | ND | *1.57* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Benzyl chloride | ND | *0.966* | ND | *5.00* | 02/20/26 | KCA | 5 | |

Project ID: 1 VINE ST LARCHMONT NY
Client ID: DC-SG-2

Phoenix I.D.: CV34751

| Parameter | ppbv Result | ppbv RL | ug/m3 Result | ug/m3 RL | Date/Time | By | Dilution | |
|---|---|---|---|---|---|---|---|---|
| Bromodichloromethane | ND | *0.747* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Bromoform | ND | *0.484* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Bromomethane | ND | *1.29* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Carbon Disulfide | ND | *1.61* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Carbon Tetrachloride | ND | *0.159* | ND | *1.00* | 02/20/26 | KCA | 5 | |
| Chlorobenzene | ND | *1.09* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Chloroethane | ND | *1.90* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Chloroform | ND | *1.02* | ND | *4.98* | 02/20/26 | KCA | 5 | |
| Chloromethane | ND | *2.42* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Cis-1,2-Dichloroethene | 0.405 | *0.252* | 1.60 | *1.00* | 02/20/26 | KCA | 5 | |
| cis-1,3-Dichloropropene | ND | *1.10* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Cyclohexane | ND | *1.45* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Dibromochloromethane | ND | *0.587* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Dichlorodifluoromethane | ND | *1.01* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Ethanol | 172 | *2.66* | 324 | *5.01* | 02/20/26 | KCA | 5 | 1 |
| Ethyl acetate | ND | *1.39* | ND | *5.01* | 02/20/26 | KCA | 5 | 1 |
| Ethylbenzene | ND | *1.15* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Heptane | 3.80 | *1.22* | 15.6 | *5.00* | 02/20/26 | KCA | 5 | |
| Hexachlorobutadiene | ND | *0.469* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Hexane | ND | *1.42* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Isooctane | ND | *1.07* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Isopropylalcohol | 8.07 | *2.04* | 19.8 | *5.01* | 02/20/26 | KCA | 5 | |
| Isopropylbenzene | ND | *1.02* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| m,p-Xylene | ND | *1.15* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Methyl Ethyl Ketone | ND | *1.70* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Methyl tert-butyl ether(MTBE) | ND | *1.39* | ND | *5.01* | 02/20/26 | KCA | 5 | |
| Methylene Chloride | ND | *4.32* | ND | *15.0* | 02/20/26 | KCA | 5 | |
| Naphthalene | ND | *1.00* | ND | *5.23* | 02/20/26 | KCA | 5 | |
| n-Butylbenzene | ND | *0.911* | ND | *5.00* | 02/20/26 | KCA | 5 | 1 |
| o-Xylene | ND | *1.15* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Propylene | ND | *2.91* | ND | *5.01* | 02/20/26 | KCA | 5 | 1 |
| sec-Butylbenzene | ND | *0.911* | ND | *5.00* | 02/20/26 | KCA | 5 | 1 |
| Styrene | ND | *1.17* | ND | *4.98* | 02/20/26 | KCA | 5 | |
| Tetrachloroethene | 5.63 | *0.184* | 38.2 | *1.25* | 02/20/26 | KCA | 5 | |
| Tetrahydrofuran | ND | *1.70* | ND | *5.01* | 02/20/26 | KCA | 5 | 1 |
| Toluene | 3.55 | *1.33* | 13.4 | *5.01* | 02/20/26 | KCA | 5 | |
| Trans-1,2-Dichloroethene | ND | *1.26* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| trans-1,3-Dichloropropene | ND | *1.10* | ND | *4.99* | 02/20/26 | KCA | 5 | |
| Trichloroethene | 0.545 | *0.185* | 2.93 | *0.99* | 02/20/26 | KCA | 5 | |
| Trichlorofluoromethane | ND | *0.891* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Trichlorotrifluoroethane | ND | *0.653* | ND | *5.00* | 02/20/26 | KCA | 5 | |
| Vinyl Chloride | ND | *0.390* | ND | *1.00* | 02/20/26 | KCA | 5 | |
| **QA/QC Surrogates/Internals** | | | | | | | | |
| % Bromofluorobenzene (5x) | 105 | *%* | 105 | *%* | 02/20/26 | KCA | 5 | |
| % IS-1,4-Difluorobenzene (5x) | 80 | *%* | 80 | *%* | 02/20/26 | KCA | 5 | |
| % IS-Bromochloromethane (5x) | 79 | *%* | 79 | *%* | 02/20/26 | KCA | 5 | |
| % IS-Chlorobenzene-d5 (5x) | 81 | *%* | 81 | *%* | 02/20/26 | KCA | 5 | |

Project ID: 1 VINE ST LARCHMONT NY
Client ID: DC-SG-2

Phoenix I.D.: CV34751

| Parameter | ppbv Result | ppbv RL | ug/m3 Result | ug/m3 RL | Date/Time | By | Dilution |
|---|---|---|---|---|---|---|---|

1 = This parameter is not certified by the primary accrediting authority (NY NELAC) for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quantitation) ND=Not Detected at RL/PQL
BRL=Below Reporting Level L=Biased Low
QA/QC Surrogates: Surrogates are compounds (preceeded with a %) added by the lab to determine analysis efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

## Comments:

If you are the client above and have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext.200.
The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.



**Phyllis Shiller, Laboratory Director**
**February 23, 2026**
**Reviewed and Released by: Greg Lawrence, Assistant Lab Director**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

NY # 11301

# Canister Sampling Information

February 23, 2026

FOR: Attn: Paul Grace
Hygenix Division of Pennoni
350 Fairfiled Ave 4th Floor #404
Bridgeport CT 06604

Location Code: PENNONI-CT

SDG I.D.: GCV34749

Project ID: 1 VINE ST LARCHMONT NY

| | | Canister | | Reg. | Chk Out | Laboratory Out | In | Out | In | Flow | Start | End | Field Sampling | Sampling |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Client Id | Lab Id | Id | Type | Id | Date | Hg | Hg | Flow | Flow | RPD | Hg | Hg | Start Date | End Date |
| SB-SG-1 | CV34749 | 21359 | 6.0L | 10597 | 02/17/26 | -30 | -8 | 178 | 188 | 5.5 | -26 | -7 | 02/18/26 13:25 | 02/18/36 13:55 |
| WSA-SG-1 | CV34750 | 489 | 6.0L | 22590 | 02/17/26 | -30 | -1 | 172 | 192 | 11.0 | -27 | -2 | 02/18/26 13:37 | 02/18/36 14:16 |
| DC-SG-2 | CV34751 | 49248 | 6.0L | 19863 | 02/17/26 | -30 | -7 | 172 | 197 | 13.6 | -27 | -4 | 02/18/26 10:05 | 02/18/36 10:35 |

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# QA/QC Report

February 23, 2026

## QA/QC Data

SDG I.D.: GCV34749

| Parameter | Blk ppbv | Blk RL ppbv | Blk ug/m3 | Blk RL ug/m3 | LCS % | Sample Result ug/m3 | Sample Dup ug/m3 | Sample Result ppbv | Sample Dup ppbv | DUP RPD | % Rec Limits | % RPD Limits |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| QA/QC Batch 827575 (ppbv), QC Sample No: CV34043 (CV34749 (5X) , CV34750 (5X) , CV34751 (5X) ) | | | | | | | | | | | | |
| **Volatiles** | | | | | | | | | | | | |
| 1,1,1,2-Tetrachloroethane | ND | 0.250 | ND | 1.72 | 92 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,1,1-Trichloroethane | ND | 0.250 | ND | 1.36 | 101 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,1,2,2-Tetrachloroethane | ND | 0.005 | ND | 0.03 | 97 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,1,2-Trichloroethane | ND | 0.010 | ND | 0.05 | 103 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,1-Dichloroethane | ND | 0.075 | ND | 0.30 | 102 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,1-Dichloroethene | ND | 0.100 | ND | 0.40 | 99 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,2,4-Trichlorobenzene | ND | 0.027 | ND | 0.20 | 102 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,2,4-Trimethylbenzene | ND | 0.250 | ND | 1.23 | 107 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,2-Dibromoethane(EDB) | ND | 0.005 | ND | 0.04 | 103 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,2-Dichlorobenzene | ND | 0.050 | ND | 0.30 | 101 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,2-Dichloroethane | ND | 0.010 | ND | 0.04 | 102 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,2-dichloropropane | ND | 0.010 | ND | 0.05 | 98 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,2-Dichlorotetrafluoroethane | ND | 0.250 | ND | 1.75 | 99 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,3,5-Trimethylbenzene | ND | 0.250 | ND | 1.23 | 102 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,3-Butadiene | ND | 0.250 | ND | 0.55 | 96 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,3-Dichlorobenzene | ND | 0.050 | ND | 0.30 | 100 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,4-Dichlorobenzene | ND | 0.040 | ND | 0.24 | 99 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 1,4-Dioxane | ND | 0.065 | ND | 0.23 | 110 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 2,2,4-Trimethylpentane | ND | 0.100 | ND | 0.47 | 102 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 2-Hexanone(MBK) | ND | 0.250 | ND | 1.02 | 108 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 4-Ethyltoluene | ND | 0.250 | ND | 1.23 | 104 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 4-Isopropyltoluene | ND | 0.250 | ND | 1.37 | 95 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| 4-Methyl-2-pentanone(MIBK) | ND | 0.250 | ND | 1.02 | 102 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Acetone | ND | 0.375 | ND | 0.89 | 94 | 8.48 | 8.50 | 3.57 | 3.58 | 0.3 | 70 - 130 | 25 |
| Acrylonitrile | ND | 0.250 | ND | 0.54 | 126 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Benzene | ND | 0.100 | ND | 0.32 | 100 | 0.75 | 0.77 | 0.234 | 0.242 | NC | 70 - 130 | 25 |
| Benzyl chloride | ND | 0.250 | ND | 1.29 | 112 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Bromodichloromethane | ND | 0.010 | ND | 0.07 | 103 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Bromoform | ND | 0.075 | ND | 0.77 | 97 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Bromomethane | ND | 0.070 | ND | 0.27 | 98 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Carbon Disulfide | ND | 0.250 | ND | 0.78 | 98 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Carbon Tetrachloride | ND | 0.043 | ND | 0.27 | 103 | 0.45 | 0.46 | 0.072 | 0.073 | NC | 70 - 130 | 25 |
| Chlorobenzene | ND | 0.100 | ND | 0.46 | 98 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Chloroethane | ND | 0.250 | ND | 0.66 | 96 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Chloroform | ND | 0.100 | ND | 0.49 | 100 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Chloromethane | ND | 0.250 | ND | 0.52 | 92 | 1.08 | 1.05 | 0.525 | 0.511 | NC | 70 - 130 | 25 |
| Cis-1,2-Dichloroethene | ND | 0.100 | ND | 0.40 | 104 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| cis-1,3-Dichloropropene | ND | 0.050 | ND | 0.23 | 106 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Cyclohexane | ND | 0.250 | ND | 0.86 | 96 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Dibromochloromethane | ND | 0.010 | ND | 0.09 | 103 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Dichlorodifluoromethane | ND | 0.250 | ND | 1.24 | 101 | 2.04 | 2.06 | 0.413 | 0.417 | NC | 70 - 130 | 25 |

# QA/QC Data

SDG I.D.: GCV34749

| Parameter | Blk ppbv | Blk RL ppbv | Blk ug/m3 | Blk RL ug/m3 | LCS % | Sample Result ug/m3 | Sample Dup ug/m3 | Sample Result ppbv | Sample Dup ppbv | DUP RPD | % Rec Limits | % RPD Limits |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Ethanol | ND | 0.375 | ND | 0.71 | 98 | 16.7 | 17.8 | 8.85 | 9.45 | 6.6 | 70 - 130 | 25 |
| Ethyl acetate | ND | 0.250 | ND | 0.90 | 110 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Ethylbenzene | ND | 0.250 | ND | 1.08 | 103 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Heptane | ND | 0.250 | ND | 1.02 | 103 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Hexachlorobutadiene | ND | 0.005 | ND | 0.05 | 89 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Hexane | ND | 0.225 | ND | 0.79 | 105 | 0.84 | 0.85 | 0.238 | 0.241 | NC | 70 - 130 | 25 |
| Isopropylalcohol | ND | 0.375 | ND | 0.92 | 96 | 3.32 | 3.22 | 1.35 | 1.31 | NC | 70 - 130 | 25 |
| Isopropylbenzene | ND | 0.250 | ND | 1.23 | 94 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| m,p-Xylene | ND | 0.500 | ND | 2.17 | 104 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Methyl Ethyl Ketone | ND | 0.225 | ND | 0.66 | 95 | 1.13 | 1.19 | 0.384 | 0.404 | NC | 70 - 130 | 25 |
| Methyl tert-butyl ether(MTBE) | ND | 0.250 | ND | 0.90 | 103 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Methylene Chloride | ND | 1.50 | ND | 5.21 | 92 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Naphthalene | ND | 2.50 | ND | 13.1 | 104 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| n-Butylbenzene | ND | 0.250 | ND | 1.37 | 97 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| o-Xylene | ND | 0.250 | ND | 1.08 | 104 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Propylene | ND | 0.250 | ND | 0.43 | 95 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| sec-Butylbenzene | ND | 0.250 | ND | 1.37 | 94 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Styrene | ND | 0.100 | ND | 0.43 | 106 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Tetrachloroethene | ND | 0.050 | ND | 0.34 | 100 | 4.74 | 4.79 | 0.700 | 0.707 | 1.0 | 70 - 130 | 25 |
| Tetrahydrofuran | ND | 0.250 | ND | 0.74 | 100 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Toluene | ND | 0.250 | ND | 0.94 | 104 | 1.75 | 1.80 | 0.465 | 0.477 | NC | 70 - 130 | 25 |
| Trans-1,2-Dichloroethene | ND | 0.100 | ND | 0.40 | 104 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| trans-1,3-Dichloropropene | ND | 0.250 | ND | 1.13 | 110 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Trichloroethene | ND | 0.025 | ND | 0.13 | 98 | 0.82 | 0.85 | 0.153 | 0.159 | 3.8 | 70 - 130 | 25 |
| Trichlorofluoromethane | ND | 0.250 | ND | 1.40 | 99 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Trichlorotrifluoroethane | ND | 0.250 | ND | 1.91 | 97 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| Vinyl Chloride | ND | 0.050 | ND | 0.13 | 94 | ND | ND | ND | ND | NC | 70 - 130 | 25 |
| % Bromofluorobenzene | 103 | % | 103 | % | 100 | 104 | 109 | 104 | 109 | NC | 70 - 130 | 25 |
| % IS-1,4-Difluorobenzene | 107 | % | 107 | % | 95 | 86 | 84 | 86 | 84 | NC | 60 - 140 | 25 |
| % IS-Bromochloromethane | 104 | % | 104 | % | 94 | 89 | 87 | 89 | 87 | NC | 60 - 140 | 25 |
| % IS-Chlorobenzene-d5 | 105 | % | 105 | % | 108 | 93 | 87 | 93 | 87 | NC | 60 - 140 | 25 |

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

RPD - Relative Percent Difference
LCS - Laboratory Control Sample
LCSD - Laboratory Control Sample Duplicate
MS - Matrix Spike
MS Dup - Matrix Spike Duplicate
NC - No Criteria
Intf - Interference
(ISO) - Isotope Dilution



Phyllis Shiller, Laboratory Director
February 23, 2026

Monday, February 23, 2026

Criteria: NY: AIRSV

State: NY

# Sample Criteria Exceedances Report

## GCV34749 - PENNONI-CT

| SampNo | Acode | Phoenix Analyte | Criteria | Result | RL | Criteria | RL Criteria | Analysis Units |
|---|---|---|---|---|---|---|---|---|

*** No Data to Display ***

Phoenix Laboratories does not assume responsibility for the data contained in this exceedance report. It is provided as an additional tool to identify requested criteria exceedences. All efforts are made to ensure the accuracy of the data (obtained from appropriate agencies). A lack of exceedence information does not necessarily suggest conformance to the criteria. It is ultimately the site professional's responsibility to determine appropriate compliance.

Bureau of Water Protection and Land Reuse
Remediation Division

# REASONABLE CONFIDENCE PROTOCOL
# LABORATORY ANALYSIS QA/QC CERTIFICATION FORM

| | |
|---|---|
| Laboratory Name<br>Phoenix Environmental Labs, Inc. | Client Name<br>Hygenix Division of Pennoni |
| Project Location<br>1 VINE ST LARCHMONT NY | Project No. |
| Sampling Date(s)<br>2/18/2026 | Laboratory Sample ID(s):<br>CV34749-CV34751 |

LIST RCP METHODS USED (e.g., 8260,8270, etc.) TO15

| | | |
|---|---|---|
| 1 | For each analytical method referenced in this laboratory report package, were all specified QA/QC performance criteria followed, including the requirement to explain any criteria falling outside of acceptable guidelines, as specified in the CT DEEP method-specific Reasonable Confidence Protocol documents? | ☑ Yes ☐ No |
| 1A | Were the method-specified preservation and holding time requirements met? | ☑ Yes ☐ No |
| 1B | VPH and EPH methods only: Was the VPH or EPH method conducted without significant modifications (see respective RCPs) | ☐ Yes ☐ No ☑ NA |
| 2 | Were all samples received by the laboratory in a condition consistent with that described on the associated chain-of-custody document(s)? | ☑ Yes ☐ No |
| 3 | Were samples received at an appropriate temperature (≤6° C)?<br>*If samples were received by the laboratory on the same day of collection and were stored and transported to the laboratory on ice, cooler temperatures above 6ºC are acceptable.* | ☐ Yes ☐ No ☑ NA |
| 4 | Were all QA/QC performance criteria specified in the CT DEEP Reasonable Confidence Protocol documents achieved? | ☑ Yes ☐ No |
| 5 | Were reporting limits / limits of quantitation specified or referenced on the chain-of-custody? | ☑ Yes ☐ No |
| 5a | Were these reporting limits / limits of quantitation met? | ☑ Yes ☐ No |
| 6 | For each analytical method referenced in this laboratory report package, were results reported for all constituents identified in the method-specific analyte lists presented in the Reasonable Confidence Protocol documents? | ☑ Yes ☐ No |
| 7 | Are project-specific matrix spikes and laboratory duplicates included in this data set for applicable RCPs? | ☐ Yes ☑ No |

Notes: For all questions to which the response was "No" (with the exception of question #7), additional information must be provided in an attached narrative. If the answer to question #1, #1A, or #1B is "No", the data package does not meet the requirements for "Reasonable Confidence." This form may not be altered, and all questions must be answered.

I, the undersigned, attest under the pains and penalties of perjury that, to the best of my knowledge and belief and based upon my personal inquiry of those responsible for providing the information contained in this analytical report, such information is accurate and complete.

Authorized Signature:  Position: Assistant Lab Director

Printed Name: Greg Lawrence Date: Monday, February 23, 2026

Name of Laboratory Phoenix Environmental Laboratory, Inc.

This certification form is to be used for RCP methods only.

**Environmental Laboratories, Inc.**
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

NY # 11301

# RCP Certification Report

February 23, 2026

SDG I.D.: GCV34749

## *SDG Comments*

CV34749 - The following analytes from the 8260 RCP Volatile list were not reported: 1,1-Dichloropropene, 1,2,3-Trichlorobenzene, 1,2,3-Trichloropropane, 1,2-Dibromo-3-chloropropane, 1,3-Dichloropropane, 2,2-Dichloropropane, 2-Chlorotoluene, 4-Chlorotoluene, Bromobenzene, Dibromomethane, n-Propylbenzene, tert-Butylbenzene, trans-1,4-dichloro-2-butene.

CV34750 - The following analytes from the 8260 RCP Volatile list were not reported: 1,1-Dichloropropene, 1,2,3-Trichlorobenzene, 1,2,3-Trichloropropane, 1,2-Dibromo-3-chloropropane, 1,3-Dichloropropane, 2,2-Dichloropropane, 2-Chlorotoluene, 4-Chlorotoluene, Bromobenzene, Dibromomethane, n-Propylbenzene, tert-Butylbenzene, trans-1,4-dichloro-2-butene.

CV34751 - The following analytes from the 8260 RCP Volatile list were not reported: 1,1-Dichloropropene, 1,2,3-Trichlorobenzene, 1,2,3-Trichloropropane, 1,2-Dibromo-3-chloropropane, 1,3-Dichloropropane, 2,2-Dichloropropane, 2-Chlorotoluene, 4-Chlorotoluene, Bromobenzene, Dibromomethane, n-Propylbenzene, tert-Butylbenzene, trans-1,4-dichloro-2-butene.

## *AIRSIM*

Were all QA/QC performance criteria specified in the Reasonable Confidence Protocol documents achieved? Yes.

### Instrument:

**CHEM20 02/19/26-1** Keith Aloisa, Chemist 02/19/26

CV34749 (5X), CV34750 (5X), CV34751 (5X)

Initial Calibration Evaluation (CHEM20/20_AIR_0217):
100% of target compounds met criteria.
The following compounds had %RSDs >30%: None.
The following compounds did not meet recommended response factors: None.

Continuing Calibration Verification #1 (CHEM20/0219_02-20_AIR_0217):
Internal standard areas were within 60 to 140% of the initial calibration with the following exceptions: None.
97% of target compounds met criteria.
The following compounds did not meet % deviation criteria: Naphthalene 33%L (30%)
The following compounds did not meet maximum % deviations: Naphthalene 33%L (30%)
The following compounds did not meet recommended response factors: None.

### QC (Batch Specific):

**Batch 827575 (CV34043)**

CV34749(5X), CV34750(5X), CV34751(5X)

All LCS recoveries were within 70 - 130 with the following exceptions: None.

# CHAIN OF CUSTODY RECORD
## AIR ANALYSES

PHOENIX Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O. Box 370, Manchester, CT 06040
Telephone: 860.645.1102 • Fax: 860.645.0823
PENNONI-CT

860-645-1102
email: greg@phoenixlabs.com

P.O. # Page 1 of 1

Data Delivery:
☐ Fax #:
☒ Email: DaWilliams@pennoni.com
☐ Phone #:

| | | | |
|---|---|---|---|
| Report to: | Paul Grace | Project Name: 1 Vinci St, Larchmont NY | Data Format: (Circle) Equis Excel Other: |
| Customer: | Hygenix Division of Pennoni | Invoice to: JMori@pennoni.com | Requested Deliverable: RCP ASP CAT B |
| Address: | 350 Fairfiled Ave 4th Floor #404 | | MCP NJ Deliverables |
| 18730 | Bridgeport CT 06604 | Sampled by: Joseph Trevino | Quote Number: |

| Phoenix ID # | Client Sample ID | Canister ID # | Canister Size (L) | Outgoing Canister Pressure ("Hg) | Incoming Canister Pressure ("Hg) | Flow Regulator ID # | Flow Controller Setting (mL/min) | Sampling Start Time | Sampling End Time | Sample Start Date | Canister Pressure at Start (" Hg) | Canister Pressure at End ("Hg) | Ambient/Indoor Air | Soil Gas | Grab (G) Composite (C) | TO-15 | APH |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | THIS SECTION FOR LAB USE ONLY | | | | | | | | | | | MATRIX | | | ANALYSES | |
| 34749 | SB-SG-1 | 21359 | 6.0L | -30 | -8 | 10597 | 178 | 1325 | 1355 | 2/18/26 | -26 | -7 | | X | X | X | |
| 34750 | WSA-SG-1 | 489 | 6.0L | -30 | -1 | 22590 | 172 | 1337 | 1416 | 2/18/26 | -27 | -2 | | X | X | X | |
| | ★ | 53454 | 6.0L | -30 | | 3511 | 171 | | | | | | | | | | |
| 34751 | DC-SG-1 | 49248 | 6.0L | -30 | -7 | 19863 | 172 | 1005 | 1035 | 2/18/26 | -27 | -4 | | X | X | X | |

| Relinquished by: | Accepted by: | Date: | Time: |
|---|---|---|---|
| Jacqui C | Jacqui C | 2/19/26 | 12:27 |
| Jacqui C | | 2/19/20 | 16:10 |

I attest that all media released by Phoenix Environmental Laboratories, Inc. have been received in good working condition and agree to the terms and conditions as listed on the back of this document:

Signature: Date: 2/19/26

State Where Samples Collected: NY

SPECIAL INSTRUCTIONS, QC REQUIREMENTS, REGULATORY INFORMATION:

(4) - 6.0L 30 min , 12ft Tubing, 4 Connectors

Turnaround Time:
- 1 Day* ☐
- 2 Day* ☐
- 3 Day* ☐
- 4 Day* ☐
- 5 Day* ☐
- Standard ☒

*SURCHARGES MAY APPLY

Requested Criteria: (Please Circle)

| CT: | MA: | NJ: | NY: | PA: | VT: |
|---|---|---|---|---|---|
| TAC I/C<br>TAC RES<br>SVVC I/C<br>SVVC RES<br>GWV I/C<br>GWV CES | Indoor Air:<br>Residential<br>Ind/Commercial<br>Soil Gas:<br>Residential<br>Ind/Commercial | Indoor Air:<br>Residential<br>Ind/Commercial<br>Soil Gas:<br>Residential<br>Ind/Commercial | Vapor Intrusion | Indoor Air<br>Residential<br>Non-residential | Indoor Air<br>Residential<br>Industrial<br>Sub-slab<br>Residential<br>Industrial |

PHOENIX
Environmental Laboratories, Inc.

**Friday, March 06, 2026**

**Attn: David Williams**
**Hygenix Division of Pennoni**
**350 Fairfiled Ave 4th Floor #404**
**Bridgeport CT 06604**

**Project ID:** **1 VINE ST, LARCHMONT, NY**
**SDG ID:** **GCV35319**
**Sample ID#s: CV35319 - CV35324**

**This laboratory is in compliance with the NELAC requirements of procedures used except where indicated.**

**This report contains results for the parameters tested, under the sampling conditions described on the Chain Of Custody, as received by the laboratory. This report is incomplete unless all pages indicated in the pagination at the bottom of the page are included.**

**All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.**

**A scanned version of the COC form accompanies the analytical report and is an exact duplicate of the original.**

**The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.**

**Sincerely yours,**

**Phyllis Shiller**

**Laboratory Director**

**NELAC - #NY11301**
**CT Lab Registration #PH-0618**
**MA Lab Registration #M-CT007**
**ME Lab Registration #CT-007**
**NH Lab Registration #213693-A,B**
**NJ Lab Registration #CT-003**
**NY Lab Registration #11301**
**PA Lab Registration #68-03530**
**RI Lab Registration #63**
**VT Lab Registration #VT11301**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

NY # 11301

# SDG Comments

March 06, 2026

SDG I.D.: GCV35319

Any compound that is not detected above the MDL/LOD is reported as ND on the report and is reported in the electronic deliverables (EDD) as <RL or U at the RL per state and EPA guidance.

Version 1: Analysis results minus raw data.

Version 2: Complete Data package report with all forms and raw data.

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

NY # 11301

# Sample Id Cross Reference

March 06, 2026

SDG I.D.: GCV35319

Project ID: 1 VINE ST, LARCHMONT, NY

| Client Id | Lab Id | Matrix | Col Date |
|---|---|---|---|
| AB-1 (7-8.4`) | CV35319 | SOIL | 02/19/26 0:00 |
| AB-2 (7-8`) | CV35320 | SOIL | 02/19/26 0:00 |
| AB-3 (1-1.5`) | CV35321 | SOIL | 02/19/26 0:00 |
| AB-4 (0.5-1.5`) | CV35322 | SOIL | 02/19/26 0:00 |
| AB-4 (2.5-5`) | CV35323 | SOIL | 02/19/26 0:00 |
| AB-4 (5-6.8`) | CV35324 | SOIL | 02/19/26 0:00 |

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# Analysis Report

March 06, 2026

FOR: Attn: David Williams
Hygenix Division of Pennoni
350 Fairfiled Ave 4th Floor #404
Bridgeport CT 06604

| Sample Information | | Custody Information | | Date | Time |
|---|---|---|---|---|---|
| Matrix: | SOIL | Collected by: | | 02/19/26 | |
| Location Code: | PENNONI-CT | Received by: | SR1 | 02/20/26 | 16:10 |
| Rush Request: | Standard | Analyzed by: | see "By" below | | |
| P.O.#: | ELKH026001-6 | | | | |

## Laboratory Data

SDG ID: GCV35319
Phoenix ID: CV35319

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-1 (7-8.4`)

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|---|
| Silver | ND | 0.33 | 0.33 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Arsenic | 1.75 | 0.67 | 0.67 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Barium | 216 | 0.33 | 0.33 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Cadmium | 0.34 | 0.33 | 0.33 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Chromium | 34.0 | 0.33 | 0.33 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Copper | 5.0 | 0.7 | 0.33 | mg/kg | 1 | 02/25/26 | TH | SW6010D | |
| Mercury | ND | 0.03 | 0.02 | mg/Kg | 1 | 03/03/26 | ZT | SW7471B | |
| Nickel | 25.6 | 0.33 | 0.33 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Lead | 5.81 | 0.33 | 0.33 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Selenium | ND | 1.3 | 1.1 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Zinc | 80.2 | 0.7 | 0.33 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Percent Solid | 90 | | | % | | 02/20/26 | JRB | SW846-%Solid | |
| Field Extraction | Completed | | | | | 02/19/26 | | SW5035A | 1 |
| Mercury Digestion | Completed | | | | | 03/03/26 | ZT/SD | SW7473 | |
| Soil Extraction for PCB | Completed | | | | | 03/02/26 | H/U | SW3546 | |
| Soil Extraction for SVOA PAH | Completed | | | | | 02/26/26 | SM/S/Z | SW3546 | |
| Total Metals Digest | Completed | | | | | 02/24/26 | C/AG | SW3050B | |
| **Polychlorinated Biphenyls** | | | | | | | | | |
| PCB-1016 | ND | 0.36 | 0.36 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| PCB-1221 | ND | 0.36 | 0.36 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| PCB-1232 | ND | 0.36 | 0.36 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| PCB-1242 | ND | 0.36 | 0.36 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| PCB-1248 | ND | 0.36 | 0.36 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| PCB-1254 | ND | 0.36 | 0.36 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| PCB-1260 | ND | 0.36 | 0.36 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| PCB-1262 | ND | 0.36 | 0.36 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |

**Ver 1**

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-1 (7-8.4`)

Phoenix I.D.: CV35319

| Parameter | Result | | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|---|---|
| PCB-1268 | ND | | 0.36 | 0.36 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| **QA/QC Surrogates** | | | | | | | | | | |
| % DCBP | 99 | | | | % | 10 | 03/03/26 | SC | 30 - 150 % | |
| % DCBP (Confirmation) | 83 | | | | % | 10 | 03/03/26 | SC | 30 - 150 % | |
| % TCMX | 69 | | | | % | 10 | 03/03/26 | SC | 30 - 150 % | |
| % TCMX (Confirmation) | 60 | | | | % | 10 | 03/03/26 | SC | 30 - 150 % | |
| **Volatiles** | | | | | | | | | | |
| 1,1,1,2-Tetrachloroethane | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,1,1-Trichloroethane | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,1,2,2-Tetrachloroethane | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,1,2-Trichloroethane | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,1-Dichloroethane | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,1-Dichloroethene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,1-Dichloropropene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,2,3-Trichlorobenzene | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,2,3-Trichloropropane | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,2,4-Trichlorobenzene | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,2,4-Trimethylbenzene | 0.68 | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,2-Dibromo-3-chloropropane | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,2-Dibromoethane | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,2-Dichlorobenzene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,2-Dichloroethane | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,2-Dichloropropane | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,3,5-Trimethylbenzene | 0.21 | | 0.18 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,3-Dichlorobenzene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,3-Dichloropropane | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 1,4-Dichlorobenzene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 2,2-Dichloropropane | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 2-Chlorotoluene | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 2-Hexanone | ND | | 1.5 | 0.3 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 2-Isopropyltoluene | 0.074 | J | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | 1 |
| 4-Chlorotoluene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| 4-Methyl-2-pentanone | ND | | 1.5 | 0.3 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| Acetone | ND | | 1.5 | 0.3 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| Acrylonitrile | ND | | 0.61 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| Benzene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| Bromobenzene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| Bromochloromethane | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| Bromodichloromethane | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| Bromoform | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| Bromomethane | ND | | 0.3 | 0.12 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| Carbon Disulfide | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| Carbon tetrachloride | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| Chlorobenzene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| Chloroethane | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| Chloroform | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| Chloromethane | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| cis-1,2-Dichloroethene | 0.19 | | 0.18 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |
| cis-1,3-Dichloropropene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D | |

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-1 (7-8.4`)

Phoenix I.D.: CV35319

| Parameter | Result | | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|---|
| Dibromochloromethane | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Dibromomethane | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Dichlorodifluoromethane | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Ethylbenzene | 0.088 | J | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Hexachlorobutadiene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Isopropylbenzene | 0.046 | J | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| m&p-Xylene | 0.35 | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Methyl Ethyl Ketone | ND | | 1.5 | 0.3 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Methyl t-butyl ether (MTBE) | ND | | 0.61 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Methylene chloride | ND | | 0.61 | 0.3 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Naphthalene | 0.65 | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| n-Butylbenzene | 0.31 | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| n-Propylbenzene | 0.12 | J | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| o-Xylene | 0.18 | | 0.12 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| p-Isopropyltoluene | 0.091 | J | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| sec-Butylbenzene | 0.3 | | 0.24 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Styrene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| tert-Butylbenzene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Tetrachloroethene | 0.11 | J | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Tetrahydrofuran (THF) | ND | | 0.61 | 0.15 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Toluene | 0.15 | | 0.12 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Total Xylenes | 0.53 | | 0.12 | 0.12 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| trans-1,2-Dichloroethene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| trans-1,3-Dichloropropene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| trans-1,4-dichloro-2-butene | ND | | 0.61 | 0.15 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Trichloroethene | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Trichlorofluoromethane | ND | | 0.3 | 0.061 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Trichlorotrifluoroethane | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| Vinyl chloride | ND | | 0.3 | 0.03 | mg/Kg | 50 | 03/03/26 | MH | SW8260D |
| **QA/QC Surrogates** | | | | | | | | | |
| % 1,2-dichlorobenzene-d4 (50x) | 101 | | | | % | 50 | 03/03/26 | MH | 70 - 130 % |
| % Bromofluorobenzene (50x) | 111 | | | | % | 50 | 03/03/26 | MH | 70 - 130 % |
| % Dibromofluoromethane (50x) | 94 | | | | % | 50 | 03/03/26 | MH | 70 - 130 % |
| % Toluene-d8 (50x) | 99 | | | | % | 50 | 03/03/26 | MH | 70 - 130 % |
| **Polynuclear Aromatic HC** | | | | | | | | | |
| 2-Methylnaphthalene | 11 | | 1.3 | 0.55 | mg/Kg | 5 | 03/03/26 | KCA | SW8270E |
| Acenaphthene | 0.92 | | 0.26 | 0.11 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |
| Acenaphthylene | 0.31 | | 0.26 | 0.1 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |
| Anthracene | 0.4 | | 0.26 | 0.12 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |
| Benzo(a)anthracene | ND | | 0.26 | 0.12 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |
| Benzo(a)pyrene | ND | | 0.26 | 0.12 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |
| Benzo(b)fluoranthene | ND | | 0.26 | 0.13 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |
| Benzo(ghi)perylene | ND | | 0.26 | 0.12 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |
| Benzo(k)fluoranthene | ND | | 0.26 | 0.12 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |
| Chrysene | ND | | 0.26 | 0.12 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |
| Dibenz(a,h)anthracene | ND | | 0.26 | 0.12 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |
| Fluoranthene | ND | | 0.26 | 0.12 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |
| Fluorene | 1.6 | | 0.26 | 0.12 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |
| Indeno(1,2,3-cd)pyrene | ND | | 0.26 | 0.12 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |

**Ver 1**

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-1 (7-8.4`)

Phoenix I.D.: CV35319

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|
| Naphthalene | 1.4 | 0.26 | 0.11 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |
| Phenanthrene | 3.1 | 0.26 | 0.11 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |
| Pyrene | ND | 0.26 | 0.13 | mg/Kg | 1 | 02/27/26 | KCA | SW8270E |
| **QA/QC Surrogates** | | | | | | | | |
| % 2-Fluorobiphenyl | 77 | | | % | 1 | 02/27/26 | KCA | 30 - 130 % |
| % Nitrobenzene-d5 | 51 | | | % | 1 | 02/27/26 | KCA | 30 - 130 % |
| % Terphenyl-d14 | 70 | | | % | 1 | 02/27/26 | KCA | 30 - 130 % |
| % 2-Fluorobiphenyl (5x) | 75 | | | % | 5 | 03/03/26 | KCA | 30 - 130 % |
| % Nitrobenzene-d5 (5x) | 58 | | | % | 5 | 03/03/26 | KCA | 30 - 130 % |
| % Terphenyl-d14 (5x) | 78 | | | % | 5 | 03/03/26 | KCA | 30 - 130 % |

1 = This parameter is not certified by the primary accrediting authority (NY NELAC) for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quantitation) ND=Not Detected BRL=Below Reporting Level L=Biased Low J=Estimated Below RL LOD=Limit of Detection MDL=Method Detection Limit1
QA/QC Surrogates: Surrogates are compounds (preceeded with a %) added by the lab to determine analysis efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

## Comments:

Volatile Comment:
Elevated reporting limits for volatiles due to the presence of target and/or non-target compounds.

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If you are the client above and have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext.200.
The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.

**Phyllis Shiller, Laboratory Director**

**March 06, 2026**

**Reviewed and Released by: Rashmi Makol, Project Manager**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# Analysis Report

March 06, 2026

FOR: Attn: David Williams
Hygenix Division of Pennoni
350 Fairfiled Ave 4th Floor #404
Bridgeport CT 06604

| Sample Information | | Custody Information | | Date | Time |
|---|---|---|---|---|---|
| Matrix: | SOIL | Collected by: | | 02/19/26 | |
| Location Code: | PENNONI-CT | Received by: | SR1 | 02/20/26 | 16:10 |
| Rush Request: | Standard | Analyzed by: | see "By" below | | |
| P.O.#: | ELKH026001-6 | | | | |

## Laboratory Data

SDG ID: GCV35319
Phoenix ID: CV35320

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-2 (7-8`)

| Parameter | Result | | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|---|---|
| Silver | ND | | 0.47 | 0.47 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Arsenic | 4.72 | | 0.94 | 0.94 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Barium | 182 | | 0.47 | 0.47 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Cadmium | ND | | 0.47 | 0.47 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Chromium | 8.39 | | 0.47 | 0.47 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Copper | 16.1 | | 0.9 | 0.47 | mg/kg | 1 | 02/25/26 | TH | SW6010D | |
| Mercury | ND | | 0.04 | 0.02 | mg/Kg | 1 | 03/03/26 | ZT | SW7471B | |
| Nickel | 10.1 | | 0.47 | 0.47 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Lead | 33.6 | | 0.47 | 0.47 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Selenium | ND | | 1.9 | 1.6 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| TCLP Silver | ND | | 0.10 | 0.010 | mg/L | 1 | 02/24/26 | TH | SW846 1311/6010 | |
| TCLP Arsenic | ND | | 0.10 | 0.040 | mg/L | 1 | 02/24/26 | TH | SW846 1311/6010 | |
| TCLP Barium | 0.29 | | 0.10 | 0.010 | mg/L | 1 | 02/24/26 | TH | SW846 1311/6010 | |
| TCLP Cadmium | ND | | 0.050 | 0.0050 | mg/L | 1 | 02/24/26 | TH | SW846 1311/6010 | |
| TCLP Chromium | ND | | 0.10 | 0.010 | mg/L | 1 | 02/24/26 | TH | SW846 1311/6010 | |
| TCLP Copper | ND | | 0.10 | 0.010 | mg/L | 1 | 02/24/26 | TH | SW846 1311/6010 | |
| TCLP Mercury | ND | | 0.0002 | 0.00015 | mg/L | 1 | 02/25/26 | ZT | SW846 1311/7470 | |
| TCLP Nickel | ND | | 0.10 | 0.010 | mg/L | 1 | 02/24/26 | TH | SW846 1311/6010 | |
| TCLP Lead | 0.01 | J | 0.10 | 0.010 | mg/L | 1 | 02/24/26 | TH | SW846 1311/6010 | |
| TCLP Selenium | ND | | 0.10 | 0.10 | mg/L | 1 | 02/24/26 | TH | SW846 1311/6010D | |
| TCLP Zinc | ND | | 0.10 | 0.011 | mg/L | 1 | 02/24/26 | TH | SW846 1311/6010D | |
| TCLP Metals Digestion | Completed | | | | | | 02/24/26 | AK/GW | SW3010A | |
| Zinc | 48.6 | | 0.9 | 0.47 | mg/Kg | 1 | 02/25/26 | TH | SW6010D | |
| Percent Solid | 73 | | | | % | | 02/20/26 | JRB | SW846-%Solid | |
| Field Extraction | Completed | | | | | | 02/19/26 | | SW5035A | 1 |
| Mercury Digestion | Completed | | | | | | 03/03/26 | ZT/SD | SW7473 | |
| Soil Extraction for PCB | Completed | | | | | | 03/02/26 | H/U | SW3546 | |

**Ver 1**

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-2 (7-8`)

Phoenix I.D.: CV35320

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|
| Soil Extraction for SVOA PAH | Completed | | | | | 02/26/26 | SM/S/Z | SW3546 |
| TCLP Digestion Mercury | Completed | | | | | 02/24/26 | AK/GW | SW7470A |
| TCLP Extraction for Metals | Completed | | | | | 02/20/26 | AK | SW1311 |
| Total Metals Digest | Completed | | | | | 02/24/26 | C/AG | SW3050B |
| **Polychlorinated Biphenyls** | | | | | | | | |
| PCB-1016 | ND | 0.44 | 0.44 | mg/Kg | 10 | 03/03/26 | SC | SW8082A |
| PCB-1221 | ND | 0.44 | 0.44 | mg/Kg | 10 | 03/03/26 | SC | SW8082A |
| PCB-1232 | ND | 0.44 | 0.44 | mg/Kg | 10 | 03/03/26 | SC | SW8082A |
| PCB-1242 | ND | 0.44 | 0.44 | mg/Kg | 10 | 03/03/26 | SC | SW8082A |
| PCB-1248 | ND | 0.44 | 0.44 | mg/Kg | 10 | 03/03/26 | SC | SW8082A |
| PCB-1254 | ND | 0.44 | 0.44 | mg/Kg | 10 | 03/03/26 | SC | SW8082A |
| PCB-1260 | ND | 0.44 | 0.44 | mg/Kg | 10 | 03/03/26 | SC | SW8082A |
| PCB-1262 | ND | 0.44 | 0.44 | mg/Kg | 10 | 03/03/26 | SC | SW8082A |
| PCB-1268 | ND | 0.44 | 0.44 | mg/Kg | 10 | 03/03/26 | SC | SW8082A |
| **QA/QC Surrogates** | | | | | | | | |
| % DCBP | 37 | | | % | 10 | 03/03/26 | SC | 30 - 150 % |
| % DCBP (Confirmation) | 33 | | | % | 10 | 03/03/26 | SC | 30 - 150 % |
| % TCMX | 75 | | | % | 10 | 03/03/26 | SC | 30 - 150 % |
| % TCMX (Confirmation) | 73 | | | % | 10 | 03/03/26 | SC | 30 - 150 % |
| **Volatiles** | | | | | | | | |
| 1,1,1,2-Tetrachloroethane | ND | 0.0068 | 0.0014 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D |
| 1,1,1-Trichloroethane | ND | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D |
| 1,1,2,2-Tetrachloroethane | ND | 0.43 | 0.086 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D |
| 1,1,2-Trichloroethane | ND | 0.0068 | 0.0014 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D |
| 1,1-Dichloroethane | ND | 0.0068 | 0.0014 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D |
| 1,1-Dichloroethene | ND | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D |
| 1,1-Dichloropropene | ND | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D |
| 1,2,3-Trichlorobenzene | ND | 0.43 | 0.086 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D |
| 1,2,3-Trichloropropane | ND | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D |
| 1,2,4-Trichlorobenzene | ND | 0.43 | 0.086 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D |
| 1,2,4-Trimethylbenzene | 0.48 | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D |
| 1,2-Dibromo-3-chloropropane | ND | 0.43 | 0.086 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D |
| 1,2-Dibromoethane | ND | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D |
| 1,2-Dichlorobenzene | ND | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D |
| 1,2-Dichloroethane | ND | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D |
| 1,2-Dichloropropane | ND | 0.0068 | 0.0014 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D |
| 1,3,5-Trimethylbenzene | 0.17 | 0.16 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D |
| 1,3-Dichlorobenzene | ND | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D |
| 1,3-Dichloropropane | ND | 0.0068 | 0.0014 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D |
| 1,4-Dichlorobenzene | ND | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D |
| 2,2-Dichloropropane | ND | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D |
| 2-Chlorotoluene | ND | 0.43 | 0.086 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D |
| 2-Hexanone | ND | 0.034 | 0.0068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D |
| 2-Isopropyltoluene | ND | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D 1 |
| 4-Chlorotoluene | ND | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D |
| 4-Methyl-2-pentanone | ND | 0.034 | 0.0068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D |
| Acetone | ND | 0.034 | 0.0068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D |
| Acrylonitrile | ND | 0.014 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D |

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-2 (7-8`)

Phoenix I.D.: CV35320

| Parameter | Result | | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|---|---|
| Benzene | ND | | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| Bromobenzene | ND | | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| Bromochloromethane | ND | | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Bromodichloromethane | ND | | 0.0068 | 0.0014 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Bromoform | ND | | 0.0068 | 0.0014 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Bromomethane | ND | | 0.0068 | 0.0027 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Carbon Disulfide | ND | | 0.43 | 0.086 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| Carbon tetrachloride | ND | | 0.0068 | 0.0014 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Chlorobenzene | ND | | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Chloroethane | ND | | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Chloroform | ND | | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Chloromethane | ND | | 0.0068 | 0.0014 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| cis-1,2-Dichloroethene | ND | | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| cis-1,3-Dichloropropene | ND | | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Dibromochloromethane | ND | | 0.0068 | 0.0014 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Dibromomethane | ND | | 0.0068 | 0.0014 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Dichlorodifluoromethane | ND | | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Ethylbenzene | 0.077 | J | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| Hexachlorobutadiene | ND | | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| Isopropylbenzene | ND | | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| m&p-Xylene | 0.39 | | 0.34 | 0.086 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| Methyl Ethyl Ketone | ND | | 0.034 | 0.0068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Methyl t-butyl ether (MTBE) | ND | | 0.86 | 0.086 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| Methylene chloride | ND | | 0.014 | 0.0068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Naphthalene | 0.14 | J | 0.43 | 0.086 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| n-Butylbenzene | 0.047 | J | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| n-Propylbenzene | 0.094 | J | 0.43 | 0.086 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| o-Xylene | 0.19 | | 0.17 | 0.086 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| p-Isopropyltoluene | ND | | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| sec-Butylbenzene | ND | | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| Styrene | ND | | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| tert-Butylbenzene | ND | | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| Tetrachloroethene | ND | | 0.43 | 0.086 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| Tetrahydrofuran (THF) | ND | | 0.014 | 0.0034 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Toluene | 0.093 | J | 0.43 | 0.043 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| Total Xylenes | 0.58 | | 0.17 | 0.17 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| trans-1,2-Dichloroethene | ND | | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| trans-1,3-Dichloropropene | ND | | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| trans-1,4-dichloro-2-butene | ND | | 0.86 | 0.22 | mg/Kg | 50 | 03/03/26 | JLI | SW8260D | |
| Trichloroethene | ND | | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Trichlorofluoromethane | ND | | 0.0068 | 0.0014 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Trichlorotrifluoroethane | ND | | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| Vinyl chloride | ND | | 0.0068 | 0.00068 | mg/Kg | 1 | 03/04/26 | JLI | SW8260D | |
| **QA/QC Surrogates** | | | | | | | | | | |
| % 1,2-dichlorobenzene-d4 | 98 | | | | % | 1 | 03/04/26 | JLI | 70 - 130 % | |
| % Bromofluorobenzene | 85 | | | | % | 1 | 03/04/26 | JLI | 70 - 130 % | |
| % Dibromofluoromethane | 104 | | | | % | 1 | 03/04/26 | JLI | 70 - 130 % | |
| % Toluene-d8 | 63 | | | | % | 1 | 03/04/26 | JLI | 70 - 130 % | 3 |
| % 1,2-dichlorobenzene-d4 (50x) | 100 | | | | % | 50 | 03/03/26 | JLI | 70 - 130 % | |

**Ver 1**

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-2 (7-8`)

Phoenix I.D.: CV35320

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|
| % Bromofluorobenzene (50x) | 99 | | | % | 50 | 03/03/26 | JLI | 70 - 130 % |
| % Dibromofluoromethane (50x) | 93 | | | % | 50 | 03/03/26 | JLI | 70 - 130 % |
| % Toluene-d8 (50x) | 98 | | | % | 50 | 03/03/26 | JLI | 70 - 130 % |
| **Polynuclear Aromatic HC** | | | | | | | | |
| 2-Methylnaphthalene | ND | 3.1 | 3.1 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Acenaphthene | ND | 3.1 | 1.4 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Acenaphthylene | ND | 3.1 | 1.3 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Anthracene | ND | 3.1 | 1.5 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Benzo(a)anthracene | ND | 3.1 | 1.5 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Benzo(a)pyrene | ND | 3.1 | 1.5 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Benzo(b)fluoranthene | ND | 3.1 | 1.5 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Benzo(ghi)perylene | ND | 3.1 | 1.5 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Benzo(k)fluoranthene | ND | 3.1 | 1.5 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Chrysene | ND | 3.1 | 1.5 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Dibenz(a,h)anthracene | ND | 3.1 | 1.5 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Fluoranthene | ND | 3.1 | 1.5 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Fluorene | ND | 3.1 | 1.5 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Indeno(1,2,3-cd)pyrene | ND | 3.1 | 1.5 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Naphthalene | ND | 3.1 | 3.1 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Phenanthrene | ND | 3.1 | 1.3 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| Pyrene | ND | 3.1 | 1.5 | mg/Kg | 10 | 03/04/26 | KCA | SW8270E |
| **QA/QC Surrogates** | | | | | | | | |
| % 2-Fluorobiphenyl (10x) | 76 | | | % | 10 | 03/04/26 | KCA | 30 - 130 % |
| % Nitrobenzene-d5 (10x) | 89 | | | % | 10 | 03/04/26 | KCA | 30 - 130 % |
| % Terphenyl-d14 (10x) | 93 | | | % | 10 | 03/04/26 | KCA | 30 - 130 % |

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|

1 = This parameter is not certified by the primary accrediting authority (NY NELAC) for this matrix. NY NELAC does not offer certification for all parameters at this time.
3 = This parameter exceeds laboratory specified limits.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quantitation) ND=Not Detected BRL=Below Reporting Level L=Biased Low J=Estimated Below RL LOD=Limit of Detection MDL=Method Detection Limit1
QA/QC Surrogates: Surrogates are compounds (preceeded with a %) added by the lab to determine analysis efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

## Comments:

Volatile Comment:
Surrogate recoveries as well as internal standard responses were outside control limits for volatiles due to matrix interference.

Volatile Comment:
There was a suppression of the last internal standard in the low level analysis, all affected compounds are reported from the methanol preserved high level analysis which did not exhibit this interference.

Volatile Comment:
Sample exhibited matrix interference in the volatile analysis. Low-level vial was analyzed with one or more poor internal standard responses. The high level analysis did not exhibit this interference. Had any compounds been detected in the high level analysis, they would have been reported at that dilution. The low level analysis was reported, in order to meet the requested reporting criteria.

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If you are the client above and have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext.200.
The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.



**Phyllis Shiller, Laboratory Director**
**March 06, 2026**
**Reviewed and Released by: Rashmi Makol, Project Manager**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# Analysis Report

March 06, 2026

FOR: Attn: David Williams
Hygenix Division of Pennoni
350 Fairfiled Ave 4th Floor #404
Bridgeport CT 06604

| Sample Information | | Custody Information | | Date | Time |
|---|---|---|---|---|---|
| Matrix: | SOIL | Collected by: | | 02/19/26 | |
| Location Code: | PENNONI-CT | Received by: | SR1 | 02/20/26 | 16:10 |
| Rush Request: | Standard | Analyzed by: | see "By" below | | |
| P.O.#: | ELKH026001-6 | | | | |

## Laboratory Data

SDG ID: GCV35319
Phoenix ID: CV35321

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-3 (1-1.5`)

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|---|
| Percent Solid | 77 | | | % | | 02/20/26 | JRB | SW846-%Solid | |
| Field Extraction | Completed | | | | | 02/19/26 | | SW5035A | 1 |
| **Volatiles** | | | | | | | | | |
| 1,1,1,2-Tetrachloroethane | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,1,1-Trichloroethane | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,1,2,2-Tetrachloroethane | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,1,2-Trichloroethane | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,1-Dichloroethane | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,1-Dichloroethene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,1-Dichloropropene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2,3-Trichlorobenzene | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2,3-Trichloropropane | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2,4-Trichlorobenzene | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2,4-Trimethylbenzene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2-Dibromo-3-chloropropane | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2-Dibromoethane | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2-Dichlorobenzene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2-Dichloroethane | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2-Dichloropropane | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,3,5-Trimethylbenzene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,3-Dichlorobenzene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,3-Dichloropropane | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,4-Dichlorobenzene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 2,2-Dichloropropane | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 2-Chlorotoluene | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 2-Hexanone | ND | 0.028 | 0.0055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-3 (1-1.5`)

Phoenix I.D.: CV35321

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|---|
| 2-Isopropyltoluene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | 1 |
| 4-Chlorotoluene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 4-Methyl-2-pentanone | ND | 0.028 | 0.0055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Acetone | ND | 0.028 | 0.0055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Acrylonitrile | ND | 0.011 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Benzene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Bromobenzene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Bromochloromethane | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Bromodichloromethane | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Bromoform | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Bromomethane | ND | 0.0055 | 0.0022 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Carbon Disulfide | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Carbon tetrachloride | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Chlorobenzene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Chloroethane | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Chloroform | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Chloromethane | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| cis-1,2-Dichloroethene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| cis-1,3-Dichloropropene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Dibromochloromethane | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Dibromomethane | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Dichlorodifluoromethane | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Ethylbenzene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Hexachlorobutadiene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Isopropylbenzene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| m&p-Xylene | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Methyl Ethyl Ketone | ND | 0.028 | 0.0055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Methyl t-butyl ether (MTBE) | ND | 0.011 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Methylene chloride | ND | 0.011 | 0.0055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Naphthalene | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| n-Butylbenzene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| n-Propylbenzene | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| o-Xylene | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| p-Isopropyltoluene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| sec-Butylbenzene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Styrene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| tert-Butylbenzene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Tetrachloroethene | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Tetrahydrofuran (THF) | ND | 0.011 | 0.0028 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Toluene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Total Xylenes | ND | 0.0055 | 0.0055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| trans-1,2-Dichloroethene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| trans-1,3-Dichloropropene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| trans-1,4-dichloro-2-butene | ND | 0.011 | 0.0028 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Trichloroethene | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Trichlorofluoromethane | ND | 0.0055 | 0.0011 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Trichlorotrifluoroethane | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Vinyl chloride | ND | 0.0055 | 0.00055 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |

**QA/QC Surrogates**

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-3 (1-1.5`)

Phoenix I.D.: CV35321

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|
| % 1,2-dichlorobenzene-d4 | 99 | | | % | 1 | 03/01/26 | JLI | 70 - 130 % |
| % Bromofluorobenzene | 91 | | | % | 1 | 03/01/26 | JLI | 70 - 130 % |
| % Dibromofluoromethane | 95 | | | % | 1 | 03/01/26 | JLI | 70 - 130 % |
| % Toluene-d8 | 96 | | | % | 1 | 03/01/26 | JLI | 70 - 130 % |

1 = This parameter is not certified by the primary accrediting authority (NY NELAC) for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quantitation) ND=Not Detected BRL=Below Reporting Level L=Biased Low LOD=Limit of Detection MDL=Method Detection Limit1
QA/QC Surrogates: Surrogates are compounds (preceeded with a %) added by the lab to determine analysis efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

## Comments:

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If you are the client above and have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext.200.
The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.

**Phyllis Shiller, Laboratory Director**
**March 06, 2026**
**Reviewed and Released by: Rashmi Makol, Project Manager**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# Analysis Report

March 06, 2026

FOR: Attn: David Williams
Hygenix Division of Pennoni
350 Fairfiled Ave 4th Floor #404
Bridgeport CT 06604

| Sample Information | | Custody Information | | Date | Time |
|---|---|---|---|---|---|
| Matrix: | SOIL | Collected by: | | 02/19/26 | |
| Location Code: | PENNONI-CT | Received by: | SR1 | 02/20/26 | 16:10 |
| Rush Request: | Standard | Analyzed by: | see "By" below | | |
| P.O.#: | ELKH026001-6 | | | | |

## Laboratory Data

SDG ID: GCV35319
Phoenix ID: CV35322

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-4 (0.5-1.5`)

| Parameter | Result | | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|---|
| Percent Solid | 91 | | | | % | | 02/20/26 | JRB | SW846-%Solid |
| Soil Extraction for SVOA PAH | Completed | | | | | | 02/26/26 | SM/S/Z | SW3546 |
| **Polynuclear Aromatic HC** | | | | | | | | | |
| 2-Methylnaphthalene | ND | | 0.32 | 0.13 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Acenaphthene | ND | | 0.32 | 0.14 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Acenaphthylene | ND | | 0.32 | 0.13 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Anthracene | ND | | 0.32 | 0.15 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Benzo(a)anthracene | ND | | 0.32 | 0.15 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Benzo(a)pyrene | ND | | 0.32 | 0.15 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Benzo(b)fluoranthene | ND | | 0.32 | 0.15 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Benzo(ghi)perylene | ND | | 0.32 | 0.15 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Benzo(k)fluoranthene | ND | | 0.32 | 0.15 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Chrysene | 0.17 | J | 0.32 | 0.15 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Dibenz(a,h)anthracene | ND | | 0.32 | 0.15 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Fluoranthene | ND | | 0.32 | 0.15 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Fluorene | ND | | 0.32 | 0.15 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Indeno(1,2,3-cd)pyrene | ND | | 0.32 | 0.15 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Naphthalene | ND | | 0.32 | 0.13 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Phenanthrene | ND | | 0.32 | 0.13 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| Pyrene | ND | | 0.32 | 0.15 | mg/Kg | 1 | 02/27/26 | AW | SW8270E |
| **QA/QC Surrogates** | | | | | | | | | |
| % 2-Fluorobiphenyl | 64 | | | | % | 1 | 02/27/26 | AW | 30 - 130 % |
| % Nitrobenzene-d5 | 62 | | | | % | 1 | 02/27/26 | AW | 30 - 130 % |
| % Terphenyl-d14 | 56 | | | | % | 1 | 02/27/26 | AW | 30 - 130 % |

**Ver 1**

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-4 (0.5-1.5`)

Phoenix I.D.: CV35322

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quantitation) ND=Not Detected BRL=Below Reporting Level L=Biased Low J=Estimated Below RL LOD=Limit of Detection MDL=Method Detection Limit1
QA/QC Surrogates: Surrogates are compounds (preceeded with a %) added by the lab to determine analysis efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

## Comments:

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If you are the client above and have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext.200.
The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.



**Phyllis Shiller, Laboratory Director**

**March 06, 2026**

**Reviewed and Released by: Rashmi Makol, Project Manager**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

NY # 11301

# Analysis Report

March 06, 2026

FOR: Attn: David Williams
Hygenix Division of Pennoni
350 Fairfiled Ave 4th Floor #404
Bridgeport CT 06604

| Sample Information | | Custody Information | | Date | Time |
|---|---|---|---|---|---|
| Matrix: | SOIL | Collected by: | | 02/19/26 | |
| Location Code: | PENNONI-CT | Received by: | SR1 | 02/20/26 | 16:10 |
| Rush Request: | Standard | Analyzed by: | see "By" below | | |
| P.O.#: | ELKH026001-6 | | | | |

## Laboratory Data

SDG ID: GCV35319
Phoenix ID: CV35323

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-4 (2.5-5`)

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|
| Silver | ND | 0.43 | 0.43 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Arsenic | 1.69 | 0.85 | 0.85 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Barium | 112 | 0.43 | 0.43 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Cadmium | ND | 0.43 | 0.43 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Chromium | 52.7 | 0.43 | 0.43 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Copper | 48.4 | 0.9 | 0.43 | mg/kg | 1 | 02/25/26 | TH | SW6010D |
| Mercury | 0.03 | 0.03 | 0.02 | mg/Kg | 1 | 03/03/26 | ZT | SW7471B |
| Nickel | 29.7 | 0.43 | 0.43 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Lead | 12.0 | 0.43 | 0.43 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Selenium | ND | 1.7 | 1.5 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Zinc | 77.5 | 0.9 | 0.43 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Percent Solid | 77 | | | % | | 02/20/26 | JRB | SW846-%Solid |
| Mercury Digestion | Completed | | | | | 03/03/26 | ZT/SD | SW7473 |
| Total Metals Digest | Completed | | | | | 02/24/26 | C/AG | SW3050B |

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-4 (2.5-5`)

Phoenix I.D.: CV35323

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quantitation) ND=Not Detected BRL=Below Reporting Level L=Biased Low LOD=Limit of Detection MDL=Method Detection Limit1

## Comments:

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If you are the client above and have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext.200.
The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.



**Phyllis Shiller, Laboratory Director**

**March 06, 2026**

**Reviewed and Released by: Rashmi Makol, Project Manager**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# Analysis Report

March 06, 2026

FOR: Attn: David Williams
Hygenix Division of Pennoni
350 Fairfiled Ave 4th Floor #404
Bridgeport CT 06604

| Sample Information | | Custody Information | | Date | Time |
|---|---|---|---|---|---|
| Matrix: | SOIL | Collected by: | | 02/19/26 | |
| Location Code: | PENNONI-CT | Received by: | SR1 | 02/20/26 | 16:10 |
| Rush Request: | Standard | Analyzed by: | see "By" below | | |
| P.O.#: | ELKH026001-6 | | | | |

## Laboratory Data

SDG ID: GCV35319
Phoenix ID: CV35324

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-4 (5-6.8`)

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|---|
| Percent Solid | 87 | | | % | | 02/20/26 | JRB | SW846-%Solid | |
| Field Extraction | Completed | | | | | 02/19/26 | | SW5035A | 1 |
| **Volatiles** | | | | | | | | | |
| 1,1,1,2-Tetrachloroethane | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,1,1-Trichloroethane | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,1,2,2-Tetrachloroethane | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,1,2-Trichloroethane | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,1-Dichloroethane | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,1-Dichloroethene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,1-Dichloropropene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2,3-Trichlorobenzene | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2,3-Trichloropropane | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2,4-Trichlorobenzene | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2,4-Trimethylbenzene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2-Dibromo-3-chloropropane | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2-Dibromoethane | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2-Dichlorobenzene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2-Dichloroethane | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,2-Dichloropropane | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,3,5-Trimethylbenzene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,3-Dichlorobenzene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,3-Dichloropropane | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 1,4-Dichlorobenzene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 2,2-Dichloropropane | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 2-Chlorotoluene | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 2-Hexanone | ND | 0.018 | 0.0035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-4 (5-6.8`)

Phoenix I.D.: CV35324

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|---|
| 2-Isopropyltoluene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | 1 |
| 4-Chlorotoluene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| 4-Methyl-2-pentanone | ND | 0.018 | 0.0035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Acetone | 0.021 | S 0.018 | 0.0035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Acrylonitrile | ND | 0.007 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Benzene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Bromobenzene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Bromochloromethane | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Bromodichloromethane | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Bromoform | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Bromomethane | ND | 0.0035 | 0.0014 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Carbon Disulfide | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Carbon tetrachloride | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Chlorobenzene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Chloroethane | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Chloroform | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Chloromethane | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| cis-1,2-Dichloroethene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| cis-1,3-Dichloropropene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Dibromochloromethane | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Dibromomethane | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Dichlorodifluoromethane | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Ethylbenzene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Hexachlorobutadiene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Isopropylbenzene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| m&p-Xylene | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Methyl Ethyl Ketone | ND | 0.018 | 0.0035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Methyl t-butyl ether (MTBE) | ND | 0.007 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Methylene chloride | ND | 0.007 | 0.0035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Naphthalene | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| n-Butylbenzene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| n-Propylbenzene | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| o-Xylene | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| p-Isopropyltoluene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| sec-Butylbenzene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Styrene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| tert-Butylbenzene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Tetrachloroethene | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Tetrahydrofuran (THF) | ND | 0.007 | 0.0018 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Toluene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Total Xylenes | ND | 0.0035 | 0.0035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| trans-1,2-Dichloroethene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| trans-1,3-Dichloropropene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| trans-1,4-dichloro-2-butene | ND | 0.007 | 0.0018 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Trichloroethene | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Trichlorofluoromethane | ND | 0.0035 | 0.0007 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Trichlorotrifluoroethane | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |
| Vinyl chloride | ND | 0.0035 | 0.00035 | mg/Kg | 1 | 03/01/26 | JLI | SW8260D | |

**QA/QC Surrogates**

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: AB-4 (5-6.8`)

Phoenix I.D.: CV35324

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|
| % 1,2-dichlorobenzene-d4 | 100 | | | % | 1 | 03/01/26 | JLI | 70 - 130 % |
| % Bromofluorobenzene | 95 | | | % | 1 | 03/01/26 | JLI | 70 - 130 % |
| % Dibromofluoromethane | 96 | | | % | 1 | 03/01/26 | JLI | 70 - 130 % |
| % Toluene-d8 | 97 | | | % | 1 | 03/01/26 | JLI | 70 - 130 % |

1 = This parameter is not certified by the primary accrediting authority (NY NELAC) for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quantitation) ND=Not Detected BRL=Below Reporting Level L=Biased Low LOD=Limit of Detection MDL=Method Detection Limit1
QA/QC Surrogates: Surrogates are compounds (preceeded with a %) added by the lab to determine analysis efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

## Comments:

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

S - Laboratory solvent, contamination is possible.

If you are the client above and have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext.200.
The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.

**Phyllis Shiller, Laboratory Director**
**March 06, 2026**
**Reviewed and Released by: Rashmi Makol, Project Manager**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# QA/QC Report

March 06, 2026

## QA/QC Data

SDG I.D.: GCV35319

| Parameter | Blank | Blk RL | Sample Result | Dup Result | Dup RPD | LCS % | LCSD % | LCS RPD | MS % | MSD % | MS RPD | % Rec Limits | % RPD Limits | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| QA/QC Batch 827818 (mg/L), QC Sample No: CV35652 (CV35320) | | | | | | | | | | | | | | |
| Mercury - Water | BRL | 0.0002 | <0.0002 | <0.0002 | NC | 97.3 | | | 97.6 | | | 75 - 125 | 20 | |
| QA/QC Batch 827924 (mg/kg), QC Sample No: CV34747 (CV35319, CV35320, CV35323) | | | | | | | | | | | | | | |
| ICP Metals - Soil | | | | | | | | | | | | | | |
| Arsenic | BRL | 0.67 | 5.83 | 2.59 | NC | 93.6 | 93.6 | 0.0 | 96.5 | | | 80 - 120 | 30 | |
| Barium | BRL | 0.33 | 200 | 145 | 31.9 | 96.6 | 90.7 | 6.3 | 115 | | | 80 - 120 | 30 | r |
| Cadmium | BRL | 0.33 | 1.47 | 0.68 | NC | 89.4 | 93.7 | 4.7 | 96.6 | | | 80 - 120 | 30 | |
| Chromium | BRL | 0.33 | 48.6 | 39.9 | 19.7 | 93.3 | 95.2 | 2.0 | 104 | | | 80 - 120 | 30 | |
| Copper | BRL | 0.67 | 46.6 | 28.0 | 49.9 | 96.1 | 96.8 | 0.7 | 99.0 | | | 80 - 120 | 30 | r |
| Lead | BRL | 0.33 | 31.3 | 13.1 | 82.0 | 95.0 | 94.2 | 0.8 | 98.3 | | | 80 - 120 | 30 | r |
| Nickel | BRL | 0.33 | 25.0 | 22.1 | 12.3 | 93.2 | 93.5 | 0.3 | 101 | | | 80 - 120 | 30 | |
| Selenium | BRL | 1.3 | <1.7 | <1.5 | NC | 90.7 | 88.0 | 3.0 | 83.6 | | | 80 - 120 | 30 | |
| Silver | BRL | 0.33 | <0.42 | <0.38 | NC | 98.8 | 99.8 | 1.0 | 103 | | | 70 - 130 | 30 | |
| Zinc | BRL | 0.67 | 63.7 | 45.8 | 32.7 | 90.8 | 91.6 | 0.9 | 99.0 | | | 80 - 120 | 30 | r |
| QA/QC Batch 827821 (mg/L), QC Sample No: CV35807 (CV35320) | | | | | | | | | | | | | | |
| ICP Metals - TCLP Extraction | | | | | | | | | | | | | | |
| Arsenic | BRL | 0.01 | <0.01 | <0.01 | NC | 108 | 108 | 0.0 | 108 | | | 80 - 120 | 20 | |
| Barium | BRL | 0.01 | 0.80 | 0.78 | 2.50 | 103 | 104 | 1.0 | 101 | | | 80 - 120 | 20 | |
| Cadmium | BRL | 0.005 | <0.005 | <0.005 | NC | 103 | 103 | 0.0 | 102 | | | 80 - 120 | 20 | |
| Chromium | BRL | 0.010 | <0.010 | <0.010 | NC | 104 | 104 | 0.0 | 103 | | | 80 - 120 | 20 | |
| Copper | BRL | 0.010 | <0.010 | <0.010 | NC | 108 | 108 | 0.0 | 110 | | | 80 - 120 | 20 | |
| Lead | BRL | 0.010 | 0.352 | 0.347 | 1.40 | 102 | 102 | 0.0 | 103 | | | 80 - 120 | 20 | |
| Nickel | BRL | 0.010 | 0.046 | 0.045 | NC | 100 | 100 | 0.0 | 99.2 | | | 80 - 120 | 20 | |
| Selenium | BRL | 0.05 | <0.05 | <0.05 | NC | 112 | 112 | 0.0 | 110 | | | 80 - 120 | 20 | |
| Silver | BRL | 0.010 | <0.010 | <0.010 | NC | 107 | 107 | 0.0 | 109 | | | 70 - 130 | 30 | |
| Zinc | BRL | 0.010 | 0.757 | 0.725 | 4.30 | 104 | 104 | 0.0 | 102 | | | 80 - 120 | 20 | |

r = This parameter is outside laboratory RPD specified recovery limits.

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# QA/QC Report

March 06, 2026

## QA/QC Data

SDG I.D.: GCV35319

| Parameter | Blank | Blk RL | LCS % | LCSD % | LCS RPD | MS % | MSD % | MS RPD | % Rec Limits | % RPD Limits | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| QA/QC Batch 828457H (mg/Kg), QC Sample No: CV33251 50X (CV35319 (50X) , CV35320 (50X) ) | | | | | | | | | | | |
| **Volatiles - Soil (High Level)** | | | | | | | | | | | |
| 1,1,1,2-Tetrachloroethane | ND | 0.25 | 97 | 102 | 5.0 | 100 | 101 | 1.0 | 70 - 130 | 30 | |
| 1,1,1-Trichloroethane | ND | 0.25 | 88 | 94 | 6.6 | 95 | 91 | 4.3 | 70 - 130 | 30 | |
| 1,1,2,2-Tetrachloroethane | ND | 0.25 | 91 | 95 | 4.3 | 97 | 94 | 3.1 | 70 - 130 | 30 | |
| 1,1,2-Trichloroethane | ND | 0.25 | 94 | 99 | 5.2 | 102 | 101 | 1.0 | 70 - 130 | 30 | |
| 1,1-Dichloroethane | ND | 0.25 | 87 | 92 | 5.6 | 93 | 90 | 3.3 | 70 - 130 | 30 | |
| 1,1-Dichloroethene | ND | 0.25 | 70 | 74 | 5.6 | 94 | 90 | 4.3 | 70 - 130 | 30 | |
| 1,1-Dichloropropene | ND | 0.25 | 90 | 96 | 6.5 | 95 | 91 | 4.3 | 70 - 130 | 30 | |
| 1,2,3-Trichlorobenzene | ND | 0.25 | 102 | 108 | 5.7 | 93 | 88 | 5.5 | 70 - 130 | 30 | |
| 1,2,3-Trichloropropane | ND | 0.25 | 87 | 92 | 5.6 | 99 | 96 | 3.1 | 70 - 130 | 30 | |
| 1,2,4-Trichlorobenzene | ND | 0.25 | 108 | 113 | 4.5 | 90 | 82 | 9.3 | 70 - 130 | 30 | |
| 1,2,4-Trimethylbenzene | ND | 0.25 | 96 | 103 | 7.0 | 96 | 92 | 4.3 | 70 - 130 | 30 | |
| 1,2-Dibromo-3-chloropropane | ND | 0.25 | 90 | 95 | 5.4 | 102 | 98 | 4.0 | 70 - 130 | 30 | |
| 1,2-Dibromoethane | ND | 0.25 | 93 | 96 | 3.2 | 101 | 100 | 1.0 | 70 - 130 | 30 | |
| 1,2-Dichlorobenzene | ND | 0.25 | 97 | 102 | 5.0 | 94 | 92 | 2.2 | 70 - 130 | 30 | |
| 1,2-Dichloroethane | ND | 0.25 | 86 | 90 | 4.5 | 91 | 91 | 0.0 | 70 - 130 | 30 | |
| 1,2-Dichloropropane | ND | 0.25 | 95 | 100 | 5.1 | 100 | 100 | 0.0 | 70 - 130 | 30 | |
| 1,3,5-Trimethylbenzene | ND | 0.25 | 96 | 102 | 6.1 | 99 | 94 | 5.2 | 70 - 130 | 30 | |
| 1,3-Dichlorobenzene | ND | 0.25 | 99 | 105 | 5.9 | 94 | 89 | 5.5 | 70 - 130 | 30 | |
| 1,3-Dichloropropane | ND | 0.25 | 94 | 98 | 4.2 | 101 | 100 | 1.0 | 70 - 130 | 30 | |
| 1,4-Dichlorobenzene | ND | 0.25 | 97 | 103 | 6.0 | 92 | 87 | 5.6 | 70 - 130 | 30 | |
| 2,2-Dichloropropane | ND | 0.25 | 89 | 91 | 2.2 | 92 | 86 | 6.7 | 70 - 130 | 30 | |
| 2-Chlorotoluene | ND | 0.25 | 94 | 102 | 8.2 | 99 | 95 | 4.1 | 70 - 130 | 30 | |
| 2-Hexanone | ND | 1.3 | 77 | 79 | 2.6 | 90 | 85 | 5.7 | 70 - 130 | 30 | |
| 2-Isopropyltoluene | ND | 0.25 | 96 | 103 | 7.0 | 100 | 97 | 3.0 | 70 - 130 | 30 | |
| 4-Chlorotoluene | ND | 0.25 | 95 | 101 | 6.1 | 94 | 90 | 4.3 | 70 - 130 | 30 | |
| 4-Methyl-2-pentanone | ND | 1.3 | 82 | 84 | 2.4 | 94 | 91 | 3.2 | 70 - 130 | 30 | |
| Acetone | ND | 0.5 | 49 | 49 | 0.0 | 75 | 72 | 4.1 | 70 - 130 | 30 | I |
| Acrylonitrile | ND | 0.25 | 75 | 79 | 5.2 | 88 | 84 | 4.7 | 70 - 130 | 30 | |
| Benzene | ND | 0.25 | 95 | 101 | 6.1 | 100 | 99 | 1.0 | 70 - 130 | 30 | |
| Bromobenzene | ND | 0.25 | 95 | 101 | 6.1 | 99 | 97 | 2.0 | 70 - 130 | 30 | |
| Bromochloromethane | ND | 0.25 | 93 | 96 | 3.2 | 99 | 98 | 1.0 | 70 - 130 | 30 | |
| Bromodichloromethane | ND | 0.25 | 92 | 96 | 4.3 | 95 | 96 | 1.0 | 70 - 130 | 30 | |
| Bromoform | ND | 0.25 | 93 | 95 | 2.1 | 97 | 98 | 1.0 | 70 - 130 | 30 | |
| Bromomethane | ND | 0.25 | 65 | 69 | 6.0 | 86 | 84 | 2.4 | 70 - 130 | 30 | I |
| Carbon Disulfide | ND | 0.25 | 71 | 76 | 6.8 | 91 | 87 | 4.5 | 70 - 130 | 30 | |
| Carbon tetrachloride | ND | 0.25 | 88 | 90 | 2.2 | 92 | 90 | 2.2 | 70 - 130 | 30 | |
| Chlorobenzene | ND | 0.25 | 96 | 102 | 6.1 | 98 | 96 | 2.1 | 70 - 130 | 30 | |
| Chloroethane | ND | 0.25 | 22 | 24 | 8.7 | 99 | 94 | 5.2 | 70 - 130 | 30 | I |
| Chloroform | ND | 0.25 | 90 | 94 | 4.3 | 95 | 92 | 3.2 | 70 - 130 | 30 | |
| Chloromethane | ND | 0.25 | 91 | 93 | 2.2 | 95 | 90 | 5.4 | 70 - 130 | 30 | |
| cis-1,2-Dichloroethene | ND | 0.25 | 94 | 98 | 4.2 | 101 | 100 | 1.0 | 70 - 130 | 30 | |

# QA/QC Data

SDG I.D.: GCV35319

| Parameter | Blank | Blk RL | LCS % | LCSD % | LCS RPD | MS % | MSD % | MS RPD | % Rec Limits | % RPD Limits | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| cis-1,3-Dichloropropene | ND | 0.25 | 96 | 101 | 5.1 | 98 | 100 | 2.0 | 70 - 130 | 30 | |
| Dibromochloromethane | ND | 0.15 | 89 | 93 | 4.4 | 94 | 95 | 1.1 | 70 - 130 | 30 | |
| Dibromomethane | ND | 0.25 | 91 | 95 | 4.3 | 96 | 96 | 0.0 | 70 - 130 | 30 | |
| Dichlorodifluoromethane | ND | 0.25 | 88 | 90 | 2.2 | 89 | 84 | 5.8 | 70 - 130 | 30 | |
| Ethylbenzene | ND | 0.25 | 98 | 103 | 5.0 | 100 | 97 | 3.0 | 70 - 130 | 30 | |
| Hexachlorobutadiene | ND | 0.25 | 102 | 109 | 6.6 | 100 | 94 | 6.2 | 70 - 130 | 30 | |
| Isopropylbenzene | ND | 0.25 | 92 | 100 | 8.3 | 101 | 96 | 5.1 | 70 - 130 | 30 | |
| m&p-Xylene | ND | 0.25 | 99 | 104 | 4.9 | 99 | 97 | 2.0 | 70 - 130 | 30 | |
| Methyl ethyl ketone | ND | 0.25 | 67 | 70 | 4.4 | 84 | 79 | 6.1 | 70 - 130 | 30 | I |
| Methyl t-butyl ether (MTBE) | ND | 0.25 | 84 | 87 | 3.5 | 90 | 89 | 1.1 | 70 - 130 | 30 | |
| Methylene chloride | ND | 0.25 | 76 | 80 | 5.1 | 82 | 80 | 2.5 | 70 - 130 | 30 | |
| Naphthalene | ND | 0.25 | 92 | 97 | 5.3 | 98 | 94 | 4.2 | 70 - 130 | 30 | |
| n-Butylbenzene | ND | 0.25 | 99 | 107 | 7.8 | 96 | 87 | 9.8 | 70 - 130 | 30 | |
| n-Propylbenzene | ND | 0.25 | 94 | 101 | 7.2 | 98 | 92 | 6.3 | 70 - 130 | 30 | |
| o-Xylene | ND | 0.25 | 96 | 101 | 5.1 | 98 | 96 | 2.1 | 70 - 130 | 30 | |
| p-Isopropyltoluene | ND | 0.25 | 97 | 104 | 7.0 | 99 | 92 | 7.3 | 70 - 130 | 30 | |
| sec-Butylbenzene | ND | 0.25 | 94 | 100 | 6.2 | 98 | 93 | 5.2 | 70 - 130 | 30 | |
| Styrene | ND | 0.25 | 99 | 104 | 4.9 | 98 | 97 | 1.0 | 70 - 130 | 30 | |
| tert-Butylbenzene | ND | 0.25 | 92 | 100 | 8.3 | 100 | 97 | 3.0 | 70 - 130 | 30 | |
| Tetrachloroethene | ND | 0.25 | 99 | 104 | 4.9 | 99 | 97 | 2.0 | 70 - 130 | 30 | |
| Tetrahydrofuran (THF) | ND | 0.25 | 77 | 79 | 2.6 | 90 | 86 | 4.5 | 70 - 130 | 30 | |
| Toluene | ND | 0.25 | 96 | 101 | 5.1 | 100 | 98 | 2.0 | 70 - 130 | 30 | |
| trans-1,2-Dichloroethene | ND | 0.25 | 87 | 91 | 4.5 | 92 | 88 | 4.4 | 70 - 130 | 30 | |
| trans-1,3-Dichloropropene | ND | 0.25 | 95 | 100 | 5.1 | 98 | 98 | 0.0 | 70 - 130 | 30 | |
| trans-1,4-dichloro-2-butene | ND | 0.25 | 88 | 92 | 4.4 | 91 | 88 | 3.4 | 70 - 130 | 30 | |
| Trichloroethene | ND | 0.25 | 96 | 101 | 5.1 | 102 | 100 | 2.0 | 70 - 130 | 30 | |
| Trichlorofluoromethane | ND | 0.25 | 31 | 34 | 9.2 | 93 | 89 | 4.4 | 70 - 130 | 30 | I |
| Trichlorotrifluoroethane | ND | 0.25 | 78 | 83 | 6.2 | 104 | 100 | 3.9 | 70 - 130 | 30 | |
| Vinyl chloride | ND | 0.25 | 85 | 90 | 5.7 | 96 | 92 | 4.3 | 70 - 130 | 30 | |
| % 1,2-dichlorobenzene-d4 | 100 | % | 102 | 101 | 1.0 | 100 | 100 | 0.0 | 70 - 130 | 30 | |
| % Bromofluorobenzene | 99 | % | 101 | 99 | 2.0 | 98 | 99 | 1.0 | 70 - 130 | 30 | |
| % Dibromofluoromethane | 94 | % | 97 | 97 | 0.0 | 100 | 97 | 3.0 | 70 - 130 | 30 | |
| % Toluene-d8 | 99 | % | 100 | 100 | 0.0 | 99 | 100 | 1.0 | 70 - 130 | 30 | |

I = This parameter is outside laboratory LCS/LCSD specified recovery limits.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

RPD - Relative Percent Difference
LCS - Laboratory Control Sample
LCSD - Laboratory Control Sample Duplicate
MS - Matrix Spike
MS Dup - Matrix Spike Duplicate
NC - No Criteria
Intf - Interference
(ISO) - Isotope Dilution

Phyllis Shiller, Laboratory Director
March 06, 2026

Friday, March 06, 2026

Criteria: None

State: NY

# Sample Criteria Exceedances Report

## GCV35319 - PENNONI-CT

| SampNo | Acode | Phoenix Analyte | Criteria | Result | RL | Criteria | RL Criteria | Analysis Units |
|---|---|---|---|---|---|---|---|---|

*** No Data to Display ***

Phoenix Laboratories does not assume responsibility for the data contained in this exceedance report. It is provided as an additional tool to identify requested criteria exceedences. All efforts are made to ensure the accuracy of the data (obtained from appropriate agencies). A lack of exceedence information does not necessarily suggest conformance to the criteria. It is ultimately the site professional's responsibility to determine appropriate compliance.

**Environmental Laboratories, Inc.**
**587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045**
**Tel. (860) 645-1102 Fax (860) 645-0823**

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# NY Temperature Narration

**March 06, 2026**

**SDG I.D.: GCV35319**

The samples in this delivery group were received at 2.2°C.
(Note acceptance criteria for relevant matrices is above freezing up to 6°C)

Cooler: Yes ☒ No ☐
Coolant: IPK ☒ ICE ☐ No ☐

# PHOENIX
*Environmental Laboratories, Inc.*

NY ~~CT/MA/RI~~ **CHAIN OF CUSTODY RECORD**

Temp 1.2 °C Pg 1 of 1

587 East Middle Turnpike, P.O. Box 370, Manchester, CT 06040
Email: makrina@phoenixlabs.com Fax (860) 645-0823
**Client Services (860) 645-1102**

**Data Delivery/Contact Options:**
☐ Fax: _____
☐ Phone: _____
☒ Email: DaWilliams@pennoni.com

Customer: Pennoni
Address: 350 Fairfield Ave - Suite 404
Bridgeport, CT

Project: 1 Vine St, Larchmont, NY
Report to: Dave Williams
Invoice to: jmorie@pennoni.com
Quote #

**Project P.O:** E/KH026001-6

***This section MUST be completed with Bottle Quantities.***

Sampler's Signature: _____ Date: 2/19/2026

**Client Sample - Information - Identification**

**Matrix Code:**
**DW**=Drinking Water **GW**=Ground Water **SW**=Surface Water **WW**=Waste Water
**RW**=Raw Water **SE**=Sediment **SL**=Sludge **S**=Soil **SD**=Solid **W**=Wipe **OIL**=Oil
**B**=Bulk **L**=Liquid **X** = _____(Other)

| PHOENIX USE ONLY SAMPLE # | Customer Sample Identification | Sample Matrix | Date Sampled | Time Sampled | *MS/MSD (May be billable at analysis unit rate) | SVOC-PAH | PCB | RCRA 8 Metals | VOC 8260/5035 | Copper/Nickel/Zinc | TCLP 8 RCRA Cr/Ni/Zn | GL Amber 8 oz. [ ] w/$H_3PO_4$ [ ] $NAHSO_4$ | Soil VOA Vials ☒ methanol ☒ $H_2O$ | GL Soil container ( 8 ) oz | GL Soil container ( ) oz | 40 ml VOA Vial [ ] As is [ ] HCl | GL Amber 1000ml [ ] As is [ ] $H_2SO_4$ | PL As is [ ] 250ml [ ] 500ml [ ] 1000ml | PL $H_2SO_4$ [ ] 250ml [ ] 500ml [ ] 1000ml | PL $HNO_3$ 250ml | PL NaOH 250ml | Bacteria Bottle w/thio | Bacteria Bottle as is |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 35319 | AB-1 (7-8.4') | S | 19 Feb | | | X | X | X | X | X | | | | | 3 | 1 | | | | | | | | |
| 35320 | AB-2 (7-8') | S | 19 Feb | | | X | X | X | X | X | X | | | | 3 | 1 | | | | | | | | |
| 35321 | AB-3 (1-1.5') | S | 19 Feb | | | | | | X | | | | | | 3 | 1 | | | | | | | | |
| 35322 | AB-4 (0.5-1.5') | S | 19 Feb | | | X | | | | | | | | | | 1 | | | | | | | | |
| 35323 | AB-4 (2.5-5') | S | 19 Feb | | | | | X | | X | | | | | | 1 | | | | | | | | |
| 35324 | AB-4 (5-6.8') | S | 19 Feb | | | | | | X | | | | | | 3 | 1 | | | | | | | | |

| Relinquished by: | Accepted by: | Date: | Time: |
|---|---|---|---|
| Jacquic | Jacquic | 2/20/26 | 11:54 |
| | | 2/20/26 | 11:10 |

**Comments, Special Requirements or Regulations:**

**Turnaround Time:**
☐ 1 Day* ☒ Standard
☐ 2 Days* ☐ Other _____
☐ 3 Days*
☐ 4 Days*
☐ 5 Days*

***MS/MSD are considered site samples and will be billed as such in accordance with the prices quoted.**

* SURCHARGES MAY APPLY

**RI**
☐ RES DEC
☐ I/C DEC
☐ GA Leachability
☐ GB Leachability
☐ GA -GW Objectives
☐ GB -GW Objectives
☐ Other

**CT**
☐ RCP Cert
☐ GWPC
☐ SWPC
☐ GA PMC
☐ GB PMC
☐ SWPC
☐ RES DEC
☐ I/C DEC

**MA**
☐ MCP Certification
☐ GW-1 ☐ RCS-1 / RCGW-1
☐ GW-2 ☐ RCS-2 / RCGW-2
☐ GW-3 ☐ _____
☐ S-1
☐ S-2
☐ S-3
☐ SW Protection

**State where samples were collected:** NY

**Data Format**
☐ Excel
☒ PDF
☐ GIS/Key
☐ EQuIS
☐ Other

**Data Package**
☐ Tier II Checklist*
☐ Full Data Package*
☐ Phoenix Std
☐ Other

* SURCHARGE APPLIES

Form PEL126 Rev. 1/23

PHOENIX
Environmental Laboratories, Inc.

**Saturday, February 28, 2026**

**Attn: David Williams**
**Hygenix Division of Pennoni**
**350 Fairfiled Ave 4th Floor #404**
**Bridgeport CT 06604**

**Project ID:** 1 VINE ST LARCHMONT NY
**SDG ID:** GCV34746
**Sample ID#s:** CV34747

**This laboratory is in compliance with the NELAC requirements of procedures used except where indicated.**

**This report contains results for the parameters tested, under the sampling conditions described on the Chain Of Custody, as received by the laboratory. This report is incomplete unless all pages indicated in the pagination at the bottom of the page are included.**

**All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.**

**A scanned version of the COC form accompanies the analytical report and is an exact duplicate of the original.**

**The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.**

**Sincerely yours,**

Phyllis Shiller

**Phyllis Shiller**
**Laboratory Director**

**NELAC - #NY11301**
**CT Lab Registration #PH-0618**
**MA Lab Registration #M-CT007**
**ME Lab Registration #CT-007**
**NH Lab Registration #213693-A,B**
**NJ Lab Registration #CT-003**
**NY Lab Registration #11301**
**PA Lab Registration #68-03530**
**RI Lab Registration #63**
**VT Lab Registration #VT11301**

**Environmental Laboratories, Inc.**
**587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045**
**Tel. (860) 645-1102 Fax (860) 645-0823**

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# NY ANALYTICAL SERVICES PROTOCOL
# DATA PACKAGE

**Client: Hygenix Division of Pennoni**

**Project: 1 VINE ST LARCHMONT NY**

**Laboratory Project: GCV34746**

**Environmental Laboratories, Inc.**
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06040
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# NY Analytical Services Protocol Format

**March 06, 2026** **SDG I.D.: GCV34746**

**Hygenix Division of Pennoni 1 VINE ST LARCHMONT NY**

## Methodology Summary

### Mercury Prep

Soil Sample - USEPA SW-846 Test Methods for Evaluating Solid Waste Physical/Chemical Methods 3rd Ed. Update IV, Method 7471B.

### Metals

ICP :
USEPA SW-846 Test Methods for Evaluating Solid Waste Physical/Chemical Methods 3rd Ed. Update IV, Method 6010D.
Mercury:
USEPA SW-846 Test Methods for Evaluating Solid Waste Physical/Chemical Methods Update III, 7471B

**Environmental Laboratories, Inc.**
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06040
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# NY Analytical Services Protocol Format

**March 06, 2026** **SDG I.D.: GCV34746**

**Hygenix Division of Pennoni 1 VINE ST LARCHMONT NY**

## Laboratory Chronicle

**The samples in this delivery group were received at 1.7°C.**

| Sample | Analysis | Collection Date | Prep Date | Analysis Date | Analyst | Hold Time Met |
|---|---|---|---|---|---|---|
| CV34746 | On Hold | 02/18/26 | 02/19/26 | 02/19/26 | | Y |
| CV34747 | Arsenic | 02/18/26 | 02/24/26 | 02/25/26 | TH | Y |
| CV34747 | Barium | 02/18/26 | 02/24/26 | 02/25/26 | TH | Y |
| CV34747 | Cadmium | 02/18/26 | 02/24/26 | 02/25/26 | TH | Y |
| CV34747 | Chromium | 02/18/26 | 02/24/26 | 02/25/26 | TH | Y |
| CV34747 | Copper | 02/18/26 | 02/24/26 | 02/25/26 | TH | Y |
| CV34747 | Lead | 02/18/26 | 02/24/26 | 02/25/26 | TH | Y |
| CV34747 | Mercury | 02/18/26 | 02/24/26 | 02/27/26 | ZT | Y |
| CV34747 | Nickel | 02/18/26 | 02/24/26 | 02/25/26 | TH | Y |
| CV34747 | Percent Solid | 02/18/26 | 02/20/26 | 02/20/26 | JRB | Y |
| CV34747 | Selenium | 02/18/26 | 02/24/26 | 02/25/26 | TH | Y |
| CV34747 | Silver | 02/18/26 | 02/24/26 | 02/25/26 | TH | Y |
| CV34747 | Zinc | 02/18/26 | 02/24/26 | 02/25/26 | TH | Y |
| CV34748 | On Hold | 02/18/26 | 02/19/26 | 02/19/26 | | Y |

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# SDG Comments

February 28, 2026

SDG I.D.: GCV34746

Any compound that is not detected above the MDL/LOD is reported as ND on the report and is reported in the electronic deliverables (EDD) as <RL or U at the RL per state and EPA guidance.

Version 1: Analysis results minus raw data.

Version 2: Complete Data package report with all forms and raw data.

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

NY # 11301

# Sample Id Cross Reference

February 28, 2026

SDG I.D.: GCV34746

Project ID: 1 VINE ST LARCHMONT NY

| Client Id | Lab Id | Matrix | Col Date |
|---|---|---|---|
| DC-1 (1-3`) | CV34747 | SOIL | 02/18/26 0:00 |

PHOENIX
Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# Analysis Report

February 28, 2026

FOR: Attn: David Williams
Hygenix Division of Pennoni
350 Fairfiled Ave 4th Floor #404
Bridgeport CT 06604

| Sample Information | | Custody Information | | Date | Time |
|---|---|---|---|---|---|
| Matrix: | SOIL | Collected by: | | 02/18/26 | |
| Location Code: | PENNONI-CT | Received by: | B | 02/19/26 | 16:10 |
| Rush Request: | Standard | Analyzed by: | see "By" below | | |
| P.O.#: | ELKHO26001 | | | | |

## Laboratory Data

SDG ID: GCV34746
Phoenix ID: CV34747

Project ID: 1 VINE ST LARCHMONT NY
Client ID: DC-1 (1-3`)

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|
| Silver | ND | 0.42 | 0.42 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Arsenic | 5.83 | 0.85 | 0.85 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Barium | 200 | 0.42 | 0.42 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Cadmium | 1.47 | 0.42 | 0.42 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Chromium | 48.6 | 0.42 | 0.42 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Copper | 46.6 | 0.8 | 0.42 | mg/kg | 1 | 02/25/26 | TH | SW6010D |
| Mercury | 0.10 | 0.03 | 0.02 | mg/Kg | 2 | 02/27/26 | ZT | SW7471B |
| Nickel | 25.0 | 0.42 | 0.42 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Lead | 31.3 | 0.42 | 0.42 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Selenium | ND | 1.7 | 1.4 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Zinc | 63.7 | 0.8 | 0.42 | mg/Kg | 1 | 02/25/26 | TH | SW6010D |
| Percent Solid | 81 | | | % | | 02/20/26 | JRB | SW846-%Solid |
| Mercury Digestion | Completed | | | | | 02/24/26 | GW/AK | SW7471B |
| Total Metals Digest | Completed | | | | | 02/24/26 | C/AG | SW3050B |

Project ID: 1 VINE ST LARCHMONT NY
Client ID: DC-1 (1-3`)

Phoenix I.D.: CV34747

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quantitation) ND=Not Detected BRL=Below Reporting Level L=Biased Low LOD=Limit of Detection MDL=Method Detection Limit1

## Comments:

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If you are the client above and have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext.200.
The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.



**Phyllis Shiller, Laboratory Director**

**March 06, 2026**

**Reviewed and Released by: Rashmi Makol, Project Manager**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# QA/QC Report

March 06, 2026

## QA/QC Data

SDG I.D.: GCV34746

| Parameter | Blank | Blk RL | Sample Result | Dup Result | Dup RPD | LCS % | LCSD % | LCS RPD | MS % | MSD % | MS RPD | % Rec Limits | % RPD Limits | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| QA/QC Batch 827808 (mg/kg), QC Sample No: CV35496 (CV34747) | | | | | | | | | | | | | | |
| Mercury - Soil | BRL | 0.03 | 0.03 | 0.09 | NC | 113 | 117 | 3.5 | 111 | 119 | 7.0 | 75 - 125 | 30 | |
| QA/QC Batch 827924 (mg/kg), QC Sample No: CV34747 (CV34747) | | | | | | | | | | | | | | |
| ICP Metals - Soil | | | | | | | | | | | | | | |
| Arsenic | BRL | 0.67 | 5.83 | 2.59 | NC | 93.6 | 93.6 | 0.0 | 96.5 | | | 80 - 120 | 30 | |
| Barium | BRL | 0.33 | 200 | 145 | 31.9 | 96.6 | 90.7 | 6.3 | 115 | | | 80 - 120 | 30 | r |
| Cadmium | BRL | 0.33 | 1.47 | 0.68 | NC | 89.4 | 93.7 | 4.7 | 96.6 | | | 80 - 120 | 30 | |
| Chromium | BRL | 0.33 | 48.6 | 39.9 | 19.7 | 93.3 | 95.2 | 2.0 | 104 | | | 80 - 120 | 30 | |
| Copper | BRL | 0.67 | 46.6 | 28.0 | 49.9 | 96.1 | 96.8 | 0.7 | 99.0 | | | 80 - 120 | 30 | r |
| Lead | BRL | 0.33 | 31.3 | 13.1 | 82.0 | 95.0 | 94.2 | 0.8 | 98.3 | | | 80 - 120 | 30 | r |
| Nickel | BRL | 0.33 | 25.0 | 22.1 | 12.3 | 93.2 | 93.5 | 0.3 | 101 | | | 80 - 120 | 30 | |
| Selenium | BRL | 1.3 | <1.7 | <1.5 | NC | 90.7 | 88.0 | 3.0 | 83.6 | | | 80 - 120 | 30 | |
| Silver | BRL | 0.33 | <0.42 | <0.38 | NC | 98.8 | 99.8 | 1.0 | 103 | | | 70 - 130 | 30 | |
| Zinc | BRL | 0.67 | 63.7 | 45.8 | 32.7 | 90.8 | 91.6 | 0.9 | 99.0 | | | 80 - 120 | 30 | r |

r = This parameter is outside laboratory RPD specified recovery limits.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

RPD - Relative Percent Difference
LCS - Laboratory Control Sample
LCSD - Laboratory Control Sample Duplicate
MS - Matrix Spike
MS Dup - Matrix Spike Duplicate
NC - No Criteria
Intf - Interference
(ISO) - Isotope Dilution

Phyllis Shiller, Laboratory Director
March 06, 2026

Friday, March 06, 2026

Criteria: None

State: NY

# Sample Criteria Exceedances Report

## GCV34746 - PENNONI-CT

| SampNo | Acode | Phoenix Analyte | Criteria | Result | RL |
|---|---|---|---|---|---|

*** No Data to Display ***

Phoenix Laboratories does not assume responsibility for the data contained in this exceedance report. It is provided as an additional tool to identify requested crit
made to ensure the accuracy of the data (obtained from appropriate agencies). A lack of exceedence information does not necessarily suggest conformance to th
professional's responsibility to determine appropriate compliance.

**Environmental Laboratories, Inc.**
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# NY Temperature Narration

**March 06, 2026**

**SDG I.D.: GCV34746**

The samples in this delivery group were received at 1.7°C.
(Note acceptance criteria for relevant matrices is above freezing up to 6°C)

Cooler: Yes ☒ No ☐
Coolant: IPK ☒ ICE ☐ No ☐

# PHOENIX
*Environmental Laboratories, Inc.*

## CHAIN OF CUSTODY RECORD

587 East Middle Turnpike, P.O. Box 370, Manchester, CT 06040
Email: info@phoenixlabs.com Fax (860) 645-0823
**Client Services (860) 645-8726**

Temp 1.7 °C Pg of

**Contact Options:**
☐ Fax:
☐ Phone:
☐ Email: dave.williams@rennoni.com

Customer: Rennoni
Address: 350 Fairfield Ave, Suite 404
Bridgeport CT

Project: 1 Vine St Larchmont NY
Report to: Dave Williams
Invoice to: jmorris@rennoni.com

Project P.O: ELKH02600)

***This section MUST be completed with Bottle Quantities.***

Sampler's Signature: [signature] Date: 2/19/26

**Client Sample - Information - Identification**

**Matrix Code:**
**DW**=Drinking Water **GW**=Ground Water **SW**=Surface Water **WW**=Waste Water
**RW**=Raw Water **SE**=Sediment **SL**=Sludge **S**=Soil **SD**=Solid **W**=Wipe
**OIL**=Oil **B**=Bulk **L**=Liquid

Analysis Request

| PHOENIX USE ONLY SAMPLE # | Customer Sample Identification | Sample Matrix | Date Sampled | Time Sampled | TPH GRO/DRO Mod 8ph (Cu, Ni, Zn) | TCLP GRO/DRO Mod (Cu, Ni, Zn) | ALS (Cu, Ni, Zn) | PAHs 8270 | Soil VOA Vials [ ] methanol [ ] H2O | GL Soil container ( 8 ) oz | GL Soil container ( ) oz | 40 ml VOA Vial [ ] As is [ ] HCl | GL Amber 1000ml [ ] As is [ ] H2SO4 | PL As is [ ] 250ml [ ] 500ml [ ] 1000ml | PL H2SO4 [ ] 250ml [ ] 500ml | PL HNO3 250ml | PL NaOH 250ml | Bacteria Bottle |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 34746 | DC-1 (0.5-1') | S | 2/18/26 | | X | | X | | | 1 | | | | | | | | |
| 34747 | DC-1 (1-3') | S | ↓ | | X | | X | | | 1 | | | | | | | | |
| 34748 | DC-1 (3-5') | S | ↓ | | X | | X | | | 1 | | | | | | | | |

| Relinquished by: | Accepted by: | Date: | Time: |
|---|---|---|---|
| [signature] | Jacquic | 2/19/26 | 12:27 |
| Jacquic | [signature] | 2/19/26 | 10:10 |

**Comments, Special Requirements or Regulations:**

HOLD

**Turnaround:**
☐ 1 Day*
☐ 2 Days*
☐ 3 Days*
☐ Standard
☐ Other
* SURCHARGE APPLIES

**RI**
☐ Direct Exposure (Residential)
☐ GW
☐ Other

**CT**
☐ RCP Cert
☐ GW Protection
☐ SW Protection
☐ GA Mobility
☐ GB Mobility
☐ Residential DEC
☐ I/C DEC
☐ Other

**MA**
☐ MCP Certification
☐ GW-1
☐ GW-2
☐ GW-3
☐ S-1
☐ S-2
☐ S-3
☐ MWRA eSMART
☐ Other

**State where samples were collected:** NY

**Data Format**
☒ Excel
☒ PDF
☐ GIS/Key
☐ EQuIS
☐ Other

**Data Package**
☐ Tier II Checklist
☐ Full Data Package*
☒ Phoenix Std Report
☐ Other
* SURCHARGE APPLIES

## Sarah Bell

**From:** David T. Williams <DaWilliams@pennoni.com>
**Sent:** Friday, February 20, 2026 11:26 AM
**To:** Sarah Bell
**Cc:** Shannon Wilhelm
**Subject:** RE: Phoenix Labs - GCV34746, 1 VINE ST LARCHMONT NY - COC Acknowledgement

Yes, 8 RCRA total metals, plus Cu Ni and Zn. Thanks

**David T. Williams, RS, CPG, LEP**
Environmental Division Manager

**Pennoni**
350 Fairfield Avenue, 4th Floor, 404 | Bridgeport, CT 06604
**Direct:** +1 203-487-8662 | **Mobile:** +1 215-986-6717
www.pennoni.com | DaWilliams@pennoni.com

---

**From:** Sarah Bell <sarah@phoenixlabs.com>
**Sent:** Friday, February 20, 2026 11:25 AM
**To:** David T. Williams <DaWilliams@pennoni.com>
**Cc:** Shannon Wilhelm <shannon@phoenixlabs.com>
**Subject:** RE: Phoenix Labs - GCV34746, 1 VINE ST LARCHMONT NY - COC Acknowledgement

Do you mean Zinc ? see below highlighted

**Sarah Bell**
**Project Manager**
**Phoenix Environmental Laboratories**
**587 East Middle Turnpike | Manchester, CT 06040**
**Direct Line: 860-812-0270**
**Website:** www.phoenixlabs.com

**From:** David T. Williams <DaWilliams@pennoni.com>
**Sent:** Friday, February 20, 2026 11:11 AM
**To:** Sarah Bell <sarah@phoenixlabs.com>
**Cc:** Shannon Wilhelm <shannon@phoenixlabs.com>
**Subject:** RE: Phoenix Labs - GCV34746, 1 VINE ST LARCHMONT NY - COC Acknowledgement

OK-thanks


**David T. Williams, RS, CPG, LEP**
Environmental Division Manager

**Pennoni**
350 Fairfield Avenue, 4th Floor, 404 | Bridgeport, CT 06604
**Direct:** +1 203-487-8662 | **Mobile:** +1 215-986-6717
www.pennoni.com | DaWilliams@pennoni.com


**From:** Sarah Bell <sarah@phoenixlabs.com>
**Sent:** Friday, February 20, 2026 11:08 AM
**To:** David T. Williams <DaWilliams@pennoni.com>
**Cc:** Shannon Wilhelm <shannon@phoenixlabs.com>
**Subject:** RE: Phoenix Labs - GCV34746, 1 VINE ST LARCHMONT NY - COC Acknowledgement

Hi
I think this email should be good 😊
Sarah

**Sarah Bell**
**Project Manager**
**Phoenix Environmental Laboratories**
587 East Middle Turnpike | Manchester, CT 06040
Direct Line: 860-812-0270
**Website:** www.phoenixlabs.com

---

**From:** David T. Williams <DaWilliams@pennoni.com>
**Sent:** Friday, February 20, 2026 11:06 AM
**To:** Sarah Bell <sarah@phoenixlabs.com>
**Subject:** FW: Phoenix Labs - GCV34746, 1 VINE ST LARCHMONT NY - COC Acknowledgement

Please run sample DC-1 (1-3') for the Total 8 RCRA metals and Cu, Ni and Ni ONLY, standard turnaround. Would you like me to submit a new, cleaner COC for this?? Thanks

**David T. Williams, RS, CPG, LEP**
Environmental Division Manager

**Pennoni**
350 Fairfield Avenue, 4th Floor, 404 | Bridgeport, CT 06604
**Direct:** +1 203-487-8662 | **Mobile:** +1 215-986-6717
www.pennoni.com | DaWilliams@pennoni.com

---

**From:** SampleReceiving@phoenixlabs.com <SampleReceiving@phoenixlabs.com>
**Sent:** Thursday, February 19, 2026 10:10 PM
**To:** David T. Williams <DaWilliams@pennoni.com>
**Subject:** Phoenix Labs - GCV34746, 1 VINE ST LARCHMONT NY - COC Acknowledgement

This is an automated sample acknowledgement.

If you were issued a Phoenix Price Quote # for this SDG and it was not listed on the chain, please email client services with the quote number so we can ensure proper invoicing. If no quote was issued, no further action is required.

Purchase Order#: ELKH026001

Samples Will Be Disposed After: 30 Days

GCV34746 Criteria:
None.

Please email client services only if you require criteria different than what is listed. Criteria added post-reporting requires re-evaluation of data and possible re-analysis therefore charges may apply. Project objectives not communicated at time of submittal may not be achieved.

Delivery group GCV34746 (1 VINE ST LARCHMONT NY ) has been logged in for the following samples:

| Phoenix Id | Client Id |
|---|---|
| CV34746 | DC-1 (0.5-1`) |
| CV34747 | DC-1 (1-3`) |
| CV34748 | DC-1 (3-5`) |

**This SDG has been logged in for Standard 7 business day turn-around time.**

Turnaround time is an estimate and may vary depending on laboratory capacity at the time of sample receipt. PEL reserves the right to revise the turnaround time, accordingly, should the scope and/or schedule of the project change.

**The samples in this delivery group were received at 1.7°C. (Note acceptance criteria for relevant matrices is above freezing up to 6°C)**

If there are any questions regarding this submittal, please call Phoenix Client Services at extension 200.

Thank you for your business,

Phoenix Environmental Laboratories, Inc.
587 East Middle Turnpike
P.O. Box 370
Manchester, CT 06374
Tel. (860) 645-1102

Fax. (860) 645-0823
www.phoenixlabs.com

Please do not reply to this email.
cc'd:dawilliams@pennoni.com

PHOENIX
Environmental Laboratories, Inc.

**Friday, March 06, 2026**

**Attn: David Williams**
**Hygenix Division of Pennoni**
**350 Fairfiled Ave 4th Floor #404**
**Bridgeport CT 06604**

**Project ID:** 1 VINE ST, LARCHMONT, NY
**SDG ID:** GCV35325
**Sample ID#s:** CV35325 - CV35326

**This laboratory is in compliance with the NELAC requirements of procedures used except where indicated.**

**This report contains results for the parameters tested, under the sampling conditions described on the Chain Of Custody, as received by the laboratory. This report is incomplete unless all pages indicated in the pagination at the bottom of the page are included.**

**All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.**

**A scanned version of the COC form accompanies the analytical report and is an exact duplicate of the original.**

**The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.**

**Sincerely yours,**

**Phyllis Shiller**
**Laboratory Director**

**NELAC - #NY11301**
**CT Lab Registration #PH-0618**
**MA Lab Registration #M-CT007**
**ME Lab Registration #CT-007**
**NH Lab Registration #213693-A,B**
**NJ Lab Registration #CT-003**
**NY Lab Registration #11301**
**PA Lab Registration #68-03530**
**RI Lab Registration #63**
**VT Lab Registration #VT11301**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# SDG Comments

March 06, 2026

SDG I.D.: GCV35325

---

Any compound that is not detected above the MDL/LOD is reported as ND on the report and is reported in the electronic deliverables (EDD) as <RL or U at the RL per state and EPA guidance.

Version 1: Analysis results minus raw data.

Version 2: Complete Data package report with all forms and raw data.

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

NY # 11301

# Sample Id Cross Reference

March 06, 2026

SDG I.D.: GCV35325

Project ID: 1 VINE ST, LARCHMONT, NY

| Client Id | Lab Id | Matrix | Col Date |
|---|---|---|---|
| EB-1 (10-12`) | CV35325 | SOIL | 02/19/26 0:00 |
| EB-2 (8.5-10`) | CV35326 | SOIL | 02/19/26 0:00 |

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

NY # 11301

# Analysis Report

March 06, 2026

FOR: Attn: David Williams
Hygenix Division of Pennoni
350 Fairfiled Ave 4th Floor #404
Bridgeport CT 06604

| Sample Information | | Custody Information | | Date | Time |
|---|---|---|---|---|---|
| Matrix: | SOIL | Collected by: | | 02/19/26 | |
| Location Code: | PENNONI-CT | Received by: | SR1 | 02/20/26 | 16:10 |
| Rush Request: | Standard | Analyzed by: | see "By" below | | |
| P.O.#: | ELKH026001-6 | | | | |

## Laboratory Data

SDG ID: GCV35325
Phoenix ID: CV35325

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: EB-1 (10-12`)

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|---|
| Percent Solid | 87 | | | % | | 02/20/26 | JRB | SW846-%Solid | |
| Field Extraction | Completed | | | | | 02/19/26 | | SW5035A | 1 |
| **Volatiles** | | | | | | | | | |
| 1,1,1,2-Tetrachloroethane | ND | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,1,1-Trichloroethane | ND | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,1,2,2-Tetrachloroethane | ND | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,1,2-Trichloroethane | ND | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,1-Dichloroethane | ND | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,1-Dichloroethene | ND | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,1-Dichloropropene | ND | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,2,3-Trichlorobenzene | ND | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,2,3-Trichloropropane | ND | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,2,4-Trichlorobenzene | ND | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,2,4-Trimethylbenzene | 0.00082 J | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,2-Dibromo-3-chloropropane | ND | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,2-Dibromoethane | ND | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,2-Dichlorobenzene | ND | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,2-Dichloroethane | ND | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,2-Dichloropropane | ND | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,3,5-Trimethylbenzene | ND | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,3-Dichlorobenzene | ND | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,3-Dichloropropane | ND | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 1,4-Dichlorobenzene | ND | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 2,2-Dichloropropane | ND | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 2-Chlorotoluene | ND | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 2-Hexanone | ND | 0.024 | 0.0048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: EB-1 (10-12`)

Phoenix I.D.: CV35325

| Parameter | Result | | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|---|---|
| 2-Isopropyltoluene | 0.00048 | J | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | 1 |
| 4-Chlorotoluene | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| 4-Methyl-2-pentanone | ND | | 0.024 | 0.0048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Acetone | 0.026 | S | 0.024 | 0.0048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Acrylonitrile | ND | | 0.0097 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Benzene | 0.00061 | J | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Bromobenzene | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Bromochloromethane | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Bromodichloromethane | ND | | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Bromoform | ND | | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Bromomethane | ND | | 0.0048 | 0.0019 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Carbon Disulfide | 0.0017 | J | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Carbon tetrachloride | ND | | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Chlorobenzene | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Chloroethane | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Chloroform | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Chloromethane | ND | | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| cis-1,2-Dichloroethene | 0.0068 | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| cis-1,3-Dichloropropene | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Dibromochloromethane | ND | | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Dibromomethane | ND | | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Dichlorodifluoromethane | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Ethylbenzene | 0.00059 | J | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Hexachlorobutadiene | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Isopropylbenzene | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| m&p-Xylene | 0.0021 | J | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Methyl Ethyl Ketone | ND | | 0.024 | 0.0048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Methyl t-butyl ether (MTBE) | ND | | 0.0097 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Methylene chloride | ND | | 0.0097 | 0.0048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Naphthalene | ND | | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| n-Butylbenzene | 0.0009 | J | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| n-Propylbenzene | ND | | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| o-Xylene | ND | | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| p-Isopropyltoluene | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| sec-Butylbenzene | 0.00097 | J | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Styrene | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| tert-Butylbenzene | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Tetrachloroethene | ND | | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Tetrahydrofuran (THF) | ND | | 0.0097 | 0.0024 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Toluene | 0.00056 | J | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Total Xylenes | ND | | 0.0048 | 0.0048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| trans-1,2-Dichloroethene | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| trans-1,3-Dichloropropene | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| trans-1,4-dichloro-2-butene | ND | | 0.0097 | 0.0024 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Trichloroethene | 0.00053 | J | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Trichlorofluoromethane | ND | | 0.0048 | 0.00097 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Trichlorotrifluoroethane | ND | | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |
| Vinyl chloride | 0.0025 | J | 0.0048 | 0.00048 | mg/Kg | 1 | 03/01/26 | MH | SW8260D | |

**QA/QC Surrogates**

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: EB-1 (10-12`)

Phoenix I.D.: CV35325

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|
| % 1,2-dichlorobenzene-d4 | 98 | | | % | 1 | 03/01/26 | MH | 70 - 130 % |
| % Bromofluorobenzene | 100 | | | % | 1 | 03/01/26 | MH | 70 - 130 % |
| % Dibromofluoromethane | 97 | | | % | 1 | 03/01/26 | MH | 70 - 130 % |
| % Toluene-d8 | 91 | | | % | 1 | 03/01/26 | MH | 70 - 130 % |

1 = This parameter is not certified by the primary accrediting authority (NY NELAC) for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quantitation) ND=Not Detected BRL=Below Reporting Level L=Biased Low J=Estimated Below RL LOD=Limit of Detection MDL=Method Detection Limit1
QA/QC Surrogates: Surrogates are compounds (preceeded with a %) added by the lab to determine analysis efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

## Comments:

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

S - Laboratory solvent, contamination is possible.

If you are the client above and have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext.200.
The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.



**Phyllis Shiller, Laboratory Director**
**March 06, 2026**
**Reviewed and Released by: Sarah Bell, Project Manager**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# Analysis Report

March 06, 2026

FOR: Attn: David Williams
Hygenix Division of Pennoni
350 Fairfiled Ave 4th Floor #404
Bridgeport CT 06604

| Sample Information | | Custody Information | | Date | Time |
|---|---|---|---|---|---|
| Matrix: | SOIL | Collected by: | | 02/19/26 | |
| Location Code: | PENNONI-CT | Received by: | SR1 | 02/20/26 | 16:10 |
| Rush Request: | Standard | Analyzed by: | see "By" below | | |
| P.O.#: | ELKH026001-6 | | | | |

## Laboratory Data

SDG ID: GCV35325
Phoenix ID: CV35326

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: EB-2 (8.5-10`)

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|---|
| Percent Solid | 79 | | | % | | 02/20/26 | JRB | SW846-%Solid | |
| Corrosivity | Negative | | | Pos/Neg | 1 | 02/20/26 | KG | SW846-Corr | 1 |
| Flash Point | >200 | 200 | 200 | Degree F | 1 | 02/26/26 | G/EG | SW1010B | |
| Ignitability | Passed | 140 | 140 | Degree F | 1 | 02/26/26 | G/EG | SW846-Ignit | 1 |
| pH at 21C - Soil | 11.0 | 1.00 | 1.00 | pH Units | 1 | 02/20/26 23:14 | KG | SW846 9045D | |
| Reactivity Cyanide | ND | 1 | 0.06 | mg/Kg | 1 | 02/25/26 | NP/GD | SW846 7.3.3.1/90 | 1 |
| Reactivity Sulfide | ND | 20 | 20 | mg/Kg | 1 | 02/27/26 | NP/GD | SW846 CH7 | 1 |
| Reactivity | Negative | | | Pos/Neg | 1 | 02/27/26 | NP/GD | SW846-React | 1 |
| Field Extraction | Completed | | | | | 02/19/26 | | SW5035A | 1 |
| Soil Extraction for PCB | Completed | | | | | 03/02/26 | H/U | SW3546 | |
| **Polychlorinated Biphenyls** | | | | | | | | | |
| PCB-1016 | ND | 0.42 | 0.42 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| PCB-1221 | ND | 0.42 | 0.42 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| PCB-1232 | ND | 0.42 | 0.42 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| PCB-1242 | ND | 0.42 | 0.42 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| PCB-1248 | ND | 0.42 | 0.42 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| PCB-1254 | ND | 0.42 | 0.42 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| PCB-1260 | ND | 0.42 | 0.42 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| PCB-1262 | ND | 0.42 | 0.42 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| PCB-1268 | ND | 0.42 | 0.42 | mg/Kg | 10 | 03/03/26 | SC | SW8082A | |
| **QA/QC Surrogates** | | | | | | | | | |
| % DCBP | 79 | | | % | 10 | 03/03/26 | SC | 30 - 150 % | |
| % DCBP (Confirmation) | 94 | | | % | 10 | 03/03/26 | SC | 30 - 150 % | |
| % TCMX | 77 | | | % | 10 | 03/03/26 | SC | 30 - 150 % | |
| % TCMX (Confirmation) | 88 | | | % | 10 | 03/03/26 | SC | 30 - 150 % | |

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: EB-2 (8.5-10`)

Phoenix I.D.: CV35326

| Parameter | Result | | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|---|---|
| **Volatiles** | | | | | | | | | | |
| 1,1,1,2-Tetrachloroethane | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,1,1-Trichloroethane | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,1,2,2-Tetrachloroethane | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,1,2-Trichloroethane | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,1-Dichloroethane | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,1-Dichloroethene | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,1-Dichloropropene | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,2,3-Trichlorobenzene | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,2,3-Trichloropropane | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,2,4-Trichlorobenzene | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,2,4-Trimethylbenzene | 0.59 | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,2-Dibromo-3-chloropropane | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,2-Dibromoethane | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,2-Dichlorobenzene | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,2-Dichloroethane | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,2-Dichloropropane | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,3,5-Trimethylbenzene | 0.17 | | 0.13 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,3-Dichlorobenzene | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,3-Dichloropropane | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 1,4-Dichlorobenzene | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 2,2-Dichloropropane | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 2-Chlorotoluene | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 2-Hexanone | ND | | 1.7 | 0.33 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 2-Isopropyltoluene | 0.093 | J | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | 1 |
| 4-Chlorotoluene | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| 4-Methyl-2-pentanone | ND | | 1.7 | 0.33 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Acetone | ND | | 1.7 | 0.33 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Acrylonitrile | ND | | 0.66 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Benzene | 0.29 | | 0.26 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Bromobenzene | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Bromochloromethane | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Bromodichloromethane | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Bromoform | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Bromomethane | ND | | 0.33 | 0.13 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Carbon Disulfide | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Carbon tetrachloride | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Chlorobenzene | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Chloroethane | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Chloroform | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Chloromethane | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| cis-1,2-Dichloroethene | 0.11 | J | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| cis-1,3-Dichloropropene | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Dibromochloromethane | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Dibromomethane | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Dichlorodifluoromethane | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Ethylbenzene | 0.4 | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Hexachlorobutadiene | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |
| Isopropylbenzene | 0.2 | | 0.2 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D | |

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: EB-2 (8.5-10`)

Phoenix I.D.: CV35326

| Parameter | Result | | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|---|
| m&p-Xylene | 1.2 | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| Methyl Ethyl Ketone | ND | | 1.7 | 0.33 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| Methyl t-butyl ether (MTBE) | ND | | 0.66 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| Methylene chloride | ND | | 0.66 | 0.33 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| Naphthalene | 14 | | 6.6 | 1.3 | mg/Kg | 1000 | 03/02/26 | JLI | SW8260D |
| n-Butylbenzene | 1.8 | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| n-Propylbenzene | 0.89 | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| o-Xylene | 0.23 | | 0.2 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| p-Isopropyltoluene | 0.04 | J | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| sec-Butylbenzene | 0.85 | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| Styrene | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| tert-Butylbenzene | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| Tetrachloroethene | 0.08 | J | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| Tetrahydrofuran (THF) | ND | | 0.66 | 0.17 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| Toluene | 0.95 | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| Total Xylenes | 1.43 | | 0.2 | 0.2 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| trans-1,2-Dichloroethene | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| trans-1,3-Dichloropropene | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| trans-1,4-dichloro-2-butene | ND | | 0.66 | 0.17 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| Trichloroethene | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| Trichlorofluoromethane | ND | | 0.33 | 0.066 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| Trichlorotrifluoroethane | ND | | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| Vinyl chloride | 0.05 | J | 0.33 | 0.033 | mg/Kg | 50 | 03/04/26 | JLI | SW8260D |
| **QA/QC Surrogates** | | | | | | | | | |
| % 1,2-dichlorobenzene-d4 (50x) | 101 | | | | % | 50 | 03/04/26 | JLI | 70 - 130 % |
| % Bromofluorobenzene (50x) | 110 | | | | % | 50 | 03/04/26 | JLI | 70 - 130 % |
| % Dibromofluoromethane (50x) | 93 | | | | % | 50 | 03/04/26 | JLI | 70 - 130 % |
| % Toluene-d8 (50x) | 92 | | | | % | 50 | 03/04/26 | JLI | 70 - 130 % |
| % 1,2-dichlorobenzene-d4 (1000x) | 100 | | | | % | 1000 | 03/02/26 | JLI | 70 - 130 % |
| % Bromofluorobenzene (1000x) | 101 | | | | % | 1000 | 03/02/26 | JLI | 70 - 130 % |
| % Dibromofluoromethane (1000x) | 94 | | | | % | 1000 | 03/02/26 | JLI | 70 - 130 % |
| % Toluene-d8 (1000x) | 100 | | | | % | 1000 | 03/02/26 | JLI | 70 - 130 % |

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|

1 = This parameter is not certified by the primary accrediting authority (NY NELAC) for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quantitation) ND=Not Detected BRL=Below Reporting Level L=Biased Low J=Estimated Below RL LOD=Limit of Detection MDL=Method Detection Limit1
QA/QC Surrogates: Surrogates are compounds (preceeded with a %) added by the lab to determine analysis efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

## Comments:

Corrosivity is based solely on the pH analysis performed above.

Ignitability is based solely on the results of the closed cup flashpoint analysis performed above. Passed is >140 degree F.

The regulatory hold time for pH is immediately. This pH was performed in the laboratory and may be considered outside of hold-time.

The reactivity, reported above, is based only on the EPA Interim Guidance for Reactive Cyanide. This method is no longer listed in the current version of SW-846.

The reactivity, reported above, is based only on the EPA Interim Guidance for Reactive Sulfide. This method is no longer listed in the current version of SW-846.

Volatile Comment:
Elevated reporting limits for volatiles due to the presence of target and/or non-target compounds.

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If you are the client above and have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext.200.
The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.

**Phyllis Shiller, Laboratory Director**
**March 06, 2026**
**Reviewed and Released by: Sarah Bell, Project Manager**

Friday, March 06, 2026

Criteria: None

State: NY

# Sample Criteria Exceedances Report

## GCV35325 - PENNONI-CT

| SampNo | Acode | Phoenix Analyte | Criteria | Result | RL | Criteria | RL Criteria | Analysis Units |
|---|---|---|---|---|---|---|---|---|

*** No Data to Display ***

Phoenix Laboratories does not assume responsibility for the data contained in this exceedance report. It is provided as an additional tool to identify requested criteria exceedences. All efforts are made to ensure the accuracy of the data (obtained from appropriate agencies). A lack of exceedence information does not necessarily suggest conformance to the criteria. It is ultimately the site professional's responsibility to determine appropriate compliance.

**Environmental Laboratories, Inc.**
**587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045**
**Tel. (860) 645-1102 Fax (860) 645-0823**

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# NY Temperature Narration

**March 06, 2026**

**SDG I.D.: GCV35325**

The samples in this delivery group were received at 2.2°C.
(Note acceptance criteria for relevant matrices is above freezing up to 6°C)

Cooler: Yes [X] No [ ]
Coolant: IPK [X] ICE [ ] No [ ]

# PHOENIX
*Environmental Laboratories, Inc.*

## CHAIN OF CUSTODY RECORD

587 East Middle Turnpike, P.O. Box 370, Manchester, CT 06040
Email: info@phoenixlabs.com Fax (860) 645-0823
**Client Services (860) 645-8726**

Temp 2.2 °C Pg 1 of 1

**Contact Options:**
[ ] Fax:
[ ] Phone:
[X] Email: DaWilliams@pennoni.com

Customer: Pennoni
Address: 350 Fairfield Ave - Suite 404
Bridgeport, CT

Project: 1 Vine St, Larchmont, NY
Report to: Dave Williams
Invoice to: jmori@pennoni.com

Project P.O: ELKH026001-6

***This section MUST be completed with Bottle Quantities.***

Sampler's Signature: [signature] Date: 2/19/2026

**Client Sample - ~~Information~~ - Identification**

**Matrix Code:**
**DW**=Drinking Water **GW**=Ground Water **SW**=Surface Water **WW**=Waste Water
**RW**=Raw Water **SE**=Sediment **SL**=Sludge **S**=Soil **SD**=Solid **W**=Wipe
**OIL**=Oil **B**=Bulk **L**=Liquid

Analysis Request

| PHOENIX USE ONLY SAMPLE # | Customer Sample Identification | Sample Matrix | Date Sampled | Time Sampled | VOC 8260/5035 | PCB | Ignitability/Corrosivity/pH | Reactivity | Soil VOA Vials [X] methanol [X] H2O | GL Soil container ( 8 ) oz | GL Soil container ( ) oz | 40 ml VOA Vial [ ] As is [ ] HCl | GL Amber 1000ml [ ] As is [ ] H2SO4 | PL As is [ ] 250ml [ ] 500ml [ ] 1000ml | PL H2SO4 [ ] 250ml [ ] 500ml | PL HNO3 250ml | PL NaOH 250ml | Bacteria Bottle |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 35325 | EB-1 (10-12') | S | 19 Feb | | X | | | | 3 | 1 | | | | | | | | |
| 35326 | EB-2 (8.5-10') | S | 19 Feb | | X | X | X | X | 3 | 1 | | | | | | | | |
| | ~~EB-3~~ | ~~S~~ | ~~19 Feb~~ | | | | | | | ~~1~~ | | | | | | | | |

| Relinquished by: | Accepted by: | Date: | Time: |
|---|---|---|---|
| [signature] | Jacqui C | 2/20/26 | 11:54 |
| Jacqui C | [signature] | 2/20/26 | 16:10 |

**Comments, Special Requirements or Regulations:**

**Turnaround:**
[ ] 1 Day*
[ ] 2 Days*
[ ] 3 Days*
[X] Standard
[ ] Other
* SURCHARGE APPLIES

**RI**
[ ] Direct Exposure (Residential)
[ ] GW
[ ] Other

**CT**
[ ] RCP Cert
[ ] GW Protection
[ ] SW Protection
[ ] GA Mobility
[ ] GB Mobility
[ ] Residential DEC
[ ] I/C DEC
[ ] Other

**MA**
[ ] MCP Certification
[ ] GW-1
[ ] GW-2
[ ] GW-3
[ ] S-1
[ ] S-2
[ ] S-3
[ ] MWRA eSMART
[ ] Other

**State where samples were collected:** NY

**Data Format**
[ ] Excel
[X] PDF
[ ] GIS/Key
[ ] EQuIS
[ ] Other

**Data Package**
[ ] Tier II Checklist
[ ] Full Data Package*
[ ] Phoenix Std Report
[ ] Other
* SURCHARGE APPLIES

PHOENIX

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# Analysis Report

March 06, 2026

FOR: Attn: David Williams
Hygenix Division of Pennoni
350 Fairfiled Ave 4th Floor #404
Bridgeport CT 06604

| Sample Information | | Custody Information | | Date | Time |
|---|---|---|---|---|---|
| Matrix: | GROUND WATER | Collected by: | | 02/18/26 | 14:06 |
| Location Code: | PENNONI-CT | Received by: | SW | 02/19/26 | 16:10 |
| Rush Request: | Standard | Analyzed by: | see "By" below | | |
| P.O.#: | ELKHO26001 | | | | |

## Laboratory Data

SDG ID: GCV34745
Phoenix ID: CV34745

Project ID: 1 VINE ST LARCHMONT NY
Client ID: MW EXISTING

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|
| Silver | ND | 0.001 | 0.001 | mg/L | 1 | 03/02/26 | TH | SW6010D |
| Arsenic | ND | 0.004 | 0.001 | mg/L | 1 | 03/02/26 | TH | SW6010D |
| Barium | 1.79 | 0.002 | 0.001 | mg/L | 1 | 03/02/26 | TH | SW6010D |
| Cadmium | 0.002 | 0.001 | 0.0005 | mg/L | 1 | 03/02/26 | TH | SW6010D |
| Chromium | ND | 0.001 | 0.001 | mg/L | 1 | 03/02/26 | TH | SW6010D |
| Copper | 0.005 | 0.005 | 0.001 | mg/L | 1 | 03/02/26 | TH | SW6010D |
| Mercury | ND | 0.0002 | 0.00015 | mg/L | 1 | 02/20/26 | AJ1 | SW7470A |
| Nickel | 0.002 | 0.001 | 0.001 | mg/L | 1 | 03/02/26 | TH | SW6010D |
| Lead | ND | 0.001 | 0.001 | mg/L | 1 | 03/02/26 | TH | SW6010D |
| Selenium | ND | 0.010 | 0.01 | mg/L | 1 | 03/02/26 | TH | SW6010D |
| Zinc | 0.011 | 0.004 | 0.002 | mg/L | 1 | 03/02/26 | TH | SW6010D |
| Mercury Digestion | Completed | | | | | 02/20/26 | GW/SD | SW7470A |
| PCB Extraction (LDL) | Completed | | | | | 02/20/26 | J/J | SW3510C |
| Semi-Volatile Extraction | Completed | | | | | 02/25/26 | L/RB/SM1 | SW3520C |
| Total Metals Digestion | Completed | | | | | 02/23/26 | AG | SW3010A |

## Polychlorinated Biphenyls

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| PCB-1016 | ND | 0.049 | 0.049 | ug/L | 1 | 02/24/26 | SC | SW8082A |
| PCB-1221 | ND | 0.049 | 0.049 | ug/L | 1 | 02/24/26 | SC | SW8082A |
| PCB-1232 | ND | 0.049 | 0.049 | ug/L | 1 | 02/24/26 | SC | SW8082A |
| PCB-1242 | ND | 0.049 | 0.049 | ug/L | 1 | 02/24/26 | SC | SW8082A |
| PCB-1248 | ND | 0.049 | 0.049 | ug/L | 1 | 02/24/26 | SC | SW8082A |
| PCB-1254 | ND | 0.049 | 0.049 | ug/L | 1 | 02/24/26 | SC | SW8082A |
| PCB-1260 | ND | 0.049 | 0.049 | ug/L | 1 | 02/24/26 | SC | SW8082A |
| PCB-1262 | ND | 0.049 | 0.049 | ug/L | 1 | 02/24/26 | SC | SW8082A |
| PCB-1268 | ND | 0.049 | 0.049 | ug/L | 1 | 02/24/26 | SC | SW8082A |

**QA/QC Surrogates**

| Parameter | Result | | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|---|---|
| % DCBP | 23 | | | | % | 1 | 02/24/26 | SC | 30 - 150 % | 3 |
| % DCBP (Confirmation) | 26 | | | | % | 1 | 02/24/26 | SC | 30 - 150 % | 3 |
| % TCMX | 70 | | | | % | 1 | 02/24/26 | SC | 30 - 150 % | |
| % TCMX (Confirmation) | 70 | | | | % | 1 | 02/24/26 | SC | 30 - 150 % | |
| **Volatiles** | | | | | | | | | | |
| 1,1,1,2-Tetrachloroethane | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,1,1-Trichloroethane | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,1,2,2-Tetrachloroethane | ND | | 0.50 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,1,2-Trichloroethane | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,1-Dichloroethane | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,1-Dichloroethene | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,1-Dichloropropene | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,2,3-Trichlorobenzene | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,2,3-Trichloropropane | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,2,4-Trichlorobenzene | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,2,4-Trimethylbenzene | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,2-Dibromo-3-chloropropane | ND | | 1.0 | 0.50 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,2-Dibromoethane | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,2-Dichlorobenzene | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,2-Dichloroethane | ND | | 0.60 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,2-Dichloropropane | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,3,5-Trimethylbenzene | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,3-Dichlorobenzene | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,3-Dichloropropane | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 1,4-Dichlorobenzene | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 2,2-Dichloropropane | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 2-Chlorotoluene | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 2-Hexanone | ND | | 5.0 | 2.5 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 2-Isopropyltoluene | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | 1 |
| 4-Chlorotoluene | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| 4-Methyl-2-pentanone | ND | | 5.0 | 2.5 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Acetone | 4.6 | JS | 25 | 2.5 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Acrylonitrile | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Benzene | ND | | 0.70 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Bromobenzene | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Bromochloromethane | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Bromodichloromethane | ND | | 0.50 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Bromoform | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Bromomethane | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Carbon Disulfide | ND | | 5.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Carbon tetrachloride | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Chlorobenzene | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Chloroethane | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Chloroform | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Chloromethane | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| cis-1,2-Dichloroethene | 43 | | 5.0 | 1.3 | ug/L | 5 | 02/21/26 | MH | SW8260D | |
| cis-1,3-Dichloropropene | ND | | 0.40 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Dibromochloromethane | ND | | 0.50 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Dibromomethane | ND | | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|---|
| Dichlorodifluoromethane | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Ethylbenzene | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Hexachlorobutadiene | ND | 0.40 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Isopropylbenzene | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| m&p-Xylene | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Methyl ethyl ketone | ND | 5.0 | 2.5 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Methyl t-butyl ether (MTBE) | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Methylene chloride | ND | 1.0 | 1.0 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Naphthalene | ND | 1.0 | 1.0 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| n-Butylbenzene | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| n-Propylbenzene | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| o-Xylene | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| p-Isopropyltoluene | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| sec-Butylbenzene | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Styrene | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| tert-Butylbenzene | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Tetrachloroethene | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Tetrahydrofuran (THF) | ND | 2.5 | 2.5 | ug/L | 1 | 02/20/26 | MH | SW8260D | 1 |
| Toluene | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Total Xylenes | ND | 1.0 | 1.0 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| trans-1,2-Dichloroethene | 1.6 | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| trans-1,3-Dichloropropene | ND | 0.40 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| trans-1,4-dichloro-2-butene | ND | 5.0 | 2.5 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Trichloroethene | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Trichlorofluoromethane | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Trichlorotrifluoroethane | ND | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| Vinyl chloride | 9.3 | 1.0 | 0.25 | ug/L | 1 | 02/20/26 | MH | SW8260D | |
| **QA/QC Surrogates** | | | | | | | | | |
| % 1,2-dichlorobenzene-d4 | 97 | | | % | 1 | 02/20/26 | MH | 70 - 130 % | |
| % Bromofluorobenzene | 97 | | | % | 1 | 02/20/26 | MH | 70 - 130 % | |
| % Dibromofluoromethane | 101 | | | % | 1 | 02/20/26 | MH | 70 - 130 % | |
| % Toluene-d8 | 92 | | | % | 1 | 02/20/26 | MH | 70 - 130 % | |
| % 1,2-dichlorobenzene-d4 (5x) | 99 | | | % | 5 | 02/21/26 | MH | 70 - 130 % | |
| % Bromofluorobenzene (5x) | 97 | | | % | 5 | 02/21/26 | MH | 70 - 130 % | |
| % Dibromofluoromethane (5x) | 108 | | | % | 5 | 02/21/26 | MH | 70 - 130 % | |
| % Toluene-d8 (5x) | 91 | | | % | 5 | 02/21/26 | MH | 70 - 130 % | |

## Semivolatiles by SIM, PAH

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 2-Methylnaphthalene | ND | 0.48 | 0.48 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| Acenaphthene | ND | 0.48 | 0.48 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| Acenaphthylene | ND | 0.48 | 0.48 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| Anthracene | ND | 0.48 | 0.48 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| Benzo(a)anthracene | ND | 0.02 | 0.02 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| Benzo(a)pyrene | ND | 0.05 | 0.05 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| Benzo(b)fluoranthene | ND | 0.03 | 0.03 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| Benzo(ghi)perylene | ND | 0.48 | 0.48 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| Benzo(k)fluoranthene | ND | 0.03 | 0.02 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| Chrysene | ND | 0.02 | 0.02 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| Dibenz(a,h)anthracene | ND | 0.48 | 0.48 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| Fluoranthene | ND | 0.48 | 0.48 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |

Project ID: 1 VINE ST LARCHMONT NY
Client ID: MW EXISTING

Phoenix I.D.: CV34745

| Parameter | Result | RL/ PQL | LOD/ MDL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|---|
| Fluorene | ND | 0.48 | 0.48 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| Indeno(1,2,3-cd)pyrene | ND | 0.12 | 0.12 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| Naphthalene | ND | 0.48 | 0.48 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| Phenanthrene | ND | 0.48 | 0.48 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| Pyrene | ND | 0.48 | 0.48 | ug/L | 1 | 02/27/26 | KCA | SW8270E (SIM) |
| **QA/QC Surrogates** | | | | | | | | |
| % 2-Fluorobiphenyl | 66 | | | % | 1 | 02/27/26 | KCA | 30 - 130 % |
| % Nitrobenzene-d5 | 68 | | | % | 1 | 02/27/26 | KCA | 30 - 130 % |
| % Terphenyl-d14 | 58 | | | % | 1 | 02/27/26 | KCA | 30 - 130 % |

1 = This parameter is not certified by the primary accrediting authority (NY NELAC) for this matrix. NY NELAC does not offer certification for all parameters at this time.
3 = This parameter exceeds laboratory specified limits.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quantitation) ND=Not Detected BRL=Below Reporting Level L=Biased Low J=Estimated Below RL LOD=Limit of Detection MDL=Method Detection Limit1
QA/QC Surrogates: Surrogates are compounds (preceeded with a %) added by the lab to determine analysis efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

## Comments:

PCB Comment:
Poor surrogate recovery was observed for PCBs. Insufficient sample for re-extraction.

S - Laboratory solvent, contamination is possible.

If you are the client above and have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext.200.
The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.

**Phyllis Shiller, Laboratory Director**
**March 06, 2026**
**Official Report Release To Follow**

# Sample Criteria Exceedances Report

## GCV34745 - PENNONI-CT



Criteria: None

State: NY

| SampNo | Acode | Phoenix Analyte | Criteria | Result | RL | Criteria | RL Criteria | Analysis Units |
|---|---|---|---|---|---|---|---|---|

*** No Data to Display ***

Phoenix Laboratories does not assume responsibility for the data contained in this exceedance report. It is provided as an additional tool to identify requested criteria exceedences. All efforts are made to ensure the accuracy of the data (obtained from appropriate agencies). A lack of exceedence information does not necessarily suggest conformance to the criteria. It is ultimately the site professional's responsibility to determine appropriate compliance.

Cooler: Yes ☒ No ☐
Coolant: IPK ☒ ICE ☐ No ☐

# PHOENIX
*Environmental Laboratories, Inc.*

## CHAIN OF CUSTODY RECORD

587 East Middle Turnpike, P.O. Box 370, Manchester, CT 06040
Email: info@phoenixlabs.com Fax (860) 645-0823
**Client Services (860) 645-8726**

Temp 1.7 °C Pg 1 of 1

**Contact Options:**
☐ Fax:
☐ Phone:
☒ Email: DaWilliams@pennoni.com

Customer: Pennoni
Address: 350 Fairfield Ave - Suite 404
Bridgeport, CT

Project: 1 Vine St, Larchmont, NY
Report to: Dave Williams
Invoice to: jmarie.pennoni.com

Project P.O: ELKH026001

***This section MUST be completed with Bottle Quantities.***

Sampler's Signature: [signature] Date: 2/18/2026

**Client Sample - Information - Identification**

**Matrix Code:**
**DW**=Drinking Water **GW**=Ground Water **SW**=Surface Water **WW**=Waste Water
**RW**=Raw Water **SE**=Sediment **SL**=Sludge **S**=Soil **SD**=Solid **W**=Wipe
**OIL**=Oil **B**=Bulk **L**=Liquid

Analysis Request: PCB 8082 | SVOC - PAHs 8270 | VOC - 8260 | TAL RCRA Metals | plus Cu, Ni, Zn

| PHOENIX USE ONLY SAMPLE # | Customer Sample Identification | Sample Matrix | Date Sampled | Time Sampled | Soil VOA Vials [ ] methanol [ ] H2O | GL Soil container ( ) oz | GL Soil container ( ) oz | 40 ml VOA Vial [ ] As is [ ] HCl | GL Amber 1000ml [X] As is [ ] H2SO4 | PL As is [ ] 250ml [ ] 500ml [ ] 1000ml | PL H2SO4 [ ] 250ml [ ] 500ml [ ] 1000ml | PL HNO3 250ml | PL NaOH 250ml | Bacteria Bottle |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 34745 | MW (Existing) | GW | 18 Feb | 1406 | X | X | X | + | | | | | | |
| | | | | | | | | | 3 | 2 | | | 1 | |

| Relinquished by: | Accepted by: | Date: | Time: |
|---|---|---|---|
| Jacqui C | Jacqui C | 2/19/26 | 12:24 |
| | | 2/19/26 | 14:10 |

**Comments, Special Requirements or Regulations:**
(Sample from exterior existing monitoring well)

**Turnaround:**
☐ 1 Day*
☐ 2 Days*
☐ 3 Days*
☒ Standard
☐ Other
* SURCHARGE APPLIES

**RI**
☐ Direct Exposure (Residential)
☐ GW
☐ Other

**CT**
☐ RCP Cert
☐ GW Protection
☐ SW Protection
☐ GA Mobility
☐ GB Mobility
☐ Residential DEC
☐ I/C DEC
☐ Other

**MA**
☐ MCP Certification
☐ GW-1
☐ GW-2
☐ GW-3
☐ S-1
☐ S-2
☐ S-3
☐ MWRA eSMART
☐ Other

**State where samples were collected:** NY

**Data Format**
☒ Excel
☒ PDF
☐ GIS/Key
☐ EQuIS
☐ Other

**Data Package**
☐ Tier II Checklist
☐ Full Data Package*
☒ Phoenix Std Report
☐ Other
* SURCHARGE APPLIES

PHOENIX
Environmental Laboratories, Inc.

**Thursday, March 12, 2026**

**Attn: David Williams**
**Hygenix Division of Pennoni**
**350 Fairfiled Ave 4th Floor #404**
**Bridgeport CT 06604**

**Project ID:** 1 VINE ST, LARCHMONT, NY
**SDG ID:** GCV38887
**Sample ID#s:** CV38887

**This laboratory is in compliance with the NELAC requirements of procedures used except where indicated.**

**This report contains results for the parameters tested, under the sampling conditions described on the Chain Of Custody, as received by the laboratory. This report is incomplete unless all pages indicated in the pagination at the bottom of the page are included.**

**A scanned version of the COC form accompanies the analytical report and is an exact duplicate of the original.**

**The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.**

**Sincerely yours,**

**Phyllis Shiller**
**Laboratory Director**

**NELAC - #NY11301**
**CT Lab Registration #PH-0618**
**MA Lab Registration #M-CT007**
**ME Lab Registration #CT-007**
**NH Lab Registration #213693-A,B**
**NJ Lab Registration #CT-003**
**NY Lab Registration #11301**
**PA Lab Registration #68-03530**
**RI Lab Registration #63**
**VT Lab Registration #VT11301**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# SDG Comments

March 12, 2026

SDG I.D.: GCV38887

SIM Analysis:
The lowest possible reporting limit under SIM conditions is 0.02 ug/L. The NY TOGS GA criteria for some PAHs is 0.002 ug/L. This level cannot be achieved.

8260 Volatile Organics:
1,2-Dibromoethane, 1,2,3 Trichloropropane, and 1,2-Dibromo-3-chloropropane do not meet NY TOGS GA criteria, these compounds are analyzed by GC/ECD method 504 or 8011 to achieve this criteria.

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823

NY # 11301

# Sample Id Cross Reference

March 12, 2026

SDG I.D.: GCV38887

Project ID: 1 VINE ST, LARCHMONT, NY

| Client Id | Lab Id | Matrix | Col Date |
|---|---|---|---|
| MW-1 | CV38887 | GROUND WATER | 02/27/26 11:20 |

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# Analysis Report

March 12, 2026

FOR: Attn: David Williams
Hygenix Division of Pennoni
350 Fairfiled Ave 4th Floor #404
Bridgeport CT 06604

| Sample Information | | Custody Information | | Date | Time |
|---|---|---|---|---|---|
| Matrix: | GROUND WATER | Collected by: | PG | 02/27/26 | 11:20 |
| Location Code: | PENNONI-CT | Received by: | SR1 | 03/02/26 | 13:15 |
| Rush Request: | Standard | Analyzed by: | see "By" below | | |
| P.O.#: | ELKH026001 | | | | |

## Laboratory Data

SDG ID: GCV38887
Phoenix ID: CV38887

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: MW-1

| Parameter | Result | RL/ PQL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|
| Silver | < 0.001 | 0.001 | mg/L | 1 | 03/03/26 | TH | SW6010D |
| Arsenic | < 0.004 | 0.004 | mg/L | 1 | 03/03/26 | TH | SW6010D |
| Barium | 0.682 | 0.002 | mg/L | 1 | 03/03/26 | TH | SW6010D |
| Cadmium | < 0.001 | 0.001 | mg/L | 1 | 03/03/26 | TH | SW6010D |
| Chromium | < 0.001 | 0.001 | mg/L | 1 | 03/03/26 | TH | SW6010D |
| Copper | < 0.005 | 0.005 | mg/L | 1 | 03/03/26 | TH | SW6010D |
| Mercury | < 0.0002 | 0.0002 | mg/L | 1 | 03/03/26 | ZT | SW7470A |
| Nickel | 0.002 | 0.001 | mg/L | 1 | 03/03/26 | TH | SW6010D |
| Lead | 0.002 | 0.001 | mg/L | 1 | 03/03/26 | TH | SW6010D |
| Selenium | < 0.010 | 0.010 | mg/L | 1 | 03/03/26 | TH | SW6010D |
| Zinc | 0.026 | 0.004 | mg/L | 1 | 03/03/26 | TH | SW6010D |
| Mercury Digestion | Completed | | | | 03/03/26 | /SD | SW7470A |
| Semi-Volatile Extraction | Completed | | | | 03/03/26 | L/RB | SW3520C |
| Total Metals Digestion | Completed | | | | 03/02/26 | AG | SW3010A |

## Volatiles

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| 1,1,1,2-Tetrachloroethane | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D |
| 1,1,1-Trichloroethane | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D |
| 1,1,2,2-Tetrachloroethane | ND | 1.0 | ug/L | 2 | 03/11/26 | MH | SW8260D |
| 1,1,2-Trichloroethane | ND | 1.0 | ug/L | 2 | 03/11/26 | MH | SW8260D |
| 1,1-Dichloroethane | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D |
| 1,1-Dichloroethene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D |
| 1,1-Dichloropropene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D |
| 1,2,3-Trichlorobenzene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D |
| 1,2,3-Trichloropropane | ND | 0.50 | ug/L | 2 | 03/11/26 | MH | SW8260D |
| 1,2,4-Trichlorobenzene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D |
| 1,2,4-Trimethylbenzene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D |

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: MW-1

Phoenix I.D.: CV38887

| Parameter | Result | RL/ PQL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|
| 1,2-Dibromo-3-chloropropane | ND | 1.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| 1,2-Dibromoethane | ND | 0.50 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| 1,2-Dichlorobenzene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| 1,2-Dichloroethane | ND | 0.60 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| 1,2-Dichloropropane | ND | 1.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| 1,3,5-Trimethylbenzene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| 1,3-Dichlorobenzene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| 1,3-Dichloropropane | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| 1,4-Dichlorobenzene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| 2,2-Dichloropropane | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| 2-Chlorotoluene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| 2-Hexanone | ND | 10 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| 2-Isopropyltoluene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | 1 |
| 4-Chlorotoluene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| 4-Methyl-2-pentanone | ND | 10 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Acetone | ND | 50 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Acrylonitrile | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Benzene | 2.3 | 1.4 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Bromobenzene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Bromochloromethane | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Bromodichloromethane | ND | 1.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Bromoform | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Bromomethane | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Carbon Disulfide | ND | 10 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Carbon tetrachloride | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Chlorobenzene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Chloroethane | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Chloroform | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Chloromethane | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| cis-1,2-Dichloroethene | 190 | 10 | ug/L | 10 | 03/10/26 | MH | SW8260D | |
| cis-1,3-Dichloropropene | ND | 0.50 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Dibromochloromethane | ND | 1.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Dibromomethane | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Dichlorodifluoromethane | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Ethylbenzene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Hexachlorobutadiene | ND | 0.50 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Isopropylbenzene | 2.3 | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| m&p-Xylene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Methyl ethyl ketone | ND | 10 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Methyl t-butyl ether (MTBE) | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Methylene chloride | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Naphthalene | 56 | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| n-Butylbenzene | 3.6 | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| n-Propylbenzene | 4.6 | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| o-Xylene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| p-Isopropyltoluene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| sec-Butylbenzene | 3.9 | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Styrene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| tert-Butylbenzene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: MW-1

Phoenix I.D.: CV38887

| Parameter | Result | RL/ PQL | Units | Dilution | Date/Time | By | Reference | |
|---|---|---|---|---|---|---|---|---|
| Tetrachloroethene | 210 | 10 | ug/L | 10 | 03/10/26 | MH | SW8260D | |
| Tetrahydrofuran (THF) | ND | 5.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | 1 |
| Toluene | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Total Xylenes | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| trans-1,2-Dichloroethene | 2.4 | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| trans-1,3-Dichloropropene | ND | 0.50 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| trans-1,4-dichloro-2-butene | ND | 5.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Trichloroethene | 81 | 10 | ug/L | 10 | 03/10/26 | MH | SW8260D | |
| Trichlorofluoromethane | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Trichlorotrifluoroethane | ND | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| Vinyl chloride | 48 | 2.0 | ug/L | 2 | 03/11/26 | MH | SW8260D | |
| **QA/QC Surrogates** | | | | | | | | |
| % 1,2-dichlorobenzene-d4 (2x) | 100 | | % | 2 | 03/11/26 | MH | 70 - 130 % | |
| % Bromofluorobenzene (2x) | 101 | | % | 2 | 03/11/26 | MH | 70 - 130 % | |
| % Dibromofluoromethane (2x) | 102 | | % | 2 | 03/11/26 | MH | 70 - 130 % | |
| % Toluene-d8 (2x) | 100 | | % | 2 | 03/11/26 | MH | 70 - 130 % | |
| % 1,2-dichlorobenzene-d4 (10x) | 99 | | % | 10 | 03/10/26 | MH | 70 - 130 % | |
| % Bromofluorobenzene (10x) | 95 | | % | 10 | 03/10/26 | MH | 70 - 130 % | |
| % Dibromofluoromethane (10x) | 110 | | % | 10 | 03/10/26 | MH | 70 - 130 % | |
| % Toluene-d8 (10x) | 96 | | % | 10 | 03/10/26 | MH | 70 - 130 % | |

## Semivolatiles by SIM, PAH

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 2-Methylnaphthalene | 5.2 | 0.48 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| Acenaphthene | 5.6 | 0.48 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| Acenaphthylene | ND | 0.48 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| Anthracene | 2.1 | 0.48 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| Benzo(a)anthracene | 0.17 | 0.02 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| Benzo(a)pyrene | 0.08 | 0.02 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| Benzo(b)fluoranthene | 0.07 | 0.02 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| Benzo(ghi)perylene | ND | 0.48 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| Benzo(k)fluoranthene | 0.06 | 0.02 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| Chrysene | 0.14 | 0.02 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| Dibenz(a,h)anthracene | ND | 0.48 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| Fluoranthene | 2.7 | 0.48 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| Fluorene | 4.1 | 0.48 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| Indeno(1,2,3-cd)pyrene | 0.06 | 0.02 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| Naphthalene | 33 | 0.10 | ug/L | 1 | 03/06/26 | MR | SW8270E | |
| Phenanthrene | 7.5 | 0.48 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| Pyrene | 1.7 | 0.48 | ug/L | 1 | 03/04/26 | MR | SW8270E (SIM) | |
| **QA/QC Surrogates** | | | | | | | | |
| % 2-Fluorobiphenyl | 72 | | % | 1 | 03/06/26 | MR | 30 - 130 % | |
| % Nitrobenzene-d5 | 87 | | % | 1 | 03/06/26 | MR | 30 - 130 % | |
| % Terphenyl-d14 | 71 | | % | 1 | 03/06/26 | MR | 30 - 130 % | |

Project ID: 1 VINE ST, LARCHMONT, NY
Client ID: MW-1

Phoenix I.D.: CV38887

| Parameter | Result | RL/ PQL | Units | Dilution | Date/Time | By | Reference |
|---|---|---|---|---|---|---|---|

1 = This parameter is not certified by the primary accrediting authority (NY NELAC) for this matrix. NY NELAC does not offer certification for all parameters at this time.

RL/PQL=Reporting/Practical Quantitation Level (Equivalent to NELAC LOQ, Limit of Quantitation) ND=Not Detected at RL/PQL
BRL=Below Reporting Level L=Biased Low
QA/QC Surrogates: Surrogates are compounds (preceeded with a %) added by the lab to determine analysis efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

## Comments:

Volatile Comment:
Elevated reporting limits for volatiles due to the presence of target and/or non-target compounds.

Volatile Comment:
To achieve client's objectives, where the lowest calibration standard or LOD justifies lowering the RL/PQL, the RL/PQL of some compounds have been lowered to meet criteria.

If you are the client above and have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext.200.
The contents of this report cannot be discussed with anyone other than the client listed above without their written consent.

**Phyllis Shiller, Laboratory Director**

**March 12, 2026**

**Reviewed and Released by: Greg Lawrence, Assistant Lab Director**

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

NY # 11301

# QA/QC Report

March 12, 2026

## QA/QC Data

SDG I.D.: GCV38887

| Parameter | Blank | Blk RL | Sample Result | Dup Result | Dup RPD | LCS % | LCSD % | LCS RPD | MS % | MSD % | MS RPD | % Rec Limits | % RPD Limits |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| QA/QC Batch 828423 (mg/L), QC Sample No: CV38472 (CV38887) | | | | | | | | | | | | | |
| Mercury - Water | BRL | 0.0002 | <0.0002 | <0.0002 | NC | 91.6 | | | 89.3 | 88.1 | 1.4 | 80 - 120 | 20 |
| Comment: Additional Mercury Criteria: LCS acceptance range is 80-120% for aqueous and for soils the acceptance range is set by vendor limits. MS acceptance range is 75-125% for aqueous and 80-120% for soils. | | | | | | | | | | | | | |
| QA/QC Batch 828363 (mg/L), QC Sample No: CV38497 (CV38887) | | | | | | | | | | | | | |
| ICP Metals - Aqueous | | | | | | | | | | | | | |
| Arsenic | BRL | 0.004 | <0.004 | <0.004 | NC | 97.4 | 96.1 | 1.3 | 97.7 | | | 80 - 120 | 20 |
| Barium | BRL | 0.002 | 0.104 | 0.103 | 1.00 | 108 | 108 | 0.0 | 105 | | | 80 - 120 | 20 |
| Cadmium | BRL | 0.001 | <0.001 | <0.001 | NC | 107 | 105 | 1.9 | 101 | | | 80 - 120 | 20 |
| Chromium | BRL | 0.001 | <0.001 | <0.001 | NC | 106 | 105 | 0.9 | 102 | | | 80 - 120 | 20 |
| Copper | BRL | 0.005 | <0.005 | <0.005 | NC | 108 | 108 | 0.0 | 108 | | | 80 - 120 | 20 |
| Lead | BRL | 0.001 | <0.001 | <0.001 | NC | 106 | 105 | 0.9 | 102 | | | 80 - 120 | 20 |
| Nickel | BRL | 0.001 | <0.001 | <0.001 | NC | 106 | 104 | 1.9 | 99.7 | | | 80 - 120 | 20 |
| Selenium | BRL | 0.010 | <0.010 | <0.010 | NC | 94.2 | 91.7 | 2.7 | 92.5 | | | 80 - 120 | 20 |
| Silver | BRL | 0.001 | <0.001 | <0.001 | NC | 102 | 101 | 1.0 | 102 | | | 80 - 120 | 20 |
| Zinc | BRL | 0.004 | 0.006 | 0.006 | NC | 103 | 102 | 1.0 | 101 | | | 80 - 120 | 20 |
| Comment: Additional Criteria: LCS acceptance range is 80-120% for aqueous and for soils the acceptance range is set by vendor limits. MS acceptance range 75-125%. | | | | | | | | | | | | | |

Environmental Laboratories, Inc.
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
Tel. (860) 645-1102

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# QA/QC Report

March 12, 2026

## QA/QC Data

SDG I.D.: GCV38887

| Parameter | Blank | Blk RL | LCS % | LCSD % | LCS RPD | MS % | MSD % | MS RPD | % Rec Limits | % RPD Limits | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| QA/QC Batch 828498 (ug/L), QC Sample No: CV38646 (CV38887) | | | | | | | | | | | |
| **Semivolatiles by SIM, PAH - Ground Water** | | | | | | | | | | | |
| 2-Methylnaphthalene | ND | 0.50 | 82 | 102 | 21.7 | | | | 30 - 130 | 20 | r |
| Acenaphthene | ND | 0.50 | 77 | 67 | 13.9 | | | | 30 - 130 | 20 | |
| Acenaphthylene | ND | 0.10 | 68 | 19 | 112.6 | | | | 30 - 130 | 20 | l,r |
| Anthracene | ND | 0.10 | 85 | 71 | 17.9 | | | | 30 - 130 | 20 | |
| Benzo(a)anthracene | ND | 0.02 | 92 | 85 | 7.9 | | | | 30 - 130 | 20 | |
| Benzo(a)pyrene | ND | 0.02 | 83 | 59 | 33.8 | | | | 30 - 130 | 20 | r |
| Benzo(b)fluoranthene | ND | 0.02 | 89 | 95 | 6.5 | | | | 30 - 130 | 20 | |
| Benzo(ghi)perylene | ND | 0.02 | 77 | 66 | 15.4 | | | | 30 - 130 | 20 | |
| Benzo(k)fluoranthene | ND | 0.02 | 82 | 80 | 2.5 | | | | 30 - 130 | 20 | |
| Chrysene | ND | 0.02 | 86 | 83 | 3.6 | | | | 30 - 130 | 20 | |
| Dibenz(a,h)anthracene | ND | 0.02 | 79 | 79 | 0.0 | | | | 30 - 130 | 20 | |
| Fluoranthene | ND | 0.50 | 91 | 85 | 6.8 | | | | 30 - 130 | 20 | |
| Fluorene | ND | 0.10 | 79 | 77 | 2.6 | | | | 30 - 130 | 20 | |
| Indeno(1,2,3-cd)pyrene | ND | 0.02 | 84 | 74 | 12.7 | | | | 30 - 130 | 20 | |
| Naphthalene | ND | 0.50 | 69 | 85 | 20.8 | | | | 30 - 130 | 20 | r |
| Phenanthrene | ND | 0.06 | 74 | 72 | 2.7 | | | | 30 - 130 | 20 | |
| Pyrene | ND | 0.07 | 89 | 60 | 38.9 | | | | 30 - 130 | 20 | r |
| % 2-Fluorobiphenyl | 70 | % | 72 | 69 | 4.3 | | | | 30 - 130 | 20 | |
| % Nitrobenzene-d5 | 74 | % | 72 | 69 | 4.3 | | | | 30 - 130 | 20 | |
| % Terphenyl-d14 | 89 | % | 88 | 82 | 7.1 | | | | 30 - 130 | 20 | |

Comment:

A LCS and LCS Duplicate were performed instead of a matrix spike and matrix spike duplicate.

Additional 8270 criteria:20% of compounds can be outside of acceptance criteria as long as recovery is at least 10%. (Acid surrogates acceptance range for aqueous samples: 15-110%, for soils 30-130%)

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| QA/QC Batch 829923 (ug/L), QC Sample No: CV38652 (CV38887 (2X) ) | | | | | | | | | | | |
| **Volatiles - Ground Water** | | | | | | | | | | | |
| 1,1,1,2-Tetrachloroethane | ND | 1.0 | 105 | 108 | 2.8 | | | | 70 - 130 | 20 | |
| 1,1,1-Trichloroethane | ND | 1.0 | 115 | 113 | 1.8 | | | | 70 - 130 | 20 | |
| 1,1,2,2-Tetrachloroethane | ND | 0.50 | 86 | 93 | 7.8 | | | | 70 - 130 | 20 | |
| 1,1,2-Trichloroethane | ND | 1.0 | 96 | 99 | 3.1 | | | | 70 - 130 | 20 | |
| 1,1-Dichloroethane | ND | 1.0 | 98 | 97 | 1.0 | | | | 70 - 130 | 20 | |
| 1,1-Dichloroethene | ND | 1.0 | 115 | 110 | 4.4 | | | | 70 - 130 | 20 | |
| 1,1-Dichloropropene | ND | 1.0 | 102 | 102 | 0.0 | | | | 70 - 130 | 20 | |
| 1,2,3-Trichlorobenzene | ND | 1.0 | 101 | 105 | 3.9 | | | | 70 - 130 | 20 | |
| 1,2,3-Trichloropropane | ND | 1.0 | 90 | 96 | 6.5 | | | | 70 - 130 | 20 | |
| 1,2,4-Trichlorobenzene | ND | 1.0 | 98 | 104 | 5.9 | | | | 70 - 130 | 20 | |
| 1,2,4-Trimethylbenzene | ND | 1.0 | 95 | 103 | 8.1 | | | | 70 - 130 | 20 | |
| 1,2-Dibromo-3-chloropropane | ND | 1.0 | 84 | 87 | 3.5 | | | | 70 - 130 | 20 | |
| 1,2-Dibromoethane | ND | 1.0 | 100 | 102 | 2.0 | | | | 70 - 130 | 20 | |
| 1,2-Dichlorobenzene | ND | 1.0 | 89 | 97 | 8.6 | | | | 70 - 130 | 20 | |

# QA/QC Data

SDG I.D.: GCV38887

| Parameter | Blank | Blk RL | LCS % | LCSD % | LCS RPD | MS % | MSD % | MS RPD | % Rec Limits | % RPD Limits |
|---|---|---|---|---|---|---|---|---|---|---|
| 1,2-Dichloroethane | ND | 1.0 | 113 | 110 | 2.7 | | | | 70 - 130 | 20 |
| 1,2-Dichloropropane | ND | 1.0 | 93 | 92 | 1.1 | | | | 70 - 130 | 20 |
| 1,3,5-Trimethylbenzene | ND | 1.0 | 96 | 102 | 6.1 | | | | 70 - 130 | 20 |
| 1,3-Dichlorobenzene | ND | 1.0 | 94 | 97 | 3.1 | | | | 70 - 130 | 20 |
| 1,3-Dichloropropane | ND | 1.0 | 98 | 100 | 2.0 | | | | 70 - 130 | 20 |
| 1,4-Dichlorobenzene | ND | 1.0 | 94 | 98 | 4.2 | | | | 70 - 130 | 20 |
| 2,2-Dichloropropane | ND | 1.0 | 121 | 121 | 0.0 | | | | 70 - 130 | 20 |
| 2-Chlorotoluene | ND | 1.0 | 88 | 94 | 6.6 | | | | 70 - 130 | 20 |
| 2-Hexanone | ND | 5.0 | 84 | 87 | 3.5 | | | | 70 - 130 | 20 |
| 2-Isopropyltoluene | ND | 1.0 | 94 | 98 | 4.2 | | | | 70 - 130 | 20 |
| 4-Chlorotoluene | ND | 1.0 | 89 | 97 | 8.6 | | | | 70 - 130 | 20 |
| 4-Methyl-2-pentanone | ND | 5.0 | 87 | 85 | 2.3 | | | | 70 - 130 | 20 |
| Acetone | ND | 5.0 | 91 | 90 | 1.1 | | | | 70 - 130 | 20 |
| Acrylonitrile | ND | 5.0 | 80 | 80 | 0.0 | | | | 70 - 130 | 20 |
| Benzene | ND | 0.70 | 98 | 97 | 1.0 | | | | 70 - 130 | 20 |
| Bromobenzene | ND | 1.0 | 96 | 98 | 2.1 | | | | 70 - 130 | 20 |
| Bromochloromethane | ND | 1.0 | 98 | 95 | 3.1 | | | | 70 - 130 | 20 |
| Bromodichloromethane | ND | 0.50 | 109 | 104 | 4.7 | | | | 70 - 130 | 20 |
| Bromoform | ND | 1.0 | 103 | 105 | 1.9 | | | | 70 - 130 | 20 |
| Bromomethane | ND | 1.0 | 93 | 102 | 9.2 | | | | 70 - 130 | 20 |
| Carbon Disulfide | ND | 1.0 | 110 | 109 | 0.9 | | | | 70 - 130 | 20 |
| Carbon tetrachloride | ND | 1.0 | 115 | 116 | 0.9 | | | | 70 - 130 | 20 |
| Chlorobenzene | ND | 1.0 | 96 | 97 | 1.0 | | | | 70 - 130 | 20 |
| Chloroethane | ND | 1.0 | 117 | 120 | 2.5 | | | | 70 - 130 | 20 |
| Chloroform | ND | 1.0 | 103 | 101 | 2.0 | | | | 70 - 130 | 20 |
| Chloromethane | ND | 1.0 | 89 | 84 | 5.8 | | | | 70 - 130 | 20 |
| cis-1,3-Dichloropropene | ND | 0.40 | 101 | 102 | 1.0 | | | | 70 - 130 | 20 |
| Dibromochloromethane | ND | 0.50 | 101 | 101 | 0.0 | | | | 70 - 130 | 20 |
| Dibromomethane | ND | 1.0 | 102 | 100 | 2.0 | | | | 70 - 130 | 20 |
| Dichlorodifluoromethane | ND | 1.0 | 115 | 118 | 2.6 | | | | 70 - 130 | 20 |
| Ethylbenzene | ND | 1.0 | 95 | 96 | 1.0 | | | | 70 - 130 | 20 |
| Hexachlorobutadiene | ND | 0.40 | 101 | 106 | 4.8 | | | | 70 - 130 | 20 |
| Isopropylbenzene | ND | 1.0 | 92 | 98 | 6.3 | | | | 70 - 130 | 20 |
| m&p-Xylene | ND | 1.0 | 95 | 97 | 2.1 | | | | 70 - 130 | 20 |
| Methyl ethyl ketone | ND | 5.0 | 86 | 86 | 0.0 | | | | 70 - 130 | 20 |
| Methyl t-butyl ether (MTBE) | ND | 1.0 | 108 | 108 | 0.0 | | | | 70 - 130 | 20 |
| Methylene chloride | ND | 1.0 | 93 | 93 | 0.0 | | | | 70 - 130 | 20 |
| Naphthalene | ND | 1.0 | 98 | 102 | 4.0 | | | | 70 - 130 | 20 |
| n-Butylbenzene | ND | 1.0 | 98 | 101 | 3.0 | | | | 70 - 130 | 20 |
| n-Propylbenzene | ND | 1.0 | 94 | 96 | 2.1 | | | | 70 - 130 | 20 |
| o-Xylene | ND | 1.0 | 94 | 91 | 3.2 | | | | 70 - 130 | 20 |
| p-Isopropyltoluene | ND | 1.0 | 94 | 98 | 4.2 | | | | 70 - 130 | 20 |
| sec-Butylbenzene | ND | 1.0 | 90 | 99 | 9.5 | | | | 70 - 130 | 20 |
| Styrene | ND | 1.0 | 97 | 99 | 2.0 | | | | 70 - 130 | 20 |
| tert-Butylbenzene | ND | 1.0 | 94 | 100 | 6.2 | | | | 70 - 130 | 20 |
| Tetrahydrofuran (THF) | ND | 2.5 | 90 | 88 | 2.2 | | | | 70 - 130 | 20 |
| Toluene | ND | 1.0 | 99 | 93 | 6.3 | | | | 70 - 130 | 20 |
| trans-1,2-Dichloroethene | ND | 1.0 | 105 | 102 | 2.9 | | | | 70 - 130 | 20 |
| trans-1,3-Dichloropropene | ND | 0.40 | 110 | 106 | 3.7 | | | | 70 - 130 | 20 |
| trans-1,4-dichloro-2-butene | ND | 5.0 | 89 | 92 | 3.3 | | | | 70 - 130 | 20 |
| Trichlorofluoromethane | ND | 1.0 | 123 | 122 | 0.8 | | | | 70 - 130 | 20 |
| Trichlorotrifluoroethane | ND | 1.0 | 135 | 130 | 3.8 | | | | 70 - 130 | 20 |
| Vinyl chloride | ND | 1.0 | 100 | 98 | 2.0 | | | | 70 - 130 | 20 |

# QA/QC Data

SDG I.D.: GCV38887

| Parameter | Blank | Blk RL | | LCS % | LCSD % | LCS RPD | MS % | MSD % | MS RPD | % Rec Limits | % RPD Limits |
|---|---|---|---|---|---|---|---|---|---|---|---|
| % 1,2-dichlorobenzene-d4 | 98 | % | | 93 | 100 | 7.3 | | | | 70 - 130 | 20 |
| % Bromofluorobenzene | 96 | % | | 99 | 99 | 0.0 | | | | 70 - 130 | 20 |
| % Dibromofluoromethane | 107 | % | | 104 | 102 | 1.9 | | | | 70 - 130 | 20 |
| % Toluene-d8 | 97 | % | | 98 | 97 | 1.0 | | | | 70 - 130 | 20 |

Comment:

A LCS and LCS Duplicate were performed instead of a matrix spike and matrix spike duplicate.

Additional 8260 criteria: 10% of LCS/LCSD compounds can be outside of acceptance criteria as long as recovery is 40-160%.

QA/QC Batch 829676 (ug/L), QC Sample No: CV44095 (CV38887 (10X) )

## Volatiles - Ground Water

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| cis-1,2-Dichloroethene | ND | 1.0 | | 108 | 106 | 1.9 | | | | 70 - 130 | 20 |
| Tetrachloroethene | ND | 1.0 | | 106 | 107 | 0.9 | | | | 70 - 130 | 20 |
| Trichloroethene | ND | 1.0 | | 105 | 103 | 1.9 | | | | 70 - 130 | 20 |
| % 1,2-dichlorobenzene-d4 | 94 | % | | 97 | 95 | 2.1 | | | | 70 - 130 | 20 |
| % Bromofluorobenzene | 93 | % | | 95 | 100 | 5.1 | | | | 70 - 130 | 20 |
| % Dibromofluoromethane | 104 | % | | 107 | 108 | 0.9 | | | | 70 - 130 | 20 |
| % Toluene-d8 | 96 | % | | 93 | 99 | 6.3 | | | | 70 - 130 | 20 |

Comment:

A LCS and LCS Duplicate were performed instead of a matrix spike and matrix spike duplicate.

Additional 8260 criteria: 10% of LCS/LCSD compounds can be outside of acceptance criteria as long as recovery is 40-160%.

l = This parameter is outside laboratory LCS/LCSD specified recovery limits.
r = This parameter is outside laboratory RPD specified recovery limits.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

RPD - Relative Percent Difference
LCS - Laboratory Control Sample
LCSD - Laboratory Control Sample Duplicate
MS - Matrix Spike
MS Dup - Matrix Spike Duplicate
NC - No Criteria
Intf - Interference
(ISO) - Isotope Dilution

Phyllis Shiller, Laboratory Director
March 12, 2026

Thursday, March 12, 2026

Criteria: NY: GW

State: NY

# Sample Criteria Exceedances Report

## GCV38887 - PENNONI-CT

| SampNo | Acode | Phoenix Analyte | Criteria | Result | RL | Criteria | RL Criteria | Analysis Units |
|---|---|---|---|---|---|---|---|---|
| CV38887 | $8100SIMR | Benzo(k)fluoranthene | NY / TAGM - Semi-Volatiles / Groundwater Standards | 0.06 | 0.02 | 0.002 | 0.002 | ug/L |
| CV38887 | $8100SIMR | Naphthalene | NY / TAGM - Semi-Volatiles / Groundwater Standards | 33 | 0.10 | 10 | 10 | ug/L |
| CV38887 | $8100SIMR | Benzo(a)pyrene | NY / TAGM - Semi-Volatiles / Groundwater Standards | 0.08 | 0.02 | 0.002 | 0.002 | ug/L |
| CV38887 | $8100SIMR | Benzo(b)fluoranthene | NY / TAGM - Semi-Volatiles / Groundwater Standards | 0.07 | 0.02 | 0.002 | 0.002 | ug/L |
| CV38887 | $8100SIMR | Benzo(a)anthracene | NY / TAGM - Semi-Volatiles / Groundwater Standards | 0.17 | 0.02 | 0.002 | 0.002 | ug/L |
| CV38887 | $8100SIMR | Indeno(1,2,3-cd)pyrene | NY / TAGM - Semi-Volatiles / Groundwater Standards | 0.06 | 0.02 | 0.002 | 0.002 | ug/L |
| CV38887 | $8100SIMR | Chrysene | NY / TAGM - Semi-Volatiles / Groundwater Standards | 0.14 | 0.02 | 0.002 | 0.002 | ug/L |
| CV38887 | $8100SIMR | Naphthalene | NY / TAGM - Volatile Organics / Groundwater Standards | 33 | 0.10 | 5 | 5 | ug/L |
| CV38887 | $8100SIMR | Naphthalene | NY / TOGS - Water Quality / GA Criteria | 33 | 0.10 | 10 | 10 | ug/L |
| CV38887 | $8100SIMR | Chrysene | NY / TOGS - Water Quality / GA Criteria | 0.14 | 0.02 | 0.002 | 0.002 | ug/L |
| CV38887 | $8100SIMR | Indeno(1,2,3-cd)pyrene | NY / TOGS - Water Quality / GA Criteria | 0.06 | 0.02 | 0.002 | 0.002 | ug/L |
| CV38887 | $8100SIMR | Benzo(k)fluoranthene | NY / TOGS - Water Quality / GA Criteria | 0.06 | 0.02 | 0.002 | 0.002 | ug/L |
| CV38887 | $8100SIMR | Benzo(b)fluoranthene | NY / TOGS - Water Quality / GA Criteria | 0.07 | 0.02 | 0.002 | 0.002 | ug/L |
| CV38887 | $8100SIMR | Benzo(a)anthracene | NY / TOGS - Water Quality / GA Criteria | 0.17 | 0.02 | 0.002 | 0.002 | ug/L |
| CV38887 | $8260GWR | Naphthalene | NY / TAGM - Semi-Volatiles / Groundwater Standards | 56 | 2.0 | 10 | 10 | ug/L |
| CV38887 | $8260GWR | Benzene | NY / TAGM - Volatile Organics / Groundwater Standards | 2.3 | 1.4 | 0.7 | 0.7 | ug/L |
| CV38887 | $8260GWR | Naphthalene | NY / TAGM - Volatile Organics / Groundwater Standards | 56 | 2.0 | 5 | 5 | ug/L |
| CV38887 | $8260GWR | Tetrachloroethene | NY / TAGM - Volatile Organics / Groundwater Standards | 210 | 10 | 5 | 5 | ug/L |
| CV38887 | $8260GWR | Trichloroethene | NY / TAGM - Volatile Organics / Groundwater Standards | 81 | 10 | 5 | 5 | ug/L |
| CV38887 | $8260GWR | Vinyl chloride | NY / TAGM - Volatile Organics / Groundwater Standards | 48 | 2.0 | 2 | 2 | ug/L |
| CV38887 | $8260GWR | 1,2-Dibromoethane | NY / TOGS - Water Quality / GA Criteria | ND | 0.50 | 0.0006 | 0.0006 | ug/L |
| CV38887 | $8260GWR | 1,2-Dibromo-3-chloropropane | NY / TOGS - Water Quality / GA Criteria | ND | 1.0 | 0.04 | 0.04 | ug/L |
| CV38887 | $8260GWR | Vinyl chloride | NY / TOGS - Water Quality / GA Criteria | 48 | 2.0 | 2 | 2 | ug/L |
| CV38887 | $8260GWR | Benzene | NY / TOGS - Water Quality / GA Criteria | 2.3 | 1.4 | 1 | 1 | ug/L |
| CV38887 | $8260GWR | cis-1,2-Dichloroethene | NY / TOGS - Water Quality / GA Criteria | 190 | 10 | 5 | 5 | ug/L |
| CV38887 | $8260GWR | cis-1,3-Dichloropropene | NY / TOGS - Water Quality / GA Criteria | ND | 0.50 | 0.4 | 0.4 | ug/L |
| CV38887 | $8260GWR | Naphthalene | NY / TOGS - Water Quality / GA Criteria | 56 | 2.0 | 10 | 10 | ug/L |
| CV38887 | $8260GWR | Tetrachloroethene | NY / TOGS - Water Quality / GA Criteria | 210 | 10 | 5 | 5 | ug/L |
| CV38887 | $8260GWR | trans-1,3-Dichloropropene | NY / TOGS - Water Quality / GA Criteria | ND | 0.50 | 0.4 | 0.4 | ug/L |
| CV38887 | $8260GWR | Trichloroethene | NY / TOGS - Water Quality / GA Criteria | 81 | 10 | 5 | 5 | ug/L |
| CV38887 | $8260GWR | 1,2,3-Trichloropropane | NY / TOGS - Water Quality / GA Criteria | ND | 0.50 | 0.04 | 0.04 | ug/L |

Phoenix Laboratories does not assume responsibility for the data contained in this exceedance report. It is provided as an additional tool to identify requested criteria exceedences. All efforts are made to ensure the accuracy of the data (obtained from appropriate agencies). A lack of exceedence information does not necessarily suggest conformance to the criteria. It is ultimately the site professional's responsibility to determine appropriate compliance.

**Environmental Laboratories, Inc.**
**587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045**
**Tel. (860) 645-1102 Fax (860) 645-0823**

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# Analysis Comments

March 12, 2026 SDG I.D.: GCV38887

The following analysis comments are made regarding exceptions to criteria not already noted in the Analysis Report or QA/QC Report:

### *VOA Narration*

**CHEM15 03/11/26-2:** CV38887

The following Continuing Calibration compounds did not meet % deviation criteria: Dichlorodifluoromethane 32%H (20%), Trichlorofluoromethane 26%H (20%), Trichlorotrifluoroethane 21%H (20%)
The following Continuing Calibration compounds did not meet Maximum % deviation criteria: None.

Up to eight compounds can be outside of ICAL %RSD criteria and up to sixteen compounds can be outside of CCAL %Dev criteria if less than 40%.

**Environmental Laboratories, Inc.**
**587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045**
**Tel. (860) 645-1102 Fax (860) 645-0823**

ACCREDITED IN ACCORDANCE WITH nelac NY # 11301

# NY Temperature Narration

**March 12, 2026**

**SDG I.D.: GCV38887**

The samples in this delivery group were received at 1.1°C.
(Note acceptance criteria for relevant matrices is above freezing up to 6°C)

Temp: 1 °C Coolant: Cooler: Yes ☐ No ☐ IPK ☐ ICE ☐ No ☐

# NY/NJ/PA CHAIN OF CUSTODY RECORD

Pg 1 of 1

PHOENIX Environmental Laboratories, Inc.

587 East Middle Turnpike, P.O. Box 370, Manchester, CT 06040
Email: Makrina Nolan, makrina@phoenixlabs.com
**Client Services (860) 645-1102**

**Contact Options:**
Phone:
Email(s): DaWilliams@pennoni.com

Customer: Pennoni
Address: 350 Fairfield Ave - Suite 404
Bridgeport, CT

Project: 1 Vine St, Larchmont, NY
Report to (name): Dave Williams
Invoice to:
QUOTE # :

Project P.O: ELKH026001

***This section MUST be completed with Bottle Quantities.***

Sampler's Signature: Mgnac Date: 2-27-26

**Matrix Code:**
**DW**=Drinking Water **GW**=Ground Water **SW**=Surface Water **STW** = Storm Water
**WW**=Waste Water **RW**=Raw Water **SE**=Sediment **SL**=Sludge **S**=Soil **C**=Concrete
**CLK**=Caulk **W**=Wipe **O**=Oil **B**=Bulk **L**=Liquid **X** = Other_____ **(Must define)**

Analysis Request

| PHOENIX USE ONLY SAMPLE # | Customer Sample Identification | Sample Matrix | Date Sampled | Time Sampled | *MS/MSD (May be billable at analysis unit rate) | VOC 8260 | SVOC-PAH | PCB | RCRA 8 Metals + Cu, Ni, Zn | GL Amber 8 oz. [ ] w/$H_3PO_4$ [ ] $NAHSO_4$ [ ] NH4CL | Soil VOA Vials [ ] methanol [ ] $H_2O$ | GL Soil container ( ) oz | GL Soil container ( ) oz | 40 ml VOA Vial [ ] As is [X] HCl [ ] $Na_2SO_3$ | GL Amber 1000ml [X] As is [ ] $H_2SO_4$ | PL As is [ ] 250ml [ ] 500ml [ ] 1000ml | PL $H_2SO_4$ [ ] 250ml [ ] 500ml [ ] 1000ml | PL HNO3 [X] 250ml [ ] 500ml | PL NAOH 250ml | Bacteria Bottle w/thio | Bacteria Bottle as is |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 38887 | MW-1 | GW | 27 Feb | 1120 | | X | X | [redacted] | X | | | | | 3 | 1[redacted] | | | 1 | | | |
| | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | |

| Relinquished by: | Accepted by: | Date: | Time: |
|---|---|---|---|
| [signature] | [signature] | 3/2/26 | 1156 |
| [signature] | [signature] | 3/2/26 | 13:15 |

**Turnaround:**
- ☐ 1 Day*
- ☐ 2 Days*
- ☐ 3 Days*
- ☐ 4 Days*
- ☐ 5 Days*
- ☒ Standard

* SURCHARGE APPLIES

**NJ**
- ☐ SRS Res. Criteria
- ☐ SRS Non-Res.
- ☐ SRS Migration to GW
- ☐ Impact to GW Soil Cleanup Criteria
- ☐ Impact to GW soil screen Criteria GW Criteria

**NY**
- ☒ TOGS GW
- ☐ CP-51 SOIL
- ☐ 375SCO Unrestricted Soil
- ☐ 375SCO Residential Soil
- ☐ 375SCO Residential Restricted Soil
- ☐ 375SCO Commercial Soil
- ☐ 375SCO Industrial Soil
- ☐ Subpart 5 DW

**PA**
- ☐ Clean Fill Limits
- ☐ PA-GW
- ☐ Reg Fill Limits
- ☐ Other:_____

**Comments, Special Requirements or Regulations:**
H=Hold do not run until Client emails

***MS/MSD are considered site samples and will be billed as such in accordance with the prices quoted.**

**Data Format:**
- ☐ Phoenix Std Report
- ☐ Excel
- ☒ PDF
- ☐ GIS/Key
- ☐ EQuIS
- ☐ NJ Hazsite EDD
- ☐ NY EZ EDD (ASP)
- ☐ Other

**Data Package:**
- ☐ NJ Reduced Deliv. *
- ☐ NY Enhanced (ASP B) *
- ☐ Other

State Samples Collected? NY

July 7, 2015

Mr. Carlos Torres
Westchester County Department of Health
145 Huguenot Street
New Rochelle, New York 10801

**Re: Underground Storage Tank Removal Report**
**J&F Chatsworth LTD**
**1 Vine Street**
**Larchmont, New York 10538**
**NYSDEC PBS #3-174394**
**NYSDEC Spill #15-01291**

Dear Mr. Torres:

Please find the attached *Underground Storage Tank Removal Summary Report* ("Report") prepared by American Petroleum Equipment & Construction Company, Inc. (American Petroleum), on behalf of J&F Chatsworth LTD, for the property located at 1 Vine Street in Larchmont, New York (the "Site").

Should you have any questions or comments regarding the information provided herein, please contact the undersigned at (845) 778-5110.

Respectfully Submitted,
**American Petroleum Equipment & Construction Company, Inc.**

Brian Weeks
Staff Geologist

Kevin Bradley
Project Manager/Geologist

Enclosure

cc: Giuseppe Sparano, J&F Chatsworth LTD
Dan Bendell, New York State Department of Environmental Conservation

# Underground Storage Tank Removal Report

**J&F Chatsworth LTD**
**1 Vine Street**
**Larchmont, New York**
**NYSDEC PBS #3-174394**
**NYSDEC Spill #15-01291**

*Prepared for:*

J&F Chatsworth
Mr. Giuseppe Sparano
1 Vine Street
Larchmont, New York

*Prepared by:*

**American Petroleum Equipment & Construction Company, Inc.**
63 Orange Avenue
Walden, New York 12586
July 2015

# TABLE OF CONTENTS


1.0 INTRODUCTION ..... 1

2.0 UNDERGROUND STORAGE TANK REMOVAL ACTIVITIES ..... 1

3.0 CONCLUSION/RECOMMENDATIONS ..... 2


**Figures**


Figure 1 Site Location Map
Figure 2 Site Map


**Appendix**


Appendix A Waste Disposal Manifests
Appendix B Photographs

## 1.0 INTRODUCTION

American Petroleum Equipment and Construction Company, Inc. (American Petroleum) was contracted by Mr. Giuseppe Sparano of J&F Chatsworth LTD to prepare this report documenting and summarizing the environmental services provided during remedial excavation and underground storage tank (UST) removal activities at the property located at 1 Vine Street in Larchmont, Westchester County, New York (the "Site"). The activities at the Site were performed in accordance with applicable local, state and federal regulations. A Site Location Map and a Site Map are included as **Figures 1** and **2**, respectively.

## 2.0 UNDERGROUND STORAGE TANK REMOVAL ACTIVITIES

On May 7, 2015, American Petroleum completed the removal of two 4,000 gallon double walled steel gasoline USTs from the Site. Groundwater was encountered during UST removal activities and in order to facilitate removal of the USTs a vacuum extraction truck was used to depress the water table. Approximately 730 gallons of groundwater were transported to Global Services of Albany, New York for disposal. The waste disposal manifests are included in **Appendix A**.

Prior to removal the USTs were purged of any residual liquids and product. Following UST removal activities American Petroleum cut, cleaned, and prepared the tanks for disposal. The American Petroleum field geologist inspected the tanks and documented that they were in good condition with no holes or pitting.

During excavation activities, soil samples were screened in the field for the presence of volatile organic compounds (VOCs) utilizing a hand held Mini Rae photo-ionization detector (PID) which was calibrated to 100 parts per million (ppm) isobutylene standard. Soils exhibiting elevated PID field screen readings were removed and stockpiled on-Site until arrangements could be made for disposal. Based upon the elevated PID readings the New York State Department of Environmental Conservation (NYSDEC) Spills Hotline was contacted and Spill #15-01291 was assigned to the Site.

During excavation of petroleum impacted soil it was determined that the USTs had been installed within the foundation of a previous building. The building (above grade) had been previously removed but the foundation remained in place and was constructed of concrete in all directions (four sidewalls and bottom). The foundation acted as a containment barrier which prevented further migration of petroleum to the environment and additionally is a structural footing for Vine Street and for the commercial building adjacent to Vine Street. As such no soil samples were collected due to the complete removal of all impacted soils located within the interior of the foundation walls. Excavation activities were not advanced beyond the foundation limits as the structural integrity of the building and road would likely have been compromised. Photographs of the excavation illustrating the concrete walls and foundation are included as **Appendix B.**

On June 12, 2015 approximately 11-tons of petroleum impacted soil was transported to the Deep Green facility in New Windsor, New York for disposal during remedial excavation activities at the Site. The waste disposal manifests documenting disposal of the petroleum impacted soil are included in **Appendix A**.

## 3.0 CONCLUSION/RECOMMENDATIONS

In May of 2015 American Petroleum completed the removal of two 4,000 USTs from the Site. As required by the NYSDEC, the condition of the UST was observed and documented by a field Geologist. The UST was in good condition with no detectable holes or pitting. American Petroleum excavated and transported approximately 11-tons of petroleum impacted soil to a disposal facility during UST removal activities.

Based on the field observations, the containment barrier (foundation walls), and the complete removal of petroleum impacted soil, American Petroleum recommends that no further action be required regarding Site conditions and requests that NYSDEC Spill #15-01291 be closed.

american petroleum
equipment & construction
*Naturally, leading the way*

## FIGURES

Site Location Map
Site Map

American Petroleum Equipment & Construction Company
63 Orange Avenue
Walden, New York 12586
Telephone: 845.778.5110
Fax: 845.778.4110


**Figure 1. Site Location Map**

J&F Chatsworth LTD
1 Vine Street, Larchmont, New York

| DRAWN | Scale | DATE | PBS # |
|---|---|---|---|
| B. Weeks | Not To Scale | 6-18-2015 | 3-174394 |

american petroleum
equipment & construction
*Naturally, leading the way*

**APPENDIX A**

Waste Disposal Manifests




American Petroleum Equipment & Construction Company
63 Orange Avenue
Walden, New York 12586
Telephone: 845.778.5110
Fax: 845.778.4110

***Figure 2. Site Map***

J&F Chatsworth LTD
1 Vine Street, Larchmont, New York

| DRAWN | SCALE | DATE | PBS # |
|---|---|---|---|
| B. Weeks | Not To Scale | 6-18-2015 | 3-174394 |

## APPENDIX B

Photographs

# SOIL TRACKING FORM — Deep Green of New York, Inc.

TRACKING FORM NO. (GIVEN BY DEEP GREEN)

| DATE OF SHIPMENT | RESPONSIBLE FOR PAYMENT | PART 364 VEHICLE PLATE NO. | FACILITY NO. | JOB NO. | LOAD NO. |
|---|---|---|---|---|---|
| | AMERICAN PETROLEUM | | B06 | DG101077 | |

**GENERATOR NAME AND BILLING ADDRESS**

J&F CHATSWORTH LTD
1 VINE STREET
Larchmont, 10538

GENERATOR PHONE NO.

GENERATOR CONTACT

GENERATOR FAX NO.

CUSTOMER ACCT. NO. WITH DEEP GREEN

**CONSULTANT NAME AND BILLING ADDRESS**

AMERICAN PETROLEUM
63 ORANGE AVE
WALDEN, NY12586

CONSULTANT PHONE NO.
845-778-5110

CONSULTANT CONTACT

CONSULTANT FAX NO.
845-778-4110

CUSTOMER ACCT. NO. WITH DEEP GREEN

**GENERATION SITE (TRANSPORT FROM) NAME AND ADDRESS**

J&F CHATSWORTH LTD
1 VINE STREET
Larchmont, 10538

SIT PHONE NO.

SITE CONTACT

SITE FAX NUMBER

**PCS PROCESSING FACILITY (TRANSPORT TO) NAME AND ADDRESS**

DEEP GREEN OF NEW YORK, INC.
1106 RIVER ROAD
NEW WINDSOR, NY 12553

FACILITY PHONE NO.
845-562-8778

PART 360 PERMIT NO.
3-3348-00150-00001-Q

FACILITY CONTACT
Amy Kane

FACILITY FAX NO.
845-562-9566

**TRANSPORTER NAME AND ADDRESS**

AMERICAN PETROLEUM
63 ORANGE AVE
WALDEN, NY12586
Permit No.: 3A-741

TRANSPORTER PHONE NO.
845-778-5110

TRANSPORTER PART 364 PERMIT NO.
3A-741

TRANSPORTER CONTACT

TRANSPORTER DOT NO.

TRANSPORTER FAX NO.
845-778-4110

CUSTOMER ACCT. NO. WITH DEEP GREEN

**MATERIAL TESTING**
*(CHECK APPROPRIATE BOXES FOR TESTS CONDUCTED)*

- ☒ TOTAL PETROLEUM HYDROCARBONS
- ☐ BENZENE (TOTAL)
- ☒ LEAD (TOTAL)
- ☐ BENZENE/TOLUENE/ETHYL BENZENE/XYLENE
- ☐ METHYL T-BUTYL ETHER (MTBE)
- ☒ HALOGENATED VOLATILE ORGANICS
- ☒ HEAVY METALS (TOTAL)
- ☐ OTHER *(PLEASE LIST)*:
- ☐ BENZENE (TCLP)
- ☐ LEAD (TCLP)
- ☐ HEAVY METALS (TCLP)

| DESCRIPTION OF DELIVERY | GROSS WEIGHT (TONS) | TARE WEIGHT (TONS) | NET WEIGHT (TONS) |
|---|---|---|---|
| NON HAZARDOUS PETROLEUM | 22.15 | 12.13 | 10.02 |
| CONTAMINATED SOIL | | | |

**GENERATOR'S AND/OR CONSULTANT'S CERTIFICATION:** I CERTIFY THAT THE SOIL REFERENCED HEREIN IS TAKEN ENTIRELY FROM THOSE SOILS DESCRIBED IN THE GENERATOR WASTE PROFILE SHEET COMPLETED AND CERTIFIED BY ME FOR THE GENERATION SITE SHOWN ABOVE AND NOTHING HAS BEEN ADDED OR DONE TO SUCH SOIL THAT WOULD ALTER IT IN ANY WAY. I HEREBY AFFIRM UNDER PENALTY OF PERJURY THAT INFORMATION PROVIDED ON THIS DOCUMENT IS TRUE TO THE BEST OF MY KNOWLEDGE AND BELIEF, AND THAT I HAVE THE AUTHORITY AS _____ (TITLE) OF _____ (ENTITY) TO SIGN THIS TRACKING DOCUMENT PURSUANT TO 6 NYCRR PART 360. I AM AWARE THAT ANY FALSE STATEMENT MADE HEREIN IS PUNISHABLE AS A CLASS A MISDEMEANOR PURSUANT TO SECTION 210.45 OF THE PENAL LAW.

| PRINT OR TYPE NAME | SIGNATURE | MONTH | DATE | YEAR |
|---|---|---|---|---|
| ☐ GENERATOR ☐ CONSULTANT Sharon Miller | Sharon Miller | 6 | 4 | 15 |

**TRANSPORTER'S CERTIFICATION:** I ACKNOWLEDGE RECEIPT OF THE SOIL DESCRIBED ABOVE AND CERTIFY THAT SUCH SOIL IS BEING DELIVERED IN EXACTLY THE SAME CONDITION AS WHEN RECEIVED. I FURTHER CERTIFY THAT THIS SOIL IS BEING DIRECTLY TRANSPORTED FROM THE GENERATION SITE TO THE PCS PROCESSING FACILITY WITHOUT OFF-LOADING, ADDING TO, SUBTRACTING FROM OR IN ANY WAY DELAYING DELIVERY TO SUCH SITE.

| PRINT OR TYPE NAME | SIGNATURE | MONTH | DATE | YEAR |
|---|---|---|---|---|
| Sharon Miller | Sharon Miller | 6 | 12 | 15 |

TRANSPORTER DISCREPANCY BOX *(ANY DISCREPANCIES IN THE TRANSPORTER NAME OR LOCATION, PCS PROCESSING NAME OR LOCATION, OR MATERIAL TESTING OR QUANTITY SHOULD BE NOTED HERE.)*

**PCS PROCESSING FACILITY CERTIFIES THE RECEIPT OF THE SOIL COVERED BY THIS SOIL TRACKING FORM EXCEPT AS NOTED BELOW.**

| PRINT OR TYPE NAME | SIGNATURE | MONTH | DATE | YEAR |
|---|---|---|---|---|
| | | 6 | 12 | 15 |

PROCESSING FACILITY DISCREPANCY BOX *(ANY DISCREPANCIES IN ABOVE INFORMATION SHOULD BE NOTED HERE.)*

**INSTRUCTIONS**

1. **GENERATOR** COMPLETES ALL ITEMS IN GENERATOR AND/OR CONSULTANT BOXES, RETAINS COPY #4, AND GIVES REMAINING COPIES TO TRANSPORTER.
2. **TRANSPORTER** COMPLETES ALL ITEMS IN TRANSPORTER BOXES, RETAINS COPY #3, AND GIVES REMAINING COPIES TO THE PROCESSING FACILITY.
3. **PROCESSING FACILITY** COMPLETES ALL ITEMS IN PROCESSING FACILITY BOXES, RETAINS COPY #2, AND RETURNS COPY #1 TO THE GENERATOR WITHIN TWO (2) WEEKS.

**GENERATOR/CONSULTANT COPY**

american petroleum
equipment & construction
*Naturally, leading the way*

63 Orange Ave., Walden, NY 12586 • Tel: 845.778.5110 • Fax: 845.778.4110 • www.apecco.biz

**Construction • Environmental • Service • Electrical • C-Store Renovations • Power Generator Systems**

american petroleum
equipment & construction
*Naturally, leading the way*

63 Orange Ave., Walden, NY 12586 • Tel: 845.778.5110 • Fax: 845.778.4110 • www.apecco.biz

**Construction • Environmental • Service • Electrical • C-Store Renovations • Power Generator Systems**

**Town of Mamaroneck**
**Building Department**
**740 West Boston Post Road**
**(914) 381-7830 Fax: (914) 381-8473**

# LETTER OF COMPLETION

**Certificate Number:** 2015-0255 **Date of Issue:** 12/3/2015

**Parcel Owner:** Mansisbro Inc
**Parcel ID:** 1-26-730
**Street Address:** 1-5 Vine St

**Applicant:** American Petroleum Equipment
63 Orange Ave
Walden,NY 12586

**Building Permit Number:** 2015-0255
**Permit Date:** 4/29/2015
**Description of Work:** Remove (2) 4,000 gallon UST.

Please be advised that work performed at the above premises under permit number : 2015-0255 issued on: 4/29/2015 has been completed to the satisfaction of this department.

**Ronald Carpaneto**
Director of Building

# Appendix C Site Reconnaissance Checklist and Photographs

LANGAN

# Site Reconnaissance Photographs

| Client Name: | Subject Property Location: | Project No. |
|---|---|---|
| One Vine LLC | One Vine Street, Larchmont, New York | 192019101 |

| Date | Photo No. |
|---|---|
| 4/13/26 | 1 |

**Direction Photo Taken:**

North

**Description:**

General view of the subject property

| Date | Photo No. |
|---|---|
| 4/13/26 | 2 |

**Direction Photo Taken:**

Northeast

**Description:**

The former drycleaning unit on the western side of the building

| Client Name: | Subject Property Location: | Project No. |
|---|---|---|
| One Vine LLC | One Vine Street, Larchmont, New York | 192019101 |

| Date | Photo No. |
|---|---|
| 4/13/26 | 3 |

**Direction Photo Taken:**

Northwest

**Description:**

The drycleaning machine in the unit

| Date | Photo No. |
|---|---|
| 4/13/26 | 4 |

**Direction Photo Taken:**

Northeast

**Description:**

Partial view of an apparent inactive gas-fired steam boiler in the drycleaning unit

| Client Name: | Subject Property Location: | Project No. |
|---|---|---|
| One Vine LLC | One Vine Street, Larchmont, New York | 192019101 |

| Date | Photo No. |
|---|---|
| 4/13/26 | 5 |

**Direction Photo Taken:**

Northeast

**Description:**

Empty plastic drums which were labeled for hazardous waste

| Date | Photo No. |
|---|---|
| 4/13/26 | 6 |

**Direction Photo Taken:**

Southwest

**Description:**

An apparent floor drain in a utility area in the drycleaning unit



| Client Name: | Subject Property Location: | Project No. |
|---|---|---|
| One Vine LLC | One Vine Street, Larchmont, New York | 192019101 |

| Date | Photo No. |
|---|---|
| 4/13/26 | 7 |

**Direction Photo Taken:**

East

**Description:**

Area of dilapidated floor in drycleaning unit

| Date | Photo No. |
|---|---|
| 4/13/26 | 8 |

**Direction Photo Taken:**

Southwest

**Description:**

The basement area underneath the southern side of the drycleaning unit

| Client Name: | Subject Property Location: | Project No. |
|---|---|---|
| One Vine LLC | One Vine Street, Larchmont, New York | 192019101 |

| Date | Photo No. |
|---|---|
| 4/13/26 | 9 |

**Direction Photo Taken:**

Down

**Description:**

A reported former in-ground hydraulic lift in the eastern corner of the building

| Date | Photo No. |
|---|---|
| 4/13/26 | 10 |

**Direction Photo Taken:**

Down

**Description:**

An apparent former floor drain in the eastern side of the automotive garage

| Client Name: | Subject Property Location: | Project No. |
|---|---|---|
| One Vine LLC | One Vine Street, Larchmont, New York | 192019101 |

| Date | Photo No. |
|---|---|
| 4/13/26 | 11 |

**Direction Photo Taken:**

North

**Description:**

A 250-gallon motor oil above-ground storage tank in the eastern side of the automotive garage

| Date | Photo No. |
|---|---|
| 4/13/26 | 12 |

**Direction Photo Taken:**

North

**Description:**

A parts washer in the eastern side of the automotive garage

| Client Name: | Subject Property Location: | Project No. |
|---|---|---|
| One Vine LLC | One Vine Street, Larchmont, New York | 192019101 |

| Date | Photo No. |
|---|---|
| 4/13/26 | 13 |

**Direction Photo Taken:**

Southeast

**Description:**

An anomaly in the central-eastern side of the automotive garage

| Date | Photo No. |
|---|---|
| 4/13/26 | 14 |

**Direction Photo Taken:**

West

**Description:**

A reported abandoned UST in the central-eastern area of the automotive garage

| Client Name: | Subject Property Location: | Project No. |
|---|---|---|
| One Vine LLC | One Vine Street, Larchmont, New York | 192019101 |

| Date | Photo No. |
|---|---|
| 4/13/26 | 15 |

**Direction Photo Taken:**

Northwest

**Description:**

The 250-gallon motor oil AST and 250-gallon waste oil AST in the central-eastern side of the automotive garage

| Date | Photo No. |
|---|---|
| 4/13/26 | 16 |

**Direction Photo Taken:**

North

**Description:**

The waste oil-fired ceiling-mounted boiler in the central-eastern side of the automotive garage

| Client Name: | Subject Property Location: | Project No. |
|---|---|---|
| One Vine LLC | One Vine Street, Larchmont, New York | 192019101 |

| Date | Photo No. |
|---|---|
| 4/13/26 | 17 |

**Direction Photo Taken:**

Northwest

**Description:**

Empty drums and partially filled waste oil drums staged in the central-eastern side of the automotive garage

| Date | Photo No. |
|---|---|
| 4/13/26 | 18 |

**Direction Photo Taken:**

Down

**Description:**

Interior of a slop sink in the central-eastern side of the automotive garage

| Client Name: | Subject Property Location: | Project No. |
|---|---|---|
| One Vine LLC | One Vine Street, Larchmont, New York | 192019101 |

| Date | Photo No. |
|---|---|
| 4/13/26 | 19 |

**Direction Photo Taken:**

Northeast

**Description:**

The spray booth on the western side of the automotive garage

| Date | Photo No. |
|---|---|
| 4/13/26 | 20 |

**Direction Photo Taken:**

West

**Description:**

Waste paint drums staged in the western side of the automotive garage

| Client Name: | Subject Property Location: | Project No. |
|---|---|---|
| One Vine LLC | One Vine Street, Larchmont, New York | 192019101 |

| Date | Photo No. |
|---|---|
| 4/13/26 | 21 |

**Direction Photo Taken:**

Down

**Description:**

Reported groundwater, note the light sheen, in the basement of the automotive garage

| Date | Photo No. |
|---|---|
| 4/13/26 | 22 |

**Direction Photo Taken:**

North

**Description:**

The central parking lot, which was previously developed as a gasoline station

| Client Name: | Subject Property Location: | Project No. |
|---|---|---|
| One Vine LLC | One Vine Street, Larchmont, New York | 192019101 |

| Date | Photo No. |
|---|---|
| 4/13/26 | 23 |

**Direction Photo Taken:**

Down

**Description:**

A monitoring well in the central parking lot area

| Date | Photo No. |
|---|---|
| 4/13/26 | 24 |

**Direction Photo Taken:**

Down

**Description:**

The reported location of the former UST vent pipes along the northern side of the central parking lot

| Client Name: | Subject Property Location: | Project No. |
|---|---|---|
| One Vine LLC | One Vine Street, Larchmont, New York | 192019101 |

| Date | Photo No. |
|---|---|
| 4/13/26 | 25 |

**Direction Photo Taken:**

Down

**Description:**

A monitoring well along the subject property boundary, near the eastern side of the automotive garage

| Date | Photo No. |
|---|---|
| 4/13/26 | 26 |

**Direction Photo Taken:**

Southeast

**Description:**

The municipal parking lot (Myrtle Boulevard), located to the north and west of the subject property

| Client Name: | Subject Property Location: | Project No. |
|---|---|---|
| One Vine LLC | One Vine Street, Larchmont, New York | 192019101 |

| Date | Photo No. |
|---|---|
| 4/13/26 | 27 |

**Direction Photo Taken:**

Southeast

**Description:**

The elevated parking and pedestrian access to Larchmont train station, overlying the New England Thruway (Interstate-95), which adjoins the subject property to the east

| Date | Photo No. |
|---|---|
| 4/13/26 | 28 |

**Direction Photo Taken:**

West

**Description:**

The adjacent park (Memorial Park), across Vine Street, to the south of the subject property

LANGAN

**PHASE I ESA SITE RECONNAISSANCE CHECKLIST**

**GENERAL INFORMATION**

Langan personnel: Olivia Miller
Date of site reconnaissance: 13 April 2026
Business name / subject property occupant: J & F Auto Body; unoccupied unit (formerly a drycleaner)
Full subject property address: 1 Vine Street, Larchmont, New York
Weather conditions: 68ºF, Sunny

| Features, Activities, Uses, and Conditions | Identified/Observed? | | | | Report Section(s) |
|---|---|---|---|---|---|
| **General Subject Property Setting** | **Yes** | | **No** | | |
| Current use(s) of the subject property | ☒ | | ☐ | | 2.0 |
| Past use(s) of the subject property | ☐ | | ☒ | | 3.1 |
| Current use(s) of adjoining properties | ☒ | | ☐ | | 4.1 |
| Past use(s) of adjoining properties | ☐ | | ☒ | | 4.2 |
| Current or past uses in the surrounding area | ☐ | | ☒ | | 4.1 and 4.2 |
| Geologic, hydrogeologic, hydrologic, and topographic conditions | ☒ | | ☐ | | 2.2 |
| Structures and other improvements at the subject property | ☒ | | ☐ | | 2.3 |
| Roads | ☐ | | ☒ | | 2.3 |
| Potable water supply/source for the subject property | ☒ | | ☐ | | 2.4 |
| Sewage disposal system for the subject property | ☒ | | ☐ | | 2.4 |
| **Interior/Exterior Features** | **At Interior?** | | **At Exterior?** | | **Report Section(s) (if yes)** |
| | **Yes** | **No** | **Yes** | **No** | |
| Hazardous substances and petroleum products in connection with identified uses | ☒ | ☐ | ☐ | ☒ | 2.5 |
| Storage tanks | ☒ | ☐ | ☐ | ☒ | 2.5.1 and 2.5.2 |
| Strong, pungent, or noxious odors and their sources | ☒ | ☐ | ☐ | ☒ | 2.6 |
| Standing surface water and pools or sumps containing liquids likely to be hazardous substances or petroleum products | ☒ | ☐ | ☐ | ☒ | 2.5 |
| Drums, totes, and intermediate bulk containers | ☒ | ☐ | ☐ | ☒ | 2.5.3 |
| Hazardous substance and petroleum product containers not in connection with identified uses | ☐ | ☒ | ☐ | ☒ | 2.5.4 |
| Unidentified substance containers | ☐ | ☒ | ☐ | ☒ | 2.5.4 |
| PCB-containing items | ☐ | ☒ | ☐ | ☒ | 2.5.4 |
| Heating/cooling | ☒ | ☐ | ☒ | ☐ | 2.4 |
| Stains or corrosion on floors, walls, or ceilings | ☒ | ☐ | ☐ | ☒ | 2.5 and 2.7 |
| Drains and sumps | ☒ | ☐ | ☐ | ☒ | 2.8 |
| Pits, ponds, or lagoons | ☒ | ☐ | ☐ | ☒ | 2.2.3 |
| Stained soil or pavement | ☐ | ☒ | ☐ | ☒ | 2.5 and 2.7 |
| Stressed vegetation | ☐ | ☒ | ☐ | ☒ | 2.9 |
| Solid waste | ☒ | ☐ | ☐ | ☒ | 2.7 |
| Water/wastewater | ☒ | ☐ | ☐ | ☒ | 2.8 and 2.9 |
| Wells | ☐ | ☒ | ☒ | ☐ | 2.2.3 |
| Septic systems or cesspools | ☐ | ☒ | ☐ | ☒ | 2.8 |

# Appendix D User Provided Information

Clear Form

# ASTM E1527-21 User Questionnaire

*Please complete the below form and return to Langan.*

Providing the following information (if available) to the environmental professional (Langan) is one of the requirements to qualify for one of the Landowner Liability Protections (LLP) offered under CERCLA. Missing or incomplete information for questions 1 through 6 could result in a determination that "all appropriate inquiry" is not complete. Additional information should be provided for "Yes" answers where relevant.

## General Information

**User/Client Names:** One Vine LLC

**Reason for the Phase I ESA:** Transaction and potential redevelopment

**Type of property:** Commercial

**Type of property transaction (e.g. sale, purchase, exchange):** Ground Lease

**Subject property address (provide documentation of subject property boundary):**
1 Vine Street, Larchmont, NY

**Site Contact and Contact Information:** Vincent Sparano (vjsparano@gmail.com)

**Relying Party(ies):** One Vine LLC

## Required Information

**(1.) Environmental liens that are filed or recorded against the subject property (40 CFR 312.25).**

Did a search of recorded land title records (or judicial records where appropriate) identify any environmental liens filed or recorded against the subject property under federal, tribal, state or local law?

Yes ○ No ◉

**(2.) Activity and use limitations that are in place on the subject property or that have been filed or recorded against the subject property (40 CFR 312.26(a)(1)(v) and (vi)).**

Did a search of recorded land title records (or judicial records where appropriate) identify any AULs, such as engineering controls, land use restrictions or institutional controls that are in place at the subject property and/or have been filed or recorded against the subject property under federal, tribal, state or local law?

Yes ○ No ◉

**(3.) Specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28).**

Do you have any specialized knowledge or experience related to the subject property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the subject property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?

Yes ○ No ◉

**(4.) Relationship of the purchase price to the fair market value of the subject property if it were not contaminated (40 CFR 312.29).**

Does the purchase price being paid for this subject property reasonably reflect the fair market value of the subject property?

Yes ◉ No ○

If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the subject property?

Yes ○ No ○

N/A

**(5.) Commonly known or reasonably ascertainable information about the subject property (40 CFR 312.30).**

| | Yes | No |
|---|---|---|
| Are you aware of commonly known or reasonably ascertainable information about the subject property that would help the environmental professional to identify conditions indicative of releases or threatened releases? | ○ | ◉ |
| For example, | Yes | No |
| (a.) Do you know the past uses of the subject property? | ◉ | ○ |
| (b.) Do you know of specific chemicals that are present or once were present at the subject property? | ○ | ◉ |
| (c.) Do you know of spills or other chemical releases that have taken place at the subject property? | ○ | ◉ |
| (d.) Do you know of any environmental cleanups that have taken place at the subject property? | ○ | ◉ |

**(6.) The degree of obviousness of the presence or likely presence of contamination at the subject property, and the ability to detect the contamination by appropriate investigation (40 CFR 312.31).**

| | Yes | No |
|---|---|---|
| Based on your knowledge and experience related to the subject property, are there any obvious indicators that point to the presence or likely presence of releases at the subject property? | ○ | ◉ |
| Do you have knowledge or experience with the subject property that may be pertinent to the environmental professional (for example, copies of any available prior environmental site assessment reports, documents, correspondence, etc., concerning the property and its environmental condition)? | ○ | ◉ |

**(7.) Proceedings Involving the Subject Property Questions (Section 10.9 of ASTM E1527-21 and Section 10.10 of ASTM E2247-16)**

| Do you know of: | Yes | No |
|---|---|---|
| (a.) Any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, or from the subject property? | ○ | ◉ |
| (b.) Any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on, at, or from the subject property? | ○ | ◉ |
| (c) Any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products? | ○ | ◉ |

**Signature**

It is understood that the information presented in this form is an integral part of the Phase I ESA process and that Langan will evaluate and rely on this information in the development of the final Phase I ESA report.

Completed By: _____

Print/Type Name: Joseph Forte

Title: Agent

Company: One Vine LLC

Relationship to Client/User: Member of One Vine LLC

Date: 4/27/26

# Appendix E Historical Resources

One Vine Street

1 Vine St

Larchmont, NY 10538

Inquiry Number: 8303563.3

April 06, 2026

# Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

# Certified Sanborn® Map Report

04/06/26

**Site Name:**

One Vine Street
1 Vine St
Larchmont, NY 10538
EDR Inquiry # 8303563.3

**Client Name:**

Langan
368 Ninth Avenue, 8th Floor
New York, NY 10001-2727
Contact: Olivia Miller

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Langan were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

## *Certified Sanborn Results:*

**Certification #** 8D00-4941-B980

**PO #** 192019101

**Project** One Vine Street

**Maps Provided:**

| | |
|---|---|
| 2003 | 1942 |
| 1996 | 1934 |
| 1995 | 1919 |
| 1994 | 1911 |
| 1992 | |
| 1988 | |
| 1963 | |
| 1950 | |

Sanborn® Library search results

Certification #: 8D00-4941-B980

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

*The Sanborn Library LLC Since 1866™*

### Limited Permission To Make Copies

Langan (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.


**Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2026 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

## *Sanborn Sheet Key*

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

### 2003 Source Sheets



Volume 1, Sheet 15
2003



Volume 1, Sheet 16
2003

Volume 1, Sheet 2
2003

### 1996 Source Sheets

Volume 1, Sheet 2
1996

Volume 1, Sheet 16
1996

Volume 1, Sheet 15
1996

### 1995 Source Sheets

Volume 1, Sheet 15
1995

Volume 1, Sheet 16
1995

Volume 1, Sheet 2
1995

### 1994 Source Sheets

Volume 1, Sheet 2
1994

Volume 1, Sheet 16
1994

Volume 1, Sheet 15
1994

## *Sanborn Sheet Key*

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

### 1992 Source Sheets

Volume 1, Sheet 15
1992

Volume 1, Sheet 2
1992

Volume 1, Sheet 16
1992

### 1988 Source Sheets

Volume 1, Sheet 2
1988



Volume 1, Sheet 15
1988



Volume 1, Sheet 16
1988

### 1963 Source Sheets

Volume 1, Sheet 15
1963

Volume 1, Sheet 2
1963



Volume 1, Sheet 16
1963

### 1950 Source Sheets



Volume 1, Sheet 16
1950



Volume 1, Sheet 15
1950

## *Sanborn Sheet Key*

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

### 1942 Source Sheets

Volume 1, Sheet 20
1942

Volume 1, Sheet 19
1942

### 1934 Source Sheets

Volume 1, Sheet 15
1934

Volume 1, Sheet 16
1934

### 1919 Source Sheets



Volume 1, Sheet 13
1919

Volume 1, Sheet 3
1919

### 1911 Source Sheets

Volume 1, Sheet 2
1911




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | One Vine Street |
| Address: | 1 Vine St |
| City, ST, ZIP: | Larchmont, NY 10538 |
| Client: | Langan |
| EDR Inquiry: | 8303563.3 |
| Order Date: | 04/06/2026 |
| Certification # | 8D00-4941-B980 |
| Copyright | 2003 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 2
Volume 1, Sheet 16
Volume 1, Sheet 15

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #8D00-4941-B980

| | |
|---|---|
| Site Name: | One Vine Street |
| Address: | 1 Vine St |
| City, ST, ZIP: | Larchmont, NY 10538 |
| Client: | Langan |
| EDR Inquiry: | 8303563.3 |
| Order Date: | 04/06/2026 |
| Certification # | 8D00-4941-B980 |
| Copyright | 1996 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 15
Volume 1, Sheet 16
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #8D00-4941-B980

| | |
|---|---|
| Site Name: | One Vine Street |
| Address: | 1 Vine St |
| City, ST, ZIP: | Larchmont, NY 10538 |
| Client: | Langan |
| EDR Inquiry: | 8303563.3 |
| Order Date: | 04/06/2026 |
| Certification #: | 8D00-4941-B980 |
| Copyright | 1995 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 2
Volume 1, Sheet 16
Volume 1, Sheet 15

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | One Vine Street |
| Address: | 1 Vine St |
| City, ST, ZIP: | Larchmont, NY 10538 |
| Client: | Langan |
| EDR Inquiry: | 8303563.3 |
| Order Date: | 04/06/2026 |
| Certification # | 8D00-4941-B980 |
| Copyright | 1994 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 15
Volume 1, Sheet 16
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | One Vine Street |
| Address: | 1 Vine St |
| City, ST, ZIP: | Larchmont, NY 10538 |
| Client: | Langan |
| EDR Inquiry: | 8303563.3 |
| Order Date: | 04/06/2026 |
| Certification #: | 8D00-4941-B980 |
| Copyright | 1992 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 16
Volume 1, Sheet 2
Volume 1, Sheet 15

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | One Vine Street |
| Address: | 1 Vine St |
| City, ST, ZIP: | Larchmont, NY 10538 |
| Client: | Langan |
| EDR Inquiry: | 8303563.3 |
| Order Date: | 04/06/2026 |
| Certification # | 8D00-4941-B980 |
| Copyright | 1988 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 16
Volume 1, Sheet 15
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #8D00-4941-B980

| | |
|---|---|
| Site Name: | One Vine Street |
| Address: | 1 Vine St |
| City, ST, ZIP: | Larchmont, NY 10538 |
| Client: | Langan |
| EDR Inquiry: | 8303563.3 |
| Order Date: | 04/06/2026 |
| Certification # | 8D00-4941-B980 |
| Copyright | 1963 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 16
Volume 1, Sheet 2
Volume 1, Sheet 15

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | One Vine Street |
| Address: | 1 Vine St |
| City, ST, ZIP: | Larchmont, NY 10538 |
| Client: | Langan |
| EDR Inquiry: | 8303563.3 |
| Order Date: | 04/06/2026 |
| Certification # | 8D00-4941-B980 |
| Copyright | 1950 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 15
Volume 1, Sheet 16

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | One Vine Street |
| Address: | 1 Vine St |
| City, ST, ZIP: | Larchmont, NY 10538 |
| Client: | Langan |
| EDR Inquiry: | 8303563.3 |
| Order Date: | 04/06/2026 |
| Certification # | 8D00-4941-B980 |
| Copyright | 1942 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600






Volume 1, Sheet 19
Volume 1, Sheet 20

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

| | |
|---|---|
| Site Name: | One Vine Street |
| Address: | 1 Vine St |
| City, ST, ZIP: | Larchmont, NY 10538 |
| Client: | Langan |
| EDR Inquiry: | 8303563.3 |
| Order Date: | 04/06/2026 |
| Certification # | 8D00-4941-B980 |
| Copyright | 1934 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 16
Volume 1, Sheet 15

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #8D00-4941-B980

| | |
|---|---|
| Site Name: | One Vine Street |
| Address: | 1 Vine St |
| City, ST, ZIP: | Larchmont, NY 10538 |
| Client: | Langan |
| EDR Inquiry: | 8303563.3 |
| Order Date: | 04/06/2026 |
| Certification # | 8D00-4941-B980 |
| Copyright | 1919 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 3
Volume 1, Sheet 13

0 Feet 150 300 600

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #8D00-4941-B980




| | |
|---|---|
| Site Name: | One Vine Street |
| Address: | 1 Vine St |
| City, ST, ZIP: | Larchmont, NY 10538 |
| Client: | Langan |
| EDR Inquiry: | 8303563.3 |
| Order Date: | 04/06/2026 |
| Certification #: | 8D00-4941-B980 |
| Copyright | 1911 |

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.




Volume 1, Sheet 2

0 Feet 150 300 600

N

One Vine Street

1 Vine St

Larchmont, NY 10538

Inquiry Number: 8303563.4

April 06, 2026

# EDR Historical Topo Map Report

## with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

# EDR Historical Topo Map Report

04/06/26

**Site Name:**

One Vine Street
1 Vine St
Larchmont, NY 10538
EDR Inquiry # 8303563.4

**Client Name:**

Langan
368 Ninth Avenue, 8th Floor
New York, NY 10001-2727
Contact: Olivia Miller

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Langan were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

***Search Results:***

**P.O.#** 192019101
**Project:** One Vine Street

***Coordinates:***

| | |
|---|---|
| **Latitude:** | 40.93547 40° 56' 8" North |
| **Longitude:** | -73.75843 -73° 45' 30" West |
| **UTM Zone:** | Zone 18 North |
| **UTM X Meters:** | 604520.88 |
| **UTM Y Meters:** | 4532335.72 |
| **Elevation:** | 41.00' above sea level |

**Maps Provided:**

| | |
|---|---|
| 2023 | 1947 |
| 2019 | 1900 |
| 2016 | 1898 |
| 2013 | 1897 |
| 1995 | |
| 1975, 1979 | |
| 1966, 1967 | |
| 1955, 1956 | |

**Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2026 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

## *Topo Sheet Key*

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

### 2023 Source Sheets



Mount Vernon
2023
7.5-minute, 24000

Mamaroneck
2023
7.5-minute, 24000

### 2019 Source Sheets

Mount Vernon
2019
7.5-minute, 24000

Mamaroneck
2019
7.5-minute, 24000

### 2016 Source Sheets

Mount Vernon
2016
7.5-minute, 24000

Mamaroneck
2016
7.5-minute, 24000

### 2013 Source Sheets

Mount Vernon
2013
7.5-minute, 24000

Mamaroneck
2013
7.5-minute, 24000

## *Topo Sheet Key*

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

### 1995 Source Sheets

Mount Vernon
1995
7.5-minute, 24000
Aerial Photo Revised 1977

### 1975, 1979 Source Sheets

Mamaroneck
1975
7.5-minute, 24000
Aerial Photo Revised 1966

Mount Vernon
1979
7.5-minute, 24000
Aerial Photo Revised 1977

### 1966, 1967 Source Sheets

Mount Vernon
1966
7.5-minute, 24000
Aerial Photo Revised 1966

Mamaroneck
1967
7.5-minute, 24000
Aerial Photo Revised 1966

### 1955, 1956 Source Sheets

Mamaroneck
1955
7.5-minute, 24000
Aerial Photo Revised 1941

Mount Vernon
1956
7.5-minute, 24000
Aerial Photo Revised 1954

## *Topo Sheet Key*

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

### 1947 Source Sheets

Mamaroneck
1947
7.5-minute, 24000
Aerial Photo Revised 1941

Mt Vernon
1947
7.5-minute, 24000
Aerial Photo Revised 1941

### 1900 Source Sheets

Harlem
1900
15-minute, 62500

Oyster Bay
1900
15-minute, 62500

### 1898 Source Sheets

Oyster Bay
1898
15-minute, 62500

Harlem
1898
15-minute, 62500

### 1897 Source Sheets

Harlem
1897
15-minute, 62500

Oyster Bay
1897
15-minute, 62500

# Historical Topo Map

2023




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 2023, 7.5-minute
E, Mamaroneck, 2023, 7.5-minute

SITE NAME: One Vine Street
ADDRESS: 1 Vine St
Larchmont, NY 10538
CLIENT: Langan

N

# Historical Topo Map

2019




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 2019, 7.5-minute
E, Mamaroneck, 2019, 7.5-minute

SITE NAME: One Vine Street
ADDRESS: 1 Vine St
Larchmont, NY 10538
CLIENT: Langan

N




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 2016, 7.5-minute
E, Mamaroneck, 2016, 7.5-minute

SITE NAME: One Vine Street
ADDRESS: 1 Vine St
Larchmont, NY 10538
CLIENT: Langan

N

# Historical Topo Map

2013




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 2013, 7.5-minute
E, Mamaroneck, 2013, 7.5-minute

SITE NAME: One Vine Street
ADDRESS: 1 Vine St
Larchmont, NY 10538
CLIENT: Langan

N




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1995, 7.5-minute

SITE NAME: One Vine Street
ADDRESS: 1 Vine St
Larchmont, NY 10538
CLIENT: Langan

N




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1979, 7.5-minute
E, Mamaroneck, 1975, 7.5-minute

SITE NAME: One Vine Street
ADDRESS: 1 Vine St
Larchmont, NY 10538
CLIENT: Langan

N


Winged Foot Golf Club
Bonnie Brian Country Club
Pinebrook Heights
Sheldrake Lake
Bayberry Park
Wykagyl Park
Forest Knolls
Beechmont Woods
Beechmont Lake
Rochelle Heights
Rochelle Park
Homestead Park
San Haven
LARCHMONT
MAMARONECK
MAMARONE
Hampshire Country Club
Flint Park
Greacen Point
Cedar
Larchmont Harbor
Edgewater Point
Umbrella Point
Horseshoe Harbor
Premium Millpond
Premium
Oak
Clifford
Sand
Table
Tank
Armory
Sewage Disposal
Harbor Island Park
West Basin
Delancey Cove
Middle Sch
East Cr
Village Hall
St Thomas Ch
St Johns Ch
St Vitos Sch
Straight Gate Ch
Fire Sta
Gasing Sta
Cem
Leonard Jr High Sch
Hudson Country Sch
Ward Sch
Murray Ave Sch
SS John and Paul Sch
Barnard Sch
Chatsworth Ave Sch
St Augustines Sch
Holy Name Sch
Stephenson Sch
Radio Tower (WVRC)
Tollgates
Pumping Sta
PARK
INTERCHANGE 7
INTERCHANGE 8
CORNELL ST
WEAVER
PENHMORE
ROCKLAND
FOREST AVE
VINE RD
MURRAY
GLENN
BOUNDARY
CHATSWORTH AVE
EDGEWOOD
MYRTLE
THRUWAY
PALMER
HALL
LARCHMONT
PO
POST
ELM
BEECH
WOODBINE
PRYER
LA
BOSTON
NEW ENGLAND
PUTTERSVILLE
MAIN
OAK ST
HAMILTON
BOULEVARD
5TH
PINE BROOK BLVD
HIGH RIDGE RD
WOODY HOLLOW
LYNCROFT AVE
RAINE AVE
BEECHMONT DR
BARNARD
PINE
BROOK
Pine Brook Bridge
SHEPARD
ORIENTA
BLEEKER
RUSHMORE
PALMER
LANE
ROAD
TRACKS
RIVER
Sheldrake River
Mamaroneck River
Mamaroneck
Sheldrake
Rockland
Forest Ave
Avon
Ave
Rd
Blvd
Dr
Pl
St
Ln
Ter
Cir
Sta
Sch
Ch
Cem
Jr High Sch
Country Sch
Park
Lake
Brook
Bridge
Heights
Knolls
Woods
Haven
Harbor
Point
Cove
Basin
Millpond
Inlet
Toe
Light
Tower
Tank
Table
Sand
Oak
Cedar
Clifford
Armory
Sewage Disposal
Pumping Sta
Tollgates
Radio Tower (WVRC)
Holy Name Sch
Stephenson Sch
Chatsworth Ave Sch
St Augustines Sch
Barnard Sch
Murray Ave Sch
SS John and Paul Sch
Middle Sch
Village Hall
St Thomas Ch
St Johns Ch
St Vitos Sch
Straight Gate Ch
Fire Sta
Gasing Sta
Cem
Leonard Jr High Sch
Hudson Country Sch
Ward Sch
Harbor Island Park
Sewage Disposal
Hampshire Country Club
Flint Park
Greacen Point
Cedar
Larchmont Harbor
Edgewater Point
Umbrella Point
Horseshoe Harbor
Premium Millpond
Premium
Oak
Clifford
Sand
Table
Tank
Armory
West Basin
Delancey Cove
Middle Sch
East Cr




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Mount Vernon, 1956, 7.5-minute
E, Mamaroneck, 1955, 7.5-minute

SITE NAME: One Vine Street
ADDRESS: 1 Vine St
Larchmont, NY 10538
CLIENT: Langan

N




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5




TP, Mt Vernon, 1947, 7.5-minute
E, Mamaroneck, 1947, 7.5-minute

SITE NAME: One Vine Street
ADDRESS: 1 Vine St
Larchmont, NY 10538
CLIENT: Langan

N




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1900, 15-minute
SE, Oyster Bay, 1900, 15-minute

SITE NAME: One Vine Street
ADDRESS: 1 Vine St
Larchmont, NY 10538
CLIENT: Langan

N




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1898, 15-minute
SE, Oyster Bay, 1898, 15-minute

SITE NAME: One Vine Street
ADDRESS: 1 Vine St
Larchmont, NY 10538
CLIENT: Langan

N




This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Harlem, 1897, 15-minute
SE, Oyster Bay, 1897, 15-minute

SITE NAME: One Vine Street
ADDRESS: 1 Vine St
Larchmont, NY 10538
CLIENT: Langan

N

**One Vine Street**

1 Vine St

Larchmont, NY 10538

Inquiry Number: 8303563.8

April 06, 2026

# The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

# EDR Aerial Photo Decade Package

04/06/26

**Site Name:**

One Vine Street
1 Vine St
Larchmont, NY 10538
EDR Inquiry # 8303563.8

**Client Name:**

Langan
368 Ninth Avenue, 8th Floor
New York, NY 10001-2727
Contact: Olivia Miller

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

***Search Results:***

| *Year* | *Scale* | *Details* | *Source* |
|---|---|---|---|
| 2024 | 1"=500' | Flight Year: 2024 | USDA/NAIP |
| 2021 | 1"=500' | Flight Year: 2021 | USDA/NAIP |
| 2017 | 1"=500' | Flight Year: 2017 | USDA/NAIP |
| 2013 | 1"=500' | Flight Year: 2013 | USDA/NAIP |
| 2009 | 1"=500' | Flight Year: 2009 | USDA/NAIP |
| 2006 | 1"=500' | Flight Year: 2006 | USDA/NAIP |
| 1994 | 1"=500' | Flight Year: 1994 | USGS/DOQQ |
| 1985 | 1"=500' | Flight Date: March 16, 1985 | USDA |
| 1980 | 1"=500' | Flight Date: July 25, 1980 | NOAA |
| 1974 | 1"=500' | Flight Date: October 24, 1974 | USDA |
| 1964 | 1"=500' | Flight Date: March 23, 1964 | USGS |
| 1962 | 1"=500' | Flight Date: January 16, 1962 | EDR Proprietary Aerial Viewpoint |
| 1953 | 1"=500' | Flight Date: December 17, 1953 | USGS |
| 1951 | 1"=500' | Flight Date: April 20, 1951 | EDR Proprietary Aerial Viewpoint |
| 1947 | 1"=500' | Flight Date: April 03, 1947 | USGS |
| 1940 | 1"=500' | Flight Date: December 19, 1940 | USGS |

**When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.**


**Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.

Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2026 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.



INQUIRY #: 8303563.8

YEAR: 2024

= 500'

N

EDR

INQUIRY #: 8303563.8

YEAR: 2021

= 500'

N

EDR

INQUIRY #: 8303563.8
YEAR: 2017
= 500'
N
EDR



INQUIRY #: 8303563.8

YEAR: 2013

= 500'

N

EDR

INQUIRY #: 8303563.8
YEAR: 2009
= 500'
N
EDR

INQUIRY #: 8303563.8

YEAR: 2006

= 500'

N

EDR



INQUIRY #: 8303563.8

YEAR: 1994

= 500'

N

EDR

INQUIRY #: 8303563.8
YEAR: 1985
= 500'
N
EDR

INQUIRY #: 8303563.8

YEAR: 1980

= 500'

N

EDR

INQUIRY #: 8303563.8

YEAR: 1974

= 500'

N

EDR

INQUIRY #: 8303563.8

YEAR: 1964

= 500'

N

EDR

INQUIRY #: 8303563.8

YEAR: 1962

= 500'

N

EDR

INQUIRY #: 8303563.8

YEAR: 1953

= 500'

N

EDR

INQUIRY #: 8303563.8

YEAR: 1951

= 500'

N

EDR

INQUIRY #: 8303563.8
YEAR: 1947
= 500'
N
EDR

INQUIRY #: 8303563.8
YEAR: 1940
= 500'
N
EDR

LIGHTBOX

# LightBox City Directory Report

**One Vine Street**

**1 Vine St**

**Larchmont, NY 10538**

Inquiry Number: 8303563.5

April 6, 2026

LightBox Parent, L.P.
6 Armstrong Road, 4th floor
Shelton, CT 06484
800.352.0050
www.lightboxre.com

# TABLE OF CONTENTS

## LIGHTBOX LIVE

Open LightBox Live to access data, tools, and advanced analytics in one online platform.
https://lightbox.live/environmental/analysis/ef9cd6ba-ef39-42aa-83aa-ab8eb1209de5

## SECTION

Executive Summary ---------- page 1

Findings ---------- page 4

**Thank you for your business.**
Please contact LightBox at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to LightBox Parent, L.P. ("LightBox"). The user of this Report accepts this Report "AS IS" and "AS AVAILABLE". NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. LIGHTBOX SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, ACCURACY, COMPLETENESS, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. TO THE MAXIMUM EXTENT PERMITTED BY LAW, IN NO EVENT SHALL LIGHTBOX, ITS AFFILIATES, LICENSORS, OR SERVICE PROVIDERS BE LIABLE FOR ANY DAMAGES OF ANY KIND, WHETHER DIRECT, INDIRECT, INCIDENTAL, CONSEQUENTIAL, SPECIAL, EXEMPLARY, OR PUNITIVE, ARISING FROM OR RELATING TO THIS REPORT OR ITS USE. IF LIABILITY CANNOT BE EXCLUDED UNDER APPLICABLE LAW, IT IS STRICTLY LIMITED TO THE AMOUNT PAID FOR THE REPORT, IF ANY, BY THE USER OF THE REPORT. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright by LightBox Parent, L.P. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of LightBox or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of LightBox Parent, L.P. or its affiliates. All other trademarks used herein are the property of their respective owners.

# EXECUTIVE SUMMARY

## DESCRIPTION

The LightBox City Directory Report is designed to assist environmental professionals in evaluating potential liabilities on select properties resulting from past activities. The report includes a search of available business directory data at approximately five-year intervals.

## SOURCES

Through agreements with major city directory publishers, including Cole Information, InfoUSA, and Bresser, as well as our own collections (Haines & Stewart), the LightBox City Directory Report offers comprehensive national coverage.
LightBox is authorized to reproduce and redistribute all works featured in this report. The purchaser of this LightBox City Directory Report may include it in their final report(s).

This report includes a search of the following sources:

| Year | Source |
|---|---|
| 2024 | Cole Information |
| 2022 | Cole Information, Data Axle |
| 2017 | Cole Information, Data Axle |
| 2014 | Cole Information, Data Axle |
| 2010 | Cole Information |
| 2005 | Cole Information, Data Axle |
| 2000 | Cole Information |
| 1995 | Cole Information |
| 1992 | Cole Information |
| 1987 | Cole Publications |
| 1983 | New York Telephone |
| 1981 | Cole Publications |
| 1977 | Cole Publications |
| 1972 | Cole Publications |
| 1971 | New York Telephone |
| 1967 | New York Telephone Co, Unknown Source |
| 1965 | New york Telephone Company |
| 1963 | New York Telephone Co |
| 1919 | H A Manning Co |

# EXECUTIVE SUMMARY

## TARGET PROPERTY SEARCH RESULTS

### Vine St

#### 1 VINE ST

| | | |
|---|---|---|
| 2024 | J & F Chatsworth Ltd | Cole Information |
| | Joe Sparano | Cole Information |
| | Sound Shore Limousine Service | Cole Information |
| 2022 | J&F CHATSWORTH AUTOBODY | Cole Information |
| | AVIS RENT A CAR LOCAL RESERVATIONS | Cole Information |
| | SOUND SHORE LIMOUSINE SERVICE INC | Cole Information |
| | Edmund R Papazian | Cole Information |
| 2017 | CLASSIC CAR SERVICE LARCHMONT | Cole Information |
| | J & F CHATSWORTH LTD | Cole Information |
| | SPARANO JOE | Cole Information |
| | LINCOLNDALE PLAZA CORPORATION | Cole Information |
| 2014 | SOUND SHORE LIMOUSINE SERVICE INCORP | Cole Information |
| | AVIS | Cole Information |
| | EMILIE GRENVILLE | Cole Information |
| 2010 | J & F CHATSWORTH LTD | Cole Information |
| | CLASSIC CAR SVC OF LARCHMONT | Cole Information |
| | AVIS RENT A CAR | Cole Information |
| 2005 | CLASSIC CAR SERVICE LARCHMONT | Cole Information |
| | SOUND SHORE LIMOUSINE SERVICE | Cole Information |
| | J & F CHATSWORTH GARAGE AUTO BODY | Cole Information |
| | AVIS RENT A CAR | Cole Information |
| | OCCUPANT UNKNOWN | Cole Information |
| 2000 | SOUND SHORE LIMOUSINE SVCE INCORPORATED | Cole Information |
| | J & F CHATSWORTH LIMITED | Cole Information |
| | AVIS RENT A CAR | Cole Information |
| 1995 | AVIS RENT A CAR-LOCAL RESERVATIONS & INFORMATI-LARCHMONT | Cole Information |
| | SOUND SHORE LIMOUSINE SVCE INC | Cole Information |
| | ANJ AUTO MACHINE SHOP & PARTS | Cole Information |
| | J & F CHATSWORTH LTD | Cole Information |
| 1992 | SOUND SHORE LIMOUSINE SVCE INC | Cole Information |
| | ANJ AUTO MACHINE SHOP & PARTS | Cole Information |
| | J & F CHATSWORTH LTD | Cole Information |
| | AVIS RENT A CAR-LOCAL RESERVATIONS & INFORMATI-LARCHMONT | Cole Information |
| 1981 | Avis Rent A Car | Cole Publications |
| | Chatsworth Auto | |

# EXECUTIVE SUMMARY

## TARGET PROPERTY SEARCH RESULTS

### Vine St (contd.)

#### 1 Vine St (contd.)

| | | |
|---|---|---|
| | Chatsworth Garage | |
| | Diezelcar inc | |
| | SportseSedn Ato Sy | |
| 1977 | Avis Rept A Car | Cole Publications |
| | Chatsworth Auto | |
| | Chatswuih Garage | |
| | Sports&sedn Ato Sy | |
| 1972 | AVIS RENT A CAR | Cole Publications |
| 1967 | Hunter Jas B | New York Telephone Co |
| | AvisRentA Car | New York Telephone Co |
| | C&M Auto Body | New York Telephone Co |
| | Chatsworth Garage of Larchmont | New York Telephone Co |
| | Chatsworth News Svce | New York Telephone Co |
| | Naeclni Tthgr Jr -garge | New York Telephone Co |
| 1963 | Honter Jas B | New York Telephone Co |
| | Avis Rent-A -Car Systm Larchmont | New York Telephone Co |
| | Chatsworth Garage of Larchmont Inc | New York Telephone Co |
| | Manclnl Arthur Jr | New York Telephone Co |

#### 5 VINE ST

| | | |
|---|---|---|
| 2024 | Kim Kwung | Cole Information |
| 2022 | MAGIC TOUCH CLEANERS | Data Axle |
| 2017 | MAGIC TOUCH CLEANERS | Data Axle |
| 2014 | MAGIC TOUCH CLEANING INC | Cole Information |
| 2010 | MAGIC TOUCH CLEANERS | Cole Information |
| 2005 | MAGIC TOUCH CLEANERS | Cole Information |
| | OCCUPANT UNKNOWN | Cole Information |
| 2000 | MAGIC TOUCH CLEANERS | Cole Information |
| 1995 | MAGIC TOUCH CLEANERS | Cole Information |
| 1992 | ANNA MARIE DRY CLNRS | Cole Information |
| 1972 | MICHELS FRENCH DRY | Cole Publications |
| 1967 | Michel's French Dry Cleang | New York Telephone Co |
| 1963 | Michl's French Dry Cleang | New York Telephone Co |

# FINDINGS

This section includes records sorted by street then year.

## STREETS

Vine St
Baldwin Ave
Cabot Rd
Depot Way W
Maple St
Murray Ave
Myrtle Blvd
Palmer Ave
Railroad Way
Thompson St
Wood St
Woodland Ave

### VINE ST

**2024** Cole Information

| | |
|---|---|
| 1 | J & F Chatsworth Ltd |
| | Joe Sparano |
| | Sound Shore Limousine Service |
| 5 | Kim Kwung |

### VINE ST

**2022** Cole Information

| | |
|---|---|
| 1 | J&F CHATSWORTH AUTOBODY |
| | AVIS RENT A CAR LOCAL RESERVATIONS |
| | SOUND SHORE LIMOUSINE SERVICE INC |

### VINE ST

**2022** Data Axle

| | |
|---|---|
| 5 | MAGIC TOUCH CLEANERS |

### VINE ST

**2017** Cole Information

| | |
|---|---|
| 1 | CLASSIC CAR SERVICE LARCHMONT |
| | J & F CHATSWORTH LTD |
| | SPARANO JOE |

### VINE ST

**2017** Data Axle

| | |
|---|---|
| 5 | MAGIC TOUCH CLEANERS |

### VINE ST

**2014** Cole Information

| | |
|---|---|
| 1 | SOUND SHORE LIMOUSINE SERVICE INCORP |
| | AVIS |
| 5 | MAGIC TOUCH CLEANING INC |

### VINE ST

**2010** Cole Information

| | |
|---|---|
| 1 | J & F CHATSWORTH LTD |

# FINDINGS

## VINE ST

**2010** (cont.) Cole Information

1 CLASSIC CAR SVC OF LARCHMONT
AVIS RENT A CAR
5 MAGIC TOUCH CLEANERS

## VINE ST

**2005** Cole Information

1 CLASSIC CAR SERVICE LARCHMONT
SOUND SHORE LIMOUSINE SERVICE
J & F CHATSWORTH GARAGE AUTO BODY
AVIS RENT A CAR
OCCUPANT UNKNOWN
5 MAGIC TOUCH CLEANERS
OCCUPANT UNKNOWN

## VINE ST

**2000** Cole Information

1 SOUND SHORE LIMOUSINE SVCE INCORPORATED
J & F CHATSWORTH LIMITED
AVIS RENT A CAR
5 MAGIC TOUCH CLEANERS

## VINE ST

**1995** Cole Information

1 AVIS RENT A CAR-LOCAL RESERVATIONS & INFORMATI-LARCHMONT
SOUND SHORE LIMOUSINE SVCE INC
ANJ AUTO MACHINE SHOP & PARTS
J & F CHATSWORTH LTD
5 MAGIC TOUCH CLEANERS

## VINE ST

**1992** Cole Information

1 SOUND SHORE LIMOUSINE SVCE INC
ANJ AUTO MACHINE SHOP & PARTS
J & F CHATSWORTH LTD
AVIS RENT A CAR-LOCAL RESERVATIONS & INFORMATI-LARCHMONT
5 ANNA MARIE DRY CLNRS

## VINE ST

**1981** Cole Publications




## VINE ST

**1977** Cole Publications




## VINE ST

**1972** Cole Publications




## VINE ST

**1967** New York Telephone Co



# FINDINGS

## VINE ST

**1967** (cont.) New York Telephone Co


Inc ---------- TEnysn 4-0008
1 Chatsworth News Svce ----------834-0942
1 Mancini Arthur Jr -------garge-TEnysn 4-0008
5 Michel's French Dry Cleang-----TEnysn 4-1632

## VINE ST

**1963** New York Telephone Co


1 Avis Rent-A-Car Systm—
Larchmont ----------TE 4-8883
1 Chatsworth Garage of Larchmont
Inc ---------- TEnysn 4-0008
1 Mancini Arthur Jr -------garge-TEnysn 4-0008
5 Michel's French Dry Cleang-----TEnysn 4-1632

# FINDINGS

## BALDWIN AVE

**2024** Cole Information

| | |
|---|---|
| 4 | ANTHONY V ILARDI |
| 6 | STEPHEN SILHAN |
| 8 | NICOLAS COJOCARU-DURAND |
| | ABIGAIL J MOHLIN |
| 18 | MATTHEW HALLEY JR |
| 20 | JOHN R CATTAU |
| 22 | PAUL M MURPHY |
| 24 | MICHELLE ZIMMERMAN |
| | ALLEN PAGE |
| | BENJAMIN M LINDEN |
| | CIARA FENTON |
| | JUSTIN B ASH |

## BALDWIN AVE

**2022** Cole Information

| | |
|---|---|
| 4 | Mary Ilardi |
| 6 | Stephen Silhan |
| 8 | Apt 2 Abigail J Mohlin |
| 18 | Matthew Halley JR |
| 20 | Apt 1 John Cattau |
| 22 | Paul Murphy |
| 24 | Apt 2 Brooke Linden |
| | Apt 1 Nicholas Silvas |

## BALDWIN AVE

**2022** Data Axle

| | |
|---|---|
| 4 | MAMARONECK TOWN PARK |
| | ELECTRIC CHARGING STATION |

## BALDWIN AVE

**2017** Cole Information

| | |
|---|---|
| 4 | ANTHONY V ILARDI |
| 6 | RICHARD G BARRELLA |
| 8 | 8 BALDWIN AVEREALTY CORP |
| | ALYSON COLLINS |
| | CARA F CONNOLLY |
| | MICHAEL G CONNOLLY |
| | Apt 2 ABIGAIL J MOHLIN |
| | MICHELE ROSEN |
| 18 | MATTHEW D HALLEY |
| 20 | Apt 1 JOHN R CATTAU |
| 22 | ANTHONY L SAPORITO |
| 24 | ROBERT V COCCIOLONE |
| | BOBBY CUTCH |
| | DIANE IOVENITTI |

## BALDWIN AVE

**2017** Data Axle

| | |
|---|---|
| 4 | MAMARONECK TOWN PARK |

## BALDWIN AVE

**2014** Cole Information

| | |
|---|---|
| 4 | ANTHONY V ILARDI |
| 6 | RICHARD G BARRELLA |
| 8 | BRIAN M CARLISLE |
| | MICHELE R MAGDO |
| | ALYSON COLLINS |
| | BRIAN S TACK |
| 14 | MARY ILARDI |
| 18 | MATTHEW D HALLEY |
| 22 | ANTHONY L SAPORITO |
| 24 | BOBBY CUTCH |
| | ROBERT V COCCIOLONE |
| | DIANE IOVENITTI |

# FINDINGS

## BALDWIN AVE

**2014** (cont.) Cole Information

| | |
|---|---|
| 24 | BENJAMIN M LINDEN |
| | PATRICIA BATISTA |

## BALDWIN AVE

**2014** Data Axle

| | |
|---|---|
| 4 | MAMARONECK TOWN PARK |

## BALDWIN AVE

**2010** Cole Information

| | |
|---|---|
| 4 | MEMORIAL PARK |
| | ANTHONY V ILARDI |
| 6 | RICHARD G BARRELLA |
| 8 | BRIAN CARLISLE |
| | BRIAN S TACK |
| 18 | DAVID HALLEY |
| 20 | JOHN R CATTAU |
| 22 | ANTHONY L SAPORITO |
| 24 | ROBERT V COCCIOLONE |
| | BENJAMIN LINDEN |
| | PATRICIA BATISTA |
| | DIANE IOVENITTI |

## BALDWIN AVE

**2005** Cole Information

| | |
|---|---|
| 4 | ANTHONY V ILARDI |
| 6 | FRANK J LEMMA |
| 8 | AHERN CONSULTING |
| | PAUL J AHERN |
| | TOMMY J ROWLEY |
| 18 | DAVID HALLEY |

## BALDWIN AVE

**2005** (cont.) Cole Information

| | |
|---|---|
| 20 | JOHN R CATTAU |
| 22 | ANTHONY L SAPORITO |
| 24 | ROBERT V COCCIOLONE |
| | BERNARD R FUSCO |
| | DIANE IOVENITTI |

## BALDWIN AVE

**2000** Cole Information

| | |
|---|---|
| 6 | FRANK J LEMMA |
| 8 | OCCUPANT UNKNOWN |
| 18 | OCCUPANT UNKNOWN |
| 20 | JOSEPH FERNANDEZ |
| 22 | ANTHONY SAPORITO |
| 24 | Unit A PAULINE SALVANI |
| | JULIO COCCIOLONE |

## BALDWIN AVE

**1995** Cole Information

| | |
|---|---|
| 6 | LEMMA, FRANK J |
| 8 | RAUKX, M V |
| 18 | HALLEY, MATTHEW |
| 20 | MARTINSON, ALEXANDER & MARIE |
| | CROWLEY, EILEEN T |
| 22 | COCCIOLONE, JULIO, JR |
| | LAUGHNA, PATRICK SHAUN |
| 24 | COCCIOLONE, R |
| | KELNHOFER, KATHLEEN |
| | MEDICO, ROBYN |
| | COCCIOLONE, JULIO |
| | SALVANI, PAULINE |

# FINDINGS

## BALDWIN AVE

**1992** Cole Information

| | |
|---|---|
| 6 | LEMMA, FRANK J |
| 8 | FORBES, JAQUELINE |
| | RAUKX, M V |
| 18 | HALLEY, MATTHEW |
| 20 | MARTINSON, ALEXANDER & MARIE |
| | MASON, GUY |
| 22 | COCCIOLONE, JULIO, JR |
| | LAUGHNA, PATRICK SHAUN |
| 24 | SALVANI, PAULINE |
| | COCCIOLONE, R |
| | KELNHOFER, KATHLEEN |
| | COCCIOLONE, JULIO |

## BALDWIN AVE

**1987** Cole Publications

| | | | |
|---|---|---|---|
| 4 | | NP | |
| 6 | Mrs Frank J Lemma | .65 | 834-5037 |
| 8 | Mrs A Campbell | .75 | 834-7923 |
| | M V Raukx | .75 | 834-0707 |
| 18 | Matthew Halley | .76 | 834-2044 |
| 20 | Andrew S Landau | .75 | 834-0616 |
| | Alex Martinson | .63 | 834-7324 |
| 22 | J Cocciolone Jr | .62 | 834-6748 |
| | J Cocciolone Jr | | 834-7930 |
| | Alicia Santana | .84 | 834-7305 |
| | C Tortorella | .78 | 834-4014 |
| 24 | M Captain | .84 | 834-3098 |
| | Julio Cocciolone | .64 | 834-0251 |
| | Pauline Salvani | .78 | 834-5064 |
| | Anthony Saportio | .83 | 834-0156 |

## BALDWIN AVE

**1981** Cole Publications

| | | | |
|---|---|---|---|
| 4 | | NP | |
| 6 | Mrs Frank J Lemma | .65 | 834-5037 |
| 8 | Mrs T M Bedford | .67 | 834-3791 |

## BALDWIN AVE

**1981** (cont.) Cole Publications

| | | | |
|---|---|---|---|
| | Mrs A Campbell | .75 | 834-7923 |
| | Roger Murphy | .¤ | 834-0962 |
| | M V Raukx | .75 | 834-0707 |
| 18 | Matthew Halley | .76 | 834-2044 |
| 20 | James Crowley | .78 | 834-7675 |
| | Alex Martinson | .63 | 834-7324 |
| 22 | J Cocciolone Jr | | 834-6748 |
| | J Cocciolone Jr | | 834-7930 |
| | P Presta | .68 | 834-3138 |
| | C Tortorella | .78 | 834-4014 |
| 24 | Julio Cocciolone | .64 | 834-0251 |
| | David Glazier | .72 | 834-8627 |
| | Corrado Iovenitti | .79 | 834-8264 |
| | Pauline Salvani | .78 | 834-5064 |

## BALDWIN AVE

**1977** Cole Publications

| | | | |
|---|---|---|---|
| 4 | L Barneman | – | 834-2355 |
| 6 | Frank J Lemma | | 834-5037 |
| 8 | Mrs T M Bedford | 7 | TE4-3791 |
| | Mrs A Campbell | 5 | 834-7923 |
| | Charles R Campbell | – | 834-3563 |
| | B A Doern | 5 | 834-4997 |
| | M V Raukx | 5 | TE4-0707 |
| 18 | Matthew Halley | – | 834-2044 |
| 20 | Philip Andolina | – | 834-3544 |
| | Alex Martinson | | 834-7324 |
| 22 | J Cocciolone Jr | | TE4-6748 |
| | J Cocciolone Jr | | 834-7930 |
| | P Presta | 8 | 834-3138 |
| 24 | Julio Cocciolone | | TE4-0251 |
| | Alfred Dipippo | 8 | 834-8968 |
| | David Glazier | 2 | 834-8627 |
| | James A McCoy | 5 | 834-0771 |

## BALDWIN AVE

**1972** Cole Publications

| | | | |
|---|---|---|---|
| 4 | MRS R HAZIRJIAN | 6 | 8340020 |
| 6 | FRANK J LEMMA | 5 | 8345037 |
| 8 | MRS T M BEDFORD | 7 | TE43791 |
| | CLAUDE ESTWICK | 9 | 8347516 |
| | E SUMMERS | | TE40707 |
| 18 | N P STAROPOLI | | 8347277 |
| 20 | DAVID DAVIES | 0 | 8340234 |

# FINDINGS

## BALDWIN AVE

**1972** (cont.) Cole Publications



```
    THOMAS E GALVIN   0 8349259
    ALEX MARTINSON    3 8347324
   *SERVICE ASSOCS INC-2352424
22  J COCCIOLONE JR     TE46748
    P PRESTA          8 8343138
    JOHN TORTORELLA     TE44014
24  JULIO COCCIOLONE  4 TE40251
    ALFRED DIPIPPO    8 8348968
    FRANCO ROTELLINI  9 8346973
    SAL SALERNO       0 8349097
```

## BALDWIN AVE

**1967** New York Telephone Co



```
4 Emilia Hairdrsrs ----------834-6493
4 Hazirjian R Mrs ----------834-0020
6 Lemma Frank J ----------834-5037
6 Lemma Joann ----------834-7274
8 Bedford Thelma Mary Mrs ------TEmpsn 4-3791
8 Summers E ----------TEmpsn 4-0707
18 Staropoli Nicholas P ----------834-7277
20 DeRubeis Cesidio ----------TEmpsn 4-8799
20 Felice Walter ----------834-1808
20 Martinson Alexndr ----------834-7324
22 Cocciolone Julio Jr ----------TEmpsn 4-6748
22 Tortorella John ----------TEmpsn 4-4014
24 Acocella Michl ----------TE 4-0997
24 Cocciolone Julio ----------TE 4-0251
```

## BALDWIN AVE

**1919** H A Manning Co

```
6 Fred E. Hall
6 John Q. Knight
```

# FINDINGS

## CABOT RD

**2024** Cole Information

| | |
|---|---|
| 3 | ILYA GILKAROV |
| 4 | HWI-WON LEE |
| | INESA FERRARO |
| 6 | ANDREA T CAPODANNO |
| 8 | JONAH SAFER |
| 10 | NEIL LASSANDRO |
| 11 | WILLIAM J REIDY JR |
| 15 | HOPE O'NEILL |
| 19 | Ste 32 Joanne L Decabia |

## CABOT RD

**2022** Cole Information

| | |
|---|---|
| 3 | Sinem Sonmez |
| 6 | Andrea T Capodanno |
| 8 | Jonah Safer |
| 10 | Neil Lassandro |
| 11 | William Reidy JR |
| 15 | Hope O'Neill |
| 19 | JOANNE DECABIA |
| | RESIDENTIAL APPRAISAL SERVICE |
| | Joanne L de Cabia |

## CABOT RD

**2017** Cole Information

| | |
|---|---|
| 3 | MICHAEL A EDELSCHICK |
| 4 | PHILIP SHANNON |
| 6 | GENNARO W CAPODANNO |
| 8 | JONAH SAFER |
| 10 | MICHAEL C BURNS |
| 11 | WILLIAM L REIDY |
| 15 | JAMES R ONEILL |
| 19 | FRANCIS C DECABIA |

## CABOT RD

**2017** Data Axle

| | |
|---|---|
| 19 | RESIDENTIAL APPRAISAL SVC |

## CABOT RD

**2014** Cole Information

| | |
|---|---|
| 3 | MICHAEL A EDELSCHICK |
| 4 | PITT LAWLESS |
| 6 | GENNARO W CAPODANNO |
| 8 | OCCUPANT UNKNOWN |
| 10 | MICHAEL C BURNS |
| 11 | WILLIAM J REIDY |
| 15 | JAMES R ONEILL |
| 19 | FRANCIS C DECABIA |

## CABOT RD

**2014** Data Axle

| | |
|---|---|
| 19 | RESIDENTIAL APPRAISAL SVC |

## CABOT RD

**2010** Cole Information

| | |
|---|---|
| 3 | ALEXANDER GOLDANSKY |
| 6 | GENNARO W CAPODANNO |
| 8 | JOANNE RICE |
| 10 | MICHAEL C BURNS |
| 11 | WILLIAM J REIDY |
| 15 | JAMES R ONEILL |
| 19 | RESIDENTIAL APPRAISAL SVC |
| | FRANCIS C DECABIA |

# FINDINGS

## CABOT RD

**2005** Cole Information

| | |
|---|---|
| 3 | DANIEL J GOLDSMITH |
| 4 | SALVATORE J FERRARO |
| 6 | GENNARO W CAPODANNO |
| 8 | ELVIRA B GRANDE |
| 10 | SEUSEUMU OKADA |
| 11 | WILMA D REIDY |
| 15 | DARREN P SICKLER |
| 19 | RESIDENTIAL APPRAISAL SERVICE |
| | LISA M DEVANE |

## CABOT RD

**2000** Cole Information

| | |
|---|---|
| 3 | DANIEL GOLDSMITH |
| 4 | M FANO |
| | SALVATO FERRARO |
| | L PARNELL |
| 6 | TOWN & VILLAGE ROOFING |
| | CAPODANNO G WILLIAM |
| | ANDREA CAPODANNO |
| 8 | E GRANDE |
| 10 | ANTHONY PALEO |
| 11 | WILMA REIDY |
| 15 | WILLIAM CARPINO |
| 19 | LISA DEVANE |
| | FRANK DECABIA |

## CABOT RD

**1995** Cole Information

| | |
|---|---|
| 3 | GOLDSMITH, DANIEL & MELISSA |
| 4 | REGAN, ANNE |
| | FERRARO, SALVATORE |
| 6 | CAPODANNO, G WM |
| | CAPODANNO, GENNARO |

## CABOT RD

**1995** (cont.) Cole Information

| | |
|---|---|
| 6 | TOWN & VILLAGE ROOFING |
| | CAPODANNO, A |
| | CAPODANNO, G WILLIAM |
| 10 | O'ROURKE, WILLIAM B |
| | CAROLEI, CARL |
| 11 | REIDY, WILMA |
| 15 | CARPINO, CARL J, JR |
| 19 | WHITTIER, PEIRCE |

## CABOT RD

**1992** Cole Information

| | |
|---|---|
| 3 | DIMARINO, MODESTINO |
| 4 | PARKER, LIZA |
| | FERRARO, SALVATORE |
| 6 | CAPODANNO, G WM |
| | CAPODANNO, GENNARO |
| | TOWN & VILLAGE ROOFING |
| | CAPODANNO, A |
| | CAPODANNO, G WILLIAM |
| | STRENNEN, STEVE |
| 8 | SHEVIN, ANDREW |
| 10 | CAROLEI, CARL |
| | O'ROURKE, WILLIAM B |
| 11 | REIDY, WILMA |
| 15 | CARPINO, CARL J, JR |
| 19 | BONITO, CARMELA |

## CABOT RD

**1987** Cole Publications

| | | | |
|---|---|---|---|
| 3 | Modestino Dimarino | .68 | 834-5193 |
| 4 | Salvatore Ferraro | .63 | 834-4888 |
| | Salvatore Ferraro | .63 | 834-7406 |
| 6 | Edward D Arnold | .71 | 834-7093 |

# FINDINGS

## CABOT RD

**1987** (cont.) Cole Publications

| | | | |
|---|---|---|---|
| | ★G W Capodanno | | 834-0954 |
| | ★G Capodanno | | 834-0954 |
| | K A Gardner | 85 | 833-0759 |
| | ★Town&Village Roofg | | 834-0954 |
| 8 | W Andrew Fry | 84 | 834-5782 |
| 10 | Carl Carolei | 62 | 834-6921 |
| | William B ORourke | 81 | 834-6140 |
| 11 | Mrs Wilma Reidy | 78 | 834-2599 |
| 15 | Carl J Carpino Jr | 71 | 834-5964 |
| 19 | Mario Bonito | 79 | 834-5240 |

## CABOT RD

**1981** Cole Publications

| | | | |
|---|---|---|---|
| 3 | Modestino Dimarino | | 834-5193 |
| 4 | Ronald E Cerniglio | 78 | 834-0001 |
| | Salvatore Ferraro | 63 | 834-4888 |
| | Salvatore Ferraro | | 834-7406 |
| 6 | Edward D Arnold | 71 | 834-7093 |
| | ★G W Capodanno | | 834-0954 |
| | ★G Capodanno | | 834-0954 |
| | Jerry Flynn | 77 | 834-6836 |
| | ★Town&Village Roofg | | 834-0954 |
| 8 | | NP | |
| 10 | Carl Carolei | | 834-6921 |
| | G Johnson | 79 | 834-3596 |
| 11 | Mrs Wilma Reidy | 78 | 834-2599 |
| 15 | Carl J Carpino Jr | 71 | 834-5964 |
| 19 | Mario Bonito | 79 | 834-5240 |

## CABOT RD

**1977** Cole Publications

| | | | |
|---|---|---|---|
| 3 | Modestino Dimarino | | 834-5193 |
| 4 | G W Capodanno | 1 | 834-1444 |
| | Salvatore Ferraro | | TE4-4888 |
| | Salvatore Ferraro | | 834-7406 |
| 6 | Edward D Arnold | 1 | 834-7093 |
| | ★G W Capodanno | | 834-0954 |
| | ★G Capodanno | | 834-0954 |
| | ★Town&Vlg Roofing | | 834-0954 |
| 8 | | NP | |
| 10 | Carl Carolei | | 834-6921 |
| 11 | L M Rudloff | 5 | 834-7718 |

## CABOT RD

**1977** (cont.) Cole Publications

| | | | |
|---|---|---|---|
| 15 | Carl J Carpino Jr | 1 | 834-5964 |

## CABOT RD

**1972** Cole Publications

| | | | |
|---|---|---|---|
| 3 | MODESTINO DIMARINO | | 8345193 |
| 4 | G W CAPODANNO | | ¤8341444 |
| | SALVATORE FERRARO | 3 | TE44888 |
| | SALVATORE FERRARO | | 8346972 |
| 6 | EDWARD D ARNOLD | | ¤8347093 |
| | *G W CAPODANNO | | TE40954 |
| | *GENNARO CAPODANNO | | TE40954 |
| | JERRY FLYNN | | ¤8346836 |
| | *TWN&VILG ROOFING | | TE40954 |
| 8 | MARCY L ROSE | | ¤8341247 |
| 10 | CARL CAROLEI | | 8346921 |
| 11 | | NP | |
| 15 | CARL J CARPINO JR | | -8345964 |

## CABOT RD

**1967** New York Telephone Co




## CABOT RD

**1967** Unknown Source

| | |
|---|---|
| 15 | Foresti Concetta Mrs |

## CABOT RD

**1963** New York Telephone Co

# FINDINGS

## DEPOT WAY W

**2024** Cole Information

| | |
|---|---|
| 6 | Ste 105 Kiap Inc |
| | Ste 106 Eye On Education Inc |
| | Ste 208 Island Resort Tours Inc |
| | HIAWATHA HUDSON |
| | LUCY J HUDSON |

## DEPOT WAY W

**2022** Cole Information

| | |
|---|---|
| 6 | TRAVEL INC |
| | HIAWATHA MARTIAL ARTS ACADEMY |
| | FAIRPOINT COMMUNICATIONS INC |
| | CHATSWORTH TRANSPORTATION |
| | CROSSROADS II TRAVEL INC |

## DEPOT WAY W

**2017** Cole Information

| | |
|---|---|
| 6 | Ste 208 ISLAND RESORT TOURS INC |

## DEPOT WAY W

**2014** Cole Information

| | |
|---|---|
| 6 | Ste 104 HIAWATHA MARTIAL ARTS ACADEMY |
| | CHATSWORTH TRANSPORTATION |
| | Ste 106 EYE ON EDUCATION |
| | DANIEL A SICKLES |
| 9 | LOCKSMITH |

## DEPOT WAY W

**2010** Cole Information

| | |
|---|---|
| 6 | MAMARONECK TAXI & LIMOUSINE |
| | DEPOT TAXI & LIMOUSINE |
| | Ste 108 ALLSTATE CRANE |
| | Ste 105 HIAWATHA MARTIAL ARTS ACADEMY |
| | LARCHMONT TAXI |
| | Ste 106 EYE ON EDUCATION |

## DEPOT WAY W

**2005** Cole Information

| | |
|---|---|
| 6 | Ste 108 ALLSTATE INTERNATIONAL CORP |
| | LARCHMONT TAXI |
| | Ste 105 KIAP INC |
| | DEPOT CHASSIS AND MCS LIMOUSINE |
| | EYE ON EDUCATION |

## DEPOT WAY W

**2005** Data Axle

| | |
|---|---|
| 60 | MAMARONECK TAXI & LIMOUSINE |

## DEPOT WAY W

**2000** Cole Information

| | |
|---|---|
| 6 | DEBBIE FRANK EXERCISE STUDIO |
| | CHARLES HOWARD C |
| | MILLER BRIAN MD |
| | EYE ON EDUCATION |
| | LARCHMONT MARTIAL ARTS ACADEMY |
| | KALCUT PAUL R |
| | ALLSTATE CRANE |
| 9 | MEATERIA |

# FINDINGS

## DEPOT WAY W

**1995** Cole Information

6 LARCHMONT MARTIAL ARTS ACADEMY
MILLER, BRIAN, MD
9 MEATERIA

## DEPOT WAY W

**1992** Cole Information

6 MILLER, BRIAN, MD
9 MEATERIA

## DEPOT WAY W

**1981** Cole Publications

6★Pjs Loft . . . . . 834-7221
9★Larchmont Meateria . . . . 834-9722

## DEPOT WAY W

**1977** Cole Publications

5★Larchmont Laundrmt TE4-0303

7★Mademoiselle Salon 834-3681
9★Larchmont Meateria 834-9722

## DEPOT WAY W

**1972** Cole Publications

5*LARCHMONT LAUNDRMT TE40303

9*LARCHMONT MEATERIA 8349722

## DEPOT WAY W

**1967** New York Telephone Co

Westchester Limousine Svce -----TEnysn 4-5800
5 Larchmont Laundromat ----- ------TE 4-0303

## DEPOT WAY W

**1963** New York Telephone Co

Westchester Limousine Svce -----TEnysn 4-5800
5 Larchmont Laundromat ----------TE 4-0303

7 Mademoiselle Hairdrsrs ---------TEnysn 4-3030

# FINDINGS

## MAPLE AVE

**2022** Cole Information

| | |
|---|---|
| 15 | Andrew Singer |
| 19 | Daniel A Moros |

## MAPLE AVE

**2017** Cole Information

| | |
|---|---|
| 15 | CHRISTOPHER H DILLON |

## MAPLE AVE

**2014** Cole Information

| | |
|---|---|
| 15 | OCCUPANT UNKNOWN |

## MAPLE AVE

**2014** Data Axle

| | |
|---|---|
| 19 | DANIEL, AARON M MD |

## MAPLE AVE

**2010** Cole Information

| | |
|---|---|
| 15 | THOMAS G DILON |
| 19 | DANIEL A MOROS |

## MAPLE AVE

**2005** Cole Information

| | |
|---|---|
| 15 | THOMAS G DILLON |
| 19 | DANIEL A MOROS |

## MAPLE AVE

**2000** Cole Information

| | |
|---|---|
| 15 | THOMAS A DILLON |
| 19 | OCCUPANT UNKNOWN |

## MAPLE AVE

**1995** Cole Information

| | |
|---|---|
| 15 | DILLON, THOMAS A, JR |

## MAPLE AVE

**1992** Cole Information

| | |
|---|---|
| 15 | DILLON, THOMAS A, JR |

## MAPLE AVE

**1987** Cole Publications

15 Thomas A Dillon Jr . . 77 834-9127
19 R J Smith . . . . . – 834-6065

## MAPLE AVE

**1981** Cole Publications

15 Thomas A Dillon Jr . . . . . 77 834-9127
19 George R Funaro . . . . . 78 834-0859

## MAPLE AVE

**1977** Cole Publications

15 Ledwith Brennan 9 TE4-2175
19 Ralph E OConnell TE4-0615

# FINDINGS

## MAPLE AVE

**1972** Cole Publications

15 LEDWITH BRENNAN 9 TE42175
19 RALPH E OCONNELL TE40615

# FINDINGS

## MAPLE ST

**2005** Cole Information

15 THOMS DILLION

# FINDINGS

## MURRAY AVE

**2014** Cole Information

| | |
|---|---|
| 12 | JESSICA LEE |

## MURRAY AVE

**2010** Cole Information

| | |
|---|---|
| 32 | TERRY P OKEEFE |

## MURRAY AVE

**2005** Cole Information

| | |
|---|---|
| 82 | TERENCE P OKEEFE |

## MURRAY AVE

**2000** Cole Information

| | |
|---|---|
| 82 | OCCUPANT UNKNOWN |
| 142 | JESSICA LEE |

## MURRAY AVE

**1995** Cole Information

| | |
|---|---|
| 82 | O'KEEFE, TERENCE |
| 142 | SAX, BEN & HOLLIS |

## MURRAY AVE

**1992** Cole Information

| | |
|---|---|
| 82 | O'KEEFE, TERENCE |
| 142 | SAX, BEN & HOLLIS |

## MURRAY AVE

**1981** Cole Publications

82 Terence P OKeefe .....77 834-2515

142 Walter A Coupe ..... 834-5444

## MURRAY AVE

**1977** Cole Publications

82 Louis Guadagnolo - 834-2750

142 Walter A Coupe 834-5444

## MURRAY AVE

**1972** Cole Publications

142 WALTER A COUPE 8345444

## MURRAY AVE

**1967** New York Telephone Co

82 Guadagnolo Anthony ----------TE 4-6693

142 Meyers Thelma Mrs ----------834-0650

257 Opper Jay ----------834-5721

# FINDINGS

## MYRTLE BLVD

**2024** Cole Information

| | |
|---|---|
| 101 | RICHARD K ALOISE |
| 103 | Scoops Dog Walking Llc |
| | DEBRA A REICH-LITZKY |
| 106 | HOTHA BHAUMIK |
| | SUSAN MALUSHAGA |
| | GREGORY AGNELLO |
| 107 | ANGELA B BARBELLA |
| 121 | Myrtle Plumbing And Heating |
| | Penske Truck Leasing Corp |
| | Plates Restaurant |

## MYRTLE BLVD

**2022** Cole Information

| | |
|---|---|
| 101 | Richard K Aloise |
| 103 | Debi A Reich-Litzky |
| 106 | Hotha Bhaumik |
| 107 | Angela B Barbella |
| 108 | Michael Vecchione |
| 121 | PLATES RESTAURANT |
| | PLATES ON THE PARK |
| | PLATES |
| | BILLY & PETES SOCIAL |
| | PENSKE TRUCK RENTAL |

## MYRTLE BLVD

**2017** Cole Information

| | |
|---|---|
| 101 | RICHARD K ALOISE |
| 103 | ALEX J LITZKY |
| 105 | EDWARDD W RICE |
| 106 | GREGORY AGNELLO |
| | GRANT DEBAKER |
| | CHRIS PLUNKETT |
| | BRIGID STALEY |

## MYRTLE BLVD

**2017** (cont.) Cole Information

| | |
|---|---|
| 106 | Apt 2 DAVID L WISOWATY |
| 107 | JOHN L BARBELLA |
| 108 | MICHAEL A VECCHIONE |
| 121 | MYRTLE PLUMBING AND HEATING |
| | PENSKE TRUCK LEASING CORP |

## MYRTLE BLVD

**2014** Cole Information

| | |
|---|---|
| 101 | RICHARD K ALOISE |
| 103 | ALEX J LITZKY |
| 105 | EDWARDD W RICE |
| 106 | DAVID L WISOWATY |
| | MADISON DEBAKER |
| | GREGORY AGNELLO |
| 107 | JOHN L BARBELLA |
| 108 | MICHAEL A VECCHIONE |
| 121 | MYRTLE PLUMBING & HEATING |
| | PENSKE TRUCK RENTAL |
| | BROOKLYN LOCKSMITH |
| | LARCHMONT RAPID LOCKSMITH |
| | PLATES RESTAURANT |

## MYRTLE BLVD

**2010** Cole Information

| | |
|---|---|
| 101 | RICHARD K ALOISE |
| 103 | DAVID J LITZKY |
| 105 | EDWARDD W RICE |
| 107 | JOHN L BARBELLA |
| 108 | MICHAEL A VECCHIONE |
| 121 | PLATES RESTAURANT |

# FINDINGS

## MYRTLE BLVD

**2005** Cole Information

| | |
|---|---|
| 101 | RICHARD K ALOISE |
| 103 | FRANCIS J ABRAHAMSEN |
| 105 | EDWARDD W RICE |
| 107 | JOHN L BARBELLA |
| 108 | MICHAEL A VECCHIONE |
| 116 | HOURS CLEANERS II |
| 121 | 121 MYRTLE BLVD RESTAURANT |
| | OCCUPANT UNKNOWN |

## MYRTLE BLVD

**2000** Cole Information

| | |
|---|---|
| 101 | F TAMURA |
| 103 | FRANCIS J ABRAHAMSEN |
| 105 | EDWARD RICE |
| 106 | TONY PORTANOVA |
| 107 | JOHN L BARBELLA |
| 108 | MICHAEL VECCHIONE |
| 121 | CARLS RESTRNT |

## MYRTLE BLVD

**1995** Cole Information

| | |
|---|---|
| 101 | ALOISE, FRANK |
| 103 | ABRAHAMSEN, FRANCIS J |
| 105 | RICE, EDWARD & MAUREEN |
| 106 | PORTANOVA, TONY |
| 107 | BARBELLA, JOHN L |
| 121 | CARL'S RESTRNT |

## MYRTLE BLVD

**1992** Cole Information

| | |
|---|---|
| 101 | ALOISE, FRANK |
| | EDMOND, GEORGINA |
| 103 | ABRAHAMSEN, FRANCIS J |
| 105 | RICE, EDWARD & MAUREEN |
| 106 | PORTANOVA, TONY |
| 107 | MUTO, HIDEYUKI & KIMIE |
| 108 | DI COSTANZO, PETER |
| 121 | CARL'S RESTRNT |

## MYRTLE BLVD

**1981** Cole Publications

| | | |
|---|---|---|
| 101 | Frank Aloise | 834-5828 |
| 103 | F J Abrahamsen .....79 | 834-2827 |
| 105 | Pietro Filosa .....69 | 834-4814 |
| 106 | Tony Portanova .....-- | 834-2166 |
| 107 | G W Capodanno .....78 | 834-1444 |
| 121 | ★Carls Restrnt | 834-1244 |

## MYRTLE BLVD

**1977** Cole Publications

| | | | |
|---|---|---|---|
| 105 | Pietro Filosa | 9 | 834-4814 |
| 106 | | NP | |
| 107 | Mrs Susie Casciaro | | TE4-4383 |
| 121 | ★Carls Restrnt | | TE4-1244 |

## MYRTLE BLVD

**1972** Cole Publications

| | | | |
|---|---|---|---|
| 101 | FRANK ALOISE | | TE45828 |
| 105 | NICK CIANCIULLI | 2 | TE42539 |
| | PIETRO FILOSA | 9 | 8344814 |
| 106 | PAUL H KEAN | 0 | 8348960 |
| 107 | MRS SUSIE CASCIARO | 6 | TE44383 |
| 121 | *CARLS RESTRNT | | TE41244 |

# FINDINGS

## MYRTLE BLVD

**1967** New York Telephone Co

99 Musacchio John ----------TEnysn 4-4100
101 Aloise Frank ----------TEnysn 4-5828
105 Cianciulli Nick ----------TEnysn 4-2539
105 Filosa Amelia Mrs ----------TEnysn 4-4987
106 LePort Maria Mrs ----------834-0167
107 Casciaro Susie Mrs ----------TE 4-4383
121 Carl's Restrnt ----------TEnysn 4-1244

## MYRTLE BLVD

**1963** New York Telephone Co


99 Musacchio John ----------TEnysn 4-4100
101 Aloise Frank ----------TEnysn 4-5828
103 O'Connell Jas ----------TEnysn 4-7358
105 Cianciulli Nick ----------TEnysn 4-2539
105 Filosa Amelia Mrs ----------TEnysn 4-4987
106 Staats Ludwig Mrs ----------TEnysn 4-2093
121 Carl's Restrnt ----------TEnysn 4-1244

# FINDINGS

## PALMER AVE

**2024** Cole Information

| | |
|---|---|
| 1299 | 1299 Palmer Avenue Inc |
| | Apt 112 Lee Hakwoon |
| | Apt 332 Stephen D Gutmann |
| | Apt 236 Honora Care Mgt Consulting Llc |
| | Westchester Beverage Ltd |
| | Roberto J Ilagan |
| | ALBERTO PEPE |
| | ALISON R FREDE |
| | JARED B BERGER |
| | SIOBHAN B SHORT |
| | VINCENT P COYNE |
| | LAURENCE PRESTON |
| | PAUL P ADAMO |
| | JACLYN R FORTUNA |
| | FRANCES M TAVOLILLA |
| | JEANETTE HERNANDEZ |
| | NANCY A ZIMMERMAN |
| | PETER L ROOME |
| | FREDERICK R ROMOSER |
| | NED HAYDEN |
| | MELISSA SHAH |
| | DONNA R DIFALCO |
| | PAUL HEACOCK |
| | ZSOLT BOKA |
| | VENERA V BARCELLONA |
| | CAROL-JUNE V CASSIDY |
| | WILLIAM MICHIELS |
| | GERRI L FLIGEL |
| | DAVID J LAKOWITZ |
| | ALBERT J ACCINELLI |
| | ANNE SHORT |
| | RACHEL SANTOS |
| | JANE E KROMM |
| | ANNA GORELOVA |
| | CHRISTINA M DHANRAJ |
| | CHARLES U OKOCHU |
| | GIANCARLO F COLAIANNI |
| | JOHN DAPOLITE |

## PALMER AVE

**2024** (cont.) Cole Information

| | |
|---|---|
| 1299 | NICHOLAS J GIACOPELLI |
| | MARIANNE TRAMELLI |
| | GREGORY J GIBSON |
| | MICHAEL FLEISCHMANN |
| | GABRIELLE N SANTO |
| | MELODY O AFRIYIE |
| | MICHAEL J MCBRIDE JR |
| | MARY NAYLOR |
| | MIRA P GJYREZI |
| | BARBARA A TERRANOVA |
| | CHARLES C HEIDSIECK |
| | REBECCA OWENS |
| | JEANINE L BRIOTTE |
| | ESTEBAN ALVAREZ |
| | PENNY S LINDEN |
| | PERICA P MARKOC |
| | FABIO R PERENGUEZ |
| | LUIS ACOSTA |
| | TARA A BERNARDINO |
| | LYNN M HORNER |
| | ERIK P LIEBLEIN |
| | STEVEN A ACCINELLI |
| | AIZAZ M SIDDIQUI |
| | ANA L LORENTE |
| | ZSOLT BOKA |
| | NIRA GJYREZI |
| | ELLEN M MASTRO |
| | MICHAEL I SALEM |
| | JACQUELINE E TERRANOVA |
| | HILLEL ABOUDI |
| | SEAN R MCCARTHY |
| | CHARLES C HEIDSIECK |
| | MARK D BERGER |
| | LISA DEL FAVERO |
| | SUSAN G ALLEN |
| | RAYMOND A SANTO |
| | ERIK VECVAGARS |
| | BARBARA S GIRARDI |

# FINDINGS

## PALMER AVE

**2024** (cont.) Cole Information

| | |
|---|---|
| 1299 | MARIA D RICCI |
| | KATHRYN L MASTRO |
| | MARION GIMBEL |
| | THERESA N MALGIOGLIO |
| | MELISSA R KEENAN |
| | VICTOR J AMMORA |
| | CLELIA C O'CONNELL |
| | GREGORY J COMITO |
| | MARK D BERGER |
| | JOHN R MCIVOR |
| | KATHLEEN B WEBB |
| | JOHN T JOLLY |
| | JOSEPH A LORENTE |
| | ANGELO MARTELLI |
| | DAVID P SALSBERG |
| | MICHAEL T WELDON |
| | CHARLES P RABINOWITZ |
| | RONALD YOUNG |
| | JANE DELLACAVA |
| | CHRISTINE G CROWTHER |
| | CHRISTOPHER J PETICCA |
| | MARCIA A ALMOND |
| | EILEEN A GENTILLO |
| 1815 | S Lomonaco Md |
| | Ste 2 Futterman Carol Lcsw |
| | Ste 3 Edward S Rosemblum Dds |
| | Apt 2D Atm Capital Partners Llc |
| | BETTE A HUTCHINGS |
| | EDWARD D RILEY |
| | OKSANA N KONOBEYEVA |
| | SUSAN R KAUFMAN |
| | ANNA A CORTESE |
| | LINDSAY CHANDLER-ALEXANDER |
| | STEPHANIE ROBERTS |
| | CAROLINE R MULCAHY |
| | THERESA R PIETRAFESA |
| | JADE RAGOSCHKE |
| | SUSAN M EGAN |

## PALMER AVE

**2024** (cont.) Cole Information

| | |
|---|---|
| 1815 | MARISSA CROFUT |
| | MARGARET G DODGE |
| | DANIEL E TEDESCHI |
| | WILLIAM PERSKY |
| | GEORGE S CASE JR |
| | CAROLINE R MULCAHY |
| | GREGORY J HANSEN |
| | SHARON H FALVEY |
| | STACEY A TRAVAGLINI |
| | CAROLYN K KELLY |
| | JAMES P VERSCAJ |
| | ALICIA COOPER |
| | NANCY PORTILLA |
| | LAURA KIRKA |
| | ERENE CAINE |
| | EDWARD S ROSENBLUM |
| | BARBARA D PEARSON |
| | BRIAN F BENEDIK |
| | JOHN A BATTISTA |
| | SAL A MALLET |
| | DOROTHY E BAILEY |
| | MARC BARBELLA |
| | CAROLYN FARINA |
| | SHOSHANA LIEBERMAN |
| | JOSE GARRIDO |
| | WILLIAM MESSEMER |
| | BETTY M MERRELL |
| | BENJAMIN B CLEVER |
| | MARIE R GARVEY |
| | ATTILIO FRANCIOLI |
| | STEPHEN BRITTON |
| | ARTHUR STANTON |
| | KRISTINA M SCHLOTE |
| | OLIVIA E DELMONICO |
| | ALFRED J GRANDA |
| | BLAIR WILKIE |
| | MARYANN SEARS |
| | OTHILYN GONZALES |

# FINDINGS

## PALMER AVE

**2024** (cont.) Cole Information

| | |
|---|---|
| 1815 | TRACY GOLDBERG |
| | RUTH D BARTEE |
| | ODENIS A ABREU |
| | CATHERINE C FABRIZIO |
| | SHELEE BERGHAUS |
| | HUMBERTO QUINONES JR |
| | MARK FUGARINO |
| | TRINH TRAN |
| | ERICA L POCCIA |
| | DOMINIC FRASSINO |
| | PATRICIA A BARCELLONA |
| | JULIAN D MARTINEZ JR |
| | ELIZABETH RAPUANO |
| | KATHLEEN P HAAS |
| | ENID K MORRONE |
| | DEBORAH A FIED |
| | STEPHEN F KIMMEY |
| | ANGEL L MALDONADO |
| | AMY E DEANGELO |
| | JOHN A CAREY JR |
| | ANITA DLUGOSZ |
| | ALEXANDRA DIGIOIA |
| | CESARE G RICCHEZZA |
| 1825 | Apt 2E Ludas Piano Studio Inc |
| | Apt 3D Paris Beauty Studio Inc |
| | HUGH K O'DONNELL |
| | JULIE D CIACCI |
| | MARGARET K KELLY |
| | MIKE BRANTLEY |
| | ARNOLD P MUMFORD |
| | JOSEPH TRICAMO |
| | JENNIFER M JENUYN |
| | KIMBERLY A COUZENS |
| | MARK J CONTE |
| | JOSEPH A FIORITA |
| | ANN M SATALICH |
| | JULIE C SALICRUP |
| | JIMMY A IBARRA |

## PALMER AVE

**2024** (cont.) Cole Information

| | |
|---|---|
| 1825 | KATHLEEN M FITZGERALD |
| | JULIE D CIACCI |
| | CARLA J BERNARD |
| 1833 | Apt 3J Kitchens By Frankie |
| | Apt 1C Patricia Gardens |
| | Apt 2J Random Turn Inc |
| | TRAVIS J WONG |
| | JACKIE BRYANT |
| | ELYSE E ROBOWSKY |
| | GRACIELA CANDIA |
| | MONICA KELLY |
| | CAROLINA ROSALES |
| | LAURIE R MARINARO |
| | ANNA GONZALEZ |
| | JOHN R REID |
| | BETH E STARKIN |
| | DOMINICK J RICCARDULLI |
| | MARY I FOSTER |
| | GINA GELARDO |
| | JUAN A SOTO |
| | DIANA CARTEGENA |
| | JOSEPHINE GIARDINA |
| | CATHRIONA A CAREY |
| | ANN BEZ |
| | MARK ABRAMS |
| | FRANKIE GONZALEZ |
| | NICOLE C AMATO |
| | CHERYL A DUNDON |
| | ANDREA VIGNOLA |
| | DMITRIY OSTROVSKIY |
| | JOHN M QUINLAN |
| | NANCY C ARBUCO |
| 1865 | Ste 203 L&M Affordable Member Llc |
| | Ste 104 15 Angels Ii Llc |
| | Ste 210 Cuccia Oster & Hansburg |
| | West Market Owners Llc |
| | Ste 203 L & M Commonwealth Cnstr Llc |
| | Ste 104 Deer Vi & Co Llc |

# FINDINGS

## PALMER AVE

**2024** (cont.)

| | Cole Information |
|---|---|
| 1865 | Ste 203 109 Mvlm Llc |
| | Ste 104 Deer Iv & Co Llc |
| | Ste 108 Joel Negrin Pc |
| | Ste 203 Livingston Urban Renewal Llc |
| | Ste 203 C&C Apartment Management Llc |
| | Ste 203 11 Brdway Hp Lib Hsing Dev Fun |
| | Ste 104 Bessemer Venture Partners |
| | Ste 203 County Builders Llc |
| | Ste 203 L & M Builders Group Llc |
| | Ste 210 Mark A Barbero |
| | Ste 203 Chatsworth Builders Llc |
| | Ste 203 Arverne Preservation Llc |
| | Ste 203 Gk Preservation Llc |
| | Ste 203 L & M Builders Llc |
| | DAVID J WEISBERGER |
| | EMILIO ZANIN |
| 1875 | Tower Management Corp |
| | American Friends Of Kashmir |
| | Ste 202 Old Cannery Specialties Llc |
| | Ste 3 Teddy Hair Salon |
| | Bell Tower Associates Llc |

## PALMER AVE

**2022**

| | Cole Information |
|---|---|
| 1299 | FREQUENCY RECORDING STUDIO |
| | 1299 PALMER AVE INC |
| | Apt 307 Theresa N Malgioglio |
| | Apt 235 Greg Keefer |
| | Apt 321 Robert A Frabasile |
| | Apt 102 Fabio R Perenguez |
| | Apt 215 Victor J Ammora |
| | Apt L3 Donna Difalco |
| | Apt 117 Erik Vecvagars |
| | Apt 223 Martha I Medina |
| | Apt 338 John R McIvor |

## PALMER AVE

**2022** (cont.)

| | Cole Information |
|---|---|
| 1299 | Apt 314 Nira Gjyrezi |
| | Apt 230 Dianna Davydkina |
| | Apt 217 Laurence Preston |
| | Apt 122 Barbara S Girardi |
| | Apt 305 Charles U Okochu |
| | Apt 204 Ellen M Mastro |
| | Apt 128 Gregory J Comito |
| | Apt 121 Kevin F Kittle |
| | Apt 218 Anne Short |
| | Apt 105 Melissa R Keenan |
| | Apt 101 Philip Denning |
| | Apt 208 Nancy A Zimmerman |
| | Apt 210 Luis Acosta |
| | Apt 317 Fred R Romoser |
| | Apt 231 Bahareh Maghamiasl |
| | Apt 138 Jeanine L Briotte |
| | Apt 116 Melissa Shah |
| | Apt 214 Gerri Fligel |
| | Apt 335 Erik P Lieblein |
| | Apt 302 Raymond A Santo |
| | Apt L1 Alberto Pepe |
| | Apt 125 Joseph A Lorente |
| | Apt 108 Alison R Frede |
| | Apt 233 Albert J Accinelli |
| | Apt 209 Angelo Martelli |
| | Apt 115 Venera Barcellona |
| | Apt 216 Susan Allen |
| | Apt 323 Kathryn L Mastro |
| | Apt 315 Linda P Gustafson |
| | Apt 324 Penny S Linden |
| | Apt 133 Wendy R Weiner |
| | Apt 206 Jared B Berger |
| | Apt 234 Paul Heacock |
| | Apt 329 Kathleen B Webb |
| | Apt 221 Lisa A Gataletto |
| | Apt L2 Perica P Markoc |
| | Apt 301 Clelia C O'Connell |
| | Apt 136 Christina M Dhanraj |

# FINDINGS

## PALMER AVE

**2022** (cont.)

Cole Information

1299 Apt 218 Siobhan B Short
Apt 221 Rachel E Nieves
Apt 135 Peter L Roome
Apt 207 Peter Casalina JR
Apt 333 Roslyn H Michiels
Apt 311 Jeanette Hernandez
Apt 134 Vincent P Coyne
Apt 319 Robert H Heckmann
Apt 115 Maria D Ricci
Apt 234 Carol J Cassidy
Apt 328 Peter J Markel
Apt 106 Michael J McBride JR
Apt 325 Jane E Kromm
Apt 201 Steven A Accinelli
Apt 330 Jaclyn Fortuna
Apt 314 Mira P Gjyrezi
Apt 236 Nicholas Giacopelli
Apt 229 Jacqueline E Terranova
Apt 104 Dominick J Castaldo
Apt 334 Lisa del Favero
Apt 138 Christopher J Peticca
Apt 320 Michael I Salem
Apt 225 David P Salsberg
Apt 205 Tara A Bernardino
Apt 129 David J Lakowitz
Apt 212 Michael Fleischmann
Apt 219 Edwin Hayden
Apt 221 Mark D Berger
Apt 331 Jane Dellacava
Apt 127 Robert J Wolfe
Apt 336 Paul P Adamo
Apt 318 Melody O Afriyie
Apt 308 John T Jolly
Apt 107 Marion Gimbel
Apt 327 Lynn Horner
Apt 133 Charles P Rabinowitz
1815 Ste 2 FUTTERMAN CAROL LCSW
GARTNER

## PALMER AVE

**2022** (cont.)

Cole Information

1815 LOMONACO S MD
ROSENBLUM EDWARD S DDS
Apt 3I Maryann Sears
Apt 2H Erene Caine
Apt 3X Shoshana Lieberman
Apt 1E Anna A Cortese
Apt 1P James P Verscaj
Apt 3A Jose Garrido
Apt 1F Joseph A Kelly
Apt 2E Caroline R Mulcahy
Apt 3H Alexandra Digioia
Apt 2Y Dorothy E Bailey
Apt 3Q William T Ulmer
Apt 2A Betty M Merrell
Apt 2B Bette A Hutchings
Apt 2V Catherine C Fabrizio
Apt 1V Theresa R Pietrafesa
Apt 1K John A Battista
Apt 2I Jade Ragoschke
Apt 3U Stacey A Travaglini
Apt 1Q Melissa Begendorf
Apt 3T Susan R Kaufman
Apt BB Nancy Portilla
Apt 2T Marie R Garvey
Apt 1G Benjamin B Clever
Apt 3S Gregory J Hansen
Apt CC Margaret G Dodge
Apt 1N George S Case JR
Apt 2Q Stephen Britton
Apt 3C Anita Dlugosz
Apt 3V Deborah A Fied
Apt 3Q Humberto Quinones JR
Apt 2X Christopher M Lane
Apt 1C Kristina M Schlote
Apt 1D Charles J Wittwer JR
Apt 3R Tracy L Goldberg
Apt 1R Joseph D Oliansky
Apt 1X Shelee Berghaus

# FINDINGS

## PALMER AVE

**2022** (cont.) Cole Information

| | |
|---|---|
| 1815 | Apt 3M Edward Riley |
| | Apt 3E John Vasili |
| | Apt 3G Cesare Ricchezza |
| | Apt 1U Stephen Kimmey |
| | Apt 2L William Houghton |
| | Apt 3J Kathleen Haas |
| | Apt 3N Dominic Frassino |
| | Apt 2S Elizabeth Rapuano |
| | Apt 2F Mary Mick |
| | Apt 2C Stephanie Roberts |
| | Apt 2D Deanna M Delborgo |
| | Apt 3L Cheryl A Palermo |
| | Apt 3S Nicole Fernandez |
| | Apt 3D Brian F Benedik |
| | Apt 3P Trinh Tran |
| | Apt 2R Susan Egan |
| | Apt 2N Oksana N Konobeyeva |
| | Apt 1Z Enid K Morrone |
| | Apt 2E Annamaria Gallello |
| | Apt 1L Sharon H Falvey |
| | Apt 3O Erica Poccia |
| | Apt 2Z Arthur Stanton |
| | Apt 3N Othilyn Gonzales |
| | Apt 2L Jodieann A Lucie |
| | Apt 1Y John Carey JR |
| 1825 | Apt 2C Kimberly A Couzens |
| | Apt 1D Jimmy A Ibarra |
| | Apt 1E Harriet R Cohen |
| | Apt 1A Ann M Satalich |
| | Apt 2B Arnold P Mumford |
| | Apt 1C Hugh K O'Donnell |
| | Apt 1F Louis Salicrup |
| | Apt 3B Joseph Tricamo |
| | Apt 2E Daniel C Molluzzo |
| | Apt 3F Steven K Ross |
| | Apt 2A Joseph Fiorita |
| | Apt 1B Wendy L Vega |
| | Apt 3E Kathleen Fitzgerald |

## PALMER AVE

**2022** (cont.) Cole Information

| | |
|---|---|
| 1825 | Apt 3A Carla J Bernard |
| | Apt 3C Thomas Haughey |
| 1833 | Apt 3J |
| | PATRICIA GARDENS |
| | Apt 3C Allen P Weaver |
| | Apt 3J Beth E Starkin |
| | Apt 1D Hector L Eugui |
| | Apt 3D Gina Gelardo |
| | Apt 2B Elyse E Robowsky |
| | Apt 1K Cheryl A Dundon |
| | Apt 1C Juan Soto |
| | Apt 1A Travis J Wong |
| | Apt 3A Dmitriy Ostrovskiy |
| | Apt 1F Nancy C Arbuco |
| | Apt 1E John R Reid |
| | Apt 2F Bennedetto Orsino |
| | Apt 2J Ann Bez |
| | Apt 2A Laurie R Marinaro |
| | Apt 1B Nicole C Amato |
| | Apt 1K Carolina Rosales |
| | Apt 2K John M Quinlan |
| | Apt 2C Josephine Giardina |
| | Apt 2D Melissa Welch |
| | Apt 1B Dominick J Riccardulli |
| | Apt 1K Graciela Candia |
| | Apt 3J Frankie Gonzalez |
| | Apt 3K Monica Kelly |
| | Apt 1D Anna Gonzalez |
| | Apt 1J Cathriona A Carey |
| 1865 | Ste 104 DEERE |
| | Ste 208 OBEX SECURITIES |
| | BLOOMBERG LP |
| | Ste 207 AMERICAN TARTARIC PRODUCTS INC |
| | Ste 104 DORMROOMFUND |
| | ATPGROUP |
| | Ste 104 LIFELOCK INC |
| | Ste 104 BESSEMER VENTURE PARTNERS |
| | Ste 207 |

# FINDINGS

## PALMER AVE

**2022** (cont.)

Cole Information

| | |
|---|---|
| 1865 | Ste 207 AMERICAN TARTARIC PRODUCTS, INC |
| | Ste 207 AMERICAN TARTARIC PRODUCTS |
| | Ste 203 L AND M EQUITY PARTICIPANTS |
| | Ste 203 C&C AFFORDABLE MANAGEMENT, LLC |
| | Ste 203 L M DEVELOPMENT PARTNERS INC |
| | Ste 108 NEGRIN JOEL PC |
| | Ste 203 NORMAS CAFE |
| | Ste 104 BVP |
| | SANTAMONICA PARTNERS |
| | Ste 210 IRIDIUM CONSULTING LLC |
| | Ste 104 DEER MANAGEMENT CO LLC |
| 1875 | PETER JONAS INSTALLATION DECORATOR LLC |
| | ROSWELL PARK CANCER INSTITUTE |
| | Ste 209 AMERITRADE |
| | Ste 209 ISLAND DESTINATIONS |
| | CENTRE STAGE |
| | ELLEN MARIE DAY SPA |
| | BACK PAIN ALLIANCE |
| | Ste 202 THE OLD CANNERY SPECIALTIES LLC |
| | I D TRAVEL GROUP |
| | Ste 209 M J SERVICE CORP |
| | CLOCK TOWER LARCHMONT CORPORATION |
| | Ste 3 TEDDY HAIR SALON |

## PALMER AVE

**2017**

Cole Information

| | |
|---|---|
| 1299 | Apt 332 STEPHEN D GUTMANN |
| | Apt 236 HONORA CARE MGT CONSULTING LLC |
| | Apt 112 HAKWOON LEE |
| | GNS BEVERAGE INC |
| | Apt 232 MARIA L ABINANTI |
| | Apt 315 ODENIS ABREU |
| | Apt 201 STEVEN A ACCINELLI |
| | Apt 336 PAUL P ADAMO |

## PALMER AVE

**2017** (cont.)

Cole Information

| | |
|---|---|
| 1299 | Apt 318 MELODY O AFRIYIE |
| | Apt 216 K ALLEN |
| | Apt 115 VENERA V BARCELLONA |
| | Apt 206 MARK D BERGER |
| | Apt 205 TARA A BERNARDINO |
| | Apt 118 F BOUSENNA |
| | Apt 334 CHRISTOPHER G BOYLE |
| | Apt 224 PETER CASALINA |
| | Apt 128 GREGORY J COMITO |
| | Apt 119 JANET CONLEY |
| | Apt 314 SUSAN M COONEY |
| | Apt 134 VINCENT P COYNE |
| | Apt 215 JAMIE S CRONIN |
| | Apt 219 FRANCESCA H CROWTHER |
| | Apt 111 GEORGE R DELFICO |
| | Apt L3 DONNA R DIFALCO |
| | Apt 132 ZAKI E EL-ADAWY |
| | Apt 214 GERRI L FLIGEL |
| | Apt 321 ROBERT A FRABASILE |
| | Apt 108 CHARLOTTE V FREDE |
| | Apt 101 THOMAS J FURLONG |
| | Apt 107 MARION L GIMBEL |
| | Apt 122 B GIRARDI |
| | Apt 120 ANNA GORELOVA |
| | Apt 332 STEPHEN D GUTHMANN |
| | Apt 234 PAUL J HEACOCK |
| | Apt 319 ROBERT H HECKMANN |
| | Apt 311 JANETTE HERNANDEZ |
| | Apt 327 LYNN M HORNER |
| | Apt 202 SEBASTIAN INFANTE |
| | CELESTE JOHN |
| | Apt 308 JOHN T JOLLY |
| | Apt 322 RICHARD E KAPLAN |
| | Apt 236 SUSAN E KEATING |
| | GREG D KEEFER |
| | Apt 324 MARY Q KING |
| | Apt 121 KEVIN F KITTLE |
| | Apt 325 JANE E KROMM |

# FINDINGS

## PALMER AVE

**2017** (cont.) Cole Information

1299 Apt 109 JACQUELINE T LEAHY
BRYAN J LEE
Apt 335 ERIK P LIEBLEIN
Apt 209 JOSEPH A LORENTE
Apt 328 PETER J MARKEL
Apt L2 PERICA P MARKOC
Apt 204 ELLEN M MASTRO
Apt 106 MICHAEL J MCBRIDE
Apt 310 SEAN R MCCARTHY
Apt 203 EMANUEL MCCOWN
Apt 237 JOHN F MCIVOR
Apt 223 MARTHA I MEDINA
Apt 337 JOHN R MILO
Apt 210 JEAN G MOCCIA
Apt 110 MARY J MOONEY
Apt 221 RACHEL N NIEVES
Apt 228 MARA A OBRIEN
Apt 301 CLELIA C OCONNELL
Apt 211 BELEN A PAMUKOFF
Apt 306 URVASHIBEN PATEL
ALBERTO PEPE
Apt 217 LAURENCE R PRESTON
Apt 125 PAUL T PRIGODA
Apt 133 CHARLES P RABINOWITZ
Apt 230 EDWIN C REED
YARDLI ROOME
Apt 320 MICHAEL SALEM
Apt 225 DAVID P SALSBERG
Apt 302 ARTHUR SANTO
JAMES SCAGNELLI
Apt 114 MARY M SEPP
Apt 218 ANNE B SHORT
ERAM SOHAIL
Apt 238 RITA P SPAMPINATO
Apt 222 CELESTE A STJOHN
Apt 131 THOMAS H STRITCH
FRANCES M TAVOLILLA
CIRO TERRANOVA

## PALMER AVE

**2017** (cont.) Cole Information

1299 Apt 117 ERIK VECVAGARS
Apt 303 ROSE M VESCOVI
CAROLYN WALCOTT
Apt 104 BRIAN D WEBB
Apt 329 WILLIAM A WEBB
Apt 330 MICHAEL T WELDON
Apt 208 NANCY M ZIMMERMAN
1815 Apt 2X SHOT FROM THE ROUGH INC
Ste 2 FUTTERMAN CAROL LCSW
LOMONACO S MD
Apt 2X LINDSAY C ALEXANDER
Apt 3I LEVON ALEXANIAN
Apt 3U LIZANDRA AYALA
Apt 1T MARC J BARBELLA
Apt 1F MICHAEL BARTEE
Apt 2I ANTHONY J BASILE
Apt 3W ANTHONY J BASILE
Apt 1Q MELISSA S BEGENDORF
Apt 1X SHELEE L BERGHAUS
SHIRLEE BERTHAUS
Apt 3B ASHLEY BILLONE
Apt 2Q STEPHEN J BRITTON
Apt 2N S CAMPANELLA
JASON CAPALBO
Apt 1N GEORGE S CASE
Apt AA CHARLES T CORNING
Apt 1E ANNA A CORTESE
Apt 2B DORA DIAZ
Apt 3H ALEXANDRA DIGIOIA
Apt 1S PATRICK J DILLON
Apt CC MARGARET G DODGE
Apt 3G GREGORY A DRAKE
Apt 2R SUSAN M EGAN
Apt 2V CATHERINE C FABRIZIO
Apt 1L SHARON H FALVEY
Apt 3V DEBBIE A FIED
Apt 3M ROSITA FUGARINO
Apt 3A JOSE GARRIDO

# FINDINGS

## PALMER AVE

**2017** (cont.) Cole Information

1815 Apt 2T MARY R GARVEY
Apt 1M DANIEL S GOROFF
Apt 2Y DOROTHY GUTIERREZ
Apt 3J KATHLEEN P HAAS
Apt 2P MARC F IACOVELLI
Apt 3T SUSAN R KAUFMAN
Apt 3C DEBORAH L KEARNEY
STEPHEN KIMMEY
Apt 3X LAURIE LIEBERMAN
Apt SUPT SAL A MALLET
JULIAN MARTINEZ
Apt BB MARK H MERKER
Apt 2L BETTY M MERRELL
Apt 2F MARY K MICK
Apt 2K MONICA P MONROY
Apt 1Z ENID K MORRONE
Apt 2E CAROLINE R MULCAHY
Apt 2H CAROLINE ORLANDO
BARBARA PEARSON
Apt 3O FRANK A POCCIA
Apt 2C STEPHANIE A ROBERTS
Apt 1C KRISTINA M SCHLOTE
Apt 1U ALEX W SCIBELLI
Apt 1Y MARYANN SEARS
Apt 1J FRANCESCO SEMILIA
Apt 2Z ART T STANTON
Apt 2U CHRISTOPHER STRICKLAND
Apt 3K TERTTU S TIMONEN
Apt 3L CHERYL A TORHAN
Apt 3P TRINH N TRAN
WILLIAM T ULMER
Apt 1P JAMES P VERSCAJ
Apt 1D CHARLES J WITTWER
1825 Apt 2E LUDAS PIANO STUDIO INC
TANO ASSOCIATES
Apt 3A CARLA N BERNARD
Apt 3F HARRIET H COHEN
Apt 2D TARA M DIGIROLAMO

## PALMER AVE

**2017** (cont.) Cole Information

1825 Apt 3E KATHLEEN M FITZGERALD
Apt 1F JOHN W FRETWELL
Apt 3C THOMAS J HAUGHEY
Apt 2F MARGARET K KELLY
Apt 1A WAYNE G MCDONNELL
Apt 3B KATHY D MENDEZ
Apt 2E DANIEL C MOLLUZZO
Apt 2B ARNOLD P MUMFORD
Apt 1D ROBERT G NAGY
Apt 1C HUGH K ODONNELL
Apt 2A JAMUS A RIVERA
Apt 1B WENDY L VEGA
1833 Apt 1F NANCY C ARBUCO
Apt 2J ANN M BEZ
Apt 3C CHRISTOPHER L CARUSO
Apt 3F MERRY L DELMONTE
Apt 1D LEEANN A DOOMES
Apt 3K MARTIN J FOSTER
Apt 3D GINA A GELARDO
Apt 3J FRANKIE P GONZALEZ
Apt 2E MELISSA V LEE
Apt 2A LAURIE R MARINARO
Apt 1J CATHRIONA A MURPHY
Apt 2F BENNY G ORSINO
Apt 3A DMITRIY OSTROVSKIY
Apt 2D GRACE PHILLIPS
Apt 1B DOMINICK J RICCARDULLI
Apt 3E RUBEN ROBLES
Apt 2B ELYSE E ROBOWSKY
Apt 1K OMAR ROSA
Apt 1C JUAN A SOTO
1865 Ste 107 SHAREHOLDER VALUE ADVISORS
Ste 203 ARVERNE PRESERVATION LLC
Ste 203 CHATSWORTH BUILDERS LLC
LAW OFFICE OF FREDERICK C
Ste 203 SITE 6 LL LLC
Ste 203 STB RETAIL OWNERS LLC
Ste 203 STB OWNERS LLC

# FINDINGS

## PALMER AVE

**2017** (cont.) Cole Information

| | |
|---|---|
| 1865 | Ste 203 C&C AFFORDABLE MANAGEMENT LLC |
| | PEARSON CAPITAL PARTNERS LLC |
| | Ste 208 OBEX COMMERCIAL LLC |
| | Ste 203 WEST 153 OWNER LLC |
| | Ste 203 MARCUS GARVEY PRESERVATION LLC |
| | Ste 203 5830 THIRD OWNER LP |
| | Ste 203 GSLM II CAPITAL PARTNERS LLC |
| | Ste 203 HARGATE JV OWNERS LLC |
| | Ste 203 ABEKEN APTS LP L&M DEVELOPME |
| | LADADANDE CORP |
| | Ste 20 NEW JAMESTOWN GP LLC |
| | Ste 203 EAST 21 RETAIL LLC |
| | Ste 203 GKV PRESERVATION PARTNR LP |
| | Ste 203 EDGECOMBE PRESERVATION LLC |
| | Ste 203 AVENUE D OWNERS LLC |
| | Ste 203 L&M EMPLOYMENT SERIES LLC |
| | Ste 203 E3 OWNER LLC |
| | Ste 203 COMMERCIAL BROAD ST LTD LBLTY |
| | Ste 203 DELANCEY BUILDERS LLC |
| | Ste 203 AVERY MANAGEMENT WEST INC |
| | Ste 203 L & M COMMONWEALTH CNSTR LLC |
| | Ste 108 SANTA MONICA PARTNERS |
| | Ste 207 BENNETT VLY VINYRD WINERY INC |
| | Ste 203 GK PRESERVATION LLC |
| | Ste 203 109 MVLM LLC |
| | Ste 203 MADISON COMMERCIAL OWNERS LLC |
| | Ste 203 BEAUMONT AVENUE APARTMENTS LP |
| | Ste 203 G LAMP OWNER LLC |
| | Ste 203 KENT & WYTHE OWNERS LLC |
| | Ste 203 PARK ROW 23 OWNERS LLC |
| | Ste 203 TRIBOROUGH PRESERVATION LLC |
| | Ste 203 ART INVESTORS LLC |
| | Ste 203 PH RESIDENTIAL LLC |
| | Ste 203 F2 OWNER LLC |
| | SMP ASSET MANAGEMENT LLC |
| | Ste 203 PEARSON L&M TIC LLC |
| | Ste 104 DEER IV & CO LLC |
| | Ste 203 L & M DEVELOPMENT PARTNERS INC |

## PALMER AVE

**2017** (cont.) Cole Information

| | |
|---|---|
| 1875 | Ste 209 BARTLETT REAL ESTATE ASSOC LLC |
| | AMERICAN FRIENDS OF KASHMIR |
| | Ste 3 TEDDY HAIR SALON |
| | Ste 202 OLD CANNERY SPECIALTIES LLC |
| | I D TRAVEL GROUP |
| | BELL TOWER ASSOCIATES |

## PALMER AVE

**2017** Data Axle

| | |
|---|---|
| 1833 | Apt 1C PATRICIA GARDENS |

## PALMER AVE

**2014** Cole Information

| | |
|---|---|
| 1299 | 1299 PALMER AVENUE INCORPORATED |
| | MARKET ACCESS |
| | Apt 320 MICHAEL SALEM |
| | Apt 225 DAVID P SALSBERG |
| | Apt 302 ARTHUR SANTO |
| | Apt 114 MARY M SEPP |
| | Apt 218 ANNE B SHORT |
| | Apt 334 ERAM SOHAIL |
| | Apt 238 MICHAEL A SPAMPINATO |
| | Apt 308 AMIR STEINBERG |
| | Apt 131 THOMAS H STRITCH |
| | Apt 133 CHARLES P RABINOWITZ |
| | Apt 103 MARTHA P REDDINGTON |
| | Apt 230 EDWIN C REED |
| | Apt 332 MARIA RIZZO |
| | Apt 120 GLENN H ROTH |
| | Apt 208 NANCY M ZIMMERMAN |
| | CAROLYN WALCOTT |
| | Apt 329 WILLIAM A WEBB |
| | Apt 233 ESTELLE S WEINTRAUB |

# FINDINGS

## PALMER AVE

**2014** (cont.) Cole Information

1299 JAMES J WELDON
Apt 323 MONICA WROBEL
Apt 303 ROSE M VESCOVI
CIRO TERRANOVA
Apt 228 MARA A OBRIEN
Apt 125 PAUL T PRIGODA
Apt 215 TIMOTHY NELSON
Apt 306 URVASHIBEN PATEL
Apt 217 LARRY PRESTON
Apt 102 MARIE CORRADO
Apt 119 VINCENT P COYNE
Apt 219 FRANCESCA H CROWTHER
Apt 221 MARK D BERGER
Apt 205 TARA A BERNARDINO
Apt 118 F BOUSENNA
Apt 132 ZAKI E EL-ADAWY
Apt 111 GEORGE R DELFICO
Apt 101 DOREEN DENNING
Apt 136 ANDREW C DHANRAJ
Apt L3 DONNA R DIFALCO
Apt 234 PAUL J HEACOCK
Apt 319 ROBERT H HECKMANN
Apt 311 JEANETTE HERNANDEZ
Apt 202 SEBASTIAN INFANTE
Apt 231 GREGORY J GIBSON
Apt 107 MARION L GIMBEL
Apt 122 B GIRARDI
SARAH B GROSSMAN
Apt 214 GERRILYNN FLIGEL
Apt 312 JOSEPH F FORTUNA
Apt 321 ROBERT A FRABASILE
Apt 108 CHARLOTTE V FREDE
Apt 335 ERIK P LIEBLEIN
Apt 212 JUSTIN KANE
Unit 3221 RICHARD KAPLAN
Apt 236 SUSAN E KEATING
GREG D KEEFER
Apt 324 MARY Q KING

## PALMER AVE

**2014** (cont.) Cole Information

1299 Apt 121 KEVIN F KITTLE
MELISSA KLEPACK
Apt 325 JANE E KROMM
Apt 307 DANIEL M MARCUCCI
Apt 328 PETER J MARKEL
Apt L2 PASHKA P MARKOC
Apt 209 ANGELA MARTELLI
Apt 204 ELLEN M MASTRO
Apt 106 MICHAEL J MCBRIDE
Apt 310 SEAN R MCCARTHY
Apt 203 EMANUEL MCCOWN
Apt 338 JOHN F MCIVOR
Apt 223 MARTHA I MEDINA
Apt 333 WILLIAM MICHIELS
Apt 337 ROBERT MILO
Apt 210 JEAN G MOCCIA
Apt 110 MARY J MOONEY
Apt 220 BRIAN CORCORAN
Apt 314 SUSAN M COONEY
JANET CONLEY
Apt 128 GREGORY J COMITO
DOMINICK J CASTALDO
Apt 207 PETER CASALINA
Apt 336 PAUL P ADAMO
Apt 112 BRYAN J LEE
Apt 201 STEVEN ACCINELLI
1815 LOMONACO S MD
FUTTERMAN CAROL LCSW
Ste 3 ROSENBLUM EDWARD S DDS
Apt 2A BETTY M MERRELL
Apt 2F MARY K MICK
JAIME MUCCIOLO
Unit 6 HECTOR ALVAREZ
Apt 3U LIZANDRA AYALA
Apt 1T MARC J BARBELLA
Apt 1F STANLEY L BARTEE
Apt 1K JOHN A BATTISTA
Apt 1X SHELEE L BERGHAUS

# FINDINGS

## PALMER AVE

**2014** (cont.)

Cole Information

1815 Apt 3D MICHAEL F BORUCH
Apt 2Q STEPHEN D BRITTON
BARBARA BRIZEL
Apt 2R FILOMENA M BRUSCHI
Apt 2B GISELLE FERREIRA
Apt 3V DEBBIE A FIED
Apt 3B ATTILIO FRANCIOLI
MARIA T DABNEY
JOSEPH M DAMICO
PATRICK J DILLON
MARGARET G DODGE
Apt 1Q JOHN CAREY
GEORGE S CASE
Apt 1Z EVAN N CHRISTON
CHARLES T CORNING
Apt 3R JAMES J HALLIGAN
MARYANN A HARRINGTON
Apt 3A JOSE GARRIDO
Apt 2T MARY R GARVEY
OTHILYN B GONZALES
Apt 1M NORIKO M GOROFF
Apt 1L SHARON H FALVEY
Apt 2X CHRISTOPHER M LANE
Apt 3X LAURIE LIEBERMAN
SALVATORE D LOMONACO
Apt 2L JODIE LUCIE
Apt 3G TRUDY KANE
Apt 3T MAIA S KAUFMAN
Apt 3C DEBORAH L KEARNEY
Apt 1G SCARLETT C KELLY
Apt 3I TIMOTHY MCQUESTION
BARBARA PEARSON
Apt 2K MONICA P PEREZ
Apt 2J BILL D PERSKY
Apt 1V TERESA R PIETRAFESA
Apt 3P TRINH N TRAN
Apt 3L CHERYL PALERMO
Apt 3K TERTTU S TIMONEN

## PALMER AVE

**2014** (cont.)

Cole Information

1815 Apt 1P JAMES P VERSCAJ
Unit 207 WILLIAM T ULMER
Apt 1D CHARLES J WITTWER
Apt 2Z ART T STANTON
Apt 3H KENNETH B SMALLWOOD
Apt 1J FRANCESCO SEMILIA
MARYANN SEARS
Apt 1U ALEX W SCIBELLI
Unit A2Z DONNA M SCHNEIDER
Apt 1C KRISTINA M SCHLOTE
Apt 1R JOSEPH D OLIANSKY
1825 Apt 1C HUGH K ODONNELL
Apt 2A JAMUS A RIVERA
Apt 1B WENDY L VEGA
Apt 3C ROBYN L STAWARZ
Apt 3B KATHY D MENDEZ
Apt 1F KATHERINE JENSEN
Apt 2B ARNOLD P MUMFORD
Apt 2F MARGARET K KELLY
HARRIET R COHEN
Apt 3D GEORGE J FOWLER
KATHLEEN M FITZGERALD
Apt 3A CARLA J BERNARD
Apt 1D GRACE B BELFIORE-NAGY
LIOUDMILA ASTAKHOVA
1833 PATRICIA GARDENS
STEPHANIE STUART
Apt 2C ANDREW J RINALDI
THOMAS H REID
Apt 1D MIGDALIA ROSA
Apt 1C JUAN A SOTO
RUBEN ROBLES
Apt 2F BENNY G ORSINO
Apt 1A COURTNEY B WONG
Apt 1B DOMINICK J RICCARDULLI
Apt 2B ELYSE C ROBOWSKY
Apt 1F NANCY C ARBUCO
Apt 2J ANN M BEZ

# FINDINGS

## PALMER AVE

**2014** (cont.) Cole Information

1833 Apt 1J CATHRIONA A MURPHY
Apt 3K MARTIN J FOSTER
Apt 3J FRANKIE P GONZALEZ
Apt 3D GINA A GELARDO
Apt 3F MALCOLM W CHARMAN
Apt 3C CHRISTOPHER L CARUSO
Apt 2A LAURIE R MARINARO

1865 Ste 108 NEGRIN JOEL PC
Ste 208 OBEX SECURITIES
Ste 107 SHAREHOLDER VALUE
Ste 108 SANTAMONICASANTAMONICA SANTAMONICASA
20 MINUTE LOCKSMITH
AONE TWENTY FOUR HOUR EMERGENCY LOCK
Ste 207 AMERICAN TARTARIC PRODUCTS
Ste 207 AMERICAN TARTARIC INCORPORATED
Ste 104 BESSEMER VENTURE PARTNERS
Ste 104 DEER MANAGEMENT COMPANY LLC
Ste 210 CUCCIA FREDERICK J LAW OFFICE OF
GAVRIN DAVID M SUITE 108
Ste 203 L & M EQUITY PARTICIPANTS LTD
Ste 203 L & M EQUITY PARTICIPANTS

1875 AMERICAN FRIENDS OF KASHMIR
BELL TOWER ASSOCIATES
Ste 2 CENTRE STAGE
CLOCK TOWER ASSOCIATES
CLOCK TOWER LARCHMONT CORPORATION
PALMER AVENUE ASSOCIATES
ELLEN MARIE DAY SPA
ISLAND DESTINATIONS
Ste 3 TEDDY HAIR SALON
I D TRAVEL GROUP
Ste 202 WHITEFLINT SPORTS LIMITED
Ste 206 BAILEY NAN P

## PALMER AVE

**2010** Cole Information

1299 1299 PALMER AVE INC
Apt 115 LEA A RICCI
Apt 114 GEORGE G WEINBERG
Apt 318 LAUREN N WEISS
Apt 329 BRIAN D WEBB
Apt 201 STEVEN ACCINELLI
Apt 227 MICHAEL J PETERS
Apt 206 MARK D BERGER
Apt 205 TARA A BERNARDINO
Apt 327 MOLLY BAILEN
Apt 309 ANTHONY S BAKER
Apt L1 ANGELINA D BARTOLI
Apt 118 F BOUSENNA
Apt 223 MARTHA FIGUEROA
Apt 322 RICHARD P KAPLAN
Apt 325 JANE E KROMM
Apt 221 RACHEL N NIEVES
Apt 108 LINDA F TRIPICCO
Apt 137 ROBERT J GEBERTH
Apt 231 A GIBSON
Apt 107 MARION L GIMBEL-SINGER
B GIRARDI
Unit 479 LAURENCE R PRESTON
Apt 321 ROBERT A FRABASILE
Apt 210 GRACE DAGOSTINO
Apt 208 LARRY A ZIMMERMAN
Apt 117 ANTHONY A DEPERNA
Apt 234 PAUL J HEACOCK
Apt 124 CHARLES C HEIDSIECK
Apt 311 JEANETTE HERNANDEZ
Apt 202 E HILL
Apt 211 GRACE C HRISTON
Apt 132 ZAKI E EL-ADAWY
GREG D KEEFER
Apt 133 EDWARD P KEATING
ALISON KEANE
Apt 121 KEVIN F KITTLE
Apt 324 SETH S KING

# FINDINGS

## PALMER AVE

**2010** (cont.) Cole Information

| | |
|---|---|
| 1299 | Apt 105 WANDA M MAYEWSKI |
| | Apt 328 PETER J MARKEL |
| | BERNARD MAGDELAIN |
| | Apt 336 PAUL P ADAMO |
| | Apt 120 GLENN H ROTH |
| | Apt 230 EDWIN C REED |
| | Apt 103 MARTHA P REDDINGTON |
| | Apt 301 CLELIA C OCONNELL |
| | Apt 119 JANET CONLEY |
| | LENA COPPELETTI |
| | Apt 134 VINCENT P COYNE |
| | Apt 305 MARY E CONDON |
| | Apt 207 CONSTANCE C CASALINA |
| | Apt 302 VINCENT A SANTO |
| | Apt 337 LARA VIVOLO |
| | Apt 335 ANNETTE F LIEBLEIN |
| | Apt 308 JOHN T JOLLY |
| | Apt 303 ROSE M VESCOVI |
| | Apt 225 DAVID P SALSBERG |
| | Apt 320 MICHAEL SALEM |
| | Apt 218 ANNE B SHORT |
| | Apt 131 THOMAS H STRITCH |
| | Apt 238 MICHAEL A SPAMPINATO |
| | Apt 228 MARA L OBRIEN |
| | Apt 216 TAMARA L MILLIKAN |
| | Apt 333 ROBERT MICHIELS |
| | MARIE A CILENTO |
| | Apt L2 JOSE M CRUZ |
| | Apt 219 PAULETTE I CROWTHER |
| | MATTHEW LOMBARDI |
| | Apt 110 MARY J MOONEY |
| | JOHN F MCIVOR |
| | Apt 203 GLORIA J MCCOWN |
| | Apt 312 FRANCIS S LEVETT |
| | Apt 106 MICHAEL J MCBRIDE |
| | Apt 310 SEAN R MCCARTHY |
| | Apt 112 HEESOON LEE |
| 1815 | Ste 3 ROSENBLUM EDWARD S DDS |

## PALMER AVE

**2010** (cont.) Cole Information

| | |
|---|---|
| 1815 | Ste 1 LOMONACO S MD |
| | FUTTERMAN CAROL |
| | Apt 2F MARY K MICK |
| | Apt 1P JAMES P VERSCAJ |
| | Apt 1X JOI L CARUSO |
| | GEORGE S CASE |
| | Apt 1R JOSEPH D OLIANSKY |
| | ANNA A CORTESE |
| | CHARLES T CORNING |
| | Apt 2U RUTH A CHIAIA |
| | SABINA CHESNIK |
| | Apt 2X JOHN MULLEN |
| | Apt 2Z ART T STANTON |
| | Apt 1U CAROLYN CIARDULLO |
| | Apt 3H KENNETH B SMALLWOOD |
| | WALTER J SEARS |
| | Apt 1J SKEHAG SEMILIA |
| | SALVATORE D LOMONACO |
| | Apt 3I AMANDA CUNEY |
| | Apt 3U LIZANDRA AYALA |
| | MONICA P MONROY |
| | Apt 2A BETTY M MERRELL |
| | Unit 792 ERNEST J CAROLAN |
| | Apt 1T MARC J BARBELLA |
| | Apt 3J KATHLEEN P HAAS |
| | MARYANN A HARRINGTON |
| | Apt 3R JAMES J HALLIGAN |
| | Apt 1F STANLEY L BARTEE |
| | Apt 3T GERARDO MARIANI |
| | MARIANNE W MAKMAN |
| | OTHILYN B GONZALES |
| | NANCY PORTILLA |
| | JOSEPH M DAMICO |
| | Apt 3L CYNTHIA J DANZA |
| | MARGARET G DODGE |
| | Apt 2C DOUG F DOWHARD |
| | SINHA HEMA |
| | Unit 6 HECTOR ALVAREZ |

# FINDINGS

## PALMER AVE

**2010** (cont.)

Cole Information

| | |
|---|---|
| 1815 | Apt 3Q HUMBERTO QUINONES |
| | Apt 3C DEBORAH L KEARNEY |
| | Apt 3Y CHRISTOPHER B KERSON |
| | ERIN KESSLER |
| | Unit 675 DAVID L WISOWATY |
| | Apt 1D CHARLES J WITTWER |
| | Apt 3B ATTILIO FRANCIOLI |
| | Apt 1V TERESA R PIETRAFESA |
| | SHARON N FALVEY |
| | BARBARA PEARSON |
| | Apt 3X IRENE T PECHECO-GEBERT |
| | Apt 2J BILL D PERSKY |
| | CAROL FUTTERMAN |
| | Apt 3V DEBBIE A FIED |
| | Apt 3G TRUDY KANE |
| | Apt 2Q STEPHEN D BRITTON |
| | BARBARA BRIZEL |
| | Apt 2R ROBERT J BRUSCHI |
| | Apt 3K TERTTU S TIMONEN |
| | Apt 3P TRINH N TRAN |
| | Apt 1C ANDREW T TAVOLARIO |
| | Apt 2T MARY R GARVEY |
| 1825 | Apt 3D GEORGE J FOWLER |
| | Apt 2C JENNIFER M ROMMEL |
| | KATHLEEN FITZGERALD |
| | LIOUDMILA ASTAKHOVA |
| | Apt 1D GRACE B BELFIORE-NAGY |
| | HARRIET R COHEN |
| | Apt 3C ROBYN L MILLO |
| | Apt 2B ARNOLD P MUMFORD |
| | Apt 1C HUGH K ODONNELL |
| | Apt 1A WAYNE G MCDONNELL |
| | Apt 3F MICHAEL A LEVY |
| | Apt 1B WENDY L VEGA |
| 1833 | Apt 1C PATRICIA GARDENS |
| | Apt 1D MIGDALIA ROSA |
| | Apt 1F NANCY ARBUCO |
| | Apt 3D GINA A GELARDO |

## PALMER AVE

**2010** (cont.)

Cole Information

| | |
|---|---|
| 1833 | Apt 3K MARY M FOSTER |
| | Apt 2D FRANCES A DETHOMAS |
| | ANN M BEZ |
| | Apt 1C JUAN A SOTO |
| | Apt 3J BETH E STARKIN |
| | Apt 3C JENNIFER MULLEN |
| | Apt 2F BENNY G ORSINO |
| 1865 | AMERICAN SALES & MARKETING |
| | Ste 104 DEER IV & CO LLC |
| | Ste 207 AMERICAN TARTARIC PRODUCTS |
| | EISNER COMPUTER SOLUTIONS |
| | Ste 203 L & M DEVELOPMENT PARTNERS INC |
| | Ste 210 J FREDERICK CUCCIA LAW OFFICE |
| | Ste 108 L J GOLDSTEIN & CO |
| | Ste 107 SHAREHOLDER VALUE ADVISORS |
| | Ste 208 OBEX SECURITIES |
| | Ste 108 JOEL NEGRIN PC |
| | Ste 104 BESSEMER VENTURE PARTNERS |
| | Ste 104 BVP |
| | JOEL NEGRIN |
| 1875 | CLOCK TOWER LARCHMONT CORP |
| | CENTRE STAGE |
| | PETER JONAS INSTALLATION DCRTR |
| | Ste 1 E B BARRETT INC |
| | Ste 206 BAILEY NAN P |
| | Ste 202 WHITEFLINT SPORTS LTD |
| | Ste 209 ISLAND DESTINATIONS |
| | ELLEN MARIE DAY SPA |

## PALMER AVE

**2005**

Cole Information

| | |
|---|---|
| 1299 | PRESTON LAURENCE |
| | EUGENE ZULLO |
| | Apt 130 CLAUDIA J FULLER |
| | Apt 229 LISA A GREGORY |

# FINDINGS

## PALMER AVE

**2005** (cont.) Cole Information

1299
- Apt 232 MICHAEL E GRIMES
- Apt 224 SARAH B GROSSMAN
- Apt 137 ROBERT J GEBERTH
- DEBRA GOLDSTEIN
- Apt 231 A GIBSON
- MARIO GIMBEL
- B GIRARDI
- Apt 325 VIOLET C TAYLOR
- Apt 301 PATRICIA V BORGES
- Apt 118 F BOUSENNA
- Apt 217 LAURENCE R PRESTON
- Apt 327 MOLLY BAILEN
- Apt 309 ANTHONY S BAKER
- Apt 111 JOHN J BARRETT
- Apt L1 ANGELINA BARTOLI
- Apt 233 VINCENT A POMA
- Apt 324 NICOLE M WHITE
- Apt 223 CHARLES R WEBB
- Apt 132 ZAKI E EL-ADAWY
- Apt 322 RICHARD P KAPLAN
- Apt 323 LORNA J KAWASHIMA
- Apt 121 KEVIN F KITTLE
- ALISON KEANE
- BERNARD MAGDELAIN
- Apt 328 PETER J MARKEL
- Apt 105 WANDA M MAYEWAKI
- Apt 103 MARTHA P REDDINGTON
- Apt 222 RICHARD S ROCK
- Apt 135 FREDERICK W ROOME
- Apt 120 GLENN H ROTH
- Apt 336 PAUL P ADAMO
- Apt 114 CARIN F HOROWITZ
- Apt 202 E HILL
- Apt 124 KATHLEEN C HEIDSIECK
- Apt 234 PAUL J HEACOCK
- Apt 211 LOUCAS P HRISTON
- JOAN DAPOLITE
- LUCA ZANIA

## PALMER AVE

**2005** (cont.) Cole Information

1299
- Apt 208 LARRY A ZIMMERMAN
- Apt 334 ELAINE DELFAVERO
- Apt 235 ESTEBAN ALVAREZ
- Apt L2 BRENDA A DEJESUS
- Apt 109 RICHARD DELBOSCO
- Apt 305 MARY E CONDON
- Apt 129 JENNIFER A COLLINS
- Apt 119 JANET CONLEY
- LENA COPPELETTI
- Apt 314 SUSAN M COONEY
- Apt 112 KWANG J LEE
- FRANCIS S LEVETT
- Apt 332 ANNE A LAPORTA
- ANTHONY E CILENTO
- Apt L3 KATHLEEN T CIOPPA
- Apt 101 JOHN LYNCH
- JOSEPH A LORENTE
- KELLY M LYNCH
- TAPIWA MULALU
- Apt 333 ROBERT MICHIELS
- Apt 133 NEIL T MILLER
- Apt 219 PAULETTE I CROWTHER
- Apt 106 MICHAEL J MCBRIDE
- J MCCANN
- Apt 310 SEAN R MCCARTHY
- Apt 338 JOHN F MCIVOR
- Apt 115 LEA A RICCI
- Apt 110 MARY J MOONEY
- Apt 207 CONSTANCE CASALINA
- Apt 225 DAVID P SALSBERG
- Apt 236 PATTI J JENNINGS
- Apt 131 SAM SCOPOLETTI
- Apt 306 AL S SCARPA
- Apt 308 JOHN T JOLLY
- Apt 303 ROSE M VESCOVIE
- Apt 335 ANNETTE F LIEBLEIN
- Apt 218 ANNE SHORT
- M OBRIEN

# FINDINGS

## PALMER AVE

**2005** (cont.) Cole Information

1299 Apt 238 MICHAEL A SPAMPINATO
Apt 212 LEV M SHAYEVICH
1815 COLONY
Apt 1R 2408 BOSTON POST ROAD LLC
Apt 2L TURNER ALLYSON CONTINENTAL LLC
MICHAEL F JOHNSTON
MICHELE SCHWEGEL
WALTER J SEARS
RYAN JENNINGS
Apt 1Z ANNA L SALVATORE
Apt 2Z ART T STANTON
Apt 2R GREGORY D STERN
Apt 3Z MICHELLE H STOLOWICKI
Apt 3U BENIGNO J CAIOLA
Unit 792 ERNEST J CAROLAN
GEORGE S CASE
S CHESNIK
Apt 2U RUTH A CHIAIA
S LOMONACO
JOSEPH LOGAN
Apt 1C JANET S MORIARTY
Apt 3I JUDITH E LIEVESLEY
Apt 1M PAUL J MIRO
Apt 2F MARY K MICK
Apt 2X ANGELO G MICHELINI
Apt 2A BETTY M MERRELL
CHARLES T CORNING
Apt 1K MARTIN J MURAFSKY
Apt 3T PERICLES MELLON
Apt 1F STANLEY L BARTEE
WILLIAM BART
Apt 3J KATHLEEN P HAAS
MARYANN A HARRINGTON
MARIANNE MAKMAN
Apt 3G GATTO J DEL
HECTOR ALVAREZ
W DAVID
Apt 3Q HUMBERTO QUINONES

## PALMER AVE

**2005** (cont.) Cole Information

1815 JOHN C RODERICK
Apt 2Q STEPHEN D BRITTON
Apt 1R JAMES T BREEN
WILLIAM J BEKEMEIER
Apt 3Y CHRISTOPHER KERSON
Apt 1H PETER J KOKENOS
KRISTEN KLIEME
SADIE EARLE
Apt 3K TERTTU S TIMONEN
TERESA GALLELLO
Apt 2T MARY R GARVEY
Apt 1X RAJAN K NAIDOO
SINHA HEMA
MARGARET G DODGE
Apt 2C DOUG F DOWHARD
GREGORY A DRAKE
Apt 3R PETER B PLAUE
Apt 2V CATHERINE C FABRIZIO
SHARON H FALVEY
Apt 2L FREDERICK D GRIMALDI
LORRAINE A PAGANELLI
OTHILYN B GONZALES
Apt 3P TRINH N TRAN
MICHAEL F BORUCH
Apt 3B ATTILIO FRANCIOLI
Apt 3H HANS D BLUNCK
Apt 3V DEBORAH A FIED
CECILE FINE
Apt 1V TERESA R PIETRAFESA
BARBARA PEARSON
MARIE C PEPIN
Apt 2J BILL D PERSKY
Unit 32 DAVID R PETER
Apt 1D CHARLES J WITTWER
1825 K FITZGERALD
Apt 3C DAVID D DILLON
LIOUDMILA ASTAKHOVA
Apt 3A CARLA BERNARD

# FINDINGS

## PALMER AVE

**2005** (cont.) Cole Information

| | |
|---|---|
| 1825 | RAHMAN DARGENIO |
| | Apt 2A ELAINE L PROFILET |
| | Apt 2C JENNIFER M ROMMEL |
| | Apt 3D GEORGE J FOWLER |
| | Apt 1B REBECCA W AXELROD |
| | Apt 1A JENNIFER D MAGGIO |
| | HARRIET R COHEN |
| | JOEL CASTELLANOS |
| | Apt 1C HUGH K ODONNELL |
| | Apt 2B ARNOLD P MUMFORD |
| | Apt 2D JULIE D CIACCI |
| 1825B | AMY S BUTLER |
| 1833 | JOHN RICHARD REID DIGITAL DESIGN |
| | JOHN RICHARD REID DIGITAL DSGN |
| | LISA FRIEDMAN |
| | Apt 1K GARY U KAPLAN |
| | KEN F MARTIN |
| | GIANCARLO DIPRIMA |
| | JOSEPH J GRAYSON |
| | Apt 3J FRANKIE P GONZALEZ |
| | ANN M BEZ |
| | Apt 3K MARY I FOSTER |
| | Apt 3C WILLIAM L MULLEN |
| | Apt 3A ELIZABETH M STANTON |
| | Apt 2F BENNY G ORSINO |
| | Apt 2D ALEXANDER H MCMILLAN |
| | Apt 1F NANCY ARBUCO |
| | S LASKY |
| | Apt 2C HERBERT JAFFE |
| 1865 | L J GOLDSTEIN & CO INC |
| | Ste 203 CLM EQUITIES |
| | Ste 207 AMERICAN TARTARIC PRODUCTS INC |
| | Ste 210 SHAREHOLDER VALUE ADVISORS |
| | Ste 104 BESSEMER VENTURE PARTNERS |
| | Ste 203 CS MELROSE COMMERCIAL LLC |
| | CUCCIA OSTER & HANSBURG |
| | Ste 210 MARK A BARBERO |
| | Ste 203 SAEEDA GILLANI |

## PALMER AVE

**2005** (cont.) Cole Information

| | |
|---|---|
| 1865 | Ste 108 SANTA MONICA PARTNERS |
| | Ste 104 BSMR VNTR INVSTR III L P |
| | Unit 10 TEACH THE EDUCTNL SEARCH CONSULTING |
| | Ste 203 PROSPECT PLAZA DEVELOPERS LLC |
| | Ste 201 WATCH HILL INVESTMENT PARTNERS |
| | Ste 203 L & M EQUITY PARTICIPANTS LTD |
| | Ste 203 L & M PROSPECT PLAZA MANAGERS LLC |
| | Ste 104 DEER III & CO |
| | Ste 104 DEER IV & CO LLC |
| | Ste 104 BVP |
| | Ste 108 GAVRIN ASSOCIATES |
| | GOLDSTEIN LAWRENCE J |
| | Ste 203 L & M WASHINGTON MANAGERS LLC |
| | Ste 208 OBEX INVESTMENTS LLC |
| | Ste 203 BX PARKVIEW DEV LLC |
| | Ste 104 ABACUS HARBOR LLC |
| | PETER NISSELSON |
| | OSTER CUCCIA |
| 1875 | COMPUTER SIGN CO |
| | BELL TOWER ASSOCIATES |
| | Ste 205 WESTCHESTER DERMATOLOGY CENTER |
| | ISLAND DESTINATIONS |
| | MARIECLAUDE INC |
| | 1875 PALMER AVE CORP |
| | KEA INTERNATIONAL |
| | ROMA VIDEO SERVICES INC |
| | OTTENSTEIN M Z & CO |
| | ELIZABETH GRADY FACE FIRST |

## PALMER AVE

**2000** Cole Information

| | |
|---|---|
| 1299 | PRESTON LAURENCE REV |
| | 1299 PALMER AVE INCORPORATED |

# FINDINGS

## PALMER AVE

**2000** (cont.) Cole Information

1299 RUSS WILLIAM STUDIO PHOTOGRAPHY
Apt 322 RICHARD KAPLAN
LORNA KAWASHIMA
ZAKI ELADAWY
Unit 33 ROBERT KREBBS
Apt 209 JILL J WOODS
Apt 225 LUCA D ZANIN
MARK ZANIN
Apt 208 NANCY A ZIMMERMAN
ELAINE DELFAVERO
Unit 2 EUGENE ZULLO
ALAN DLUGASH
Apt 115 AGNES DIFFLEY
Apt 133 ORNA HADAR
Apt 301 GREGORY HAVILAND
Apt 234 PAUL HEACOCK
Apt 233 VINCENT POMA
Apt 309 ANTHONY S BAKER
Apt 219 PAUL BARKAN
Apt 111 JOHN J BARRETT
L PRESTON
PAUL D FOOTE
Apt 211 LOUCAS P HRISTON
E HILL
Apt 133 RAUL NUNEZ
JOHN NARDELLI
E TATEO
Apt 325 VIOLET TAYLOR
Apt 231 A GIBSON
MARION GIMBELSINGER
Apt 319 B GIRARDI
STEVEN GATES
Apt 104 TRICIA A TURCO
Apt 137 ROBERT GEBERTH
Apt 206 SEPEHR GRANFAR
J GREENBERG
Apt 134 DEBRA E GOLDSTEIN
Apt 109 J ALLEYNE

## PALMER AVE

**2000** (cont.) Cole Information

1299 R FENTON
Apt 232 ARNOLD BREAKSTONE
Apt 318 J BOCCINI
Apt 206 G BODNAR
Apt 118 F BOUSENNA
Apt 224 TRACY BELL
Apt 221 M BERGER
Unit A ERIC A BLUNT
Apt 127 V BUONO
Apt 227 MICHAEL J PETERS
Apt 116 LUIS E PABON
Apt 229 ROY A ARCHER
Apt 316 M REDDINGTON
Apt 320 CHRISTA REICHELT
Apt 222 RICHARD ROCK
Apt 230 VINCENT ROMAGNOLI
CHARLES H ROTHSCHILD
Apt 206 NAZARIA L RIBOLINO
Apt 106 MICHAEL J MCBRIDE
ROBERT J MCCARTHY
SEAN R MCCARTHY
LILLIAN MACNAUGHTON
PETER MARKEL
Apt 105 H MAYEWSKI
SEMIR KAPETANOVIC
Unit A B MITCHELL
Apt 304 ANTHONY CILENTO
Apt L3 K CIOPPA
Apt 324 KEVIN ONEILL
SHAUN CUSICK
Apt 335 A LIEBLEIN
Apt 305 EDWIN J CONDON
Apt 314 SUSAN COONEY
Apt 219 ALISA B LOEFFEL
Apt 131 DAWN LOMBARDI
Apt 112 KWANG J LEE
H LEVITAN-UR
Apt 101 FRED S LEVY

# FINDINGS

## PALMER AVE

**2000** (cont.)

Cole Information

1299 Apt 306 AL SCARPA
Apt 235 SUSAN SHOOP
Apt 218 A SHORT
Apt 236 PATTI JENNINGS
Apt 333 WILLIAM MICHIELS
Apt L2 ANNETTE CARRASQUILLO
CAROL A CAPPIELLO
MARIA C OCONNELL
Apt 110 M J MOONEY
Apt 204 LILLIAN MORA
B SNIPAS
DAWN SUSCA
Apt 308 JOHN JOLLY
Apt 238 MICHAEL SPAMPINATO
Apt 228 MARIO STANO
WILLIAM STAGER
Apt 121 C JACKSON
KELLY M LYNCH
1811 OCCUPANT UNKNOWN
1815 MAKMAN MARIANNE MD
SAFIAN MURRAY Z PH D
ROSENBLUM EDWARD S DDS
LOMONACO S MD
Apt 3J K HAAS
Apt 1Q ELLEN A MALISCHKE
J JORLING
WALTER J SEARS
Apt 1J MARIA SEMILIA
J S MORIARTY
Apt 1M PAUL MIRO
Apt 3G SUSAN R LUECKE
ERNEST J CAROLAN
Apt 3G GEORGE S CASE
Apt 2X ANN MICHELINI
Apt 2F MARY K MICK
Apt 2P GREG J MUTSCHLER
JUSTIN JONES
ANTONIO SACOTO

## PALMER AVE

**2000** (cont.)

Cole Information

1815 PAUL VICTORY
Apt 3U ANTHONY F CAPRARO IV
Apt 2R M H LUCAS
RICHARD SCHNEIDER
Apt 1K AIMEE L DALTON
Apt 1V KAREN DAMMEYER
HEIDI DAVIS
Ste 1 ANNETTE V YOUNG
Apt 3I ERIN M ZEGEL
M G DODGE
Apt 2C DOUGLAS F DOWHARD
Apt 2C DOUG DOWNARD
Apt 3A P BARCELLONA
WILLIAM BART
Apt 1F STANLEY BARTEE
Apt 1P FRANK PONDICCIO
Apt 3G THERESA FARINACCI
Unit 130 E F FANNING
TERTTU TIMONEN
Apt 2T M GARVEY
IRENE T GEBERT
JEFFREY S GOLDSTEIN
Apt 1X ANTONIO ACEVEDO
Apt 1T EDWARD AJODAH
Apt 1D CHARLES J WITTWER
Ste 2 JOSEPH FERRIGNO
ATTILIO FRANCIOLI
GERARDO FRASSINO
Apt 2U SCOTT R FORCINO
Apt 1R JAMES S BREEN
Apt 2K JAMES A BRITTON
Apt 2Q STEPHEN BRITTON
M FLYNN
Apt 1Z ROBERT R BISACCIA
K BEAL
Unit 25 WILLIAM BEKEMEIER
Apt 2I PAUL A BELLO
Apt 1A SALLY BLUM

# FINDINGS

## PALMER AVE

**2000** (cont.)

Cole Information

1815 Apt 3H PETER BLUNCK
Apt 3M LAURA A BIGAOUETTE
M A KING
OLOF KJELLBERG
R BURCHSTED
BARBARA PEARSON
Apt 2J BILL PERSKY
L PAGANELLI
Apt 3R PETER PLAUE
HOLLY ROACH
DAVID S ROLLAND
Apt 1H HELEN M RIGSBY
KEVIN MCCARRON
P MELLON
BETTY M MERRELL
SADIE EARLE
MARION ESPOSITER
1825 Apt 1A J MAGGIO
DAVID MARCHINI
EDWARD M KIMMEY
Apt 1F MATTHEW WESTERMANN
KEVIN KENEALLY
GEORGE FOWLER
Apt 1B REBECCA AXELROD
Apt 2A ELAINE PROFILET
M D DOYLE
Apt 1A MARK HABEEB
Apt 3C J DILLON
THOMAS G MAYTROTT
Apt 3A AMY BUTLER
Unit 3 LAUREN LOUGHLIN
Apt 1D M VITALI
1833 PATRICIA GARDENS
JOHN MANNIX
Apt 2K JACK QUINLAN
Apt 1J KETY KOEN
Apt 3J THOMAS WALSH
Apt 1K GEORGE GOODLOE

## PALMER AVE

**2000** (cont.)

Cole Information

1833 Apt 1B ROBERT W PREZORSKI
FRANCES FAZIO
Apt 1A EMMET FINNERTY
Apt 1D CHERIE TITUS
K GARNEAU
ELAINE S GRAYSON
GREGG WINIARSKI
M FOSTER
RAJ SONELL
Apt 2D ERIN CONSTABILE
Apt 2C HERBERT JAFFE
1865 CUCCIA OSTER & HANSBURG
CYPRUS MINERAL COMPANY
SALINGER JAMES J INS
DOUGLAS GOULD CO
L & M EQUITY PARTICIPANTS LIMITED
BARBERO MARK A CLAIM SERVICE
ROSNER LAWRENCE M INS
BURTEN K MD
TEACH
GAVRIN DAVID M
ODANI RESEARCH COMPANY
FIRST LAWRENCE CAPITOL CORPORATION
NEW YORK PROFESSIONAL RESPONSIBILITY REPORT
GALLUP BROADCASTING CONSULTANTS
LASK INTERNATIONAL CORPORATION
WATCH HILL INVESTMENT PARTNERS
DAVENPORT & ASSOCIATES INCORPORATED
EMANUEL PUBLISHING CORPORATION
OTOOLE DENNIS P & ASSOCIATES INCORPORATED
NISSELSON PETER
GOLDSTEIN LAWRENCE J
EAGLE PRESS INCORPORATED
MEDIC-AIR CORP
AMERICAN TARTARIC PRODUCTS
AMERICAN SALES & MARKETING

# FINDINGS

## PALMER AVE

**2000** (cont.)

| | Cole Information |
|---|---|
| 1865 | MULTIMEDIA RESOURCES |
| | NATIONAL FOOTBALL FOUNDATION & HALL OF FAME |
| | BIOSINT USA INCORPORATED |
| | BAILEY NAN P |
| | Ste 205 A COSTA |
| | Ste 207 LYNN G LIBERTELLA |
| 1875 | ROMA VIDEO |
| | CLOCK TOWER ASSOCIATES |
| | KASHMIR CREWEL INTERNATIONAL |
| | ACTION COMPUTER INCORPORATED |
| | WALD MICHAEL A PHD |
| | Unit 105 KEA INTERNATIONAL INCORPORATED |
| | BRIDGES |
| | BELL TOWER ASSOCIATES |
| | FOTOMAT CORPORATION 1 HR MINILAB STORE LOCATIONS |
| | ISLAND DESTINATIONS |
| | AMERICAN FRIENDS OF KASHMIR |
| | PALMER AVE ASSOCIATES |
| | OMAHA STEAKS |
| | OTTENSTEIN M Z & COMPANY CPAS |
| | ELIZABETH GRADY FACE FIRST CORP |
| | FRIED PHILIP MD |
| | Ste 202 COMPUTER SIGN COMPANY |
| | COGENT MANAGEMENT |
| | PHILIP D FRIED |

## PALMER AVE

**1995**

| | Cole Information |
|---|---|
| 1299 | 1299 PALMER AVE INC |
| | RUSS WILLIAM STUDIO, PHOTOGRAPHY |
| | ZANIN, LUCA D |
| | GRANFAR, SEPEHR |
| | KARMEN, PETER |

## PALMER AVE

**1995** (cont.)

| | Cole Information |
|---|---|
| 1299 | HUNT, DANNER |
| | GATALETTO, DOMINICK, JR |
| | WALLACH, GARY |
| | BEHRENS, MARION |
| | JACKSON, CLIFFORD |
| | ROMAGNOLI, VINCENT |
| | CONDON, EDWIN J |
| | BREAKSTONE, ARNOLD |
| | APPEL, MARTIN |
| | KROGERMEIER, M |
| | OSTRO, P |
| | HRISTON, L P |
| | MCBRIDE, MICHAEL J |
| | SHAUN, T |
| | LONGHURST, STANLEY |
| | REDDINGTON, M |
| | MCKELVY, JOHNSON S |
| | WALLACH, J |
| | LEVY, FRED S |
| | GIRARDI, S |
| | LEVITAN-UR, H |
| | O'NEILL, KEVIN & ROSEMARIE |
| | BELL, TRACY |
| | HILL, E |
| | RUSS, WM & HANNAH |
| | FLIGEL, M |
| | CIOPPA, KATHLEEN |
| | HOGAN, MAUREEN |
| | ZIMMERMAN, NANCY A |
| | ROTHSCHILD, CHARLES H |
| | CILENTO, ANTHONY |
| | KAPLAN, RICHARD |
| | RENZ, ADAM C |
| | MAYEWSKI, H & W |
| | ALBERT, MICHAEL & JOANNE |
| | STAGER, WILLIAM |
| | HERSH, IRA |
| | GIBSON, A |

# FINDINGS

## PALMER AVE

**1995** (cont.)

Cole Information

1299 PRESTON, LAURENCE
MCCARTHY, ROBT J
JOLLY, JOHN
TAYLOR, VIOLET
KLEINMAN, BURT
BARRETT, JOHN J
MACNAUGHTON, L
MICHIELS, WM
BROADHEAD, H C
ROMAGNOLI, DANIEL A
BAKER, ANTHONY S
SERRANO, ANGELA
ZULLO, EUGENE, JR
MOONEY, M J
SWEENEY, JAMES & SUSAN
ARCHER, ROY A
BRADNER, A
GATES, STEVEN
GUALANO, E
MITCHELL, B
EL-ADAWY, ZAKI
KARBSTEIN, C
CAMPBELL, PHILLIP D
REICH, AMY
D'AQUILA, JOHN
AZALINO, E
BUONO, VINCENZO
SHAH, MELISSA
MARKEL, PETER
LIEBLEIN, A
MCCARTHY, SEAN R
DELFAVERO, E
SPAMPINATO, MICHAEL
CHEUNG, JEN
FOOTE, PAUL D
GIRARDI, B
COONEY, S
SHORT, A

## PALMER AVE

**1995** (cont.)

Cole Information

1299 PAYNE, BRIAN M
WHEELER, CARLTON
GIMBEL-SINGER, MARION
SINGER, MARION
PETERS, MICHAEL J, JR
MONGNO, GREGORY
MORELLI, G
HAVILAND, GREGORY
1815 LOMONACO, S, MD
ROSENBLUM, EDWARD S, DDS
MAKMAN, MARIANNE, MD
SEARS, WALTER J
CASE, GEORGE S, JR
MAHER, E M
FINN, ROBERT
MCGOURTY, M A
FRANCIOLI, ATTILIO
LANGENAUER, JEANNE
BLUM, SALLY
CAPRARO, ANTHONY F, IV
JAEGER, J
BRITTON, STEPHEN
DOLAN, THOMAS J
HAERTEL, CHRIS
DARLINGTON, MARK
BRITTON, JAMES A
MATTIACE, LINDA ANNE
CUQUA, CARLTON J
O'KEEFE, KIM
FELDMAN, LAWRENCE
ANTINELLI, STEPHEN J
MONCINI, RAYMOND J
HAAS, KATHLEEN
MERRELL, BETTY M
BRADY, THOMAS
CASERTA, ANTHONY G
ESPOSITER, M
MELLON, PERICLES

# FINDINGS

## PALMER AVE

**1995** (cont.) Cole Information

1815 GARVEY, M
CORETH, E
RIGSBY, H M
DI PASQUALE, LEO & LEIGHANN
EARLE, SADIE
BELLO, PAUL A
HUTCHINGS, B A
FANNING, E F
PEARSON, BARBARA
BEKEMEIER, WILLIAM
LUCAS, M H
FRASSINO, GERARDO, SR
MACINTYRE, DUAL
BRANDON, D
WARREN, E B
GONZALES, OTHILYN
PAGANELLI, L
CASPAR, DAVID
FRANKEL, THOMAS E
DODGE, MARGARET G
DE ROSA, CAROL
MARON, R
MAZIN, S E
ZELIN, STEVEN & JOY
BAUM, ANDREW
BIGAOUETTE, L A
CACCHIONE, DONALD
GAROFALO, GARY
LAVINE, M
MALCOLM, OSCAR F
BREEN, JAMES S
YOUNG, ANNETTE V
ROSENFELD, A
DOONAN, THOMAS
BARTEE, STANLEY
RASOR, RICHARD & KATHLEEN
FISCHER, STEPHEN M
SAFIAN, MURRAY Z, PHD

## PALMER AVE

**1995** (cont.) Cole Information

1815 CAROLAN, E J
FERRIGNO, J
1825 DOYLE, GEO J
FITZSIMONS, PATRICIA
PROFILET, ELAINE
JERMYN, PATRICK
MAYTROTT, THOMAS G
O'DONNELL, HUGH K
MONTANARO, MICHAEL
MUMFORD, JARRETT
KLEIN, DAVID
MC GETRICK, JAMES M
AXELROD, R
KIMMEY, ELWIN C
GARBARINI, M
1833 PATRICIA GARDENS
SHARPE, T
RADOCY, MICHAEL
GRAYSON, ELAINE S
FISCHLE, CLARENCE R
JAFFE, HERBERT
QUINLAN, JACK-FAX
DUNDON, MICHAEL K
GORDON, JOHN
QUINLAN, JACK
MANNIX, MARK
MELLIS, ALIX
BROWN, JAMES
O'CONNELL, JOHN
MAKOUJY, RICK, JR
ALFIERI, PAUL A, III
KOEN, MORIS & KETTY
QUINLAN, BARBARA & JACK
1865 NATL FOOTBALL FOUNDATION & HALL OF FAME
ODANI RESEARCH CO
BAILEY, NAN P
CUCCIA OSTER & HANSBURG
AMERICAN TARTARIC PRODUCTS

# FINDINGS

## PALMER AVE

**1995** (cont.)

Cole Information

| | |
|---|---|
| 1865 | WEXLER, ARTHUR JAY, ARCHT |
| | ROSNER-SIMON ASSOCS INC |
| | STERNSCHUSS, DAVID |
| | BARBERO, MARK A, CLAIM SERVICE |
| | DGM-I CORP |
| | DGM PARTNERS |
| | INDIAN HILL TOWN HOMES |
| | MAW DEVELOPERS CORP |
| | O'TOOLE DENNIS P & ASSOCS INC |
| | WATCH HILL INVESTMENT PARTNERS |
| | E J MICHAELS LTD |
| | KURTZ LINDA S, ACSW |
| | GALLUP BROADCASTING CONSULTANTS |
| | BURTEN, K, MD |
| | MEEKER & ASSOCIATES |
| | ROSNER SIMON ASSOCS INC |
| | ROSNER, LAWRENCE M, INS |
| | THE COLLEGE DIGEST |
| | TEACH |
| | IVY SATELLITE NETWORK |
| | CAPRARO, ANTHONY |
| | A F C PUBLISHING |
| | L & M EQUITY PARTICIPANTS LTD |
| | WELKIS, JERRY |
| | CYPRUS MINERAL CO |
| | EMANUEL LAW OUTLINES INC |
| 1875 | ARTWATCH INTL INC |
| | GEOFFREY WALSH ENTERPRISES INC |
| | V P GROUP |
| | DARPHIN-BEAUTE, SKIN & BODY CARE |
| | AMERICAN FRIENDS OF KASHMIR |
| | BELL TOWER ASSOCS |
| | BIERMAN, STANLEY |
| | CLOCK TOWER ASSOCS |
| | IFO ENTERPRISES LTD |
| | KASHMIR CREWEL INTERNATIONAL |
| | KEA INTERNATIONAL INC |
| | PALMER AVE ASSOCS |

## PALMER AVE

**1995** (cont.)

Cole Information

| | |
|---|---|
| 1875 | WYKAGYL TOWER ASSOCS |
| | WYTHBURN ASSOC LTD |
| | ACTION COMPUTER INC |
| | COMPUTER SIGN CO |
| | OTTENSTEIN, GEORGE, CPA |
| | BRIDGES |
| | FRIED PHILIP, MD |
| | OTTENSTEIN M Z & CO, CPAS |
| | COGENTMANAGEMENT |
| | ISLAND DESTINATIONS |
| | ROMA VIDEO |
| | FIRST IMPRESSION |

## PALMER AVE

**1992**

Cole Information

| | |
|---|---|
| 1299 | RUSS WILLIAM STUDIO, PHOTOGRAPHY |
| | 1299 PALMER AVE INC |
| | CAMPBELL, PHILLIP D |
| | MITCHELL, B |
| | MARKEL, PETER |
| | METZ, A S |
| | CONDON, LAWRENCE M |
| | SPAMPINATO, MICHAEL |
| | REICH, AMY |
| | MOONEY, M J |
| | ZULLO, EUGENE, JR |
| | CONDON, EDWIN J |
| | DIFIORE, WILLIAM |
| | GUALANO, E |
| | BROADHEAD, H C |
| | LEVITAN-UR, H |
| | DEMARCO, ROBERT |
| | BUONO, VINCENZO |
| | COHEN, BERNARD |
| | HAVILAND, GREGORY |

# FINDINGS

## PALMER AVE

**1992** (cont.) Cole Information

1299 LANZA, JOAN
BEHRENS, MARION
SCIAVILLO, M
LONGHURST, STANLEY
PETERS, MICHAEL J, JR
HOGAN, M
PRESTON, LAURENCE
KARBSTEIN, C
ROBUSTELLI, MONA & PETER
AZALINO, JOSEPH
HUNT, DANNER
RUSS, WM & HANNAH
WHEELER, CARLTON
BREAKSTONE, ARNOLD
WALLACH, GARY
PHETHEAN, DAVID & TARA
LEVY, FRED S
GIRARDI, S
STAGER, WILLIAM
WALLACH, J
FOOTE, RICHARD G
HILL, E
FLIGEL, M
DEMONTRAVEL, PETER R
LIEBLEIN, A
BELL, TRACY
CORRADO, JOSEPH
JOLLY, JOHN
COONEY, S
RENZ, ADAM C
ALBERT, MICHAEL & JOANNE
BADNER, VICTOR
KRAFT, FREIDA
BAKER, ANTHONY S
CORCORAN, PATRICK & KAREN
KLEINMAN, BURT
ROMAGNOLI, VINCENT
ZIMMERMAN, LARRY

## PALMER AVE

**1992** (cont.) Cole Information

1299 SHAUN, T
MCCARTHY, ROBT J
GRANFAR, SEPEHR
CILENTO, ANTHONY
DORIAN, D
MACNAUGHTON, L
EL-ADAWY, ZAKI
KAPLAN, RICHARD
DELFAVERO, E
GIBSON, A
OSTRO, P
TAYLOR, VIOLET
MCBRIDE, MICHAEL J
SHORT, A
BARRETT, JOHN J
HRISTON, L P
GIMBEL-SINGER, MARION
SINGER, MARION
MC GRATH, M
BONITO, JOHN D
MICHIELS, WM
MC GEE, JONN
MCCARTHY, SEAN R
MAFFEI, LEONARD
FORTE, A
O'NEILL, KEVIN & ROSEMARIE
FABBRI, F D
ROMAGNOLI, DANIEL A
ROTHSCHILD, CHARLES H
D'AQUILA, JOHN
REDDINGTON, M
AZALINO, E
MONGNO, GREGORY
1815 ROSENBLUM, EDWARD S, DDS
MAKMAN, MARIANNE, MD
LOMONACO, S, MD
MCGOURTY, M A
BELLO, PAUL A

# FINDINGS

## PALMER AVE

**1992** (cont.) Cole Information

1815 PETRILLO, ABBIE
MELLON, PERICLES
CULLEN, WALTER T
LUCAS, M H
NOUVEL, A J
RIGSBY, H M
MERRELL, BETTY M
ZADLOCK, ANTHONY
EARLE, SADIE
EATON, WM V
KAUFMANN, DAVID M
CAPRARO, ANTHONY F, IV
TAGUE, JOHN F, III
MACINTYRE, DUAL
JAEGER, J
FERRIGNO, J
BARRELLA, MICHAEL
HOUTS, D C
FANNING, E F
FISCHER, STEPHEN M
DI PASQUALE, LEO & LEIGHANN
BRADY, THOMAS
SEARS, WALTER J
KLEIN, RICHARD A
SAFIAN, MURRAY Z, PHD
BUSHELL, LYNN
PEARSON, BARBARA
BEKEMEIER, WILLIAM
BRITTON, STEPHEN
HAERTEL, CHRIS
WARREN, E B
WILLETT, C K
REO, S
LAVINE, M
GARVEY, M
DORIAN, J
PAGANELLI, L
RYAN, E F X

## PALMER AVE

**1992** (cont.) Cole Information

1815 HUTCHINGS, B A
BLUM, SALLY
MAHER, E M
LANGENAUER, JEANNE
FELDMAN, LAWRENCE
YOUNG, ANNETTE V
PINTO, THOMAS
MALCOLM, OSCAR F
GUALANO, FRANK
DODGE, MARGARET G
MARON, R
MAZIN, S E
BARTEE, STANLEY
DE ROSA, CAROL
DAMMEYER, KENNETH
CORETH, E
FRANCIOLI, ATTILIO
CACCHIONE, DONALD
DARLINGTON, MARK
CUQUA, CARLTON J
CAROLAN, E J
MATTIACE, LINDA ANNE
LEVINE, RICHARD & JEFF
FRANZ, MARY
HAAS, KATHLEEN
FERRINO, JOHN
CASE, GEORGE S, JR
BIGAOUETTE, L A
CASERTA, ANTHONY G
KOERNER, JONATHAN
ESPOSITER, M
1825 MAYTROTT, THOMAS G
PROFILET, ELAINE
LYNCH, BILL
O'DONNELL, HUGH K
KIMMEY, ELWIN C
MC GETRICK, JAMES M
NATHAN, PAUL & JOYCE

# FINDINGS

## PALMER AVE

**1992** (cont.) Cole Information

| | |
|---|---|
| 1825 | DOYLE, GEO J |
| 1825B | KLEIN, DAVID |
| | WILLIAMS, DONALD, III |
| 1825F | FABBRI, WM |
| 1833 | PATRICIA GARDENS |
| | MANNIX, RICHARD, JR |
| | JOHNSON, KAREN |
| | KOEN, MORIS & KETTY |
| | JAFFE, HERBERT |
| | GRAYSON, J J |
| | VALSANGKAR, SUNITA |
| | ALFIERI, PAUL A, III |
| | DE LORENZO, T M |
| | MURRAY, A |
| | FISCHLE, CLARENCE R |
| | BRECHT, GREGORY |
| | QUINLAN, JACK |
| | FRANK, IRVING |
| | PHILLIPS, ANDREW & KAREN |
| 1865 | ROSNER SIMON ASSOCS INC |
| | D J E COVERAGE CORP |
| | K B C SYSTEMS CORP |
| | NATL FOOTBALL FOUNDATION & HALL OF FAME |
| | AMERICAN TARTARIC PRODUCTS |
| | MEEKER & ASSOCIATES |
| | DJ E COVERAGE CORP |
| | D J E LIFE ASSOCS |
| | ODANI RESEARCH CO |
| | GALLUP BROADCASTING CONSULTANTS |
| | THE COLLEGE DIGEST |
| | TEACH |
| | IVY SATELLITE NETWORK |
| | CAPRARO, ANTHONY |
| | A F C PUBLISHING |
| | WELKIS, JERRY |
| | QUARTET TRAVEL INC |
| | CREDIT PARTNERS INC |
| | E J MICHAELS LTD |

## PALMER AVE

**1992** (cont.) Cole Information

| | |
|---|---|
| 1865 | CYPRUS MINERAL CO |
| | FAST TRACK COMMUNICATIONS INC |
| | O'TOOLE DENNIS P & ASSOCS INC |
| | CUCCIA OSTER & HANSBURG |
| | KORBEN INTERNATIONAL CORP |
| | EMANUEL LAW OUTLINES INC |
| | DOCUFIND |
| | ROSNER-SIMON ASSOCS INC |
| | STERNSCHUSS, DAVID |
| | K B C SYSTEMS CORP, INSURANCE |
| | KAGAN, A MICHAEL, INS |
| | ROSNER, LAWRENCE M, INS |
| 1875 | MARIECLAUDE INC, SKIN & BODY CARE |
| | STEIN, ALAN J, MD |
| | CHANSON D'AMOUR INC, FASHION |
| | FASHION SOURCE THE |
| | OLD WORLD ANTIQUES |
| | OTTENSTEIN, GEORGE, CPA |
| | OTTENSTEIN M Z & CO, CPAS |
| | ACTION COMPUTER INC |
| | COMPUTER SIGN CO |
| | GEOFFREY WALSH ENTERPRISES INC |
| | V P GROUP |
| | WALSH ORGANIZATION INC |
| | FOTOMAT CORPORATION-1 HR MINILAB STORE LOCATIONS |
| | JUST FOUND LINGERIE INC |
| | AMERICAN FRIENDS OF KASHMIR |
| | BELL TOWER ASSOCS |
| | BIERMAN, STANLEY |
| | CLOCK TOWER ASSOCS |
| | IFO ENTERPRISES LTD |
| | KASHMIR CREWEL INTERNATIONAL |
| | KEA INTERNATIONAL INC |
| | PALMER AVE ASSOCS |
| | WYKAGYL TOWER ASSOCS |
| | WYTHBURN ASSOC LTD |
| | WING, MARIA, MD |

# FINDINGS

## PALMER AVE

**1987** Cole Publications

| | | | | |
|---|---|---|---|---|
| | **1299 ★ Larchmnt Palmr Hse** | | | |
| 1299 | L MacNaughton | .68 | | 834-5854 |
| | Leonard Maffei | .68 | | 834-1417 |
| | Peter Markel | .85 | | 834-9317 |
| | Michael J McBride | .80 | | 834-4505 |
| | Robert J McCarthy | .78 | | 834-8784 |
| | Sean R McCarthy | .80 | | 834-8431 |
| | A McGovern | .73 | | 834-7158 |
| | L J McGrath | .70 | | 834-6854 |
| | M Mesmer | | ¤ | 834-0766 |
| | D Messemer | | - | 834-1288 |
| | A S Metz | .77 | | 834-9329 |
| | William Michiels | .78 | | 834-7047 |
| | Philip Miller | .70 | | 834-7965 |
| | B Mitchell | | ¤ | 834-7791 |
| | H L Morgenroth | .67 | | 834-7176 |
| | Elyse Moroz | | ¤ | 834-9242 |
| | Albert Ohebshalom | .81 | | 834-8721 |
| | G W Olson | .72 | | 834-2924 |
| | H G OReilly | .74 | | 834-8219 |
| | P Ostro | .77 | | 834-4217 |
| | Michl J Peters Jr | .75 | | 834-6785 |
| | Hafkaz Petrossian | .73 | | 834-5811 |
| | E V Rader | .72 | | 834-4473 |
| | M Reddington | | ¤ | 833-0941 |
| | Amy Reich | .84 | | 834-0960 |
| | Kevin Reilly | .85 | | 834-6289 |
| | Adam C Renz | .85 | | 833-0698 |
| | S Rothberg-Renz | .78 | | 834-9419 |
| | Chas H Rothschild | | ¤ | 834-1852 |
| | William Russ | .85 | | 834-1017 |
| | G Schwarz | .84 | | 834-4628 |
| | Rafeef Seirafi | | ¤ | 834-5611 |
| | Julie Sherman | | ¤ | 834-2379 |
| | A Short | .73 | | 834-4425 |
| | I Slomowitz | .80 | | 834-6840 |
| | Michael Spampinato | .76 | | 834-9257 |
| | D Stamper | .83 | | 833-0184 |
| | I M Storms | .76 | | 834-6471 |
| | M M Tuck | .77 | | 834-8563 |
| | **★ 1299 Palmer Ave** | **.81** | | **834-1218** |
| | Jimmy Wang | | ¤ | 834-9449 |
| | Richard Zalmstra | .79 | | 834-0839 |
| | **1815 ★ The Colony Apts** | | | |
| 1825 | H A Collins | .69 | | 834-3978 |

## PALMER AVE

**1987** (cont.) Cole Publications

| | | | | |
|---|---|---|---|---|
| | George J Doyle | .70 | | 834-9269 |
| | M L Ferris | .85 | | 834-8507 |
| | D Hines | .84 | | 834-2437 |
| | Thomas Kelly | .85 | | 833-0457 |
| | Edward Kimmey | .85 | | 834-8627 |
| | Thomas Layden | | ¤ | 833-0317 |
| | **★ Dr Chas Margulies** | | - | **834-2941** |
| | J McGeary | .77 | | 834-8506 |
| | Akio Nakamura | .85 | | 833-0511 |
| | R Sacino | .75 | | 834-3192 |
| **1825** | **★ Dr Eric Spellman** | **.78** | | **834-2941** |
| | **★ Dr Sidney H Stone** | | | **834-2941** |
| | B David Klein | .80 | | 834-1693 |
| | B D Williams III | .63 | | 834-1236 |
| | C William Fabbri | .68 | | 834-8273 |
| 1833 | Jiwat Advani | .85 | | 833-0045 |
| | Paul A Alfieri III | | ¤ | 833-0038 |
| | T M Delorenzo | .85 | | 834-7405 |
| | Daria Ferrentino | .85 | | 834-0527 |
| | Clarence R Fischle | .77 | | 834-0706 |
| | Michele Forenza | .67 | | 834-5416 |
| | Irving Frank | .70 | | 834-2991 |
| | J J Grayson | .79 | | 834-2368 |
| | Herbert Jaffe | .70 | | 834-0998 |
| | Moris Koen | .79 | | 834-7340 |
| | Donna M Latoronica | .85 | | 834-8670 |
| | A Murray | .75 | | 834-3206 |
| | A M Nicoletti | .68 | | 834-7067 |
| | Mary E ODonnell | .79 | | 834-4023 |
| | **★ Patricia Gardens** | **.75** | | **834-5888** |
| | Martin Schwartz | .78 | | 833-0106 |
| | Martin Schwartz | .78 | | 834-5014 |
| **1865** | **★ AFC Publishing** | | ¤ | **833-0900** |

# FINDINGS

## PALMER AVE

**1987** (cont.) Cole Publications

| | | | | |
|---|---|---|---|---|
| | ★ Gerald E Bodell PC | . . | 85 | 834-1808 |
| | ★ Bodell&Gross Aty | . . . | 85 | 834-1808 |
| | ★ DJE Coverage Corp | . . | ¤ | 833-0111 |
| | ★ DJE Life Assoc | . . . . | - | 833-0111 |
| | ★ Emanuel Data Systm | . | - | 834-7706 |
| | ★ Emanuel Law Outlne | . | - | 834-7735 |
| | ★ Greenfield Partner | . . | ¤ | 834-3338 |
| | ★ Ivy Satellite Ntwk | . . | ¤ | 833-0900 |
| | ★ KBC Systems Corp | . . | - | 833-0111 |
| | ★ A M Kagan Ins | . . . . | - | 833-0111 |
| | ★ Korben Intrntl CRP | . . | - | 834-1114 |
| | ★ Learning Channels | . . | ¤ | 833-0911 |
| | ★ R H Lovell Aty | . . . . | - | 834-7735 |
| | ★ Madisons Inc | . . . . . | ¤ | 834-9300 |
| | ★ Madisons Inc | . . . . . | ¤ | 834-9338 |
| | ★ Natl Football | . . . . . | ¤ | 834-0474 |
| | ★ E Rosenfeld Ionc | . . . | - | 834-5722 |
| | ★ Teach | . . . . . | - | 833-0900 |
| | ★ The College Digest | . . | ¤ | 833-0900 |
| | ★ The Learning Chnnl | . . | ¤ | 833-0911 |

| | | | | |
|---|---|---|---|---|
| 1875 | ★ Amer Friends Kshmr | . | 84 | 834-0400 |
| | ★ Bell Tower Assocs | . . | ¤ | 834-0400 |
| | ★ Stanley Bierman | . . . | 84 | 834-0400 |
| | ★ Cachet Sportswear | . . | 80 | 834-5550 |
| | ★ Clock Tower Assoc | . . | 83 | 834-0400 |
| | ★ Comlog Inc | . . . . . | 84 | 834-5544 |
| | ★ Computer Sign Str | . . | ¤ | 834-3000 |
| | ★ Fotomat Corp | . . . . . | 78 | 834-6923 |
| | ★ IFO Entrprs Ltd | . . . . | 82 | 834-0400 |
| | ★ Kashmir Crewel Int | . . | 76 | 834-0400 |
| | ★ Kea Intl Inc | . . . . . | 76 | 834-0400 |
| | ★ Marieclaude Inc | . . . . | 83 | 834-4800 |
| | ★ Old Wrld Antiques | . . | 84 | 833-0705 |
| | ★ Geo Ottenstein CPA | . . | 84 | 834-1081 |
| | ★ M Z Ottenstein&Co | . . | 84 | 834-1081 |
| | ★ Palmer Ave Assoc | . . | 83 | 834-0400 |
| | ★ Dr Alan J Stein | . . . | 84 | 834-9360 |
| | ★ Wykagyl Tower Assc | . | ¤ | 834-0400 |
| | ★ Wythburn Assoc | . . . | 85 | 834-0400 |

## PALMER AVE

**1983** New York Telephone

| | |
|---|---|
| 1875 | THREE SIGMA RESEARCH CENTER INC |

## PALMER AVE

**1981** Cole Publications

| | |
|---|---|
| 1299 | ★ Larchmnt Palmr Hse . . . . |

# FINDINGS

## PALMER AVE

**1981** (cont.) Cole Publications

| | | |
|---|---|---|
| Mrs M A Adelberg .....78 | 834-8184 |
| R Aron .....76 | 834-0063 |
| Joseph Azalino .....72 | 834-0977 |
| Michael Azalino .....72 | 834-3216 |
| Robert Balestneri .....¤ | 834-9047 |
| Renan Ballas .....¤ | 834-7234 |
| Joseph S Banks ..... | 834-8846 |
| William Bartoli .....77 | 834-9544 |
| W Baum .....70 | 834-9186 |
| Marion Behrens .....¤ | 834-3953 |
| M Berkowitz .....76 | 834-9126 |
| Eugene S Boyd .....72 | 834-7606 |
| Judith A Brendolan .....78 | 834-0383 |
| Vincenzo Buono .....75 | 834-8891 |
| Bernard Cohen ..... | 834-8760 |
| John H Collins Jr .....69 | 834-5317 |
| Edwin J Condon .....77 | 834-0726 |
| John D Coming .....79 | 834-0013 |
| E Delfavero .....71 | 834-8692 |
| P R Demontravel .....73 | 834-5096 |
| S Demontravel .....77 | 834-4325 |
| J Digaetano .....79 | 834-0659 |
| Robert M Duncan .....78 | 834-6729 |
| Larry Edlavitch .....¤ | 834-5089 |
| Zaki M El-Adawy .....78 | 834-3679 |
| F D Fabbri .....73 | 834-5932 |
| M D Flagg .....76 | 834-0740 |
| C Frede .....78 | 834-5243 |
| A Gibson .....72 | 834-8663 |
| H Greenberg .....68 | 834-6577 |
| James Greenwood .....78 | 834-4024 |
| Daniel L Herbst .....77 | 834-0693 |
| L P Hriston .....68 | 834-5730 |
| D Hufnagel .....73 | 834-7764 |
| Danner Hunt .....67 | 834-0869 |
| E Jerome .....¤ | 834-1483 |
| Frank Keefer .....72 | 834-8225 |
| Jack Keleshian .....76 | 834-0597 |
| Henry Kraus .....71 | 834-1654 |
| Isaac Lamon .....78 | 834-0297 |
| ★Larchmnt Palmr Hse .... | 834-1218 |
| T C Larywon .....77 | 834-5297 |
| John Leddy .....77 | 834-9339 |
| J Lesourd .....78 | 834-7274 |
| Fred S Levy .....66 | 834-3783 |
| A Lieblein .....76 | 834-3266 |
| Stanley Longhurst .....68 | 834-5288 |
| L MacNaughton .....68 | 834-5854 |
| Leonard Maffei .....68 | 834-1417 |
| Arnold Markel .....73 | 834-0496 |
| John J McBride .....66 | 834-6049 |
| Michael J McBride .....¤ | 834-4505 |
| Robert J McCarthy .....78 | 834-8784 |
| Sean R McCarthy .....- | 834-8431 |
| A McGovern .....73 | 834-7158 |

## PALMER AVE

**1981** (cont.) Cole Publications

| | | |
|---|---|---|
| 1815 ★The Colony Apts ..... | | |
| Stefan Bauer .....75 | 834-7988 |
| Robert W Baum .....70 | 834-2458 |
| Mrs Margt H Beeley .... | 834-0594 |
| Leslie K Bennett ..... | 834-5705 |
| Hulda Bewick .....63 | 834-5934 |
| George O Boelker ..... | 834-1520 |
| George S Case Jr .....69 | 834-4216 |
| Gabriel Casiano .....75 | 834-5053 |
| H M Coffey .....67 | 834-4954 |

| | | |
|---|---|---|
| 1815 J King .....- | 834-4882 |
| D L Kopins ..... | 834-5468 |
| Gerard W Kunkel .....77 | 834-4278 |
| J Levin .....77 | 834-8089 |
| M H Lucas .....74 | 834-4618 |
| Charles MacDonald ..... | 834-4570 |
| Charles Mallinson .....78 | 834-0764 |
| Walter G Marple Jr .....¤ | 834-8862 |

| | | |
|---|---|---|
| 1825 Mark S Abrams .....76 | 834-4316 |
| M Calvano .....79 | 834-2642 |
| H A Collins .....69 | 834-3978 |
| George J Doyle .....70 | 834-9269 |
| Louis Marder .....¤ | 834-0975 |
| J McGeary .....77 | 834-8506 |
| D Mojica .....¤ | 834-2437 |
| S Rosenthal .....¤ | 834-2835 |
| R Sacino .....75 | 834-3192 |
| ★Dr Eric Spellman ..... | 834-2941 |
| ★Dr Sidney H Stone .... | 834-2941 |
| A Mead Weiss .....¤ | 834-2297 |
| B David Klein .....- | 834-1693 |
| B D Williams III ..... | 834-1236 |
| C William Fabbri .....68 | 834-8273 |

| | | |
|---|---|---|
| 1833 L Cannata .....78 | 834-4018 |
| Arth L Coleman III .....- | 834-8710 |
| Michele Forenza .....67 | 834-5416 |
| Irving Frank .....70 | 834-2991 |
| J J Grayson .....79 | 834-2368 |
| M T Hannigan .....79 | 834-2365 |
| Marel Harayda .....77 | 834-2914 |

| | | |
|---|---|---|
| 1875 ★The Arcade ..... | 834-0400 |
| ★Cachet Sportswear .....¤ | 834-5550 |
| ★Capitol Coin&Stamp .... | 834-4696 |
| ★Capitol Coin&Stmp ..... | 834-4696 |
| ★Fotomat Corp ..... | 834-6923 |
| ★Ralph S Herson ..... | 834-0733 |
| ★Inter-Fibres Inc ..... | 834-0733 |
| ★Kashmir Crewel Int .... | 834-0400 |
| ★Kea Intl Inc ..... | 834-0400 |

## PALMER AVE

**1977** Cole Publications

| | | |
|---|---|---|
| 1299 Elza Maria Alano ¤ | 834-8373 |

# FINDINGS

## PALMER AVE

**1977** (cont.) Cole Publications

| | | | | |
|---|---|---|---|---|
| | | Fredk L Allen Jr | 3 | 834-7756 |
| | | R Aron | ¤ | 834-0063 |
| | | Joseph Azalino | 2 | 834-0977 |
| | | Michael Azalino | 2 | 834-3216 |
| | | Joseph S Banks | | 834-8846 |
| | | W Baum | 0 | 834-9186 |
| | | John H Beerman | | 834-8836 |
| | | Marion Behrens | 7 | 834-0703 |
| | | M Berkowitz | ¤ | 834-9126 |
| | | Mrs D E Botter Jr | | 834-7141 |
| | | Eugene S Boyd | 2 | 834-7606 |
| | | [illegible] | [illegible] | [illegible] |
| | 1299 | Herman Coplan | 1 | 834-4927 |
| | | E Delfavero | 1 | 834-8692 |
| | | P R Demontravel | 3 | 834-5096 |
| | | Zaki Eladawy | ¤ | 834-4937 |
| | | F D Fabbri | 3 | 834-5932 |
| | | M D Flagg | ¤ | 834-0740 |
| | | R B Frascella | 8 | 834-1020 |
| | | Joseph H Garst | 0 | 834-0457 |
| | | A Gibson | 2 | 834-8663 |
| | | H J Goldschmidt | 9 | 834-0982 |
| | | C B Greenbaum | 1 | 834-6960 |
| | | H Greenberg | 8 | 834-6577 |
| | | [illegible] | [illegible] | [illegible] |
| | 1815 | F D Allen | | TE4-4855 |
| | | William Bartoli | 5 | 834-9544 |
| | | Stefan Bauer | 5 | 834-7988 |
| | | Robert W Baum | 0 | 834-2458 |
| | | William Baumert | 7 | 834-9477 |
| | | Mrs Margt H Beeley | | TE4-0594 |
| | | Leslie K Bennett | | TE4-5705 |
| | | Hulda Bewick | | TE4-5934 |
| | | George O Boelker | | TE4-1520 |
| | | A Boysen | | TE4-5649 |
| | | W J Campbell | | TE4-3897 |
| | | George S Case Jr | 9 | 834-4216 |
| | | Gabriel Casiano | 5 | 834-5053 |
| | | Mrs Joyce Clarke | | 834-4705 |
| | | H M Coffey | 7 | 834-4954 |
| | | [illegible] | [illegible] | [illegible] |
| **38** | 1815 | Frank P Scott | – | 834-8089 |
| 27 | | Mrs Loretta Scott | | 834-5419 |
| 92 | | Walter J Sears | 8 | 834-0564 |
| 96 | | H B Sliger | | 834-3538 |
| | | [illegible] | [illegible] | [illegible] |

## PALMER AVE

**1977** (cont.) Cole Publications

| | | | | |
|---|---|---|---|---|
| 63 | 1825 | Mark S Abrams | ¤ | 834-4316 |
| 82 | | R Brucculeri | ¤ | 834-3881 |
| 60 | | H A Collins | 9 | 834-3978 |
| 77 | | George J Doyle | 0 | 834-9269 |
| 30 | | F M Lewis | 5 | 834-7238 |
| 64 | | Andre Mallander | ¤ | 834-8115 |
| 69 | | J Mannix | ¤ | 834-4359 |
| 25 | | Oliver Martin Jr | 5 | 834-0168 |
| 97 | | ★**Patricia Grdn Apts** | | **737-0688** |
| 77 | | R Sacino | 5 | 834-3192 |
| 54 | | John D Waterbury | 2 | 834-2622 |
| 36 | | B Edward L Jenny | 4 | 834-4716 |
| **18** | | B D Williams III | | TE4-1236 |
| 83 | | C William Fabbri | 8 | TE4-8273 |
| 66 | | **C Dr Sidney H Stone** | | **TE4-2941** |
| | | [illegible] | [illegible] | [illegible] |
| 85 | 1833 | Anthony Caruso | 3 | 834-3119 |
| 96 | | P Farrell | 3 | 834-3781 |
| 76 | | Michele Forenza | 7 | 834-5416 |
| 93 | | Irving Frank | 0 | TE4-2991 |
| 74 | | Mrs M Fulleylove | | 834-5086 |
| 73 | | Andrew Hajducek | ¤ | 834-4016 |
| 45 | | B L Hower | 4 | 834-7367 |
| 70 | | Herbert Jaffe | 0 | 834-0998 |
| 17 | | Carol Johnson | – | 834-1799 |
| 65 | | William L McDevitt | ¤ | 834-0654 |
| 14 | | A Murray | 5 | 834-3206 |
| 62 | | Ann M Nicoletti | 8 | 834-7067 |
| 29 | | ★**Patricia Gardens** | | **834-5888** |
| 25 | | J D Renson | 8 | 834-3189 |
| 57 | | I Schneider | 1 | 834-7841 |
| 50 | | Neil Vetrano | 0 | 834-9567 |
| 71 | | John Wagner | ¤ | 834-5273 |
| | | [illegible] | [illegible] | [illegible] |
| 96 | **1861** | ★**A&P Food Stores** | ¤ | **834-9887** |
| 07 | | ★**Larchmont Ctr Clnr** | | **TE4-0156** |

## PALMER AVE

**1972** Cole Publications

| | | | | |
|---|---|---|---|---|
| 1298 | [illegible] | [illegible] | [illegible] | [illegible] |
| 1299 | | ROBERT C AHLERS | 0 | 8349286 |
| | | [illegible] | [illegible] | [illegible] |

# FINDINGS

## PALMER AVE

**1972** (cont.) Cole Publications

1299
SELIM AKYUZ ¤8340024
JOSEPH S BANKS 8348846
W BAUM 0 8349186
JOHN H BEERMAN 6 8348836
MARION BEHRENS 7 8340703
MRS D E BOTTER JR 8347141
JOHN S BROWN 8342040
JOSEPH CARDELLA 7 8346947
MRS HELEN CHALMERS-8349056
GEORGE CHOFFLETTI ¤8342892
ROGER W CLAVEY 7 8345634
BERNARD COHEN TE48760
LAWRENCE S COHEN 8347317
JOHN H COLLINS JR9 8345317
R P CONLEY 6 8345331
KEVIN P CONNOLLY 0 8343057
HERMAN COPLAN ¤8344927
E DELFAVERO ¤8348692
SAM EISENSTARK -8342099
WALLACE FERRIER 7 8343248
MRS PALUEL J FLAGG-8340740
R B FRASCELLA 8 8341020
MRS MARY H FREMD 6 8347409
JOSEPH H GARST 0 8340457
HOWARD J GILB 6 8341968
G M GIRARDI 0 8349477
JOHN B GJERULDSEN6 8343227
H J GOLDSCHMIDT 9 8340982
PATRICIA GOMEZ 0 8348223
GEORGE W GOODLOE 9 8342640
C B GREENBAUM ¤8346960
H GREENBERG 8 8346577
MRS C B HARVEY 0 TE46925
JAMES E HEAP JR 9 8342243
Y HIKITA 0 8347977
ELLA HOWARD 6 8343227
L P HRISTON 8 8345730
DANNER HUNT 7 8340869
KENNETH JENSEN 0 8349195
JOHN F KANE JR TE47689
THOMAS KIRCHOFF 7 8346003
HENRY KRAUS -8341654
MRS GENIA KWARTIN6 8340736
*LARCHMONT PALMER 8346264
J LAWLOR JR TE45437
A LEGGIERO ¤8340052
FRED S LEVY 6 8343783
PAUL M LOGUERICIO ¤8347660
STANLEY LONGHURST8 8345288
L MACNAUGHTON 8 8345854
LEONARD MAFFEI 8 8341417
HERBERT MARESCH 6 8348039
JOHN MARSH 0 8343081
PATRICIA MCALROY ¤8347756
JOHN J MCBRIDE 6 8346049
MRS J E MCDONNELL0 8349152
L J MCGRATH 0 8346854
CAROL MICELI ¤8342998
PHILIP MILLER 0 8347965
HERBERT MORGENROTH 7 8347176
HAROLD L NELSON 6 8344533
E H NORBOM 9 8342860
HELEN G OREILLY 6 8348219
COLE H PILCHER 8 8346193
LAURENCE PRESTON ¤8346324
FRED REINHART 9 8344313
MRS GERT ROSENFELD 8341545
E SAKURAI 0 8349489
MRS L M SANDERS 6 8344920
W V SCHLEICHER 8347114

## PALMER AVE

**1972** (cont.) Cole Publications

1815 *COLONY APTS
MRS E W BARD TE44009
F D ALLEN TE44855
E W BARD TE44009
ROBERT W BAUM 0 8342458
MRS H W BEARMAN 8 TE41687
MRS MARG H BEELEY TE40594
LESLIE K BENNETT TE45705
HULDA BEWICK 3 TE45934
GEORGE O BOELKER TE41520
CHARLES S BOULTON -8346338
A BOYSEN TE45649
MRS E F BURNS TE44281
LOUIS R CALDERAIO3 TE47697
W J CAMPBELL TE43897
THDR CANNAVARO 8342126
GEORGE S CASE JR 9 8344216
MRS JOYCE CLARKE TE43132
H M COFFEY 7 8344954
*THE COLONY APTS 8342222
MRS JOHN F CONDON7 8347633
CARLTON J CUQUA 8347488
MRS ROSS L DAGGETT 0 8348165
MRS G T DECATUR 8 TE46178
HENRY C DOBLER TE43639
WILLIAM V EATON 0 8346457
*E REHNBORG CSMTICS TE45934
F ELMIGER SR TE46442
MRS JOHN S ENGLISH TE43358
E F FANNING 0 TE46640
*J FERRIGNO PAINTR TE43658
FRED GAERTNER JR TE40853
RICHARD F HANSER TE42196
RUSSELL E HEBBARD8 TE45388
DOROTHY HOUTS 7 8346495
THOMAS B HOWELL 7 TE43603
RITA A JONES -8341374
H J KENNEDY 0 8347776
T KOLLER 7 8341513
D L KOPINS 8345468
*LARCH MEDICAL LAB TE42871
CHARLES MACDONALD TE44570
E MANDRACCHIA ¤8346719
JEAN MARDER 6 8344321
MRS C E MARTENS ¤8340805
A L MCCARTHY RN 5 TE47268
MRS K W MCCONKY 8348178
MRS J A MCEVOY 8 8346603
M A MCGOURTY TE47352
*DR HUGH MCHUGH TE43800

1815 P MELLON 7 8341639

# FINDINGS

## PALMER AVE

**1972** (cont.) Cole Publications



*DR SIDNEY MELNICK 8340402
BETTY M MERRELL 8 8345989
EDMOND R MOREY 8344449
REV ARTHUR B MOSSO 8342012
FRANK T MOSS 0 8344119
D C MULLER TE44727
EDWARD A MURPHY 5 8341188
LESLIE M W NEVILLE 5 8346341
K J NIXON TE42531
JOSEPH F NOONAN 0 8347988
*NUTRLITE FD SUPLMT TE45934
RICHARD OBRIEN 0 8349419
GERALD S PRATT 5 TE47306
JOHN F RIGSBY TE45644
DR MURRAY Z SAFIAN 0 8340820
MRS LORETTA SCOTT 5 8345419
WALTER J SEARS 8 8340564
DONALD P SERTON TE43859
ELMA SERTON TE48148
MIRIAM B SHAUER TE46071
P SIMONETTI 8 8342459
BETSY SKINNER 9 8343597
H B SLIGER 8343538
MRS A W D SMITH TE40430
CHARLES SMITH 8346689
EMILY C STRAWN 3 TE42576
MRS E S TEMPLETON 6 8344685
MRS DANA TURCK TE41094
*FREDK W TURCK LAB TE42871
*TURCKS LAB TE42871
JAMES W WALKUP 0 8343597
PETER L WALSH TE46436
PETER F WARREN JR 0 8341277



1833 W CHESTER ¤8344425
FRANK CRAI TE41174
MICHAEL FERGUSON ¤8342819
MICHELE FORENZA 7 8345416
IRVING FRANK 0 TE42991
MRS M FULLEYLOVE 6 8345086
DONALD A HUPPERT 0 8347758
HERBERT JAFFE 0 8340998
TED KOEPPER 7 8340812
RONALD MUHLFELDER 0 8347895
ANN M NICOLETTI 8 8347067
J D RENSON 8 8343189
EUGENE RIVIEZZO 7 8344715
I SCHNEIDER ¤8347841
C F SIMONSEN 6 8345256
NEIL VETRANO 0 8349567
K WARREN 8343019
AY H DAVIS 9 8344211
ALEWIS LANDES TE43891
BMRS HARRY C HENN 9 8344652
BNEVILLE C STOPFORD 6 8346335
CPEDRO ROSENBACH 8 8344665

## PALMER AVE

**1967** New York Telephone Co



1299 Beerman John H 834-8836
1299 Behrens Marion 834-0703
1299 Berry Stephen B TE 4-4975
1299 Biven L R 834-6464
1299 Bladwin Marguerite 834-1889
1299 Blumberg Leonard 834-3583
1299 Botter David E Jr Mrs 834-7141
1299 Cardella Jos 834-6947
1299 Carroll G 834-8583
1299 Clark H Ward 834-8772
1299 Clavey Roger W 834-5634
1299 Clemens Frank J Jr 834-8258
1299 Close Geo Mrs 834-5209
1299 Cohen Bernard TE 4-8760
1299 Colmes Benj S 834-3770
1299 Conley Ruth P Mrs 834-5331
1299 Crosby Wm F Mrs TE 4-8969
1299 Dobbins L C 834-0115
1299 Donnelly Fredk 834-5506
1299 Durst Rudolph C 834-8216
1299 Eastwood H R Mrs 834-2308
1299 Ferrier Wallace 834-3248
1299 Fremd Mary H Mrs 834-7409
1299 Gibson Timothy 834-8360
1299 Gilb Howard J 834-1968
1299 Gjeruldsen John B 834-3227
1299 Grafton Frank A 834-0475
1299 Graham Jas 834-5311
1299 Green Cora A Mrs TE 4-8608
1299 Hand Joel 834-4036
1299 Harvey Wm J TE 4-6925
1299 Hogan John J TE 4-8037
1299 Howard Ella 834-3227



1299 Iverson Raymond F
1299 Kane John F Jr TE 4-7689
1299 Kane Louis 834-3967



1299 Keating Mary Josephine 834-7430
1299 Kirchoff Thos 834-6003
1299 Kojima K 834-3267
1299 Koster Adele 834-8196
1299 Kwartin Genia Mrs 834-0736
1299 Landes B P 834-4438
1299 Larchmont Palmer Hse 834-6264
1299 Lawlor Jeremiah Jr TE 4-5437
1299 Lee Isidore TE 4-8666
1299 Levy Fred S 834-3783
1299 Liguori Salvatore C 834-0855
1299 Lipton Beatrice 834-4251
1299 Loomis LeRoy 834-8615
1299 Lucadamo John J 834-8054
1299 Lynch Roger M 834-3196
1299 Mancini Alfred 834-4375
1299 Mancuso Mildred

## PALMER AVE

**1967** (cont.) New York Telephone Co

1299 Mancuso Mildred ----------834-4375
1299 Mancuso Mildred ----------834-7025
1299 Maresch Herbert ----------834-8039
1299 Mascia Mary Mrs ----------834-4470
1299 McBride John J ----------834-6049
1299 McCann Margaret E Mrs ----------834-8360
1299 Morgenroth Herbert L ----------834-7176
1299 Nelson Harold L ----------834-4533
1299 Nesbitt Warren R ----------834-4145
1299 Ohbayashi Masaya ----------834-4597
1299 Okamoto Shigekazu ----------834-2202
1299 O'Reilly Helen G ----------834-8219
1299 Ostberg Geo W ---------- TE 4-7622
1299 Patton Geo F ----------834-5320
1299 Ronningen K ----------834-3597
1299 Rosenfeld Gertrud Mrs ----------834-1545
1299 Sanders L M Mrs ----------834-4920
1299 Schilero Anthony Jr ----------834-1069
1299 Schleicher Walter V ----------TE 4-7114
1299 Schulman Leonard ----------834-6466
1299 Sheehy Robert M ----------834-6729
1299 Silverman Lena F ----------834-0692
1299 Sonnek Delores ----------834-6240
1299 Staelin Richd A ----------TE 4-0982
1299 Stine Florence H ----------834-3980
1299 Sutherland G P ----------834-8252
1299 Tuck M M ----------834-8563
1299 Tulloch John R ----------834-0831
1299 Walden Robt L ----------834-6265
1299 Wasserman Regina Mrs ----------834-2903
1299 Webster V H Mrs ----------834-1949
1299 Weinstein Ruth Mrs ----------834-6531
1299 Weiss Walter ----------TE 4-5163
1299 Weschler Wm A ----------834-5746
1299 Wheeler John T ----------834-3294
1299 Wheeler Timothy J ----------834-3657
1299 Wiehe Virginia B Mrs ----------834-1735
1299 Wilson Geo M ----------834-6731
1299 Wilson Marie Mrs ----------834-6393
1299 Winkel John A ----------834-8065
1299 Young Stephen W ----------834-5859
1299 Zulch John Sr ----------TE 4-6141
1806 McGuire Wm F ----------834-5707

1815 COLONY APTS
1815 Allen F D ----------TE 4-4855
1815 Bard E W Mrs ----------TEnysn 4-4009
1815 Barry Andrew F ----------834-5031
1815 Baum Robt W ----------b-TE 4-7307
1815 Bearman H W Mrs ----------TEnysn 4-1687
1815 Beeley Margaret H Mrs----TEnysn 4-0594
1815 Bennett Leslie K ----------TEnysn 4-5705
1815 Bewick Hulda ----------TEnysn 4-5934
1815 Boelker Geo O ----------TEnysn 4-1520
1815 Boysen A ----------TE 4-5649
1815 Burns E F Mrs ----------TEnysn 4-4281
1815 Calderaio Louis R ----------TEnysn 4-7697

## PALMER AVE

**1967** (cont.) New York Telephone Co

1815 Burns E F Mrs ----------TEnysn 4-4281
1815 Calderaio Louis R ----------TEnysn 4-7697
1815 Campbell W J ----------TEnysn 4-3897
1815 Cannavaro Theo ----------TEnysn 4-2126
1815 Carnochan John F ----------834-8306
1815 Clarke Joyce Mrs ----------TEnysn 4-3132
1815 Coffey H M ----------834-4954
1815 Colony Apts The ----------834-2222
1815 Condon John F Mrs ----------TE 4-7633
1815 Cuqua Carlton J ----------834-7488
1815 Curtiss Mary E ----------TEnysn 4-0120
1815 DeCatur Gerald T Mrs----TEnysn 4-6178
1815 Dobler Henry C ----------TEnysn 4-3639
1815 Edith Rehnborg Cosmetics
Distribtr ---------- TEnysn 4-5934
1815 Elmiger Fredk J Sr ----------TEnysn 4-6442
1815 Emerson Ruth ----------834-1542
1815 English John S Mrs ----------TEnysn 4-3358
1815 Fanning Edw F Mrs ----------TE 4-6640
1815 Ferrigno Jos ----------paintr-TEnysn 4-3658
1815 Foster Arthur C ----------TEnysn 4-2305
1815 Gaertner Fred Jr ----------TEnysn 4-0853
1815 Goerner Erich A ----------834-7629
1815 Graff Anna S ----------TEnysn 4-1203
1815 Hanser Richd F ----------TEnysn 4-2196
1815 Hebbard Russell E ----------TEnysn 4-5368
1815 Hoehn Walter ----------834-6508
1815 Houts Dorothy C ----------834-6495
1815 Howell John J Mrs ----TEnysn 4-1666
1815 Howell Thos B ----------TE 4-3603
1815 Howell Thos B ----------artst 834-3608
1815 Koller T ----------834-1513
1815 Kopins D L ----------834-5468
1815 Larchmont Medical Lab ----TEnysn 4-2871
1815 Macdonald Chas L ----------TEnysn 4-4570
1815 Marder Jean ----------834-4321
1815 Marx J H ----------TEnysn 4-1863
1815 Mawrenko Anna ----------834-8632
1815 McCarthy Agnes L ----RN-TEnysn 4-7268
1815 McConky Kenneth W Mrs ----------834-8178
1815 McGourty M A ----------TE 4-7352
1815 McHugh Hugh ----MD ofc-TEnysn 4-3600
1815 McLean Donald ----------834-3646
1815 Mellon Pericles ----------834-1639
1815 Morey Edmond R ----------834-4449
1815 Muller D C ----------TEnysn 4-4727
1815 Murphy Edw A ----------834-1188
1815 Neville Leslie M W ----------834-6341
1815 Newnam Gaither T ----------834-8205
1815 Nixon K J ----------TEnysn 4-2531
1815 Nutrilite Food Supplement
Distribtr ---------- TEnysn 4-5934
1815 Petterson John A Mrs ----------TEnysn 4-0486
1815 Pratt Gerald S ----------TE 4-7306
1815 Pringle Thos E P Mrs ----------834-2724

# FINDINGS

## PALMER AVE

**1967** (cont.) New York Telephone Co



1815 Pringle Thos E P Mrs ----------834-2724
1815 Reed Wm P ----------MD ofc-TEnysn 4-3282
1815 Rice Frank R Mrs ----------TE 4-7534
1815 Rigsby John F ----------TEnysn 4-5644
1815 Scott Loretta M Mrs ----------834-5419
1815 Sears Walter J ----------834-0564
1815 Serton Donald P ----------TE 4-3859
1815 Serton Elma ----------TEnysn 4-8148
1815 Shauer Miriam B ----------TEnysn 4-6071
1815 Smith A W D Mrs --------TEnysn 4-0430
1815 Sorensen C ----------834-4719
1815 Strawn Emily C ----------TE 4-2576

1815 Walsh Peter L ----------TE 4-6436
1825 PATRICIA GARDENS
1825 Basile Frank ----------TE 4-6136
1825 Cope Harold L ----------834-6486

1825C Damon Thos A ----------TE 4-1567
1825C Fabbri Wm ----------TE 4-8273

1833 Baker Roy T ----------834-3419
1833 Cassin J Harold Mrs --------TEnysn 4-4297
1833 Denninger Allan W ----------834-1277
1833 Doren Bruno ----------834-2680
1833 Evans John A ----------834-0599
1833 Francella Louis ----------TE 4-0281
1833 Fulleylove Margery Mrs --------834-5086
1833 Koepper Ted ----------834-0812
1833 Riviezzo Eugene ----------834-4715
1833 Rogers Benj Duke ----------834-6926
1833 Simonsen Christian F ----------834-5256
1833 Warren Peter F Jr ----------834-1277
1833 Wood Frank Jr ----------834-3564
1833A Doherty John M ----------834-8150
1833A Kreycir Jos Geo ----------834-8539
1833A Landes Lewis ----------TE 4-3891
1833B Belanger Theresa M --------TEnysn 4-7065
1833B Eaton Wm V ----------TEnysn 4-6457
1833B Henn Harry C Mrs ----------834-4652
1833B Sliger H B ----------TEnysn 4-3538
1833B Stopford Neville C ----------834-6335
1833C Cral Frank ----------TEnysn 4-1174

1860 Pruginic Borislav ----------834-7695
1861 Larchmnt Centr Cleanrs -----TEnysn 4-0156
*FRANKLIN AV 1864*

## PALMER AVE

**1963** New York Telephone Co



1815 COLONY APTS
1815 Agostinelli Wm J ----------TEnysn 4-4625
1815 Allen F D Mrs ----------TE 4-4855
1815 Bard E W Mrs ----------TEnysn 4-4009
1815 Barnie Clifford G ----------TEnysn 4-4515
1815 Baum J S ----------TE 4-7307
1815 Bearman H W Mrs --------TEnysn 4-1687
1815 Beeley Margaret H Mrs-----TEnysn 4-0594
1815 Bennett Leslie K ----------TEnysn 4-5705
1815 Bewick Hulda ----------TEnysn 4-5934
1815 Boelker Geo O ----------TEnysn 4-1520
1815 Boysen A Miss ----------TEnysn 4-5649
1815 Burns E F Mrs ----------TEnysn 4-4281
1815 Butze Herman ----------TEnysn 4-5445
1815 Calderaio Louis R ----------TEnysn 4-7697
1815 Campagna Peter A ----------TEnysn 4-8946
1815 Campbell W J ----------TEnysn 4-3897
1815 Cannavaro Theo ----------TEnysn 4-2126
1815 Clarke Joyce Mrs ---------TEnysn 4-3132
1815 Colony Apts The ----------TEnysn 4-2222
1815 Condon John F ----------TEnysn 4-7633
1815 Cuqua Carlton J ----------TEnysn 4-7488
1815 Curtiss Mary E ----------TEnysn 4-0120
1815 DeCatur Gerald T Mrs------TEnysn 4-6178
1815 DiEdwards Sam J ---------TEnysn 4-2788
1815 DiMeola Louis ----------TEnysn 4-7446
1815 Dobler Henry C ----------TEnysn 4-3639
1815 Edith Rehnborg Cosmetics
Distribtr ---------- TEnysn 4-5934
1815 Elliott Geo A Mrs ---------TEnysn 4-6759
1815 Elmiger Fredk J Sr --------TEnysn 4-6442
1815 English John S Mrs --------TEnysn 4-3358
1815 Faillace A S Mrs ----------TEnysn 4-4599
1815 Fanning Edw F Mrs ----------TE 4-6640
1815 Ferrall Jos F Mrs ----------TEnysn 4-5279
1815 Ferrigno Jos ----------TEnysn 4-0191
1815 Ferrigno Jos --------paintr-TEnysn 4-3658
1815 Foster Arthur C ----------TEnysn 4-2305
1815 Freeman Peter D ----------TE 4-8994
1815 Gaertner Fred Jr ----------TEnysn 4-0853
1815 Graff Anna S ----------TEnysn 4-1203
1815 Hannula Aune J ----------TEnysn 4-0631
1815 Hanser Richd F ----------TEnysn 4-2196
1815 Hashagen John H ----------TEnysn 4-1062
1815 Hebbard Russell E --------TEnysn 4-5388
1815 Houts Dorothy C ----------TEnysn 4-6495
1815 Howell John J Mrs --------TEnysn 4-1666
1815 Howell Thos B ----------TE 4-3603
1815 Hummel Chas U ------rl est-TEnysn 4-2222
1815 Keenan Thos F Jr Mrs -----TEnysn 4-2163
1815 Kenny Jos P ----------TEnysn 4-0123

# FINDINGS

## PALMER AVE

**1963** (cont.) New York Telephone Co

1815 Kenny Jos P ----------TEnysn 4-0123
1815 King Chas F ----------TEnysn 4-0106
1815 Kitchell Chas W Mrs --------TEnysn 4-4611
1815 Kopins Dorothea L --------TEnysn 4-5468
1815 Larchmont Medical Lab -----TEnysn 4-2871
1815 Macdonald Chas L ---------TEnysn 4-4570
1815 Marx J H ----------TEnysn 4-1863
1815 McCarthy Agnes L ------RN TEnysn 4-7268
1815 McGibbon W C Jr Mrs -----TEnysn 4-7620
1815 McGourty M A ----------TE 4-7352
1815 McHugh Hugh -----MD ofc-TEnysn 4-3800
1815 McLean Donald ----------TE 4-3646
1815 Merrell Richd G ----------TEnysn 4-8944
1815 More Jas ----------TEnysn 4-1726
1815 Morey Edmond R ----------TEnysn 4-4449
1815 Muller D C ----------TEnysn 4-4727
1815 Nixon K J ----------TEnysn 4-2531
1815 Nutrilite Food Supplement
Distribtr ---------- TEnysn 4-5934
1815 Nye Roswell C ----------TE 4-3115
1815 Peterson Beatrice W Mrs --TEnysn 4-7295
1815 Petterson John A Mrs -------TEnysn 4-0486
1815 Pratt Gerald S ----------TE 4-7306
1815 Pushkal Jos J ---------- TE 4-2225
1815 Reed Wm P ---------MD ofc TEnysn 4-3282
1815 Rice Frank R Mrs ----------TE 4-7534
1815 Rigsby John F ----------TEnysn 4-5644
1815 Russell Dolores J ---------TEnysn 4-1195
1815 Serton Elma ----------TEnysn 4-8148
1815 Shauer Miriam B ----------TEnysn 4-6071
1815 Shea Nicholas F Mrs ------TEnysn 4-1359
1815 Smith A W D Mrs --------TEnysn 4-0430
1815 Strawn Emily C ----------TE 4-2576
1815 Turck Dana Mrs ----------TEnysn 4-1094
1815 Turck Fredk W --------lab TEnysn 4-2871
1815 Turck's Lab ----------TEnysn 4-2871
1825 PATRICIA GARDENS
1825 Carlson Edith E ----------TEnysn 4-4280
1825 Forlano John F ---------- TE 4-5428
1825 Frank Irving ----------TEnysn 4-2991
1825 Hopkins Eliz ----------TEnysn 4-1890
1825 Mahrlig Edw Jos Jr ---------- TE 4-5537
1825 Mahrlig Rita Mrs ----------TE 4-5537
1825 Meier Wm G ----------TEnysn 4-2197
1825 Munro Helen P ----------TEnysn 4-0673
1825 Overton Isabel J Mrs ------TEnysn 4-1890
1825 Rubin Emanuel ----------TEnysn 4-5963
1825 Scali Phillip ---------- TE 4-2807
1825 Scott Eliz ----------TEnysn 4-6017
1825 Underhill Gerard B Mrs ----TEnysn 4-1635
1825 Waterbury Robt H Jr --------TEnysn 4-3997
1825B Bloem Henry J Jr -------TEnysn 4-1236
1825B Ferriss Warren ----------TEnysn 4-6228
1825B Hamilton Chas W Mrs ------TEnysn 4-0526

## PALMER AVE

**1963** (cont.) New York Telephone Co

1825C Derks Helen M ----------TEnysn 4-8273
1825C Fabbri Wm ----------TEnysn 4-8273
1825C Stone Sidney H ---DDS-ofc-TEnysn 4-2941
1829-C Whittemore M C ----------TEnysn 4-8409
1833 Cassin J Harold Mrs -------TEnysn 4-4297
1833 Cromwell Inda A ----------TEnysn 4-0403
1833 Francella Louis ----------TE 4-0281
1833 O'Connor Terence ----------TEnysn 4-7412
1833 Whelan Richd ----------TE 4-8873
1833 Whitney Alice de Lappe -----TEnysn 4-5842
1833A Mackay Beverly ----------TEnysn 4-5897
1833A Maiello Louis ---------- TE 4-5173
1833B Belanger Theresa M ----------TEnysn 4-7065
1833B Singer H B ----------TEnysn 4-3338
1833C Clarke Helen V Mrs ----------TE 4-4704
1833C Cral Frank ----------TEnysn 4-1174
1833C Harris Oliver M ----------TEnysn 4-0233
1833C Sibson John B ----------TEnysn 4-0577
1833D Sichler Chas C ----------MD TEnysn 4-2356
1860 Long Forrest D Jr ----------TE 4-4585
1861 Larchmnt Centr Cleanrs -----TEnysn 4-0156
1875 Larchmont Lanes ---------bwlg TE 4-1060
1879 Revivalist Andrzej ----------TEnysn 4-7300

# FINDINGS

## RAILROAD WAY

**2024** Cole Information

6 Prime Performance
Chatsworth Taxi Co Inc
Prime Performance And Dev Llc
LUIGI G PIZZI
ADRIAN R CAMACHO
8 Around Corner Ltd

## RAILROAD WAY

**2022** Cole Information

1 WELLS FARGO
LARCHMONT
6 CHATSWORTH TAXI
CHATSWORTH TAXI CO INC
8 THE CELLAR BAR

## RAILROAD WAY

**2022** Data Axle

8A GOLDSTEIN, JEFFREY L DO

## RAILROAD WAY

**2017** Cole Information

8 AROUND THE CORNER LTD

## RAILROAD WAY

**2017** Data Axle

1 LARCHMONT METRO NORTH
6 Unit A CHATSWORTH TAXI CO INC

## RAILROAD WAY

**2014** Cole Information

6 CHATSWORTH TAXI COMPANY INCORPORATED
8 CELLAR BAR THE

## RAILROAD WAY

**2014** Data Axle

1 LARCHMONT METRO NORTH
WELLS FARGO ATM

## RAILROAD WAY

**2010** Cole Information

6 CHATSWORTH TAXI CO INC
8 CELLAR BAR

## RAILROAD WAY

**2005** Cole Information

6 MARK J MAFFIA
Unit A MARK J MAFFIA

## RAILROAD WAY

**2005** Data Axle

8 CELLAR BAR

## RAILROAD WAY

**2000** Cole Information

6 LARCHMONT BEVERAGE

# FINDINGS

## RAILROAD WAY

**2000** (cont.) Cole Information

8 CELLAR BAR THE
Unit A PUSH BUTTON PUBLISHING

## RAILROAD WAY

**1995** Cole Information

6 LARCHMONT BEVERAGE
8 CELLAR BAR THE
PUSH BUTTON PUBLISHING
P C LAN SVCES

## RAILROAD WAY

**1992** Cole Information

6 LARCHMONT BEVERAGE
8 CELLAR BAR THE

## RAILROAD WAY

**1987** Cole Publications

6★Larchmont Beverage . . 79 834-6221
8★The Cellar Bar . . . . 82 834-8723

## RAILROAD WAY

**1981** Cole Publications

6★Larchmont Beverage . . . . 834-6221

## RAILROAD WAY

**1972** Cole Publications


6*SYMPHNTE FCTRY OUT□8342133

## RAILROAD WAY

**1967** New York Telephone Co

Yellow Cab Co Inc ..... TEnysn 4-2200
6 Derf Radio&Electrncs Corp ..... TE 4-4400

# FINDINGS

## THOMPSON ST

**2024** Cole Information

12 SALVATORE FAZZOLARI

## THOMPSON ST

**2017** Cole Information

12 SALVATORE F FAZZOLARI

## THOMPSON ST

**2014** Cole Information

12 SALVATORE F FAZZOLARI

## THOMPSON ST

**2010** Cole Information

12 SALVATORE FAZZOLARI

## THOMPSON ST

**2005** Cole Information

12 ANN M LIBRANDI

## THOMPSON ST

**2000** Cole Information

12 ANTHONY N LIBRANDI

## THOMPSON ST

**1995** Cole Information

12 MACRI, JOSEPH
LIBRANDI, ANTHONY N

## THOMPSON ST

**1992** Cole Information

12 SUMMERSON, TODD
LIBRANDI, ANTHONY N

## THOMPSON ST

**1987** Cole Publications

12 George Fowler . . . . .77 834-1679
Anthony Librandi . . . .64 834-0178

## THOMPSON ST

**1981** Cole Publications


12 George Fowler . . . . . .77 834-1679
Anthony Librandi . . . . . .64 834-0178

## THOMPSON ST

**1977** Cole Publications

12 Anthony Librandi TE4-0178

## THOMPSON ST

**1972** Cole Publications

12 ANTHONY LIBRANDI 4 TE40178

# FINDINGS

## VINE PL

**2022** Cole Information

| | |
|---|---|
| 1 | Edmund R Papazian |

## VINE PL

**2017** Cole Information

| | |
|---|---|
| 1 | LINCOLNDALE PLAZA CORPORATION |

## VINE PL

**2014** Cole Information

| | |
|---|---|
| 1 | EMILIE GRENVILLE |

## VINE PL

**1967** New York Telephone Co




## VINE PL

**1963** New York Telephone Co



# FINDINGS

## WOOD ST

**2024** Cole Information

5 ANTHONY C ZAVAGLIA

## WOOD ST

**2022** Cole Information

5 Anthony C Zavaglia

## WOOD ST

**2017** Cole Information

3 BRIAN PERCIASEPE
5 LINDA ZAVAGLIA

## WOOD ST

**2014** Cole Information

3 JONATHAN S BAUER
5 LINDA ZAVAGLIA
BRIAN C STEN

## WOOD ST

**2010** Cole Information

3 CARMINE PERCIASEPE
5 ANGELA ZAVAGLIA
HENRY L MARTIN

## WOOD ST

**2005** Cole Information

3 CARMINE PERCIASEPE
5 SALVATORE ZAVAGLIA
HENRY L MARTIN
GARY A SCOGGAN

## WOOD ST

**2000** Cole Information

3 CARMINE PERCIASEPE
5 SALVATO ZAVAGLIA
HENRY L MARTIN
C KENNEDY

## WOOD ST

**1995** Cole Information

3 PERCIASEPE, CARMINE, JR
5 PRICEMAN, OLIVER
MARTIN, HENRY L
ZAVAGLIA, SALVATORE

## WOOD ST

**1992** Cole Information

3 PERCIASEPE, CARMINE, JR
5 ZAVAGLIA, SALVATORE

## WOOD ST

**1987** Cole Publications


3 C Perciasepe Jr . . . . 834-7219
5 Eric R Waite . . . . . ¤ 833-0755
S Zavaglia . . . . . .68 834-5113

# FINDINGS

## WOOD ST

**1981** Cole Publications


3 C Perciasepe Jr . . . . . 834-7219
5 S Zavaglia . . . . . 834-5113

## WOOD ST

**1977** Cole Publications


3 C Perciasepe Jr TE4-7219
5 S Zavaglia TE4-5113
No # Vaino Rahko 962-4261
No # Matti Toikka YO2-4263

## WOOD ST

**1972** Cole Publications

3 C PERCIASEPE JR TE47219
5 S ZAVAGLIA TE45113

## WOOD ST

**1967** New York Telephone Co

3 Perciasepe Carmine Jr ---------- TE 4-7219
5 Zavaglia Salvatore ---------- TE 4-5113

## WOOD ST

**1963** New York Telephone Co

641 Zingler Morris ---------- OWens 8-4798

# FINDINGS

## WOODLAND AVE

**2024** Cole Information

| | |
|---|---|
| 2 | FRANCINE O DELOATCH |
| | COUNCIL INTERFAITH |
| | JONATHAN I JOSHUA |
| | DIANA M DESANTIAGO |
| 3 | Identitystream Corp |
| | KENNETH S PROVERBS |
| | EBRU L DEMIR |
| | BEATRICE CHILEMBA |
| | JANET MALCOLM |
| 5 | JOSE ROSEMBERG |
| | THOMAS V SMITH |
| | JANE V D'AGOSTINO |
| | JOSE VILLALOBO |
| 7 | Ste 7 Marshall Cohen Associates Llc |
| | Ste 7 Arthur Goldstein |
| | Ste 8 Pollack Services Group Ltd |
| | Ste 4 Irwin Cohen |
| | Ste 1 Mary Oconnor |
| | Ste 9 Martin S Cohen |
| | Ste 11 Cable Consultants Corporation |
| | Ste 8 Global Coverage Inc |
| | Ste 11 El-Tech Technology Inc |
| | Ste 15 Dalba It Services Llc |
| | Ste 14 Tarek Morad Agency |
| | Ste 15 Picsello Inc |
| | Ste 7 Jane Goodrich Photography |
| | Ste 14 Gibraltar Financial |
| | STEVEN P ESKOW |
| | ARTHUR GOLDSTEIN |
| | WALID MORAD |
| | LINDA STEIN |
| | TAREK MORAD |
| 8 | MICHAEL A DISOTTO |
| | MARCO A ONELLI |
| | SUSANNA DISOTTO |

## WOODLAND AVE

**2022** Cole Information

| | |
|---|---|
| 1 | JOYCEROBINS.NET |
| | Rafael Kam |
| 2 | Apt 2 Jonathan I Joshua |
| | Council Interfaith |
| | Apt 1 Zashelle M Larosa |
| | Apt 2 Kayla T Smith |
| | Jophnathan R Scott |
| 3 | Apt 2 Kenneth S Proverbs |
| | Apt 2 Jeremy Skehan |
| | Apt 2 Manuel Odar |
| | Apt 1 Janet Malcolm |
| | Apt 3 Beatrice Chilemba |
| 5 | Jose Rosemberg |
| | Jayne V D'Agostino |
| 7 | Ste 7 GOLDSTEIN ARTHUR |
| | Ste 9 JAY LEFER MD |
| | Ste 8 GLOBAL COVERAGE INC |
| | Ste 8 GLOBAL COVERAGE, INC |
| | Ste 8 POLLACK SERVICES GROUP LTD |
| | Ste 5 D ALBA IT SERVICES LLC |
| | Ste 8 GLOBAL COVERAGE |
| | DALBA IT SERVICES |
| | Ste 9 COHEN MARTIN S PH.D. |
| | GIBRALTAR FINANCIAL |
| | Ste 4 IRWIN COHEN |
| | Ste 15 LARCHMONT CAPITAL |
| | Ste 9 PROFESSIONAL GROUP |
| | Ste 7 CENTER FOR COUNSELING & PSYCH |
| | Ste 10 LAW OFFICE OF MARY ELLEN OCONNOR |
| | Ste 11 EL-TECH TECHNOLOGY INC |
| | CULTURE CHANGE CONSULTANTS |
| | Ste 7 COHEN MARSHALL ASSOCS |
| | Ste 9 MICHAEL S BEHAR MD |
| | Ste 15 DALBA IT SERVICES LLC |
| | CENTER FOR COUNSELING & PSYCHOLOGICAL SVCES |
| 8 | Marco Onelli |
| | Apt 2 Susanna Disotto |

# FINDINGS

## WOODLAND AVE

**2022** (cont.) Cole Information

8 Apt 2 Michael A Disotto

## WOODLAND AVE

**2017** Cole Information

1 RAFAEL KAM
2 Apt 1 DIANA D DESANTIAGO
JUSTIN A LAROSA
3 Apt 1 SEDAR S DEMIR
ASHLEY L LAWLER
5 GOLDEN APPLE SERVICES LLC
DANIEL J HACKER
7 Ste 11 EL TECH TECHNOLOGY INC
Ste 1 OCONNOR MARY
Ste 11 CABLE CONSULTANTS CORP
Ste 4 IRWIN COHEN
Ste 8 GLOBAL COVERAGE INC
8 Apt 2 SUSANNA V DISOTTO
MARCO A ONELLI

## WOODLAND AVE

**2014** Cole Information

1 RAFAEL KAM
2 Apt 1 DIANA M DESANTIAGO
Unit A NICK R CAMACHO-SANTIAGO
Apt 2 JONATHAN I JOSHUA
3 STEVEN M FERRETTI
ASHLEY L LAWLER
7 Ste 4 IRC PARTNERS
Ste 14 LARCHMONT CAPITAL CAPITAL
GOLDSTEIN ARTHUR
Ste 8 GLOBAL COVERAGE
Ste 14 GIBRALTAR FINANCIAL
Ste 4 ZOFFNESS MATH TUTORING

## WOODLAND AVE

**2014** (cont.) Cole Information

7 Ste 9 COHEN MARTIN S PHD
Ste 1 ST FRANCIS CONSTRUCTION COMPANY
CULTURE CHANGE CONSULTANTS
DALBA IT SERVICES LLC
Ste 7 COHEN MARSHALL ASSOCIATES
Ste 7 CENTER FOR COUNSELING & PSYCHOLOGICA
Ste 11 EL TECH TECHNOLOGY INCORPORATED
Ste 11 CABLE CONSULTANTS CORPORATION
JAY M LEFER
8 Unit 2 ANDREW F DENGLER
Apt 1 MICHELLE I SULLIVAN

## WOODLAND AVE

**2010** Cole Information

1 RAFAEL KAM
2 JASON HOLMES
DIANA M DESANTIAGO
3 SEDAR S DEMIR
ENRIQUE BENEDETTI
5 STEFANIE J SCHNEIDER
7 Ste 14 TAREK MORAD AGENCY
Ste 10 MIKLUS PAUL J
Ste 7 MARSHALL COHEN ASSOC
Ste 4 ZOFFNESS MATH TUTORING
Ste 11 ELTECH TECHNOLOGY INC
Ste 1 ST FRANCIS CONSTRUCTION CO
Ste 9 BEHAR MICHAEL S MD
Ste 8 GLOBAL COVERAGE
Ste 4 IRC PARTNERS
Ste 15 DALBA IT SVC LLC
STUNTZ MAYO
Ste 14 GIBRALTAR FINANCIAL
LEFER JAY MD
Ste 7 CENTER FOR COUNSELING & PSYCH

# FINDINGS

## WOODLAND AVE

**2010** (cont.) Cole Information

7 Ste 14 OMEGA CAPITAL
MAYO STUNTZ
JAY M LEFER
COHEN IRWIN
8 ROBERT GOLDMAN
MICHAEL A DISOTTO
MICHELLE BORDENGA
MICHELLE J SULLIVAN

## WOODLAND AVE

**2005** Cole Information

1 PATRICK N WESTOO
2 ALEASE M ANDERSON
J HOLMES
DIANA DESANTIAGO
JOHNATHAN SCOTT
3 JOHN W LAWLER
JOHN A BARRERA
Apt 3 AL F FERRETTI
ASHLEY L PEARSON
5 MARIA ERASO
JOSE URIBE
7 IRC PARTNERS
ST FRANCIS CONSTRUCTION CO
Ste 8 ALL SPECIALTIES AGENCY II INC
STUNTZ MAYO CONSLNT
LEONE DESIGN GROUP INC
Ste 8 GLOBAL COVERAGE
COHEN MARSHALL ASSOCS
ROBERT PRIAULX PROMOTIONS INC
Ste 14 MORAD WALID
CENTER FOR COUNSELING & PSYCHOLOGICA
CABLE CONSULTANTS CORP
Ste 11 EL TECH TECHNOLOGY INC
WALID MORAD

## WOODLAND AVE

**2005** (cont.) Cole Information

7 LEWIS J TAUB
MAYO STUNTZ
DIMITRI A STEIN
JAY M LEFER
PAL J MIKLUS
8 ULTIMATE HOMES
ELIA L MOLINA
CHRIS MARCON
SUSANNA B GABRIELE
MICHAEL KOPPY
Unit 2 ALEXANDER YOFFE
MICHAEL A DISOTTO

## WOODLAND AVE

**2000** Cole Information

1 C RUBERO
2 SANDRA TRAPP
3 AL FERRETTI
5 K OCONNER
7 QUINN & ASSOCIATES INCORPORATED
Ste 11 CABLE CONSULTANTS CORPORATION
Ste 11 CABLE CONSULTANTS CORP
COHEN MARTIN S PHD
COHEN MARSHALL ASSOCIATES
GOLDSTEIN ARTHUR
LEONE DESIGN GROUP INCORPORATED
J B HENRIQUES SALES CORPORATION
LIPPMAN GUSTAVE ATTORNEY
LIPPMAN GUSTAVE
GMELIN INSTITUTE
ROBERT PRIAULX PROMOTIONS INCORPORATED
CENTER FOR COUNSELING & PSYCHOLOGICAL SVCES
HERNDON ASSOCIATES

# FINDINGS

## WOODLAND AVE

**2000** (cont.) Cole Information

7 KRAWCHICK LOUIS ATTORNEY
LEFER JAY MD
STUNTZ MAYO CONSLNT
EL TECHNOLOGY TECHNOLOGY INCORPORATED
Ste 11 SCIENTIFIC INFORMATION SVCE INCORPORATED
DEMPSEY MCEVILY APPRAISAL
MIKLUS PAUL J ATTORNEY
JOHN SPECIC
8 MICHAEL A DISOTTO
DANIEL ABRAMSON
Apt 1 SUZANNE Y GROSSMAN
STEVEN N WAYLAND

## WOODLAND AVE

**1995** Cole Information

3 SKEHAN, JAMES
FERRETTI, ALBERT, JR
5 MCNULTY, THERESA & PATRICK
STEINNAGEL, C
7 KRAWCHICK, LOUIS, ATTY
TRADE MARKETING & PROMOTION GROUP INC
IBMS
GOLDSTEIN, ARTHUR
MIKLUS, PAUL J, ATTY
LIPPMAN, GUSTAVE, ATTY
LEONE DESIGN GROUP INC
SCIENTIFIC INFORMATION SVCE INC
GMELIN INST
EL-TECH TECHNOLOGY INC
CABLE CONSULTANTS CORP
MIKLUS PAUL J, ATTY
LIPPMAN GUSTAVE
LEFER, JAY, MD

## WOODLAND AVE

**1995** (cont.) Cole Information

7 QUINN & ASSOCS INC
HERNDON ASSOCIATES
SPECIC, JOHN & CAROLINE
8 DI SOTTO, M A

## WOODLAND AVE

**1992** Cole Information

2 AMES, MARY
HUNTER, GWENDOLYN
3 GORESEN, R & D
FERRETTI, L
5 MC NULTY, EUGENE
7 LEFER, JAY, MD
LIPPMAN GUSTAVE
LIPPMAN, GUSTAVE, ATTY
SCIENTIFIC INFORMATION SVCE INC
GMELIN INST
ELTEK CORP
CABLE CONSULTANTS CORP
BABITT & CO
HERNDON ASSOCIATES
KRAWCHICK HEBEN & CO, CPA'S
KRAWCHICK, LOUIS, CPA
KRAWCHICK, LOUIS, ATTY
HEBEN, EDWARD D, CPA
DIVERSIFIED ECONOMIC SVCS INC
GOLDSTEIN, ARTHUR
PALADIN II LTD
LEONE DESIGN GROUP INC
ROTHBERG & CO
GEOCOM INC
SPECIC, JOHN & CAROLINE
8 STYER, BRIAN

# FINDINGS

## WOODLAND AVE

**1987** Cole Publications

| | | | | |
|---|---|---|---|---|
| 2 | W Chronowski | .77 | | 834-5054 |
| | Eduardo Nunez | .84 | | 834-4651 |
| 3 | A Ferretti | .70 | | 834-9398 |
| | L Ferretti | .84 | | 834-8359 |
| | C M Maasz | | ¤ | 833-0160 |
| | L Valesio | | ¤ | 833-0890 |
| 5 | Norman Finger | .67 | | 834-1645 |
| 7 | ★ Cable Conslts Corp | | | 834-8864 |
| | ★ Kathryn H Clarke | .83 | | 834-3466 |
| | ★ Eltek Corp | | | 834-8864 |
| | ★ G P Forbes Jr Aty | | | 834-3500 |
| | ★ Gmelin Institute | | | 834-8864 |
| | ★ J B Griffin Lyr | .85 | | 834-0111 |
| | ★ Kaplow&Ziplow Inc | .74 | | 834-8700 |
| | ★ M Kaufman Realty | .85 | | 833-0393 |
| | ★ K Mitchell&Co Inc | .85 | | 833-0393 |
| | ★ Krawchick&Co | .79 | | 834-5600 |
| | ★ G Krawchick Aty | | | 834-5600 |
| | ★ Louis Krawchick | .75 | | 834-5600 |
| | ★ Leone Design Group | .84 | | 834-5700 |
| | ★ Carroll B Low Lyr | | | 834-3500 |
| | ★ Low&Low Lyr | | | 834-3500 |
| | ★ Mitchell Kfmn Rlt | .85 | | 833-0393 |
| | ★ G M Moch Inc | .72 | | 834-3530 |
| | ★ NY St Beer Whlslrs | .82 | | 834-8712 |
| | ★ Schwartzreich&Assc | | | 834-3500 |
| | ★ Scientific Info | .79 | | 834-8864 |
| | ★ John Specic | .81 | | 834-7906 |
| | ★ Taft Co | | ¤ | 834-7260 |
| | ★ Raymond Ziplow Inc | .73 | | 834-8700 |
| | ★ Raymond Ziplow Mng | .71 | | 834-8700 |
| 8 | Vincent Reviello | .65 | | 834-0492 |

## WOODLAND AVE

**1983** New York Telephone

| | |
|---|---|
| 7 | FAVORITE BROKERAGE INC |

## WOODLAND AVE

**1981** Cole Publications



| | | |
|---|---|---|
| 2 | W Chronowski .....77 | 834-5054 |
| | Robert L Correia .....- | 834-6101 |

## WOODLAND AVE

**1981** (cont.) Cole Publications



| | | |
|---|---|---|
| 3 | A Ferretti .....70 | 834-9398 |
| 5 | Norman Finger .....67 | 834-1645 |
| 7 | Lawrence Ames .....77 | 834-6246 |
| | ★Cable Conslts Corp .... | 834-8864 |
| | ★Concepts Internatl .... | 834-3890 |
| | ★John L Delius Atty .... | 834-3500 |
| | ★Eltek Corp ..... | 834-8864 |
| | ★Robert B Fish Sale .... | 834-0974 |
| | ★G P Forbes Jr Atty .... | 834-3500 |
| | ★Gmelin Institute ..... | 834-8864 |
| | ★Kaplow&Ziplow Inc .... | 834-8700 |
| | ★David Klein Atty ..... | 834-1776 |
| | ★Krawchick&Co CPAS .... | 834-5600 |
| | ★G Krawchick Atty ..... | 834-5600 |
| | ★G Krawchick CPA ..... | 834-5600 |
| | ★L Krawchck CPA&Aty ... | 834-1898 |
| | ★Carroll B Low Lwyr .... | 834-3500 |
| | ★Low&Low Lwyrs ..... | 834-3500 |
| | ★M H Concepts Intnl ....¤ | 834-3890 |
| | ★G M Moch Inc ..... | 834-3530 |
| | ★Schaefam ..... | 834-0390 |
| | ★Schwartzreich&Assc .... | 834-3500 |
| | ★Scientific Info ..... | 834-8864 |
| | ★The Arthritis Fndn .... | 834-6464 |
| | ★Trustan Co Inc ..... | 834-0111 |
| | ★Raymond Ziplow Inc ... | 834-8700 |
| | ★Raymond Ziplow Mng ... | 834-8700 |
| 8 | Vincent Reviello .....65 | 834-0492 |

## WOODLAND AVE

**1977** Cole Publications



| | | | |
|---|---|---|---|
| 2 | Tanil Bas | 3 | 834-8032 |
| 3 | A Ferretti | 0 | 834-9398 |
| 5 | Norman Finger | 7 | 834-1645 |
| 7 | ★ Atomc Enrgy Docmtn | | 834-8864 |
| | ★ Cable Conslts Corp | | 834-8864 |
| | ★ Jos F Curren Atty | | TE4-7374 |
| | ★ John L Delius Atty | | TE4-3500 |
| | ★ Eltek Corp | | 834-8864 |
| | ★ G P Forbes Jr Atty | | TE4-3500 |
| | ★ Gmelin Institute | | 834-8864 |
| | ★ George R Hamilton | | 834-6883 |
| | ★ Kaplow&Ziplow Inc | | 834-8700 |
| | ★ G Krawchick Atty | | 834-5600 |
| | ★ G Krawchick CPA | | 834-5600 |

# FINDINGS

## WOODLAND AVE

**1977** (cont.) Cole Publications

| | | |
|---|---|---|
| 7 | ★Louis Krawchick | 834-1898 |
| | ★Carroll B Low Lwyr | TE4-3500 |
| | ★Low&Low Lwyrs | TE4-3500 |
| | ★Lund International | TE4-2430 |
| | ★Robert T Lund | TE4-2430 |
| | ★G M Moch Inc | 834-3530 |
| | ★Russwin Division – | 834-5633 |
| | ★Russwin Hardware – | 834-5633 |
| | ★Schaefam | 834-0390 |
| | ★Schwartzreich&Assc | TE4-3500 |
| | ★G B Tepper CPA | 834-7190 |
| | ★Raymond Ziplow Inc | 834-8700 |
| | ★Raymond Ziplow Inc | 834-8700 |
| 8 | Vincent Reviello | TE4-0492 |

## WOODLAND AVE

**1972** Cole Publications



| | | | |
|---|---|---|---|
| 2 | *BOUKOUKLIAN ARDCHS | | TE41904 |
| | W CHRONOWSKI | 5 | 8345236 |
| 3 | A FERRETTI | 0 | 8349398 |
| 5 | NORMAN FINGER | 7 | 8341645 |
| 7 | *ATOMC ENRGY DOCMTN | | 8348864 |

## WOODLAND AVE

**1972** (cont.) Cole Publications



| | | | |
|---|---|---|---|
| | *CABLE CONSLTS CORP | | 8348864 |
| | *JOS F CURREN ATTY | | TE47374 |
| | *JOHN L DELIUS ATTY | | TE43500 |
| | *PATRICK ELLAM INC | | 8348886 |
| | *PATRICK ELLAM INC | ¤ | 8345463 |
| | *ELTEK CORP | | 8348864 |
| | *EQUIPMENT SYSTEMS | | 8345845 |
| | *G P FORBES JR ATTY | | TE43500 |
| | *GMELIN INSTITUTE | | 8348864 |
| | GEORGE R HAMILTON | 6 | 8346883 |
| | JACK KANTOR | 7 | 8345131 |
| | *G KRAWCHICK ATTY | | 8345600 |
| | *KRAWCHICK&TVERY | | 8345600 |
| | *CARROLL B LOW LWYR | | TE43500 |
| | *LOW&LOW LWYRS | | TE43500 |
| | *LUND INTERNATIONAL | | TE42430 |
| | *ROBERT T LUND | | TE42430 |
| | *D MOORE ATTY | | TE46660 |
| | *T F MOORE JR ATTY | | TE46660 |
| | *VALERIE OKEEFFE M | | TE46660 |
| | *RHODES YACHTS | ¤ | 8348666 |
| | *SCHWARTZREICH&ASSC | | TE43500 |
| | *S SCHWARTZREICH | | TE43500 |
| | *STRICKLAND ASSOCS | | 8348800 |
| | *RONALD M TVERT CPA | | 8345600 |
| | *WORLD MRKTNG SERV | | TE42430 |
| | *YARWAY CORP | – | 8340161 |
| 8 | VINCENT REVIELLO | 5 | TE40492 |

## WOODLAND AVE

**1971** New York Telephone

| | |
|---|---|
| 7 | KANTOR JACK |

## WOODLAND AVE

**1965** New york Telephone Company

| | |
|---|---|
| 7 | FRIEND JOS B |

# FINDINGS

## WOODLAND AVE

**1963** New York Telephone Co



2 Boukoukllan Ardaches ---------TEnysn 4-1904
2 Monnett Gregory F ---------TE 4-0089
3 Bouchard Linda Mrs ---------TE 4-7107
3 Tietge Paul ---------TEnysn 4-7416
5 Biondo Catherine Mrs ---------TEnysn 4-1645
7 Atomic Energy Documentation Cntr ---TE 4-8864
7 Brill&Darrow ---------lwyrs-TE 4-7171
7 Brill Wm S ---------lwyr-TEnysn 4-7171
7 Burchell Geo D ---------atty TEnysn 4-3500
7 Cable Consultants Corp ---------TE 4-8865
7 Campbell-Sheehan ---------TE 4-7090
7 Coughlin Agency Inc ---------TE 4-1661
7 Curren Jos F ---------atty-TE 4-7374
7 Darrow Wm L ---------atty-TE 4-7171
7 Delius John L ---------atty-TEnysn 4-3500
7 Elruss Foundtn Inc ---------TE 4-0064
7 Executive Pension Planning Corp of Amer ---------TE 4-8330
7 Finesse Prods Inc ---------TEnysn 4-8580
7 Friend Jos ---------b-TE 4-8620
From NYC Tels ---------212 TY 2-3510
7 Gmelin Inst ---------TE 4-8864
7 Hamilton Geo R ---------TE 4-6883
7 Harmstorf Corp ---------TE 4-6164
7 Krawchick Geo ---------atty-TEnysn 4-3500
7 Krawchick Geo ---------CPA-TEnysn 4-5600
7 Lund Robt T ---------b-TE 4-2430
7 Rosner Lawrence M ---------ins TE 4-8894
7 Rosner-Simon Assocs Inc ---------ins-TE 4-8894
7 S&K Sales Co ---------TE 4-8620
From NYC Tels ---------212 TY 2-3510
7 Schwartzreich&Burchell ---lwyrs-TEnysn 4-3500
7 Schwartzreich Sylvan ---------atty TEnysn 4-3500
7 World Marketing Svce Inc ---------TE 4-2430
8 Reviello Vincent ---------TEnysn 4-0492

AREA CODE

149 Norton David J ---------
149 Wandler Emma ---------
150 Stuart Fred L ---------
153 Claudet Eugene ---------
153 Claudet Henri L ---------
154 Burrill Dudley F ---------
158 Quinn Jas W Mrs ---------
158 Sinopoli Anthony E ---------
159 Kraft John E ---------
159 Pressmar Geo F Sr ---------
165 Strand Helen Mrs ---------
166 Girsti Gerhard ---------
166 Rutan Violet S Mrs ---------
173 Doering Charlotte E ---------
173 Young Marian E ---------
176 DeFrancesco Michl ---------
176 Mowatt John W ---------
177 Miceli Frank G ---------
177 Shiraishi Susumu ---------
184 deSimone Jos N ---------
184 Ferguson John F ---------
185 Cioffoletti John ---------
185 Cioffoletti Rocco G ---------
186 Balascio Frank ---------
186 Michelotti Madeline Mrs ---------
191 Rafferty J P ---------
192 Powers John L ---------
193 Maxcy Lloyd ---------
196 Mitchel Michl E ---------
199 Gehrung Carl F Jr ---------
199 Russell Day ---------
199 Winner Wm ---------

# Appendix F Environmental Database Report

**One Vine Street**
1 Vine St
Larchmont, NY  10538

Inquiry Number: 8303563.2s
April 06, 2026

# The EDR Radius Map™  Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

# TABLE OF CONTENTS

## LIGHTBOX LIVE

Open LightBox Live to access data, tools, and advanced analytics in one online platform.

http://www.web.edrnet.com/ordering/switchboard/login.aspx?s=goto_lightbox&pguid=EF9CD6BA-EF39-42AA-83AA-AB8EB1209DE5


| SECTION | PAGE |
|---|---|
| Executive Summary | ES1 |
| Overview Map | 2 |
| Detail Map | 3 |
| Map Findings Summary | 4 |
| Map Findings | 9 |
| Orphan Summary | 474 |
| Government Records Searched/Data Currency Tracking | GR-1 |

## GEOCHECK ADDENDUM

| | |
|---|---|
| Physical Setting Source Addendum | A-1 |
| Physical Setting Source Summary | A-2 |
| Physical Setting SSURGO Soil Map | A-5 |
| Physical Setting Source Map | A-10 |
| Physical Setting Source Map Findings | A-12 |
| Physical Setting Source Records Searched | PSGR-1 |



**Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2026 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

# EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E2247 - 23), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E1528 - 22) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

## TARGET PROPERTY INFORMATION

### ADDRESS

1 VINE ST
LARCHMONT, NY 10538

### COORDINATES

| | |
|---|---|
| Latitude (North): | 40.9354700 - 40° 56' 7.69'' |
| Longitude (West): | 73.7584300 - 73° 45' 30.34'' |
| Universal Tranverse Mercator: | Zone 18 |
| UTM X (Meters): | 604523.7 |
| UTM Y (Meters): | 4532124.0 |
| Elevation: | 41 ft. above sea level |

### USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

| | |
|---|---|
| Target Property Map: | 50026534 MOUNT VERNON, NY |
| Version Date: | 2023 |
| East Map: | 50026533 MAMARONECK, NY |
| Version Date: | 2023 |

### AERIAL PHOTOGRAPHY IN THIS REPORT

| | |
|---|---|
| Photo Year: | 2024 |
| Source: | USDA |

# MAPPED SITES SUMMARY

Target Property Address:
1 VINE ST
LARCHMONT, NY 10538

Click on Map ID to see full detail.

| MAP ID | SITE NAME | ADDRESS | DATABASE ACRONYMS | RELATIVE ELEVATION | DIST (ft. & mi.) DIRECTION |
|---|---|---|---|---|---|
| A1 | J & F CHATSWORTH AUT | 1 VINE ST | RCRA-SQG, E MANIFEST, NY MANIFEST, NJ MANIFEST | | TP |
| A2 | MAGIC TOUCH CLEANERS | 1 VINE ST | EDR Hist Cleaner | | TP |
| A3 | CHATSWORTH GARAGE IN | 1 VINE ST | EDR Hist Auto | | TP |
| A4 | MARISIERO INC. | 1-5 VINE STREET | NY LTANKS | | TP |
| A5 | JS CHADWORTHS | 1 VINE ST | NY Spills | | TP |
| A6 | J & F CHATSWORTH GAS | 1 VINE STREET | UST FINDER RELEASE | | TP |
| A7 | J & F CHATSWORTH LTD | 1 VINE STREET | NY UST, NY AST | | TP |
| A8 | JF CHATSWORTH | 1 VINE STREET | NY LTANKS, NY Spills | | TP |
| A9 | J & F CHATSWORTH AUT | 3 VINE ST | US AIRS, FINDS, ECHO | | TP |
| A10 | J & F CHATSWORTH AUT | 3 VINE ST | NY AIRS | | TP |
| A11 | MAGIC TOUCH CLEANERS | 5 VINE STREET | FINDS, ECHO | | TP |
| A12 | KIM KWUNG | 5 VINE ST | EDR Hist Cleaner | | TP |
| A13 | MAGIC TOUCH CLEANERS | 5 VINE ST | RCRA NonGen / NLR, ICIS, US AIRS, NY DRYCLEANERS,... | | TP |
| A14 | TRAFFIC ACCIDENT | I-95 MP 7.7 | NY Spills | Higher | 163, 0.031, SSW |
| 15 | 7 MAPLE ST | 7 MAPLE ST | NY Spills | Higher | 193, 0.037, West |
| B16 | CON EDISON | 10 CABOT RD | RCRA NonGen / NLR | Lower | 286, 0.054, NNE |
| C17 | NEW YORK STATE AUTHO | 1 RAILROAD WAY | RCRA-SQG, ECHO | Higher | 333, 0.063, South |
| B18 | DECABIA - UST | 19 CABOT RD | NY Spills | Lower | 420, 0.080, NE |
| C19 | FIRST IMPRESSION | 1875 PALMER AVE | EDR Hist Cleaner | Higher | 468, 0.089, South |
| C20 | GLOBE RESTAURANT | 1879 PALMER AVE | NY LTANKS | Higher | 508, 0.096, South |
| D21 | PATRICIA GARDENS | 1825 PALMER AVE | NY LTANKS, NY Spills | Higher | 526, 0.100, ESE |
| D22 | PATRICIA GARDENS OWN | 1825 PALMER AVENUE | NY UST | Higher | 526, 0.100, ESE |
| D23 | PATRICIA GARDENS OWN | 1825 PALMER AVENUE | NY AST | Higher | 526, 0.100, ESE |
| D24 | LARCHMONT CENTER CLE | 1861 PALMER AVE | EDR Hist Cleaner | Higher | 550, 0.104, SE |
| C25 | MANOPP REALTY | 1885-1889 PALMER AVE | NY Spills | Higher | 562, 0.106, South |
| C26 | LUSARDI'S RESTAURANT | 1885-1889 PALMER AVE | NY AST | Higher | 562, 0.106, South |
| E27 | COLONY TENANTS CORP. | 1815 PALMER AVENUE | NY UST | Lower | 570, 0.108, East |
| E28 | SPILL NUMBER 9909425 | 1815 PALMER AVE | NY Spills | Lower | 570, 0.108, East |
| F29 | REAR OF 1880 PALMER | FRANKLYN AVE | NY LTANKS | Higher | 608, 0.115, SSE |
| G30 | TRIPLE CLEAN GROUP I | 1895 PALMER AVE | EDR Hist Cleaner | Higher | 643, 0.122, South |
| G31 | EMBASSY CLEANERS | 1895 PALMER AVE | RCRA-SQG, ICIS, US AIRS, FINDS, ECHO, NY... | Higher | 643, 0.122, South |
| G32 | BROMPTON APTS. | 1880 PALMER AVE. | NY LTANKS | Higher | 652, 0.123, South |
| G33 | THE BROMPTON | 1880 PALMER AVENUE | NY AST | Higher | 652, 0.123, South |
| G34 | SIDEWALK AND PARKING | 1880 PALMER AVE | NY Spills | Higher | 652, 0.123, South |
| F35 | HOFFMANS | 1850 PALMER AVE. | NY LTANKS | Higher | 665, 0.126, SE |
| D36 | CON EDISON SERVICE B | PALMER AVE & E DEPOT | RCRA NonGen / NLR, FINDS | Lower | 674, 0.128, ESE |
| D37 | CON EDISON | PALMER AVE & E DEPOT | NY MANIFEST | Lower | 674, 0.128, ESE |
| H38 | CON EDISON | MYRTLE BLVD & MURRAY | NY MANIFEST | Higher | 725, 0.137, SW |
| H39 | CONSOLIDATED EDISON | MYRTLE BLVD & MURRAY | E MANIFEST | Higher | 725, 0.137, SW |

## MAPPED SITES SUMMARY

Target Property Address:
1 VINE ST
LARCHMONT, NY 10538

Click on Map ID to see full detail.

| MAP ID | SITE NAME | ADDRESS | DATABASE ACRONYMS | RELATIVE ELEVATION | DIST (ft. & mi.) DIRECTION |
|---|---|---|---|---|---|
| H40 | CON EDISON | MYRTLE BLVD & MURRAY | NJ MANIFEST | Higher | 725, 0.137, SW |
| H41 | CON EDISON | MYRTLE BLVD & MURRAY | RCRA NonGen / NLR, FINDS, ECHO | Higher | 725, 0.137, SW |
| G42 | HOFFMAN INVESTORS CO | 1890 PALMER AVENUE | NY LTANKS, NY LIENS | Higher | 748, 0.142, South |
| G43 | LARCHMONT PLAZA | 1890 PALMER AVE. | NY UST | Higher | 748, 0.142, South |
| G44 | NEW YORK STATE AUTHO | 147-199 CHATSWORTH A | RCRA-SQG, ECHO | Higher | 766, 0.145, SSW |
| I45 | LARCHMONT/PALMER COO | 1299 PALMER AVE | NY AST, NY Spills | Higher | 769, 0.146, ENE |
| I46 | LARCHMONT PALMER | 1299 PALMER AVENUE | NY UST | Higher | 769, 0.146, ENE |
| J47 | VERIZON NEW YORK INC | 5 FRANKLIN AVENUE | NY UST | Higher | 837, 0.159, SSE |
| J48 | BELL ATLANTIC | 5 FRANKLIN ST | NY LTANKS, NY AST, NY Spills | Higher | 837, 0.159, SSE |
| 49 | PRESTO RESIDNECE | 130 LAUREL AVE | NY LTANKS | Higher | 856, 0.162, NE |
| H50 | CON EDISON | MYRTLE BLVD &D CHATS | NJ MANIFEST | Higher | 859, 0.163, SW |
| H51 | CON EDISON | MYRTLE AVE & CHATSWO | NJ MANIFEST | Higher | 859, 0.163, SW |
| H52 | CON EDISON | MYRTLE BLVD &D CHATS | RCRA NonGen / NLR | Higher | 859, 0.163, SW |
| H53 | CON EDISON | MYRTLE AVE & CHATSWO | RCRA NonGen / NLR, FINDS, ECHO | Higher | 859, 0.163, SW |
| H54 | CON EDISON | MYRTLE AVE & CHATSWO | NY MANIFEST | Higher | 859, 0.163, SW |
| G55 | CON EDISON | PALMER AVE & CHATSWO | NY MANIFEST | Higher | 862, 0.163, South |
| G56 | CON EDISON MANHOLE: | CHATSWORTH AVE & PAL | RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST | Higher | 862, 0.163, South |
| H57 | CHATSWORTH GARDENS C | 14 NORTH CHATSWORTH | NY AST | Higher | 862, 0.163, WSW |
| K58 | NYS THRUWAY MAINTENA | I-95 EXIT 17 OFF NEW | RCRA NonGen / NLR | Higher | 870, 0.165, SSW |
| G59 | HOWELL ASSOCIATES | 132 CHATSWORTH AVENU | NY AST | Higher | 880, 0.167, SSW |
| G60 | SPILL NUMBER 8906916 | 132 CHATSWORTH AVE | NY LTANKS | Higher | 880, 0.167, SSW |
| G61 | EXXON | 124 CHATSWORTH AVE | UST FINDER RELEASE | Higher | 900, 0.170, SSW |
| G62 | THE BANK OF NEW YORK | 124 CHATSWORTH AVE | NY UST | Higher | 900, 0.170, SSW |
| G63 | BANK OF NEW YORK | 124 CHATSWORTH AVE. | NY LTANKS | Higher | 900, 0.170, SSW |
| L64 | CHATSWORTH CLEANERS | 120 CHATSWORTH AVE | RCRA-VSQG, US AIRS, FINDS, NY DRYCLEANERS, NY... | Higher | 916, 0.173, South |
| J65 | MOBIL OIL CORP SS D3 | 107 CHATSWORTH AVE | RCRA-LQG, FINDS, ECHO, NY MANIFEST | Higher | 933, 0.177, South |
| J66 | DOM'S CAR CARE CENTE | 107 CHATSWORTH AVENU | NY UST | Higher | 933, 0.177, South |
| L67 | CON EDISON - ELECTRI | 1906 PALMER AVE | E MANIFEST | Higher | 948, 0.180, South |
| M68 | CON EDISON | CHATSWORTH AVE & WAS | NY MANIFEST | Higher | 957, 0.181, WSW |
| M69 | CONSOLIDATED EDISON | WASHINGTON & N CHATS | NY MANIFEST | Higher | 957, 0.181, WSW |
| N70 | CON EDISON - SERVICE | MURRAY AVE & EDGEWOO | NY MANIFEST | Higher | 957, 0.181, NW |
| N71 | CON EDISON - SERVICE | MURRAY AVE & EDGEWOO | RCRA NonGen / NLR | Higher | 957, 0.181, NW |
| L72 | EMBASSY CLEANERS | 1908 PALMER AVE | RCRA NonGen / NLR, US AIRS, NY MANIFEST | Higher | 960, 0.182, South |
| L73 | EMBASSY CLEANERS | 1908 PALMER AVENUE | NY DRYCLEANERS | Higher | 960, 0.182, South |
| 74 | CON EDISON POLE W10 | HALL AVE & CONCORD A | RCRA NonGen / NLR, NY MANIFEST | Lower | 966, 0.183, ESE |
| M75 | 16 NORTH CHATSWORTH | 16 NORTH CHATSWORTH | NY UST, NY AST | Higher | 977, 0.185, WSW |
| L76 | DUTCH GIRL PROFESSIO | 1912 PALMER AVE | RCRA NonGen / NLR, FINDS, ECHO | Higher | 1007, 0.191, South |
| M77 | LARCHMONT HILLS OWNE | 17 NORTH CHATSWORTH | NY AST | Higher | 1019, 0.193, SW |
| K78 | DONALD RITACCO & CO | 7-11 NORTH AVE | RCRA NonGen / NLR, NY MANIFEST | Higher | 1023, 0.194, SSW |

## MAPPED SITES SUMMARY

Target Property Address:
1 VINE ST
LARCHMONT, NY 10538

Click on Map ID to see full detail.

| MAP ID | SITE NAME | ADDRESS | DATABASE ACRONYMS | RELATIVE ELEVATION | DIST (ft. & mi.) DIRECTION |
|---|---|---|---|---|---|
| L79 | LARCH REALTY CORP | 1923/1925 PALMER AV | NY UST | Higher | 1038, 0.197, SSW |
| L80 | LARCH REALTY CORP PR | 1925 PALMER AVE | NY LTANKS | Higher | 1051, 0.199, SSW |
| M81 | CONSOLIDATED EDISON | 21 N CHATSWORTH AVE | E MANIFEST | Higher | 1079, 0.204, WSW |
| M82 | 21 NORTH CHATSWORTH | 21 NORTH CHATSWORTH | NY UST | Higher | 1079, 0.204, WSW |
| O83 | 172 MYRTLE BLVD. APT | 172 MYRTLE BOULEVARD | NY AST | Higher | 1085, 0.205, SW |
| L84 | CITIBANK #10658 | 1920 PALMER AVE | RCRA-LQG | Higher | 1094, 0.207, South |
| P85 | FORLANI | 15-17 HILLCREST AVE | NY LTANKS | Higher | 1147, 0.217, North |
| 86 | MOONEY ED RESIDENCE | 22 CARLEON AVE | RCRA NonGen / NLR, FINDS, ECHO | Lower | 1163, 0.220, East |
| Q87 | CON EDISON | 6 OVERLOOK TER | RCRA NonGen / NLR, NY MANIFEST | Higher | 1195, 0.226, West |
| Q88 | CON EDISON GAS DRIP | 6 OVERLOOK TERR GAS | RCRA NonGen / NLR | Higher | 1195, 0.226, West |
| R89 | PARK PLAZA LARCHMONT | 3,5,7 EAST AVENUE | NY UST, NY AST | Higher | 1200, 0.227, SSW |
| M90 | CARLSHIRE TENANTS IN | 1-3 WASHINGTON SQUAR | NY AST | Higher | 1213, 0.230, WSW |
| M91 | CARLSHIRE TENANTS IN | 1-3 WASHINGTON SQUAR | NY UST | Higher | 1213, 0.230, WSW |
| R92 | THE KEYSTONE | 76 WENDT AVENUE | NY AST | Higher | 1213, 0.230, South |
| O93 | LARCHMONT TERRACE CO | 2 WASHINGTON SQUARE | NY UST | Higher | 1223, 0.232, SW |
| P94 | VALKENBURGH HOME | 47 MAPLE HILL DRIVE | NY LTANKS | Higher | 1263, 0.239, NNW |
| 95 | CON EDISON - OVERHEA | 6 VIRGINIA PL | NY Spills, NY MANIFEST | Lower | 1288, 0.244, ESE |
| O96 | CON EDISON SERVICE B | 178 MYRTLE BLVD | RCRA NonGen / NLR, NY MANIFEST | Lower | 1288, 0.244, SW |
| S97 | SPILL NUMBER 9910464 | 116 LAUREL AVE | NY LTANKS | Higher | 1312, 0.248, NE |
| 98 | COMMERCIAL PROPERTY | 35 NORTH CHATSWORTH | NY LTANKS | Lower | 1326, 0.251, WSW |
| T99 | RESIDENCE | 60 MAPLE HILL DR | NY LTANKS | Higher | 1326, 0.251, NNW |
| U100 | SPILL NUMBER 0107991 | 21 EDGEWOOD AVE | NY LTANKS | Higher | 1335, 0.253, NNE |
| V101 | RESI:BISNO | 53 HILLSIDE RD | NY LTANKS | Higher | 1353, 0.256, NW |
| U102 | REISMAN RESIDENCE | 24 EDGEWOOD AVE | NY LTANKS | Higher | 1362, 0.258, NNE |
| S103 | SPILL NUMBER 9910463 | 114 LAUREL AVE | NY LTANKS | Higher | 1372, 0.260, NE |
| W104 | RESIDENCE | 9 SUMMIT AVE | NY LTANKS | Higher | 1387, 0.263, SE |
| R105 | WACHOVIA BANK | 1940 PALMER AVE | NY LTANKS | Higher | 1392, 0.264, SSW |
| 106 | SPILL NUMBER 9806441 | 26 HILLSIDE ROAD | NY LTANKS | Higher | 1418, 0.269, WNW |
| 107 | SPILL NUMBER 9903173 | 26 SUMMITT AVE | NY LTANKS | Higher | 1431, 0.271, SSE |
| 108 | PRIVATE RESIDENCE | 125 MURRAY AVE | NY LTANKS | Higher | 1451, 0.275, NW |
| T109 | RESIDENCE | 8 ORSINI DRIVE | NY LTANKS | Higher | 1475, 0.279, NNW |
| 110 | YAHIA RESIDENCE | 17 HALL AVE | NY LTANKS | Lower | 1504, 0.285, ESE |
| 111 | CARRIER RESIDENCE | 45 CARLEON AV | NY LTANKS | Higher | 1517, 0.287, East |
| V112 | ALPERT HOME | 80 LOOKOUT CIRCLE | NY LTANKS | Higher | 1525, 0.289, WNW |
| W113 | SPILL NUMBER 0011319 | 14 HALL AVE | NY LTANKS | Lower | 1542, 0.292, SE |
| X114 | BLONDIE'S TREEHOUSE | 21 NORTH AVE | NY LTANKS | Lower | 1588, 0.301, SSW |
| X115 | SPILL NUMBER 9914491 | 21 NORTH AVE | NY LTANKS | Lower | 1588, 0.301, SSW |
| Y116 | PHIL LEBOWITZ | 12 ORSINI DRIVE | NY LTANKS | Higher | 1597, 0.302, NNW |
| X117 | UNITED ARTISTS THEAT | 1975 PALMER AVE. | NY LTANKS, NY Spills | Higher | 1653, 0.313, SSW |

## MAPPED SITES SUMMARY

Target Property Address:
1 VINE ST
LARCHMONT, NY 10538

Click on Map ID to see full detail.

| MAP ID | SITE NAME | ADDRESS | DATABASE ACRONYMS | RELATIVE ELEVATION | DIST (ft. & mi.) DIRECTION |
|---|---|---|---|---|---|
| 118 | YOUNG HOME | 6 ROCKHILL TERRACE | NY LTANKS | Higher | 1689, 0.320, South |
| 119 | DILIETO HOME | 104 LAUREL AVE | NY LTANKS | Higher | 1690, 0.320, NE |
| Z120 | VERNER RES | 46 ECHO LN | NY LTANKS | Higher | 1710, 0.324, NW |
| AA121 | LARCHMONT AUTO GARAG | 5TH AV & MADISON | NY LTANKS | Lower | 1716, 0.325, WSW |
| AB122 | GRECO DWELLING | 212 LARCHMONT AVE | NY LTANKS | Higher | 1718, 0.325, South |
| AB123 | PRIVATE DWELLING | 212 LARCHMONT AVE | NY LTANKS | Higher | 1718, 0.325, South |
| Y124 | CONDON HOME | 16 ORSINI DRIVE | NY LTANKS | Higher | 1719, 0.326, NNW |
| AC125 | LEVY | 7 ROOSEVELT AV | NY LTANKS | Higher | 1730, 0.328, SE |
| AD126 | MOCCIA - TTF | 23 DANTE ST | NY LTANKS | Higher | 1740, 0.330, North |
| 127 | SPILL NUMBER 9913035 | 54 LOOKOUT CIRCLE | NY LTANKS | Higher | 1749, 0.331, WNW |
| AC128 | BEN BEDERSON TTF | 8 HALL AVE | NY LTANKS | Lower | 1774, 0.336, SE |
| AD129 | SLATTERY RESIDENCE | 25 DANTE ST | NY LTANKS | Higher | 1792, 0.339, North |
| 130 | SPILL NUMBER 0205284 | 60 CHATSWORTH AVE | NY LTANKS | Higher | 1814, 0.344, SSE |
| 131 | RESIDENCE | 41 MYRTLE BLVD | NY LTANKS | Higher | 1827, 0.346, NNE |
| Z132 | PRIVATE RESIDENCE | 23 MAPLEWOOD STREET | NY LTANKS | Higher | 1851, 0.351, NW |
| 133 | BIRDVELL RESIDENCE | 4 FOREST PARK AVE | NY LTANKS | Lower | 1871, 0.354, ESE |
| AE134 | MARTIN RES | 16 FOREST PARK AVE | NY LTANKS | Lower | 1883, 0.357, SE |
| AA135 | MAMARONECK MANOR | 636 FIFTH AVENUE | NY BROWNFIELDS | Lower | 1886, 0.357, WSW |
| AF136 | SPRINGER RESIDENCE | 200 LARCHMONT AVE | NY LTANKS | Higher | 1895, 0.359, South |
| 137 | MOSER RESIDENCE | 161 MURRAY AVE | NY LTANKS | Higher | 1905, 0.361, NW |
| AF138 | GLASS RESIDENCE | 5 IDEN AVE | NY LTANKS | Higher | 1934, 0.366, South |
| 139 | ELEMENTARY SCHOOL | 125 WEAVER STREET | NY LTANKS, NY Spills | Higher | 1974, 0.374, NE |
| AE140 | RESIDENCE | 15 FOREST PARK AVE | NY LTANKS | Lower | 2026, 0.384, SE |
| 141 | LARCHMONT/MAMARONECK | 41 MAXWELL AVENUE(LO | NY SWF/LF | Lower | 2040, 0.386, SW |
| AG142 | ST. JOHN'S | 280 WEAVER ST. | NY LTANKS | Higher | 2049, 0.388, NNE |
| 143 | RESIDENCE | 1 FRANCE PLACE | NY LTANKS | Higher | 2054, 0.389, West |
| AH144 | GARRY RESIDENCE | 7 MEADOW PL | NY LTANKS | Higher | 2059, 0.390, East |
| AH145 | SPILL NUMBER 0106394 | 110 CARLEON AVE | NY LTANKS | Lower | 2078, 0.394, East |
| AI146 | PRIVATE RES | 41 MAPLEWOOD ST | NY LTANKS | Higher | 2114, 0.400, NW |
| 147 | BEZ - TTF | 72 HOWELL AVE | NY LTANKS | Lower | 2140, 0.405, ENE |
| AJ148 | RESIDENCE | 2 CAMBRIDGE COURT | NY LTANKS | Lower | 2149, 0.407, ESE |
| AJ149 | ESTATE OF LANDES | 10 CAMBRIDGE COURT | NY LTANKS | Lower | 2151, 0.407, SE |
| AK150 | SPILL NUMBER 9905950 | 10 ROCHELLE RD | NY LTANKS | Higher | 2171, 0.411, West |
| AK151 | SPILL NUMBER 9911157 | 10 ROCHELLE RD | NY LTANKS | Higher | 2171, 0.411, West |
| 152 | SPILL NUMBER 8900768 | 4 WAKEMAN PLACE | NY LTANKS | Lower | 2179, 0.413, South |
| AL153 | CITY PARK SERV BLUEB | 613 5TH AVE | UST FINDER RELEASE | Lower | 2192, 0.415, SW |
| AK154 | PVT DWELLING | 13 ROCHELLE ROAD | NY LTANKS | Higher | 2211, 0.419, West |
| AM155 | LARCHMONT AVE CHURCH | 60 FOREST PARK AVE | NY LTANKS, NY Spills | Higher | 2214, 0.419, SSE |
| 156 | SUTIN RESIDENCE | 21 COPLEY RD | NY LTANKS, NY Spills | Lower | 2219, 0.420, East |

## MAPPED SITES SUMMARY

Target Property Address:
1 VINE ST
LARCHMONT, NY 10538

Click on Map ID to see full detail.

| MAP ID | SITE NAME | ADDRESS | DATABASE ACRONYMS | RELATIVE ELEVATION | DIST (ft. & mi.) DIRECTION |
|---|---|---|---|---|---|
| AN157 | SPILL NUMBER 0313036 | 7 HARMONY DRIVE | NY LTANKS | Lower | 2221, 0.421, ESE |
| 158 | TTF | 12 COOPER LANE | NY LTANKS | Higher | 2223, 0.421, NNE |
| AG159 | DALEY RESIDENCE | 2 HEATHER LANE | NY LTANKS | Higher | 2235, 0.423, NNE |
| AN160 | FORECLOSURE - TTF | 18 ALDEN RD | NY LTANKS | Lower | 2264, 0.429, ESE |
| AJ161 | RESIDENCE | 3 CAMBRIDGE CT | NY LTANKS | Lower | 2265, 0.429, ESE |
| AI162 | 104 NORTH CHATSWORTH | 104 NORTH CHATSWORTH | NY LTANKS | Higher | 2292, 0.434, NW |
| AL163 | NYS THRUWAY | 629 FIFTH AVE | UST FINDER RELEASE | Lower | 2296, 0.435, SW |
| 164 | SPILL NUMBER 0201523 | 101 NORTH CHATSWORTH | NY LTANKS | Higher | 2355, 0.446, NW |
| AM165 | DURON RESIDENCE | 174 LARCHMONT AVE | NY LTANKS | Lower | 2375, 0.450, SSE |
| AO166 | FITCH RESIDENCE | 3 WILDWOOD ROAD | NY LTANKS | Higher | 2388, 0.452, WNW |
| 167 | KUNREUTHER - TTF | 17 BONNETT AVENUE | NY LTANKS | Lower | 2390, 0.453, SE |
| AJ168 | RESIDENCE | 10 NASSAU RD | NY LTANKS | Lower | 2408, 0.456, ESE |
| AP169 | DEPT PUBLIC WORKS | MAXWELL AVE | NY LTANKS | Lower | 2420, 0.458, SW |
| AP170 | MAMARONECK DPW | MAXWELL ST | NY LTANKS | Lower | 2420, 0.458, SW |
| AQ171 | VACANT BUILDING | 615 5TH AVE | UST FINDER RELEASE | Lower | 2443, 0.463, WSW |
| AR172 | PRIVATE HOME | 259 BARNARD RD | NY LTANKS | Higher | 2457, 0.465, West |
| 173 | APT BLD | 11 ALDEN RD | NY LTANKS | Lower | 2510, 0.475, ESE |
| AO174 | SPILL NUMBER 9812365 | 1 SETON RD | NY LTANKS | Higher | 2513, 0.476, WNW |
| 175 | MARMON - TTF | 36 COLONIAL AVE | NY LTANKS | Higher | 2515, 0.476, NNW |
| AR176 | SPILL NUMBER 0108033 | 260 BARNARD RD | NY LTANKS | Higher | 2523, 0.478, West |
| 177 | CHATSWORTH COAL AND | 2101, 2103 AND 2101- | NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS | Lower | 2525, 0.478, SW |
| 178 | LEVINSON RESIDENCE | 35 MAYHEW AVE | NY LTANKS | Lower | 2525, 0.478, South |
| 179 | ROBERT TRIPPETT | 4 STUYVESANT AVE | NY LTANKS | Lower | 2530, 0.479, SSE |
| 180 | WEBERS HOME | 76 PINEBROOK DRIVE | NY LTANKS | Lower | 2573, 0.487, SSW |
| 181 | BALLARD RESIDENCE | 4 ACORN LN | NY LTANKS | Higher | 2582, 0.489, West |
| AQ182 | PARISSI TTF | 608 5TH AVE | NY LTANKS | Lower | 2590, 0.491, WSW |
| 183 | SPILL NUMBER 9901044 | 193 ROCKING STONE AV | NY LTANKS | Higher | 2607, 0.494, WNW |
| 184 | COTUGNO RESIDENCE | 53 WEST GARDEN RD | NY LTANKS | Higher | 2619, 0.496, NNE |
| 185 | PBS | 1 ADDISON ST | NY LTANKS, NY AST | Higher | 2621, 0.496, SE |
| 186 | RENZ RESIDENCE | 44 VALLEY ROAD | NY LTANKS | Higher | 2624, 0.497, NW |

# EXECUTIVE SUMMARY

**TARGET PROPERTY SEARCH RESULTS**

The target property was identified in the following records. For more information on this property see page 9 of the attached EDR Radius Map report:

| Site | Database(s) | EPA ID |
|---|---|---|
| J & F CHATSWORTH AUT<br>1 VINE ST<br>LARCHMONT, NY 10538 | RCRA-SQG<br>EPA ID:: NYD982718272<br>E MANIFEST<br>NY MANIFEST<br>EPA ID: NYD982718272<br>NJ MANIFEST<br>EPA Id: NYD982718272 | NYD982718272 |
| MAGIC TOUCH CLEANERS<br>1 VINE ST<br>LARCHMONT, NY 10538 | EDR Hist Cleaner | N/A |
| CHATSWORTH GARAGE IN<br>1 VINE ST<br>LARCHMONT, NY 10538 | EDR Hist Auto | N/A |
| MARISIERO INC.<br>1-5 VINE STREET<br>LARCHMONT, NY | NY LTANKS<br>Spill Number/Closed Date: 9102813 / 1997-11-14<br>Site ID: 88022<br>Spill Date: 1991-06-10 | N/A |
| JS CHADWORTHS<br>1 VINE ST<br>LARCHMONT, NY | NY Spills<br>Spill Number/Closed Date: 1501291 / 2015-07-08<br>Site ID: 507486<br>Spill Date: 2015-05-05 | N/A |
| J & F CHATSWORTH GAS<br>1 VINE STREET<br>LARCHMONT, NY 0 | UST FINDER RELEASE | N/A |
| J & F CHATSWORTH LTD<br>1 VINE STREET<br>LARCHMONT, NY 10538 | NY UST<br>Database: WESTCHESTER CO. UST, Date of Government Version: 01/28/2026<br>Status: 3. Closed - Removed<br>Id/Status:: 3-174394<br>Site Status: Active<br>NY AST<br>Database: WESTCHESTER CO. AST, Date of Government Version: 01/28/2026<br>Status: 1. In-Service | N/A |

# EXECUTIVE SUMMARY

PBS Number: 3-174394

| | | |
|---|---|---|
| JF CHATSWORTH<br>1 VINE STREET<br>LARCHMONT, NY | NY LTANKS<br>Spill Number/Closed Date: 9410303 / 2005-02-27<br>Site ID: 64161<br>Spill Date: 1994-11-02<br><br>NY Spills<br>Spill Number/Closed Date: 9413519 / 1995-01-23<br>Site ID: 64162<br>Spill Date: 1995-01-10 | N/A |
| J & F CHATSWORTH AUT<br>3 VINE ST<br>LARCHMONT, NY 10538 | US AIRS<br>Database: US AIRS MINOR, Date of Government Version: 10/12/2016<br>EPA plant ID:: 110038456514<br><br>FINDS<br>Registry ID:: 110019224409<br><br>ECHO<br>Registry ID: 110019224409 | N/A |
| J & F CHATSWORTH AUT<br>3 VINE ST<br>LARCHMONT, NY 10538 | NY AIRS<br>DEC Id: 3553200136 | N/A |
| MAGIC TOUCH CLEANERS<br>5 VINE STREET<br>LARCHMONT, NY 10538 | FINDS<br>Registry ID:: 110004313975<br><br>ECHO<br>Registry ID: 110004313975 | N/A |
| KIM KWUNG<br>5 VINE ST<br>LARCHMONT, NY 10538 | EDR Hist Cleaner | N/A |
| MAGIC TOUCH CLEANERS<br>5 VINE ST<br>LARCHMONT, NY 10538 | RCRA NonGen / NLR<br>EPA ID:: NY0000204958<br><br>ICIS<br>FRS ID:: 110004313975<br><br>US AIRS<br>Database: US AIRS MINOR, Date of Government Version: 10/12/2016<br>EPA plant ID:: 110004420564<br><br>NY DRYCLEANERS<br>Facility Id: 3-5532-00313<br><br>NY MANIFEST<br>EPA ID: NY0000204958<br>EPA ID: NYD000204958 | NY0000204958 |

# EXECUTIVE SUMMARY

**DATABASES WITH NO MAPPED SITES**

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

**STANDARD ENVIRONMENTAL RECORDS**

***Lists of Federal NPL (Superfund) sites***

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

***Lists of Federal Delisted NPL sites***

Delisted NPL ---------- National Priority List Deletions

***Lists of Federal sites subject to CERCLA removals and CERCLA orders***

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

***Lists of Federal CERCLA sites with NFRAP***

SEMS-ARCHIVE ---------- Superfund Enterprise Management System Archive

***Lists of Federal RCRA facilities undergoing Corrective Action***

CORRACTS ---------- Corrective Action Report

***Lists of Federal RCRA TSD facilities***

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

***Federal institutional controls / engineering controls registries***

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

***Federal ERNS list***

ERNS ---------- Emergency Response Notification System

***Lists of state- and tribal hazardous waste facilities***

NY SHWS ---------- Inactive Hazardous Waste Disposal Sites in New York State

***Lists of state and tribal leaking storage tanks***

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

NY HIST LTANKS - Listing of Leaking Storage Tanks

***Lists of state and tribal registered storage tanks***

FEMA UST - Underground Storage Tank Listing
NY CBS UST - Chemical Bulk Storage Database
NY MOSF UST - Major Oil Storage Facilities Database
NY MOSF - Major Oil Storage Facility Site Listing
NY CBS - Chemical Bulk Storage Site Listing
NY CBS AST - Chemical Bulk Storage Database
NY MOSF AST - Major Oil Storage Facilities Database
INDIAN UST - Underground Storage Tanks on Indian Land
NY TANKS - Storage Tank Faciliy Listing

***State and tribal institutional control / engineering control registries***

NY RES DECL - Restrictive Declarations Listing

***Lists of state and tribal voluntary cleanup sites***

NY VCP - Voluntary Cleanup Agreements
INDIAN VCP - Voluntary Cleanup Priority Listing

***Lists of state and tribal brownfield sites***

NY ERP - Environmental Restoration Program Listing

**ADDITIONAL ENVIRONMENTAL RECORDS**

***Local Brownfield lists***

US BROWNFIELDS - A Listing of Brownfields Sites

***Local Lists of Landfill / Solid Waste Disposal Sites***

NY SWRCY - Registered Recycling Facility List
NY SWTIRE - Registered Waste Tire Storage & Facility List
INDIAN ODI - Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 - Torres Martinez Reservation Illegal Dump Site Locations
ODI - Open Dump Inventory
IHS OPEN DUMPS - Open Dumps on Indian Land

***Local Lists of Hazardous waste / Contaminated Sites***

US HIST CDL - Delisted National Clandestine Laboratory Register
NY DEL SHWS - Delisted Registry Sites
US CDL - National Clandestine Laboratory Register

***Local Lists of Registered Storage Tanks***

NY HIST UST - Historical Petroleum Bulk Storage Database
NY HIST AST - Historical Petroleum Bulk Storage Database

***Local Land Records***

LIENS 2 - CERCLA Lien Information

# EXECUTIVE SUMMARY

***Records of Emergency Release Reports***

| | |
|---|---|
| HMIRS | Hazardous Materials Information Reporting System |
| NY Hist Spills | SPILLS Database |
| NY SPILLS 90 | SPILLS 90 data from FirstSearch |
| NY SPILLS 80 | SPILLS 80 data from FirstSearch |

***Other Ascertainable Records***

| | |
|---|---|
| FUDS | Formerly Used Defense Sites |
| DOD | Department of Defense Sites |
| SCRD DRYCLEANERS | State Coalition for Remediation of Drycleaners Listing |
| US FIN ASSUR | Financial Assurance Information |
| EPA WATCH LIST | EPA WATCH LIST |
| 2020 COR ACTION | 2020 Corrective Action Program List |
| TSCA | Toxic Substances Control Act |
| TRIS | Toxic Chemical Release Inventory System |
| SSTS | Section 7 Tracking Systems |
| ROD | Records Of Decision |
| RMP | Risk Management Plans |
| RAATS | RCRA Administrative Action Tracking System |
| PRP | Potentially Responsible Parties |
| PADS | PCB Activity Database System |
| FTTS | FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act) |
| MLTS | Material Licensing Tracking System |
| COAL ASH DOE | Steam-Electric Plant Operation Data |
| COAL ASH EPA | Coal Combustion Residues Surface Impoundments List |
| PCB TRANSFORMER | PCB Transformer Registration Database |
| RADINFO | Radiation Information Database |
| HIST FTTS | FIFRA/TSCA Tracking System Administrative Case Listing |
| DOT OPS | Incident and Accident Data |
| CONSENT | Superfund (CERCLA) Consent Decrees |
| INDIAN RESERV | Indian Reservations |
| FUSRAP | Formerly Utilized Sites Remedial Action Program |
| UMTRA | Uranium Mill Tailings Sites |
| LEAD SMELTERS | Lead Smelter Sites |
| US MINES | Mines Master Index File |
| MINES MRDS | Mineral Resources Data System |
| ABANDONED MINES | Abandoned Mines |
| UXO | Unexploded Ordnance Sites |
| DOCKET HWC | Hazardous Waste Compliance Docket Listing |
| FUELS PROGRAM | EPA Fuels Program Registered Listing |
| PFAS NPL | Superfund Sites with PFAS Detections Information |
| PFAS FEDERAL SITES | Federal Sites PFAS Information |
| PFAS TRIS | List of PFAS Added to the TRI |
| PFAS TSCA | PFAS Manufacture and Imports Information |
| PFAS RCRA MANIFEST | PFAS Transfers Identified In the RCRA Database Listing |
| PFAS ATSDR | PFAS Contamination Site Location Listing |
| PFAS WQP | Ambient Environmental Sampling for PFAS |
| PFAS PROJECT | NORTHEASTERN UNIVERSITY PFAS PROJECT |
| PFAS NPDES | Clean Water Act Discharge Monitoring Information |
| PFAS ECHO | Facilities in Industries that May Be Handling PFAS Listing |
| PFAS ECHO FIRE TRAIN | Facilities in Industries that May Be Handling PFAS Listing |

PFAS PT 139 AIRPORT All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC Aqueous Foam Related Incidents Listing
BIOSOLIDS ICIS-NPDES Biosolids Facility Data
UST FINDER UST Finder Database
NY PFAS PFAS Contamination Site Location Listing
NY COAL ASH Coal Ash Disposal Site Listing
NY E DESIGNATION E DESIGNATION SITE LISTING
NY Financial Assurance Financial Assurance Information Listing
NY HSWDS Hazardous Substance Waste Disposal Site Inventory
NY LEAD Lead-based Paint Testing Results
NY SPDES State Pollutant Discharge Elimination System
NY VAPOR REOPENED Vapor Intrusion Legacy Site List
NY UIC Underground Injection Control Wells
NY COOLING TOWERS Registered Cooling Towers
NY MGP Manufactured Gas Plants Listing
NY ILI New York State Inactive Landfill Initiative
NY NYC OER OER Cleanup Sites Listing
NY NYC LAND USE New York City Land Use Information
ABAND AIRFIELDS Abandoned & Little-Known Airfields Listing
DRYCLEANERS Drycleaner Facility Listing

**EDR HIGH RISK HISTORICAL RECORDS**

***EDR Exclusive Records***

EDR MGP EDR Proprietary Manufactured Gas Plants

**EDR RECOVERED GOVERNMENT ARCHIVES**

***Exclusive Recovered Govt. Archives***

NY RGA HWS Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF Recovered Government Archive Solid Waste Facilities List

**SURROUNDING SITES: SEARCH RESULTS**

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

**STANDARD ENVIRONMENTAL RECORDS**

***Lists of Federal RCRA generators***

# EXECUTIVE SUMMARY

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 11/30/2025 has revealed that there are 2 RCRA-LQG sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***MOBIL OIL CORP SS D3*** EPA ID:: NYD986958171 | ***107 CHATSWORTH AVE*** | ***S 1/8 - 1/4 (0.177 mi.)*** | ***J65*** | ***240*** |
| CITIBANK #10658 EPA ID:: NYR000265116 | 1920 PALMER AVE | S 1/8 - 1/4 (0.207 mi.) | L84 | 294 |

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 11/30/2025 has revealed that there are 3 RCRA-SQG sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***NEW YORK STATE AUTHO*** EPA ID:: NYR000271593 | ***1 RAILROAD WAY*** | ***S 0 - 1/8 (0.063 mi.)*** | ***C17*** | ***81*** |
| ***EMBASSY CLEANERS*** EPA ID:: NYD986995249 | ***1895 PALMER AVE*** | ***S 0 - 1/8 (0.122 mi.)*** | ***G31*** | ***96*** |
| ***NEW YORK STATE AUTHO*** EPA ID:: NYR000271585 | ***147-199 CHATSWORTH A*** | ***SSW 1/8 - 1/4 (0.145 mi.)*** | ***G44*** | ***169*** |

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 11/30/2025 has revealed that there is 1 RCRA-VSQG site within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***CHATSWORTH CLEANERS*** EPA ID:: NY0000363101 | ***120 CHATSWORTH AVE*** | ***S 1/8 - 1/4 (0.173 mi.)*** | ***L64*** | ***211*** |

# EXECUTIVE SUMMARY

***Lists of state and tribal landfills and solid waste disposal facilities***

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the  list.

A review of the NY SWF/LF list, as provided by EDR, and dated 12/09/2025 has revealed that there is 1 NY SWF/LF site  within approximately  0.5 miles of the target property.

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| LARCHMONT/MAMARONECK | 41 MAXWELL AVENUE(LO | SW 1/4 - 1/2 (0.386 mi.) | 141 | 380 |

***Lists of state and tribal leaking storage tanks***

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 10/30/2025 has revealed that there are 97 NY LTANKS sites within approximately  0.5 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| GLOBE RESTAURANT<br>Spill Number/Closed Date: 0511734 / 2006-02-21<br>Site ID: 357947<br>Spill Date: 2006-01-11 | 1879 PALMER AVE | S 0 - 1/8 (0.096 mi.) | C20 | 86 |
| ***PATRICIA GARDENS***<br>Spill Number/Closed Date: 9802511 / 1999-02-08<br>Site ID: 200510<br>Spill Date: 1998-05-26 | ***1825 PALMER AVE*** | ***ESE 0 - 1/8 (0.100 mi.)*** | ***D21*** | ***87*** |
| REAR OF 1880 PALMER<br>Spill Number/Closed Date: 9602833 / 1996-05-29<br>Site ID: 292396<br>Spill Date: 1996-05-29 | FRANKLYN AVE | SSE 0 - 1/8 (0.115 mi.) | F29 | 95 |
| BROMPTON APTS.<br>Spill Number/Closed Date: 9112775 / 1992-03-17<br>Site ID: 93770<br>Spill Date: 1992-03-16 | 1880 PALMER AVE. | S 0 - 1/8 (0.123 mi.) | G32 | 151 |
| HOFFMANS<br>Spill Number/Closed Date: 9211944 / 1993-01-21<br>Site ID: 111285<br>Spill Date: 1993-01-19 | 1850 PALMER AVE. | SE 1/8 - 1/4 (0.126 mi.) | F35 | 154 |
| ***HOFFMAN INVESTORS CO***<br>Spill Number/Closed Date: 9211942 / 2000-03-09<br>Site ID: 104436<br>Spill Date: 1993-01-19 | ***1890 PALMER AVENUE*** | ***S 1/8 - 1/4 (0.142 mi.)*** | ***G42*** | ***165*** |
| ***BELL ATLANTIC***<br>Spill Number/Closed Date: 9810030 / 1998-11-09<br>Site ID: 245767 | ***5 FRANKLIN ST*** | ***SSE 1/8 - 1/4 (0.159 mi.)*** | ***J48*** | ***180*** |

| | | | | |
|---|---|---|---|---|
| Spill Date: 1998-11-06 | | | | |
| PRESTO RESIDNECE<br>Spill Number/Closed Date: 1100421 / 2011-09-15<br>Site ID: 447824<br>Spill Date: 2011-04-12 | 130 LAUREL AVE | NE 1/8 - 1/4 (0.162 mi.) | 49 | 184 |
| SPILL NUMBER 8906916<br>Spill Number/Closed Date: 8906577 / 1992-07-30<br>Spill Number/Closed Date: 8906916 / 1992-07-30<br>Site ID: 275785<br>Site ID: 275786<br>Spill Date: 1989-10-04<br>Spill Date: 1989-10-09 | 132 CHATSWORTH AVE | SSW 1/8 - 1/4 (0.167 mi.) | G60 | 205 |
| BANK OF NEW YORK<br>Spill Number/Closed Date: 9011938 / 1993-02-23<br>Site ID: 276370<br>Spill Date: 1991-02-14 | 124 CHATSWORTH AVE. | SSW 1/8 - 1/4 (0.170 mi.) | G63 | 209 |
| LARCH REALTY CORP PR<br>Spill Number/Closed Date: 8801114 / 1997-12-01<br>Site ID: 108260<br>Spill Date: 1988-02-07 | 1925 PALMER AVE | SSW 1/8 - 1/4 (0.199 mi.) | L80 | 289 |
| FORLANI<br>Spill Number/Closed Date: 9804871 / 2004-12-07<br>Site ID: 120774<br>Spill Date: 1998-07-20 | 15-17 HILLCREST AVE | N 1/8 - 1/4 (0.217 mi.) | P85 | 296 |
| VALKENBURGH HOME<br>Spill Number/Closed Date: 0606523 / 2007-01-04<br>Site ID: 369884<br>Spill Date: 2006-09-07 | 47 MAPLE HILL DRIVE | NNW 1/8 - 1/4 (0.239 mi.) | P94 | 311 |
| SPILL NUMBER 9910464<br>Spill Number/Closed Date: 9910464 / 2000-02-10<br>Site ID: 283585<br>Spill Date: 1999-12-01 | 116 LAUREL AVE | NE 1/8 - 1/4 (0.248 mi.) | S97 | 317 |
| RESIDENCE<br>Spill Number/Closed Date: 9904648 / 1999-09-28<br>Site ID: 254123<br>Spill Date: 1999-07-19 | 60 MAPLE HILL DR | NNW 1/4 - 1/2 (0.251 mi.) | T99 | 321 |
| SPILL NUMBER 0107991<br>Spill Number/Closed Date: 0107991 / 2002-02-28<br>Site ID: 220664<br>Spill Date: 2001-11-06 | 21 EDGEWOOD AVE | NNE 1/4 - 1/2 (0.253 mi.) | U100 | 323 |
| RESI:BISNO<br>Spill Number/Closed Date: 0003197 / 2005-04-03<br>Site ID: 257812<br>Spill Date: 2000-06-14 | 53 HILLSIDE RD | NW 1/4 - 1/2 (0.256 mi.) | V101 | 324 |
| REISMAN RESIDENCE<br>Spill Number/Closed Date: 0800763 / 2008-07-08<br>Site ID: 396571<br>Spill Date: 2008-04-18 | 24 EDGEWOOD AVE | NNE 1/4 - 1/2 (0.258 mi.) | U102 | 325 |
| SPILL NUMBER 9910463<br>Spill Number/Closed Date: 9910463 / 2000-02-10<br>Site ID: 171857 | 114 LAUREL AVE | NE 1/4 - 1/2 (0.260 mi.) | S103 | 327 |

| | | | | |
|---|---|---|---|---|
| Spill Date: 1999-12-01 | | | | |
| RESIDENCE<br>Spill Number/Closed Date: 9702679 / 1997-08-08<br>Site ID: 229293<br>Spill Date: 1997-06-02 | 9 SUMMIT AVE | SE 1/4 - 1/2 (0.263 mi.) | W104 | 328 |
| WACHOVIA BANK<br>Spill Number/Closed Date: 0401512 / 2004-11-18<br>Site ID: 173845<br>Spill Date: 2004-05-12 | 1940 PALMER AVE | SSW 1/4 - 1/2 (0.264 mi.) | R105 | 329 |
| SPILL NUMBER 9806441<br>Spill Number/Closed Date: 9806441 / 1998-09-08<br>Site ID: 107995<br>Spill Date: 1998-08-25 | 26 HILLSIDE ROAD | WNW 1/4 - 1/2 (0.269 mi.) | 106 | 331 |
| SPILL NUMBER 9903173<br>Spill Number/Closed Date: 9903173 / 1999-07-27<br>Site ID: 66265<br>Spill Date: 1999-06-18 | 26 SUMMITT AVE | SSE 1/4 - 1/2 (0.271 mi.) | 107 | 332 |
| PRIVATE RESIDENCE<br>Spill Number/Closed Date: 0400156 / 2004-06-16<br>Site ID: 158874<br>Spill Date: 2004-04-06 | 125 MURRAY AVE | NW 1/4 - 1/2 (0.275 mi.) | 108 | 333 |
| RESIDENCE<br>Spill Number/Closed Date: 9312714 / 1995-01-19<br>Site ID: 99667<br>Spill Date: 1994-01-28 | 8 ORSINI DRIVE | NNW 1/4 - 1/2 (0.279 mi.) | T109 | 334 |
| CARRIER RESIDENCE<br>Spill Number/Closed Date: 0307038 / 2003-11-20<br>Site ID: 174655<br>Spill Date: 2003-10-03 | 45 CARLEON AV | E 1/4 - 1/2 (0.287 mi.) | 111 | 337 |
| ALPERT HOME<br>Spill Number/Closed Date: 0713708 / 2009-08-31<br>Site ID: 395508<br>Spill Date: 2008-03-27 | 80 LOOKOUT CIRCLE | WNW 1/4 - 1/2 (0.289 mi.) | V112 | 338 |
| PHIL LEBOWITZ<br>Spill Number/Closed Date: 1309250 / 2014-03-17<br>Site ID: 490038<br>Spill Date: 2013-12-18 | 12 ORSINI DRIVE | NNW 1/4 - 1/2 (0.302 mi.) | Y116 | 343 |
| ***UNITED ARTISTS THEAT***<br>Spill Number/Closed Date: 9401111 / 2001-03-12<br>Site ID: 323532<br>Spill Date: 1994-04-22 | ***1975 PALMER AVE.*** | ***SSW 1/4 - 1/2 (0.313 mi.)*** | ***X117*** | ***345*** |
| YOUNG HOME<br>Spill Number/Closed Date: 0606153 / 2012-08-17<br>Site ID: 369457<br>Spill Date: 2006-08-29 | 6 ROCKHILL TERRACE | S 1/4 - 1/2 (0.320 mi.) | 118 | 347 |
| DILIETO HOME<br>Spill Number/Closed Date: 0502224 / 2006-08-11<br>Site ID: 346541<br>Spill Date: 2005-05-25 | 104 LAUREL AVE | NE 1/4 - 1/2 (0.320 mi.) | 119 | 349 |
| VERNER RES | 46 ECHO LN | NW 1/4 - 1/2 (0.324 mi.) | Z120 | 350 |

Spill Number/Closed Date: 9802021 / 1998-06-15
Site ID: 160747
Spill Date: 1998-05-15

| | | | | |
|---|---|---|---|---|
| GRECO DWELLING | 212 LARCHMONT AVE | S 1/4 - 1/2 (0.325 mi.) | AB122 | 353 |
| Spill Number/Closed Date: 1201664 / 2012-08-20<br>Site ID: 464387<br>Spill Date: 2012-05-21 | | | | |
| PRIVATE DWELLING | 212 LARCHMONT AVE | S 1/4 - 1/2 (0.325 mi.) | AB123 | 354 |
| Spill Number/Closed Date: 1201667 / 2012-08-20<br>Site ID: 464390<br>Spill Date: 2012-05-21 | | | | |
| CONDON HOME | 16 ORSINI DRIVE | NNW 1/4 - 1/2 (0.326 mi.) | Y124 | 355 |
| Spill Number/Closed Date: 0612662 / 2007-03-29<br>Site ID: 377553<br>Spill Date: 2007-02-22 | | | | |
| LEVY | 7 ROOSEVELT AV | SE 1/4 - 1/2 (0.328 mi.) | AC125 | 356 |
| Spill Number/Closed Date: 9601585 / 1996-06-12<br>Site ID: 215731<br>Spill Date: 1996-04-30 | | | | |
| MOCCIA - TTF | 23 DANTE ST | N 1/4 - 1/2 (0.330 mi.) | AD126 | 358 |
| Spill Number/Closed Date: 9906899 / 2000-01-10<br>Site ID: 299008<br>Spill Date: 1999-09-09 | | | | |
| SPILL NUMBER 9913035 | 54 LOOKOUT CIRCLE | WNW 1/4 - 1/2 (0.331 mi.) | 127 | 359 |
| Spill Number/Closed Date: 9913035 / 2000-06-01<br>Site ID: 289288<br>Spill Date: 2000-02-16 | | | | |
| SLATTERY RESIDENCE | 25 DANTE ST | N 1/4 - 1/2 (0.339 mi.) | AD129 | 362 |
| Spill Number/Closed Date: 0705870 / 2007-09-25<br>Site ID: 386276<br>Spill Date: 2007-08-23 | | | | |
| SPILL NUMBER 0205284 | 60 CHATSWORTH AVE | SSE 1/4 - 1/2 (0.344 mi.) | 130 | 363 |
| Spill Number/Closed Date: 0205284 / 2002-09-11<br>Site ID: 98006<br>Spill Date: 2002-08-20 | | | | |
| RESIDENCE | 41 MYRTLE BLVD | NNE 1/4 - 1/2 (0.346 mi.) | 131 | 364 |
| Spill Number/Closed Date: 0507572 / 2006-08-09<br>Site ID: 353041<br>Spill Date: 2005-09-23 | | | | |
| PRIVATE RESIDENCE | 23 MAPLEWOOD STREET | NW 1/4 - 1/2 (0.351 mi.) | Z132 | 366 |
| Spill Number/Closed Date: 0509152 / 2005-10-31<br>Spill Number/Closed Date: 0400048 / 2004-06-04<br>Site ID: 354880<br>Site ID: 316083<br>Spill Date: 2005-10-13<br>Spill Date: 2004-04-02 | | | | |
| SPRINGER RESIDENCE | 200 LARCHMONT AVE | S 1/4 - 1/2 (0.359 mi.) | AF136 | 373 |
| Spill Number/Closed Date: 0404212 / 2004-10-28<br>Site ID: 328692<br>Spill Date: 2004-07-20 | | | | |
| MOSER RESIDENCE | 161 MURRAY AVE | NW 1/4 - 1/2 (0.361 mi.) | 137 | 374 |

| | | | | |
|---|---|---|---|---|
| Spill Number/Closed Date: 0907297 / 2009-12-22<br>Site ID: 419812<br>Spill Date: 2009-09-29 | | | | |
| GLASS RESIDENCE<br>Spill Number/Closed Date: 0200914 / 2002-05-29<br>Site ID: 174074<br>Spill Date: 2002-04-24 | 5 IDEN AVE | S 1/4 - 1/2 (0.366 mi.) | AF138 | 375 |
| ***ELEMENTARY SCHOOL***<br>Spill Number/Closed Date: 2100760 / 2021-06-22<br>Site ID: 618445<br>Spill Date: 2021-04-26 | ***125 WEAVER STREET*** | ***NE 1/4 - 1/2 (0.374 mi.)*** | ***139*** | ***376*** |
| ST. JOHN'S<br>Spill Number/Closed Date: 0310652 / 2004-01-16<br>Spill Number/Closed Date: 8705481 / 1988-07-27<br>Spill Number/Closed Date: 1205086 / 2013-05-07<br>Site ID: 123833<br>Site ID: 246329<br>Site ID: 468002<br>Spill Date: 2003-12-16<br>Spill Date: 1987-09-29<br>Spill Date: 2012-08-20 | 280 WEAVER ST. | NNE 1/4 - 1/2 (0.388 mi.) | AG142 | 381 |
| RESIDENCE<br>Spill Number/Closed Date: 9812530 / 2000-01-13<br>Site ID: 220361<br>Spill Date: 1999-01-11 | 1 FRANCE PLACE | W 1/4 - 1/2 (0.389 mi.) | 143 | 384 |
| GARRY RESIDENCE<br>Spill Number/Closed Date: 0109734 / 2002-02-04<br>Site ID: 324496<br>Spill Date: 2002-01-08 | 7 MEADOW PL | E 1/4 - 1/2 (0.390 mi.) | AH144 | 386 |
| PRIVATE RES<br>Spill Number/Closed Date: 0402017 / 2004-09-15<br>Site ID: 321600<br>Spill Date: 2004-05-24 | 41 MAPLEWOOD ST | NW 1/4 - 1/2 (0.400 mi.) | AI146 | 388 |
| SPILL NUMBER 9905950<br>Spill Number/Closed Date: 9905950 / 2000-10-17<br>Site ID: 215426<br>Spill Date: 1999-08-18 | 10 ROCHELLE RD | W 1/4 - 1/2 (0.411 mi.) | AK150 | 393 |
| SPILL NUMBER 9911157<br>Spill Number/Closed Date: 9911157 / 2000-10-17<br>Site ID: 215427<br>Spill Date: 1999-12-21 | 10 ROCHELLE RD | W 1/4 - 1/2 (0.411 mi.) | AK151 | 394 |
| PVT DWELLING<br>Spill Number/Closed Date: 0913558 / 2010-06-08<br>Site ID: 426508<br>Spill Date: 2010-03-23 | 13 ROCHELLE ROAD | W 1/4 - 1/2 (0.419 mi.) | AK154 | 398 |
| ***LARCHMONT AVE CHURCH***<br>Spill Number/Closed Date: 1114153 / 2013-03-28<br>Site ID: 462194<br>Spill Date: 2012-03-21 | ***60 FOREST PARK AVE*** | ***SSE 1/4 - 1/2 (0.419 mi.)*** | ***AM155*** | ***399*** |
| TTF<br>Spill Number/Closed Date: 0013697 / 2009-12-30 | 12 COOPER LANE | NNE 1/4 - 1/2 (0.421 mi.) | 158 | 406 |

Spill Number/Closed Date: 0713255 / 2008-05-28
Spill Number/Closed Date: 0301842 / 2003-06-17
Site ID: 165408
Site ID: 394981
Site ID: 125348
Spill Date: 2001-03-31
Spill Date: 2008-03-14
Spill Date: 2003-05-21

| | | | | |
|---|---|---|---|---|
| DALEY RESIDENCE | 2 HEATHER LANE | NNE 1/4 - 1/2 (0.423 mi.) | AG159 | 410 |
| Spill Number/Closed Date: 0400710 / 2004-06-04<br>Site ID: 130559<br>Spill Date: 2004-04-21 | | | | |
| 104 NORTH CHATSWORTH | 104 NORTH CHATSWORTH | NW 1/4 - 1/2 (0.434 mi.) | AI162 | 413 |
| Spill Number/Closed Date: 0306408 / 2004-03-23<br>Site ID: 168951<br>Spill Date: 2003-09-17 | | | | |
| SPILL NUMBER 0201523 | 101 NORTH CHATSWORTH | NW 1/4 - 1/2 (0.446 mi.) | 164 | 416 |
| Spill Number/Closed Date: 0201523 / 2002-06-07<br>Spill Number/Closed Date: 0200579 / 2005-02-09<br>Site ID: 314806<br>Site ID: 82904<br>Spill Date: 2002-05-10<br>Spill Date: 2002-04-16 | | | | |
| FITCH RESIDENCE | 3 WILDWOOD ROAD | WNW 1/4 - 1/2 (0.452 mi.) | AO166 | 419 |
| Spill Number/Closed Date: 1103135 / 2011-08-25<br>Site ID: 450687<br>Spill Date: 2011-06-20 | | | | |
| PRIVATE HOME | 259 BARNARD RD | W 1/4 - 1/2 (0.465 mi.) | AR172 | 427 |
| Spill Number/Closed Date: 0800316 / 2008-06-30<br>Site ID: 396052<br>Spill Date: 2008-04-08 | | | | |
| SPILL NUMBER 9812365 | 1 SETON RD | WNW 1/4 - 1/2 (0.476 mi.) | AO174 | 431 |
| Spill Number/Closed Date: 9812365 / 1999-03-09<br>Site ID: 319993<br>Spill Date: 1999-01-06 | | | | |
| MARMON - TTF | 36 COLONIAL AVE | NNW 1/4 - 1/2 (0.476 mi.) | 175 | 432 |
| Spill Number/Closed Date: 0107574 / 2002-03-14<br>Site ID: 228035<br>Spill Date: 2001-10-24 | | | | |
| SPILL NUMBER 0108033 | 260 BARNARD RD | W 1/4 - 1/2 (0.478 mi.) | AR176 | 434 |
| Spill Number/Closed Date: 0108033 / 2002-03-13<br>Site ID: 80897<br>Spill Date: 2001-11-06 | | | | |
| BALLARD RESIDENCE | 4 ACORN LN | W 1/4 - 1/2 (0.489 mi.) | 181 | 463 |
| Spill Number/Closed Date: 0211936 / 2003-09-02<br>Site ID: 314363<br>Spill Date: 2003-03-04 | | | | |
| SPILL NUMBER 9901044 | 193 ROCKING STONE AV | WNW 1/4 - 1/2 (0.494 mi.) | 183 | 465 |
| Spill Number/Closed Date: 9901044 / 1999-07-01<br>Site ID: 227509<br>Spill Date: 1999-04-27 | | | | |
| COTUGNO RESIDENCE | 53 WEST GARDEN RD | NNE 1/4 - 1/2 (0.496 mi.) | 184 | 467 |

Spill Number/Closed Date: 9808948 / 1998-10-19
Site ID: 63099
Spill Date: 1998-10-19

| | | | | |
|---|---|---|---|---|
| ***PBS*** | ***1 ADDISON ST*** | ***SE 1/4 - 1/2 (0.496 mi.)*** | ***185*** | ***468*** |

Spill Number/Closed Date: 1904732 / 2020-03-24
Spill Number/Closed Date: 1908402 / 2020-02-07
Spill Number/Closed Date: 0406076 / 2004-11-26
Site ID: 592730
Site ID: 598583
Site ID: 282666
Spill Date: 2019-08-05
Spill Date: 2019-11-20
Spill Date: 2004-09-02

| | | | | |
|---|---|---|---|---|
| RENZ RESIDENCE | 44 VALLEY ROAD | NW 1/4 - 1/2 (0.497 mi.) | 186 | 472 |

Spill Number/Closed Date: 0510121 / 2005-11-26
Site ID: 356031
Spill Date: 2005-11-26

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| COMMERCIAL PROPERTY | 35 NORTH CHATSWORTH | WSW 1/4 - 1/2 (0.251 mi.) | 98 | 318 |

Spill Number/Closed Date: 0513382 / 2006-07-30
Spill Number/Closed Date: 2310041 / 2024-04-22
Site ID: 359767
Site ID: 664221
Spill Date: 2006-02-20
Spill Date: 2024-03-26

| | | | | |
|---|---|---|---|---|
| YAHIA RESIDENCE | 17 HALL AVE | ESE 1/4 - 1/2 (0.285 mi.) | 110 | 335 |

Spill Number/Closed Date: 0602686 / 2007-01-03
Spill Number/Closed Date: 0601851 / 2007-01-03
Site ID: 365228
Site ID: 364200
Spill Date: 2006-05-22
Spill Date: 2006-05-19

| | | | | |
|---|---|---|---|---|
| SPILL NUMBER 0011319 | 14 HALL AVE | SE 1/4 - 1/2 (0.292 mi.) | W113 | 340 |

Spill Number/Closed Date: 0011319 / 2001-04-11
Site ID: 184309
Spill Date: 2001-01-17

| | | | | |
|---|---|---|---|---|
| BLONDIE'S TREEHOUSE | 21 NORTH AVE | SSW 1/4 - 1/2 (0.301 mi.) | X114 | 341 |

Spill Number/Closed Date: 0000712 / 2000-08-08
Site ID: 175577
Spill Date: 2000-04-18

| | | | | |
|---|---|---|---|---|
| SPILL NUMBER 9914491 | 21 NORTH AVE | SSW 1/4 - 1/2 (0.301 mi.) | X115 | 342 |

Spill Number/Closed Date: 9914491 / 2002-06-29
Site ID: 175578
Spill Date: 2000-03-22

| | | | | |
|---|---|---|---|---|
| LARCHMONT AUTO GARAG | 5TH AV & MADISON | WSW 1/4 - 1/2 (0.325 mi.) | AA121 | 351 |

Spill Number/Closed Date: 9611599 / 1996-12-23
Site ID: 249760
Spill Date: 1996-12-21

| | | | | |
|---|---|---|---|---|
| BEN BEDERSON TTF | 8 HALL AVE | SE 1/4 - 1/2 (0.336 mi.) | AC128 | 360 |

Spill Number/Closed Date: 9410735 / 1995-02-13

Site ID: 146635
Spill Date: 1994-11-11

| | | | | |
|---|---|---|---|---|
| BIRDVELL RESIDENCE<br>Spill Number/Closed Date: 0208984 / 2003-02-27<br>Site ID: 249561<br>Spill Date: 2002-12-02 | 4 FOREST PARK AVE | ESE 1/4 - 1/2 (0.354 mi.) | 133 | 368 |
| MARTIN RES<br>Spill Number/Closed Date: 0111809 / 2002-05-03<br>Site ID: 206085<br>Spill Date: 2002-03-14 | 16 FOREST PARK AVE | SE 1/4 - 1/2 (0.357 mi.) | AE134 | 369 |
| RESIDENCE<br>Spill Number/Closed Date: 9505787 / 1996-09-10<br>Site ID: 120940<br>Spill Date: 1995-08-10 | 15 FOREST PARK AVE | SE 1/4 - 1/2 (0.384 mi.) | AE140 | 379 |
| SPILL NUMBER 0106394<br>Spill Number/Closed Date: 0106394 / 2002-01-03<br>Site ID: 314780<br>Spill Date: 2001-09-18 | 110 CARLEON AVE | E 1/4 - 1/2 (0.394 mi.) | AH145 | 387 |
| BEZ - TTF<br>Spill Number/Closed Date: 0000190 / 2000-04-18<br>Site ID: 231198<br>Spill Date: 2000-04-05 | 72 HOWELL AVE | ENE 1/4 - 1/2 (0.405 mi.) | 147 | 390 |
| RESIDENCE<br>Spill Number/Closed Date: 0311004 / 2003-12-31<br>Site ID: 293841<br>Spill Date: 2003-12-26 | 2 CAMBRIDGE COURT | ESE 1/4 - 1/2 (0.407 mi.) | AJ148 | 391 |
| ESTATE OF LANDES<br>Spill Number/Closed Date: 0401701 / 2004-09-14<br>Site ID: 217696<br>Spill Date: 2004-05-17 | 10 CAMBRIDGE COURT | SE 1/4 - 1/2 (0.407 mi.) | AJ149 | 392 |
| SPILL NUMBER 8900768<br>Spill Number/Closed Date: 8900768 / 1989-11-29<br>Site ID: 89508<br>Spill Date: 1989-04-15 | 4 WAKEMAN PLACE | S 1/4 - 1/2 (0.413 mi.) | 152 | 396 |
| ***SUTIN RESIDENCE***<br>Spill Number/Closed Date: 0307108 / 2003-12-03<br>Site ID: 62335<br>Spill Date: 2003-10-06 | ***21 COPLEY RD*** | ***E 1/4 - 1/2 (0.420 mi.)*** | ***156*** | ***401*** |
| SPILL NUMBER 0313036<br>Spill Number/Closed Date: 0311429 / 2004-04-26<br>Spill Number/Closed Date: 0313036 / 2004-04-22<br>Site ID: 260818<br>Site ID: 260819<br>Spill Date: 2004-01-09<br>Spill Date: 2004-02-26 | 7 HARMONY DRIVE | ESE 1/4 - 1/2 (0.421 mi.) | AN157 | 404 |
| FORECLOSURE - TTF<br>Spill Number/Closed Date: 1512394 / 2016-07-27<br>Site ID: 525209<br>Spill Date: 2016-03-28 | 18 ALDEN RD | ESE 1/4 - 1/2 (0.429 mi.) | AN160 | 411 |
| RESIDENCE<br>Spill Number/Closed Date: 9800085 / 1998-05-01 | 3 CAMBRIDGE CT | ESE 1/4 - 1/2 (0.429 mi.) | AJ161 | 412 |

Site ID: 161347
Spill Date: 1998-04-02

| | | | | |
|---|---|---|---|---|
| DURON RESIDENCE | 174 LARCHMONT AVE | SSE 1/4 - 1/2 (0.450 mi.) | AM165 | 418 |
| Spill Number/Closed Date: 9909450 / 2000-04-11<br>Site ID: 299475<br>Spill Date: 1999-11-03 | | | | |
| KUNREUTHER - TTF | 17 BONNETT AVENUE | SE 1/4 - 1/2 (0.453 mi.) | 167 | 420 |
| Spill Number/Closed Date: 9902354 / 2000-07-19<br>Spill Number/Closed Date: 1007092 / 2010-10-27<br>Site ID: 243264<br>Site ID: 440479<br>Spill Date: 1999-06-01<br>Spill Date: 2010-10-01 | | | | |
| RESIDENCE | 10 NASSAU RD | ESE 1/4 - 1/2 (0.456 mi.) | AJ168 | 423 |
| Spill Number/Closed Date: 0403388 / 2004-10-28<br>Site ID: 138656<br>Spill Date: 2004-06-29 | | | | |
| DEPT PUBLIC WORKS | MAXWELL AVE | SW 1/4 - 1/2 (0.458 mi.) | AP169 | 424 |
| Spill Number/Closed Date: 9907873 / 2003-12-05<br>Site ID: 197874<br>Spill Date: 1999-09-29 | | | | |
| MAMARONECK DPW | MAXWELL ST | SW 1/4 - 1/2 (0.458 mi.) | AP170 | 425 |
| Spill Number/Closed Date: 9906831 / 2005-09-20<br>Site ID: 217177<br>Spill Date: 1999-09-08 | | | | |
| APT BLD | 11 ALDEN RD | ESE 1/4 - 1/2 (0.475 mi.) | 173 | 429 |
| Spill Number/Closed Date: 1011710 / 2011-05-20<br>Spill Number/Closed Date: 0602133 / 2006-09-22<br>Site ID: 445598<br>Site ID: 364540<br>Spill Date: 2011-02-23<br>Spill Date: 2006-05-26 | | | | |
| LEVINSON RESIDENCE | 35 MAYHEW AVE | S 1/4 - 1/2 (0.478 mi.) | 178 | 460 |
| Spill Number/Closed Date: 0401870 / 2004-06-07<br>Site ID: 70244<br>Spill Date: 2004-05-20 | | | | |
| ROBERT TRIPPETT | 4 STUYVESANT AVE | SSE 1/4 - 1/2 (0.479 mi.) | 179 | 461 |
| Spill Number/Closed Date: 1304359 / 2013-08-29<br>Site ID: 484874<br>Spill Date: 2013-07-22 | | | | |
| WEBERS HOME | 76 PINEBROOK DRIVE | SSW 1/4 - 1/2 (0.487 mi.) | 180 | 462 |
| Spill Number/Closed Date: 0505197 / 2005-09-26<br>Site ID: 350147<br>Spill Date: 2005-07-29 | | | | |
| PARISSI TTF | 608 5TH AVE | WSW 1/4 - 1/2 (0.491 mi.) | AQ182 | 464 |
| Spill Number/Closed Date: 1810894 / 2019-07-08<br>Site ID: 581804<br>Spill Date: 2019-01-22 | | | | |

***Lists of state and tribal registered storage tanks***

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 13 NY UST sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| PATRICIA GARDENS OWN | 1825 PALMER AVENUE | ESE 0 - 1/8 (0.100 mi.) | D22 | 89 |
| Database: WESTCHESTER CO. UST, Date of Government Version: 01/28/2026<br>Status: 4. Closed - in place<br>Id/Status:: 3-048429<br>Site Status: Active | | | | |
| LARCHMONT PLAZA | 1890 PALMER AVE. | S 1/8 - 1/4 (0.142 mi.) | G43 | 167 |
| Database: WESTCHESTER CO. UST, Date of Government Version: 01/28/2026<br>Status: 3. Closed - Removed<br>Status: 0. Administratively closed<br>Id/Status:: 3-505102<br>Site Status: Unregulated: <1101 gal. PBS | | | | |
| LARCHMONT PALMER | 1299 PALMER AVENUE | ENE 1/8 - 1/4 (0.146 mi.) | I46 | 178 |
| Database: WESTCHESTER CO. UST, Date of Government Version: 01/28/2026<br>Status: 3a. Closed - Prior to 04/1991<br>Status: 3. Closed - Removed<br>Id/Status:: 3-504467<br>Site Status: Active | | | | |
| VERIZON NEW YORK INC | 5 FRANKLIN AVENUE | SSE 1/8 - 1/4 (0.159 mi.) | J47 | 179 |
| Database: WESTCHESTER CO. UST, Date of Government Version: 01/28/2026<br>Status: 3. Closed - Removed<br>Id/Status:: 3-184519<br>Site Status: Active | | | | |
| THE BANK OF NEW YORK | 124 CHATSWORTH AVE | SSW 1/8 - 1/4 (0.170 mi.) | G62 | 209 |
| Database: WESTCHESTER CO. UST, Date of Government Version: 01/28/2026<br>Status: 3. Closed - Removed<br>Id/Status:: 3-078948<br>Site Status: Unregulated: <1101 gal. PBS | | | | |
| DOM'S CAR CARE CENTE | 107 CHATSWORTH AVENU | S 1/8 - 1/4 (0.177 mi.) | J66 | 247 |
| Database: WESTCHESTER CO. UST, Date of Government Version: 01/28/2026<br>Status: 3. Closed - Removed<br>Id/Status:: 3-048852<br>Site Status: Unregulated: <1101 gal. PBS | | | | |
| ***16 NORTH CHATSWORTH*** | ***16 NORTH CHATSWORTH*** | ***WSW 1/8 - 1/4 (0.185 mi.)*** | ***M75*** | ***277*** |
| Database: WESTCHESTER CO. UST, Date of Government Version: 01/28/2026<br>Status: 3. Closed - Removed<br>Status: 4. Closed - in place<br>Id/Status:: 3-167819<br>Site Status: Active | | | | |
| LARCH REALTY CORP | 1923/1925 PALMER AV | SSW 1/8 - 1/4 (0.197 mi.) | L79 | 288 |
| Database: WESTCHESTER CO. UST, Date of Government Version: 01/28/2026<br>Status: 1. In-Service<br>Id/Status:: 3-169285 | | | | |

Site Status: Unregulated: <1101 gal. PBS

21 NORTH CHATSWORTH — 21 NORTH CHATSWORTH — WSW 1/8 - 1/4 (0.204 mi.) — M82 — 292
Database: WESTCHESTER CO. UST, Date of Government Version: 01/28/2026
Status: 3. Closed - Removed
Id/Status:: 3-028800
Site Status: Unregulated

***PARK PLAZA LARCHMONT — 3,5,7 EAST AVENUE — SSW 1/8 - 1/4 (0.227 mi.) — R89 — 306***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/28/2026
Status: 4. Closed - in place
Id/Status:: 3-171123
Site Status: Active

CARLSHIRE TENANTS IN — 1-3 WASHINGTON SQUAR — WSW 1/8 - 1/4 (0.230 mi.) — M91 — 308
Database: WESTCHESTER CO. UST, Date of Government Version: 01/28/2026
Status: 3. Closed - Removed
Id/Status:: 3-167185
Site Status: Active

LARCHMONT TERRACE CO — 2 WASHINGTON SQUARE — SW 1/8 - 1/4 (0.232 mi.) — O93 — 310
Database: WESTCHESTER CO. UST, Date of Government Version: 01/28/2026
Status: 1. In-Service
Status: 3. Closed - Removed
Id/Status:: 3-166146
Site Status: Active

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|

COLONY TENANTS CORP. — 1815 PALMER AVENUE — E 0 - 1/8 (0.108 mi.) — E27 — 93
Database: WESTCHESTER CO. UST, Date of Government Version: 01/28/2026
Status: 1. In-Service
Status: 3. Closed - Removed
Id/Status:: 3-104590
Site Status: Active

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 13 NY AST sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|

PATRICIA GARDENS OWN — 1825 PALMER AVENUE — ESE 0 - 1/8 (0.100 mi.) — D23 — 89
Database: WESTCHESTER CO. AST, Date of Government Version: 01/28/2026
Status: 1. In-Service
PBS Number: 3-048429

LUSARDI'S RESTAURANT — 1885-1889 PALMER AVE — S 0 - 1/8 (0.106 mi.) — C26 — 92
Database: WESTCHESTER CO. AST, Date of Government Version: 01/28/2026
Status: 3. Closed - Removed
PBS Number: 3-801570

THE BROMPTON — 1880 PALMER AVENUE — S 0 - 1/8 (0.123 mi.) — G33 — 152
Database: WESTCHESTER CO. AST, Date of Government Version: 01/28/2026
Status: 4. Closed - in place
Status: 1. In-Service

PBS Number: 3-800888

***LARCHMONT/PALMER COO*** ***1299 PALMER AVE*** ***ENE 1/8 - 1/4 (0.146 mi.)*** ***I45*** ***173***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/28/2026
Status: 1. In-Service
PBS Number: 3-504467

***BELL ATLANTIC*** ***5 FRANKLIN ST*** ***SSE 1/8 - 1/4 (0.159 mi.)*** ***J48*** ***180***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/28/2026
Status: 1. In-Service
PBS Number: 3-184519

CHATSWORTH GARDENS C 14 NORTH CHATSWORTH WSW 1/8 - 1/4 (0.163 mi.) H57 199
Database: WESTCHESTER CO. AST, Date of Government Version: 01/28/2026
Status: 3. Closed - Removed
Status: 1. In-Service
PBS Number: 3-506788

HOWELL ASSOCIATES 132 CHATSWORTH AVENU SSW 1/8 - 1/4 (0.167 mi.) G59 204
Database: WESTCHESTER CO. AST, Date of Government Version: 01/28/2026
Status: 1. In-Service
PBS Number: 3-049565

***16 NORTH CHATSWORTH*** ***16 NORTH CHATSWORTH*** ***WSW 1/8 - 1/4 (0.185 mi.)*** ***M75*** ***277***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/28/2026
Status: 1. In-Service
PBS Number: 3-167819

LARCHMONT HILLS OWNE 17 NORTH CHATSWORTH SW 1/8 - 1/4 (0.193 mi.) M77 282
Database: WESTCHESTER CO. AST, Date of Government Version: 01/28/2026
Status: 3. Closed - Removed
Status: 1. In-Service
PBS Number: 3-048488

172 MYRTLE BLVD. APT 172 MYRTLE BOULEVARD SW 1/8 - 1/4 (0.205 mi.) O83 293
Database: WESTCHESTER CO. AST, Date of Government Version: 01/28/2026
Status: 1. In-Service
PBS Number: 3-800128

***PARK PLAZA LARCHMONT*** ***3,5,7 EAST AVENUE*** ***SSW 1/8 - 1/4 (0.227 mi.)*** ***R89*** ***306***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/28/2026
Status: 1. In-Service
PBS Number: 3-171123

CARLSHIRE TENANTS IN 1-3 WASHINGTON SQUAR WSW 1/8 - 1/4 (0.230 mi.) M90 308
Database: WESTCHESTER CO. AST, Date of Government Version: 01/28/2026
Status: 1. In-Service
PBS Number: 3-167185

THE KEYSTONE 76 WENDT AVENUE S 1/8 - 1/4 (0.230 mi.) R92 309
Database: WESTCHESTER CO. AST, Date of Government Version: 01/28/2026
Status: 1. In-Service
PBS Number: 3-801206

***State and tribal institutional control / engineering control registries***

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 10/30/2025 has revealed that

there is 1 NY ENG CONTROLS site within approximately 0.5 miles of the target property.

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***CHATSWORTH COAL AND*** Site Code: 484785 | ***2101, 2103 AND 2101-*** | ***SW 1/4 - 1/2 (0.478 mi.)*** | ***177*** | ***435*** |

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 10/30/2025 has revealed that there is 1 NY INST CONTROL site within approximately 0.5 miles of the target property.

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***CHATSWORTH COAL AND*** Site Code: 484785 | ***2101, 2103 AND 2101-*** | ***SW 1/4 - 1/2 (0.478 mi.)*** | ***177*** | ***435*** |

***Lists of state and tribal brownfield sites***

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 10/30/2025 has revealed that there are 2 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| MAMARONECK MANOR Site Code: 676662 | 636 FIFTH AVENUE | WSW 1/4 - 1/2 (0.357 mi.) | AA135 | 370 |
| ***CHATSWORTH COAL AND*** Site Code: 484785 | ***2101, 2103 AND 2101-*** | ***SW 1/4 - 1/2 (0.478 mi.)*** | ***177*** | ***435*** |

**ADDITIONAL ENVIRONMENTAL RECORDS**

***Records of Emergency Release Reports***

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 10/30/2025 has revealed that there are 7 NY Spills sites within approximately 0.125 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| TRAFFIC ACCIDENT<br>Spill Number/Closed Date: 9407990 / 1994-09-22<br>Site ID: 154341<br>Spill Date: 1994-09-15 | I-95 MP 7.7 | SSW 0 - 1/8 (0.031 mi.) | A14 | 76 |
| 7 MAPLE ST | 7 MAPLE ST | W 0 - 1/8 (0.037 mi.) | 15 | 78 |

Spill Number/Closed Date: 9903923 / 1999-07-06
Site ID: 169578
Spill Date: 1999-07-06

| | | | | |
|---|---|---|---|---|
| ***PATRICIA GARDENS*** | ***1825 PALMER AVE*** | ***ESE 0 - 1/8 (0.100 mi.)*** | ***D21*** | ***87*** |
| Spill Number/Closed Date: 9515259 / 1996-02-27<br>Site ID: 71681<br>Spill Date: 1996-02-27 | | | | |
| MANOPP REALTY | 1885-1889 PALMER AVE | S 0 - 1/8 (0.106 mi.) | C25 | 91 |
| Spill Number/Closed Date: 0900003 / 2010-05-17<br>Site ID: 411912<br>Spill Date: 2009-01-30 | | | | |
| SIDEWALK AND PARKING | 1880 PALMER AVE | S 0 - 1/8 (0.123 mi.) | G34 | 153 |
| Spill Number/Closed Date: 1300547 / 2013-04-18<br>Site ID: 480875<br>Spill Date: 2013-04-16 | | | | |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| DECABIA - UST | 19 CABOT RD | NE 0 - 1/8 (0.080 mi.) | B18 | 84 |
| Spill Number/Closed Date: 2202138 / 2022-07-14<br>Site ID: 637212<br>Spill Date: 2022-06-08 | | | | |
| SPILL NUMBER 9909425 | 1815 PALMER AVE | E 0 - 1/8 (0.108 mi.) | E28 | 94 |
| Spill Number/Closed Date: 9909425 / 2000-02-22<br>Site ID: 165122<br>Spill Date: 1999-11-03 | | | | |

***Other Ascertainable Records***

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 11/30/2025 has revealed that there are 16 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***CON EDISON*** | ***MYRTLE BLVD & MURRAY*** | ***SW 1/8 - 1/4 (0.137 mi.)*** | ***H41*** | ***163*** |
| EPA ID:: NYP004777850 | | | | |
| CON EDISON | MYRTLE BLVD &D CHATS | SW 1/8 - 1/4 (0.163 mi.) | H52 | 188 |
| EPA ID:: NYP004835332 | | | | |
| ***CON EDISON*** | ***MYRTLE AVE & CHATSWO*** | ***SW 1/8 - 1/4 (0.163 mi.)*** | ***H53*** | ***190*** |
| EPA ID:: NYP004766622 | | | | |
| ***CON EDISON MANHOLE:*** | ***CHATSWORTH AVE & PAL*** | ***S 1/8 - 1/4 (0.163 mi.)*** | ***G56*** | ***195*** |
| EPA ID:: NYP004309225 | | | | |
| NYS THRUWAY MAINTENA | I-95 EXIT 17 OFF NEW | SSW 1/8 - 1/4 (0.165 mi.) | K58 | 201 |
| EPA ID:: NY0000198762 | | | | |
| CON EDISON - SERVICE | MURRAY AVE & EDGEWOO | NW 1/8 - 1/4 (0.181 mi.) | N71 | 255 |

| | | | | |
|---|---|---|---|---|
| EPA ID:: NYP005106317 | | | | |
| ***EMBASSY CLEANERS*** EPA ID:: NYD012815395 | ***1908 PALMER AVE*** | ***S 1/8 - 1/4 (0.182 mi.)*** | ***L72*** | ***258*** |
| ***DUTCH GIRL PROFESSIO*** EPA ID:: NYD106797061 | ***1912 PALMER AVE*** | ***S 1/8 - 1/4 (0.191 mi.)*** | ***L76*** | ***279*** |
| ***DONALD RITACCO & CO*** EPA ID:: NYD982718249 | ***7-11 NORTH AVE*** | ***SSW 1/8 - 1/4 (0.194 mi.)*** | ***K78*** | ***283*** |
| ***CON EDISON*** EPA ID:: NYP004162822 | ***6 OVERLOOK TER*** | ***W 1/8 - 1/4 (0.226 mi.)*** | ***Q87*** | ***301*** |
| CON EDISON GAS DRIP EPA ID:: NYP004149621 | 6 OVERLOOK TERR GAS | W 1/8 - 1/4 (0.226 mi.) | Q88 | 304 |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| CON EDISON EPA ID:: NYP005249410 | 10 CABOT RD | NNE 0 - 1/8 (0.054 mi.) | B16 | 79 |
| ***CON EDISON SERVICE B*** EPA ID:: NYP004486809 | ***PALMER AVE & E DEPOT*** | ***ESE 1/8 - 1/4 (0.128 mi.)*** | ***D36*** | ***155*** |
| ***CON EDISON POLE W10*** EPA ID:: NYP004145074 | ***HALL AVE & CONCORD A*** | ***ESE 1/8 - 1/4 (0.183 mi.)*** | ***74*** | ***274*** |
| ***MOONEY ED RESIDENCE*** EPA ID:: NYR000073171 | ***22 CARLEON AVE*** | ***E 1/8 - 1/4 (0.220 mi.)*** | ***86*** | ***298*** |
| ***CON EDISON SERVICE B*** EPA ID:: NYP004457297 | ***178 MYRTLE BLVD*** | ***SW 1/8 - 1/4 (0.244 mi.)*** | ***O96*** | ***314*** |

UST FINDER RELEASE: US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

A review of the UST FINDER RELEASE list, as provided by EDR, and dated 06/08/2023 has revealed that there are 4 UST FINDER RELEASE sites within approximately 0.5 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| EXXON | 124 CHATSWORTH AVE | SSW 1/8 - 1/4 (0.170 mi.) | G61 | 208 |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| CITY PARK SERV BLUEB | 613 5TH AVE | SW 1/4 - 1/2 (0.415 mi.) | AL153 | 397 |
| NYS THRUWAY | 629 FIFTH AVE | SW 1/4 - 1/2 (0.435 mi.) | AL163 | 415 |
| VACANT BUILDING | 615 5TH AVE | WSW 1/4 - 1/2 (0.463 mi.) | AQ171 | 427 |

E MANIFEST: EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

A review of the E MANIFEST list, as provided by EDR, and dated 11/30/2025 has revealed that there are

3 E MANIFEST sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| CONSOLIDATED EDISON | MYRTLE BLVD & MURRAY | SW 1/8 - 1/4 (0.137 mi.) | H39 | 160 |
| CON EDISON - ELECTRI | 1906 PALMER AVE | S 1/8 - 1/4 (0.180 mi.) | L67 | 250 |
| CONSOLIDATED EDISON | 21 N CHATSWORTH AVE | WSW 1/8 - 1/4 (0.204 mi.) | M81 | 291 |

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 11/25/2025 has revealed that there are 3 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***EMBASSY CLEANERS*** Facility Id: 3-5532-00266 | ***1895 PALMER AVE*** | ***S 0 - 1/8 (0.122 mi.)*** | ***G31*** | ***96*** |
| ***CHATSWORTH CLEANERS*** Facility Id: 3-5532-00305 | ***120 CHATSWORTH AVE*** | ***S 1/8 - 1/4 (0.173 mi.)*** | ***L64*** | ***211*** |
| EMBASSY CLEANERS Facility Id: 3-5532-00189 | 1908 PALMER AVENUE | S 1/8 - 1/4 (0.182 mi.) | L73 | 273 |

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 12/31/2019 has revealed that there are 17 NY MANIFEST sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***EMBASSY CLEANERS*** EPA ID: NYD986995249 | ***1895 PALMER AVE*** | ***S 0 - 1/8 (0.122 mi.)*** | ***G31*** | ***96*** |
| CON EDISON EPA ID: NYP004777850 | MYRTLE BLVD & MURRAY | SW 1/8 - 1/4 (0.137 mi.) | H38 | 159 |
| CON EDISON EPA ID: NYP004766622 | MYRTLE AVE & CHATSWO | SW 1/8 - 1/4 (0.163 mi.) | H54 | 192 |
| CON EDISON EPA ID: NYP004699658 | PALMER AVE & CHATSWO | S 1/8 - 1/4 (0.163 mi.) | G55 | 194 |
| ***CON EDISON MANHOLE:*** EPA ID: NYP004309225 | ***CHATSWORTH AVE & PAL*** | ***S 1/8 - 1/4 (0.163 mi.)*** | ***G56*** | ***195*** |
| ***CHATSWORTH CLEANERS*** EPA ID: NY0000363101 | ***120 CHATSWORTH AVE*** | ***S 1/8 - 1/4 (0.173 mi.)*** | ***L64*** | ***211*** |
| ***MOBIL OIL CORP SS D3*** EPA ID: NYD986958171 | ***107 CHATSWORTH AVE*** | ***S 1/8 - 1/4 (0.177 mi.)*** | ***J65*** | ***240*** |
| CON EDISON EPA ID: NYP004682852 | CHATSWORTH AVE & WAS | WSW 1/8 - 1/4 (0.181 mi.) | M68 | 252 |
| CONSOLIDATED EDISON EPA ID: NYP004093696 | WASHINGTON & N CHATS | WSW 1/8 - 1/4 (0.181 mi.) | M69 | 253 |
| CON EDISON - SERVICE EPA ID: NYP005106317 | MURRAY AVE & EDGEWOO | NW 1/8 - 1/4 (0.181 mi.) | N70 | 254 |
| ***EMBASSY CLEANERS*** | ***1908 PALMER AVE*** | ***S 1/8 - 1/4 (0.182 mi.)*** | ***L72*** | ***258*** |

EPA ID: NYD012815395

| | | | | |
|---|---|---|---|---|
| ***DONALD RITACCO & CO*** | ***7-11 NORTH AVE*** | ***SSW 1/8 - 1/4 (0.194 mi.)*** | ***K78*** | ***283*** |
| EPA ID: NYD982718249 | | | | |
| ***CON EDISON*** | ***6 OVERLOOK TER*** | ***W 1/8 - 1/4 (0.226 mi.)*** | ***Q87*** | ***301*** |
| EPA ID: NYP004162822 | | | | |

| Lower Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| CON EDISON | PALMER AVE & E DEPOT | ESE 1/8 - 1/4 (0.128 mi.) | D37 | 157 |
| EPA ID: NYP004486809 | | | | |
| ***CON EDISON POLE W10*** | ***HALL AVE & CONCORD A*** | ***ESE 1/8 - 1/4 (0.183 mi.)*** | ***74*** | ***274*** |
| EPA ID: NYP004145074 | | | | |
| ***CON EDISON - OVERHEA*** | ***6 VIRGINIA PL*** | ***ESE 1/8 - 1/4 (0.244 mi.)*** | ***95*** | ***312*** |
| EPA ID: NYP005194162 | | | | |
| ***CON EDISON SERVICE B*** | ***178 MYRTLE BLVD*** | ***SW 1/8 - 1/4 (0.244 mi.)*** | ***O96*** | ***314*** |
| EPA ID: NYP004457297 | | | | |

RI MANIFEST: Hazardous waste manifest information

A review of the RI MANIFEST list, as provided by EDR, and dated 12/31/2020 has revealed that there is 1 RI MANIFEST site within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| ***EMBASSY CLEANERS*** | ***1895 PALMER AVE*** | ***S 0 - 1/8 (0.122 mi.)*** | ***G31*** | ***96*** |
| EPA Id: NYD986995249 | | | | |
| Manifest Document Number: 002496373SKS | | | | |

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 3 NJ MANIFEST sites within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| CON EDISON | MYRTLE BLVD & MURRAY | SW 1/8 - 1/4 (0.137 mi.) | H40 | 162 |
| EPA Id: NYP004777850 | | | | |
| CON EDISON | MYRTLE BLVD &D CHATS | SW 1/8 - 1/4 (0.163 mi.) | H50 | 186 |
| EPA Id: NYP004835332 | | | | |
| CON EDISON | MYRTLE AVE & CHATSWO | SW 1/8 - 1/4 (0.163 mi.) | H51 | 187 |
| EPA Id: NYP004766622 | | | | |

**EDR HIGH RISK HISTORICAL RECORDS**

***EDR Exclusive Records***

# EXECUTIVE SUMMARY

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 3 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page |
|---|---|---|---|---|
| FIRST IMPRESSION | 1875 PALMER AVE | S 0 - 1/8 (0.089 mi.) | C19 | 86 |
| LARCHMONT CENTER CLE | 1861 PALMER AVE | SE 0 - 1/8 (0.104 mi.) | D24 | 90 |
| TRIPLE CLEAN GROUP I | 1895 PALMER AVE | S 0 - 1/8 (0.122 mi.) | G30 | 96 |

# EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 4 records.

| Site Name | Database(s) |
|---|---|
| MEARL CORP. | NY SHWS |
| SPILL NUMBER 8601246 | NY LTANKS |
| N.SHORE LONG ISLAND SOUND | NY LTANKS |
| MM 5.4 LEFT LANE | NY LTANKS |

# OVERVIEW MAP - 8303563.2S




Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

Indian Reservations BIA

Special Flood Hazard Area (1%)

0.2% Annual Chance Flood Hazard

National Wetland Inventory

State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

| | | | |
|---|---|---|---|
| SITE NAME: | One Vine Street | CLIENT: | Langan |
| ADDRESS: | 1 Vine St<br>Larchmont NY 10538 | CONTACT: | Olivia Miller |
| | | INQUIRY #: | 8303563.2s |
| LAT/LONG: | 40.93547 / 73.75843 | DATE: | April 06, 2026 12:57 pm |

Copyright © 2026 EDR, Inc. © 2015 TomTom Rel. 2015.

# DETAIL MAP - 8303563.2S




This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

| | | | |
|---|---|---|---|
| SITE NAME: | One Vine Street | CLIENT: | Langan |
| ADDRESS: | 1 Vine St<br>Larchmont NY 10538 | CONTACT: | Olivia Miller |
| | | INQUIRY #: | 8303563.2s |
| LAT/LONG: | 40.93547 / 73.75843 | DATE: | April 06, 2026 12:58 pm |

Copyright © 2026 EDR, Inc. © 2015 TomTom Rel. 2015.

# MAP FINDINGS SUMMARY

| Database | Search Distance (Miles) | Target Property | < 1/8 | 1/8 - 1/4 | 1/4 - 1/2 | 1/2 - 1 | > 1 | Total Plotted |
|---|---|---|---|---|---|---|---|---|
| **STANDARD ENVIRONMENTAL RECORDS** | | | | | | | | |
| ***Lists of Federal NPL (Superfund) sites*** | | | | | | | | |
| NPL | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| Proposed NPL | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| NPL LIENS | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| ***Lists of Federal Delisted NPL sites*** | | | | | | | | |
| Delisted NPL | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| ***Lists of Federal sites subject to CERCLA removals and CERCLA orders*** | | | | | | | | |
| FEDERAL FACILITY | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| SEMS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Lists of Federal CERCLA sites with NFRAP*** | | | | | | | | |
| SEMS-ARCHIVE | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Lists of Federal RCRA facilities undergoing Corrective Action*** | | | | | | | | |
| CORRACTS | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| ***Lists of Federal RCRA TSD facilities*** | | | | | | | | |
| RCRA-TSDF | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Lists of Federal RCRA generators*** | | | | | | | | |
| RCRA-LQG | 0.250 | | 0 | 2 | NR | NR | NR | 2 |
| RCRA-SQG | 0.250 | 1 | 2 | 1 | NR | NR | NR | 4 |
| RCRA-VSQG | 0.250 | | 0 | 1 | NR | NR | NR | 1 |
| ***Federal institutional controls / engineering controls registries*** | | | | | | | | |
| LUCIS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| US ENG CONTROLS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| US INST CONTROLS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Federal ERNS list*** | | | | | | | | |
| ERNS | TP | | NR | NR | NR | NR | NR | 0 |
| ***Lists of state- and tribal hazardous waste facilities*** | | | | | | | | |
| NY SHWS | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| ***Lists of state and tribal landfills and solid waste disposal facilities*** | | | | | | | | |
| NY SWF/LF | 0.500 | | 0 | 0 | 1 | NR | NR | 1 |
| ***Lists of state and tribal leaking storage tanks*** | | | | | | | | |
| INDIAN LUST | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |

# MAP FINDINGS SUMMARY

| Database | Search Distance (Miles) | Target Property | < 1/8 | 1/8 - 1/4 | 1/4 - 1/2 | 1/2 - 1 | > 1 | Total Plotted |
|---|---|---|---|---|---|---|---|---|
| NY LTANKS | 0.500 | 2 | 4 | 10 | 83 | NR | NR | 99 |
| NY HIST LTANKS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Lists of state and tribal registered storage tanks*** | | | | | | | | |
| FEMA UST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY UST | 0.250 | 1 | 2 | 11 | NR | NR | NR | 14 |
| NY CBS UST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY MOSF UST | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| NY MOSF | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| NY CBS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY AST | 0.250 | 1 | 3 | 10 | NR | NR | NR | 14 |
| NY CBS AST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY MOSF AST | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| INDIAN UST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY TANKS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ***State and tribal institutional control / engineering control registries*** | | | | | | | | |
| NY RES DECL | 0.125 | | 0 | NR | NR | NR | NR | 0 |
| NY ENG CONTROLS | 0.500 | | 0 | 0 | 1 | NR | NR | 1 |
| NY INST CONTROL | 0.500 | | 0 | 0 | 1 | NR | NR | 1 |
| ***Lists of state and tribal voluntary cleanup sites*** | | | | | | | | |
| NY VCP | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| INDIAN VCP | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Lists of state and tribal brownfield sites*** | | | | | | | | |
| NY BROWNFIELDS | 0.500 | | 0 | 0 | 2 | NR | NR | 2 |
| NY ERP | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| **ADDITIONAL ENVIRONMENTAL RECORDS** | | | | | | | | |
| ***Local Brownfield lists*** | | | | | | | | |
| US BROWNFIELDS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Local Lists of Landfill / Solid Waste Disposal Sites*** | | | | | | | | |
| NY SWRCY | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| NY SWTIRE | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| INDIAN ODI | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| DEBRIS REGION 9 | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ODI | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| IHS OPEN DUMPS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| ***Local Lists of Hazardous waste / Contaminated Sites*** | | | | | | | | |
| US HIST CDL | TP | | NR | NR | NR | NR | NR | 0 |
| NY DEL SHWS | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| US CDL | TP | | NR | NR | NR | NR | NR | 0 |
| ***Local Lists of Registered Storage Tanks*** | | | | | | | | |
| NY HIST UST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |

# MAP FINDINGS SUMMARY

| Database | Search Distance (Miles) | Target Property | < 1/8 | 1/8 - 1/4 | 1/4 - 1/2 | 1/2 - 1 | > 1 | Total Plotted |
|---|---|---|---|---|---|---|---|---|
| NY HIST AST | TP | | NR | NR | NR | NR | NR | 0 |
| ***Local Land Records*** | | | | | | | | |
| NY LIENS | TP | | NR | NR | NR | NR | NR | 0 |
| LIENS 2 | TP | | NR | NR | NR | NR | NR | 0 |
| ***Records of Emergency Release Reports*** | | | | | | | | |
| HMIRS | TP | | NR | NR | NR | NR | NR | 0 |
| NY Spills | 0.125 | 2 | 7 | NR | NR | NR | NR | 9 |
| NY Hist Spills | 0.125 | | 0 | NR | NR | NR | NR | 0 |
| NY SPILLS 90 | 0.125 | | 0 | NR | NR | NR | NR | 0 |
| NY SPILLS 80 | 0.125 | | 0 | NR | NR | NR | NR | 0 |
| ***Other Ascertainable Records*** | | | | | | | | |
| RCRA NonGen / NLR | 0.250 | 1 | 1 | 15 | NR | NR | NR | 17 |
| FUDS | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| DOD | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| SCRD DRYCLEANERS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| US FIN ASSUR | TP | | NR | NR | NR | NR | NR | 0 |
| EPA WATCH LIST | TP | | NR | NR | NR | NR | NR | 0 |
| 2020 COR ACTION | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| TSCA | TP | | NR | NR | NR | NR | NR | 0 |
| TRIS | TP | | NR | NR | NR | NR | NR | 0 |
| SSTS | TP | | NR | NR | NR | NR | NR | 0 |
| ROD | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| RMP | TP | | NR | NR | NR | NR | NR | 0 |
| RAATS | TP | | NR | NR | NR | NR | NR | 0 |
| PRP | TP | | NR | NR | NR | NR | NR | 0 |
| PADS | TP | | NR | NR | NR | NR | NR | 0 |
| ICIS | TP | 1 | NR | NR | NR | NR | NR | 1 |
| FTTS | TP | | NR | NR | NR | NR | NR | 0 |
| MLTS | TP | | NR | NR | NR | NR | NR | 0 |
| COAL ASH DOE | TP | | NR | NR | NR | NR | NR | 0 |
| COAL ASH EPA | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| PCB TRANSFORMER | TP | | NR | NR | NR | NR | NR | 0 |
| RADINFO | TP | | NR | NR | NR | NR | NR | 0 |
| HIST FTTS | TP | | NR | NR | NR | NR | NR | 0 |
| DOT OPS | TP | | NR | NR | NR | NR | NR | 0 |
| CONSENT | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| INDIAN RESERV | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| FUSRAP | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| UMTRA | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| LEAD SMELTERS | TP | | NR | NR | NR | NR | NR | 0 |
| US AIRS | TP | 2 | NR | NR | NR | NR | NR | 2 |
| US MINES | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| MINES MRDS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| ABANDONED MINES | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| FINDS | TP | 2 | NR | NR | NR | NR | NR | 2 |
| UXO | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| ECHO | TP | 2 | NR | NR | NR | NR | NR | 2 |
| DOCKET HWC | TP | | NR | NR | NR | NR | NR | 0 |

# MAP FINDINGS SUMMARY

| Database | Search Distance (Miles) | Target Property | < 1/8 | 1/8 - 1/4 | 1/4 - 1/2 | 1/2 - 1 | > 1 | Total Plotted |
|---|---|---|---|---|---|---|---|---|
| FUELS PROGRAM | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS NPL | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS FEDERAL SITES | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS TRIS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS TSCA | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS RCRA MANIFEST | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS ATSDR | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS WQP | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS PROJECT | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS NPDES | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS ECHO | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS ECHO FIRE TRAIN | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| PFAS PT 139 AIRPORT | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| AQUEOUS FOAM NRC | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| BIOSOLIDS | TP | | NR | NR | NR | NR | NR | 0 |
| UST FINDER | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| UST FINDER RELEASE | 0.500 | 1 | 0 | 1 | 3 | NR | NR | 5 |
| E MANIFEST | 0.250 | 1 | 0 | 3 | NR | NR | NR | 4 |
| NY PFAS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| NY AIRS | TP | 1 | NR | NR | NR | NR | NR | 1 |
| NY COAL ASH | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| NY DRYCLEANERS | 0.250 | 1 | 1 | 2 | NR | NR | NR | 4 |
| NY E DESIGNATION | 0.125 | | 0 | NR | NR | NR | NR | 0 |
| NY Financial Assurance | TP | | NR | NR | NR | NR | NR | 0 |
| NY HSWDS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| NY LEAD | TP | | NR | NR | NR | NR | NR | 0 |
| NY MANIFEST | 0.250 | 2 | 1 | 16 | NR | NR | NR | 19 |
| RI MANIFEST | 0.250 | | 1 | 0 | NR | NR | NR | 1 |
| NJ MANIFEST | 0.250 | 1 | 0 | 3 | NR | NR | NR | 4 |
| NY SPDES | TP | | NR | NR | NR | NR | NR | 0 |
| NY VAPOR REOPENED | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| NY UIC | TP | | NR | NR | NR | NR | NR | 0 |
| NY COOLING TOWERS | TP | | NR | NR | NR | NR | NR | 0 |
| NY MGP | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| NY ILI | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| NY NYC OER | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| NY NYC LAND USE | TP | | NR | NR | NR | NR | NR | 0 |
| ABAND AIRFIELDS | 0.500 | | 0 | 0 | 0 | NR | NR | 0 |
| DRYCLEANERS | 0.250 | | 0 | 0 | NR | NR | NR | 0 |
| **EDR HIGH RISK HISTORICAL RECORDS** | | | | | | | | |
| ***EDR Exclusive Records*** | | | | | | | | |
| EDR MGP | 1.000 | | 0 | 0 | 0 | 0 | NR | 0 |
| EDR Hist Auto | 0.125 | 1 | 0 | NR | NR | NR | NR | 1 |
| EDR Hist Cleaner | 0.125 | 2 | 3 | NR | NR | NR | NR | 5 |
| **EDR RECOVERED GOVERNMENT ARCHIVES** | | | | | | | | |
| ***Exclusive Recovered Govt. Archives*** | | | | | | | | |
| NY RGA HWS | TP | | NR | NR | NR | NR | NR | 0 |

# MAP FINDINGS SUMMARY

| Database | Search Distance (Miles) | Target Property | < 1/8 | 1/8 - 1/4 | 1/4 - 1/2 | 1/2 - 1 | > 1 | Total Plotted |
|---|---|---|---|---|---|---|---|---|
| NY RGA LF | TP | | NR | NR | NR | NR | NR | 0 |
| - Totals -- | | 25 | 25 | 75 | 91 | 0 | 0 | 216 |

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

**A1** **J & F CHATSWORTH AUTO BODY** **RCRA-SQG** **1000113677**
**Target** **1 VINE ST** **E MANIFEST** **NYD982718272**
**Property** **LARCHMONT, NY 10538** **NY MANIFEST**
**NJ MANIFEST**

**Site 1 of 14 in cluster A**

**Actual:** **41 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20070101 |
| Handler Name: | | J & F Chatsworth Ltd |
| Handler Address: | | Vine St |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYD982718272 |
| Contact Name: | | JOSEPH SPARANO |
| Contact Address: | | VINE ST |
| Contact City,State,Zip: | | LARCHMONT, NY 10538 |
| Contact Telephone: | | 914-834-0008 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Small Quantity Generator |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Handler Activities |
| State District Owner: | | Ny |
| State District: | | NYSDEC R3 |
| Mailing Address: | | VINE ST |
| Mailing City,State,Zip: | | LARCHMONT, NY 10538 |
| Owner Name: | J&F Chatsworth Ltd | |
| Owner Type: | | Private |
| Operator Name: | J&F Chatsworth Ltd | |
| Operator Type: | | Private |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| Corrective Action Priority Ranking: | | No NCAPS ranking |
| Environmental Control Indicator: | | No |
| Institutional Control Indicator: | | No |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20150414 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | D000 |
| Waste Description: | Not Defined |
| Waste Code: | D001 |
| Waste Description: | Ignitable Waste |

Handler - Owner Operator:

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: J&F CHATSWORTH LTD | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | NOT REQUIRED |
| Owner/Operator City,State,Zip: | NOT REQUIRED, WY 99999 |
| Owner/Operator Telephone: | 212-555-1212 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: J&F CHATSWORTH LTD | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | NOT REQUIRED |
| Owner/Operator City,State,Zip: | NOT REQUIRED, WY 99999 |
| Owner/Operator Telephone: | 212-555-1212 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |
| Owner/Operator Indicator: | Operator |
| Owner/Operator Name: J&F CHATSWORTH LTD | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | NOT REQUIRED |
| Owner/Operator City,State,Zip: | NOT REQUIRED, WY 99999 |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Owner/Operator Telephone: | 212-555-1212 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20060101 |
| Handler Name: J & F CHATSWORTH LTD | |
| Federal Waste Generator Description: | Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20070101 |
| Handler Name: J & F CHATSWORTH LTD | |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 19881208 |
| Handler Name: J & F CHATSWORTH LTD | |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 19960122 |
| Handler Name: J & F CHATSWORTH | |
| Federal Waste Generator Description: | Large Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 4471
NAICS Description: Gasoline Stations

NAICS Code: 44711
NAICS Description: Gasoline Stations With Convenience Stores

NAICS Code: 811111
NAICS Description: General Automotive Repair

NAICS Code: 811121
NAICS Description: Automotive Body, Paint, And Interior Repair And Maintenance

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20120913

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Evaluation Responsible Agency: | State |
| Found Violation: | No |
| Evaluation Type Description: | COMPLIANCE EVALUATION INSPECTION |
| Evaluation Responsible Person Identifier: | NYFKY |
| Evaluation Responsible Sub-Organization: | R3 |
| Actual Return to Compliance Date: | Not reported |
| Scheduled Compliance Date: | Not reported |
| Date of Request: | Not reported |
| Date Response Received: | Not reported |
| Request Agency: | Not reported |
| Former Citation: | Not reported |

E MANIFEST:

| | |
|---|---|
| Manifest Tracking Number: | 001714764VES |
| Last Updated Date: | 20190904 |
| Shipped Date: | 20190830 |
| Received Date: | 20190830 |
| Manifest Status: | Signed |
| Submission Type: | DataImage5Copy |
| Origin Type: | Service |
| Generator EPA ID: | NYD982718272 |
| Generator Name: | J & F Chatsworth Auto Body |
| Generator Location Street Number: | Not reported |
| Generator Location Street 1: | 1 VINE ST |
| Generator Location Street 2: | Not reported |
| Generator Location City: | LARCHMONT |
| Generator Location State: | NY |
| Generator Location Zip: | 10538-2328 |
| Generator Mail Street Number: | Not reported |
| Generator Mail Street 1: | 1 VINE ST |
| Generator Mail Street 2: | Not reported |
| Generator Mail City: | LARCHMONT |
| Generator Mail Zip: | 10538-2328 |
| Generator Mail State: | NY |
| Generator Contact Company Name: | Not reported |
| Designated Facility EPA ID: | NJD980536593 |
| Designated Facility Name: | Not reported |
| Designated Facility Mail Street Number: | 1 |
| Designated Facility Mail Street 1: | Not reported |
| Designated Facility Mail Street 2: | 1 EDEN LANE |
| Designated Facility Mail City: | FLANDERS |
| Designated Facility Mail Zip: | 07836 |
| Designated Facility Mail State: | NJ |
| Designated Facility Location Street Number: | 1 |
| Designated Facility Location Street 1: | 1 EDEN LANE |
| Designated Facility Location Street 2: | Not reported |
| Designated Facility Location City: | FLANDERS |
| Designated Facility Location Zip: | 07836 |
| Designated Facility Location State: | NJ |
| Designated Facility Contact Company Name: | Veolia Es Technical Solutions Llc |
| Manifest Residue Indicator: | N |
| Rejection Indicator: | N |

| | |
|---|---|
| Manifest Tracking Number: | 001885749VES |
| Last Updated Date: | 20210223 |
| Shipped Date: | 20210216 |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Received Date: | 20210216 |
| Manifest Status: | Signed |
| Submission Type: | DataImage5Copy |
| Origin Type: | Service |
| Generator EPA ID: | NYD982718272 |
| Generator Name: | J & F Chatsworth Auto Body |
| Generator Location Street Number: | Not reported |
| Generator Location Street 1: | 1 VINE ST |
| Generator Location Street 2: | Not reported |
| Generator Location City: | LARCHMONT |
| Generator Location State: | NY |
| Generator Location Zip: | 10538-2328 |
| Generator Mail Street Number: | Not reported |
| Generator Mail Street 1: | 1 VINE ST |
| Generator Mail Street 2: | Not reported |
| Generator Mail City: | LARCHMONT |
| Generator Mail Zip: | 10538-2328 |
| Generator Mail State: | NY |
| Generator Contact Company Name: | Not reported |
| Designated Facility EPA ID: | NJD980536593 |
| Designated Facility Name: | Not reported |
| Designated Facility Mail Street Number: | 1 |
| Designated Facility Mail Street 1: | 1 EDEN LANE |
| Designated Facility Mail Street 2: | L.L.C. |
| Designated Facility Mail City: | FLANDERS |
| Designated Facility Mail Zip: | 07836 |
| Designated Facility Mail State: | NJ |
| Designated Facility Location Street Number: | 1 |
| Designated Facility Location Street 1: | L.L.C. |
| Designated Facility Location Street 2: | 1 EDEN LANE |
| Designated Facility Location City: | FLANDERS |
| Designated Facility Location Zip: | 07836 |
| Designated Facility Location State: | NJ |
| Designated Facility Contact Company Name: | Veolia Es Technical Solutions |
| Manifest Residue Indicator: | N |
| Rejection Indicator: | N |

| | |
|---|---|
| Manifest Tracking Number: | 002079850VES |
| Last Updated Date: | 20221115 |
| Shipped Date: | 20221104 |
| Received Date: | 20221107 |
| Manifest Status: | Signed |
| Submission Type: | DataImage5Copy |
| Origin Type: | Service |
| Generator EPA ID: | NYD982718272 |
| Generator Name: | J & F Chatsworth Auto Body |
| Generator Location Street Number: | Not reported |
| Generator Location Street 1: | 1 VINE ST |
| Generator Location Street 2: | Not reported |
| Generator Location City: | LARCHMONT |
| Generator Location State: | NY |
| Generator Location Zip: | 10538-2328 |
| Generator Mail Street Number: | Not reported |
| Generator Mail Street 1: | 1 VINE ST |
| Generator Mail Street 2: | Not reported |
| Generator Mail City: | LARCHMONT |
| Generator Mail Zip: | 10538-2328 |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Generator Mail State: | NY |
| Generator Contact Company Name: | Not reported |
| Designated Facility EPA ID: | NJD980536593 |
| Designated Facility Name: | Not reported |
| Designated Facility Mail Street Number: | 1 |
| Designated Facility Mail Street 1: | 1 EDEN LANE |
| Designated Facility Mail Street 2: | L.L.C. |
| Designated Facility Mail City: | FLANDERS |
| Designated Facility Mail Zip: | 07836 |
| Designated Facility Mail State: | NJ |
| Designated Facility Location Street Number: | 1 |
| Designated Facility Location Street 1: | L.L.C. |
| Designated Facility Location Street 2: | 1 EDEN LANE |
| Designated Facility Location City: | FLANDERS |
| Designated Facility Location Zip: | 07836 |
| Designated Facility Location State: | NJ |
| Designated Facility Contact Company Name: | Veolia Es Technical Solutions |
| Manifest Residue Indicator: | N |
| Rejection Indicator: | N |

| | |
|---|---|
| Manifest Tracking Number: | 009021258SKS |
| Last Updated Date: | 20250615 |
| Shipped Date: | 20250430 |
| Received Date: | 20250526 |
| Manifest Status: | Signed |
| Submission Type: | DataImage5Copy |
| Origin Type: | Service |
| Generator EPA ID: | NYD982718272 |
| Generator Name: | J&F Chatsworth Ltd Auto Repair |
| Generator Location Street Number: | 1 |
| Generator Location Street 1: | 1 VINE ST |
| Generator Location Street 2: | Not reported |
| Generator Location City: | LARCHMONT |
| Generator Location State: | NY |
| Generator Location Zip: | 10538 |
| Generator Mail Street Number: | 1 |
| Generator Mail Street 1: | VINE ST |
| Generator Mail Street 2: | Not reported |
| Generator Mail City: | LARCHMONT |
| Generator Mail Zip: | 10538 |
| Generator Mail State: | NY |
| Generator Contact Company Name: | J&F CHATSWORTH LTD AUTO REPAIR |
| Designated Facility EPA ID: | ARD069748192 |
| Designated Facility Name: | Clean Harbors El Dorado Llc |
| Designated Facility Mail Street Number: | 301 |
| Designated Facility Mail Street 1: | Not reported |
| Designated Facility Mail Street 2: | 309 AMERICAN CIRCLE |
| Designated Facility Mail City: | EL DORADO |
| Designated Facility Mail Zip: | 71730 |
| Designated Facility Mail State: | AR |
| Designated Facility Location Street Number: | 309 |
| Designated Facility Location Street 1: | AMERICAN CIRCLE |
| Designated Facility Location Street 2: | Not reported |
| Designated Facility Location City: | EL DORADO |
| Designated Facility Location Zip: | 71730 |
| Designated Facility Location State: | AR |
| Designated Facility Contact Company Name: | Not reported |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 009021258SKS
Transporter Line Number: 1
Transporter EPA ID: TXR000081205
Transporter Name: Safety-Kleen Systems, Inc.

Manifest Tracking Number: 009021258SKS
Transporter Line Number: 2
Transporter EPA ID: MAD039322250
Transporter Name: Clean Harbors Environmental Services, Inc.

Waste Line:
Manifest Tracking Number: 009021258SKS
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA1993
U.S. DOT Description: Na1993, Waste Fuel Oil Mixture, 3, Pg Iii
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DF
Container Type Description: Fiberboard or plastic drums, barrels, kegs
Waste Quantity: 55
Quantity Unit of Measure Code: G
Quantity Unit of Measure Description: Gallons
Waste Quantity, in Tons: 0.22936
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.22936
Waste Quantity, in Kilograms: 208.0344
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 208.0364008
Management Method Code: H040
Management Method Description: INCINERATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D001, D018
Quantity Haz Kg: 208.0364008
Quantity Haz Tons: 0.22936
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: NY-B

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYD982718272 |
| Country: | USA |
| Name: | J & F Chatsworth |
| Address: | 1 VINE ST |
| Address 2: | Not reported |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Zip 4: | Not reported |
| Location Address 1: | 1 VINE ST. ATTN: BODY SHOP MGR |
| Location Address 2: | Not reported |
| Location City,State,Zip: | LARCHMONT, NY 10538 |
| Location Zip 4: | Not reported |
| Facility Status: | Not reported |
| Total Tanks: | Not reported |
| Code: | BP |

Mailing:

| | |
|---|---|
| Mailing Name: | J & F Chatsworth |
| Mailing Contact: | J & F Chatsworth |
| Mailing Address 1: | 1 VINE ST. ATTN;BODY SHOP MGR |
| Mailing Address 2: | Not reported |
| Mailing City,State,Zip: | LARCHMONT, NY 10538 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 9148340008 |

Manifest Data:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD080631369 |
| Year: | 2018 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 08/16/2010 |
| Trans1 Recv Date: | 08/16/2010 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 08/16/2010 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982718272 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD980536593 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 000431611VES |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H141 |
| Waste Code a: | The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| | Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code b: | Ignitable Waste |
| Waste Code c: | The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code e: | Methyl Ethyl Ketone |
| Waste Code f: | Not reported |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 800 |
| Units: | Pounds |
| Number of Containers: | 2 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 1 |
| | |
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD080631369 |
| Year: | 2018 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 12/28/2011 |
| Trans1 Recv Date: | 12/28/2011 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/29/2011 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982718272 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD980536593 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 000530807VES |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H141 |
| Waste Code a: | The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code b: | Ignitable Waste |
| Waste Code c: | Not reported |
| Waste Code e: | The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code f: | Methyl Ethyl Ketone |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 450 |
| Units: | Pounds |
| Number of Containers: | 1 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 1 |
| | |
| Document ID: | MAK0292680 |
| Manifest Status: | Not reported |
| Trans1 State ID: | P298709IL |
| Year: | 1998 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 12/10/1998 |
| Trans1 Recv Date: | 12/10/1998 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/14/1998 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982718272 |
| Trans1 EPA ID: | NJD080631369 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | MAD053452637 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00100 |
| Units: | Gallons (liquids only) |
| Number of Containers: | 001 |
| Container Type: | Cargo tanks (tank trucks) |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NJA0851210 |
| Manifest Status: | Not reported |
| Trans1 State ID: | 000000000 |
| Year: | 1990 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 02/21/1990 |
| Trans1 Recv Date: | 02/21/1990 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 02/22/1990 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982718272 |
| Trans1 EPA ID: | NJD980787147 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD002454544 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00195
Units: Gallons (liquids only)
Number of Containers: 001
Container Type: Cargo tanks (tank trucks)
Handling Method: Recycle
Specific Gravity: 01.00

Document ID: MAM1397630
Manifest Status: Not reported
Trans1 State ID: P298709IL
Year: 2001
Trans2 State ID: Not reported
Generator Ship Date: 12/12/2001
Trans1 Recv Date: 12/12/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/14/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982718272
Trans1 EPA ID: NJD080631369
Trans2 EPA ID: Not reported
TSDF ID 1: MAD053452637
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| | Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00085 |
| Units: | Gallons (liquids only) |
| Number of Containers: | 001 |
| Container Type: | Cargo tanks (tank trucks) |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | MAM1600760 |
| Manifest Status: | Not reported |
| Trans1 State ID: | P298709IL |
| Year: | 2002 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 07/02/2002 |
| Trans1 Recv Date: | 07/02/2002 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 07/11/2002 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982718272 |
| Trans1 EPA ID: | NJD080631369 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | MAD053452637 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00080 |
| Units: | Gallons (liquids only) |
| Number of Containers: | 001 |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Container Type: | Cargo tanks (tank trucks) |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD080631369 |
| Year: | 2018 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 05/02/2017 |
| Trans1 Recv Date: | 05/02/2017 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 05/02/2017 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982718272 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD980536593 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 001063122VES |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H141 |
| Waste Code a: | The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code b: | Ignitable Waste |
| Waste Code c: | Not reported |
| Waste Code e: | The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code f: | Methyl Ethyl Ketone |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 300 |
| Units: | Pounds |
| Number of Containers: | 2 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 1 |
| | |
| Document ID: | MAK0297480 |
| Manifest Status: | Not reported |
| Trans1 State ID: | P207083IL |
| Year: | 1997 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 12/15/1997 |
| Trans1 Recv Date: | 12/15/1997 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/17/1997 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982718272 |
| Trans1 EPA ID: | NJD080631369 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | MAD053452637 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00165 |
| Units: | Gallons (liquids only) |
| Number of Containers: | 001 |
| Container Type: | Cargo tanks (tank trucks) |
| Handling Method: | Burn |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Specific Gravity: | 01.00 |
| | |
| Document ID: | CTF0399136 |
| Manifest Status: | Not reported |
| Trans1 State ID: | P52018IL |
| Year: | 1995 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 05/15/1995 |
| Trans1 Recv Date: | 05/15/1995 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 05/17/1995 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982718272 |
| Trans1 EPA ID: | ILD099202681 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | CTD072138969 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 01042 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Cargo tanks (tank trucks) |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYB4306761 |
| Manifest Status: | Not reported |
| Trans1 State ID: | XAA8859NJ |
| Year: | 1994 |
| Trans2 State ID: | Not reported |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Generator Ship Date: | 12/13/1994 |
| Trans1 Recv Date: | 12/13/1994 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/16/1994 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982718272 |
| Trans1 EPA ID: | NYD980761191 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD082785429 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | Benzene |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 01200 |
| Units: | Pounds |
| Number of Containers: | 004 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Landfill |
| Specific Gravity: | 01.00 |

| | |
|---|---|
| Document ID: | CTF0908572 |
| Manifest Status: | Not reported |
| Trans1 State ID: | P298709IL |
| Year: | 2003 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 10/15/2003 |
| Trans1 Recv Date: | 10/15/2003 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 10/17/2003 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD982718272 |
| Trans1 EPA ID: | NJD080631369 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | CTD021816889 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00075 |
| Units: | Gallons (liquids only) |
| Number of Containers: | 001 |
| Container Type: | Cargo tanks (tank trucks) |
| Handling Method: | Treat |
| Specific Gravity: | 01.00 |

Click this hyperlink while viewing on your computer to access
21 additional NY MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

| | |
|---|---|
| EPA ID: | NYD982718272 |
| Name: | J & F CHATSWORTH LTD |
| Address: | 1 VINE STREET |
| City,State,Zip: | LARCHMONT, NY 10538 |
| County: | Not reported |
| Mailing Address: | Not reported |
| Mailing City,State,Zip: | Not reported |
| Telephone: | 9148340008 |
| Emergency Telephone: | Not reported |
| Contact: | Not reported |
| Comments: | Not reported |
| SIC Code: | Not reported |
| County: | 00 |
| Municipal: | 00 |
| Previous EPAID: | Not reported |
| Generator Flag: | X |
| Transporter Flag: | Not reported |
| TSDF Flag: | Not reported |
| Name Change: | Not reported |
| Date Change: | 000000 |

Manifest Data:

| | |
|---|---|
| EPA ID: | NYD982718272 |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Manifest Number: | 000564725VES |
| Date Shipped: | 9/14/2011 |
| TSDF EPA ID: | NJD980536593 |
| Transporter EPA ID: | NJD080631369 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Was Load Rejected: | Not reported |
| Reason Load Was Rejected: | Not reported |

Waste:

| | |
|---|---|
| Manifest Year: | Not reported |
| Waste Code: | F003 |
| Hand Code: | H141 |
| Quantity: | 800.00 |
| Unit: | Pounds |

| | |
|---|---|
| EPA ID: | NYD982718272 |
| Manifest Number: | 000431611VES |
| Date Shipped: | 08/16/2010 |
| TSDF EPA ID: | NJD980536593 |
| Transporter EPA ID: | NJD080631369 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 08/16/2010 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 08/16/2010 |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Was Load Rejected: | N |
| Reason Load Was Rejected: | Not reported |

Waste:

| | |
|---|---|
| Manifest Year: | Not reported |
| Waste Code: | F003 |
| Hand Code: | H141 |
| Quantity: | 800 |
| Unit: | P |

| | |
|---|---|
| EPA ID: | NYD982718272 |
| Manifest Number: | 000807409VES |
| Date Shipped: | 8/27/2013 |
| TSDF EPA ID: | NJD980536593 |
| Transporter EPA ID: | NJD080631369 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Was Load Rejected: | Not reported |
| Reason Load Was Rejected: | Not reported |

Waste:

| | |
|---|---|
| Manifest Year: | Not reported |
| Waste Code: | F003 D001 F005 D035 |
| Hand Code: | Not reported |
| Quantity: | 400.00 |
| Unit: | Pounds |

| | |
|---|---|
| Manifest Year: | Not reported |
| Waste Code: | F003 D001 F005 D035 |
| Hand Code: | Not reported |
| Quantity: | 400.00 |
| Unit: | Pounds |

| | |
|---|---|
| EPA ID: | NYD982718272 |
| Manifest Number: | 000807409VES |
| Date Shipped: | 8/27/2013 |
| TSDF EPA ID: | NJD980536593 |
| Transporter EPA ID: | NJD080631369 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Was Load Rejected: | Not reported |
| Reason Load Was Rejected: | Not reported |

Waste:

| | |
|---|---|
| Manifest Year: | Not reported |
| Waste Code: | F003 D001 F005 D035 |
| Hand Code: | Not reported |
| Quantity: | 400.00 |
| Unit: | Pounds |

| | |
|---|---|
| Manifest Year: | Not reported |
| Waste Code: | F003 D001 F005 D035 |
| Hand Code: | Not reported |
| Quantity: | 400.00 |
| Unit: | Pounds |

| | |
|---|---|
| EPA ID: | NYD982718272 |
| Manifest Number: | 000530807VES |
| Date Shipped: | 12/28/2011 |
| TSDF EPA ID: | NJD980536593 |
| Transporter EPA ID: | NJD080631369 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Was Load Rejected: | Not reported |
| Reason Load Was Rejected: | Not reported |

Waste:

| | |
|---|---|
| Manifest Year: | Not reported |
| Waste Code: | F003 |
| Hand Code: | H141 |
| Quantity: | 450.00 |
| Unit: | Pounds |

| | |
|---|---|
| EPA ID: | NYD982718272 |
| Manifest Number: | NJA5320339 |
| Date Shipped: | 08/29/2006 |
| TSDF EPA ID: | NJD980536593 |
| Transporter EPA ID: | NJD080631369 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | 08/29/2006 |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | 08/29/2006 |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |

**J & F CHATSWORTH AUTO BODY (Continued)** **1000113677**

| | |
|---|---|
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | 09280622 |
| Was Load Rejected: | N |
| Reason Load Was Rejected: | Not reported |

---

**A2** **MAGIC TOUCH CLEANERS** **EDR Hist Cleaner** **1020032815**
**Target** **1 VINE ST** **N/A**
**Property** **LARCHMONT, NY 10538**

**Site 2 of 14 in cluster A**

**Actual:** EDR Hist Cleaner
**41 ft.**

| Year: | Name: | Type: |
|---|---|---|
| 1995 | MAGIC TOUCH CLEANERS | Drycleaning Plants, Except Rugs, NEC |

---

**A3** **CHATSWORTH GARAGE INC** **EDR Hist Auto** **1021470908**
**Target** **1 VINE ST** **N/A**
**Property** **LARCHMONT, NY 10538**

**Site 3 of 14 in cluster A**

**Actual:** EDR Hist Auto
**41 ft.**

| Year: | Name: | Type: |
|---|---|---|
| 1969 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1970 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1971 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1972 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1973 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1974 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1975 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1976 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1977 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1978 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1979 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1980 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1982 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1983 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1985 | CHATSWORTH GARAGE INC | Gasoline Service Stations |
| 1992 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 1993 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 1994 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 1995 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 1996 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 1997 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 1998 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 1999 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2000 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2001 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2002 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2003 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2004 | J & F CHATSWORTH LTD | General Automotive Repair Shops |

**CHATSWORTH GARAGE INC (Continued)** **1021470908**

| | | |
|---|---|---|
| 2005 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2006 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2007 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2008 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2009 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2010 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2011 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2012 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2013 | J & F CHATSWORTH LTD | General Automotive Repair Shops |
| 2014 | J & F CHATSWORTH LTD | General Automotive Repair Shops |

---

**A4** **MARISIERO INC.** **NY LTANKS** **S100153891**
**Target** **1-5 VINE STREET** **N/A**
**Property** **LARCHMONT, NY**

**Site 4 of 14 in cluster A**

**Actual:** **41 ft.**

LTANKS:

| | |
|---|---|
| Name: | MARISIERO INC. |
| Address: | 1-5 VINE STREET |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9102813 / 1997-11-14 |
| Facility ID: | 9102813 |
| Site ID: | 88022 |
| Spill Date: | 1991-06-10 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1991-06-10 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Health Department |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1991-06-13 |
| Spill Record Last Update: | 1997-12-01 |
| Spiller Name: | Not reported |
| Spiller Company: | JOE SPERANO |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 80580 |
| Latitude: | 40.9353841 |
| Longitude: | -73.7585846 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY |
| Remarks: | TANK LEAKED IN BASEMENT OIL IN SUMP PUMP AND PUMPED TO SEWER PADS APPLIED AND BARRIER HIRED TO CLEAN UP SPILL |

**MARISIERO INC. (Continued)** **S100153891**

All Materials:

| | |
|---|---|
| Site ID: | 88022 |
| Operable Unit ID: | 956692 |
| Operable Unit: | 01 |
| Material ID: | 425300 |
| Material Code: | 0022 |
| Material Name: | waste oil/used oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 30.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**A5** **JS CHADWORTHS** **NY Spills** **S117852880**
**Target** **1 VINE ST** **N/A**
**Property** **LARCHMONT, NY**

**Site 5 of 14 in cluster A**

**Actual:** **41 ft.**

SPILLS:

| | |
|---|---|
| Name: | JS CHADWORTHS |
| Address: | 1 VINE ST |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1501291 / 2015-07-08 |
| Facility ID: | 1501291 |
| Facility Type: | ER |
| DER Facility ID: | 462241 |
| Site ID: | 507486 |
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | C4 |
| SWIS: | 6032 |
| Spill Date: | 2015-05-05 |
| Investigator: | RDBENDEL |
| Referred To: | Not reported |
| Reported to Dept: | 2015-05-05 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2015-05-05 |
| Spill Record Last Update: | 2015-09-01 |
| Spiller Name: | Not reported |
| Spiller Company: | CHADSWORTH |
| Spiller Address: | Not reported |
| Spiller Company: | 999 |
| Contact Name: | MIKE CARR |
| Latitude: | Not reported |
| Longitude: | Not reported |

**JS CHADWORTHS (Continued)** **S117852880**

DEC Memo: Received an email from C Lalak, WCDOH. American Petroleum has a permit to pull tanks, Denise,
WCDOH, is on site...mm From WCHD 2 UST s (DW Steel with Sac. Anode installed 1995)removed at this
former gas station 3-174394 (now repair shop) on 5/5 & 5/7/15. Spill called in due to elevated PID
reading s during excavation. Upon removal both tanks sound no leaks. APECCO removed 11 tons
impacted soil. Discovered that tanks were actually installed inside lower level of building s
foundation & surrounded by 4 concrete walls & bottom no end point samples available. Any excavation
beyond foundation would comprise structure & roadway. 07-08-15 TCR, NFA RDB

Remarks: cleanup in progress

All Materials:

| | |
|---|---|
| Site ID: | 507486 |
| Operable Unit ID: | 1256819 |
| Operable Unit: | 01 |
| Material ID: | 2259781 |
| Material Code: | 0009 |
| Material Name: | gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**A6** **J & F CHATSWORTH GAS STA** **UST FINDER RELEASE** **1029076989**
**Target** **1 VINE STREET** **N/A**
**Property** **LARCHMONT, NY 0**

**Site 6 of 14 in cluster A**

**Actual:**
**41 ft.**

UST FINDER RELEASE:

| | |
|---|---|
| Object ID: | 262710 |
| Facility ID: | NY61873 |
| Lust ID: | NY9410303 |
| Name: | J & F CHATSWORTH GAS STA |
| Address: | 1 VINE STREET |
| City,State,Zip: | LARCHMONT, NY 0 |
| Address Match Type: | Not reported |
| Reported Date: | 1994/11/02 15:59:59+00 |
| Status: | No Further Action |
| Substance: | Not reported |
| Population within 1500ft: | 2505 |
| Domestic Wells within 1500ft: | 0 |
| Land Use: | Developed, High Intensity |
| Within SPA: | No |
| SPA PWS Facility ID: | Not reported |
| SPA Water Type: | Not reported |
| SPA Facility Type: | Not reported |
| SPA HUC12: | Not reported |
| Within WHPA: | No |
| WHPA PWS Facility ID: | Not reported |

**J & F CHATSWORTH GAS STA (Continued)** **1029076989**

| | |
|---|---|
| WHPA Water Type: | Not reported |
| WHPA Facility Type: | Not reported |
| WHPA HUC12: | Not reported |
| Within 100yr Floodplain: | No |
| Tribe: | Not reported |
| EPA Region: | 2 |
| NFA Letter 1: | Not reported |
| NFA Letter 2: | Not reported |
| NFA Letter 3: | Not reported |
| NFA Letter 4: | Not reported |
| Closed With Residual Contaminate: | Not reported |
| Coordinate Source: | State |
| X Coord: | -73.75848 |
| Y Coord: | 40.9353300000001 |
| Latitude: | 40.93533 |
| Longitude: | -73.75848 |

---

**A7** **J & F CHATSWORTH LTD.** **NY UST U003884522**
**Target** **1 VINE STREET** **NY AST N/A**
**Property** **LARCHMONT, NY 10538**

**Site 7 of 14 in cluster A**

**Actual:** **41 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | J & F CHATSWORTH LTD. |
| Address: | 1 VINE STREET |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-174394 / Active |
| Operator Name: | Giuseppe Sparano |
| Owner Name: | Giuseppe Sparano |
| Owner Street: | 1 Vine Street |
| Owner Address2: | Not reported |
| Owner City: | Larchmont |
| Owner State: | NY |
| Owner Zipcode: | 10538 |
| GDS Number: | 3553200241 |
| | |
| Tank Number: | 1 |
| Status: | 3. Closed - Removed |
| Capacity: | 4000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 1. Electronic Interstitial Monitoring |
| Date Installation: | 04/01/1995 |
| Date Perm Closure: | 05/05/2015 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 2. Original sacrificial anode |
| Tank Secondary Containment: | 4. Double-Walled (underground only) |
| Piping Location: | 2. Underground/on Ground |
| Piping Type: | 6. Fiberglass Reinforced Plastic (FRP) |
| Piping External Protection: | 4. Fiberglass |
| Overfill Prevention: | 2. High Level Alarm |
| Piping Secondary Containment: | 0. None |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

**J & F CHATSWORTH LTD. (Continued)** **U003884522**

| | |
|---|---|
| Tank Number: | 1old |
| Status: | 3. Closed - Removed |
| Capacity: | 2000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 08/01/1981 |
| Date Perm Closure: | 04/01/1995 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 2 |
| Status: | 3. Closed - Removed |
| Capacity: | 4000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 1. Electronic Interstitial Monitoring |
| Date Installation: | 04/01/1995 |
| Date Perm Closure: | 05/07/2015 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 2. Original sacrificial anode |
| Tank Secondary Containment: | 4. Double-Walled (underground only) |
| Piping Location: | 2. Underground/on Ground |
| Piping Type: | 6. Fiberglass Reinforced Plastic (FRP) |
| Piping External Protection: | 4. Fiberglass |
| Overfill Prevention: | 2. High Level Alarm |
| Piping Secondary Containment: | 0. None |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 2 old |
| Status: | 3. Closed - Removed |
| Capacity: | 2000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 08/01/1981 |
| Date Perm Closure: | 04/01/1995 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |

**J & F CHATSWORTH LTD. (Continued)** **U003884522**

| | |
|---|---|
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 3 old |
| Status: | 3. Closed - Removed |
| Capacity: | 2000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 08/01/1981 |
| Date Perm Closure: | 04/01/1995 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 4 old |
| Status: | 3. Closed - Removed |
| Capacity: | 2000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 08/01/1981 |
| Date Perm Closure: | 04/01/1995 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 5 old |
| Status: | 3. Closed - Removed |
| Capacity: | 2000 |
| Product Stored: | 0009. Gasoline |

**J & F CHATSWORTH LTD. (Continued)** **U003884522**

| | |
|---|---|
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 08/01/1981 |
| Date Perm Closure: | 04/01/1995 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 6 old |
| Status: | 3. Closed - Removed |
| Capacity: | 2000 |
| Product Stored: | 0008. Diesel |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 08/01/1981 |
| Date Perm Closure: | 04/01/1995 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | J & F CHATSWORTH LTD. |
| Address: | 1 VINE STREET |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-174394 |
| Site Status: | Active |
| GDS Number: | 3553200241 |
| Operator Name: | Giuseppe Sparano |
| Owner Name: | Giuseppe Sparano |
| Owner Street: | 1 Vine Street |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | Larchmont, NY 10538 |

| | |
|---|---|
| Tank Number: | 3 |
| Status: | 1. In-Service |
| Date Installation: | 01/01/1999 |
| Capacity: | 250 |
| Product Stored: | 0015. Motor Oil |

**J & F CHATSWORTH LTD. (Continued)** **U003884522**

| | |
|---|---|
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating,SW LUBE CUBE LOCATED INSIDE SHOP |
| Tank Leak Detection: | 6. Impervious Barrier/Concrete Pad (Aboveground Only) |
| Tank Secondary Containment: | 1. Diking (aboveground only),10. Impervious Underlayment (AST Only) |
| Piping Location: | Not reported |
| Piping Type: | Not reported |
| Piping External Protection: | Not reported |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | Not reported |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only) |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 1. Submersible |

| | |
|---|---|
| Tank Number: | 4 |
| Status: | 1. In-Service |
| Date Installation: | 01/01/1996 |
| Capacity: | 250 |
| Product Stored: | 2642. Used Oil (Heating) |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating,SW LUBE CUBE LOCATED INSIDE SHOP |
| Tank Leak Detection: | 6. Impervious Barrier/Concrete Pad (Aboveground Only) |
| Tank Secondary Containment: | 1. Diking (aboveground only),10. Impervious Underlayment (AST Only) |
| Piping Location: | Not reported |
| Piping Type: | Not reported |
| Piping External Protection: | Not reported |
| Piping Leak Detection: | Not reported |
| Piping Secondary Containment: | Not reported |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only) |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 1. Submersible |

---

**A8** **JF CHATSWORTH** **NY LTANKS S102110180**
**Target** **1 VINE STREET** **NY Spills N/A**
**Property** **LARCHMONT, NY**

**Site 8 of 14 in cluster A**

**Actual:** **41 ft.**

LTANKS:

| | |
|---|---|
| Name: | J & F CHATSWORTH GAS STA |
| Address: | 1 VINE STREET |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9410303 / 2005-02-27 |
| Facility ID: | 9410303 |
| Site ID: | 64161 |
| Spill Date: | 1994-11-02 |
| Spill Cause: | Tank Failure |
| Spill Source: | Gasoline Station or other PBS Facility |
| Spill Class: | B3 |
| Cleanup Ceased: | Not reported |

**JF CHATSWORTH (Continued)** **S102110180**

| | |
|---|---|
| SWIS: | 6000 |
| Investigator: | WXWADSWO |
| Referred To: | Not reported |
| Reported to Dept: | 1994-11-02 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Health Department |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | True |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-12-02 |
| Spill Record Last Update: | 2005-02-27 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 61873 |
| Latitude: | 40.9353299 |
| Longitude: | -73.7584840 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 02/27/05 LUZON REPORTEDLY COMPLETED CLEAN UP. FILE ADMINISTRATIVELY CLOSED. jod |
| Remarks: | CONTRACTOR (LUZON) ENROUTE TO CLEAN UP |

All Materials:

| | |
|---|---|
| Site ID: | 64161 |
| Operable Unit ID: | 1008064 |
| Operable Unit: | 01 |
| Material ID: | 376176 |
| Material Code: | 0009 |
| Material Name: | gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | Not reported |
| Recovered: | .00 |
| Oxygenate: | Not reported |

SPILLS:

| | |
|---|---|
| Name: | JF CHATSWORTH |
| Address: | 1 VINE STREET |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9413519 / 1995-01-23 |
| Facility ID: | 9413519 |
| Facility Type: | ER |
| DER Facility ID: | 61873 |
| Site ID: | 64162 |
| DEC Region: | 3 |
| Spill Cause: | Human Error |
| Spill Class: | C3 |

**JF CHATSWORTH (Continued)** **S102110180**

| | |
|---|---|
| SWIS: | 6000 |
| Spill Date: | 1995-01-10 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1995-01-10 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Tank Truck |
| Spill Notifier: | Fire Department |
| Cleanup Ceased: | 1995-01-23 |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-12-02 |
| Spill Record Last Update: | 2003-12-02 |
| Spiller Name: | Not reported |
| Spiller Company: | BARNER OIL |
| Spiller Address: | Not reported |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Latitude: | 40.9353289 |
| Longitude: | -73.7584787 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY |
| Remarks: | FILL HOSE SLIPPED OUT OF DRIVER HAND SPILL HAS BEEN CLEANED UP |

All Materials:

| | |
|---|---|
| Site ID: | 64162 |
| Operable Unit ID: | 1011074 |
| Operable Unit: | 01 |
| Material ID: | 372268 |
| Material Code: | 0009 |
| Material Name: | gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 4.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**A9** **J & F CHATSWORTH AUTO BODY** **US AIRS 1012092493**
**Target** **3 VINE ST** **FINDS N/A**
**Property** **LARCHMONT, NY 10538** **ECHO**

**Site 9 of 14 in cluster A**

**Actual:** **41 ft.**

US AIRS MINOR:

| | |
|---|---|
| Envid: | 1012092493 |
| Region Code: | 02 |
| Programmatic ID: | AIR NY0000003553200136 |
| Facility Registry ID: | 110019224409 |
| D and B Number: | Not reported |
| Primary SIC Code: | 7532 |
| NAICS Code: | 811121 |
| Default Air Classification Code: | MIN |

**J & F CHATSWORTH AUTO BODY (Continued)** **1012092493**

Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000003553200136
Facility Registry ID: 110019224409
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-02-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:
Registry ID: 110019224409

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1012092493
Registry ID: 110019224409

DFR URL:
Name: J & F CHATSWORTH AUTO BODY
Address: 3 Vine St
City,State,Zip: LARCHMONT, NY 10538

**A10** **J & F CHATSWORTH AUTO BODY** **NY AIRS** **S121490474**
**Target** **3 VINE ST** **N/A**
**Property** **LARCHMONT, NY 10538**

**Site 10 of 14 in cluster A**

**Actual:** AIRS:
**41 ft.**

| | |
|---|---|
| Name: | J & F CHATSWORTH AUTO BODY |
| Address: | 3 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 |
| DECID: | 3553200136 |
| Process ID: | Not reported |
| Latitude: | Not reported |
| Longitude: | Not reported |
| FIPS Code: | Not reported |
| Auth Type Code: | AFR |
| Permit Status: | Issued |
| Auth Status Code: | 2 |
| Emissions: | Not reported |
| Issue date: | 03/02/2009 |
| Expired Date: | Not reported |
| Emission Unit date: | Not reported |
| Contamination: | Not reported |
| EPA Control Code: | Not reported |
| Control Eff: | Not reported |
| Unit: | Not reported |

---

**A11** **MAGIC TOUCH CLEANERS** **FINDS** **1016071092**
**Target** **5 VINE STREET** **ECHO** **N/A**
**Property** **LARCHMONT, NY 10538**

**Site 11 of 14 in cluster A**

**Actual:** FINDS:
**41 ft.**
Registry ID: 110004313975

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

**MAGIC TOUCH CLEANERS (Continued)** **1016071092**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016071092
Registry ID: 110004313975

DFR URL:
Name: MAGIC TOUCH CLEANERS
Address: 5 Vine Street
City,State,Zip: LARCHMONT, NY 10538

---

**A12** **KIM KWUNG** **EDR Hist Cleaner** **1018463930**
**Target** **5 VINE ST** **N/A**
**Property** **LARCHMONT, NY 10538**

**Site 12 of 14 in cluster A**

**Actual:** **41 ft.**

EDR Hist Cleaner

| Year: | Name: | Type: |
|---|---|---|
| 1971 | MICHELS FRENCY DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1972 | MICHELS FRENCY DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1973 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1974 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1976 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1977 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1978 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1979 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1980 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1982 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1983 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1985 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1986 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1987 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1988 | MICHELS FRENCH DRY CLEANING | Drycleaning Plants, Except Rugs |
| 1989 | ANNA MARIAS CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1990 | ANNA MARIAS CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1991 | ANNA MARIAS CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1992 | ANNA MARIAS CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1993 | ANNA MARIAS CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1996 | MAGIC TOUCH CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1997 | MAGIC TOUCH CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1998 | MAGIC TOUCH CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 1999 | MAGIC TOUCH CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 2000 | MAGIC TOUCH CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 2001 | MAGIC TOUCH CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 2002 | MAGIC TOUCH CLEANERS | Drycleaning Plants, Except Rugs, NEC |
| 2003 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2004 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2005 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2006 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2007 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2008 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2009 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2010 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2011 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |

**KIM KWUNG (Continued)** **1018463930**

| | | |
|---|---|---|
| 2012 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2013 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |
| 2014 | KIM KWUNG | Drycleaning Plants, Except Rugs, NEC |

---

**A13** **MAGIC TOUCH CLEANERS** **RCRA NonGen / NLR** **1000890004**
**Target** **5 VINE ST** **ICIS** **NY0000204958**
**Property** **LARCHMONT, NY 10538** **US AIRS**
**NY DRYCLEANERS**
**Site 13 of 14 in cluster A** **NY MANIFEST**

**Actual:**
**41 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20070101 |
| Handler Name: | | Magic Touch |
| Handler Address: | | Vine St |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NY0000204958 |
| Contact Name: | | KWANG KIM |
| Contact Address: | | VINE ST |
| Contact City,State,Zip: | | LARCHMONT, NY 10538 |
| Contact Telephone: | | 917-834-8880 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | Ny |
| State District: | | NYSDEC R3 |
| Mailing Address: | | VINE ST |
| Mailing City,State,Zip: | | LARCHMONT, NY 10538 |
| Owner Name: | Yoon S Kim | |
| Owner Type: | | Private |
| Operator Name: | Yoon S Kim | |
| Operator Type: | | Private |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | | No |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20150414 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | D000 |
| Waste Description: | Not Defined |
| Waste Code: | D001 |
| Waste Description: | Ignitable Waste |
| Waste Code: | D007 |
| Waste Description: | Chromium |
| Waste Code: | D008 |
| Waste Description: | Lead |
| Waste Code: | D039 |
| Waste Description: | Tetrachloroethylene |
| Waste Code: | D040 |
| Waste Description: | Trichloroethylene |
| Waste Code: | F002 |
| Waste Description: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |

Handler - Owner Operator:

| | |
|---|---|
| Owner/Operator Indicator: | Operator |
| Owner/Operator Name: KWANG JIN KIM | |
| Legal Status: | Private |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 175 HALSTEAD AVE
Owner/Operator City,State,Zip: HARRISON, NY 10528
Owner/Operator Telephone: 914-834-8880
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: YOON S KIM
Legal Status: Private
Date Became Current: 19961101
Date Ended Current: Not reported
Owner/Operator Address: 330 FORT LEE RD
Owner/Operator City,State,Zip: LEONIA, NJ 07605
Owner/Operator Telephone: 201-944-4638
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: KWANG JIN KIM
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 175 HALSTEAD AVE
Owner/Operator City,State,Zip: HARRISON, NY 10528
Owner/Operator Telephone: 914-834-8880
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: KWANG JIN KIM
Legal Status: Private
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 175 HALSTEAD AVE
Owner/Operator City,State,Zip: HARRISON, NY 10528
Owner/Operator Telephone: 914-834-8880
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: YOON S KIM
Legal Status: Private
Date Became Current: 19961101
Date Ended Current: Not reported
Owner/Operator Address: 330 FORT LEE RD
Owner/Operator City,State,Zip: LEONIA, NJ 07605
Owner/Operator Telephone: 201-944-4638
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: YOON S KIM | |
| Legal Status: | Private |
| Date Became Current: | 19961101 |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 330 FORT LEE RD |
| Owner/Operator City,State,Zip: | LEONIA, NJ 07605 |
| Owner/Operator Telephone: | 201-944-4638 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

Historic Generators:

| | |
|---|---|
| Receive Date: | 19990714 |
| Handler Name: MAGIC TOUCH | |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20060101 |
| Handler Name: MAGIC TOUCH | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20070101 |
| Handler Name: MAGIC TOUCH | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 19961114 |
| Handler Name: MAGIC TOUCH | |
| Federal Waste Generator Description: | Large Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20001122
Handler Name: MAGIC TOUCH
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ICIS:
Enforcement Action ID: NY000A0000355320031300308
FRS ID: 110004313975
Action Name: MAGIC TOUCH CLEANERS 36119R232000308
Facility Name: MAGIC TOUCH CLEANERS
Facility Address: 5 VINE ST
LARCHMONT, NY 105382328
Enforcement Action Type: Notice of Violation
Facility County: WESTCHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.935512
Longitude in Decimal Degrees: -73.758465
Permit Type Desc: Not reported
Program System Acronym: NY0000003553200313
Facility NAICS Code: 812320
Tribal Land Code: Not reported

US AIRS MINOR:
Envid: 1000890004

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

Region Code: 02
Programmatic ID: AIR NY0000003553200313
Facility Registry ID: 110004313975
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000003553200313
Facility Registry ID: 110004313975
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-12-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200313
Facility Registry ID: 110004313975
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2006-04-27 00:00:00
Activity Status Date: 2006-04-27 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000003553200313
Facility Registry ID: 110004313975
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-12-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

DRYCLEANERS:
Name: MAGIC TOUCH CLEANERS
Address: 5 VINE ST
City,State,Zip: LARCHMONT, NY 10538 2328
Facility ID: 3-5532-00313
Phone Number: 9148348880
Region: Not reported
Registration Effective Date: 03/10/2004

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Inspection Date: | 12/06/2000 |
| Install Date: | Not reported |
| Expiration Date: | 05/03/2019 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 03/10/2004 |
| Inspection Date: | 12/14/2001 |
| Install Date: | Not reported |
| Expiration Date: | 05/03/2019 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 03/10/2004 |
| Inspection Date: | 12/13/2002 |
| Install Date: | Not reported |
| Expiration Date: | 05/03/2019 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 05/03/2019 |
| Inspection Date: | 12/06/2000 |
| Install Date: | Not reported |
| Expiration Date: | 05/03/2029 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 05/03/2019 |
| Inspection Date: | 12/14/2001 |
| Install Date: | Not reported |
| Expiration Date: | 05/03/2029 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 05/29/2003 |
| Inspection Date: | 12/13/2002 |
| Install Date: | Not reported |
| Expiration Date: | 06/11/2003 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 12/11/2000 |
| Inspection Date: | 12/06/2000 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2003 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | MAGIC TOUCH CLEANERS |
| Address: | 5 VINE ST |
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 12/11/2000 |
| Inspection Date: | 12/14/2001 |
| Install Date: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

Expiration Date: 05/29/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec.
Current Business: Not reported

Name: MAGIC TOUCH CLEANERS
Address: 5 VINE ST
City,State,Zip: LARCHMONT, NY 10538 2328
Facility ID: 3-5532-00313
Phone Number: 9148348880
Region: Not reported
Registration Effective Date: 12/11/2000
Inspection Date: 12/13/2002
Install Date: Not reported
Expiration Date: 05/29/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec.
Current Business: Not reported

Name: MAGIC TOUCH CLEANERS
Address: 5 VINE ST
City,State,Zip: LARCHMONT, NY 10538 2328
Facility ID: 3-5532-00313
Phone Number: 9148348880
Region: Not reported
Registration Effective Date: 05/29/2003
Inspection Date: 12/06/2000
Install Date: Not reported
Expiration Date: 06/11/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec.
Current Business: Not reported

Name: MAGIC TOUCH CLEANERS
Address: 5 VINE ST
City,State,Zip: LARCHMONT, NY 10538 2328
Facility ID: 3-5532-00313
Phone Number: 9148348880
Region: Not reported
Registration Effective Date: 05/29/2003
Inspection Date: 12/14/2001
Install Date: Not reported
Expiration Date: 06/11/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec.
Current Business: Not reported

Name: MAGIC TOUCH CLEANERS
Address: 5 VINE ST

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| City,State,Zip: | LARCHMONT, NY 10538 2328 |
| Facility ID: | 3-5532-00313 |
| Phone Number: | 9148348880 |
| Region: | Not reported |
| Registration Effective Date: | 05/03/2019 |
| Inspection Date: | 12/13/2002 |
| Install Date: | Not reported |
| Expiration Date: | 05/03/2029 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SB-32 GreenEarth; CAS 541-02-6, decamethylcyclopentasiloxane, Gen. Elec. |
| Current Business: | Not reported |

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NY0000204958 |
| Country: | USA |
| Name: | Magic Touch Clnrs |
| Address: | 5 VINE ST |
| Address 2: | Not reported |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Zip 4: | Not reported |
| Location Address 1: | 5 VINE ST |
| Location Address 2: | Not reported |
| Location City,State,Zip: | LARCHMONT, NY 10538 |
| Location Zip 4: | Not reported |
| Facility Status: | Not reported |
| Total Tanks: | Not reported |
| Code: | BP |

Mailing:

| | |
|---|---|
| Mailing Name: | Magic Touch Clnrs |
| Mailing Contact: | Yoon Kim |
| Mailing Address 1: | 5 VINE ST |
| Mailing Address 2: | Not reported |
| Mailing City,State,Zip: | LARCHMONT, NY 10538 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 9148348880 |

Manifest Data:

| | |
|---|---|
| Document ID: | NYC3126003 |
| Manifest Status: | Not reported |
| Trans1 State ID: | GP2381NY |
| Year: | 1994 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 06/24/1994 |
| Trans1 Recv Date: | 06/24/1994 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 06/24/1994 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000204958 |
| Trans1 EPA ID: | ILD984908202 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00060 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

| | |
|---|---|
| Document ID: | NYC5785064 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR2436 |
| Year: | 2001 |
| Trans2 State ID: | M0001 |
| Generator Ship Date: | 05/21/2001 |
| Trans1 Recv Date: | 05/21/2001 |
| Trans2 Recv Date: | 05/25/2001 |
| TSD Site Recv Date: | 05/26/2001 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000204958 |
| Trans1 EPA ID: | SCR000075150 |
| Trans2 EPA ID: | MOD095038998 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00390 |
| Units: | Pounds |
| Number of Containers: | 002 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC5528452 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR2436 |
| Year: | 1999 |
| Trans2 State ID: | NJT913LY |
| Generator Ship Date: | 01/25/1999 |
| Trans1 Recv Date: | 01/25/1999 |
| Trans2 Recv Date: | 01/28/1999 |
| TSD Site Recv Date: | 02/01/1999 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000204958 |
| Trans1 EPA ID: | ILD984908202 |
| Trans2 EPA ID: | SCD987574647 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| | Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00120 |
| Units: | Pounds |
| Number of Containers: | 002 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| Waste Code 7: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 8: | Not reported |
| Waste Code: | Not reported |
| Waste Code 10: | Not reported |
| Waste Code 11: | Not reported |
| Quantity: | 00195 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC3604746 |
| Manifest Status: | Not reported |
| Trans1 State ID: | GT9066 |
| Year: | 1995 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 07/19/1995 |
| Trans1 Recv Date: | 07/19/1995 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 07/19/1995 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000204958 |
| Trans1 EPA ID: | ILD984908202 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00180 |
| Units: | Pounds |
| Number of Containers: | 003 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | CTF0607216 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR2436 |
| Year: | 1997 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 03/26/1997 |
| Trans1 Recv Date: | 03/26/1997 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 03/31/1997 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000204958 |
| Trans1 EPA ID: | ILD984908202 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | CTD001156009 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| | Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00060 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| Waste Code 7: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 8: | Not reported |
| Waste Code: | Not reported |
| Waste Code 10: | Not reported |
| Waste Code 11: | Not reported |
| Quantity: | 00060 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC5915226 |
| Manifest Status: | Not reported |
| Trans1 State ID: | AV4489 |
| Year: | 1999 |
| Trans2 State ID: | T422NXNJ |
| Generator Ship Date: | 09/08/1999 |
| Trans1 Recv Date: | 09/08/1999 |
| Trans2 Recv Date: | 09/13/1999 |
| TSD Site Recv Date: | 09/16/1999 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000204958 |
| Trans1 EPA ID: | ILD984908202 |
| Trans2 EPA ID: | SCD987574647 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00120 |
| Units: | Pounds |
| Number of Containers: | 002 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

| | |
|---|---|
| Document ID: | NYC3491954 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYAV4489 |
| Year: | 1995 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 02/27/1995 |
| Trans1 Recv Date: | 02/27/1995 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 02/27/1995 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000204958 |
| Trans1 EPA ID: | ILD984908202 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00120
Units: Pounds
Number of Containers: 002
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYC5577682
Manifest Status: Not reported
Trans1 State ID: NY300747A
Year: 1999
Trans2 State ID: T422NXNJ
Generator Ship Date: 03/25/1999
Trans1 Recv Date: 03/25/1999
Trans2 Recv Date: 03/29/1999
TSD Site Recv Date: 04/01/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NY0000204958
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: SCD987574647
TSDF ID 1: OHD980587364
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| | Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00180 |
| Units: | Pounds |
| Number of Containers: | 003 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC6052566 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYR2436 |
| Year: | 2000 |
| Trans2 State ID: | T486JZNJ |
| Generator Ship Date: | 01/24/2000 |
| Trans1 Recv Date: | 01/24/2000 |
| Trans2 Recv Date: | 01/28/2000 |
| TSD Site Recv Date: | 02/02/2000 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000204958 |
| Trans1 EPA ID: | ILD984908202 |
| Trans2 EPA ID: | SCR000074591 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Quantity: | 00180 |
| Units: | Pounds |
| Number of Containers: | 003 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | CTF0624740 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR2436 |
| Year: | 1997 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 02/27/1997 |
| Trans1 Recv Date: | 02/27/1997 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 03/03/1997 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000204958 |
| Trans1 EPA ID: | ILD984908202 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | CTD001156009 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00195 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | CTF0634126 |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR2436 |
| Year: | 1997 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 10/06/1997 |
| Trans1 Recv Date: | 10/06/1997 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 10/09/1997 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000204958 |
| Trans1 EPA ID: | ILD984908202 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | CTD001156009 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00390 |
| Units: | Pounds |
| Number of Containers: | 002 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

Click this hyperlink while viewing on your computer to access
18 additional NY MANIFEST: record(s) in the EDR Site Report.

| | |
|---|---|
| EPA ID: | NYD000204958 |
| Country: | USA |
| Name: | Magic Touch |
| Address: | 5 VINE STREET |
| Address 2: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

City,State,Zip: LARCHMONT, NY 10538
Zip 4: Not reported
Location Address 1: 5 VINE STREET
Location Address 2: Not reported
Location City,State,Zip: LARCHMONT, NY 10538
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Magic Touch
Mailing Contact: Stacey Kim
Mailing Address 1: 5 VINE STREET
Mailing Address 2: Not reported
Mailing City,State,Zip: LARCHMONT, NY 10538
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9148348880

Manifest Data:
Document ID: NYC6437046
Manifest Status: Not reported
Trans1 State ID: NYCR2436
Year: 2001
Trans2 State ID: Not reported
Generator Ship Date: 09/14/2001
Trans1 Recv Date: 09/14/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/19/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000204958
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: Not reported
TSDF ID 1: OHD980587364
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| | Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00180 |
| Units: | Pounds |
| Number of Containers: | 003 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| Waste Code 7: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 8: | Not reported |
| Waste Code: | Not reported |
| Waste Code 10: | Not reported |
| Waste Code 11: | Not reported |
| Quantity: | 00195 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

| | |
|---|---|
| Document ID: | NYG0323523 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJ420 |
| Year: | 2003 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 06/27/2003 |
| Trans1 Recv Date: | 06/27/2003 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 07/03/2003 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD000204958 |
| Trans1 EPA ID: | NJD000564906 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD000564906 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00160 |
| Units: | Pounds |
| Number of Containers: | 002 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Treat |
| Specific Gravity: | 01.00 |
| Waste Code 7: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 8: | Not reported |
| Waste Code: | Not reported |
| Waste Code 10: | Not reported |
| Waste Code 11: | Not reported |
| Quantity: | 00650 |
| Units: | Pounds |
| Number of Containers: | 005 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Treat |
| Specific Gravity: | 01.00 |
| Waste Code 12: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 13: | Not reported |
| Waste Code 14: | Not reported |
| Waste Code 15: | Not reported |
| Waste Code 16: | Not reported |
| Quantity: | 00080 |
| Units: | Pounds |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Number of Containers: | 001 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Treat |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC6812728 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NY49455JE |
| Year: | 2002 |
| Trans2 State ID: | NJ044 |
| Generator Ship Date: | 08/21/2002 |
| Trans1 Recv Date: | 08/21/2002 |
| Trans2 Recv Date: | 08/28/2002 |
| TSD Site Recv Date: | 08/29/2002 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD000204958 |
| Trans1 EPA ID: | SCR000075150 |
| Trans2 EPA ID: | NJD071629976 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00150 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC6805361 |
| Manifest Status: | Not reported |
| Trans1 State ID: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Year: | 2002 |
| Trans2 State ID: | T25L8DNJ |
| Generator Ship Date: | 05/30/2002 |
| Trans1 Recv Date: | 05/30/2002 |
| Trans2 Recv Date: | 06/05/2002 |
| TSD Site Recv Date: | 06/06/2002 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD000204958 |
| Trans1 EPA ID: | SCR000075150 |
| Trans2 EPA ID: | NJD071629976 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00195 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC6917433 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR3164 |
| Year: | 2002 |
| Trans2 State ID: | T22L8DNJ |
| Generator Ship Date: | 11/11/2002 |
| Trans1 Recv Date: | 11/11/2002 |
| Trans2 Recv Date: | 11/13/2002 |
| TSD Site Recv Date: | 11/14/2002 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Generator EPA ID: | NYD000204958 |
| Trans1 EPA ID: | SCR000075150 |
| Trans2 EPA ID: | NJD071629976 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00150 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC5764432 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCF7875 |
| Year: | 2003 |
| Trans2 State ID: | T2L231NJ |
| Generator Ship Date: | 07/03/2003 |
| Trans1 Recv Date: | 07/03/2003 |
| Trans2 Recv Date: | 07/09/2003 |
| TSD Site Recv Date: | 07/10/2003 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD000204958 |
| Trans1 EPA ID: | TXR000050930 |
| Trans2 EPA ID: | NJD071629976 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00300 |
| Units: | Pounds |
| Number of Containers: | 002 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| Waste Code 7: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 8: | Not reported |
| Waste Code: | Not reported |
| Waste Code 10: | Not reported |
| Waste Code 11: | Not reported |
| Quantity: | 00300 |
| Units: | Pounds |
| Number of Containers: | 002 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC7125131 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR3164 |
| Year: | 2003 |
| Trans2 State ID: | FT97358 |
| Generator Ship Date: | 04/15/2003 |
| Trans1 Recv Date: | 04/15/2003 |
| Trans2 Recv Date: | 04/23/2003 |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| TSD Site Recv Date: | 04/24/2003 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD000204958 |
| Trans1 EPA ID: | TXR000050930 |
| Trans2 EPA ID: | MOR000505358 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00450 |
| Units: | Pounds |
| Number of Containers: | 003 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC6670980 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR3436 |
| Year: | 2002 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 03/07/2002 |
| Trans1 Recv Date: | 03/07/2002 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 03/14/2002 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD000204958 |
| Trans1 EPA ID: | SCR000075150 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00195 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| Waste Code 7: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 8: | Not reported |
| Waste Code: | Not reported |
| Waste Code 10: | Not reported |
| Waste Code 11: | Not reported |
| Quantity: | 00195 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC6934061 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR3164 |
| Year: | 2002 |
| Trans2 State ID: | T51G9TNJ |

**MAGIC TOUCH CLEANERS (Continued)** **1000890004**

| | |
|---|---|
| Generator Ship Date: | 12/13/2002 |
| Trans1 Recv Date: | 12/13/2002 |
| Trans2 Recv Date: | 12/18/2002 |
| TSD Site Recv Date: | 12/19/2002 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD000204958 |
| Trans1 EPA ID: | SCR000075150 |
| Trans2 EPA ID: | NJD071629976 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00450 |
| Units: | Pounds |
| Number of Containers: | 003 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Recycle |
| Specific Gravity: | 01.00 |

---

**A14** **TRAFFIC ACCIDENT** **NY Spills** **S102109878**
**SSW** **I-95 MP 7.7** **N/A**
**< 1/8** **LARCHMONT, NY**
**0.031 mi.**
**163 ft.** **Site 14 of 14 in cluster A**

**Relative:** SPILLS:
**Higher**

| | |
|---|---|
| Name: | TRAFFIC ACCIDENT |
| Address: | I-95 MP 7.7 |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9407990 / 1994-09-22 |
| Facility ID: | 9407990 |
| Facility Type: | ER |

**Actual:**
**44 ft.**

**TRAFFIC ACCIDENT (Continued)** **S102109878**

| | |
|---|---|
| DER Facility ID: | 130891 |
| Site ID: | 154341 |
| DEC Region: | 3 |
| Spill Cause: | Traffic Accident |
| Spill Class: | C3 |
| SWIS: | 6000 |
| Spill Date: | 1994-09-15 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1994-09-15 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial Vehicle |
| Spill Notifier: | Police Department |
| Cleanup Ceased: | 1994-09-22 |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-12-02 |
| Spill Record Last Update: | 2003-12-02 |
| Spiller Name: | Not reported |
| Spiller Company: | ELIAS STOLTZSUN |
| Spiller Address: | 435 BEACHDALE ROAD |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Latitude: | Not reported |
| Longitude: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY |
| Remarks: | TANK RUPTURED DRIVER INJURED LARCHMONT & MAMARONECK F.D. ON SCENE T-WAY AUTHORITY ON SCENE & PERFORMING CLEAN UP |

All Materials:

| | |
|---|---|
| Site ID: | 154341 |
| Operable Unit ID: | 1002173 |
| Operable Unit: | 01 |
| Material ID: | 377444 |
| Material Code: | 0008 |
| Material Name: | diesel |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 20.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**15**
**West**
**< 1/8**
**0.037 mi.**
**193 ft.**

**7 MAPLE ST**
**7 MAPLE ST**
**HASTINGS, NY**

**NY Spills** **S103939262**
**N/A**

**Relative:**
**Higher**

**Actual:**
**42 ft.**

SPILLS:

| | |
|---|---|
| Name: | 7 MAPLE ST |
| Address: | 7 MAPLE ST |
| City,State,Zip: | HASTINGS, NY |
| Spill Number/Closed Date: | 9903923 / 1999-07-06 |
| Facility ID: | 9903923 |
| Facility Type: | ER |
| DER Facility ID: | 142767 |
| Site ID: | 169578 |
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | C4 |
| SWIS: | 6000 |
| Spill Date: | 1999-07-06 |
| Investigator: | DVWEHRFR |
| Referred To: | Not reported |
| Reported to Dept: | 1999-07-06 |
| CID: | 205 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-07-06 |
| Spill Record Last Update: | 1999-07-19 |
| Spiller Name: | CALLER |
| Spiller Company: | CON ED |
| Spiller Address: | 4 IRVING PLACE |
| Spiller Company: | 001 |
| Contact Name: | CALLER |
| Latitude: | Not reported |
| Longitude: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was WEHRFRITZ |
| Remarks: | spill to ground. cleanup crew enroute. con ed #126114 |

All Materials:

| | |
|---|---|
| Site ID: | 169578 |
| Operable Unit ID: | 1078367 |
| Operable Unit: | 01 |
| Material ID: | 303822 |
| Material Code: | 0020A |
| Material Name: | transformer oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**B16** **CON EDISON** **RCRA NonGen / NLR** **1028907675**
**NNE** **10 CABOT RD** **NYP005249410**
**< 1/8** **LARCHMONT, NY 10538**
**0.054 mi.**
**286 ft.** **Site 1 of 2 in cluster B**

**Relative:** **Lower**
**Actual:** **40 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20240711 |
| Handler Name: | | Con Edison |
| Handler Address: | | Cabot Rd |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYP005249410 |
| Contact Name: | | NICHOLAS DIROMA |
| Contact Address: | | Not reported |
| Contact City,State,Zip: | | Not reported |
| Contact Telephone: | | 212-460-4005 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | SCIENTIST |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | Ny |
| State District: | | NYSDEC R3 |
| Mailing Address: | | IRVING PL, 15TH FL NE |
| Mailing City,State,Zip: | | NEW YORK, NY 10003 |
| Owner Name: | Not reported | |
| Owner Type: | | Not reported |
| Operator Name: | Not reported | |
| Operator Type: | | Not reported |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| Corrective Action Priority Ranking: | | No NCAPS ranking |
| Environmental Control Indicator: | | No |
| Institutional Control Indicator: | | No |

**CON EDISON (Continued)** **1028907675**

| | |
|---|---|
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20240711 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20240711 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | No |
| Electronic Manifest Broker: | No |

| | |
|---|---|
| Receive Date: | 20231029 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | No |
| Electronic Manifest Broker: | No |

List of NAICS Codes and Descriptions:

| | |
|---|---|
| NAICS Codes: | No NAICS Codes Found |

Facility Has Received Notices of Violations:

| | |
|---|---|
| Violations: | No Violations Found |

Evaluation Action Summary:

| | |
|---|---|
| Evaluations: | No Evaluations Found |

**C17** **NEW YORK STATE AUTHORITY-LARCHMONT STATION PLAZA O** **RCRA-SQG** **1031488799**
**South** **1 RAILROAD WAY** **ECHO** **NYR000271593**
**< 1/8** **LARCHMONT, NY 10538**
**0.063 mi.**
**333 ft.** **Site 1 of 5 in cluster C**

**Relative:** **Higher**

**Actual:** **47 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20250529 |
| Handler Name: | | New York State Authority-Larchmont Station Plaza Over I-95 - Bin 5514610 |
| Handler Address: | | Railroad Way |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYR000271593 |
| Contact Name: | | PAMILA RAMOTAR-JOHN |
| Contact Address: | | EXECUTIVE BLVD STE 400 |
| Contact City,State,Zip: | | SUFFERN, NY 10901 |
| Contact Telephone: | | 845-918-2526 |
| Contact Fax: | | Not reported |
| Contact Email: | | PAMILA.JOHN@THRUWAY.NY.GOV |
| Contact Title: | | ENV SPECIALIST II |
| EPA Region: | | 02 |
| Land Type: | | State |
| Federal Waste Generator Description: | | Small Quantity Generator |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Handler Activities |
| State District Owner: | | Ny |
| State District: | | NYSDEC R3 |
| Mailing Address: | | EXECUTIVE BLVD STE 400 |
| Mailing City,State,Zip: | | SUFFERN, NY 10901 |
| Owner Name: | Nys Thruway Auth | |
| Owner Type: | | State |
| Operator Name: | Nys Thruway Auth | |
| Operator Type: | | State |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| Corrective Action Priority Ranking: | | No NCAPS ranking |
| Environmental Control Indicator: | | No |

**NEW YORK STATE AUTHORITY-LARCHMONT STATION PLAZA OVER I-95 - (Continued)** **1031488799**

| | |
|---|---|
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20250530 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | D001 |
| Waste Description: | Ignitable Waste |
| Waste Code: | D002 |
| Waste Description: | Corrosive Waste |
| Waste Code: | D007 |
| Waste Description: | Chromium |
| Waste Code: | D008 |
| Waste Description: | Lead |
| Waste Code: | D018 |
| Waste Description: | Benzene |
| Waste Code: | D035 |
| Waste Description: | Methyl Ethyl Ketone |
| Waste Code: | F003 |
| Waste Description: | The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code: | F005 |
| Waste Description: | The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |

**NEW YORK STATE AUTHORITY-LARCHMONT STATION PLAZA OVER I-95 - (Continued)** **1031488799**

Handler - Owner Operator:

| | |
|---|---|
| Owner/Operator Indicator: | Operator |
| Owner/Operator Name: NYS THRUWAY AUTH | |
| Legal Status: | State |
| Date Became Current: | 19551215 |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 200 SOUTHERN BLVD |
| Owner/Operator City,State,Zip: | ALBANY, NY 12201 |
| Owner/Operator Telephone: | 518-436-3190 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: NYS THRUWAY AUTH | |
| Legal Status: | State |
| Date Became Current: | 19551215 |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 200 SOUTHERN BLVD |
| Owner/Operator City,State,Zip: | ALBANY, NY 12201 |
| Owner/Operator Telephone: | 518-436-3190 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

| | |
|---|---|
| Owner/Operator Indicator: | Operator |
| Owner/Operator Name: NYS THRUWAY AUTH | |
| Legal Status: | State |
| Date Became Current: | 19551215 |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 200 SOUTHERN BLVD |
| Owner/Operator City,State,Zip: | ALBANY, NY 12201 |
| Owner/Operator Telephone: | 518-436-3190 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: NYS THRUWAY AUTH | |
| Legal Status: | State |
| Date Became Current: | 19551215 |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 200 SOUTHERN BLVD |
| Owner/Operator City,State,Zip: | ALBANY, NY 12201 |
| Owner/Operator Telephone: | 518-436-3190 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20250129 |
| Handler Name: | NYS THRUWAY AUTH-LARCHMONT STATION PLAZA OVER I-95 - BIN 5514610 |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |

**NEW YORK STATE AUTHORITY-LARCHMONT STATION PLAZA OVER I-95 - (Continued)** **1031488799**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20250529
Handler Name: NEW YORK STATE AUTHORITY-LARCHMONT STATION PLAZA OVER I-95 - BIN 5514610
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 237310
NAICS Description: Highway, Street, And Bridge Construction

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ECHO:
Envid: 1031488799
Registry ID: 110072070766

DFR URL:
Name: NEW YORK STATE AUTHORITY-LARCHMONT STATION PLAZA OVER I-95 - BIN 5514610
Address: 1 Railroad Way
City,State,Zip: LARCHMONT, NY 10538

---

**B18** **DECABIA - UST** **NY Spills** **S128911954**
**NE** **19 CABOT RD** **N/A**
**< 1/8** **LARCHMONT, NY**
**0.080 mi.**
**420 ft.** **Site 2 of 2 in cluster B**

**Relative:**
**Lower**

**Actual:**
**40 ft.**

SPILLS:
Name: DECABIA - UST
Address: 19 CABOT RD
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 2202138 / 2022-07-14
Facility ID: 2202138
Facility Type: ER
DER Facility ID: 583872

**DECABIA - UST (Continued)** **S128911954**

| | |
|---|---|
| Site ID: | 637212 |
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | C3 |
| SWIS: | 6032 |
| Spill Date: | 2022-06-08 |
| Investigator: | JBODEE |
| Referred To: | Not reported |
| Reported to Dept: | 2022-06-08 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2022-06-08 |
| Spill Record Last Update: | 2022-07-14 |
| Spiller Name: | Joanne Decabia |
| Spiller Company: | Decabia |
| Spiller Address: | 19 CABOT RD |
| Spiller Company: | 999 |
| Contact Name: | Not reported |
| Latitude: | Not reported |
| Longitude: | Not reported |
| DEC Memo: | 6/8/22 Tank removal at residence. Multiple holes found in the tank. Staining and odor in soil. 550 UST. Homeowner is in contact with Elite for cleanup. EKT 7/14/2022: Elite Environmental removed the leaking UST and disposed of a total of 42.11 tons of petroleum contaminated soil. Post excavation soil sample results were below CP-51 Guidance values. Report has been reviewed and entered in DecDocs. Based upon the information provided, no further action is required at this time. jod |
| Remarks: | TANK REMOVAL 550GAL UST. UNK AMOUNT OF PRODUCT RELEASED TO SOIL. CLEAN UP PENDING. |

All Materials:

| | |
|---|---|
| Site ID: | 637212 |
| Operable Unit ID: | 1384272 |
| Operable Unit: | 01 |
| Material ID: | 2398815 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

**C19** **FIRST IMPRESSION** **EDR Hist Cleaner** **1018764214**
**South** **1875 PALMER AVE** **N/A**
**< 1/8** **LARCHMONT, NY 10538**
**0.089 mi.**
**468 ft.** **Site 2 of 5 in cluster C**

**Relative:** EDR Hist Cleaner
**Higher**

**Actual:** Year: Name: Type:
**49 ft.** 1996 FIRST IMPRESSION Drycleaning Plants, Except Rugs
1997 PEARL CLEANERS Garment Pressing And Cleaners' Agents

---

**C20** **GLOBE RESTAURANT** **NY LTANKS** **S107523363**
**South** **1879 PALMER AVE** **N/A**
**< 1/8** **LARCHMONT, NY**
**0.096 mi.**
**508 ft.** **Site 3 of 5 in cluster C**

**Relative:** LTANKS:
**Higher**

**Actual:**
**53 ft.**

| | |
|---|---|
| Name: | GLOBE RESTAURANT |
| Address: | 1879 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0511734 / 2006-02-21 |
| Facility ID: | 0511734 |
| Site ID: | 357947 |
| Spill Date: | 2006-01-11 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | Not reported |
| Reported to Dept: | 2006-01-11 |
| CID: | 44 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2006-01-11 |
| Spill Record Last Update: | 2006-02-21 |
| Spiller Name: | GERARD TUNNEY |
| Spiller Company: | GLOBE RESTERAUNT |
| Spiller Address: | 1879 PALMER AVE |
| Spiller County: | 001 |
| Spiller Contact: | GERARD TUNNEY |
| Spiller Phone: | (914) 921-3422 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 307980 |
| Latitude: | 40.9337750 |
| Longitude: | -73.7578200 |
| DEC Memo: | 1/11/06 Vaulted AST removed- NES to Contact J. O'Dee for guidance<br>February 21, 2006: NORTHEAST ENVIRONMENTAL DISPOSED OF TANK AND 2 DRUMSOF CONTAMINATED SOIL. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod |
| Remarks: | 550 GALLON AST, IN VAULT AND SAND INSIDE IS CONTAMINATED: |

**GLOBE RESTAURANT (Continued)** **S107523363**

All Materials:

| | |
|---|---|
| Site ID: | 357947 |
| Operable Unit ID: | 1115213 |
| Operable Unit: | 01 |
| Material ID: | 2105269 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**D21** **PATRICIA GARDENS** **NY LTANKS** **U003645239**
**ESE** **1825 PALMER AVE** **NY Spills** **N/A**
**< 1/8** **LARCHMONT, NY**
**0.100 mi.**
**526 ft.** **Site 1 of 6 in cluster D**

**Relative:** **Higher**

**Actual:** **41 ft.**

LTANKS:

| | |
|---|---|
| Name: | PATRICIA GARDENS |
| Address: | 1825 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9802511 / 1999-02-08 |
| Facility ID: | 9802511 |
| Site ID: | 200510 |
| Spill Date: | 1998-05-26 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1998-05-27 |
| CID: | 351 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-05-27 |
| Spill Record Last Update: | 1999-03-01 |
| Spiller Name: | ROBERT ORLOFSKI |
| Spiller Company: | PATRICIA GARDENS |
| Spiller Address: | 1825 PALMER AVE |
| Spiller County: | 001 |
| Spiller Contact: | ROBERT ORLOFSKI |
| Spiller Phone: | (914) 328-6962 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 166857 |
| Latitude: | 40.9347344 |

**PATRICIA GARDENS (Continued)** **U003645239**

| | |
|---|---|
| Longitude: | -73.7559717 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE |
| Remarks: | SITE IS AN APARTMENT COMPLEX - RECOMMEND ISOLATE EXCAVATE AND RETEST |

SPILLS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 1825 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9515259 / 1996-02-27 |
| Facility ID: | 9515259 |
| Facility Type: | ER |
| DER Facility ID: | 67799 |
| Site ID: | 71681 |
| DEC Region: | 3 |
| Spill Cause: | Unknown |
| Spill Class: | C4 |
| SWIS: | 6000 |
| Spill Date: | 1996-02-27 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1996-02-27 |
| CID: | 204 |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1996-02-27 |
| Spill Record Last Update: | 1996-03-06 |
| Spiller Name: | JIM CAREY |
| Spiller Company: | CASTLE OIL |
| Spiller Address: | 290 LOCUST AVE |
| Spiller Company: | 001 |
| Contact Name: | JIM CAREY |
| Latitude: | 40.9347344 |
| Longitude: | -73.7559717 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 02/27/96 CASTLE OIL DID CLEAN UP AND WILL PROVIDE CLEAN FILL |
| Remarks: | WHILE FILLING TANK OIL CAME OUT OF VENT PIPE |

All Materials:

| | |
|---|---|
| Site ID: | 71681 |
| Operable Unit ID: | 1026370 |
| Operable Unit: | 01 |
| Material ID: | 355382 |
| Material Code: | 0002A |
| Material Name: | #4 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 20.00 |
| Units: | G |

**PATRICIA GARDENS (Continued)** **U003645239**

Recovered: 20.00
Oxygenate: Not reported

---

**D22** **PATRICIA GARDENS OWNERS, INC.** **NY UST** **U004333700**
**ESE** **1825 PALMER AVENUE** **N/A**
**< 1/8** **LARCHMONT, NY 10538**
**0.100 mi.**
**526 ft.** **Site 2 of 6 in cluster D**

**Relative:** **Higher**
**Actual:** **41 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | PATRICIA GARDENS OWNERS, INC. |
| Address: | 1825 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-048429 / Active |
| Operator Name: | Humberto Sanchez |
| Owner Name: | Patricia Gardens Owners, Inc. |
| Owner Street: | 7 Bryant Crescent, Suite 1C |
| Owner Address2: | Not reported |
| Owner City: | White Plains |
| Owner State: | NY |
| Owner Zipcode: | 10605 |
| GDS Number: | Not reported |
| Tank Number: | 825 |
| Status: | 4. Closed - in place |
| Capacity: | 10000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | Not reported |
| Date Perm Closure: | 07/03/2002 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 2. Underground/on ground |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Overfill Prevention: | 5. Vent Whistle |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 2. Suction |

---

**D23** **PATRICIA GARDENS OWNERS, INC.** **NY AST** **A100276801**
**ESE** **1825 PALMER AVENUE** **N/A**
**< 1/8** **LARCHMONT, NY 10538**
**0.100 mi.**
**526 ft.** **Site 3 of 6 in cluster D**

**Relative:** **Higher**
**Actual:** **41 ft.**

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | PATRICIA GARDENS OWNERS, INC. |
| Address: | 1825 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-048429 |

**PATRICIA GARDENS OWNERS, INC. (Continued)** **A100276801**

| | |
|---|---|
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | Humberto Sanchez |
| Owner Name: | Patricia Gardens Owners, Inc. |
| Owner Street: | 7 Bryant Crescent, Suite 1C |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | White Plains, NY 10605 |
| | |
| Tank Number: | 1 |
| Status: | 1. In-Service |
| Date Installation: | 08/01/2002 |
| Capacity: | 8000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 6. Aboveground in subterranean vault with access for inspections |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | 5. Synthetic Liner |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

---

**D24** **LARCHMONT CENTER CLEANERS** **EDR Hist Cleaner** **1020024404**
**SE** **1861 PALMER AVE** **N/A**
**< 1/8** **LARCHMONT, NY 10538**
**0.104 mi.**
**550 ft.** **Site 4 of 6 in cluster D**

**Relative:** EDR Hist Cleaner
**Higher**

**Actual:**
**49 ft.**

| Year: | Name: | Type: |
|---|---|---|
| 1969 | LARCHMONT CENTER CLEANERS | Drycleaning Plants, Except Rugs |
| 1970 | LARCHMONT CENTER CLEANERS | Drycleaning Plants, Except Rugs |
| 1971 | LARCHMONT CENTER CLEANERS | Drycleaning Plants, Except Rugs |
| 1972 | LARCHMONT CENTER CLEANERS | Drycleaning Plants, Except Rugs |
| 1973 | LARCHMONT CENTER CLEANERS | Drycleaning Plants, Except Rugs |
| 1974 | LARCHMONT CENTER CLEANERS | Drycleaning Plants, Except Rugs |
| 1975 | LARCHMONT CENTER CLEANERS | Drycleaning Plants, Except Rugs |
| 1976 | LARCHMONT CENTER CLEANERS | Drycleaning Plants, Except Rugs |
| 1977 | LARCHMONT CENTER CLEANERS | Drycleaning Plants, Except Rugs |
| 1978 | LARCHMONT CENTER CLEANERS | Drycleaning Plants, Except Rugs |
| 1979 | LARCHMONT CENTER CLEANERS | Drycleaning Plants, Except Rugs |
| 1980 | LARCHMONT CENTER CLEANERS | Drycleaning Plants, Except Rugs |
| 1982 | LARCHMONT CENTER CLEANERS | Drycleaning Plants, Except Rugs |
| 1983 | LARCHMONT CENTER CLEANERS | Drycleaning Plants, Except Rugs |

**C25** **MANOPP REALTY** **NY Spills** **S109581484**
**South** **1885-1889 PALMER AVE** **N/A**
**< 1/8** **LARCHMONT, NY**
**0.106 mi.**
**562 ft.** **Site 4 of 5 in cluster C**

**Relative:** **Higher**

**Actual:** **56 ft.**

SPILLS:

| | |
|---|---|
| Name: | MANOPP REALTY |
| Address: | 1885-1889 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0900003 / 2010-05-17 |
| Facility ID: | 0900003 |
| Facility Type: | ER |
| DER Facility ID: | 361114 |
| Site ID: | 411912 |
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | B3 |
| SWIS: | 6032 |
| Spill Date: | 2009-01-30 |
| Investigator: | JKOMARA |
| Referred To: | Not reported |
| Reported to Dept: | 2009-04-01 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2009-04-01 |
| Spill Record Last Update: | 2010-05-17 |
| Spiller Name: | MARIO FAVA |
| Spiller Company: | MANOPP REALTY |
| Spiller Address: | 1885-1889 PALMER AVE |
| Spiller Company: | 999 |
| Contact Name: | PAUL HINKSTON |
| Latitude: | 40.9336565 |
| Longitude: | -73.7580649 |
| DEC Memo: | 040109: V.Mc.^ MARIO FAVA/MANOPP REALTY: Owner of property, Mr. Fava will contact C.Tor./WCHD for follow up/req. Aband.-in-Place. Provided phone # for WCHD & J.O'M. 05/17/10 From WCDOH John, It is my recommendation that the above referenced spill at 1885-1889 Palmer Ave in Larchmont should be closed. I am in receipt of a closure report from NES that states that the spill number above was generated by a Phase II assessment of a tank buried in sand in a concrete vault at the above address. The report states that the tank, concrete blocks and sand have all been removed and that there was no indication of petroleum contamination. If you have any other questions, please let me know. Thanks, Brian Kaley Sanitarian Westchester County Dept. of Health Office of Environmental Health Risk Control (914)813-5165 bmk2@westchestergov.com Agreed JO'M |

**MANOPP REALTY (Continued)** **S109581484**

Remarks: CALLER STATES THAT THEY FOUND VOC'S IN THE SOIL NEAR A 5000 GALLON UST, WHICH IS FULL AND CONTAINES #2 HEATING OIL. TANK ABANDONMENT AND CLEAN UP IS PENDING.

All Materials:

| | |
|---|---|
| Site ID: | 411912 |
| Operable Unit ID: | 1168405 |
| Operable Unit: | 01 |
| Material ID: | 2160012 |
| Material Code: | 0066A |
| Material Name: | unknown petroleum |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**C26** **LUSARDI'S RESTAURANT** **NY AST** **A100540434**
**South** **1885-1889 PALMER AVENUE** **N/A**
**< 1/8** **LARCHMONT, NY 10538**
**0.106 mi.**
**562 ft.** **Site 5 of 5 in cluster C**

**Relative:**
**Higher**

**Actual:**
**56 ft.**

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | LUSARDI'S RESTAURANT |
| Address: | 1885-1889 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-801570 |
| Site Status: | Unregulated |
| GDS Number: | Not reported |
| Operator Name: | Paula Lusardi |
| Owner Name: | Manopp Realty Corp. |
| Owner Street: | 175 Tanner Marsh Road |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | Guilford, CT 06437 |
| | |
| Tank Number: | 1 |
| Status: | 3. Closed - Removed |
| Date Installation: | 06/01/1979 |
| Capacity: | 5000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | 100 |
| Date Perm Closure: | 10/17/2009 |
| Tank Location: | 2. Aboveground (contact w/ impervious barrier) |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | 3. Vault (w/ no access) |
| Piping Location: | 3. Aboveground/underground combination |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 5. Vent Whistle |
| Spill Prevention: | 0. None |

**LUSARDI'S RESTAURANT (Continued)** **A100540434**

Dispenser: 0. None

---

**E27** **COLONY TENANTS CORP.** **NY UST** **U003855870**
**East** **1815 PALMER AVENUE** **N/A**
**< 1/8** **LARCHMONT, NY 10538**
**0.108 mi.**
**570 ft.** **Site 1 of 2 in cluster E**

**Relative:** **Lower**
**Actual:** **38 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | COLONY TENANTS CORP. |
| Address: | 1815 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-104590 / Active |
| Operator Name: | Archer Property Management |
| Owner Name: | Colony Tenants Corp., c/o Archer Property Mgmt. |
| Owner Street: | 105 Calvert Street |
| Owner Address2: | Not reported |
| Owner City: | Harrison |
| Owner State: | NY |
| Owner Zipcode: | 10528 |
| GDS Number: | Not reported |
| | |
| Tank Number: | 002 |
| Status: | 1. In-Service |
| Capacity: | 5000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 2. Manual Interstitial Monitoring |
| Date Installation: | 06/01/1999 |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 10. Urethane clad steel |
| Tank Internal Protection: | 4. Glass liner |
| Tank External Protection: | 2. Original sacrificial anode,9. Urethane |
| Tank Secondary Containment: | 4. Double-Walled (underground only) |
| Piping Location: | 2. Underground/on Ground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 4. Fiberglass |
| Overfill Prevention: | 2. High Level Alarm,5. Vent Whistle |
| Piping Secondary Containment: | 4. Double-Walled (underground only) |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 2. Suction |
| | |
| Tank Number: | 1 |
| Status: | 3. Closed - Removed |
| Capacity: | 5000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | Not reported |
| Date Perm Closure: | 12/14/1999 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |

**COLONY TENANTS CORP. (Continued)** **U003855870**

| | |
|---|---|
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | Not reported |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 2. Suction |

---

**E28** **SPILL NUMBER 9909425** **NY Spills** **S104649892**
**East** **1815 PALMER AVE** **N/A**
**< 1/8** **LARCHMONT, NY**
**0.108 mi.**
**570 ft.** **Site 2 of 2 in cluster E**

**Relative:** **Lower**

**Actual:** **38 ft.**

SPILLS:

| | |
|---|---|
| Name: | SPILL NUMBER 9909425 |
| Address: | 1815 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9909425 / 2000-02-22 |
| Facility ID: | 9909425 |
| Facility Type: | ER |
| DER Facility ID: | 139195 |
| Site ID: | 165122 |
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | C3 |
| SWIS: | 6032 |
| Spill Date: | 1999-11-03 |
| Investigator: | JBODEE |
| Referred To: | WESTCHESTER CNTY HEALTH DEPT |
| Reported to Dept: | 1999-11-03 |
| CID: | 382 |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-11-03 |
| Spill Record Last Update: | 2019-11-14 |
| Spiller Name: | COLONIE TENATS CORP |
| Spiller Company: | Not reported |
| Spiller Address: | 1815 PALMER AVE |
| Spiller Company: | 001 |
| Contact Name: | COLONIE TENANTS CORP |
| Latitude: | 40.9350904 |
| Longitude: | -73.7555730 |
| DEC Memo: | Not reported |
| Remarks: | DISCHARGE FROM AN UNDERGROUND TANK. CLEAN UP IS UNKNOWN |

All Materials:

| | |
|---|---|
| Site ID: | 165122 |
| Operable Unit ID: | 1088110 |
| Operable Unit: | 01 |
| Material ID: | 298513 |
| Material Code: | 0001A |

**SPILL NUMBER 9909425 (Continued)** **S104649892**

| | |
|---|---|
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**F29** **REAR OF 1880 PALMER AVE** **NY LTANKS** **S102675195**
**SSE** **FRANKLYN AVE** **N/A**
**< 1/8** **LARCHMONT, NY**
**0.115 mi.**
**608 ft.** **Site 1 of 2 in cluster F**

**Relative:**
**Higher**

**Actual:**
**51 ft.**

LTANKS:

| | |
|---|---|
| Name: | REAR OF 1880 PALMER AVE |
| Address: | FRANKLYN AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9602833 / 1996-05-29 |
| Facility ID: | 9602833 |
| Site ID: | 292396 |
| Spill Date: | 1996-05-29 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Tank Truck |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1996-05-29 |
| CID: | 233 |
| Water Affected: | Not reported |
| Spill Notifier: | Fire Department |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1996-05-29 |
| Spill Record Last Update: | 1996-06-14 |
| Spiller Name: | JIM CAREY |
| Spiller Company: | CASTLE OIL |
| Spiller Address: | 290 LOCUST AVE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 236741 |
| Latitude: | Not reported |
| Longitude: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY |
| Remarks: | tank overfill fd used 2 bags of speddy dri eastmond spill recovery on scene now |

All Materials:

**REAR OF 1880 PALMER AVE (Continued)** **S102675195**

| | |
|---|---|
| Site ID: | 292396 |
| Operable Unit ID: | 1034129 |
| Operable Unit: | 01 |
| Material ID: | 349071 |
| Material Code: | 0003A |
| Material Name: | #6 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 15.00 |
| Units: | G |
| Recovered: | 15.00 |
| Oxygenate: | Not reported |

---

**G30** **TRIPLE CLEAN GROUP INC** **EDR Hist Cleaner** **1020108546**
**South** **1895 PALMER AVE** **N/A**
**< 1/8** **LARCHMONT, NY 10538**
**0.122 mi.**
**643 ft.** **Site 1 of 15 in cluster G**

**Relative:** EDR Hist Cleaner
**Higher**

**Actual:**
**55 ft.**

| Year: | Name: | Type: |
|---|---|---|
| 2000 | TRIPLE CLEAN GROUP INC | Drycleaning Plants, Except Rugs |
| 2001 | TRIPLE CLEAN GROUP INC | Drycleaning Plants, Except Rugs |
| 2002 | TRIPLE CLEAN GROUP INC | Drycleaning Plants, Except Rugs |
| 2003 | TRIPLE CLEAN GROUP INC | Drycleaning Plants, Except Rugs |
| 2004 | TRIPLE CLEAN GROUP INC | Drycleaning Plants, Except Rugs |
| 2005 | TRIPLE CLEAN GROUP INC | Drycleaning Plants, Except Rugs |
| 2006 | TRIPLE CLEAN GROUP INC | Drycleaning Plants, Except Rugs |
| 2007 | TRIPLE CLEAN GROUP INC | Drycleaning Plants, Except Rugs |
| 2008 | TRIPLE CLEAN GROUP INC | Drycleaning Plants, Except Rugs |
| 2009 | TRIPLE CLEAN GROUP INC | Drycleaning Plants, Except Rugs |
| 2010 | TRIPLE CLEAN GROUP INC | Drycleaning Plants, Except Rugs |
| 2011 | TRIPLE CLEAN GROUP INC | Drycleaning Plants, Except Rugs |
| 2012 | TRIPLE CLEAN GROUP INC | Drycleaning Plants, Except Rugs |
| 2013 | TRIPLE CLEAN GROUP INC | Drycleaning Plants, Except Rugs |
| 2014 | TRIPLE CLEAN GROUP INC | Drycleaning Plants, Except Rugs |

---

**G31** **EMBASSY CLEANERS** **RCRA-SQG** **1000708538**
**South** **1895 PALMER AVE** **ICIS** **NYD986995249**
**< 1/8** **LARCHMONT, NY 10538** **US AIRS**
**0.122 mi.** **FINDS**
**643 ft.** **Site 2 of 15 in cluster G** **ECHO**
**NY DRYCLEANERS**

**Relative:** **NY MANIFEST**
**Higher** **RI MANIFEST**

**Actual:**
**55 ft.**

RCRA Listings:

| | |
|---|---|
| Date Form Received by Agency: | 20070101 |
| Handler Name: | Embassy Cleaners |
| Handler Address: | Palmer Ave |
| Handler City,State,Zip: | LARCHMONT, NY 10538 |
| EPA ID: | NYD986995249 |
| Contact Name: | BILL STERN |
| Contact Address: | PALMER AVE |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | | |
|---|---|---|
| Contact City,State,Zip: | | LARCHMONT, NY 10538 |
| Contact Telephone: | | 914-834-2700 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Small Quantity Generator |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Handler Activities |
| State District Owner: | | Ny |
| State District: | | NYSDEC R3 |
| Mailing Address: | | PALMER AVE |
| Mailing City,State,Zip: | | LARCHMONT, NY 10538 |
| Owner Name: | Bill Stern | |
| Owner Type: | | Private |
| Operator Name: | Bill Stern | |
| Operator Type: | | Private |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| Corrective Action Priority Ranking: | | No NCAPS ranking |
| Environmental Control Indicator: | | No |
| Institutional Control Indicator: | | No |
| Human Exposure Controls Indicator: | | N/A |
| Groundwater Controls Indicator: | | N/A |
| Significant Non-Complier Universe: | | No |
| Unaddressed Significant Non-Complier Universe: | | No |
| Addressed Significant Non-Complier Universe: | | No |
| Significant Non-Complier With a Compliance Schedule Universe: | | No |
| Financial Assurance Required: | | Not reported |
| Handler Date of Last Change: | | 20150414 |
| Recognized Trader-Importer: | | No |
| Recognized Trader-Exporter: | | No |
| Importer of Spent Lead Acid Batteries: | | No |
| Exporter of Spent Lead Acid Batteries: | | No |

**EMBASSY CLEANERS (Continued)** **1000708538**

Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: BILL STERN
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1895 PALMER AVE
Owner/Operator City,State,Zip: LARCHMONT, NY 10538
Owner/Operator Telephone: 914-834-2700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: BILL STERN
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1895 PALMER AVE
Owner/Operator City,State,Zip: LARCHMONT, NY 10538
Owner/Operator Telephone: 914-834-2700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: BILL STERN
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1895 PALMER AVE
Owner/Operator City,State,Zip: LARCHMONT, NY 10538
Owner/Operator Telephone: 914-834-2700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101

**EMBASSY CLEANERS (Continued)** **1000708538**

Handler Name: EMBASSY CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: EMBASSY CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920324
Handler Name: EMBASSY CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Permits - Application
Date Violation was Determined: 20101210
Actual Return to Compliance Date: 20110207
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20101223
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No

**EMBASSY CLEANERS (Continued)** **1000708538**

Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20110211
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHBR
Enforcement Responsible Sub-Organization: R4
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20101210
Actual Return to Compliance Date: 20101222
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20101223
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20110211
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHBR
Enforcement Responsible Sub-Organization: R4
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Final Monetary Amount: | Not reported |
| Paid Amount: | Not reported |
| Final Count: | Not reported |
| Final Amount: | Not reported |
| | |
| Found Violation: | Yes |
| Agency Which Determined Violation: | State |
| Violation Short Description: | Generators - Pre-transport |
| Date Violation was Determined: | 20101210 |
| Actual Return to Compliance Date: | 20101210 |
| Return to Compliance Qualifier: | Observed |
| Violation Responsible Agency: | State |
| Scheduled Compliance Date: | Not reported |
| Enforcement Identifier: | 001 |
| Date of Enforcement Action: | 20101223 |
| Enforcement Responsible Agency: | State |
| Enforcement Docket Number: | Not reported |
| Enforcement Attorney: | Not reported |
| Corrective Action Component: | No |
| Appeal Initiated Date: | Not reported |
| Appeal Resolution Date: | Not reported |
| Disposition Status Date: | 20110211 |
| Disposition Status: | AS |
| Disposition Status Description: | ACTION SATISFIED (CASE CLOSED) |
| Consent/Final Order Sequence Number: | Not reported |
| Consent/Final Order Respondent Name: | Not reported |
| Consent/Final Order Lead Agency: | Not reported |
| Enforcement Type: | WRITTEN INFORMAL |
| Enforcement Responsible Person: | NYHBR |
| Enforcement Responsible Sub-Organization: | R4 |
| SEP Sequence Number: | Not reported |
| SEP Expenditure Amount: | Not reported |
| SEP Scheduled Completion Date: | Not reported |
| SEP Actual Date: | Not reported |
| SEP Defaulted Date: | Not reported |
| SEP Type: | Not reported |
| SEP Type Description: | Not reported |
| Proposed Amount: | Not reported |
| Final Monetary Amount: | Not reported |
| Paid Amount: | Not reported |
| Final Count: | Not reported |
| Final Amount: | Not reported |
| | |
| Found Violation: | Yes |
| Agency Which Determined Violation: | State |
| Violation Short Description: | Generators - Pre-transport |
| Date Violation was Determined: | 20101210 |
| Actual Return to Compliance Date: | 20101210 |
| Return to Compliance Qualifier: | Documented |
| Violation Responsible Agency: | State |
| Scheduled Compliance Date: | Not reported |
| Enforcement Identifier: | 001 |
| Date of Enforcement Action: | 20101223 |
| Enforcement Responsible Agency: | State |
| Enforcement Docket Number: | Not reported |
| Enforcement Attorney: | Not reported |
| Corrective Action Component: | No |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Appeal Initiated Date: | Not reported |
| Appeal Resolution Date: | Not reported |
| Disposition Status Date: | 20110211 |
| Disposition Status: | AS |
| Disposition Status Description: | ACTION SATISFIED (CASE CLOSED) |
| Consent/Final Order Sequence Number: | Not reported |
| Consent/Final Order Respondent Name: | Not reported |
| Consent/Final Order Lead Agency: | Not reported |
| Enforcement Type: | WRITTEN INFORMAL |
| Enforcement Responsible Person: | NYHBR |
| Enforcement Responsible Sub-Organization: | R4 |
| SEP Sequence Number: | Not reported |
| SEP Expenditure Amount: | Not reported |
| SEP Scheduled Completion Date: | Not reported |
| SEP Actual Date: | Not reported |
| SEP Defaulted Date: | Not reported |
| SEP Type: | Not reported |
| SEP Type Description: | Not reported |
| Proposed Amount: | Not reported |
| Final Monetary Amount: | Not reported |
| Paid Amount: | Not reported |
| Final Count: | Not reported |
| Final Amount: | Not reported |

| | |
|---|---|
| Found Violation: | Yes |
| Agency Which Determined Violation: | State |
| Violation Short Description: | TSD IS-Preparedness and Prevention |
| Date Violation was Determined: | 20101210 |
| Actual Return to Compliance Date: | 20101220 |
| Return to Compliance Qualifier: | Documented |
| Violation Responsible Agency: | State |
| Scheduled Compliance Date: | Not reported |
| Enforcement Identifier: | 001 |
| Date of Enforcement Action: | 20101223 |
| Enforcement Responsible Agency: | State |
| Enforcement Docket Number: | Not reported |
| Enforcement Attorney: | Not reported |
| Corrective Action Component: | No |
| Appeal Initiated Date: | Not reported |
| Appeal Resolution Date: | Not reported |
| Disposition Status Date: | 20110211 |
| Disposition Status: | AS |
| Disposition Status Description: | ACTION SATISFIED (CASE CLOSED) |
| Consent/Final Order Sequence Number: | Not reported |
| Consent/Final Order Respondent Name: | Not reported |
| Consent/Final Order Lead Agency: | Not reported |
| Enforcement Type: | WRITTEN INFORMAL |
| Enforcement Responsible Person: | NYHBR |
| Enforcement Responsible Sub-Organization: | R4 |
| SEP Sequence Number: | Not reported |
| SEP Expenditure Amount: | Not reported |
| SEP Scheduled Completion Date: | Not reported |
| SEP Actual Date: | Not reported |
| SEP Defaulted Date: | Not reported |
| SEP Type: | Not reported |
| SEP Type Description: | Not reported |
| Proposed Amount: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20101210
Actual Return to Compliance Date: 20101210
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20101223
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20110211
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHBR
Enforcement Responsible Sub-Organization: R4
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20101210
Actual Return to Compliance Date: 20101210
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20101223
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No

**EMBASSY CLEANERS (Continued)** **1000708538**

Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20110211
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHBR
Enforcement Responsible Sub-Organization: R4
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20101210
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYFKY
Evaluation Responsible Sub-Organization: R3
Actual Return to Compliance Date: 20110207
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20101210
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYFKY
Evaluation Responsible Sub-Organization: R3
Actual Return to Compliance Date: 20101222
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20101210
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYFKY
Evaluation Responsible Sub-Organization: R3

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Actual Return to Compliance Date: | 20101210 |
| Scheduled Compliance Date: | Not reported |
| Date of Request: | Not reported |
| Date Response Received: | Not reported |
| Request Agency: | Not reported |
| Former Citation: | Not reported |
| | |
| Evaluation Date: | 20101210 |
| Evaluation Responsible Agency: | State |
| Found Violation: | Yes |
| Evaluation Type Description: | COMPLIANCE EVALUATION INSPECTION |
| Evaluation Responsible Person Identifier: | NYFKY |
| Evaluation Responsible Sub-Organization: | R3 |
| Actual Return to Compliance Date: | 20101210 |
| Scheduled Compliance Date: | Not reported |
| Date of Request: | Not reported |
| Date Response Received: | Not reported |
| Request Agency: | Not reported |
| Former Citation: | Not reported |
| | |
| Evaluation Date: | 20101210 |
| Evaluation Responsible Agency: | State |
| Found Violation: | Yes |
| Evaluation Type Description: | COMPLIANCE EVALUATION INSPECTION |
| Evaluation Responsible Person Identifier: | NYFKY |
| Evaluation Responsible Sub-Organization: | R3 |
| Actual Return to Compliance Date: | 20101220 |
| Scheduled Compliance Date: | Not reported |
| Date of Request: | Not reported |
| Date Response Received: | Not reported |
| Request Agency: | Not reported |
| Former Citation: | Not reported |
| | |
| Evaluation Date: | 20101210 |
| Evaluation Responsible Agency: | State |
| Found Violation: | Yes |
| Evaluation Type Description: | COMPLIANCE EVALUATION INSPECTION |
| Evaluation Responsible Person Identifier: | NYFKY |
| Evaluation Responsible Sub-Organization: | R3 |
| Actual Return to Compliance Date: | 20101210 |
| Scheduled Compliance Date: | Not reported |
| Date of Request: | Not reported |
| Date Response Received: | Not reported |
| Request Agency: | Not reported |
| Former Citation: | Not reported |
| | |
| Evaluation Date: | 20101210 |
| Evaluation Responsible Agency: | State |
| Found Violation: | Yes |
| Evaluation Type Description: | COMPLIANCE EVALUATION INSPECTION |
| Evaluation Responsible Person Identifier: | NYFKY |
| Evaluation Responsible Sub-Organization: | R3 |
| Actual Return to Compliance Date: | 20101210 |
| Scheduled Compliance Date: | Not reported |
| Date of Request: | Not reported |
| Date Response Received: | Not reported |
| Request Agency: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

Former Citation: Not reported

ICIS:

| | |
|---|---|
| Enforcement Action ID: | NY000A0000355320026600337 |
| FRS ID: | 110001601516 |
| Action Name: | EMBASSY CLEANERS 36119R208800337 |
| Facility Name: | EMBASSY CLEANERS |
| Facility Address: | 1895 PALMER AVE<br>LARCHMONT, NY 105383035 |
| Enforcement Action Type: | Notice of Violation |
| Facility County: | WESTCHESTER |
| Program System Acronym: | AIR |
| Enforcement Action Forum Desc: | Administrative - Informal |
| EA Type Code: | NOV |
| Facility SIC Code: | 7216 |
| Federal Facility ID: | Not reported |
| Latitude in Decimal Degrees: | 40.93337 |
| Longitude in Decimal Degrees: | -73.75856 |
| Permit Type Desc: | Not reported |
| Program System Acronym: | NY0000003553200266 |
| Facility NAICS Code: | 812320 |
| Tribal Land Code: | Not reported |

| | |
|---|---|
| Enforcement Action ID: | NY000A0000355320026600330 |
| FRS ID: | 110001601516 |
| Action Name: | EMBASSY CLEANERS 36119R208800330 |
| Facility Name: | EMBASSY CLEANERS |
| Facility Address: | 1895 PALMER AVE<br>LARCHMONT, NY 105383035 |
| Enforcement Action Type: | Administrative Order |
| Facility County: | WESTCHESTER |
| Program System Acronym: | AIR |
| Enforcement Action Forum Desc: | Administrative - Formal |
| EA Type Code: | SCAAAO |
| Facility SIC Code: | 7216 |
| Federal Facility ID: | Not reported |
| Latitude in Decimal Degrees: | 40.93337 |
| Longitude in Decimal Degrees: | -73.75856 |
| Permit Type Desc: | Not reported |
| Program System Acronym: | NY0000003553200266 |
| Facility NAICS Code: | 812320 |
| Tribal Land Code: | Not reported |

| | |
|---|---|
| Enforcement Action ID: | NY000A0000355320026600323 |
| FRS ID: | 110001601516 |
| Action Name: | EMBASSY CLEANERS 36119R208800323 |
| Facility Name: | EMBASSY CLEANERS |
| Facility Address: | 1895 PALMER AVE<br>LARCHMONT, NY 105383035 |
| Enforcement Action Type: | Notice of Violation |
| Facility County: | WESTCHESTER |
| Program System Acronym: | AIR |
| Enforcement Action Forum Desc: | Administrative - Informal |
| EA Type Code: | NOV |
| Facility SIC Code: | 7216 |
| Federal Facility ID: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

Latitude in Decimal Degrees: 40.93337
Longitude in Decimal Degrees: -73.75856
Permit Type Desc: Not reported
Program System Acronym: NY0000003553200266
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000355320026600305
FRS ID: 110001601516
Action Name: EMBASSY CLEANERS 36119R208800305
Facility Name: EMBASSY CLEANERS
Facility Address: 1895 PALMER AVE
LARCHMONT, NY 105383035
Enforcement Action Type: Notice of Violation
Facility County: WESTCHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.93337
Longitude in Decimal Degrees: -73.75856
Permit Type Desc: Not reported
Program System Acronym: NY0000003553200266
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000355320018900309
FRS ID: 110004345361
Action Name: EMBASSY CLEANERS 361190021300309
Facility Name: EMBASSY CLEANERS
Facility Address: 1908 PALMER AVE
LARCHMONT, NY 105382408
Enforcement Action Type: Notice of Violation
Facility County: WESTCHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7212
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.93337
Longitude in Decimal Degrees: -73.75856
Permit Type Desc: Not reported
Program System Acronym: NY0000003553200189
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000355320018900305
FRS ID: 110004345361
Action Name: EMBASSY CLEANERS 361190021300305
Facility Name: EMBASSY CLEANERS
Facility Address: 1908 PALMER AVE
LARCHMONT, NY 105382408
Enforcement Action Type: Notice of Violation
Facility County: WESTCHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal

**EMBASSY CLEANERS (Continued)** **1000708538**

EA Type Code: NOV
Facility SIC Code: 7212
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.93337
Longitude in Decimal Degrees: -73.75856
Permit Type Desc: Not reported
Program System Acronym: NY0000003553200189
Facility NAICS Code: 812320
Tribal Land Code: Not reported

US AIRS MINOR:
Envid: 1000708538
Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-12-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2010-12-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-09-19 00:00:00
Activity Status Date: Not reported

**EMBASSY CLEANERS (Continued)** **1000708538**

Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2012-08-07 00:00:00
Activity Status Date: 2012-08-07 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-07-18 00:00:00
Activity Status Date: 2002-07-18 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2012-06-22 00:00:00
Activity Status Date: 2012-06-22 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2014-02-13 00:00:00
Activity Status Date: 2014-02-13 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN

**EMBASSY CLEANERS (Continued)** **1000708538**

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-12-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-12-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-09-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-08-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200266
Facility Registry ID: 110001601516
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-07-18 00:00:00
Activity Status Date: 2002-07-18 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

**EMBASSY CLEANERS (Continued)** **1000708538**

FINDS:
Registry ID: 110004345361

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000708538
Registry ID: 110004345361

DFR URL:
Name: EMBASSY CLEANERS
Address: 1908 Palmer Ave
City,State,Zip: LARCHMONT, NY 10538

DRYCLEANERS:
Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/16/2013
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Registration Effective Date: | 05/30/2018 |
| Inspection Date: | 02/27/2015 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 05/30/2018 |
| Inspection Date: | 12/17/2015 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/14/2001 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/20/2000 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/11/2002 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/11/2003 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/08/2004 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/17/2015 |
| Install Date: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/14/2001
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/20/2000
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/11/2002
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE

**EMBASSY CLEANERS (Continued)** **1000708538**

City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/11/2003
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/08/2004
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/15/2005
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/19/2006
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported

**EMBASSY CLEANERS (Continued)** **1000708538**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/19/2007
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/16/2008
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/23/2009
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 05/30/2018 |
| Inspection Date: | 12/22/2010 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 05/30/2018 |
| Inspection Date: | 09/19/2011 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 05/30/2018 |
| Inspection Date: | 12/12/2011 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 05/30/2018 |
| Inspection Date: | 12/17/2012 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/16/2013
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 02/27/2015
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/17/2015
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/14/2001 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/20/2000 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/11/2002 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/11/2003 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/08/2004 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/15/2005 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/19/2006 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/19/2007 |
| Install Date: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 12/16/2008
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 12/23/2009
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 12/22/2010
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE

**EMBASSY CLEANERS (Continued)** **1000708538**

City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 09/19/2011
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 12/12/2011
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 12/17/2012
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 12/16/2013
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported

**EMBASSY CLEANERS (Continued)** **1000708538**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 02/27/2015
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 12/17/2015
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/14/2001
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 05/30/2018 |
| Inspection Date: | 12/20/2000 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 05/30/2018 |
| Inspection Date: | 12/11/2002 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 05/30/2018 |
| Inspection Date: | 12/11/2003 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 05/30/2018 |
| Inspection Date: | 12/08/2004 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/15/2005
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/19/2006
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/19/2007
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported

**EMBASSY CLEANERS (Continued)** **1000708538**

Registration Effective Date: 05/30/2018
Inspection Date: 12/16/2008
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/23/2009
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 12/22/2010
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 05/30/2018
Inspection Date: 09/19/2011
Install Date: Not reported
Expiration Date: 05/29/2028
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 05/30/2018 |
| Inspection Date: | 12/12/2011 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 05/30/2018 |
| Inspection Date: | 12/17/2012 |
| Install Date: | Not reported |
| Expiration Date: | 05/29/2028 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/15/2005 |
| Install Date: | Not reported |
| Expiration Date: | 05/30/2018 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 3035 |
| Facility ID: | 3-5532-00266 |
| Phone Number: | 9148345955 |
| Region: | Not reported |
| Registration Effective Date: | 06/13/2002 |
| Inspection Date: | 12/19/2006 |
| Install Date: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 12/19/2007
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 12/16/2008
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 12/23/2009
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE

**EMBASSY CLEANERS (Continued)** **1000708538**

City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 12/22/2010
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 09/19/2011
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 12/12/2011
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 12/17/2012
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported

**EMBASSY CLEANERS (Continued)** **1000708538**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 12/16/2013
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: EMBASSY CLEANERS
Address: 1895 PALMER AVE
City,State,Zip: LARCHMONT, NY 10538 3035
Facility ID: 3-5532-00266
Phone Number: 9148345955
Region: Not reported
Registration Effective Date: 06/13/2002
Inspection Date: 02/27/2015
Install Date: Not reported
Expiration Date: 05/30/2018
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

NY MANIFEST:
EPA ID: NYD986995249
Country: USA
Name: Embassy Cleaners
Address: 1895 PALMER AVE
Address 2: Not reported
City,State,Zip: LARCHMONT, NY 10538
Zip 4: Not reported
Location Address 1: 1895 PALMER AVENUE
Location Address 2: Not reported
Location City,State,Zip: LARCHMONT, NY 10538
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Embassy Cleaners
Mailing Contact: Brian
Mailing Address 1: 1895 PALMER AVENUE

**EMBASSY CLEANERS (Continued)** **1000708538**

Mailing Address 2: Not reported
Mailing City,State,Zip: LARCHMONT, NY 10538
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9148342700

Manifest Data:
Document ID: NYC5609801
Manifest Status: Not reported
Trans1 State ID: NY30747AL
Year: 1999
Trans2 State ID: NJT913LY
Generator Ship Date: 04/28/1999
Trans1 Recv Date: 04/28/1999
Trans2 Recv Date: 04/29/1999
TSD Site Recv Date: 05/04/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986995249
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: SCD987574647
TSDF ID 1: OHD980587364
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00300
Units: Pounds
Number of Containers: 005
Container Type: Fiberboard or plastic drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYC2306057

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Manifest Status: | Not reported |
| Trans1 State ID: | NYGP2381 |
| Year: | 1993 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 05/24/1993 |
| Trans1 Recv Date: | 05/24/1993 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 05/24/1993 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986995249 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00320 |
| Units: | Pounds |
| Number of Containers: | 006 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| Waste Code 7: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 8: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Waste Code: | Not reported |
| Waste Code 10: | Not reported |
| Waste Code 11: | Not reported |
| Quantity: | 00195 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

| | |
|---|---|
| Document ID: | NYC3367361 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYGT9066 |
| Year: | 1994 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 12/05/1994 |
| Trans1 Recv Date: | 12/05/1994 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/05/1994 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986995249 |
| Trans1 EPA ID: | ILD984908202 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00195 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Specific Gravity: | 01.00 |
| Waste Code 7: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 8: | Not reported |
| Waste Code: | Not reported |
| Waste Code 10: | Not reported |
| Waste Code 11: | Not reported |
| Quantity: | 00360 |
| Units: | Pounds |
| Number of Containers: | 006 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

| | |
|---|---|
| Document ID: | NYC6275564 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR2436 |
| Year: | 2000 |
| Trans2 State ID: | T104414IL |
| Generator Ship Date: | 08/31/2000 |
| Trans1 Recv Date: | 08/31/2000 |
| Trans2 Recv Date: | 09/05/2000 |
| TSD Site Recv Date: | 09/07/2000 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986995249 |
| Trans1 EPA ID: | SCR000075150 |
| Trans2 EPA ID: | SCR000074591 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| | Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00585 |
| Units: | Pounds |
| Number of Containers: | 003 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC6263414 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR2436 |
| Year: | 2000 |
| Trans2 State ID: | ILT39706 |
| Generator Ship Date: | 11/07/2000 |
| Trans1 Recv Date: | 11/07/2000 |
| Trans2 Recv Date: | 11/09/2000 |
| TSD Site Recv Date: | 11/14/2000 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986995249 |
| Trans1 EPA ID: | SCR000075150 |
| Trans2 EPA ID: | SCR000074591 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00975 |
| Units: | Pounds |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Number of Containers: | 005 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC2712295 |
| Manifest Status: | Not reported |
| Trans1 State ID: | GP2381NY |
| Year: | 1993 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 12/07/1993 |
| Trans1 Recv Date: | 12/07/1993 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/07/1993 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986995249 |
| Trans1 EPA ID: | ILD984908202 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00300 |
| Units: | Pounds |
| Number of Containers: | 005 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC6455114 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR2436 |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Year: | 2001 |
| Trans2 State ID: | 086902 |
| Generator Ship Date: | 05/09/2001 |
| Trans1 Recv Date: | 05/09/2001 |
| Trans2 Recv Date: | 05/14/2001 |
| TSD Site Recv Date: | 05/15/2001 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986995249 |
| Trans1 EPA ID: | SCR000075150 |
| Trans2 EPA ID: | SCR000074591 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00360 |
| Units: | Pounds |
| Number of Containers: | 006 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| Waste Code 7: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 8: | Not reported |
| Waste Code: | Not reported |
| Waste Code 10: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Waste Code 11: | Not reported |
| Quantity: | 00975 |
| Units: | Pounds |
| Number of Containers: | 005 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC6437711 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYC39320J |
| Year: | 2001 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 11/02/2001 |
| Trans1 Recv Date: | 11/02/2001 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 11/08/2001 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986995249 |
| Trans1 EPA ID: | SCR000075150 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00585 |
| Units: | Pounds |
| Number of Containers: | 003 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Document ID: | NYC6422354 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR2436 |
| Year: | 2001 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 09/06/2001 |
| Trans1 Recv Date: | 09/06/2001 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 09/13/2001 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986995249 |
| Trans1 EPA ID: | SCR000075150 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00535 |
| Units: | Pounds |
| Number of Containers: | 003 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

| | |
|---|---|
| Document ID: | NYC5528496 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR2436 |
| Year: | 1999 |
| Trans2 State ID: | NJT913LY |
| Generator Ship Date: | 01/25/1999 |
| Trans1 Recv Date: | 01/25/1999 |
| Trans2 Recv Date: | 01/28/1999 |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| TSD Site Recv Date: | 02/01/1999 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986995249 |
| Trans1 EPA ID: | ILD984908202 |
| Trans2 EPA ID: | SCD987574647 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00300 |
| Units: | Pounds |
| Number of Containers: | 005 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| Waste Code 7: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 8: | Not reported |
| Waste Code: | Not reported |
| Waste Code 10: | Not reported |
| Waste Code 11: | Not reported |
| Quantity: | 00195 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | TXR000050930 |
| Year: | 2018 |
| Trans2 State ID: | NJD071629976 |
| Generator Ship Date: | 08/29/2012 |
| Trans1 Recv Date: | 08/29/2012 |
| Trans2 Recv Date: | 09/07/2012 |
| TSD Site Recv Date: | 09/10/2012 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986995249 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | RID084802842 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 003575801SKS |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H020 |
| Waste Code a: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code b: | Chromium |
| Waste Code c: | 1,1-Dichloroethylene |
| Waste Code e: | Tetrachloroethylene |
| Waste Code f: | Trichlorethylene |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 200 |
| Units: | Pounds |
| Number of Containers: | 2 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Recycle |
| Specific Gravity: | 1 |

**EMBASSY CLEANERS (Continued)** **1000708538**

Click this hyperlink while viewing on your computer to access
191 additional NY MANIFEST: record(s) in the EDR Site Report.

RI MANIFEST:

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1895 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| EPA Id: | NYD986995249 |
| GEN Cert Date: | 11/23/2010 |
| Manifest Document Number: | 002496373SKS |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| TSDF Id: | RID084802842 |
| TSDF Name: | SAFETY KLEEN |
| Qty: | 240 |
| WT/Vol Units: | P |
| TSDF Date: | 12/3/2010 |
| Transporter 2 Id: | NJD071629976 |
| Item Number: | 1 |
| Transporter 2 Name: | 12/3/2010 |
| Transporter Name 2: | SAFETY KLEEN |
| Transporter EPAID: | TXR000050930 |
| Transporter Receipt Date: | 11/23/2010 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Fee Exempt Code: | Not reported |
| Comment: | Not reported |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| Quarter: | Not reported |
| Transporter Contact Name: | Not reported |
| Transporter Contact Email: | Not reported |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Billing Name: | Not reported |
| Paid Date: | Not reported |
| Paid Time: | Not reported |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Manifest Created Date: | Not reported |
| Manifest Updated Date: | Not reported |

RI MANIFEST:

| | |
|---|---|
| Transporter Receipt Date: | 8/29/2012 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 003575801SKS |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 200 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 8/29/2012 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 9/7/2012 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 9/7/2012 |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 3/26/2012 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 002740089SKS |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 200 |
| Transporter Contact Email: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 3/26/2012 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 4/7/2012 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 4/7/2012 |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 2/21/2011 |
| Number Of Containers: | 3 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 003591202FLE |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 300 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 2/21/2011 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 2/25/2011 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 2/25/2011 |
| Transporter 2 ID: | NJD071629976 |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 2/21/2011 |
| Number Of Containers: | 3 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 003591202FLE |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 300 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 2/21/2011 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 2/25/2011 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 2/25/2011 |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 7/8/2011 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 004246318FLE |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 200 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 7/8/2011 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 7/15/2011 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 7/15/2011 |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |

| | |
|---|---|
| Transporter Receipt Date: | 7/8/2011 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 004246318FLE |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 200 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 7/8/2011 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 7/15/2011 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 7/15/2011 |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 11/23/2010 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 002496373SKS |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 240 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 11/23/2010 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 12/3/2010 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 12/3/2010 |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 11/23/2010 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | SAFETY KLEEN |
| TSDF Id: | RID084802842 |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 002496373SKS |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 240 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 11/23/2010 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 12/3/2010 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | 12/3/2010 |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 9/17/2010 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | Not reported |
| TSDF Id: | Not reported |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 003869495FLE |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| Quantity: | 240 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 9/17/2010 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 9/29/2010 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | Not reported |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 8/17/2010 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | Not reported |
| TSDF Id: | Not reported |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 003860185FLE |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 240 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 8/17/2010 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 8/24/2010 |
| Manifest Created Date: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000708538**

| | |
|---|---|
| TSDF Receipt Date: | Not reported |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |
| | |
| Transporter Receipt Date: | 8/17/2010 |
| Number Of Containers: | 2 |
| Container Type: | DF |
| Waste Code1: | D007 |
| Waste Code2: | D029 |
| Waste Code3: | D039 |
| Waste Code4: | Not reported |
| Waste Code5: | Not reported |
| Waste Code6: | Not reported |
| Comment: | Not reported |
| Fee Exempt Code: | Not reported |
| TSDF Name: | Not reported |
| TSDF Id: | Not reported |
| Transporter Name 2: | SJ TRANSPORTATION CO INC |
| Company Permit Number: | Not reported |
| Year: | Not reported |
| EPA ID: | NYD986995249 |
| Manifest Docket Number: | 003860185FLE |
| Quarter: | Not reported |
| Waste Description: | TOXIC LIQUIDS ORGANIC NOS |
| Transporter Contact Name: | Not reported |
| Quantity: | 240 |
| Transporter Contact Email: | Not reported |
| WT/Vol Units: | P |
| Filing Date: | Not reported |
| Total Fee: | Not reported |
| Item Number: | 1 |
| Transporter Name: | SAFETY KLEEN |
| Billing Name: | Not reported |
| Transporter EPA ID: | TXR000050930 |
| Date Paid: | Not reported |
| Time Paid: | Not reported |
| GEN Cert Date: | 8/17/2010 |
| Facility Receipt Date: | Not reported |
| Fee: | Not reported |
| Transporter 2 Receipt Date: | 8/24/2010 |
| Manifest Created Date: | Not reported |
| TSDF Receipt Date: | Not reported |
| Transporter 2 ID: | NJD071629976 |
| Manifest Updated Date: | Not reported |

Click this hyperlink while viewing on your computer to access
2 additional RI_MANIFEST: record(s) in the EDR Site Report.

**G32** **BROMPTON APTS.** **NY LTANKS** **S102673824**
**South** **1880 PALMER AVE.** **N/A**
**< 1/8** **LARCHMONT, NY**
**0.123 mi.**
**652 ft.** **Site 3 of 15 in cluster G**

**Relative:**
**Higher**

**Actual:**
**60 ft.**

LTANKS:

| | |
|---|---|
| Name: | BROMPTON APTS. |
| Address: | 1880 PALMER AVE. |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9112775 / 1992-03-17 |
| Facility ID: | 9112775 |
| Site ID: | 93770 |
| Spill Date: | 1992-03-16 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Commercial/Industrial |
| Spill Class: | D3 |
| Cleanup Ceased: | 1992-03-17 |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1992-03-16 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1992-03-17 |
| Spill Record Last Update: | 1995-10-20 |
| Spiller Name: | Not reported |
| Spiller Company: | CASTLE OIL |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 84034 |
| Latitude: | 40.9336041 |
| Longitude: | -73.7580834 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY |
| Remarks: | SPILL ON PAVEMENT SPILL TO BE CLEANED AND DISPOSED |

All Materials:

| | |
|---|---|
| Site ID: | 93770 |
| Operable Unit ID: | 963250 |
| Operable Unit: | 01 |
| Material ID: | 414331 |
| Material Code: | 0003A |
| Material Name: | #6 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 15.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**G33** **THE BROMPTON** **NY AST** **A100112006**
**South** **1880 PALMER AVENUE** **N/A**
**< 1/8** **LARCHMONT, NY 10538**
**0.123 mi.**
**652 ft.** **Site 4 of 15 in cluster G**

**Relative:** **Higher**

**Actual:** **60 ft.**

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | THE BROMPTON |
| Address: | 1880 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-800888 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | Edvin Sanahaim |
| Owner Name: | County Estates LLC |
| Owner Street: | 384 Mamaroneck Avenue |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | White Plains, NY 10605 |
| | |
| Tank Number: | 1 |
| Status: | 4. Closed - in place |
| Date Installation: | 10/01/1950 |
| Capacity: | 5000 |
| Product Stored: | 0003. #6 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 03/01/2009 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 6. Impervious Barrier/Concrete Pad (Aboveground Only) |
| Tank Secondary Containment: | 2. Vault (w/ access),10. Impervious Underlayment (AST Only) |
| Piping Location: | 1. Aboveground |
| Piping Type: | 0. No Piping |
| Piping External Protection: | 0. None |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 2. Transfer Station Containment |
| Dispenser: | 1. Submersible |
| | |
| Tank Number: | 2 |
| Status: | 1. In-Service |
| Date Installation: | 03/01/2009 |
| Capacity: | 5000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | 0 |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 6. Aboveground in subterranean vault with access for inspections |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 6. Impervious Barrier/Concrete Pad (Aboveground Only) |
| Tank Secondary Containment: | 2. Vault (w/ access),10. Impervious Underlayment (AST Only) |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | 0. None |

**THE BROMPTON (Continued)** **A100112006**

Piping Secondary Containment: 0. None
Overfill Prevention: 4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention: 1. Catch Basin
Dispenser: 1. Submersible

---

**G34** **SIDEWALK AND PARKING LOT** **NY Spills** **S113493160**
**South** **1880 PALMER AVE** **N/A**
**< 1/8** **LARCHMONT, NY**
**0.123 mi.**
**652 ft.** **Site 5 of 15 in cluster G**

**Relative:**
**Higher**

**Actual:**
**60 ft.**

SPILLS:
Name: SIDEWALK AND PARKING LOT
Address: 1880 PALMER AVE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 1300547 / 2013-04-18
Facility ID: 1300547
Facility Type: ER
DER Facility ID: 436158
Site ID: 480875
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 6032
Spill Date: 2013-04-16
Investigator: MBMASTRO
Referred To: Not reported
Reported to Dept: 2013-04-16
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2013-04-16
Spill Record Last Update: 2013-04-21
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: BRENDA CUMMING
Latitude: 40.9334317
Longitude: -73.7579486
DEC Memo: Spoke to caller. She was called by bldg owner. The fuel oil company overfilled the tank and product
came out of the vent onto the sidewalk and parking lot. No soil or waterways impacted. Cleanup
underway. NFA....mm
Remarks: overflow out of vent

All Materials:
Site ID: 480875
Operable Unit ID: 1230662
Operable Unit: 01

**SIDEWALK AND PARKING LOT (Continued)** **S113493160**

| | |
|---|---|
| Material ID: | 2229342 |
| Material Code: | 0002A |
| Material Name: | #4 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 10.00 |
| Units: | G |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**F35** **HOFFMANS** **NY LTANKS** **S100492358**
**SE** **1850 PALMER AVE.** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.126 mi.**
**665 ft.** **Site 2 of 2 in cluster F**

**Relative:** **Higher**
**Actual:** **49 ft.**

LTANKS:

| | |
|---|---|
| Name: | HOFFMANS |
| Address: | 1850 PALMER AVE. |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9211944 / 1993-01-21 |
| Facility ID: | 9211944 |
| Site ID: | 111285 |
| Spill Date: | 1993-01-19 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C3 |
| Cleanup Ceased: | 1993-01-21 |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1993-01-19 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1993-01-21 |
| Spill Record Last Update: | 1993-03-19 |
| Spiller Name: | Not reported |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 97345 |
| Latitude: | 40.9339059 |
| Longitude: | -73.7568306 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY |
| Remarks: | 50,000 GAL UST LEAKING PUMPING OUT TANK TO DETERMINE CAUSE CALL BACK # NOT USABLE SAME AS SPILL # 9211942 |

**HOFFMANS (Continued)** **S100492358**

All Materials:

| | |
|---|---|
| Site ID: | 111285 |
| Operable Unit ID: | 978846 |
| Operable Unit: | 01 |
| Material ID: | 405327 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | Not reported |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**D36** **CON EDISON SERVICE BOX: 01375** **RCRA NonGen / NLR** **1017771736**
**ESE** **PALMER AVE & E DEPOT WAY** **FINDS** **NYP004486809**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.128 mi.**
**674 ft.** **Site 5 of 6 in cluster D**

**Relative:** **Lower**
**Actual:** **38 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20140502 |
| Handler Name: | | Con Edison Service Box: 01375 |
| Handler Address: | | Palmer Ave & E Depot Way |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYP004486809 |
| Contact Name: | | THOMAS TEELING |
| Contact Address: | | Not reported |
| Contact City,State,Zip: | | Not reported |
| Contact Telephone: | | 212-460-3770 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | SENIOR SCIENTIST |
| EPA Region: | | 02 |
| Land Type: | | Private |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | Ny |
| State District: | | NYSDEC R2 |
| Mailing Address: | | IRVING PL, 15TH FL NE |
| Mailing City,State,Zip: | | NEW YORK, NY 10003 |
| Owner Name: | Not reported | |
| Owner Type: | | Not reported |
| Operator Name: | Not reported | |
| Operator Type: | | Not reported |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |

**CON EDISON SERVICE BOX: 01375 (Continued)** **1017771736**

| | |
|---|---|
| Underground Injection Control: | No |
| Off-Site Waste Receipt: | No |
| Universal Waste Indicator: | No |
| Universal Waste Destination Facility: | No |
| Federal Universal Waste: | No |
| Active Site State-Reg Handler: | --- |
| Federal Facility Indicator: | Not reported |
| Hazardous Secondary Material Indicator: | N |
| Sub-Part K Indicator: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20150211 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20140402 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Large Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20140402 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |

**CON EDISON SERVICE BOX: 01375 (Continued)** **1017771736**

| | |
|---|---|
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |
| Receive Date: | 20140502 |
| Handler Name: CON EDISON SERVICE BOX: | 01375 |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063796183

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

**D37**
**ESE**
**1/8-1/4**
**0.128 mi.**
**674 ft.**

**CON EDISON** **NY MANIFEST** **S116550320**
**PALMER AVE & E DEPOT WAY** **N/A**
**LARCHMONT, NY 10538**

**Site 6 of 6 in cluster D**

**Relative:**
**Lower**

**Actual:**
**38 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004486809 |
| Country: | USA |
| Name: | Con Edison |
| Address: | PALMER AVE & E DEPOT WAY |
| Address 2: | Not reported |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Zip 4: | Not reported |
| Location Address 1: | PALMER AVE & E DEPOT WAY |
| Location Address 2: | SB01375 |
| Location City,State,Zip: | LARCHMONT, NY 10538 |
| Location Zip 4: | Not reported |
| Facility Status: | Not reported |
| Total Tanks: | Not reported |

**CON EDISON (Continued)** **S116550320**

Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Con Edison
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 04/02/2014
Trans1 Recv Date: 04/02/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/08/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004486809
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012354041JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 20
Units: Pounds
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)

**CON EDISON (Continued)** **S116550320**

Handling Method: Treat
Specific Gravity: 1

---

**H38** **CON EDISON** **NY MANIFEST** **S119075037**
**SW** **MYRTLE BLVD & MURRAY AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.137 mi.**
**725 ft.** **Site 1 of 10 in cluster H**

**Relative:**
**Higher**

**Actual:**
**49 ft.**

NY MANIFEST:
EPA ID: NYP004777850
Country: USA
Name: Con Edison
Address: MYRTLE BLVD & MURRAY AVE
Address 2: Not reported
City,State,Zip: LARCHMONT, NY 10538
Zip 4: Not reported
Location Address 1: MYRTLE BLVD & MURRAY
Location Address 2: SB 273
Location City,State,Zip: LARCHMONT, NY 10538
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Dennis Huacon
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 05/01/2015
Trans1 Recv Date: 05/01/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/05/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004777850
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014454351JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N

**CON EDISON (Continued)** **S119075037**

| | |
|---|---|
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H110 |
| Waste Code a: | Not reported |
| Waste Code b: | Not reported |
| Waste Code c: | Not reported |
| Waste Code e: | Lead |
| Waste Code f: | Not reported |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 50 |
| Units: | Pounds |
| Number of Containers: | 1 |
| Container Type: | Cargo tanks (tank trucks) |
| Handling Method: | Treat |
| Specific Gravity: | 1 |

---

**H39** **CONSOLIDATED EDISON COMPANY OF NY C/O ACV ENVIRO** **E MANIFEST** **1031972966**
**SW** **MYRTLE BLVD & MURRAY AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.137 mi.**
**725 ft.** **Site 2 of 10 in cluster H**

**Relative:** **Higher**

**Actual:** **49 ft.**

E MANIFEST:

| | |
|---|---|
| Manifest Tracking Number: | 024111742JJK |
| Last Updated Date: | 20221025 |
| Shipped Date: | 20221014 |
| Received Date: | 20221018 |
| Manifest Status: | Signed |
| Submission Type: | DataImage5Copy |
| Origin Type: | Service |
| Generator EPA ID: | NYR000114579 |
| Generator Name: | Consolidated Edison Company Of Ny C/O Acv Enviro |
| Generator Location Street Number: | Not reported |
| Generator Location Street 1: | MYRTLE BLVD & MURRAY AVE |
| Generator Location Street 2: | Not reported |
| Generator Location City: | LARCHMONT |
| Generator Location State: | NY |
| Generator Location Zip: | 10538 |
| Generator Mail Street Number: | Not reported |
| Generator Mail Street 1: | 928 E HAZELWOOD AVE |
| Generator Mail Street 2: | Not reported |
| Generator Mail City: | RAHWAY |
| Generator Mail Zip: | 07065 |
| Generator Mail State: | NJ |
| Generator Contact Company Name: | Not reported |
| Designated Facility EPA ID: | NJD991291105 |
| Designated Facility Name: | Clean Earth Of North Jersey |

**CONSOLIDATED EDISON COMPANY OF NY C/O ACV ENVIRO (Continued)** **1031972966**

Designated Facility Mail Street Number: 105
Designated Facility Mail Street 1: Not reported
Designated Facility Mail Street 2: JACOBUS AVE
Designated Facility Mail City: KEARNY
Designated Facility Mail Zip: 07032
Designated Facility Mail State: NJ
Designated Facility Location Street Number: 105
Designated Facility Location Street 1: JACOBUS AVE
Designated Facility Location Street 2: Not reported
Designated Facility Location City: KEARNY
Designated Facility Location Zip: 07032
Designated Facility Location State: NJ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 024111742JJK
Transporter Line Number: 1
Transporter EPA ID: NJD003812047
Transporter Name: Acv Environmental Services Inc.

Waste Line:
Manifest Tracking Number: 024111742JJK
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 500
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.25
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.25
Waste Quantity, in Kilograms: 226.7575
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 226.7575
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported

**CONSOLIDATED EDISON COMPANY OF NY C/O ACV ENVIRO (Continued)** **1031972966**

| | |
|---|---|
| EPA Waste Indicator: | Y |
| Federal Waste Codes: | D008 |
| Quantity Haz Kg: | 226.7575 |
| Quantity Haz Tons: | 0.25 |
| Quantity Non Haz Kg: | 0 |
| Quantity Non Haz Tons: | 0 |
| State Waste Codes: | NY-T |

---

**H40** **CON EDISON** **NJ MANIFEST** **S120671354**
**SW** **MYRTLE BLVD & MURRAY AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.137 mi.**
**725 ft.** **Site 3 of 10 in cluster H**

**Relative:**
**Higher**

**Actual:**
**49 ft.**

NJ MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004777850 |
| Name: | CON EDISON |
| Address: | MYRTLE BLVD & MURRAY AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| County: | Not reported |
| Mailing Address: | IRVING PL 15TH FL NE |
| Mailing City,State,Zip: | NEW YORK, NY 10003 |
| Telephone: | Not reported |
| Emergency Telephone: | Not reported |
| Contact: | THOMAS TEELING |
| Comments: | Not reported |
| SIC Code: | Not reported |
| County: | NY119 |
| Municipal: | Not reported |
| Previous EPAID: | Not reported |
| Generator Flag: | Not reported |
| Transporter Flag: | Not reported |
| TSDF Flag: | Not reported |
| Name Change: | Not reported |
| Date Change: | Not reported |

Manifest Data:

| | |
|---|---|
| EPA ID: | NYP004777850 |
| Manifest Number: | 014454351JJK |
| Date Shipped: | 5/1/2015 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NYD006982359 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |

**CON EDISON (Continued)** **S120671354**

| | |
|---|---|
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Was Load Rejected: | Not reported |
| Reason Load Was Rejected: | Not reported |

---

**H41** **CON EDISON** **RCRA NonGen / NLR** **1019902790**
**SW** **MYRTLE BLVD & MURRAY AVE** **FINDS** **NYP004777850**
**1/8-1/4** **LARCHMONT, NY 10538** **ECHO**
**0.137 mi.**
**725 ft.** **Site 4 of 10 in cluster H**

**Relative:** **Higher**

**Actual:** **49 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20150501 |
| Handler Name: | | Con Edison |
| Handler Address: | | Myrtle Blvd & Murray Ave |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYP004777850 |
| Contact Name: | | THOMAS TEELING |
| Contact Address: | | Not reported |
| Contact City,State,Zip: | | Not reported |
| Contact Telephone: | | 212-460-3770 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Private |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | Ny |
| State District: | | NYSDEC R2 |
| Mailing Address: | | IRVING PL 15TH FL NE |
| Mailing City,State,Zip: | | NEW YORK, NY 10003 |
| Owner Name: | Not reported | |
| Owner Type: | | Not reported |
| Operator Name: | Not reported | |
| Operator Type: | | Not reported |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |

**CON EDISON (Continued)** **1019902790**

| | |
|---|---|
| Transporter Activity: | No |
| Transfer Facility Activity: | No |
| Recycler Activity with Storage: | No |
| Small Quantity On-Site Burner Exemption: | No |
| Smelting Melting and Refining Furnace Exemption: | No |
| Underground Injection Control: | No |
| Off-Site Waste Receipt: | No |
| Universal Waste Indicator: | No |
| Universal Waste Destination Facility: | No |
| Federal Universal Waste: | No |
| Active Site State-Reg Handler: | --- |
| Federal Facility Indicator: | Not reported |
| Hazardous Secondary Material Indicator: | N |
| Sub-Part K Indicator: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20160909 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20150501 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20150501 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |

**CON EDISON (Continued)** **1019902790**

| | |
|---|---|
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069694726

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

| | |
|---|---|
| Envid: | 1019902790 |
| Registry ID: | 110069694726 |

DFR URL:

| | |
|---|---|
| Name: | CON EDISON |
| Address: | Myrtle Blvd & Murray Ave |
| City,State,Zip: | LARCHMONT, NY 10538 |

---

**G42** **HOFFMAN INVESTORS CORP.** **NY LTANKS** **S100492356**
**South** **1890 PALMER AVENUE** **NY LIENS** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.142 mi.**
**748 ft.** **Site 6 of 15 in cluster G**

**Relative:**
**Higher**

**Actual:**
**59 ft.**

LTANKS:

| | |
|---|---|
| Name: | EAST RIVER SAVINGS BANK |
| Address: | 1890 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9211942 / 2000-03-09 |
| Facility ID: | 9211942 |
| Site ID: | 104436 |
| Spill Date: | 1993-01-19 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |

**HOFFMAN INVESTORS CORP. (Continued)** **S100492356**

| | |
|---|---|
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1993-01-19 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Affected Persons |
| Last Inspection: | Not reported |
| Recommended Penalty: | True |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1993-01-21 |
| Spill Record Last Update: | 2005-11-23 |
| Spiller Name: | Not reported |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 92263 |
| Latitude: | 40.9334466 |
| Longitude: | -73.7585140 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/28/99 CLEANUP COMPLETED. ISR COMPLETED 6/23/99. |
| Remarks: | UNDERGROUND STORAGE TANK AT BANK LEAKING PETROLEUM LEAKING INTO BASEMENT BLDG. NEXT DOOR NOTIFIED HD & HAZMAT ON SCENE CONTRACTOR CALLED TO CLEAN UP |

All Materials:

| | |
|---|---|
| Site ID: | 104436 |
| Operable Unit ID: | 976512 |
| Operable Unit: | 01 |
| Material ID: | 405325 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

LIENS:

| | |
|---|---|
| Name: | HOFFMAN INVESTORS CORP. |
| Address: | 1890 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY |
| Region: | 3 |
| Spill No: | 92-11942 |
| Tax Map Id: | 6-3-6 |
| Lien Request Received: | 06/26/2001 |
| Request Sent To APA Or Vendor: | 07/09/2001 |
| Draft Lien Received From Vendor: | 08/13/2001 |
| Approved Lien To Administrator: | Not reported |
| Signed By Administrator: | Not reported |

**HOFFMAN INVESTORS CORP. (Continued)** **S100492356**

| | |
|---|---|
| Received From Administrator: | Not reported |
| Sent For Filing: | Not reported |
| Resent For Filing: | Not reported |
| Proof Of Service Received: | Not reported |
| Sent To OAG: | 08/15/2001 |
| Amount: | 25322.07 |
| Release Required: | 06/28/2002 |
| Sent To Administrator: | Not reported |
| Signed By Adminstrator: | Not reported |
| Received From Adminsitrator: | Not reported |
| Release Sent To OAG: | 06/30/2002 |
| Complete: | True |
| Release: | True |
| Withdrawn: | Not reported |

---

**G43** **LARCHMONT PLAZA** **NY UST** **U004370092**
**South** **1890 PALMER AVE.** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.142 mi.**
**748 ft.** **Site 7 of 15 in cluster G**

**Relative:** WESTCHESTER CO. UST:
**Higher**

**Actual:**
**59 ft.**

| | |
|---|---|
| Name: | LARCHMONT PLAZA |
| Address: | 1890 PALMER AVE. |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-505102 / Unregulated: <1101 gal. PBS |
| Operator Name: | Hoffmann Investors Corp. |
| Owner Name: | Hoffmann Investors Corp. |
| Owner Street: | 56 Harrison Street |
| Owner Address2: | Not reported |
| Owner City: | New Rochelle |
| Owner State: | NY |
| Owner Zipcode: | 10801 |
| GDS Number: | Not reported |
| | |
| Tank Number: | 1 |
| Status: | 3. Closed - Removed |
| Capacity: | 6000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 06/01/1978 |
| Date Perm Closure: | Not reported |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 4. Fiberglass coated steel |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 2. Underground/on ground |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 0. None |
| | |
| Tank Number: | 1 TEMPORARY |

**LARCHMONT PLAZA (Continued)** **U004370092**

| | |
|---|---|
| Status: | 0. Administratively closed |
| Capacity: | 1000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 01/01/1900 |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | Not reported |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 1. Aboveground |
| Piping Type: | 10. Copper |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 1 TEMPORARY |
| Status: | 0. Administratively closed |
| Capacity: | 1000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 01/01/1900 |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | Not reported |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 1. Aboveground |
| Piping Type: | 10. Copper |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 2 |
| Status: | 3. Closed - Removed |
| Capacity: | 1000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 06/01/1978 |
| Date Perm Closure: | Not reported |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 4. Fiberglass coated steel |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 2. Underground/on ground |

**LARCHMONT PLAZA (Continued)** **U004370092**

| | |
|---|---|
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 0. None |

---

**G44** **NEW YORK STATE AUTHORITY - CHATSWORTH AVE OVER I-9** **RCRA-SQG 1031488798**
**SSW** **147-199 CHATSWORTH AVE** **ECHO NYR000271585**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.145 mi.**
**766 ft.** **Site 8 of 15 in cluster G**

**Relative:** **Higher**

**Actual:** **57 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20250529 |
| Handler Name: | | New York State Authority - Chatsworth Ave Over I-95 Ny-Nh-Hrr - Bin 5514600 |
| Handler Address: | | Chatsworth Ave |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYR000271585 |
| Contact Name: | | PAMILA RAMOTAR-JOHN |
| Contact Address: | | EXECUTIVE BLVD STE 400 |
| Contact City,State,Zip: | | SUFFERN, NY 10901 |
| Contact Telephone: | | 845-918-2526 |
| Contact Fax: | | Not reported |
| Contact Email: | | PAMILA.JOHN@THRUWAY.NY.GOV |
| Contact Title: | | ENV SPECIALIST II |
| EPA Region: | | 02 |
| Land Type: | | State |
| Federal Waste Generator Description: | | Small Quantity Generator |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Handler Activities |
| State District Owner: | | Ny |
| State District: | | NYSDEC R3 |
| Mailing Address: | | EXECUTIVE BLVD STE 400 |
| Mailing City,State,Zip: | | SUFFERN, NY 10901 |
| Owner Name: | Nys Thruway Auth | |
| Owner Type: | | State |
| Operator Name: | Nys Thruway Auth | |
| Operator Type: | | State |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |

**NEW YORK STATE AUTHORITY - CHATSWORTH AVE OVER I-95 NY-NH-HR (Continued)** **1031488798**

| | |
|---|---|
| Sub-Part K Indicator: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20250530 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | D001 |
| Waste Description: | Ignitable Waste |
| Waste Code: | D002 |
| Waste Description: | Corrosive Waste |
| Waste Code: | D007 |
| Waste Description: | Chromium |
| Waste Code: | D008 |
| Waste Description: | Lead |
| Waste Code: | D018 |
| Waste Description: | Benzene |
| Waste Code: | D035 |
| Waste Description: | Methyl Ethyl Ketone |
| Waste Code: | F003 |
| Waste Description: | The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |

**NEW YORK STATE AUTHORITY - CHATSWORTH AVE OVER I-95 NY-NH-HR (Continued)** **1031488798**

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: NYS THRUWAY AUTH
Legal Status: State
Date Became Current: 19551215
Date Ended Current: Not reported
Owner/Operator Address: 200 SOUTHERN BLVD
Owner/Operator City,State,Zip: ALBANY, NY 12201
Owner/Operator Telephone: 518-436-2700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYS THRUWAY AUTH
Legal Status: State
Date Became Current: 19551215
Date Ended Current: Not reported
Owner/Operator Address: 200 SOUTHERN BLVD
Owner/Operator City,State,Zip: ALBANY, NY 12201
Owner/Operator Telephone: 518-436-2700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYS THRUWAY AUTH
Legal Status: State
Date Became Current: 19551215
Date Ended Current: Not reported
Owner/Operator Address: 200 SOUTHERN BLVD
Owner/Operator City,State,Zip: ALBANY, NY 12201
Owner/Operator Telephone: 518-436-2700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYS THRUWAY AUTH
Legal Status: State
Date Became Current: 19551215
Date Ended Current: Not reported
Owner/Operator Address: 200 SOUTHERN BLVD
Owner/Operator City,State,Zip: ALBANY, NY 12201
Owner/Operator Telephone: 518-436-2700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

**NEW YORK STATE AUTHORITY - CHATSWORTH AVE OVER I-95 NY-NH-HR (Continued)** **1031488798**

Historic Generators:

| | |
|---|---|
| Receive Date: | 20250129 |
| Handler Name: | NYS THRUWAY AUTH-CHATSWORTH AVE OVER I-95 NY-NH-HRR - BIN 5514600 |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | No |
| Electronic Manifest Broker: | No |

| | |
|---|---|
| Receive Date: | 20250529 |
| Handler Name: | NEW YORK STATE AUTHORITY - CHATSWORTH AVE OVER I-95 NY-NH-HRR - BIN 5514600 |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | No |
| Electronic Manifest Broker: | No |

List of NAICS Codes and Descriptions:

| | |
|---|---|
| NAICS Code: | 237310 |
| NAICS Description: | Highway, Street, And Bridge Construction |

Facility Has Received Notices of Violations:

| | |
|---|---|
| Violations: | No Violations Found |

Evaluation Action Summary:

| | |
|---|---|
| Evaluations: | No Evaluations Found |

ECHO:

| | |
|---|---|
| Envid: | 1031488798 |
| Registry ID: | 110072070765 |

DFR URL:

| | |
|---|---|
| Name: | NEW YORK STATE AUTHORITY - CHATSWORTH AVE OVER I-95 NY-NH-HRR - BIN 5514600 |
| Address: | 147-199 Chatsworth Ave |
| City,State,Zip: | LARCHMONT, NY 10538 |

**I45** **LARCHMONT/PALMER COOP.** **NY AST** **S110540027**
**ENE** **1299 PALMER AVE** **NY Spills** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.146 mi.**
**769 ft.** **Site 1 of 2 in cluster I**

**Relative:**
**Higher**

**Actual:**
**54 ft.**

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | LARCHMONT PALMER |
| Address: | 1299 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-504467 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | Rodney Ciriano |
| Owner Name: | Larchmont Palmer Owners, Inc. |
| Owner Street: | 1299 Palmer Avenue |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | Larchmont, NY 10538 |
| | |
| Tank Number: | 003 |
| Status: | 1. In-Service |
| Date Installation: | 12/07/2010 |
| Capacity: | 7000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | 0 |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 6. Impervious Barrier/Concrete Pad (Aboveground Only) |
| Tank Secondary Containment: | 2. Vault (w/ access) |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | Not reported |
| Piping Secondary Containment: | Not reported |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 2. Suction |

SPILLS:

| | |
|---|---|
| Name: | CON ED POLE 38 |
| Address: | 1299 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 2502974 / 2025-07-17 |
| Facility ID: | 2502974 |
| Facility Type: | ER |
| DER Facility ID: | 394390 |
| Site ID: | 680333 |
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | Not reported |
| SWIS: | 6032 |
| Spill Date: | 2025-07-03 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2025-07-03 |
| CID: | Not reported |

**LARCHMONT/PALMER COOP. (Continued)** **S110540027**

| | |
|---|---|
| Water Affected: | Not reported |
| Spill Source: | Transformer |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2025-07-03 |
| Spill Record Last Update: | 2025-07-17 |
| Spiller Name: | Not reported |
| Spiller Company: | CON ED |
| Spiller Address: | Not reported |
| Spiller Company: | 999 |
| Contact Name: | MIKE BETTO |
| Latitude: | Not reported |
| Longitude: | Not reported |
| DEC Memo: | 07/03/25 Excerpt from EMIS, BW Emergency Overhead on location for leaking transformer reported 3 gallons of oil (unknown PCB information) to soil and sidewalk, active leak on Pole 38. Yellow tag 112064. Overhead has been notified and pending resources for cleanup. Area to be barricaded. NYSDEC & WCDOH were notified. TG Excerpt from EMIS, 7/7/2025 2:58 PM On 07/07/2025 at 13:00 Clean Harbors removed oily soil/grass and double wash sidewalk with safe wash. Clean Harbors vactor removed 500 pounds of waste to be disposed at Clean Earth of North Jersey under Manifest BOL 2114339. Transformer still bagged on pole. Khwalsingh, Taniki 7/8/2025 11:35 AM Overhead crews removed bagged transformer and install new transformer. Scavone, Paul NFA. TG concrete |
| Remarks: | |

All Materials:

| | |
|---|---|
| Site ID: | 680333 |
| Operable Unit ID: | 1426958 |
| Operable Unit: | 01 |
| Material ID: | 2446905 |
| Material Code: | 0020A |
| Material Name: | transformer oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 3.00 |
| Units: | G |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | LARCHMONT/PALMER COOP. |
| Address: | 1299 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9001057 / 1991-06-25 |
| Facility ID: | 9001057 |
| Facility Type: | ER |
| DER Facility ID: | 394390 |
| Site ID: | 223629 |

**LARCHMONT/PALMER COOP. (Continued)** **S110540027**

| | |
|---|---|
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | B3 |
| SWIS: | 6032 |
| Spill Date: | 1990-04-27 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1990-04-27 |
| CID: | Not reported |
| Water Affected: | L.I. SOUND |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Citizen |
| Cleanup Ceased: | 1953-06-18 |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1990-05-08 |
| Spill Record Last Update: | 2010-09-03 |
| Spiller Name: | Not reported |
| Spiller Company: | LARCHMONT PALMER OWNERS |
| Spiller Address: | 1299 PALMER AVE. |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Latitude: | 40.9361759 |
| Longitude: | -73.7543291 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/25/91: COOP HIRED EES TO CLEAN UP SURFACE SPILL AND REMOVE LEAKING TANK. CLEANUP WAS SATISFACTORY. NFA. |
| Remarks: | BLACK LIQUID IN CULVERT TRACED TO 1295 PALMER AVE MAMARONECK FUEL TANKOR PIPELINE SERVICING ABOVE APT. COMPLEX DEVELOPED A LEAK SUBSURFACE #6 FUEL OIL ENTERED STORM DRAIN SYSTEM |

All Materials:

| | |
|---|---|
| Site ID: | 223629 |
| Operable Unit ID: | 939490 |
| Operable Unit: | 01 |
| Material ID: | 439409 |
| Material Code: | 0003A |
| Material Name: | #6 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1000.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | APARTMENT BLDG |
| Address: | 1299 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1006062 / 2015-11-10 |
| Facility ID: | 1006062 |
| Facility Type: | ER |
| DER Facility ID: | 394390 |
| Site ID: | 439399 |

**LARCHMONT/PALMER COOP. (Continued)** **S110540027**

| | |
|---|---|
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | A3 |
| SWIS: | 6032 |
| Spill Date: | 2010-09-01 |
| Investigator: | TDGHIOSA |
| Referred To: | WCDOH |
| Reported to Dept: | 2010-09-01 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2010-09-01 |
| Spill Record Last Update: | 2015-11-13 |
| Spiller Name: | RON SINCLARE |
| Spiller Company: | LARCHMONT PALMER INC |
| Spiller Address: | 1299 PALMER AVE |
| Spiller Company: | 999 |
| Contact Name: | RON SINCLARE |
| Latitude: | 40.9359000 |
| Longitude: | -73.7548730 |
| DEC Memo: | 9-1-10 Called and left message for Barbara to return call to dispatch desk with details. jm Spoke with Barbara. She is on top of this. Tank is being tested today. She told RP that it if isn't tested today they need to empty the tank. Petroleum odors are in the air near the tank. Barbara will follow up with O'Mara, O'Dee and Todd. jm 9/3/10: Update from Chris Lalak of WCDoH: This spill is a large release from a 10000 UST. Clean up is going on, but there is likely oil in the pea gravel around the tank. Eastmond and Moran are working on the spill clean-up. If we get some heavy rains today some oil may be pushed out. If it does get out it will likely get to the Pine Brook. The drainage route is not clear. Everything is culverted in the area. The spill so far has gotten into drain and then into a drainage gully next to the railroad tracks jod 3/21/11: See letter from WCDOH in eDocs. jod Lalak, Chris 3/14/2011 9:51 AM 1006062 1299 Palmer ave, Mamaroneck Further action required. I gave them 1 month to get all the paperwork in. 7/25/11: Letter from WCDOH dated 7 June 2011 entered into eDocs. Further work required. jod 11/30/2011: Letter from WCDOH dated 24 Oct 2011 entered into eDocs. Further monitoring of site conditions required. jod 07/13/15 Todd, As discussed in our recent conversation: MER would like to utilize Guite Environmental to oversee the application and injection of the same surfactant material we utilized in the basement of 1299 |

**LARCHMONT/PALMER COOP. (Continued)** **S110540027**

Palmer Avenue, into the swale in the back of the same property. It appears that the application of this material has cleaned up the contamination in the basement area, but since a sheen has been witnessed in the swale, we feel there must still be contamination either in the piping leading to the swale or trapped in the ballast rock in the swale itself. Chris Lalak with WCDOH has witnessed a sheen still appearing in the swale. We have been changing the sorbents monthly, but this is an ongoing defensive move, vs offensive move to remove the contaminate causing the ongoing sheen. . First we would like to utilize a jet rod machine to clean the inside of the pipe that empties into the swale. MER would also flush and power wash the 2 access manholes that are in the parking lot. ( the sumps/piping discharge to these 2 manholes) MER would setup a containment with absorbents in the swale to capture any oil/sheen that was flushed back to the swale. Once this flush has been done, MER would start at the sumps in the basement and apply a surfactant material that would flow from the sumps to the swale, again, being captured in a containment in the swale. Next MER would inject the surfactant based product into various points (temp wells) on bottom and sides walls of the swale, both on the ballast side and fence side. MER would have a containment setup at the southern end of the property to capture the product and allow our vacuum truck to remove released product. We do not have a designated date at this time when we would like to perform this work, as first we wanted to seek your written approval for this action. We would then present our proposal to Larchmont Palmer owners. This work would be performed when the swale is at a very low water level to allow for better results. I have copied Ron Sinclair from Larchmont Palmer (Stillman Management) to keep him in the loop. Michael C. Barden Moran Environmental Recovery 20 Commerce Road Newtown, CT 06470 07/13/15 Proposed work plan submitted by M Barden was approved. TG 11/10/15 Guite Environmental Corp submitted a Surfactant and Oxidant Implementation report describing the use of a surfactant and peroxide mixture to remediate the drainage system and impacted drainage swale. (report in DecDocs). NFA. TG

Remarks: 10,000 GAL TANK LEAKING WITH 3,000 GAL IN TANK. CLEANUP IN PROGRESS. PRODUCT IN INPROPER SPACE.

All Materials:

Site ID: 439399
Operable Unit ID: 1190044
Operable Unit: 01
Material ID: 2185011
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported

**LARCHMONT/PALMER COOP. (Continued)** **S110540027**

| | |
|---|---|
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**I46** **LARCHMONT PALMER** **NY UST** **U003994687**
**ENE** **1299 PALMER AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.146 mi.**
**769 ft.** **Site 2 of 2 in cluster I**

**Relative:** **Higher**

**Actual:** **54 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | LARCHMONT PALMER |
| Address: | 1299 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-504467 / Active |
| Operator Name: | Rodney Ciriano |
| Owner Name: | Larchmont Palmer Owners, Inc. |
| Owner Street: | 1299 Palmer Avenue |
| Owner Address2: | Not reported |
| Owner City: | Larchmont |
| Owner State: | NY |
| Owner Zipcode: | 10538 |
| GDS Number: | Not reported |
| | |
| Tank Number: | 001 |
| Status: | 3a. Closed - Prior to 04/1991 |
| Capacity: | 10000 |
| Product Stored: | 0003. #6 Fuel Oil |
| Product Stored Percent: | 0 |
| Tank Leak Detection: | 0. None |
| Date Installation: | 01/01/1900 |
| Date Perm Closure: | 09/01/1990 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 1. Epoxy liner |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | Not reported |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | Not reported |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 2. Suction |
| | |
| Tank Number: | 002 |
| Status: | 3. Closed - Removed |
| Capacity: | 10000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | 0 |
| Tank Leak Detection: | 2. Manual Interstitial Monitoring |
| Date Installation: | 09/01/1990 |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |

**LARCHMONT PALMER (Continued)** **U003994687**

| | |
|---|---|
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 2. Original sacrificial anode |
| Tank Secondary Containment: | 4. Double-Walled (underground only) |
| Piping Location: | 2. Underground/on ground |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 2. Original sacrificial anode |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only) |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 2. Suction |

---

**J47** **VERIZON NEW YORK INC. (NY96242)** **NY UST** **U004469183**
**SSE** **5 FRANKLIN AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.159 mi.**
**837 ft.** **Site 1 of 4 in cluster J**

**Relative:** WESTCHESTER CO. UST:
**Higher**

**Actual:** **57 ft.**

| | |
|---|---|
| Name: | VERIZON NEW YORK INC. (NY96242) |
| Address: | 5 FRANKLIN AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-184519 / Active |
| Operator Name: | Verizon New York, Inc. |
| Owner Name: | Verizon New York, Inc. |
| Owner Street: | 140 West Street |
| Owner Address2: | Not reported |
| Owner City: | New York |
| Owner State: | NY |
| Owner Zipcode: | 10007 |
| GDS Number: | Not reported |
| | |
| Tank Number: | 1 |
| Status: | 3. Closed - Removed |
| Capacity: | 3000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 01/01/1954 |
| Date Perm Closure: | 11/01/1997 |
| Tank Location: | Not reported |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Secondary Containment: | Not reported |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only) |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 2. Suction |
| | |
| Tank Number: | 2 |
| Status: | 3. Closed - Removed |
| Capacity: | 550 |
| Product Stored: | 0008. Diesel |

**VERIZON NEW YORK INC. (NY96242) (Continued)** **U004469183**

| | |
|---|---|
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 01/01/1954 |
| Date Perm Closure: | 11/01/1997 |
| Tank Location: | Not reported |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Secondary Containment: | Not reported |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only) |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 3 |
| Status: | 3. Closed - Removed |
| Capacity: | 1300 |
| Product Stored: | 0008. Diesel |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 5. In-Tank System (auto tank gauge) |
| Date Installation: | Not reported |
| Date Perm Closure: | 01/01/2003 |
| Tank Location: | Not reported |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Secondary Containment: | Not reported |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 2. High Level Alarm |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 2. Suction |

---

**J48** **BELL ATLANTIC** **NY LTANKS** **U003648326**
**SSE** **5 FRANKLIN ST** **NY AST** **N/A**
**1/8-1/4** **LARCHMONT, NY** **NY Spills**
**0.159 mi.**
**837 ft.** **Site 2 of 4 in cluster J**

**Relative:**
**Higher**

**Actual:**
**57 ft.**

LTANKS:

| | |
|---|---|
| Name: | BELL ATLANTIC |
| Address: | 5 FRANKLIN ST |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9810030 / 1998-11-09 |
| Facility ID: | 9810030 |
| Site ID: | 245767 |
| Spill Date: | 1998-11-06 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |

**BELL ATLANTIC (Continued)** **U003648326**

| | |
|---|---|
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1998-11-09 |
| CID: | 281 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-11-09 |
| Spill Record Last Update: | 1998-11-20 |
| Spiller Name: | Not reported |
| Spiller Company: | CASTLE FUELS |
| Spiller Address: | UNKNOWN |
| Spiller County: | 001 |
| Spiller Contact: | JANE ARMSTRONG |
| Spiller Phone: | (914) 834-9994 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 201824 |
| Latitude: | 40.9326945 |
| Longitude: | -73.7581005 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY |
| Remarks: | CALLER RESPONDED TO ABOVE LOCATION FOR CLEANUP OF ABOVE MATERIAL. MATERIAL HAS BEEN CONTAINED AND CLEANUP EXPECTED TO BE COMPLETED THIS DATE. SPILL CAUSE IS TANK OVERFILL BY OIL COMPANY. NO FURTHER INFO ON OIL COMPANY AT THIS TIME. NO CALL BACK REQUESTED. |

All Materials:

| | |
|---|---|
| Site ID: | 245767 |
| Operable Unit ID: | 1067301 |
| Operable Unit: | 01 |
| Material ID: | 313917 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 50.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | VERIZON NEW YORK INC. (NY96242) |
| Address: | 5 FRANKLIN AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-184519 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | Verizon New York, Inc. |
| Owner Name: | Verizon New York, Inc. |
| Owner Street: | 140 West Street |
| Owner Address2: | Not reported |

**BELL ATLANTIC (Continued)** **U003648326**

Owner City/State/Zip: New York, NY 10007

Tank Number: 4
Status: 1. In-Service
Date Installation: 09/01/1997
Capacity: 1500
Product Stored: 0008. Diesel
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating
Tank Leak Detection: 1. Electronic Interstitial Monitoring
Tank Secondary Containment: 2. Vault (w/ access)
Piping Location: 1. Aboveground
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 0. None
Piping Leak Detection: 0. None
Piping Secondary Containment: 0. None
Overfill Prevention: 2. High Level Alarm
Spill Prevention: 1. Catch Basin
Dispenser: 2. Suction

Tank Number: 5
Status: 1. In-Service
Date Installation: 10/01/2005
Capacity: 300
Product Stored: 0008. Diesel
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating
Tank Leak Detection: 1. Electronic Interstitial Monitoring
Tank Secondary Containment: 9. Modified double-walled (aboveground only)
Piping Location: 1. Aboveground
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 0. None
Piping Leak Detection: 0. None
Piping Secondary Containment: 0. None
Overfill Prevention: 3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention: 0. None
Dispenser: 2. Suction

SPILLS:
Name: BELL ATLANTIC
Address: 5 FRANKLIN AVE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 9712641 / 1998-02-18
Facility ID: 9712641
Facility Type: ER
DER Facility ID: 139540
Site ID: 165557
DEC Region: 3

**BELL ATLANTIC (Continued)** **U003648326**

| | |
|---|---|
| Spill Cause: | Equipment Failure |
| Spill Class: | C4 |
| SWIS: | 6000 |
| Spill Date: | 1998-02-11 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1998-02-11 |
| CID: | 252 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Affected Persons |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-02-11 |
| Spill Record Last Update: | 2003-08-27 |
| Spiller Name: | UNK |
| Spiller Company: | CASTLE FUEL OIL CO |
| Spiller Address: | 290 LOCUST AVE |
| Spiller Company: | 001 |
| Contact Name: | FARNK YAZZETTA |
| Latitude: | 40.9326945 |
| Longitude: | -73.7581005 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 02/18/98 C.BADOLATO; OIL IN BASEMENT; CLEANED BY COOK CO. NO OIL ON FLOOR OF TANK ROOM; NO DRAINS IN ROOM; |
| Remarks: | SPILL HAS BEEN CONTAINED-WILL MAKE THEIR OWN ARRANGEMENTS FOR CLEANUP |

All Materials:

| | |
|---|---|
| Site ID: | 165557 |
| Operable Unit ID: | 1055509 |
| Operable Unit: | 01 |
| Material ID: | 327241 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 200.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | SPILL NUMBER 9811748 |
| Address: | 5 FRANKLIN AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9811748 / 1998-12-23 |
| Facility ID: | 9811748 |
| Facility Type: | ER |
| DER Facility ID: | 139540 |
| Site ID: | 165558 |
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | C4 |

**BELL ATLANTIC (Continued)** **U003648326**

| | |
|---|---|
| SWIS: | 6000 |
| Spill Date: | 1998-12-17 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1998-12-17 |
| CID: | 322 |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-12-17 |
| Spill Record Last Update: | 1999-01-20 |
| Spiller Name: | FRANK |
| Spiller Company: | BELL ATLANTIC |
| Spiller Address: | 5 FRANKLIN AVE |
| Spiller Company: | 001 |
| Contact Name: | FRANK YAZZETTA |
| Latitude: | 40.9326945 |
| Longitude: | -73.7581005 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY |
| Remarks: | Defective high level alarm caused spill - chemtel was hired to do clean up |

All Materials:

| | |
|---|---|
| Site ID: | 165558 |
| Operable Unit ID: | 1072541 |
| Operable Unit: | 01 |
| Material ID: | 312034 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1000.00 |
| Units: | G |
| Recovered: | 1000.00 |
| Oxygenate: | Not reported |

---

**49**
**NE**
**1/8-1/4**
**0.162 mi.**
**856 ft.**

**PRESTO RESIDNECE** **NY LTANKS** **S111012254**
**130 LAUREL AVE** **N/A**
**LARCHMONT, NY**

**Relative: Higher**

**Actual: 46 ft.**

LTANKS:

| | |
|---|---|
| Name: | PRESTO RESIDNECE |
| Address: | 130 LAUREL AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1100421 / 2011-09-15 |
| Facility ID: | 1100421 |
| Site ID: | 447824 |
| Spill Date: | 2011-04-12 |

**PRESTO RESIDNECE (Continued)** **S111012254**

| | |
|---|---|
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2011-04-12 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2011-04-12 |
| Spill Record Last Update: | 2011-09-15 |
| Spiller Name: | Not reported |
| Spiller Company: | PRESTO |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | PRESTO |
| Spiller Phone: | (914) 834-8344 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 402415 |
| Latitude: | 40.9373517 |
| Longitude: | -73.7562086 |
| DEC Memo: | 4-12-11 Spoke with Paul. Tank will be removed. They have given homeowner a list of contractors to choose from for this work. jm 09/06/11 Northeast environkmental reported that they removed the tank along with 82.14 tons of impacted soil. NFA Tg |
| Remarks: | 550gal ust |

All Materials:

| | |
|---|---|
| Site ID: | 447824 |
| Operable Unit ID: | 1198056 |
| Operable Unit: | 01 |
| Material ID: | 2194303 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

**H50** **CON EDISON** **NJ MANIFEST** **S120676415**
**SW** **MYRTLE BLVD &D CHATSWORTH AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.163 mi.**
**859 ft.** **Site 5 of 10 in cluster H**

**Relative:**
**Higher**

**Actual:**
**50 ft.**

NJ MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004835332 |
| Name: | CON EDISON |
| Address: | MYRTLE BLVD &D CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| County: | Not reported |
| Mailing Address: | IRVING PL 15TH FL NE |
| Mailing City,State,Zip: | NEW YORK, NY 10003 |
| Telephone: | Not reported |
| Emergency Telephone: | Not reported |
| Contact: | THOMAS TEELING |
| Comments: | Not reported |
| SIC Code: | Not reported |
| County: | NY119 |
| Municipal: | Not reported |
| Previous EPAID: | Not reported |
| Generator Flag: | Not reported |
| Transporter Flag: | Not reported |
| TSDF Flag: | Not reported |
| Name Change: | Not reported |
| Date Change: | Not reported |

Manifest Data:

| | |
|---|---|
| EPA ID: | NYP004835332 |
| Manifest Number: | 014454345JJK |
| Date Shipped: | 9/7/2015 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NYD006982359 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |

**CON EDISON (Continued)** **S120676415**

| | |
|---|---|
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Was Load Rejected: | Not reported |
| Reason Load Was Rejected: | Not reported |

---

**H51** **CON EDISON** **NJ MANIFEST** **S120670369**
**SW** **MYRTLE AVE & CHATSWORTH AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.163 mi.**
**859 ft.** **Site 6 of 10 in cluster H**

**Relative:**
**Higher**

**Actual:**
**50 ft.**

NJ MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004766622 |
| Name: | CON EDISON |
| Address: | MYRTLE AVE & CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| County: | Not reported |
| Mailing Address: | IRVING PL 15TH FL NE |
| Mailing City,State,Zip: | NEW YORK, NY 10003 |
| Telephone: | Not reported |
| Emergency Telephone: | Not reported |
| Contact: | THOMAS TEELING |
| Comments: | Not reported |
| SIC Code: | Not reported |
| County: | NY119 |
| Municipal: | Not reported |
| Previous EPAID: | Not reported |
| Generator Flag: | Not reported |
| Transporter Flag: | Not reported |
| TSDF Flag: | Not reported |
| Name Change: | Not reported |
| Date Change: | Not reported |

Manifest Data:

| | |
|---|---|
| EPA ID: | NYP004766622 |
| Manifest Number: | 014085125JJK |
| Date Shipped: | 4/12/2015 |
| TSDF EPA ID: | NJD002200046 |
| Transporter EPA ID: | NYD006982359 |
| Transporter 2 EPA ID: | Not reported |
| Transporter 3 EPA ID: | Not reported |
| Transporter 4 EPA ID: | Not reported |
| Transporter 5 EPA ID: | Not reported |
| Transporter 6 EPA ID: | Not reported |
| Transporter 7 EPA ID: | Not reported |
| Transporter 8 EPA ID: | Not reported |
| Transporter 9 EPA ID: | Not reported |
| Transporter 10 EPA ID: | Not reported |
| Date Trans1 Transported Waste: | Not reported |
| Date Trans2 Transported Waste: | Not reported |
| Date Trans3 Transported Waste: | Not reported |
| Date Trans4 Transported Waste: | Not reported |

**CON EDISON (Continued)** **S120670369**

| | |
|---|---|
| Date Trans5 Transported Waste: | Not reported |
| Date Trans6 Transported Waste: | Not reported |
| Date Trans7 Transported Waste: | Not reported |
| Date Trans8 Transported Waste: | Not reported |
| Date Trans9 Transported Waste: | Not reported |
| Date Trans10 Transported Waste: | Not reported |
| Date TSDF Received Waste: | Not reported |
| TSDF EPA Facility Name: | Not reported |
| QTY Units: | Not reported |
| Transporter SEQ ID: | Not reported |
| Transporter-1 Date: | Not reported |
| Waste SEQ ID: | Not reported |
| Waste Type Code 2: | Not reported |
| Waste Type Code 3: | Not reported |
| Waste Type Code 4: | Not reported |
| Waste Type Code 5: | Not reported |
| Waste Type Code 6: | Not reported |
| Date Accepted: | Not reported |
| Manifest Discrepancy Type: | Not reported |
| Data Entry Number: | Not reported |
| Was Load Rejected: | Not reported |
| Reason Load Was Rejected: | Not reported |

---

**H52** **CON EDISON** **RCRA NonGen / NLR** **1019907540**
**SW** **MYRTLE BLVD &D CHATSWORTH AVE** **NYP004835332**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.163 mi.**
**859 ft.** **Site 7 of 10 in cluster H**

**Relative:** **Higher**
**Actual:** **50 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20150907 |
| Handler Name: | | Con Edison |
| Handler Address: | | Myrtle Blvd &D Chatsworth Ave |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYP004835332 |
| Contact Name: | | THOMAS TEELING |
| Contact Address: | | Not reported |
| Contact City,State,Zip: | | Not reported |
| Contact Telephone: | | 212-460-3770 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Private |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | Ny |
| State District: | | NYSDEC R2 |
| Mailing Address: | | IRVING PL 15TH FL NE |
| Mailing City,State,Zip: | | NEW YORK, NY 10003 |
| Owner Name: | Not reported | |
| Owner Type: | | Not reported |
| Operator Name: | Not reported | |
| Operator Type: | | Not reported |

**CON EDISON (Continued)** **1019907540**

| | |
|---|---|
| Short-Term Generator Activity: | No |
| Importer Activity: | No |
| Mixed Waste Generator: | No |
| Transporter Activity: | No |
| Transfer Facility Activity: | No |
| Recycler Activity with Storage: | No |
| Small Quantity On-Site Burner Exemption: | No |
| Smelting Melting and Refining Furnace Exemption: | No |
| Underground Injection Control: | No |
| Off-Site Waste Receipt: | No |
| Universal Waste Indicator: | No |
| Universal Waste Destination Facility: | No |
| Federal Universal Waste: | No |
| Active Site State-Reg Handler: | --- |
| Federal Facility Indicator: | Not reported |
| Hazardous Secondary Material Indicator: | N |
| Sub-Part K Indicator: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20160909 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20150907 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20150907 |

**CON EDISON (Continued)** **1019907540**

Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

---

**H53** **CON EDISON** **RCRA NonGen / NLR** **1019901839**
**SW** **MYRTLE AVE & CHATSWORTH AVE** **FINDS** **NYP004766622**
**1/8-1/4** **LARCHMONT, NY 10538** **ECHO**
**0.163 mi.**
**859 ft.** **Site 8 of 10 in cluster H**

**Relative:**
**Higher**

**Actual:**
**50 ft.**

RCRA Listings:
Date Form Received by Agency: 20150412
Handler Name: Con Edison
Handler Address: Myrtle Ave & Chatsworth Ave
Handler City,State,Zip: LARCHMONT, NY 10538
EPA ID: NYP004766622
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Ny
State District: NYSDEC R2
Mailing Address: IRVING PL 15TH FL NE
Mailing City,State,Zip: NEW YORK, NY 10003
Owner Name: Not reported
Owner Type: Not reported
Operator Name: Not reported
Operator Type: Not reported

**CON EDISON (Continued)** **1019901839**

| | |
|---|---|
| Short-Term Generator Activity: | No |
| Importer Activity: | No |
| Mixed Waste Generator: | No |
| Transporter Activity: | No |
| Transfer Facility Activity: | No |
| Recycler Activity with Storage: | No |
| Small Quantity On-Site Burner Exemption: | No |
| Smelting Melting and Refining Furnace Exemption: | No |
| Underground Injection Control: | No |
| Off-Site Waste Receipt: | No |
| Universal Waste Indicator: | No |
| Universal Waste Destination Facility: | No |
| Federal Universal Waste: | No |
| Active Site State-Reg Handler: | --- |
| Federal Facility Indicator: | Not reported |
| Hazardous Secondary Material Indicator: | N |
| Sub-Part K Indicator: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20160909 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20150412 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Large Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20150412 |

**CON EDISON (Continued)** **1019901839**

Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069661976

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019901839
Registry ID: 110069661976

DFR URL:
Name: CON EDISON
Address: Myrtle Ave & Chatsworth Ave
City,State,Zip: LARCHMONT, NY 10538

---

**H54** **CON EDISON** **NY MANIFEST** **S119074367**
**SW** **MYRTLE AVE & CHATSWORTH AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.163 mi.**
**859 ft.** **Site 9 of 10 in cluster H**

**Relative:**
**Higher**

**Actual:**
**50 ft.**

NY MANIFEST:
EPA ID: NYP004766622
Country: USA
Name: Con Edison
Address: MYRTLE AVE & CHATSWORTH AVE
Address 2: Not reported
City,State,Zip: LARCHMONT, NY 10538
Zip 4: Not reported
Location Address 1: N CHATSWORTH AVE & MYRTLE BLVD
Location Address 2: TM 259

**CON EDISON (Continued)** **S119074367**

Location City,State,Zip: LARCHMONT, NY 10538
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Con Edison
Mailing Contact: Tom Teeling
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 04/12/2015
Trans1 Recv Date: 04/12/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/15/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004766622
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014085125JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: Lead
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported

**CON EDISON (Continued)** **S119074367**

| | |
|---|---|
| Quantity: | 150 |
| Units: | Pounds |
| Number of Containers: | 1 |
| Container Type: | Cargo tanks (tank trucks) |
| Handling Method: | Treat |
| Specific Gravity: | 1 |

---

**G55** **CON EDISON** **NY MANIFEST** **S117537406**
**South** **PALMER AVE & CHATSWORTH AV** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.163 mi.**
**862 ft.** **Site 9 of 15 in cluster G**

**Relative:**
**Higher**

**Actual:**
**58 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004699658 |
| Country: | USA |
| Name: | Con Edison |
| Address: | PALMER AVE & CHATSWORTH AV |
| Address 2: | TM267 |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Zip 4: | Not reported |
| Location Address 1: | PALMER AVE & CHATSWORTH AV |
| Location Address 2: | TM267 |
| Location City,State,Zip: | LARCHMONT, NY 10538 |
| Location Zip 4: | Not reported |
| Facility Status: | Not reported |
| Total Tanks: | Not reported |
| Code: | BP |

Mailing:

| | |
|---|---|
| Mailing Name: | Con Edison |
| Mailing Contact: | Con Edison |
| Mailing Address 1: | 4 IRVING PL |
| Mailing Address 2: | 15TH FL |
| Mailing City,State,Zip: | NEW YORK, NY 10003 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | Not reported |

Manifest Data:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD006982359 |
| Year: | 2018 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 11/25/2014 |
| Trans1 Recv Date: | 11/25/2014 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 11/26/2014 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004699658 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD002200046 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 012772403JJK |

**CON EDISON (Continued)** **S117537406**

| | |
|---|---|
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H110 |
| Waste Code a: | Lead |
| Waste Code b: | Not reported |
| Waste Code c: | Not reported |
| Waste Code e: | Not reported |
| Waste Code f: | Not reported |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 800 |
| Units: | Pounds |
| Number of Containers: | 1 |
| Container Type: | Cargo tanks (tank trucks) |
| Handling Method: | Treat |
| Specific Gravity: | 1 |

---

**G56** **CON EDISON MANHOLE: 263** **RCRA NonGen / NLR** **1016677341**
**South** **CHATSWORTH AVE & PALMER AVE** **FINDS** **NYP004309225**
**1/8-1/4** **LARCHMONT, NY 10538** **ECHO**
**0.163 mi.** **NY MANIFEST**
**862 ft.** **Site 10 of 15 in cluster G**

**Relative:** **Higher**

**Actual:** **58 ft.**

RCRA Listings:

| | |
|---|---|
| Date Form Received by Agency: | 20130608 |
| Handler Name: | Con Edison Manhole: 263 |
| Handler Address: | Chatsworth Ave & Palmer Ave |
| Handler City,State,Zip: | LARCHMONT, NY 10538 |
| EPA ID: | NYP004309225 |
| Contact Name: | DONALD SENNO |
| Contact Address: | Not reported |
| Contact City,State,Zip: | Not reported |
| Contact Telephone: | 914-925-6219 |
| Contact Fax: | Not reported |
| Contact Email: | Not reported |
| Contact Title: | SR SPECIALIST |
| EPA Region: | 02 |
| Land Type: | Private |
| Federal Waste Generator Description: | Not a generator, verified |
| Non-Notifier: | Not reported |
| Biennial Report Cycle: | Not reported |
| Accessibility: | Not reported |
| Active Site Indicator: | Not reported |
| State District Owner: | Ny |

**CON EDISON MANHOLE: 263 (Continued)** **1016677341**

| | | |
|---|---|---|
| State District: | | NYSDEC R2 |
| Mailing Address: | | VING PL, RM 828 |
| Mailing City,State,Zip: | | NEW YORK, NY 10003 |
| Owner Name: | Not reported | |
| Owner Type: | | Not reported |
| Operator Name: | Not reported | |
| Operator Type: | | Not reported |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| Corrective Action Priority Ranking: | | No NCAPS ranking |
| Environmental Control Indicator: | | No |
| Institutional Control Indicator: | | No |
| Human Exposure Controls Indicator: | | N/A |
| Groundwater Controls Indicator: | | N/A |
| Significant Non-Complier Universe: | | No |
| Unaddressed Significant Non-Complier Universe: | | No |
| Addressed Significant Non-Complier Universe: | | No |
| Significant Non-Complier With a Compliance Schedule Universe: | | No |
| Financial Assurance Required: | | Not reported |
| Handler Date of Last Change: | | 20140402 |
| Recognized Trader-Importer: | | No |
| Recognized Trader-Exporter: | | No |
| Importer of Spent Lead Acid Batteries: | | No |
| Exporter of Spent Lead Acid Batteries: | | No |
| Recycler Activity Without Storage: | | No |
| Manifest Broker: | | No |
| Sub-Part P Indicator: | | No |

Historic Generators:

| | | |
|---|---|---|
| Receive Date: | | 20130508 |
| Handler Name: | CON EDISON MANHOLE: 263 | |
| Federal Waste Generator Description: | | Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator |
| State District Owner: | | Ny |
| Large Quantity Handler of Universal Waste: | | No |
| Recognized Trader Importer: | | No |

**CON EDISON MANHOLE: 263 (Continued)** **1016677341**

| | |
|---|---|
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20130608 |
| Handler Name: | CON EDISON MANHOLE: 263 |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110058872171

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016677341
Registry ID: 110058872171

DFR URL:
Name: CON EDISON MANHOLE: 263
Address: Chatsworth Ave & Palmer Ave
City,State,Zip: LARCHMONT, NY 10538

**CON EDISON MANHOLE: 263 (Continued)** **1016677341**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004309225 |
| Country: | USA |
| Name: | Con Edison |
| Address: | CHATSWORTH AVE & PALMER AVE |
| Address 2: | Not reported |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Zip 4: | Not reported |
| Location Address 1: | PALMER AVE & CHATSWORTH AVE |
| Location Address 2: | Not reported |
| Location City,State,Zip: | LARCHMONT, NY 10538 |
| Location Zip 4: | Not reported |
| Facility Status: | Not reported |
| Total Tanks: | Not reported |
| Code: | BP |

Mailing:

| | |
|---|---|
| Mailing Name: | Con Edison |
| Mailing Contact: | Con Edison |
| Mailing Address 1: | 4 IRVING PLACE 15TH FLOOR |
| Mailing Address 2: | Not reported |
| Mailing City,State,Zip: | NEW YORK, NY 10003 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 2124603770 |

Manifest Data:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD006982359 |
| Year: | 2018 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 05/08/2013 |
| Trans1 Recv Date: | 05/08/2013 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 05/14/2013 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004309225 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD002200046 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 007655517JJK |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H110 |
| Waste Code a: | Lead |
| Waste Code b: | Not reported |

**CON EDISON MANHOLE: 263 (Continued)** **1016677341**

| | |
|---|---|
| Waste Code c: | Not reported |
| Waste Code e: | Not reported |
| Waste Code f: | Not reported |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 55 |
| Units: | Pounds |
| Number of Containers: | 1 |
| Container Type: | Cargo tanks (tank trucks) |
| Handling Method: | Treat |
| Specific Gravity: | 1 |

---

**H57** **CHATSWORTH GARDENS CONDO** **NY AST** **A100276647**
**WSW** **14 NORTH CHATSWORTH AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.163 mi.**
**862 ft.** **Site 10 of 10 in cluster H**

**Relative:** **Higher**

**Actual:** **50 ft.**

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | CHATSWORTH GARDENS CONDO |
| Address: | 14 NORTH CHATSWORTH AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-506788 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | Amir Zarabi |
| Owner Name: | Chatsworth Gardens Condo |
| Owner Street: | 14 North Chatsworth Avenue |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | Larchmont, NY 10538 |
| | |
| Tank Number: | 1 |
| Status: | 3. Closed - Removed |
| Date Installation: | 01/01/1928 |
| Capacity: | 5000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 07/28/2023 |
| Tank Location: | 2. Aboveground (contact w/ impervious barrier) |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 1. Epoxy liner |
| Tank External Protection: | 0. None |
| Tank Leak Detection: | 4. Groundwater Well |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 3. Aboveground/Underground Combination |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | Not reported |
| Piping Secondary Containment: | Not reported |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 2. Suction |

**CHATSWORTH GARDENS CONDO (Continued)** **A100276647**

| | |
|---|---|
| Tank Number: | 2 |
| Status: | 1. In-Service |
| Date Installation: | 01/01/1928 |
| Capacity: | 1500 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 1. Aboveground (contact w/ soil) |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 1. Epoxy liner |
| Tank External Protection: | 0. None |
| Tank Leak Detection: | 4. Groundwater Well |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 3. Aboveground/Underground Combination |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | Not reported |
| Piping Secondary Containment: | Not reported |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 3 |
| Status: | 3. Closed - Removed |
| Date Installation: | 01/01/1958 |
| Capacity: | 275 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 07/28/2023 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | Not reported |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | Not reported |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 0. None |
| Piping Leak Detection: | Not reported |
| Piping Secondary Containment: | Not reported |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 4 |
| Status: | 3. Closed - Removed |
| Date Installation: | 01/01/1958 |
| Capacity: | 275 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 07/28/2023 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |

**CHATSWORTH GARDENS CONDO (Continued)** **A100276647**

| | |
|---|---|
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | Not reported |
| Piping Location: | Not reported |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 0. None |
| Piping Leak Detection: | Not reported |
| Piping Secondary Containment: | Not reported |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 5 |
| Status: | 1. In-Service |
| Date Installation: | 11/29/2023 |
| Capacity: | 3000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | Not reported |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 1. Electronic Interstitial Monitoring |
| Tank Secondary Containment: | 2. Vault (w/ access) |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | Not reported |
| Piping Secondary Containment: | Not reported |
| Overfill Prevention: | 2. High Level Alarm |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | Not reported |

---

**K58** **NYS THRUWAY MAINTENANCE CENTER** **RCRA NonGen / NLR** **1000889946**
**SSW** **I-95 EXIT 17 OFF NEW ENGLAND** **NY0000198762**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.165 mi.**
**870 ft.** **Site 1 of 2 in cluster K**

**Relative:** **Higher**

**Actual:** **46 ft.**

RCRA Listings:

| | |
|---|---|
| Date Form Received by Agency: | 20070101 |
| Handler Name: | Nys Thruway Maintenance Center |
| Handler Address: | I-95 Exit 17 Off New England |
| Handler City,State,Zip: | LARCHMONT, NY 10538 |
| EPA ID: | NY0000198762 |
| Contact Name: | Not reported |
| Contact Address: | I-95 EXIT 17 OFF NEW ENGLAND |
| Contact City,State,Zip: | LARCHMONT, NY 10538 |
| Contact Telephone: | Not reported |
| Contact Fax: | Not reported |
| Contact Email: | Not reported |
| Contact Title: | Not reported |
| EPA Region: | 02 |
| Land Type: | Not reported |
| Federal Waste Generator Description: | Not a generator, verified |
| Non-Notifier: | Not reported |
| Biennial Report Cycle: | Not reported |

**NYS THRUWAY MAINTENANCE CENTER (Continued)** **1000889946**

| | | |
|---|---|---|
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | Ny |
| State District: | | NYSDEC R3 |
| Mailing Address: | | I-95 EXIT 17 OFF NEW ENGLAND |
| Mailing City,State,Zip: | | LARCHMONT, NY 10538 |
| Owner Name: | Nys Thruway Auth | |
| Owner Type: | | State |
| Operator Name: | Nys Thruway Auth | |
| Operator Type: | | State |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| Corrective Action Priority Ranking: | | No NCAPS ranking |
| Environmental Control Indicator: | | No |
| Institutional Control Indicator: | | No |
| Human Exposure Controls Indicator: | | N/A |
| Groundwater Controls Indicator: | | N/A |
| Significant Non-Complier Universe: | | No |
| Unaddressed Significant Non-Complier Universe: | | No |
| Addressed Significant Non-Complier Universe: | | No |
| Significant Non-Complier With a Compliance Schedule Universe: | | No |
| Financial Assurance Required: | | Not reported |
| Handler Date of Last Change: | | 20150414 |
| Recognized Trader-Importer: | | No |
| Recognized Trader-Exporter: | | No |
| Importer of Spent Lead Acid Batteries: | | No |
| Exporter of Spent Lead Acid Batteries: | | No |
| Recycler Activity Without Storage: | | No |
| Manifest Broker: | | No |
| Sub-Part P Indicator: | | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | D001 |
| Waste Description: | Ignitable Waste |

**NYS THRUWAY MAINTENANCE CENTER (Continued)** **1000889946**

Handler - Owner Operator:

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: NYS THRUWAY AUTH | |
| Legal Status: | State |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 200 SOUTHERN BLVD |
| Owner/Operator City,State,Zip: | ALBANY, NY 12209 |
| Owner/Operator Telephone: | 518-436-2700 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: NYS THRUWAY AUTH | |
| Legal Status: | State |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 200 SOUTHERN BLVD |
| Owner/Operator City,State,Zip: | ALBANY, NY 12209 |
| Owner/Operator Telephone: | 518-436-2700 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

| | |
|---|---|
| Owner/Operator Indicator: | Operator |
| Owner/Operator Name: NYS THRUWAY AUTH | |
| Legal Status: | State |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 200 SOUTHERN BLVD |
| Owner/Operator City,State,Zip: | ALBANY, NY 12209 |
| Owner/Operator Telephone: | 518-436-2700 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

Historic Generators:

| | |
|---|---|
| Receive Date: | 19990708 |
| Handler Name: | NYS THRUWAY MAINTENANCE CENTER |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20060101 |
| Handler Name: | NYS THRUWAY MAINTENANCE CENTER |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |

**NYS THRUWAY MAINTENANCE CENTER (Continued)** **1000889946**

| | |
|---|---|
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20070101 |
| Handler Name: | NYS THRUWAY MAINTENANCE CENTER |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 19940406 |
| Handler Name: | NYS THRUWAY MAINTENANCE CENTER |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

---

**G59** **HOWELL ASSOCIATES** **NY AST** **A100359836**
**SSW** **132 CHATSWORTH AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.167 mi.**
**880 ft.** **Site 11 of 15 in cluster G**

**Relative:** WESTCHESTER CO. AST:
**Higher**

| | |
|---|---|
| Name: | HOWELL ASSOCIATES |
| Address: | 132 CHATSWORTH AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-049565 |
| Site Status: | Active |

**Actual:**
**57 ft.**

**HOWELL ASSOCIATES (Continued)** **A100359836**

| | |
|---|---|
| GDS Number: | Not reported |
| Operator Name: | Luis Zelaya |
| Owner Name: | Howell Associates, c/o DeLaurentis Mgmt. |
| Owner Street: | 384 Mamaroneck Avenue |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | White Plains, NY 10605 |
| Tank Number: | 880 |
| Status: | 1. In-Service |
| Date Installation: | 10/01/1990 |
| Capacity: | 2000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | 2. Vault (w/ access) |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 6. Wrapped (Piping) |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 0. None |
| Dispenser: | 1. Submersible |

---

**G60** **SPILL NUMBER 8906916** **NY LTANKS** **S100140639**
**SSW** **132 CHATSWORTH AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.167 mi.**
**880 ft.** **Site 12 of 15 in cluster G**

**Relative:** **Higher**
**Actual:** **57 ft.**

LTANKS:

| | |
|---|---|
| Name: | ORLOFSKY APT. BLDG. |
| Address: | 132 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 8906577 / 1992-07-30 |
| Facility ID: | 8906577 |
| Site ID: | 275785 |
| Spill Date: | 1989-10-04 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C4 |
| Cleanup Ceased: | 1992-07-30 |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1989-10-04 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | 1989-10-04 |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |

**SPILL NUMBER 8906916 (Continued)** **S100140639**

| | |
|---|---|
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1989-10-11 |
| Spill Record Last Update: | 1992-07-30 |
| Spiller Name: | Not reported |
| Spiller Company: | ORLOFSKY MANAGEMENT |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 224219 |
| Latitude: | 40.9330874 |
| Longitude: | -73.7594591 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY |
| Remarks: | 2K TANK. PETROTITE EIR TODD G ON SITE FOR INITIAL TEST |

All TTF:

| | |
|---|---|
| Facility ID: | 8906577 |
| Spill Number: | 8906577 |
| Spill Tank Test: | 1536152 |
| Site ID: | 275785 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 275785 |
| Operable Unit ID: | 931594 |
| Operable Unit: | 01 |
| Material ID: | 559430 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | Not reported |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | SPILL NUMBER 8906916 |
| Address: | 132 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 8906916 / 1992-07-30 |
| Facility ID: | 8906916 |

**SPILL NUMBER 8906916 (Continued)** **S100140639**

| | |
|---|---|
| Site ID: | 275786 |
| Spill Date: | 1989-10-09 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | C4 |
| Cleanup Ceased: | 1992-07-30 |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1989-10-10 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1989-11-01 |
| Spill Record Last Update: | 2003-09-26 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 224219 |
| Latitude: | 40.9330874 |
| Longitude: | -73.7594591 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY |
| Remarks: | PETRO, 2K, TODD GHIOSAY ON SITE PIPING PROBLEM, TANK TO BE REMOVED. TANK IS BEING REMOVED TODAY 10/16/89 |

All TTF:

| | |
|---|---|
| Facility ID: | 8906916 |
| Spill Number: | 8906916 |
| Spill Tank Test: | 1536232 |
| Site ID: | 275786 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 275786 |

**SPILL NUMBER 8906916 (Continued)** **S100140639**

| | |
|---|---|
| Operable Unit ID: | 934694 |
| Operable Unit: | 01 |
| Material ID: | 443724 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**G61** **EXXON** **UST FINDER RELEASE** **1029057039**
**SSW** **124 CHATSWORTH AVE** **N/A**
**1/8-1/4** **MAMARONECK, NY 0**
**0.170 mi.**
**900 ft.** **Site 13 of 15 in cluster G**

**Relative:** **Higher**

**Actual:** **57 ft.**

UST FINDER RELEASE:

| | |
|---|---|
| Object ID: | 262689 |
| Facility ID: | NY106560 |
| Lust ID: | NY8100036 |
| Name: | EXXON |
| Address: | 124 CHATSWORTH AVE |
| City,State,Zip: | MAMARONECK, NY 0 |
| Address Match Type: | Not reported |
| Reported Date: | 1981/04/08 16:00:00+00 |
| Status: | No Further Action |
| Substance: | Not reported |
| Population within 1500ft: | 2471 |
| Domestic Wells within 1500ft: | 0 |
| Land Use: | Developed, High Intensity |
| Within SPA: | No |
| SPA PWS Facility ID: | Not reported |
| SPA Water Type: | Not reported |
| SPA Facility Type: | Not reported |
| SPA HUC12: | Not reported |
| Within WHPA: | No |
| WHPA PWS Facility ID: | Not reported |
| WHPA Water Type: | Not reported |
| WHPA Facility Type: | Not reported |
| WHPA HUC12: | Not reported |
| Within 100yr Floodplain: | No |
| Tribe: | Not reported |
| EPA Region: | 2 |
| NFA Letter 1: | Not reported |
| NFA Letter 2: | Not reported |
| NFA Letter 3: | Not reported |
| NFA Letter 4: | Not reported |
| Closed With Residual Contaminate: | Not reported |
| Coordinate Source: | State |
| X Coord: | -73.75926 |
| Y Coord: | 40.93278 |
| Latitude: | 40.93278 |
| Longitude: | -73.7592599999999 |

**G62** **THE BANK OF NEW YORK** **NY UST** **U004441910**
**SSW** **124 CHATSWORTH AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.170 mi.**
**900 ft.** **Site 14 of 15 in cluster G**

**Relative:** WESTCHESTER CO. UST:
**Higher**

| | |
|---|---|
| Name: | THE BANK OF NEW YORK |
| Address: | 124 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-078948 / Unregulated: <1101 gal. PBS |
| Operator Name: | The Bank Of New York |
| Owner Name: | General Electric Pension Trust |
| Owner Street: | 112 Prospect St Box 7900 |
| Owner Address2: | Not reported |
| Owner City: | Stamford |
| Owner State: | CT |
| Owner Zipcode: | 06904 |
| GDS Number: | Not reported |
| Tank Number: | 1 |
| Status: | 3. Closed - Removed |
| Capacity: | 2000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | Not reported |
| Date Perm Closure: | 12/01/1994 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | Not reported |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 2. Suction |

**Actual:**
**57 ft.**

---

**G63** **BANK OF NEW YORK** **NY LTANKS** **S100166446**
**SSW** **124 CHATSWORTH AVE.** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.170 mi.**
**900 ft.** **Site 15 of 15 in cluster G**

**Relative:** LTANKS:
**Higher**

| | |
|---|---|
| Name: | BANK OF NEW YORK |
| Address: | 124 CHATSWORTH AVE. |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9011938 / 1993-02-23 |
| Facility ID: | 9011938 |
| Site ID: | 276370 |
| Spill Date: | 1991-02-14 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | B3 |
| Cleanup Ceased: | 1993-02-23 |
| SWIS: | 6000 |

**Actual:**
**57 ft.**

**BANK OF NEW YORK (Continued)** **S100166446**

| | |
|---|---|
| Investigator: | WXWADSWO |
| Referred To: | Not reported |
| Reported to Dept: | 1991-02-14 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1991-02-19 |
| Spill Record Last Update: | 2024-07-03 |
| Spiller Name: | Not reported |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 224685 |
| Latitude: | 40.9329027 |
| Longitude: | -73.7590349 |
| DEC Memo: | 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST. |
| Remarks: | TANK IS FIVE YEARS OLD SUSPECT AIR POCKET OIL SITE ASSESMENT DONE AT SERVICE STATION BEHIND BANK OIL RECOVERY 30 FT.AWAY WILL EIR WCHD NOTIFIED SYSTEM-PETRO -.124 |

All TTF:

| | |
|---|---|
| Facility ID: | 9011938 |
| Spill Number: | 9011938 |
| Spill Tank Test: | 1538257 |
| Site ID: | 276370 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 276370 |
| Operable Unit ID: | 948945 |
| Operable Unit: | 01 |
| Material ID: | 428447 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |

**BANK OF NEW YORK (Continued)** **S100166446**

| | |
|---|---|
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | Not reported |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**L64** **CHATSWORTH CLEANERS** **RCRA-VSQG 1000890429**
**South** **120 CHATSWORTH AVE** **US AIRS NY0000363101**
**1/8-1/4** **LARCHMONT, NY 10538** **FINDS**
**0.173 mi.** **NY DRYCLEANERS**
**916 ft.** **Site 1 of 8 in cluster L** **NY MANIFEST**

**Relative:** **Higher**
**Actual:** **58 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20070101 |
| Handler Name: | | Chatsworth Cleaners |
| Handler Address: | | Chatsworth Ave |
| Handler City,State,Zip: | | LARCHMONT, NY 10538-2901 |
| EPA ID: | | NY0000363101 |
| Contact Name: | | JIMMY KIM |
| Contact Address: | | CHATSWORTH AVE |
| Contact City,State,Zip: | | LARCHMONT, NY 10538-2901 |
| Contact Telephone: | | 914-834-7203 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Conditionally Exempt Small Quantity Generator |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Handler Activities |
| State District Owner: | | Ny |
| State District: | | NYSDEC R3 |
| Mailing Address: | | CHATSWORTH AVE |
| Mailing City,State,Zip: | | LARCHMONT, NY 10538-2901 |
| Owner Name: | Jimmy Kim | |
| Owner Type: | | Private |
| Operator Name: | Jimmy Kim | |
| Operator Type: | | Private |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |

**CHATSWORTH CLEANERS (Continued)** **1000890429**

| | |
|---|---|
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20150414 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | D000 |
| Waste Description: | Not Defined |
| Waste Code: | D039 |
| Waste Description: | Tetrachloroethylene |
| Waste Code: | F002 |
| Waste Description: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |

Handler - Owner Operator:

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: JIMMY KIM | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 120 CHATSWORTH AVE |
| Owner/Operator City,State,Zip: | LARCHMONT, NY 10538 |
| Owner/Operator Telephone: | 914-834-7203 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

**CHATSWORTH CLEANERS (Continued)** **1000890429**

Owner/Operator Indicator: Owner
Owner/Operator Name: JIMMY KIM
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 120 CHATSWORTH AVE
Owner/Operator City,State,Zip: LARCHMONT, NY 10538
Owner/Operator Telephone: 914-834-7203
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: JIMMY KIM
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 120 CHATSWORTH AVE
Owner/Operator City,State,Zip: LARCHMONT, NY 10538
Owner/Operator Telephone: 914-834-7203
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: CHATSWORTH CLEANERS
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CHATSWORTH CLEANERS
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19981218
Handler Name: CHATSWORTH CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny

**CHATSWORTH CLEANERS (Continued)** **1000890429**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20170516
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION

**CHATSWORTH CLEANERS (Continued)** **1000890429**

| | |
|---|---|
| Evaluation Responsible Person Identifier: | NYMOC |
| Evaluation Responsible Sub-Organization: | R3 |
| Actual Return to Compliance Date: | Not reported |
| Scheduled Compliance Date: | Not reported |
| Date of Request: | Not reported |
| Date Response Received: | Not reported |
| Request Agency: | Not reported |
| Former Citation: | Not reported |

US AIRS MINOR:

| | |
|---|---|
| Envid: | 1000890429 |
| Region Code: | 02 |
| Programmatic ID: | AIR NY0000003553200305 |
| Facility Registry ID: | 110004316204 |
| D and B Number: | Not reported |
| Primary SIC Code: | 7216 |
| NAICS Code: | 812320 |
| Default Air Classification Code: | MIN |
| Facility Type of Ownership Code: | POF |
| Air CMS Category Code: | Not reported |
| HPV Status: | Not reported |

US AIRS MINOR:

| | |
|---|---|
| Region Code: | 02 |
| Programmatic ID: | AIR NY0000003553200305 |
| Facility Registry ID: | 110004316204 |
| Air Operating Status Code: | OPR |
| Default Air Classification Code: | MIN |
| Air Program: | State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards |
| Activity Date: | 2014-08-26 00:00:00 |
| Activity Status Date: | Not reported |
| Activity Group: | Compliance Monitoring |
| Activity Type: | Inspection/Evaluation |
| Activity Status: | Not reported |

FINDS:

Registry ID: 110004316204

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the

**CHATSWORTH CLEANERS (Continued)** **1000890429**

Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

DRYCLEANERS:

| | |
|---|---|
| Name: | NEW CHATSWORTH AVE |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347204 |
| Region: | Not reported |
| Registration Effective Date: | 09/08/2025 |
| Inspection Date: | 07/10/2002 |
| Install Date: | Not reported |
| Expiration Date: | 09/07/2035 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | NEW CHATSWORTH AVE |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347204 |
| Region: | Not reported |
| Registration Effective Date: | 09/08/2025 |
| Inspection Date: | 07/12/2001 |
| Install Date: | Not reported |
| Expiration Date: | 09/07/2035 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | NEW CHATSWORTH AVE |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347204 |
| Region: | Not reported |
| Registration Effective Date: | 09/08/2025 |
| Inspection Date: | 07/02/2003 |
| Install Date: | Not reported |
| Expiration Date: | 09/07/2035 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | NEW CHATSWORTH AVE |

**CHATSWORTH CLEANERS (Continued)** **1000890429**

Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 09/08/2025
Inspection Date: 06/30/2004
Install Date: Not reported
Expiration Date: 09/07/2035
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 09/08/2025
Inspection Date: 06/23/2005
Install Date: Not reported
Expiration Date: 09/07/2035
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 09/08/2025
Inspection Date: 06/21/2006
Install Date: Not reported
Expiration Date: 09/07/2035
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 09/08/2025
Inspection Date: 06/20/2007
Install Date: Not reported
Expiration Date: 09/07/2035

**CHATSWORTH CLEANERS (Continued)** **1000890429**

Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 09/08/2025
Inspection Date: 06/19/2008
Install Date: Not reported
Expiration Date: 09/07/2035
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 09/08/2025
Inspection Date: 06/17/2009
Install Date: Not reported
Expiration Date: 09/07/2035
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 09/08/2025
Inspection Date: 06/20/2012
Install Date: Not reported
Expiration Date: 09/07/2035
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901

**CHATSWORTH CLEANERS (Continued)** **1000890429**

| | |
|---|---|
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347204 |
| Region: | Not reported |
| Registration Effective Date: | 09/08/2025 |
| Inspection Date: | 06/16/2010 |
| Install Date: | Not reported |
| Expiration Date: | 09/07/2035 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | NEW CHATSWORTH AVE |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347204 |
| Region: | Not reported |
| Registration Effective Date: | 09/08/2025 |
| Inspection Date: | 06/20/2011 |
| Install Date: | Not reported |
| Expiration Date: | 09/07/2035 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | NEW CHATSWORTH AVE |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347204 |
| Region: | Not reported |
| Registration Effective Date: | 09/08/2025 |
| Inspection Date: | 06/25/2014 |
| Install Date: | Not reported |
| Expiration Date: | 09/07/2035 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | NEW CHATSWORTH AVE |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347204 |
| Region: | Not reported |
| Registration Effective Date: | 09/08/2025 |
| Inspection Date: | 06/28/2013 |
| Install Date: | Not reported |
| Expiration Date: | 09/07/2035 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |

**CHATSWORTH CLEANERS (Continued)** **1000890429**

Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 09/08/2025
Inspection Date: 06/24/2015
Install Date: Not reported
Expiration Date: 09/07/2035
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 09/08/2025
Inspection Date: 06/22/2016
Install Date: Not reported
Expiration Date: 09/07/2035
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 03/02/2000
Inspection Date: 07/10/2002
Install Date: Not reported
Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204

**CHATSWORTH CLEANERS (Continued)** **1000890429**

Region: Not reported
Registration Effective Date: 03/02/2000
Inspection Date: 07/12/2001
Install Date: Not reported
Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 03/02/2000
Inspection Date: 07/02/2003
Install Date: Not reported
Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 03/02/2000
Inspection Date: 06/30/2004
Install Date: Not reported
Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 03/02/2000
Inspection Date: 06/23/2005
Install Date: Not reported
Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler

**CHATSWORTH CLEANERS (Continued)** **1000890429**

| | |
|---|---|
| Current Business: | Not reported |
| Name: | NEW CHATSWORTH AVE |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347204 |
| Region: | Not reported |
| Registration Effective Date: | 03/02/2000 |
| Inspection Date: | 06/21/2006 |
| Install Date: | Not reported |
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |
| Name: | NEW CHATSWORTH AVE |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347204 |
| Region: | Not reported |
| Registration Effective Date: | 03/02/2000 |
| Inspection Date: | 06/20/2007 |
| Install Date: | Not reported |
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |
| Name: | NEW CHATSWORTH AVE |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347204 |
| Region: | Not reported |
| Registration Effective Date: | 03/02/2000 |
| Inspection Date: | 06/19/2008 |
| Install Date: | Not reported |
| Expiration Date: | 07/05/2017 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |
| Name: | NEW CHATSWORTH AVE |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347204 |
| Region: | Not reported |
| Registration Effective Date: | 03/02/2000 |

**CHATSWORTH CLEANERS (Continued)** **1000890429**

Inspection Date: 06/17/2009
Install Date: Not reported
Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 03/02/2000
Inspection Date: 06/20/2012
Install Date: Not reported
Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 03/02/2000
Inspection Date: 06/16/2010
Install Date: Not reported
Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 03/02/2000
Inspection Date: 06/20/2011
Install Date: Not reported
Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

**CHATSWORTH CLEANERS (Continued)** **1000890429**

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 03/02/2000
Inspection Date: 06/25/2014
Install Date: Not reported
Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 03/02/2000
Inspection Date: 06/28/2013
Install Date: Not reported
Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 03/02/2000
Inspection Date: 06/24/2015
Install Date: Not reported
Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 03/02/2000
Inspection Date: 06/22/2016
Install Date: Not reported

**CHATSWORTH CLEANERS (Continued)** **1000890429**

Expiration Date: 07/05/2017
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 07/05/2017
Inspection Date: 07/10/2002
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 07/05/2017
Inspection Date: 06/22/2016
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 07/05/2017
Inspection Date: 06/24/2015
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE

**CHATSWORTH CLEANERS (Continued)** **1000890429**

City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 07/05/2017
Inspection Date: 06/28/2013
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 07/05/2017
Inspection Date: 06/25/2014
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 07/05/2017
Inspection Date: 06/20/2011
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 07/05/2017
Inspection Date: 06/16/2010
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported

**CHATSWORTH CLEANERS (Continued)** **1000890429**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 07/05/2017
Inspection Date: 06/20/2012
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 07/05/2017
Inspection Date: 06/17/2009
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 07/05/2017
Inspection Date: 06/19/2008
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305

**CHATSWORTH CLEANERS (Continued)** **1000890429**

Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 07/05/2017
Inspection Date: 06/20/2007
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 07/05/2017
Inspection Date: 06/21/2006
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 07/05/2017
Inspection Date: 06/23/2005
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler
Current Business: Not reported

Name: NEW CHATSWORTH AVE
Address: 120 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY 10538 2901
Facility ID: 3-5532-00305
Phone Number: 9148347204
Region: Not reported
Registration Effective Date: 07/05/2017
Inspection Date: 07/12/2001
Install Date: Not reported
Expiration Date: 07/04/2027
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported

**CHATSWORTH CLEANERS (Continued)** **1000890429**

| | |
|---|---|
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | NEW CHATSWORTH AVE |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347204 |
| Region: | Not reported |
| Registration Effective Date: | 07/05/2017 |
| Inspection Date: | 07/02/2003 |
| Install Date: | Not reported |
| Expiration Date: | 07/04/2027 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

| | |
|---|---|
| Name: | NEW CHATSWORTH AVE |
| Address: | 120 CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY 10538 2901 |
| Facility ID: | 3-5532-00305 |
| Phone Number: | 9148347204 |
| Region: | Not reported |
| Registration Effective Date: | 07/05/2017 |
| Inspection Date: | 06/30/2004 |
| Install Date: | Not reported |
| Expiration Date: | 07/04/2027 |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Not reported |
| Alternate Solvent: | SolvonK4; CAS 2568-90-3, dibutoxymethane, Kreussler |
| Current Business: | Not reported |

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NY0000363101 |
| Country: | USA |
| Name: | Chatsworth Clnrs |
| Address: | 120 CHATSWORTH AVE |
| Address 2: | Not reported |
| City,State,Zip: | LARCHMONT, NY 10538-2901 |
| Zip 4: | Not reported |
| Location Address 1: | 120 CHATSWORTH AVE |
| Location Address 2: | Not reported |
| Location City,State,Zip: | LARCHMONT, NY 10538 |
| Location Zip 4: | Not reported |
| Facility Status: | Not reported |
| Total Tanks: | Not reported |
| Code: | BP |

Mailing:

| | |
|---|---|
| Mailing Name: | Chatsworth Clnrs |
| Mailing Contact: | Young Kim |
| Mailing Address 1: | 120 CHATSWORTH AVE |
| Mailing Address 2: | Not reported |
| Mailing City,State,Zip: | LARCHMONT, NY 10538 |

**CHATSWORTH CLEANERS (Continued)** **1000890429**

Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9148347203

Manifest Data:
Document ID: NYC5601352
Manifest Status: Not reported
Trans1 State ID: NY30747AL
Year: 1999
Trans2 State ID: NJT913LY
Generator Ship Date: 04/28/1999
Trans1 Recv Date: 04/28/1999
Trans2 Recv Date: 04/29/1999
TSD Site Recv Date: 05/04/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NY0000363101
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: SCD987574647
TSDF ID 1: OHD980587364
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00390
Units: Pounds
Number of Containers: 002
Container Type: Fiberboard or plastic drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYC6280198
Manifest Status: Not reported
Trans1 State ID: NYCR2436

**CHATSWORTH CLEANERS (Continued)** **1000890429**

| | |
|---|---|
| Year: | 2000 |
| Trans2 State ID: | TNT218034 |
| Generator Ship Date: | 11/28/2000 |
| Trans1 Recv Date: | 11/28/2000 |
| Trans2 Recv Date: | 11/30/2000 |
| TSD Site Recv Date: | 12/04/2000 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000363101 |
| Trans1 EPA ID: | SCR000075150 |
| Trans2 EPA ID: | SCR000074591 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00195 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC6437114 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR2436 |
| Year: | 2001 |
| Trans2 State ID: | 503217083 |
| Generator Ship Date: | 10/20/2001 |
| Trans1 Recv Date: | 10/20/2001 |
| Trans2 Recv Date: | 10/26/2001 |
| TSD Site Recv Date: | 10/31/2001 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |

**CHATSWORTH CLEANERS (Continued)** **1000890429**

| | |
|---|---|
| Generator EPA ID: | NY0000363101 |
| Trans1 EPA ID: | SCR000075150 |
| Trans2 EPA ID: | NJD071629976 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00195 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD000564906 |
| Year: | 2018 |
| Trans2 State ID: | MIK814262374 |
| Generator Ship Date: | 06/28/2008 |
| Trans1 Recv Date: | 06/28/2008 |
| Trans2 Recv Date: | 07/01/2008 |
| TSD Site Recv Date: | 07/01/2008 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000363101 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | CDX107000000 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 003371482JJK |
| Import Indicator: | N |
| Export Indicator: | Y |

**CHATSWORTH CLEANERS (Continued)** **1000890429**

| | |
|---|---|
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H020 |
| Waste Code a: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code b: | Tetrachloroethylene |
| Waste Code c: | Not reported |
| Waste Code e: | Not reported |
| Waste Code f: | Not reported |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 260 |
| Units: | Pounds |
| Number of Containers: | 2 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Recycle |
| Specific Gravity: | 1 |
| | |
| Document ID: | CTF0642088 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR2436 |
| Year: | 1997 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 12/01/1997 |
| Trans1 Recv Date: | 12/01/1997 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/04/1997 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000363101 |
| Trans1 EPA ID: | ILD984908202 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | CTD001156009 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |

**CHATSWORTH CLEANERS (Continued)** **1000890429**

| | |
|---|---|
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00195 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

| | |
|---|---|
| Document ID: | NYC6631187 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYDW9495 |
| Year: | 2002 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 02/13/2002 |
| Trans1 Recv Date: | 02/13/2002 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 02/20/2002 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000363101 |
| Trans1 EPA ID: | SCR000075150 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, |

**CHATSWORTH CLEANERS (Continued)** **1000890429**

Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00390
Units: Pounds
Number of Containers: 002
Container Type: Fiberboard or plastic drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: TXR000050930
Year: 2018
Trans2 State ID: NJD071629976
Generator Ship Date: 02/15/2007
Trans1 Recv Date: 02/15/2007
Trans2 Recv Date: 02/20/2007
TSD Site Recv Date: 02/21/2007
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NY0000363101
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: OHD980587364
TSDF ID 2: Not reported
Manifest Tracking Number: 000377561SKS
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H020
Waste Code a: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

**CHATSWORTH CLEANERS (Continued)** **1000890429**

| | |
|---|---|
| Waste Code b: | Chromium |
| Waste Code c: | Tetrachloroethylene |
| Waste Code e: | Trichlorethylene |
| Waste Code f: | Not reported |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 300 |
| Units: | Pounds |
| Number of Containers: | 2 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Recycle |
| Specific Gravity: | 1 |
| | |
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | TXR000050930 |
| Year: | 2018 |
| Trans2 State ID: | MOD095038998 |
| Generator Ship Date: | 08/31/2006 |
| Trans1 Recv Date: | 08/31/2006 |
| Trans2 Recv Date: | 09/12/2006 |
| TSD Site Recv Date: | 09/13/2006 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000363101 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | NYC7849440 |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code a: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code b: | Not reported |
| Waste Code c: | Not reported |

**CHATSWORTH CLEANERS (Continued)** **1000890429**

| | |
|---|---|
| Waste Code e: | Not reported |
| Waste Code f: | Not reported |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 300 |
| Units: | Pounds |
| Number of Containers: | 2 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 1 |
| | |
| Document ID: | NYC7009896 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR3164 |
| Year: | 2003 |
| Trans2 State ID: | NJ044 |
| Generator Ship Date: | 04/02/2003 |
| Trans1 Recv Date: | 04/02/2003 |
| Trans2 Recv Date: | 04/09/2003 |
| TSD Site Recv Date: | 04/10/2003 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000363101 |
| Trans1 EPA ID: | TXR000050930 |
| Trans2 EPA ID: | NJD071629976 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |

**CHATSWORTH CLEANERS (Continued)** **1000890429**

| | |
|---|---|
| Waste Code 6: | Not reported |
| Quantity: | 00150 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC7000536 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR3164 |
| Year: | 2003 |
| Trans2 State ID: | T854MWNJ |
| Generator Ship Date: | 01/10/2003 |
| Trans1 Recv Date: | 01/10/2003 |
| Trans2 Recv Date: | 01/15/2003 |
| TSD Site Recv Date: | 01/16/2003 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000363101 |
| Trans1 EPA ID: | TXR000050930 |
| Trans2 EPA ID: | NJD071629976 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00150 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

**CHATSWORTH CLEANERS (Continued)** **1000890429**

| | |
|---|---|
| Document ID: | NYC7082111 |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYCR3164 |
| Year: | 2003 |
| Trans2 State ID: | T854MWNJ |
| Generator Ship Date: | 06/10/2003 |
| Trans1 Recv Date: | 06/10/2003 |
| Trans2 Recv Date: | 06/18/2003 |
| TSD Site Recv Date: | 06/19/2003 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NY0000363101 |
| Trans1 EPA ID: | TXR000050930 |
| Trans2 EPA ID: | NJD071629976 |
| TSDF ID 1: | OHD980587364 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00150 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

Click this hyperlink while viewing on your computer to access
54 additional NY MANIFEST: record(s) in the EDR Site Report.

**J65** **MOBIL OIL CORP SS D3M** **RCRA-LQG** **1000553397**
**South** **107 CHATSWORTH AVE** **FINDS** **NYD986958171**
**1/8-1/4** **LARCHMONT, NY 10538** **ECHO**
**0.177 mi.** **NY MANIFEST**
**933 ft.** **Site 3 of 4 in cluster J**

**Relative:** **Higher**
**Actual:** **57 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20070101 |
| Handler Name: | | Mobil Oil Corp Ss D3m |
| Handler Address: | | Chatsworth Ave |
| Handler City,State,Zip: | | LARCHMONT, NY 10538-2923 |
| EPA ID: | | NYD986958171 |
| Contact Name: | | Not reported |
| Contact Address: | | GALLOWS RD - MKTG ENVIRON |
| Contact City,State,Zip: | | FAIRFAX, NY 22037 |
| Contact Telephone: | | Not reported |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Large Quantity Generator |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Handler Activities |
| State District Owner: | | Ny |
| State District: | | NYSDEC R3 |
| Mailing Address: | | GALLOWS RD - MKTG ENVIRON |
| Mailing City,State,Zip: | | FAIRFAX, NY 22037 |
| Owner Name: | Mobil Oil Corp | |
| Owner Type: | | Private |
| Operator Name: | Mobil Oil Corp | |
| Operator Type: | | Private |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| Corrective Action Priority Ranking: | | No NCAPS ranking |
| Environmental Control Indicator: | | No |
| Institutional Control Indicator: | | No |

**MOBIL OIL CORP SS D3M (Continued)** **1000553397**

| | |
|---|---|
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20150414 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | D000 |
| Waste Description: | Not Defined |
| Waste Code: | D001 |
| Waste Description: | Ignitable Waste |
| Waste Code: | D008 |
| Waste Description: | Lead |

Handler - Owner Operator:

| | |
|---|---|
| Owner/Operator Indicator: | Operator |
| Owner/Operator Name: MOBIL OIL CORP | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 3225 GALLOWS RD |
| Owner/Operator City,State,Zip: | FAIRFAX, VA 22037 |
| Owner/Operator Telephone: | 703-849-3330 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: MOBIL OIL CORP | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 3225 GALLOWS RD |
| Owner/Operator City,State,Zip: | FAIRFAX, VA 22037 |
| Owner/Operator Telephone: | 703-849-3330 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: MOBIL OIL CORP | |
| Legal Status: | Private |
| Date Became Current: | Not reported |

**MOBIL OIL CORP SS D3M (Continued)** **1000553397**

| | |
|---|---|
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 3225 GALLOWS RD |
| Owner/Operator City,State,Zip: | FAIRFAX, VA 22037 |
| Owner/Operator Telephone: | 703-849-3330 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

Historic Generators:

| | |
|---|---|
| Receive Date: | 19990708 |
| Handler Name: MOBIL OIL CORP SS D3M | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20060101 |
| Handler Name: MOBIL OIL CORP SS D3M | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20070101 |
| Handler Name: MOBIL OIL CORP SS D3M | |
| Federal Waste Generator Description: | Large Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 19910410 |
| Handler Name: MOBIL OIL CORP SS D3M | |
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |

**MOBIL OIL CORP SS D3M (Continued)** **1000553397**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110019560606

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
Registry ID: 110004469708

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000553397
Registry ID: 110004469708

DFR URL:
Name: MOBIL OIL CORP SS D3M
Address: 107 Chatsworth Ave
City,State,Zip: LARCHMONT, NY 10538

NY MANIFEST:
EPA ID: NYD986958171
Country: USA
Name: Mobil Oil Corp Ss D3m - Former Dom'S Auto Care Center
Address: 107 CHATSWORTH AVE
Address 2: Not reported
City,State,Zip: LARCHMONT, NY 10538-2923
Zip 4: Not reported

**MOBIL OIL CORP SS D3M (Continued)** **1000553397**

Location Address 1: 107 CHATSWORTH AVE
Location Address 2: Not reported
Location City,State,Zip: LARCHMONT, NY 10538
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Mobil Oil Corp Ss D3m - Former Dom'S Auto Care Center
Mailing Contact: Mobil Oil Corp Ss D3m - Former Dom'S Auto Care Center
Mailing Address 1: 107 CHATSWORTH AVE
Mailing Address 2: Not reported
Mailing City,State,Zip: LARCHMONT, NY 10538
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9326131660

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD986607380
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 12/18/2006
Trans1 Recv Date: 12/18/2006
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/20/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986958171
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 000307005FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H061
Waste Code a: Ignitable Waste
Waste Code b: Benzene
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported

**MOBIL OIL CORP SS D3M (Continued)** **1000553397**

| | |
|---|---|
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 330 |
| Units: | Gallons (liquids only) |
| Number of Containers: | 6 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 1 |
| | |
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD986607380 |
| Year: | 2018 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 12/18/2006 |
| Trans1 Recv Date: | 12/18/2006 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/20/2006 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986958171 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD002200046 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 000307005FLE |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H061 |
| Waste Code a: | Ignitable Waste |
| Waste Code b: | The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code c: | Not reported |
| Waste Code e: | Not reported |
| Waste Code f: | Not reported |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |

**MOBIL OIL CORP SS D3M (Continued)** **1000553397**

| | |
|---|---|
| Waste Code 6: | Not reported |
| Quantity: | 55 |
| Units: | Gallons (liquids only) |
| Number of Containers: | 1 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 1 |
| | |
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD986607380 |
| Year: | 2018 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 12/18/2006 |
| Trans1 Recv Date: | 12/18/2006 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/20/2006 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986958171 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD002200046 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 000307005FLE |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H141 |
| Waste Code a: | Ignitable Waste |
| Waste Code b: | Corrosive Waste |
| Waste Code c: | Not reported |
| Waste Code e: | Not reported |
| Waste Code f: | Not reported |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 55 |
| Units: | Gallons (liquids only) |
| Number of Containers: | 1 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 1 |
| | |
| Document ID: | Not reported |
| Manifest Status: | Not reported |

**MOBIL OIL CORP SS D3M (Continued)** **1000553397**

| | |
|---|---|
| Trans1 State ID: | NJD054126164 |
| Year: | 2018 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 11/30/2006 |
| Trans1 Recv Date: | 11/30/2006 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 11/30/2006 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD986958171 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD002200046 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 000307003FLE |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H141 |
| Waste Code a: | Ignitable Waste |
| Waste Code b: | Benzene |
| Waste Code c: | Not reported |
| Waste Code e: | Not reported |
| Waste Code f: | Not reported |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 3711 |
| Units: | Gallons (liquids only) |
| Number of Containers: | 1 |
| Container Type: | Cargo tanks (tank trucks) |
| Handling Method: | Burn |
| Specific Gravity: | 1 |

---

**J66** **DOM'S CAR CARE CENTER, INC.** **NY UST** **U004369955**
**South** **107 CHATSWORTH AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.177 mi.**
**933 ft.** **Site 4 of 4 in cluster J**

**Relative:** WESTCHESTER CO. UST:
**Higher**

| | |
|---|---|
| Name: | DOM'S CAR CARE CENTER, INC. |
| Address: | 107 CHATSWORTH AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-048852 / Unregulated: <1101 gal. PBS |
| Operator Name: | Nicholas J. Ianello |

**Actual:**
**57 ft.**

**DOM'S CAR CARE CENTER, INC. (Continued)** **U004369955**

| | |
|---|---|
| Owner Name: | Nicholas J. Ianello |
| Owner Street: | 1510 Henry avenue |
| Owner Address2: | Not reported |
| Owner City: | Mamaroneck |
| Owner State: | NY |
| Owner Zipcode: | 10543 |
| GDS Number: | Not reported |

| | |
|---|---|
| Tank Number: | 1 |
| Status: | 3. Closed - Removed |
| Capacity: | 4000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 5. In-Tank System (auto tank gauge) |
| Date Installation: | 12/01/1982 |
| Date Perm Closure: | 11/28/2006 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 6. Fiberglass reinforced plastic (FRP) |
| Tank Internal Protection: | 3. Fiberglass liner (FRP) |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 2. Underground/on ground |
| Piping Type: | Not reported |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 1. Float Vent Valve |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 1. Submersible |

| | |
|---|---|
| Tank Number: | 2 |
| Status: | 3. Closed - Removed |
| Capacity: | 4000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 5. In-Tank System (auto tank gauge) |
| Date Installation: | 12/01/1982 |
| Date Perm Closure: | 11/28/2006 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 6. Fiberglass reinforced plastic (FRP) |
| Tank Internal Protection: | 3. Fiberglass liner (FRP) |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 2. Underground/on ground |
| Piping Type: | Not reported |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 1. Float Vent Valve |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 1. Submersible |

| | |
|---|---|
| Tank Number: | 3 |
| Status: | 3. Closed - Removed |
| Capacity: | 4000 |
| Product Stored: | 0009. Gasoline |
| Product Stored Percent: | Not reported |

**DOM'S CAR CARE CENTER, INC. (Continued)** **U004369955**

| | |
|---|---|
| Tank Leak Detection: | 5. In-Tank System (auto tank gauge) |
| Date Installation: | 12/01/1982 |
| Date Perm Closure: | 11/28/2006 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 6. Fiberglass reinforced plastic (FRP) |
| Tank Internal Protection: | 3. Fiberglass liner (FRP) |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 2. Underground/on ground |
| Piping Type: | Not reported |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 1. Float Vent Valve |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 1. Submersible |

| | |
|---|---|
| Tank Number: | 4 |
| Status: | 3. Closed - Removed |
| Capacity: | 1000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 12/01/1982 |
| Date Perm Closure: | 11/28/2006 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 6. Fiberglass reinforced plastic (FRP) |
| Tank Internal Protection: | 3. Fiberglass liner (FRP) |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 2. Underground/on ground |
| Piping Type: | Not reported |
| Piping External Protection: | 0. None |
| Overfill Prevention: | Not reported |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 0. None |

| | |
|---|---|
| Tank Number: | 5 |
| Status: | 3. Closed - Removed |
| Capacity: | 550 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 12/01/1982 |
| Date Perm Closure: | 11/28/2006 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 6. Fiberglass reinforced plastic (FRP) |
| Tank Internal Protection: | 3. Fiberglass liner (FRP) |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 2. Underground/on ground |
| Piping Type: | Not reported |
| Piping External Protection: | 0. None |
| Overfill Prevention: | Not reported |
| Piping Secondary Containment: | Not reported |

**DOM'S CAR CARE CENTER, INC. (Continued)** **U004369955**

| | |
|---|---|
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 0. None |
| Tank Number: | found |
| Status: | 3. Closed - Removed |
| Capacity: | 550 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | Not reported |
| Date Perm Closure: | 01/18/2007 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | Not reported |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 0. No Pippping |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 0. None |

---

**L67** **CON EDISON - ELECTRIC** **E MANIFEST** **1031951813**
**South** **1906 PALMER AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.180 mi.**
**948 ft.** **Site 2 of 8 in cluster L**

**Relative:** **Higher**
**Actual:** **59 ft.**

E MANIFEST:

| | |
|---|---|
| Manifest Tracking Number: | 016272641FLE |
| Last Updated Date: | 20211130 |
| Shipped Date: | 20211116 |
| Received Date: | 20211117 |
| Manifest Status: | Signed |
| Submission Type: | DataImage5Copy |
| Origin Type: | Service |
| Generator EPA ID: | NYR000114579 |
| Generator Name: | Con Edison - Electric |
| Generator Location Street Number: | Not reported |
| Generator Location Street 1: | 1906 PALMER AVE |
| Generator Location Street 2: | Not reported |
| Generator Location City: | LARCHMONT |
| Generator Location State: | NY |
| Generator Location Zip: | 10538 |
| Generator Mail Street Number: | Not reported |
| Generator Mail Street 1: | 116 Skyline Drive |
| Generator Mail Street 2: | Not reported |
| Generator Mail City: | South Plainfield |
| Generator Mail Zip: | 10462 |
| Generator Mail State: | NJ |
| Generator Contact Company Name: | Not reported |
| Designated Facility EPA ID: | NJD991291105 |
| Designated Facility Name: | Clean Earth Of North Jersey |
| Designated Facility Mail Street Number: | 105 |
| Designated Facility Mail Street 1: | Not reported |

**CON EDISON - ELECTRIC (Continued)** **1031951813**

Designated Facility Mail Street 2: JACOBUS AVE
Designated Facility Mail City: KEARNY
Designated Facility Mail Zip: 07032
Designated Facility Mail State: NJ
Designated Facility Location Street Number: 105
Designated Facility Location Street 1: JACOBUS AVE
Designated Facility Location Street 2: Not reported
Designated Facility Location City: KEARNY
Designated Facility Location Zip: 07032
Designated Facility Location State: NJ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 016272641FLE
Transporter Line Number: 1
Transporter EPA ID: MAD039322250
Transporter Name: Clean Harbors Environmental Services Inc

Waste Line:
Manifest Tracking Number: 016272641FLE
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: NA3082
U.S. DOT Description: Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: TT
Container Type Description: Cargo tanks (tank trucks)
Waste Quantity: 800
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.4
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.4
Waste Quantity, in Kilograms: 362.812
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 362.812
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D008

**CON EDISON - ELECTRIC (Continued)** **1031951813**

| | |
|---|---|
| Quantity Haz Kg: | 362.812 |
| Quantity Haz Tons: | 0.4 |
| Quantity Non Haz Kg: | 0 |
| Quantity Non Haz Tons: | 0 |
| State Waste Codes: | NY-T |

---

**M68** **CON EDISON** **NY MANIFEST** **S117535866**
**WSW** **CHATSWORTH AVE & WASHINGTON SQ** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.181 mi.**
**957 ft.** **Site 1 of 8 in cluster M**

**Relative:**
**Higher**

**Actual:**
**47 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004682852 |
| Country: | USA |
| Name: | Con Edison |
| Address: | CHATSWORTH AVE & WASHINGTON SQ |
| Address 2: | SB232 |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Zip 4: | Not reported |
| Location Address 1: | CHATSWORTH AVE & WASHINGTON SQ |
| Location Address 2: | SB232 |
| Location City,State,Zip: | LARCHMONT, NY 10538 |
| Location Zip 4: | Not reported |
| Facility Status: | Not reported |
| Total Tanks: | Not reported |
| Code: | BP |

Mailing:

| | |
|---|---|
| Mailing Name: | Con Edison |
| Mailing Contact: | Con Edison |
| Mailing Address 1: | 4 IRVING PL |
| Mailing Address 2: | 15TH FLOOR |
| Mailing City,State,Zip: | NEW YORK, NY 10003 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | Not reported |

Manifest Data:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD006982359 |
| Year: | 2018 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 10/23/2014 |
| Trans1 Recv Date: | 10/23/2014 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 10/24/2014 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004682852 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD002200046 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 012773175JJK |
| Import Indicator: | N |
| Export Indicator: | N |

**CON EDISON (Continued)** **S117535866**

| | |
|---|---|
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H110 |
| Waste Code a: | Lead |
| Waste Code b: | Not reported |
| Waste Code c: | Not reported |
| Waste Code e: | Not reported |
| Waste Code f: | Not reported |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 85 |
| Units: | Pounds |
| Number of Containers: | 1 |
| Container Type: | Cargo tanks (tank trucks) |
| Handling Method: | Treat |
| Specific Gravity: | 1 |

---

**M69** **CONSOLIDATED EDISON TM4093** **NY MANIFEST** **1009241052**
**WSW** **WASHINGTON & N CHATSWORTH** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.181 mi.**
**957 ft.** **Site 2 of 8 in cluster M**

**Relative:** **Higher**
**Actual:** **47 ft.**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004093696 |
| Country: | USA |
| Name: | Consolidated Edison Tm4093 |
| Address: | WASHINGTON & N CHATSWORTH |
| Address 2: | Not reported |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Zip 4: | Not reported |
| Location Address 1: | WASHINGTON & N CHATSWORTH |
| Location Address 2: | Not reported |
| Location City,State,Zip: | LARCHMONT, NY 10538 |
| Location Zip 4: | Not reported |
| Facility Status: | Not reported |
| Total Tanks: | Not reported |
| Code: | BP |

Mailing:

| | |
|---|---|
| Mailing Name: | Consolidated Edison Tm4093 |
| Mailing Contact: | Franklin Murray |
| Mailing Address 1: | 4 IRVING PLACE RM 828 |
| Mailing Address 2: | Not reported |
| Mailing City,State,Zip: | NEW YORK, NY 10003 |
| Mailing Zip 4: | Not reported |

**CONSOLIDATED EDISON TM4093 (Continued)** **1009241052**

Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: NYE0706455
Manifest Status: Not reported
Trans1 State ID: 20856AD
Year: 2001
Trans2 State ID: Not reported
Generator Ship Date: 12/14/2001
Trans1 Recv Date: 12/14/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/14/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004093696
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B002
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00616
Units: Kilograms
Number of Containers: 001
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 01.00

---

**N70** **CON EDISON - SERVICE BOX 720** **NY MANIFEST** **S121968319**
**NW** **MURRAY AVE & EDGEWOOD AVE INT** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.181 mi.**
**957 ft.** **Site 1 of 2 in cluster N**

**Relative:** NY MANIFEST:
**Higher**
EPA ID: NYP005106317
**Actual:** Country: USA
**72 ft.** Name: Con Edison - Service Box 720
Address: MURRAY AVE & EDGEWOOD AVE INT

**CON EDISON - SERVICE BOX 720 (Continued)** **S121968319**

| | |
|---|---|
| Address 2: | Not reported |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Zip 4: | Not reported |
| Location Address 1: | MURRAY AVE & EDGEWOOD AVE INT |
| Location Address 2: | Not reported |
| Location City,State,Zip: | LARCHMONT, NY 10538 |
| Location Zip 4: | Not reported |
| Facility Status: | Not reported |
| Total Tanks: | Not reported |
| Code: | BP |

Mailing:

| | |
|---|---|
| Mailing Name: | Con Edison - Service Box 720 |
| Mailing Contact: | Con Edison |
| Mailing Address 1: | 4 IRVING PL |
| Mailing Address 2: | Not reported |
| Mailing City,State,Zip: | NEW YORK, NY 10003 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | Not reported |

---

**N71** **CON EDISON - SERVICE BOX 720** **RCRA NonGen / NLR** **1024891395**
**NW** **MURRAY AVE & EDGEWOOD AVE INT** **NYP005106317**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.181 mi.**
**957 ft.** **Site 2 of 2 in cluster N**

**Relative:** **Higher**

**Actual:** **72 ft.**

RCRA Listings:

| | |
|---|---|
| Date Form Received by Agency: | 20250421 |
| Handler Name: | Con Edison - Service Box 720 |
| Handler Address: | Murray Ave & Edgewood Ave Int |
| Handler City,State,Zip: | LARCHMONT, NY 10538 |
| EPA ID: | NYP005106317 |
| Contact Name: | ALYSSA SOTTO |
| Contact Address: | IRVING PLACE, 15TH FL NE |
| Contact City,State,Zip: | NEW YORK, NY 10003 |
| Contact Telephone: | 212-460-2757 |
| Contact Fax: | Not reported |
| Contact Email: | SOTTOA@CONED.COM |
| Contact Title: | ASSOCIATE SCIENTIST |
| EPA Region: | 02 |
| Land Type: | Private |
| Federal Waste Generator Description: | Not a generator, verified |
| Non-Notifier: | Not reported |
| Biennial Report Cycle: | Not reported |
| Accessibility: | Not reported |
| Active Site Indicator: | Not reported |
| State District Owner: | Ny |
| State District: | NYSDEC R3 |
| Mailing Address: | IRVING PLACE, 15TH FL NE |
| Mailing City,State,Zip: | NEW YORK, NY 10003 |
| Owner Name: Not reported | |
| Owner Type: | Not reported |
| Operator Name: Not reported | |
| Operator Type: | Not reported |
| Short-Term Generator Activity: | No |
| Importer Activity: | No |

**CON EDISON - SERVICE BOX 720 (Continued)** **1024891395**

| | |
|---|---|
| Mixed Waste Generator: | No |
| Transporter Activity: | No |
| Transfer Facility Activity: | No |
| Recycler Activity with Storage: | No |
| Small Quantity On-Site Burner Exemption: | No |
| Smelting Melting and Refining Furnace Exemption: | No |
| Underground Injection Control: | No |
| Off-Site Waste Receipt: | No |
| Universal Waste Indicator: | No |
| Universal Waste Destination Facility: | No |
| Federal Universal Waste: | No |
| Active Site State-Reg Handler: | --- |
| Federal Facility Indicator: | Not reported |
| Hazardous Secondary Material Indicator: | N |
| Sub-Part K Indicator: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20250421 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170705
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003

**CON EDISON - SERVICE BOX 720 (Continued)** **1024891395**

Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170705
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170705
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170705
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - SERVICE BOX 720
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20170705
Handler Name: CON EDISON SB720

**CON EDISON - SERVICE BOX 720 (Continued)** **1024891395**

| | |
|---|---|
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | No |
| Electronic Manifest Broker: | No |

| | |
|---|---|
| Receive Date: | 20250421 |
| Handler Name: | CON EDISON - SERVICE BOX 720 |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | No |
| Electronic Manifest Broker: | No |

List of NAICS Codes and Descriptions:

| | |
|---|---|
| NAICS Code: | 221122 |
| NAICS Description: | Electric Power Distribution |

Facility Has Received Notices of Violations:

| | |
|---|---|
| Violations: | No Violations Found |

Evaluation Action Summary:

| | |
|---|---|
| Evaluations: | No Evaluations Found |

---

**L72** **EMBASSY CLEANERS** **RCRA NonGen / NLR** **1000158278**
**South** **1908 PALMER AVE** **US AIRS** **NYD012815395**
**1/8-1/4** **LARCHMONT, NY 10538** **NY MANIFEST**
**0.182 mi.**
**960 ft.** **Site 3 of 8 in cluster L**

**Relative:** **Higher**
**Actual:** **58 ft.**

RCRA Listings:

| | |
|---|---|
| Date Form Received by Agency: | 20070101 |
| Handler Name: | Embassy Cleaners |
| Handler Address: | Palmer Ave |
| Handler City,State,Zip: | LARCHMONT, NY 10538-2408 |
| EPA ID: | NYD012815395 |
| Contact Name: | Not reported |
| Contact Address: | PALMER AVE |
| Contact City,State,Zip: | LARCHMONT, NY 10538 |
| Contact Telephone: | Not reported |
| Contact Fax: | Not reported |
| Contact Email: | Not reported |
| Contact Title: | Not reported |
| EPA Region: | 02 |
| Land Type: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000158278**

| | | |
|---|---|---|
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | Ny |
| State District: | | NYSDEC R3 |
| Mailing Address: | | PALMER AVE |
| Mailing City,State,Zip: | | LARCHMONT, NY 10538 |
| Owner Name: | Ownername | |
| Owner Type: | | Private |
| Operator Name: | Ownername | |
| Operator Type: | | Private |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| Corrective Action Priority Ranking: | | No NCAPS ranking |
| Environmental Control Indicator: | | No |
| Institutional Control Indicator: | | No |
| Human Exposure Controls Indicator: | | N/A |
| Groundwater Controls Indicator: | | N/A |
| Significant Non-Complier Universe: | | No |
| Unaddressed Significant Non-Complier Universe: | | No |
| Addressed Significant Non-Complier Universe: | | No |
| Significant Non-Complier With a Compliance Schedule Universe: | | No |
| Financial Assurance Required: | | Not reported |
| Handler Date of Last Change: | | 20150414 |
| Recognized Trader-Importer: | | No |
| Recognized Trader-Exporter: | | No |
| Importer of Spent Lead Acid Batteries: | | No |
| Exporter of Spent Lead Acid Batteries: | | No |
| Recycler Activity Without Storage: | | No |
| Manifest Broker: | | No |
| Sub-Part P Indicator: | | No |

Hazardous Waste Summary:
Waste Code: F002

**EMBASSY CLEANERS (Continued)** **1000158278**

Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

| | |
|---|---|
| Owner/Operator Indicator: | Operator |
| Owner/Operator Name: OWNERNAME | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | NOT REQUIRED |
| Owner/Operator City,State,Zip: | NOT REQUIRED, WY 99999 |
| Owner/Operator Telephone: | 212-555-1212 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: OWNERNAME | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | NOT REQUIRED |
| Owner/Operator City,State,Zip: | NOT REQUIRED, WY 99999 |
| Owner/Operator Telephone: | 212-555-1212 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: OWNERNAME | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | NOT REQUIRED |
| Owner/Operator City,State,Zip: | NOT REQUIRED, WY 99999 |
| Owner/Operator Telephone: | 212-555-1212 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

Historic Generators:

| | |
|---|---|
| Receive Date: | 19990708 |
| Handler Name: EMBASSY CLEANERS | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |

**EMBASSY CLEANERS (Continued)** **1000158278**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: EMBASSY CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: EMBASSY CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19850506
Handler Name: EMBASSY CLEANERS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

US AIRS MINOR:

**EMBASSY CLEANERS (Continued)** **1000158278**

Envid: 1000158278
Region Code: 02
Programmatic ID: AIR NY0000003553200189
Facility Registry ID: 110004345361
D and B Number: Not reported
Primary SIC Code: 7212
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000003553200189
Facility Registry ID: 110004345361
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1997-06-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200189
Facility Registry ID: 110004345361
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-12-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200189
Facility Registry ID: 110004345361
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-08-05 00:00:00
Activity Status Date: 2002-08-05 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000003553200189
Facility Registry ID: 110004345361
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-07-11 00:00:00
Activity Status Date: 2008-07-11 00:00:00
Activity Group: Enforcement Action

**EMBASSY CLEANERS (Continued)** **1000158278**

Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000003553200189
Facility Registry ID: 110004345361
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-12-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000003553200189
Facility Registry ID: 110004345361
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-08-05 00:00:00
Activity Status Date: 2002-08-05 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

NY MANIFEST:
EPA ID: NYD012815395
Country: USA
Name: Embassy Cleaners
Address: 1908 PALMER AVE
Address 2: Not reported
City,State,Zip: LARCHMONT, NY 10538-2408
Zip 4: Not reported
Location Address 1: 120 CHATSWORTH AVENUE
Location Address 2: Not reported
Location City,State,Zip: LARCHMONT, NY 10538
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Embassy Cleaners
Mailing Contact: Embassy Cleaners
Mailing Address 1: 120 CHATSWORTH AVENUE
Mailing Address 2: Not reported
Mailing City,State,Zip: LARCHMONT, NY 10538
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9143342700

Manifest Data:
Document ID: NYC1098077
Manifest Status: Not reported

**EMBASSY CLEANERS (Continued)** **1000158278**

| | |
|---|---|
| Trans1 State ID: | DW9495NY |
| Year: | 1991 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 07/30/1991 |
| Trans1 Recv Date: | 07/30/1991 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 07/30/1991 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD012815395 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00180 |
| Units: | Pounds |
| Number of Containers: | 003 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| Waste Code 7: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 8: | Not reported |
| Waste Code: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000158278**

| | |
|---|---|
| Waste Code 10: | Not reported |
| Waste Code 11: | Not reported |
| Quantity: | 00390 |
| Units: | Pounds |
| Number of Containers: | 002 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYC1386415 |
| Manifest Status: | Not reported |
| Trans1 State ID: | DW1495-NY |
| Year: | 1991 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 12/11/1991 |
| Trans1 Recv Date: | 12/11/1991 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/11/1991 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD012815395 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00195 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiberboard or plastic drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

**EMBASSY CLEANERS (Continued)** **1000158278**

| | |
|---|---|
| Document ID: | NYC0393085 |
| Manifest Status: | Not reported |
| Trans1 State ID: | 000000000 |
| Year: | 1990 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 07/26/1990 |
| Trans1 Recv Date: | 07/26/1990 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 07/26/1990 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD012815395 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00240 |
| Units: | Pounds |
| Number of Containers: | 004 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

| | |
|---|---|
| Document ID: | NYA9410703 |
| Manifest Status: | C - Completed copy |
| Trans1 State ID: | AV4489 |
| Year: | 1989 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 890412 |
| Trans1 Recv Date: | 890412 |
| Trans2 Recv Date: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000158278**

| | |
|---|---|
| TSD Site Recv Date: | 890412 |
| Part A Recv Date: | 890419 |
| Part B Recv Date: | 890426 |
| Generator EPA ID: | NYD012815395 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00080 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiber or plastic boxes, cartons, cases |
| Handling Method: | Recycle |
| Specific Gravity: | 100 |
| | |
| Document ID: | NYA6668458 |
| Manifest Status: | C - Completed copy |
| Trans1 State ID: | AV4489 |
| Year: | 1987 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 870515 |
| Trans1 Recv Date: | 870515 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 870515 |
| Part A Recv Date: | 870520 |
| Part B Recv Date: | 870520 |
| Generator EPA ID: | NYD012815395 |
| Trans1 EPA ID: | ILD000805911 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000158278**

| | |
|---|---|
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00200 |
| Units: | Pounds |
| Number of Containers: | 003 |
| Container Type: | Fiber or plastic boxes, cartons, cases |
| Handling Method: | Recycle |
| Specific Gravity: | 100 |

| | |
|---|---|
| Document ID: | NYC1211534 |
| Manifest Status: | Not reported |
| Trans1 State ID: | DW9495NY |
| Year: | 1991 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 09/19/1991 |
| Trans1 Recv Date: | 09/19/1991 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 09/19/1991 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD012815395 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000158278**

| | |
|---|---|
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00180 |
| Units: | Pounds |
| Number of Containers: | 003 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |
| | |
| Document ID: | NYA5667102 |
| Manifest Status: | C - Completed copy |
| Trans1 State ID: | AV4489 |
| Year: | 1987 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 870611 |
| Trans1 Recv Date: | 870611 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 870611 |
| Part A Recv Date: | 870615 |
| Part B Recv Date: | 870616 |
| Generator EPA ID: | NYD012815395 |
| Trans1 EPA ID: | ILD000805911 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, |

**EMBASSY CLEANERS (Continued)** **1000158278**

Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

| | |
|---|---|
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00080 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiber or plastic boxes, cartons, cases |
| Handling Method: | Recycle |
| Specific Gravity: | 100 |
| | |
| Document ID: | NYA6643890 |
| Manifest Status: | C - Completed copy |
| Trans1 State ID: | AV4489 |
| Year: | 1987 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 870416 |
| Trans1 Recv Date: | 870416 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 870416 |
| Part A Recv Date: | 870422 |
| Part B Recv Date: | 870421 |
| Generator EPA ID: | NYD012815395 |
| Trans1 EPA ID: | ILD000805911 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000158278**

| | |
|---|---|
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00080 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Fiber or plastic boxes, cartons, cases |
| Handling Method: | Recycle |
| Specific Gravity: | 100 |
| | |
| Document ID: | NYC0496001 |
| Manifest Status: | Not reported |
| Trans1 State ID: | 000000000 |
| Year: | 1990 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 09/19/1990 |
| Trans1 Recv Date: | 09/19/1990 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 09/19/1990 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD012815395 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00060 |
| Units: | Pounds |
| Number of Containers: | 001 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

**EMBASSY CLEANERS (Continued)** **1000158278**

| | |
|---|---|
| Document ID: | NYA9501355 |
| Manifest Status: | C - Completed copy |
| Trans1 State ID: | AV4489 |
| Year: | 1989 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 890609 |
| Trans1 Recv Date: | 890609 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 890609 |
| Part A Recv Date: | 890615 |
| Part B Recv Date: | 890619 |
| Generator EPA ID: | NYD012815395 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00240 |
| Units: | Pounds |
| Number of Containers: | 003 |
| Container Type: | Fiber or plastic boxes, cartons, cases |
| Handling Method: | Recycle |
| Specific Gravity: | 100 |

| | |
|---|---|
| Document ID: | NYC0207641 |
| Manifest Status: | Not reported |
| Trans1 State ID: | AV4489NY |
| Year: | 1990 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 04/10/1990 |
| Trans1 Recv Date: | 04/10/1990 |
| Trans2 Recv Date: | Not reported |

**EMBASSY CLEANERS (Continued)** **1000158278**

| | |
|---|---|
| TSD Site Recv Date: | 04/10/1990 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYD012815395 |
| Trans1 EPA ID: | ILD051060408 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000708172 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00300 |
| Units: | Pounds |
| Number of Containers: | 005 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Burn |
| Specific Gravity: | 01.00 |

Click this hyperlink while viewing on your computer to access
48 additional NY MANIFEST: record(s) in the EDR Site Report.

---

**L73** **EMBASSY CLEANERS** **NY DRYCLEANERS** **S110246512**
**South** **1908 PALMER AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.182 mi.**
**960 ft.** **Site 4 of 8 in cluster L**

**Relative:** DRYCLEANERS:
**Higher**

| | |
|---|---|
| Name: | EMBASSY CLEANERS |
| Address: | 1908 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Facility ID: | 3-5532-00189 |
| Phone Number: | NOT LISTED |
| Region: | Not reported |

**Actual:**
**58 ft.**

**EMBASSY CLEANERS (Continued)** **S110246512**

| | |
|---|---|
| Registration Effective Date: | N/A |
| Inspection Date: | 01/07/2016 |
| Install Date: | -/07 |
| Expiration Date: | Not reported |
| Removal Date: | Not reported |
| Drop Shop: | Not reported |
| Shutdown: | Y |
| Alternate Solvent: | Not reported |
| Current Business: | Not reported |

---

**74** **CON EDISON POLE W10** **RCRA NonGen / NLR** **1010327190**
**ESE** **HALL AVE & CONCORD AVE** **NY MANIFEST** **NYP004145074**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.183 mi.**
**966 ft.**

**Relative:**
**Lower**

**Actual:**
**35 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20070111 |
| Handler Name: | | Con Edison Pole W10 |
| Handler Address: | | Hall Ave & Concord Ave |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYP004145074 |
| Contact Name: | | MICHAEL D'AGOSTINO |
| Contact Address: | | IRVING PL RM 828 |
| Contact City,State,Zip: | | NEW YORK, NY 10003 |
| Contact Telephone: | | 212-580-8383 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | Ny |
| State District: | | NYSDEC R3 |
| Mailing Address: | | IRVING PL RM 828 |
| Mailing City,State,Zip: | | NEW YORK, NY 10003 |
| Owner Name: | Not reported | |
| Owner Type: | | Not reported |
| Operator Name: | Not reported | |
| Operator Type: | | Not reported |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |

**CON EDISON POLE W10 (Continued)** **1010327190**

| | |
|---|---|
| Federal Facility Indicator: | Not reported |
| Hazardous Secondary Material Indicator: | N |
| Sub-Part K Indicator: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20150414 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20070109 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Not reported |
| State District Owner: | Not reported |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20070110 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Not reported |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20070111 |
| Handler Name: CON EDISON POLE W10 | |

**CON EDISON POLE W10 (Continued)** **1010327190**

| | |
|---|---|
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

List of NAICS Codes and Descriptions:

| | |
|---|---|
| NAICS Codes: | No NAICS Codes Found |

Facility Has Received Notices of Violations:

| | |
|---|---|
| Violations: | No Violations Found |

Evaluation Action Summary:

| | |
|---|---|
| Evaluations: | No Evaluations Found |

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004145074 |
| Country: | USA |
| Name: | Coned |
| Address: | HALL AVE & CONCORD AVE |
| Address 2: | Not reported |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Zip 4: | Not reported |
| Location Address 1: | VANDENBURGH AVE & HALL AVE |
| Location Address 2: | Not reported |
| Location City,State,Zip: | LARCHMONT, NY 10001 |
| Location Zip 4: | Not reported |
| Facility Status: | Not reported |
| Total Tanks: | Not reported |
| Code: | BP |

Mailing:

| | |
|---|---|
| Mailing Name: | Coned |
| Mailing Contact: | Coned |
| Mailing Address 1: | 31-01 20TH AVE |
| Mailing Address 2: | BLDG 136 |
| Mailing City,State,Zip: | ASTORIA, NY 11105 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 7182044151 |

Manifest Data:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NJD003812047 |
| Year: | 2018 |
| Trans2 State ID: | NJD003812047 |
| Generator Ship Date: | 09/07/2006 |
| Trans1 Recv Date: | 09/07/2006 |

**CON EDISON POLE W10 (Continued)** **1010327190**

| | |
|---|---|
| Trans2 Recv Date: | 09/14/2006 |
| TSD Site Recv Date: | 09/18/2006 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004145074 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD077444263 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 000017408GBF |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H141 |
| Waste Code a: | B007 |
| Waste Code b: | Not reported |
| Waste Code c: | Not reported |
| Waste Code e: | Not reported |
| Waste Code f: | Not reported |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 70 |
| Units: | Kilograms |
| Number of Containers: | 1 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Landfill |
| Specific Gravity: | 1 |

---

**M75** **16 NORTH CHATSWORTH AVENUE CORP** **NY UST U004175921**
**WSW** **16 NORTH CHATSWORTH AVENUE** **NY AST N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.185 mi.**
**977 ft.** **Site 3 of 8 in cluster M**

**Relative:** **Higher**
**Actual:** **42 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | 16 NORTH CHATSWORTH AVENUE CORP |
| Address: | 16 NORTH CHATSWORTH AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-167819 / Active |
| Operator Name: | Archer Property Management |
| Owner Name: | 16 North Chatsworth Ave Corp, c/o Archer Property |
| Owner Street: | 16 North Chatsworth Avenue |
| Owner Address2: | Not reported |
| Owner City: | Larchmont |
| Owner State: | NY |

**16 NORTH CHATSWORTH AVENUE CORP (Continued)** **U004175921**

| | |
|---|---|
| Owner Zipcode: | 10538 |
| GDS Number: | Not reported |
| Tank Number: | 016 |
| Status: | 3. Closed - Removed |
| Capacity: | 6000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 02/01/1972 |
| Date Perm Closure: | 09/01/2005 |
| Tank Location: | 6. Underground, vaulted, with access |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | Not reported |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 160 |
| Status: | 4. Closed - in place |
| Capacity: | 6000 |
| Product Stored: | 9999. Other |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 02/01/1972 |
| Date Perm Closure: | 07/01/1999 |
| Tank Location: | 6. Underground, vaulted, with access |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | Not reported |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 2. Suction |

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | 16 NORTH CHATSWORTH AVENUE CORP |
| Address: | 16 NORTH CHATSWORTH AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-167819 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | Archer Property Management |
| Owner Name: | 16 North Chatsworth Ave Corp, c/o Archer Property |
| Owner Street: | 16 North Chatsworth Avenue |
| Owner Address2: | Not reported |

**16 NORTH CHATSWORTH AVENUE CORP (Continued)** **U004175921**

| | |
|---|---|
| Owner City/State/Zip: | Larchmont, NY 10538 |
| Tank Number: | 01 |
| Status: | 1. In-Service |
| Date Installation: | 09/01/2005 |
| Capacity: | 5500 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 0. None |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 5. Vent Whistle |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

---

**L76** **DUTCH GIRL PROFESSIONAL CLEANERS** **RCRA NonGen / NLR** **1000169418**
**South** **1912 PALMER AVE** **FINDS** **NYD106797061**
**1/8-1/4** **LARCHMONT, NY 10538** **ECHO**
**0.191 mi.**
**1007 ft.** **Site 5 of 8 in cluster L**

**Relative:** **Higher**
**Actual:** **58 ft.**

RCRA Listings:

| | |
|---|---|
| Date Form Received by Agency: | 20070101 |
| Handler Name: | Dutch Girl Professional Cleaners |
| Handler Address: | Palmer Ave |
| Handler City,State,Zip: | LARCHMONT, NY 10538 |
| EPA ID: | NYD106797061 |
| Contact Name: | Not reported |
| Contact Address: | PALMER AVE |
| Contact City,State,Zip: | LARCHMONT, NY 10538 |
| Contact Telephone: | Not reported |
| Contact Fax: | Not reported |
| Contact Email: | Not reported |
| Contact Title: | Not reported |
| EPA Region: | 02 |
| Land Type: | Not reported |
| Federal Waste Generator Description: | Not a generator, verified |
| Non-Notifier: | O |
| Biennial Report Cycle: | Not reported |
| Accessibility: | Not reported |
| Active Site Indicator: | Not reported |
| State District Owner: | Ny |
| State District: | NYSDEC R3 |
| Mailing Address: | PALMER AVE |
| Mailing City,State,Zip: | LARCHMONT, NY 10538 |
| Owner Name: | Not reported |
| Owner Type: | Not reported |
| Operator Name: | Not reported |
| Operator Type: | Not reported |

**DUTCH GIRL PROFESSIONAL CLEANERS (Continued)** **1000169418**

| | |
|---|---|
| Short-Term Generator Activity: | No |
| Importer Activity: | No |
| Mixed Waste Generator: | No |
| Transporter Activity: | No |
| Transfer Facility Activity: | No |
| Recycler Activity with Storage: | No |
| Small Quantity On-Site Burner Exemption: | No |
| Smelting Melting and Refining Furnace Exemption: | No |
| Underground Injection Control: | No |
| Off-Site Waste Receipt: | No |
| Universal Waste Indicator: | No |
| Universal Waste Destination Facility: | No |
| Federal Universal Waste: | No |
| Active Site State-Reg Handler: | --- |
| Federal Facility Indicator: | Not reported |
| Hazardous Secondary Material Indicator: | N |
| Sub-Part K Indicator: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20230615 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | NONE |
| Waste Description: | Not Defined |

Handler - Owner Operator:

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: TAMES HADDEN | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | NOT REQUIRED |
| Owner/Operator City,State,Zip: | NOT REQUIRED, WY 99999 |
| Owner/Operator Telephone: | 212-555-1212 |
| Owner/Operator Telephone Ext: | Not reported |

**DUTCH GIRL PROFESSIONAL CLEANERS (Continued)** **1000169418**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19791231
Handler Name: DUTCH GIRL PROFESSIONAL CLEANERS
Federal Waste Generator Description: Not reported
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: DUTCH GIRL PROFESSIONAL CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: DUTCH GIRL PROFESSIONAL CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004379324

**DUTCH GIRL PROFESSIONAL CLEANERS (Continued)** **1000169418**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000169418
Registry ID: 110004379324

DFR URL:
Name: DUTCH GIRL PROFESSIONAL CLEANERS
Address: 1912 Palmer Ave
City,State,Zip: LARCHMONT, NY 10538

---

**M77** **LARCHMONT HILLS OWNERS, CORP.** **NY AST** **A100276756**
**SW** **17 NORTH CHATSWORTH AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.193 mi.**
**1019 ft.** **Site 4 of 8 in cluster M**

**Relative:**
**Higher**

**Actual:**
**50 ft.**

WESTCHESTER CO. AST:
Name: LARCHMONT HILLS OWNERS, CORP.
Address: 17 NORTH CHATSWORTH AVENUE
City,State,Zip: LARCHMONT, NY 10538
PBS Number: 3-048488
Site Status: Active
GDS Number: Not reported
Operator Name: Larchmont Hills Owners, Corp.
Owner Name: Larchmont Hills Owners Corp.
Owner Street: 17 North Chatsworth Avenue
Owner Address2: Not reported
Owner City/State/Zip: Larchmont, NY 10538

Tank Number: 17
Status: 3. Closed - Removed
Date Installation: 05/01/1948
Capacity: 5000
Product Stored: 0002. #4 Fuel Oil
Product Stored Percent: Not reported
Date Perm Closure: 04/21/2021
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating
Tank Leak Detection: 0. None
Tank Secondary Containment: 2. Vault (w/ access)
Piping Location: 1. Aboveground
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 1. Painted/Asphalt Coating
Piping Leak Detection: 0. None

**LARCHMONT HILLS OWNERS, CORP. (Continued)** **A100276756**

| | |
|---|---|
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only),5. Vent Whistle |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

| | |
|---|---|
| Tank Number: | 18 |
| Status: | 1. In-Service |
| Date Installation: | 07/02/2021 |
| Capacity: | 3500 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | Not reported |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 5. In-Tank System (auto tank gauge),6. Impervious Barrier/Concrete Pad (Aboveground Only) |
| Tank Secondary Containment: | 2. Vault (w/ access) |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | Not reported |
| Piping Secondary Containment: | Not reported |
| Overfill Prevention: | 2. High Level Alarm,4. Product Level Gauge (Aboveground Only) |
| Spill Prevention: | Not reported |
| Dispenser: | Not reported |

---

**K78** **DONALD RITACCO & CO LTD** **RCRA NonGen / NLR** **1000148702**
**SSW** **7-11 NORTH AVE** **NY MANIFEST** **NYD982718249**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.194 mi.**
**1023 ft.** **Site 2 of 2 in cluster K**

**Relative:** **Higher**
**Actual:** **55 ft.**

RCRA Listings:

| | |
|---|---|
| Date Form Received by Agency: | 20070101 |
| Handler Name: | Donald Ritacco & Co Ltd |
| Handler Address: | North Ave |
| Handler City,State,Zip: | LARCHMONT, NY 10538 |
| EPA ID: | NYD982718249 |
| Contact Name: | Not reported |
| Contact Address: | NORTH AVE |
| Contact City,State,Zip: | LARCHMONT, NY 10538 |
| Contact Telephone: | Not reported |
| Contact Fax: | Not reported |
| Contact Email: | Not reported |
| Contact Title: | Not reported |
| EPA Region: | 02 |
| Land Type: | Not reported |
| Federal Waste Generator Description: | Not a generator, verified |
| Non-Notifier: | Not reported |
| Biennial Report Cycle: | Not reported |
| Accessibility: | Not reported |
| Active Site Indicator: | Not reported |
| State District Owner: | Ny |
| State District: | NYSDEC R3 |
| Mailing Address: | NORTH AVE |
| Mailing City,State,Zip: | LARCHMONT, NY 10538 |

**DONALD RITACCO & CO LTD (Continued)** **1000148702**

| | |
|---|---|
| Owner Name: | Donald Ritacco Keystone Mgmt Bldg Bus |
| Owner Type: | Private |
| Operator Name: | Donald Ritacco Keystone Mgmt Bldg Bus |
| Operator Type: | Private |
| Short-Term Generator Activity: | No |
| Importer Activity: | No |
| Mixed Waste Generator: | No |
| Transporter Activity: | No |
| Transfer Facility Activity: | No |
| Recycler Activity with Storage: | No |
| Small Quantity On-Site Burner Exemption: | No |
| Smelting Melting and Refining Furnace Exemption: | No |
| Underground Injection Control: | No |
| Off-Site Waste Receipt: | No |
| Universal Waste Indicator: | No |
| Universal Waste Destination Facility: | No |
| Federal Universal Waste: | No |
| Active Site State-Reg Handler: | --- |
| Federal Facility Indicator: | Not reported |
| Hazardous Secondary Material Indicator: | N |
| Sub-Part K Indicator: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20150414 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | D001 |
| Waste Description: | Ignitable Waste |
| Waste Code: | F001 |
| Waste Description: | The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed |

**DONALD RITACCO & CO LTD (Continued)** **1000148702**

In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: DONALD RITACCO KEYSTONE MGMT BLDG BUS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DONALD RITACCO KEYSTONE MGMT BLDG BUS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported

**DONALD RITACCO & CO LTD (Continued)** **1000148702**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DONALD RITACCO KEYSTONE MGMT BLDG BUS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: DONALD RITACCO & CO LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: DONALD RITACCO & CO LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: DONALD RITACCO & CO LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19881208
Handler Name: DONALD RITACCO & CO LTD

**DONALD RITACCO & CO LTD (Continued)** **1000148702**

| | |
|---|---|
| Federal Waste Generator Description: | Small Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

List of NAICS Codes and Descriptions:

| | |
|---|---|
| NAICS Codes: | No NAICS Codes Found |

Facility Has Received Notices of Violations:

| | |
|---|---|
| Violations: | No Violations Found |

Evaluation Action Summary:

| | |
|---|---|
| Evaluations: | No Evaluations Found |

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYD982718249 |
| Country: | USA |
| Name: | Donald Rittacco Company |
| Address: | 7-11 NORTH AVE |
| Address 2: | Not reported |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Zip 4: | Not reported |
| Location Address 1: | 7-11 NORTH AVENUE |
| Location Address 2: | Not reported |
| Location City,State,Zip: | LARCHMONT, NY 10538 |
| Location Zip 4: | Not reported |
| Facility Status: | Not reported |
| Total Tanks: | Not reported |
| Code: | BP |

Mailing:

| | |
|---|---|
| Mailing Name: | Donald Rittacco Company |
| Mailing Contact: | Donald Rittacco Company |
| Mailing Address 1: | 7-11 NORTH AVENUE |
| Mailing Address 2: | Not reported |
| Mailing City,State,Zip: | LARCHMONT, NY 10538 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 9148340441 |

Manifest Data:

| | |
|---|---|
| Document ID: | CTC0241551 |
| Manifest Status: | C - Completed copy |
| Trans1 State ID: | H18750CT |
| Year: | 1989 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 890314 |
| Trans1 Recv Date: | 890314 |

**DONALD RITACCO & CO LTD (Continued)** **1000148702**

| | |
|---|---|
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 890316 |
| Part A Recv Date: | 890407 |
| Part B Recv Date: | 890330 |
| Generator EPA ID: | NYD982718249 |
| Trans1 EPA ID: | VAD980831580 |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | CTD072138969 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | Not reported |
| Import Indicator: | Not reported |
| Export Indicator: | Not reported |
| Discr Quantity Indicator: | Not reported |
| Discr Type Indicator: | Not reported |
| Discr Residue Indicator: | Not reported |
| Discr Partial Reject Indicator: | Not reported |
| Discr Full Reject Indicator: | Not reported |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | Not reported |
| Waste Code 1: | The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures. |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 00110 |
| Units: | Gallons (liquids only) |
| Number of Containers: | 001 |
| Container Type: | Cargo tanks (tank trucks) |
| Handling Method: | Treat |
| Specific Gravity: | 100 |

---

**L79** **LARCH REALTY CORP** **NY UST** **U004440717**
**SSW** **1923/1925 PALMER AV** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.197 mi.**
**1038 ft.** **Site 6 of 8 in cluster L**

**Relative:** **Higher**
**Actual:** **57 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | LARCH REALTY CORP |
| Address: | 1923/1925 PALMER AV |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-169285 / Unregulated: <1101 gal. PBS |
| Operator Name: | Martin Bergin |
| Owner Name: | Larch Realty Corp |
| Owner Street: | C/o L E Tomback 88 Lk Shore Dr |

**LARCH REALTY CORP (Continued)** **U004440717**

| | |
|---|---|
| Owner Address2: | Not reported |
| Owner City: | Town Of Eastchester |
| Owner State: | NY |
| Owner Zipcode: | 10709 |
| GDS Number: | Not reported |
| | |
| Tank Number: | 1 |
| Status: | 1. In-Service |
| Capacity: | 1080 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 01/01/1900 |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | Not reported |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | Not reported |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 2. Suction |

---

**L80** **LARCH REALTY CORP PROPERT** **NY LTANKS** **S100140337**
**SSW** **1925 PALMER AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.199 mi.**
**1051 ft.** **Site 7 of 8 in cluster L**

**Relative:** **Higher**
**Actual:** **57 ft.**

LTANKS:

| | |
|---|---|
| Name: | LARCH REALTY CORP PROPERT |
| Address: | 1925 PALMER AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 8801114 / 1997-12-01 |
| Facility ID: | 8801114 |
| Site ID: | 108260 |
| Spill Date: | 1988-02-07 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | D1 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1988-03-08 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Affected Persons |
| Last Inspection: | 1988-12-14 |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1988-05-13 |

**LARCH REALTY CORP PROPERT (Continued)** **S100140337**

| | |
|---|---|
| Spill Record Last Update: | 2005-11-25 |
| Spiller Name: | Not reported |
| Spiller Company: | LARCH REALTY C/O TOMBACK |
| Spiller Address: | 37 CHURCH LANE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 95150 |
| Latitude: | 40.9324829 |
| Longitude: | -73.7593635 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : PROPERTY OWNER TESTED HIS OWN TANK. TANK WAS A MARGINAL FAILURE. DEC INSPECTED ALL OTHER BUILDINGS IN THE VICINITY. ALL NEARBY FUEL TANKS ARE ABOVE GROUND OR CONTAIN OIL OTHER THAN # 2 FUEL. |
| | Not reported |
| Remarks: | PETROLEUM IS COMING UP THROUGH THE FLOOR OF THE JEWLRY STORE & 4 ADJAENT BUILDING. SPEEDY DRY IS BEING USED. |

All TTF:

| | |
|---|---|
| Facility ID: | 8801114 |
| Spill Number: | 8801114 |
| Spill Tank Test: | 1533838 |
| Site ID: | 108260 |
| Tank Number: | 001 |
| Tank Size: | 0 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 108260 |
| Operable Unit ID: | 916605 |
| Operable Unit: | 01 |
| Material ID: | 460272 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**M81**
**WSW**
**1/8-1/4**
**0.204 mi.**
**1079 ft.**

**CONSOLIDATED EDISON COMPANY OF NY C/O ACV ENVIRO**
**21 N CHATSWORTH AVE**
**LARCHMONT, NY 10538**

**Site 5 of 8 in cluster M**

**E MANIFEST** | **1031971916** / **N/A**

**Relative:**
**Higher**

**Actual:**
**48 ft.**

E MANIFEST:

| | |
|---|---|
| Manifest Tracking Number: | 024111743JJK |
| Last Updated Date: | 20221025 |
| Shipped Date: | 20221014 |
| Received Date: | 20221018 |
| Manifest Status: | Signed |
| Submission Type: | DataImage5Copy |
| Origin Type: | Service |
| Generator EPA ID: | NYR000114579 |
| Generator Name: | Consolidated Edison Company Of Ny C/O Acv Enviro |
| Generator Location Street Number: | Not reported |
| Generator Location Street 1: | 21 N CHATSWORTH AVE |
| Generator Location Street 2: | Not reported |
| Generator Location City: | LARCHMONT |
| Generator Location State: | NY |
| Generator Location Zip: | 10538 |
| Generator Mail Street Number: | Not reported |
| Generator Mail Street 1: | 928 E HAZELWOOD AVE |
| Generator Mail Street 2: | Not reported |
| Generator Mail City: | RAHWAY |
| Generator Mail Zip: | 07065 |
| Generator Mail State: | NJ |
| Generator Contact Company Name: | Not reported |
| Designated Facility EPA ID: | NJD991291105 |
| Designated Facility Name: | Clean Earth Of North Jersey |
| Designated Facility Mail Street Number: | 105 |
| Designated Facility Mail Street 1: | Not reported |
| Designated Facility Mail Street 2: | JACOBUS AVE |
| Designated Facility Mail City: | KEARNY |
| Designated Facility Mail Zip: | 07032 |
| Designated Facility Mail State: | NJ |
| Designated Facility Location Street Number: | 105 |
| Designated Facility Location Street 1: | JACOBUS AVE |
| Designated Facility Location Street 2: | Not reported |
| Designated Facility Location City: | KEARNY |
| Designated Facility Location Zip: | 07032 |
| Designated Facility Location State: | NJ |
| Designated Facility Contact Company Name: | Not reported |
| Manifest Residue Indicator: | N |
| Rejection Indicator: | N |

Transporter:

| | |
|---|---|
| Manifest Tracking Number: | 024111743JJK |
| Transporter Line Number: | 1 |
| Transporter EPA ID: | NJD003812047 |
| Transporter Name: | Acv Environmental Services Inc. |

Waste Line:

| | |
|---|---|
| Manifest Tracking Number: | 024111743JJK |
| Waste Line Number: | 1 |
| U.S. DOT Hazardous Indicator: | Y |
| U.S. DOT ID Number: | NA3082 |

**CONSOLIDATED EDISON COMPANY OF NY C/O ACV ENVIRO (Continued)** **1031971916**

| | |
|---|---|
| U.S. DOT Description: | Na3082, Hazardous Waste, Liquid N.O.S., 9, Pg Iii, Rq |
| Non-Hazardous Waste Description: | Not reported |
| Number of Containers: | 1 |
| Container Type Code: | TT |
| Container Type Description: | Cargo tanks (tank trucks) |
| Waste Quantity: | 1000 |
| Quantity Unit of Measure Code: | P |
| Quantity Unit of Measure Description: | Pounds |
| Waste Quantity, in Tons: | 0.5 |
| Acute Waste Quantity, in Tons: | 0 |
| Non-Acute Waste Quantity, in Tons: | 0.5 |
| Waste Quantity, in Kilograms: | 453.515 |
| Acute Waste Quantity, in Kilograms: | 0 |
| Non-Acute Waste Quantity, in Kilorgrams: | 453.515 |
| Management Method Code: | H110 |
| Management Method Description: | STABILIZATION |
| Waste Residue Indicator: | N |
| Quantity Discrepancy Indicator: | N |
| Waste Type Discrepancy Indicator: | N |
| Waste Density: | Not reported |
| Waste Density Unit of Measure Code: | Not reported |
| Waste Density Unit of Measure Description: | Not reported |
| Form Code: | Not reported |
| Form Code Description: | Not reported |
| Source Code: | Not reported |
| Source Code Description: | Not reported |
| Waste Minimization Code: | Not reported |
| Waste Minimization Code Description: | Not reported |
| Consent Number: | Not reported |
| EPA Waste Indicator: | Y |
| Federal Waste Codes: | D008 |
| Quantity Haz Kg: | 453.515 |
| Quantity Haz Tons: | 0.5 |
| Quantity Non Haz Kg: | 0 |
| Quantity Non Haz Tons: | 0 |
| State Waste Codes: | NY-T |

---

**M82** **21 NORTH CHATSWORTH OWNERS CORP.** **NY UST** **U004439167**
**WSW** **21 NORTH CHATSWORTH AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.204 mi.**
**1079 ft.** **Site 6 of 8 in cluster M**

**Relative:** WESTCHESTER CO. UST:
**Higher**

| | |
|---|---|
| Name: | 21 NORTH CHATSWORTH OWNERS CORP. |
| Address: | 21 NORTH CHATSWORTH AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-028800 / Unregulated |
| Operator Name: | Stillman Management |
| Owner Name: | Not reported |
| Owner Street: | 440 Mamaroneck Avenue |
| Owner Address2: | Not reported |
| Owner City: | Harrision |
| Owner State: | NY |
| Owner Zipcode: | 10528 |
| GDS Number: | Not reported |
| Tank Number: | 1 |

**Actual:**
**48 ft.**

**21 NORTH CHATSWORTH OWNERS CORP. (Continued)** **U004439167**

| | |
|---|---|
| Status: | 3. Closed - Removed |
| Capacity: | 5000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | 0 |
| Tank Leak Detection: | 0. None |
| Date Installation: | 03/01/1978 |
| Date Perm Closure: | 10/17/2017 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 2. Underground/on Ground |
| Piping Type: | 11. Flexible Piping |
| Piping External Protection: | 9. Urethane |
| Overfill Prevention: | 5. Vent Whistle |
| Piping Secondary Containment: | 4. Double-Walled (underground only) |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

---

**O83** **172 MYRTLE BLVD. APT. CORP.** **NY AST** **A100252288**
**SW** **172 MYRTLE BOULEVARD** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.205 mi.**
**1085 ft.** **Site 1 of 3 in cluster O**

**Relative:** **Higher**
**Actual:** **48 ft.**

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | 172 MYRTLE BLVD. APT. CORP. |
| Address: | 172 MYRTLE BOULEVARD |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-800128 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | 172 Myrtle Blvd Apt Corp |
| Owner Name: | 172 Myrtle Blvd. Apt. Corp. |
| Owner Street: | 172 Myrtle Boulevard |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | Larchmont, NY 10538 |
| | |
| Tank Number: | 1 |
| Status: | 1. In-Service |
| Date Installation: | 07/01/1999 |
| Capacity: | 1500 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 6. Aboveground in subterranean vault with access for inspections |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 1. Epoxy liner |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 6. Impervious Barrier/Concrete Pad (Aboveground Only) |
| Tank Secondary Containment: | 2. Vault (w/ access) |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 2. Vault (w/ access) |
| Overfill Prevention: | 5. Vent Whistle |

**172 MYRTLE BLVD. APT. CORP. (Continued)** **A100252288**

Spill Prevention: 1. Catch Basin
Dispenser: 3. Gravity

---

**L84** **CITIBANK #10658** **RCRA-LQG** **1031076056**
**South** **1920 PALMER AVE** **NYR000265116**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.207 mi.**
**1094 ft.** **Site 8 of 8 in cluster L**

**Relative:** **Higher**
**Actual:** **54 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20231130 |
| Handler Name: | | Citibank #10658 |
| Handler Address: | | Palmer Ave |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYR000265116 |
| Contact Name: | | JUSTIN TAYLOR |
| Contact Address: | | PALMER AVE |
| Contact City,State,Zip: | | LARCHMONT, NY 10538 |
| Contact Telephone: | | 813-734-2948 |
| Contact Fax: | | Not reported |
| Contact Email: | | JUSTIN.K.TAYLOR@CUSHWAKE.COM |
| Contact Title: | | MANGER |
| EPA Region: | | 02 |
| Land Type: | | Private |
| Federal Waste Generator Description: | | Large Quantity Generator |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Handler Activities |
| State District Owner: | | Ny |
| State District: | | NYSDEC R3 |
| Mailing Address: | | PALMER AVE |
| Mailing City,State,Zip: | | LARCHMONT, NY 10538 |
| Owner Name: | Citigroup | |
| Owner Type: | | Private |
| Operator Name: | Citigroup | |
| Operator Type: | | Private |
| Short-Term Generator Activity: | | Yes |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | | No |
| Subject to Corrective Action Universe: | | No |

**CITIBANK #10658 (Continued)** **1031076056**

| | |
|---|---|
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20231205 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | D001 |
| Waste Description: | Ignitable Waste |
| Waste Code: | D002 |
| Waste Description: | Corrosive Waste |
| Waste Code: | D009 |
| Waste Description: | Mercury |
| Waste Code: | D016 |
| Waste Description: | 2,4-D (2,4-Dichlorophenoxyacetic Acid) |
| Waste Code: | D035 |
| Waste Description: | Methyl Ethyl Ketone |

Handler - Owner Operator:

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: CITIGROUP | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 355 GREENWICH ST |
| Owner/Operator City,State,Zip: | NEW YORK, NY 10013 |
| Owner/Operator Telephone: | 212-793-0710 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | CITISALUTES@CITI.COM |
| Owner/Operator Indicator: | Operator |
| Owner/Operator Name: CITIGROUP | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 355 GREENWICH ST |

**CITIBANK #10658 (Continued)** **1031076056**

Owner/Operator City,State,Zip: NEW YORK, NY 10013
Owner/Operator Telephone: 212-793-0710
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: CITISALUTES@CITI.COM

Historic Generators:
Receive Date: 20231130
Handler Name: CITIBANK #10658
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 522110
NAICS Description: Commercial Banking

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

---

**P85** **FORLANI** **NY LTANKS** **S106703855**
**North** **15-17 HILLCREST AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.217 mi.**
**1147 ft.** **Site 1 of 2 in cluster P**

**Relative: Higher**
**Actual: 96 ft.**

LTANKS:
Name: FORLANI
Address: 15-17 HILLCREST AVE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 9804871 / 2004-12-07
Facility ID: 9804871
Site ID: 120774
Spill Date: 1998-07-20
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: D5
Cleanup Ceased: Not reported
SWIS: 6000
Investigator: JBODee
Referred To: WESTCHESTER CNTY HEALTH D
Reported to Dept: 1998-07-20
CID: 266
Water Affected: Not reported
Spill Notifier: Tank Tester

**FORLANI (Continued)** **S106703855**

| | |
|---|---|
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-07-20 |
| Spill Record Last Update: | 2004-12-07 |
| Spiller Name: | KEVIN DOYLE |
| Spiller Company: | KEVIN DOYLE |
| Spiller Address: | 15-17 HILLCREST AVE |
| Spiller County: | 001 |
| Spiller Contact: | KEVIN DOYLE |
| Spiller Phone: | (914) 279-2365 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 104840 |
| Latitude: | 40.9387763 |
| Longitude: | -73.7590675 |
| DEC Memo: | 12/07/04 TANK TEST FAILURE OF UNREGULATED, RESIDENTIAL HEATING OIL TANK. TANK REPORTEDLY FAILED A RETEST AND WAS ABANDONED IN PLACE BY TAKE PRIDE CONTRACTING. NO CLOSURE INFORMATION RECEIVED BY DEC. ADMINISTRATIVELY CLOSED. jbo |
| Remarks: | TANK TO BE UNCOVERED, ISOLATED AND RETESTED. |

All TTF:

| | |
|---|---|
| Facility ID: | 9804871 |
| Spill Number: | 9804871 |
| Spill Tank Test: | 1546083 |
| Site ID: | 120774 |
| Tank Number: | Not reported |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | F |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 120774 |
| Operable Unit ID: | 1062777 |
| Operable Unit: | 01 |
| Material ID: | 319633 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**86**
**East**
**1/8-1/4**
**0.220 mi.**
**1163 ft.**

**MOONEY ED RESIDENCE**
**22 CARLEON AVE**
**LARCHMONT, NY 10538**

**RCRA NonGen / NLR**
**FINDS**
**ECHO**

**1001489256**
**NYR000073171**

**Relative:**
**Lower**

**Actual:**
**40 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20070101 |
| Handler Name: | | Mooney Ed Residence |
| Handler Address: | | Carleon Ave |
| Handler City,State,Zip: | | LARCHMONT, NY 10538 |
| EPA ID: | | NYR000073171 |
| Contact Name: | | RICHARD LOUIS |
| Contact Address: | | CARLEON AVE |
| Contact City,State,Zip: | | LARCHMONT, NY 10538 |
| Contact Telephone: | | 203-380-5644 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Private |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | Ny |
| State District: | | NYSDEC R3 |
| Mailing Address: | | CARLEON AVE |
| Mailing City,State,Zip: | | LARCHMONT, NY 10538 |
| Owner Name: | Ed Mooney | |
| Owner Type: | | Private |
| Operator Name: | Ed Mooney | |
| Operator Type: | | Private |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| Corrective Action Priority Ranking: | | No NCAPS ranking |
| Environmental Control Indicator: | | No |
| Institutional Control Indicator: | | No |

**MOONEY ED RESIDENCE (Continued)** **1001489256**

| | |
|---|---|
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20150414 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Hazardous Waste Summary:

| | |
|---|---|
| Waste Code: | D001 |
| Waste Description: | Ignitable Waste |

Handler - Owner Operator:

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: ED MOONEY | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 22 CARLEON AVE |
| Owner/Operator City,State,Zip: | LARCHMONT, NY 10538 |
| Owner/Operator Telephone: | 914-834-8919 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

| | |
|---|---|
| Owner/Operator Indicator: | Owner |
| Owner/Operator Name: ED MOONEY | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 22 CARLEON AVE |
| Owner/Operator City,State,Zip: | LARCHMONT, NY 10538 |
| Owner/Operator Telephone: | 914-834-8919 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |
| Owner/Operator Email: | Not reported |

| | |
|---|---|
| Owner/Operator Indicator: | Operator |
| Owner/Operator Name: ED MOONEY | |
| Legal Status: | Private |
| Date Became Current: | Not reported |
| Date Ended Current: | Not reported |
| Owner/Operator Address: | 22 CARLEON AVE |
| Owner/Operator City,State,Zip: | LARCHMONT, NY 10538 |
| Owner/Operator Telephone: | 914-834-8919 |
| Owner/Operator Telephone Ext: | Not reported |
| Owner/Operator Fax: | Not reported |

**MOONEY ED RESIDENCE (Continued)** **1001489256**

Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20060101
Handler Name: MOONEY ED RESIDENCE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MOONEY ED RESIDENCE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19990702
Handler Name: MOONEY ED RESIDENCE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004554161

**MOONEY ED RESIDENCE (Continued)** **1001489256**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001489256
Registry ID: 110004554161

DFR URL:
Name: MOONEY ED RESIDENCE
Address: 22 Carleon Ave
City,State,Zip: LARCHMONT, NY 10538

---

**Q87** **CON EDISON** **RCRA NonGen / NLR** **1012185475**
**West** **6 OVERLOOK TER** **NY MANIFEST** **NYP004162822**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.226 mi.**
**1195 ft.** **Site 1 of 2 in cluster Q**

**Relative:**
**Higher**

**Actual:**
**82 ft.**

RCRA Listings:

| | |
|---|---|
| Date Form Received by Agency: | 20160601 |
| Handler Name: | Con Edison |
| Handler Address: | Overlook Ter |
| Handler City,State,Zip: | LARCHMONT, NY 10538 |
| EPA ID: | NYP004162822 |
| Contact Name: | HERMAN BAKER |
| Contact Address: | Not reported |
| Contact City,State,Zip: | Not reported |
| Contact Telephone: | 718-267-3853 |
| Contact Fax: | Not reported |
| Contact Email: | Not reported |
| Contact Title: | Not reported |
| EPA Region: | 02 |
| Land Type: | Private |
| Federal Waste Generator Description: | Not a generator, verified |
| Non-Notifier: | Not reported |
| Biennial Report Cycle: | Not reported |
| Accessibility: | Not reported |
| Active Site Indicator: | Not reported |
| State District Owner: | Ny |
| State District: | NYSDEC R3 |
| Mailing Address: | 4 IRVING PL, RM 828 |
| Mailing City,State,Zip: | NEW YORK, NY 10003 |
| Owner Name: | Not reported |
| Owner Type: | Not reported |
| Operator Name: | Not reported |
| Operator Type: | Not reported |
| Short-Term Generator Activity: | No |
| Importer Activity: | No |

**CON EDISON (Continued)** **1012185475**

| | |
|---|---|
| Mixed Waste Generator: | No |
| Transporter Activity: | No |
| Transfer Facility Activity: | No |
| Recycler Activity with Storage: | No |
| Small Quantity On-Site Burner Exemption: | No |
| Smelting Melting and Refining Furnace Exemption: | No |
| Underground Injection Control: | No |
| Off-Site Waste Receipt: | No |
| Universal Waste Indicator: | No |
| Universal Waste Destination Facility: | No |
| Federal Universal Waste: | No |
| Active Site State-Reg Handler: | --- |
| Federal Facility Indicator: | Not reported |
| Hazardous Secondary Material Indicator: | N |
| Sub-Part K Indicator: | Not reported |
| 2018 GPRA Permit Baseline: | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | No |
| Subject to Corrective Action Universe: | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | No |
| Corrective Action Priority Ranking: | No NCAPS ranking |
| Environmental Control Indicator: | No |
| Institutional Control Indicator: | No |
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20161101 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20081213 |
| Handler Name: CON EDISON | |
| Federal Waste Generator Description: | Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator |
| State District Owner: | Not reported |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20160601 |
| Handler Name: CON EDISON | |

**CON EDISON (Continued)** **1012185475**

| | |
|---|---|
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

List of NAICS Codes and Descriptions:

| | |
|---|---|
| NAICS Codes: | No NAICS Codes Found |

Facility Has Received Notices of Violations:

| | |
|---|---|
| Violations: | No Violations Found |

Evaluation Action Summary:

| | |
|---|---|
| Evaluations: | No Evaluations Found |

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004162822 |
| Country: | USA |
| Name: | Consolidated Edison |
| Address: | 6 OVERLOOK TER |
| Address 2: | Not reported |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Zip 4: | Not reported |
| Location Address 1: | 6 OVERLOOK TERRACE |
| Location Address 2: | Not reported |
| Location City,State,Zip: | MAMARONECK, NY 10538 |
| Location Zip 4: | Not reported |
| Facility Status: | Not reported |
| Total Tanks: | Not reported |
| Code: | BP |

Mailing:

| | |
|---|---|
| Mailing Name: | Consolidated Edison |
| Mailing Contact: | Franklyn Murray |
| Mailing Address 1: | 4 IRVING PLACE RM 828 |
| Mailing Address 2: | Not reported |
| Mailing City,State,Zip: | NEW YORK, NY 10003 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 2124602808 |

Manifest Data:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD006982359 |
| Year: | 2018 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 12/13/2008 |
| Trans1 Recv Date: | 12/13/2008 |

**CON EDISON (Continued)** **1012185475**

| | |
|---|---|
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 12/13/2008 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004162822 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NYD000705939 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 002012544FLE |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H135 |
| Waste Code a: | Benzene |
| Waste Code b: | Not reported |
| Waste Code c: | Not reported |
| Waste Code e: | Not reported |
| Waste Code f: | Not reported |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 20 |
| Units: | Gallons (liquids only) |
| Number of Containers: | 1 |
| Container Type: | Metal drums, barrels, kegs |
| Handling Method: | Treat |
| Specific Gravity: | 1 |

---

**Q88** **CON EDISON GAS DRIP 362** **RCRA NonGen / NLR** **1010787440**
**West** **6 OVERLOOK TERR GAS DRIP 362** **NYP004149621**
**1/8-1/4** **MAMARONECK, NY 10543**
**0.226 mi.**
**1195 ft.** **Site 2 of 2 in cluster Q**

**Relative:** **Higher**
**Actual:** **82 ft.**

RCRA Listings:

| | |
|---|---|
| Date Form Received by Agency: | 20080315 |
| Handler Name: | Con Edison Gas Drip 362 |
| Handler Address: | Overlook Terr Gas Drip 362 |
| Handler City,State,Zip: | MAMARONECK, NY 10543 |
| EPA ID: | NYP004149621 |
| Contact Name: | PAUL WALSH |
| Contact Address: | 4 IRVING PL, RM 828 |
| Contact City,State,Zip: | NEW YORK, NY 10003 |
| Contact Telephone: | 212-580-8383 |
| Contact Fax: | Not reported |

**CON EDISON GAS DRIP 362 (Continued)** **1010787440**

| | | |
|---|---|---|
| Contact Email: | | Not reported |
| Contact Title: | | Not reported |
| EPA Region: | | 02 |
| Land Type: | | Not reported |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | Ny |
| State District: | | NYSDEC R3 |
| Mailing Address: | | 4 IRVING PL, RM 828 |
| Mailing City,State,Zip: | | NEW YORK, NY 10003 |
| Owner Name: | Not reported | |
| Owner Type: | | Not reported |
| Operator Name: | Not reported | |
| Operator Type: | | Not reported |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| Corrective Action Priority Ranking: | | No NCAPS ranking |
| Environmental Control Indicator: | | No |
| Institutional Control Indicator: | | No |
| Human Exposure Controls Indicator: | | N/A |
| Groundwater Controls Indicator: | | N/A |
| Significant Non-Complier Universe: | | No |
| Unaddressed Significant Non-Complier Universe: | | No |
| Addressed Significant Non-Complier Universe: | | No |
| Significant Non-Complier With a Compliance Schedule Universe: | | No |
| Financial Assurance Required: | | Not reported |
| Handler Date of Last Change: | | 20150414 |
| Recognized Trader-Importer: | | No |
| Recognized Trader-Exporter: | | No |
| Importer of Spent Lead Acid Batteries: | | No |
| Exporter of Spent Lead Acid Batteries: | | No |
| Recycler Activity Without Storage: | | No |
| Manifest Broker: | | No |
| Sub-Part P Indicator: | | No |

**CON EDISON GAS DRIP 362 (Continued)** **1010787440**

Historic Generators:

| | | |
|---|---|---|
| Receive Date: | | 20080314 |
| Handler Name: | CON EDISON | |
| Federal Waste Generator Description: | | Not reported |
| State District Owner: | | Not reported |
| Large Quantity Handler of Universal Waste: | | No |
| Recognized Trader Importer: | | No |
| Recognized Trader Exporter: | | No |
| Spent Lead Acid Battery Importer: | | No |
| Spent Lead Acid Battery Exporter: | | No |
| Current Record: | | No |
| Non Storage Recycler Activity: | | Not reported |
| Electronic Manifest Broker: | | Not reported |

| | | |
|---|---|---|
| Receive Date: | | 20080315 |
| Handler Name: | CON EDISON GAS DRIP 362 | |
| Federal Waste Generator Description: | | Not a generator, verified |
| State District Owner: | | Ny |
| Large Quantity Handler of Universal Waste: | | No |
| Recognized Trader Importer: | | No |
| Recognized Trader Exporter: | | No |
| Spent Lead Acid Battery Importer: | | No |
| Spent Lead Acid Battery Exporter: | | No |
| Current Record: | | Yes |
| Non Storage Recycler Activity: | | Not reported |
| Electronic Manifest Broker: | | Not reported |

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

---

**R89** **PARK PLAZA LARCHMONT LLC** **NY UST U004177095**
**SSW** **3,5,7 EAST AVENUE** **NY AST N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.227 mi.**
**1200 ft.** **Site 1 of 3 in cluster R**

**Relative:**
**Higher**

**Actual:**
**52 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | PARK PLAZA LARCHMONT LLC |
| Address: | 3,5,7 EAST AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-171123 / Active |
| Operator Name: | James Van Dorn |
| Owner Name: | Park Plaza Larchmont, LLC |
| Owner Street: | 6001 Montrose Road |
| Owner Address2: | #606 |
| Owner City: | Rockville |
| Owner State: | MD |
| Owner Zipcode: | 20852 |
| GDS Number: | Not reported |

**PARK PLAZA LARCHMONT LLC (Continued)** **U004177095**

| | |
|---|---|
| Tank Number: | 1 |
| Status: | 4. Closed - in place |
| Capacity: | 4800 |
| Product Stored: | 0003. #6 Fuel Oil |
| Product Stored Percent: | 100 |
| Tank Leak Detection: | 0. None |
| Date Installation: | 01/01/1929 |
| Date Perm Closure: | 12/08/2011 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Piping |
| Piping Type: | 0. No Piping |
| Piping External Protection: | 0. None |
| Overfill Prevention: | 5. Vent Whistle |
| Piping Secondary Containment: | 0. None |
| Spill Prevention: | 0. None |
| Dispenser: | 0. None |

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | PARK PLAZA LARCHMONT LLC |
| Address: | 3,5,7 EAST AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-171123 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | James Van Dorn |
| Owner Name: | Park Plaza Larchmont, LLC |
| Owner Street: | 6001 Montrose Road |
| Owner Address2: | #606 |
| Owner City/State/Zip: | Rockville, MD 20852 |

| | |
|---|---|
| Tank Number: | 2 |
| Status: | 1. In-Service |
| Date Installation: | 04/01/2012 |
| Capacity: | 4500 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | 0 |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 6. Aboveground in subterranean vault with access for inspections |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 2. Manual Interstitial Monitoring |
| Tank Secondary Containment: | 2. Vault (w/ access) |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 0. None |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 5. Vent Whistle |
| Spill Prevention: | 1. Catch Basin |
| Dispenser: | 2. Suction |

**M90** **CARLSHIRE TENANTS INC.** **NY AST** **U003855728**
**WSW** **1-3 WASHINGTON SQUARE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.230 mi.**
**1213 ft.** **Site 7 of 8 in cluster M**

**Relative:** **Higher**
**Actual:** **53 ft.**

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | CARLSHIRE TENANTS INC. |
| Address: | 1-3 WASHINGTON SQUARE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-167185 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | Carlshire Tenants |
| Owner Name: | Carlshire Tenants Inc. |
| Owner Street: | 1-3 Washington Square |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | Larchmont, NY 10538 |
| | |
| Tank Number: | 2 |
| Status: | 1. In-Service |
| Date Installation: | 04/01/1997 |
| Capacity: | 7500 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 3. Aboveground on saddles,legs,stilts,racks or cradle |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | 2. Vault (w/ access) |
| Piping Location: | 3. Aboveground/Underground Combination |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 1. Painted/Asphalt Coating |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 4. Product Level Gauge (Aboveground Only) |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

---

**M91** **CARLSHIRE TENANTS INC.** **NY UST** **U004333716**
**WSW** **1-3 WASHINGTON SQUARE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.230 mi.**
**1213 ft.** **Site 8 of 8 in cluster M**

**Relative:** **Higher**
**Actual:** **53 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | CARLSHIRE TENANTS INC. |
| Address: | 1-3 WASHINGTON SQUARE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-167185 / Active |
| Operator Name: | Carlshire Tenants |
| Owner Name: | Carlshire Tenants Inc. |
| Owner Street: | 1-3 Washington Square |
| Owner Address2: | Not reported |
| Owner City: | Larchmont |
| Owner State: | NY |
| Owner Zipcode: | 10538 |
| GDS Number: | Not reported |

**CARLSHIRE TENANTS INC. (Continued)** **U004333716**

| | |
|---|---|
| Tank Number: | 1 |
| Status: | 3. Closed - Removed |
| Capacity: | 15000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 12/01/1955 |
| Date Perm Closure: | 04/01/1997 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 1. Painted/Asphalt Coating |
| Tank Secondary Containment: | 0. None |
| Piping Location: | 3. Aboveground/underground combination |
| Piping Type: | 1. Steel/Carbon/ steel/iron |
| Piping External Protection: | 0. None |
| Overfill Prevention: | Not reported |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 2. Suction |

---

**R92** **THE KEYSTONE** **NY AST** **A100395305**
**South** **76 WENDT AVENUE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.230 mi.**
**1213 ft.** **Site 2 of 3 in cluster R**

**Relative:** **Higher**

**Actual:** **53 ft.**

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | THE KEYSTONE |
| Address: | 76 WENDT AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-801206 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | Peter Hatzis |
| Owner Name: | Wendt Owners LLC |
| Owner Street: | 72 Wendt Avenue |
| Owner Address2: | Not reported |
| Owner City/State/Zip: | Larchmont, NY 10538 |
| | |
| Tank Number: | 76 |
| Status: | 1. In-Service |
| Date Installation: | 09/01/2004 |
| Capacity: | 2500 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 6. Aboveground in subterranean vault with access for inspections |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Leak Detection: | 6. Impervious Barrier/Concrete Pad (Aboveground Only) |
| Tank Secondary Containment: | 2. Vault (w/ access),10. Impervious Underlayment (AST Only) |
| Piping Location: | 1. Aboveground |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 0. None |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |

**THE KEYSTONE (Continued)** **A100395305**

| | |
|---|---|
| Overfill Prevention: | 5. Vent Whistle |
| Spill Prevention: | Not reported |
| Dispenser: | Not reported |

---

**O93** **LARCHMONT TERRACE CONDOMINIUM ASSOC. INC.** **NY UST** **U003886190**
**SW** **2 WASHINGTON SQUARE** **N/A**
**1/8-1/4** **LARCHMONT, NY 10538**
**0.232 mi.**
**1223 ft.** **Site 2 of 3 in cluster O**

**Relative:**
**Higher**

**Actual:**
**48 ft.**

WESTCHESTER CO. UST:

| | |
|---|---|
| Name: | LARCHMONT TERRACE CONDOMINIUM ASSOC. INC. |
| Address: | 2 WASHINGTON SQUARE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Id/Status: | 3-166146 / Active |
| Operator Name: | John Zivan |
| Owner Name: | Larchmont Terrace Condominium, Inc. |
| Owner Street: | 2 Washington Square |
| Owner Address2: | PO Box 750 |
| Owner City: | Larchmont |
| Owner State: | NY |
| Owner Zipcode: | 10538 |
| GDS Number: | Not reported |
| | |
| Tank Number: | 01 |
| Status: | 1. In-Service |
| Capacity: | 5000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 1. Electronic Interstitial Monitoring |
| Date Installation: | 04/01/1994 |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 5. Underground including vaulted with no access for inspection |
| Tank Type: | 4. Fiberglass coated steel |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 4. Fiberglass |
| Tank Secondary Containment: | 4. Double-Walled (underground only) |
| Piping Location: | 2. Underground/on Ground |
| Piping Type: | 2. Galvanized Steel |
| Piping External Protection: | 4. Fiberglass |
| Overfill Prevention: | 0. None |
| Piping Secondary Containment: | 4. Double-Walled (underground only) |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |
| | |
| Tank Number: | 1 |
| Status: | 3. Closed - Removed |
| Capacity: | 10000 |
| Product Stored: | Not reported |
| Product Stored Percent: | Not reported |
| Tank Leak Detection: | 0. None |
| Date Installation: | 10/01/1956 |
| Date Perm Closure: | 04/01/1994 |
| Tank Location: | 6. Underground, vaulted, with access |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |

**LARCHMONT TERRACE CONDOMINIUM ASSOC. INC. (Continued)** **U003886190**

| | |
|---|---|
| Tank Secondary Containment: | 0. None |
| Piping Location: | 0. No Pipiing |
| Piping Type: | 2. Galvanized steel |
| Piping External Protection: | 0. None |
| Overfill Prevention: | Not reported |
| Piping Secondary Containment: | Not reported |
| Spill Prevention: | Not reported |
| Dispenser: | 2. Suction |

---

**P94** **VALKENBURGH HOME** **NY LTANKS** **S108131410**
**NNW** **47 MAPLE HILL DRIVE** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.239 mi.**
**1263 ft.** **Site 2 of 2 in cluster P**

**Relative:** **Higher**

**Actual:** **89 ft.**

LTANKS:

| | |
|---|---|
| Name: | VALKENBURGH HOME |
| Address: | 47 MAPLE HILL DRIVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0606523 / 2007-01-04 |
| Facility ID: | 0606523 |
| Site ID: | 369884 |
| Spill Date: | 2006-09-07 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | Not reported |
| Reported to Dept: | 2006-09-07 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2006-09-07 |
| Spill Record Last Update: | 2007-01-04 |
| Spiller Name: | MARY ANN VAN VALKENBURGH |
| Spiller Company: | VALKENBURGH HOME |
| Spiller Address: | 47 MAPLE HILL DRIVE |
| Spiller County: | 001 |
| Spiller Contact: | MARY ANN VAN VALKENBURGH |
| Spiller Phone: | (914) 834-3978 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 319747 |
| Latitude: | 40.9390717 |
| Longitude: | -73.7593386 |
| DEC Memo: | (v.M.) Tank has been in house since 1988. Approximately 18 years ago (heating) was converted from coil to fuel. January 4, 2007: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 20.71 TONS OF CONTAMINATED SOIL. CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION PROVIDED, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod |
| Remarks: | 550 GALLON TANK HAD HOLES AND CONTAMINATION |

**VALKENBURGH HOME (Continued)** **S108131410**

All Materials:

| | |
|---|---|
| Site ID: | 369884 |
| Operable Unit ID: | 1127711 |
| Operable Unit: | 01 |
| Material ID: | 2117312 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**95**
**ESE**
**1/8-1/4**
**0.244 mi.**
**1288 ft.**

**CON EDISON - OVERHEAD TRANSFORMER POLE W** **NY Spills** **S121983820**
**6 VIRGINIA PL** **NY MANIFEST** **N/A**
**LARCHMONT, NY 10538**

**Relative:**
**Lower**

**Actual:**
**35 ft.**

SPILLS:

| | |
|---|---|
| Name: | CON ED TRANSFORMER POLE TOP |
| Address: | 6 VIRGINIA PLACE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1711072 / 2018-03-21 |
| Facility ID: | 1711072 |
| Facility Type: | ER |
| DER Facility ID: | 520994 |
| Site ID: | 567628 |
| DEC Region: | 3 |
| Spill Cause: | Storm |
| Spill Class: | C4 |
| SWIS: | 6032 |
| Spill Date: | 2018-03-06 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2018-03-06 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Transformer |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2018-03-06 |
| Spill Record Last Update: | 2018-03-21 |
| Spiller Name: | Not reported |
| Spiller Company: | CON ED |
| Spiller Address: | Not reported |
| Spiller Company: | 999 |
| Contact Name: | ERT |
| Latitude: | Not reported |
| Longitude: | Not reported |

**CON EDISON - OVERHEAD TRANSFORMER POLE W (Continued)** **S121983820**

DEC Memo: 03/06/18 excerpt form EMIS 264732, Distribution Splicer L1-2Richard A Ehring (00067) discovered 1
gallon of transformer oil spilled from overhead transformer on Pole W3 to soil/grass and concrete.
The transformer is hanging from the pole and oil is dripping from the unit at 6 drops per minute.
There was no Env Tag available at the time of the call. There were no visible non-PCB markings on
the unit. The control center will be notified. TG 03/21/18 Excerpt from EMIS 264732/3 3/9/2018 4:34
PM Crews double washed and removed patches of soil from the affected area. The old transformer was
removed and bagged and a new transformer was installed. Baxter, Brandon TG

Remarks: clean up pending crew

All Materials:

| | |
|---|---|
| Site ID: | 567628 |
| Operable Unit ID: | 1315532 |
| Operable Unit: | 01 |
| Material ID: | 2323240 |
| Material Code: | 0020A |
| Material Name: | transformer oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1.00 |
| Units: | G |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP005194162 |
| Country: | USA |
| Name: | Con Edison - Overhead Transformer Pole W |
| Address: | 6 VIRGINIA PL |
| Address 2: | Not reported |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Zip 4: | Not reported |
| Location Address 1: | 6 VIRGINIA PL |
| Location Address 2: | Not reported |
| Location City,State,Zip: | LARCHMONT, NY 10538 |
| Location Zip 4: | Not reported |
| Facility Status: | Not reported |
| Total Tanks: | Not reported |
| Code: | BP |

Mailing:

| | |
|---|---|
| Mailing Name: | Con Edison - Overhead Transformer Pole W |
| Mailing Contact: | Annamarie Moylan |
| Mailing Address 1: | 4 IRVING PLACE 15TH FL NE |
| Mailing Address 2: | Not reported |
| Mailing City,State,Zip: | NEW YORK, NY 10003 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 2124602278 |

**O96** **CON EDISON SERVICE BOX: 1119** **RCRA NonGen / NLR** **1016971971**
**SW** **178 MYRTLE BLVD** **NY MANIFEST** **NYP004457297**
**1/8-1/4** **MAMARONECK, NY 10543**
**0.244 mi.**
**1288 ft.** **Site 3 of 3 in cluster O**

**Relative:** **Lower**
**Actual:** **31 ft.**

RCRA Listings:

| | | |
|---|---|---|
| Date Form Received by Agency: | | 20140404 |
| Handler Name: | | Con Edison Service Box: 1119 |
| Handler Address: | | Myrtle Blvd |
| Handler City,State,Zip: | | MAMARONECK, NY 10543 |
| EPA ID: | | NYP004457297 |
| Contact Name: | | THOMAS TEELING |
| Contact Address: | | Not reported |
| Contact City,State,Zip: | | Not reported |
| Contact Telephone: | | 212-460-3770 |
| Contact Fax: | | Not reported |
| Contact Email: | | Not reported |
| Contact Title: | | SENIOR SCIENTIST |
| EPA Region: | | 02 |
| Land Type: | | Private |
| Federal Waste Generator Description: | | Not a generator, verified |
| Non-Notifier: | | Not reported |
| Biennial Report Cycle: | | Not reported |
| Accessibility: | | Not reported |
| Active Site Indicator: | | Not reported |
| State District Owner: | | Ny |
| State District: | | NYSDEC R2 |
| Mailing Address: | | IRVING PL, 15TH FL NE |
| Mailing City,State,Zip: | | NEW YORK, NY 10003 |
| Owner Name: | Not reported | |
| Owner Type: | | Not reported |
| Operator Name: | Not reported | |
| Operator Type: | | Not reported |
| Short-Term Generator Activity: | | No |
| Importer Activity: | | No |
| Mixed Waste Generator: | | No |
| Transporter Activity: | | No |
| Transfer Facility Activity: | | No |
| Recycler Activity with Storage: | | No |
| Small Quantity On-Site Burner Exemption: | | No |
| Smelting Melting and Refining Furnace Exemption: | | No |
| Underground Injection Control: | | No |
| Off-Site Waste Receipt: | | No |
| Universal Waste Indicator: | | No |
| Universal Waste Destination Facility: | | No |
| Federal Universal Waste: | | No |
| Active Site State-Reg Handler: | | --- |
| Federal Facility Indicator: | | Not reported |
| Hazardous Secondary Material Indicator: | | N |
| Sub-Part K Indicator: | | Not reported |
| 2018 GPRA Permit Baseline: | | Not on the Baseline |
| 2018 GPRA Renewals Baseline: | | Not on the Baseline |
| 202 GPRA Corrective Action Baseline: | | No |
| Subject to Corrective Action Universe: | | No |
| Non-TSDFs Where RCRA CA has Been Imposed Universe: | | No |
| Corrective Action Priority Ranking: | | No NCAPS ranking |
| Environmental Control Indicator: | | No |
| Institutional Control Indicator: | | No |

**CON EDISON SERVICE BOX: 1119 (Continued)** **1016971971**

| | |
|---|---|
| Human Exposure Controls Indicator: | N/A |
| Groundwater Controls Indicator: | N/A |
| Significant Non-Complier Universe: | No |
| Unaddressed Significant Non-Complier Universe: | No |
| Addressed Significant Non-Complier Universe: | No |
| Significant Non-Complier With a Compliance Schedule Universe: | No |
| Financial Assurance Required: | Not reported |
| Handler Date of Last Change: | 20141014 |
| Recognized Trader-Importer: | No |
| Recognized Trader-Exporter: | No |
| Importer of Spent Lead Acid Batteries: | No |
| Exporter of Spent Lead Acid Batteries: | No |
| Recycler Activity Without Storage: | No |
| Manifest Broker: | No |
| Sub-Part P Indicator: | No |

Historic Generators:

| | |
|---|---|
| Receive Date: | 20140304 |
| Handler Name: CON EDISON SERVICE BOX: | 1119 |
| Federal Waste Generator Description: | Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | No |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

| | |
|---|---|
| Receive Date: | 20140404 |
| Handler Name: CON EDISON SERVICE BOX: | 1119 |
| Federal Waste Generator Description: | Not a generator, verified |
| State District Owner: | Ny |
| Large Quantity Handler of Universal Waste: | No |
| Recognized Trader Importer: | No |
| Recognized Trader Exporter: | No |
| Spent Lead Acid Battery Importer: | No |
| Spent Lead Acid Battery Exporter: | No |
| Current Record: | Yes |
| Non Storage Recycler Activity: | Not reported |
| Electronic Manifest Broker: | Not reported |

List of NAICS Codes and Descriptions:

| | |
|---|---|
| NAICS Codes: | No NAICS Codes Found |

Facility Has Received Notices of Violations:

| | |
|---|---|
| Violations: | No Violations Found |

Evaluation Action Summary:

| | |
|---|---|
| Evaluations: | No Evaluations Found |

**CON EDISON SERVICE BOX: 1119 (Continued)** **1016971971**

NY MANIFEST:

| | |
|---|---|
| EPA ID: | NYP004457297 |
| Country: | USA |
| Name: | Con Ed |
| Address: | 178 MYRTLE BLVD |
| Address 2: | Not reported |
| City,State,Zip: | MAMARONECK, NY 10543 |
| Zip 4: | Not reported |
| Location Address 1: | FO 148 MYRTLE BLVD |
| Location Address 2: | SB 1119 |
| Location City,State,Zip: | MAMARONECK, NY 10538 |
| Location Zip 4: | Not reported |
| Facility Status: | Not reported |
| Total Tanks: | Not reported |
| Code: | BP |

Mailing:

| | |
|---|---|
| Mailing Name: | Con Ed |
| Mailing Contact: | Tom Teeling |
| Mailing Address 1: | 4 IRVING PLACE - 15TH FLOOR |
| Mailing Address 2: | Not reported |
| Mailing City,State,Zip: | NEW YORK, NY 10003 |
| Mailing Zip 4: | Not reported |
| Mailing Country: | USA |
| Mailing Phone: | 2124603770 |

Manifest Data:

| | |
|---|---|
| Document ID: | Not reported |
| Manifest Status: | Not reported |
| Trans1 State ID: | NYD006982359 |
| Year: | 2018 |
| Trans2 State ID: | Not reported |
| Generator Ship Date: | 03/04/2014 |
| Trans1 Recv Date: | 03/04/2014 |
| Trans2 Recv Date: | Not reported |
| TSD Site Recv Date: | 03/10/2014 |
| Part A Recv Date: | Not reported |
| Part B Recv Date: | Not reported |
| Generator EPA ID: | NYP004457297 |
| Trans1 EPA ID: | Not reported |
| Trans2 EPA ID: | Not reported |
| TSDF ID 1: | NJD002200046 |
| TSDF ID 2: | Not reported |
| Manifest Tracking Number: | 012772773JJK |
| Import Indicator: | N |
| Export Indicator: | N |
| Discr Quantity Indicator: | N |
| Discr Type Indicator: | N |
| Discr Residue Indicator: | N |
| Discr Partial Reject Indicator: | N |
| Discr Full Reject Indicator: | N |
| Manifest Ref Number: | Not reported |
| Alt Facility RCRA ID: | Not reported |
| Alt Facility Sign Date: | Not reported |
| MGMT Method Type Code: | H110 |
| Waste Code a: | Lead |
| Waste Code b: | Not reported |

**CON EDISON SERVICE BOX: 1119 (Continued)** **1016971971**

| | |
|---|---|
| Waste Code c: | Not reported |
| Waste Code e: | Not reported |
| Waste Code f: | Not reported |
| Waste Code g: | Not reported |
| Waste Code 1: | Not reported |
| Waste Code 2: | Not reported |
| Waste Code 3: | Not reported |
| Waste Code 4: | Not reported |
| Waste Code 5: | Not reported |
| Waste Code 6: | Not reported |
| Quantity: | 20 |
| Units: | Pounds |
| Number of Containers: | 1 |
| Container Type: | Cargo tanks (tank trucks) |
| Handling Method: | Treat |
| Specific Gravity: | 1 |

---

**S97** **SPILL NUMBER 9910464** **NY LTANKS** **S104620682**
**NE** **116 LAUREL AVE** **N/A**
**1/8-1/4** **LARCHMONT, NY**
**0.248 mi.**
**1312 ft.** **Site 1 of 2 in cluster S**

**Relative:** **Higher**

**Actual:** **49 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9910464 |
| Address: | 116 LAUREL AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9910464 / 2000-02-10 |
| Facility ID: | 9910464 |
| Site ID: | 283585 |
| Spill Date: | 1999-12-01 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-12-01 |
| CID: | 207 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-12-01 |
| Spill Record Last Update: | 2000-02-24 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | ANGELO CARDUCCI |
| Spiller Phone: | (914) 698-2460 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |

**SPILL NUMBER 9910464 (Continued)** **S104620682**

| | |
|---|---|
| DER Facility ID: | 230016 |
| Latitude: | 40.9385564 |
| Longitude: | -73.7553773 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/10/2000 TANK PASSED RETEST. NFA |
| Remarks: | tank contained #2 fuel no product leaked |

All TTF:

| | |
|---|---|
| Facility ID: | 9910464 |
| Spill Number: | 9910464 |
| Spill Tank Test: | 1547894 |
| Site ID: | 283585 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

---

**98**
**WSW**
**1/4-1/2**
**0.251 mi.**
**1326 ft.**

**COMMERCIAL PROPERTY - PBS TTF** **NY LTANKS** **S107658601**
**35 NORTH CHATSWORTH AVE** **N/A**
**LARCHMONT, NY**

**Relative:**
**Lower**

**Actual:**
**29 ft.**

LTANKS:

| | |
|---|---|
| Name: | UNKNOWN RESIDENCE |
| Address: | 35 NORTH CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0513382 / 2006-07-30 |
| Facility ID: | 0513382 |
| Site ID: | 359767 |
| Spill Date: | 2006-02-20 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Non Major Facility > 1,100 gal |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | WCDOH |
| Reported to Dept: | 2006-02-20 |
| CID: | 409 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2006-02-21 |

**COMMERCIAL PROPERTY - PBS TTF (Continued)** **S107658601**

| | |
|---|---|
| Spill Record Last Update: | 2006-07-30 |
| Spiller Name: | MARLON JOESPH |
| Spiller Company: | UNKNOWN RESIDENE |
| Spiller Address: | 35 NORTH CHATSWORTON AVE |
| Spiller County: | 001 |
| Spiller Contact: | MARLON JOESPH |
| Spiller Phone: | (718) 772-7949 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 309899 |
| Latitude: | 40.9346600 |
| Longitude: | -73.7631540 |
| DEC Memo: | Tank Test Failure July 30, 2006: Tank passed a retest after piping was repaired. Based upon information provided to DEC, no further action is required at this time |
| Remarks: | ABOVE LIQUID LEAK . |

All TTF:

| | |
|---|---|
| Facility ID: | 0513382 |
| Spill Number: | 0513382 |
| Spill Tank Test: | 1549742 |
| Site ID: | 359767 |
| Tank Number: | 1 |
| Tank Size: | 15000 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

| | |
|---|---|
| Facility ID: | 0513382 |
| Spill Number: | 0513382 |
| Spill Tank Test: | 1549743 |
| Site ID: | 359767 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 359767 |
| Operable Unit ID: | 1116960 |

**COMMERCIAL PROPERTY - PBS TTF (Continued)** **S107658601**

| | |
|---|---|
| Operable Unit: | 01 |
| Material ID: | 2107425 |
| Material Code: | 0002A |
| Material Name: | #4 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | COMMERCIAL PROPERTY - PBS TTF |
| Address: | 35 NORTH CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 2310041 / 2024-04-22 |
| Facility ID: | 2310041 |
| Site ID: | 664221 |
| Spill Date: | 2024-03-26 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODEE |
| Referred To: | Not reported |
| Reported to Dept: | 2024-03-26 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2024-03-26 |
| Spill Record Last Update: | 2024-04-22 |
| Spiller Name: | JOHN KARRAS - SITE SUPVR |
| Spiller Company: | COMMERCIAL PROPERTY |
| Spiller Address: | 35 NORTH CHATSWORTH AVE |
| Spiller County: | 999 |
| Spiller Contact: | Donnie Feeney |
| Spiller Phone: | (914) 449-6608 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 309899 |
| Latitude: | Not reported |
| Longitude: | Not reported |
| DEC Memo: | 3-26-24 Spoke to Norine from Innovative who stated that the external tank failed the tank test. She didn t have many details but stated Innovative was trying to fix the outer tank. I attempted to call John Karras but the call would not go through. Will attempt to call at a later time. CMO 03/27/24 Stefan Goreau from the WCDoH advised the facility to repair and retest or remove from service. TG 4/24/2024: Innovative Environmental reports the UST passed a retest after piping was repaired. Passing retest report received and uploaded to DecDocs. Reports were also submitted to WCDOH PBS unit. jod |

**COMMERCIAL PROPERTY - PBS TTF (Continued)** **S107658601**

Remarks: Internal tank test passed, external tank failed. Further investigation planned.

All TTF:

| | |
|---|---|
| Facility ID: | 2310041 |
| Spill Number: | 2310041 |
| Spill Tank Test: | 2515183 |
| Site ID: | 664221 |
| Tank Number: | 2 |
| Tank Size: | 15000 |
| Material: | 0001 |
| EPA UST: | False |
| UST: | True |
| Cause: | 00 |
| Source: | 01 |
| Test Method: | 34 |
| Test Method 2: | EZY 3 Locator Plus |
| Leak Rate: | Not reported |
| Gross Fail: | Not reported |
| Modified By: | JBODEE |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 664221 |
| Operable Unit ID: | 1411028 |
| Operable Unit: | 01 |
| Material ID: | 2428784 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**T99** **RESIDENCE** **NY LTANKS** **S104191487**
**NNW** **60 MAPLE HILL DR** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.251 mi.**
**1326 ft.** **Site 1 of 2 in cluster T**

**Relative: Higher**
**Actual: 88 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 60 MAPLE HILL DR |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9904648 / 1999-09-28 |
| Facility ID: | 9904648 |
| Site ID: | 254123 |
| Spill Date: | 1999-07-19 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |

**RESIDENCE (Continued)** **S104191487**

| | |
|---|---|
| Reported to Dept: | 1999-07-19 |
| CID: | 252 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-07-19 |
| Spill Record Last Update: | 1999-09-30 |
| Spiller Name: | MR THOMAS AMLICKE |
| Spiller Company: | RESIDENCE |
| Spiller Address: | 60 MAPLE HILL DR |
| Spiller County: | 001 |
| Spiller Contact: | MR THOMAS AMLICKE |
| Spiller Phone: | (914) 834-6299 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 208144 |
| Latitude: | 40.9387494 |
| Longitude: | -73.7607548 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 9/28/99 NORTHEAST ENVIRONMENTAL DISPOSED OF TANK AND 21.3 TONS OF SOIL. NFA |
| Remarks: | RECOMMEND EXCAVATE-ISOLATE AND RE-TEST. |

All TTF:

| | |
|---|---|
| Facility ID: | 9904648 |
| Spill Number: | 9904648 |
| Spill Tank Test: | 1547386 |
| Site ID: | 254123 |
| Tank Number: | Not reported |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 254123 |
| Operable Unit ID: | 1083412 |
| Operable Unit: | 01 |
| Material ID: | 300977 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |

**RESIDENCE (Continued)** **S104191487**

Recovered: .00
Oxygenate: Not reported

---

**U100** **SPILL NUMBER 0107991** **NY LTANKS** **S105230054**
**NNE** **21 EDGEWOOD AVE** **N/A**
**1/4-1/2** **MAMARONECK, NY**
**0.253 mi.**
**1335 ft.** **Site 1 of 2 in cluster U**

**Relative:**
**Higher**

**Actual:**
**80 ft.**

LTANKS:
Name: SPILL NUMBER 0107991
Address: 21 EDGEWOOD AVE
City,State,Zip: MAMARONECK, NY
Spill Number/Closed Date: 0107991 / 2002-02-28
Facility ID: 0107991
Site ID: 220664
Spill Date: 2001-11-06
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6032
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2001-11-06
CID: 207
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-11-06
Spill Record Last Update: 2002-03-20
Spiller Name: HAROLD PITTS
Spiller Company: FEIMAN
Spiller Address: 21 EDGEWOOD AVE
Spiller County: 001
Spiller Contact: HAROLD PITTS
Spiller Phone: (914) 969-1006
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 182529
Latitude: 40.9389817
Longitude: -73.7567586
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/28/2002 TAKE PRIDE DISPOSED OF 19.59 TONS OF SOIL. DEC INSPECTED SITE WITH H2M. NO FURTHER ACTION.
Remarks: contaminated soil found during tank removal

All Materials:
Site ID: 220664
Operable Unit ID: 845229
Operable Unit: 01
Material ID: 529248
Material Code: 0001A

**SPILL NUMBER 0107991 (Continued)** **S105230054**

| | |
|---|---|
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**V101** **RESI:BISNO** **NY LTANKS** **S104621790**
**NW** **53 HILLSIDE RD** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.256 mi.**
**1353 ft.** **Site 1 of 2 in cluster V**

**Relative:** **Higher**

**Actual:** **98 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESI:BISNO |
| Address: | 53 HILLSIDE RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0003197 / 2005-04-03 |
| Facility ID: | 0003197 |
| Site ID: | 257812 |
| Spill Date: | 2000-06-14 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C5 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2000-06-14 |
| CID: | 398 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2000-06-14 |
| Spill Record Last Update: | 2005-04-03 |
| Spiller Name: | ALLISON BISNO |
| Spiller Company: | RESI:BISNO |
| Spiller Address: | 53 HILLSIDE RD |
| Spiller County: | 001 |
| Spiller Contact: | ALLISON BISNO |
| Spiller Phone: | (212) 852-3686 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 211096 |
| Latitude: | 40.9376773 |
| Longitude: | -73.7624142 |
| DEC Memo: | 06/15/00 Letter sent to tank owner by John O'Dee outlining DEC procedures for closing spill and requesting call back. 04/03/05 NON-REGULATED TTF. NO RETEST OR CLOSURE INFORMATION SUBMITTED TO DEC. TANK TEST COMPANY IS NO LONGER IN BUSINESS. SPILL ADMINISTRATIVELY CLOSED AS PER DIRECTIVE FROM CENTRAL OFFICE. jod |
| Remarks: | GROSS FAILURE ON TANK. HOME OWNER WILL UNCOVER, ISOLATE AND RETEST |

**RESI:BISNO (Continued)** **S104621790**

TANK.

All TTF:

| | |
|---|---|
| Facility ID: | 0003197 |
| Spill Number: | 0003197 |
| Spill Tank Test: | 1525687 |
| Site ID: | 257812 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 257812 |
| Operable Unit ID: | 825400 |
| Operable Unit: | 01 |
| Material ID: | 551524 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**U102** **REISMAN RESIDENCE** **NY LTANKS** **S109064266**
**NNE** **24 EDGEWOOD AVE** **N/A**
**1/4-1/2** **MAMARONECK, NY**
**0.258 mi.**
**1362 ft.** **Site 2 of 2 in cluster U**

**Relative:**
**Higher**

**Actual:**
**89 ft.**

LTANKS:

| | |
|---|---|
| Name: | REISMAN RESIDENCE |
| Address: | 24 EDGEWOOD AVE |
| City,State,Zip: | MAMARONECK, NY |
| Spill Number/Closed Date: | 0800763 / 2008-07-08 |
| Facility ID: | 0800763 |
| Site ID: | 396571 |
| Spill Date: | 2008-04-18 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2008-04-18 |

**REISMAN RESIDENCE (Continued)** **S109064266**

| | |
|---|---|
| CID: | 408 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | Not reported |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2008-04-18 |
| Spill Record Last Update: | 2008-07-08 |
| Spiller Name: | MR. PHIL RICEMAN |
| Spiller Company: | PRIVATE HOME |
| Spiller Address: | 24 EDGEWOOD AVE |
| Spiller County: | 001 |
| Spiller Contact: | MR. PHIL RICEMAN |
| Spiller Phone: | (914) 337-6522 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 346050 |
| Latitude: | 40.9392716 |
| Longitude: | -73.7573186 |
| DEC Memo: | 4/18/08 Tank tested prior to home being put up for sale. House currently vacant. Unknown tank age, at least 25+ years. Tank to be pulled, contractors list given to contact, son-in-law of previous owner. jod 06/27/08 New England Tank Services reported that they abandoned in place one 1,000 gallon tank. They stated that the tank test failure may have been due to a rotted vent pipe. No petroleum contaminated soil was noted and the results of a soil sample were below DEC guidance values. Nfa. TG |
| Remarks: | RECOMMEND REMOVAL; |

All TTF:

| | |
|---|---|
| Facility ID: | 0800763 |
| Spill Number: | 0800763 |
| Spill Tank Test: | 2453548 |
| Site ID: | 396571 |
| Tank Number: | Not reported |
| Tank Size: | 1000 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | True |
| Cause: | 99 |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 396571 |
| Operable Unit ID: | 1153543 |
| Operable Unit: | 01 |
| Material ID: | 2144310 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |

**REISMAN RESIDENCE (Continued)** **S109064266**

| | |
|---|---|
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**S103** **SPILL NUMBER 9910463** **NY LTANKS** **S104620681**
**NE** **114 LAUREL AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.260 mi.**
**1372 ft.** **Site 2 of 2 in cluster S**

**Relative:**
**Higher**

**Actual:**
**49 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9910463 |
| Address: | 114 LAUREL AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9910463 / 2000-02-10 |
| Facility ID: | 9910463 |
| Site ID: | 171857 |
| Spill Date: | 1999-12-01 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-12-01 |
| CID: | 207 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-12-01 |
| Spill Record Last Update: | 2000-02-24 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | ANGELO CARDUCCI |
| Spiller Phone: | (914) 698-2460 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 144634 |
| Latitude: | 40.9386900 |
| Longitude: | -73.7552441 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/10/2000 TANK PASSED RETEST. NFA |
| Remarks: | gross fail tank contained #2 |

All TTF:

| | |
|---|---|
| Facility ID: | 9910463 |
| Spill Number: | 9910463 |

**SPILL NUMBER 9910463 (Continued)** **S104620681**

| | |
|---|---|
| Spill Tank Test: | 1547893 |
| Site ID: | 171857 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

---

**W104** **RESIDENCE** **NY LTANKS** **S102618923**
**SE** **9 SUMMIT AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.263 mi.**
**1387 ft.** **Site 1 of 2 in cluster W**

**Relative:** **Higher**
**Actual:** **54 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 9 SUMMIT AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9702679 / 1997-08-08 |
| Facility ID: | 9702679 |
| Site ID: | 229293 |
| Spill Date: | 1997-06-02 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1997-06-02 |
| CID: | 233 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1997-06-02 |
| Spill Record Last Update: | 1997-10-14 |
| Spiller Name: | JIM ROOD |
| Spiller Company: | Not reported |
| Spiller Address: | 9 SUMMIT AVE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 189044 |

**RESIDENCE (Continued)** **S102618923**

Latitude: 40.9328915
Longitude: -73.7546522
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 08/08/97 TTF; NES REMOVED THE TANK AND CONTAMINATED SOIL; ONLY THREE TONS OF SOIL WERE FOUND;
Remarks: home heating system was tested and failed jim rood will be contacting nes and will make plans to remove tank

All TTF:
Facility ID: 9702679
Spill Number: 9702679
Spill Tank Test: 1545143
Site ID: 229293
Tank Number: 1
Tank Size: 275
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 229293
Operable Unit ID: 1045404
Operable Unit: 01
Material ID: 335612
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

**R105** **WACHOVIA BANK** **NY LTANKS** **S106471628**
**SSW** **1940 PALMER AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.264 mi.**
**1392 ft.** **Site 3 of 3 in cluster R**

**Relative: Higher**
**Actual: 51 ft.**

LTANKS:
Name: WACHOVIA BANK
Address: 1940 PALMER AVE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 0401512 / 2004-11-18
Facility ID: 0401512
Site ID: 173845
Spill Date: 2004-05-12
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial

**WACHOVIA BANK (Continued)** **S106471628**

| | |
|---|---|
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODEE |
| Referred To: | WESTCHESTER CNTY HEALTH D |
| Reported to Dept: | 2004-05-12 |
| CID: | 407 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-05-12 |
| Spill Record Last Update: | 2024-11-22 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | DOUG NEWTON |
| Spiller Phone: | (610) 941-9700 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 146229 |
| Latitude: | 40.9317577 |
| Longitude: | -73.7597809 |
| DEC Memo: | 11/22/04: Letter to Steven A. Colton, Sr. VP, Wachovia Bank, dated 18Nov2004. Spill closed by Stefan Goreau, WCDOH. |
| Remarks: | Dry leak, they believe its a manhole cover or line problem. They will redo the manhole cover and do a tank only test. |

All TTF:

| | |
|---|---|
| Facility ID: | 0401512 |
| Spill Number: | 0401512 |
| Spill Tank Test: | 1529256 |
| Site ID: | 173845 |
| Tank Number: | 1 |
| Tank Size: | 1500 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

**106**
**WNW**
**1/4-1/2**
**0.269 mi.**
**1418 ft.**

**SPILL NUMBER 9806441**
**26 HILLSIDE ROAD**
**LARCHMONT, NY**

**NY LTANKS** **S104619658**
**N/A**

**Relative:**
**Higher**

**Actual:**
**91 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9806441 |
| Address: | 26 HILLSIDE ROAD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9806441 / 1998-09-08 |
| Facility ID: | 9806441 |
| Site ID: | 107995 |
| Spill Date: | 1998-08-25 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1998-08-25 |
| CID: | 266 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-08-25 |
| Spill Record Last Update: | 1998-10-02 |
| Spiller Name: | ARTHUR BLANCO |
| Spiller Company: | ARTHUR BLANCO |
| Spiller Address: | 26 HILLSIDE ROAD |
| Spiller County: | 001 |
| Spiller Contact: | ARTHUR BLANCO |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 94936 |
| Latitude: | 40.9370687 |
| Longitude: | -73.7636253 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY |
| Remarks: | SPILLER'S WORK PHONE NUMBER (914) 381-9700. HOLES FOUND IN 550 GALLON UNDERGROUND STORAGE TANK DURING REMOVAL. TANK STILL BEING REMOVED. SOIL TO BE STOCKPILED AS NECESSARY. |

All Materials:

| | |
|---|---|
| Site ID: | 107995 |
| Operable Unit ID: | 1067629 |
| Operable Unit: | 01 |
| Material ID: | 317596 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |

**SPILL NUMBER 9806441 (Continued)** **S104619658**

Recovered: .00
Oxygenate: Not reported

---

**107**
**SSE**
**1/4-1/2**
**0.271 mi.**
**1431 ft.**

**SPILL NUMBER 9903173**
**26 SUMMITT AVE**
**LARCHMONT, NY**

**NY LTANKS** **S104620271**
**N/A**

**Relative:**
**Higher**

**Actual:**
**58 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9903173 |
| Address: | 26 SUMMITT AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9903173 / 1999-07-27 |
| Facility ID: | 9903173 |
| Site ID: | 66265 |
| Spill Date: | 1999-06-18 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-06-18 |
| CID: | 312 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-06-18 |
| Spill Record Last Update: | 1999-08-04 |
| Spiller Name: | OLAFSON |
| Spiller Company: | Not reported |
| Spiller Address: | 26 SUMMITT AVE |
| Spiller County: | 001 |
| Spiller Contact: | OLAFSON |
| Spiller Phone: | (914) 834-5586 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 63479 |
| Latitude: | 40.9317939 |
| Longitude: | -73.7556111 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 6/18/99 PER NES--DURING TANK REPLACEMENT HOLES WERE NOTED IN A/G 275 GALLON OUTSIDE OF HOUSE. NEW TANK INSTALLED IN BASEMENT. NES DOING CLEANUP. 7/27/99 NES REMOVED TANK AND 70 TONS OF CONTAMINATED SOIL. CLEANUP COMPLETE. NFA |
| Remarks: | 275GAL UST HAD FAILED - REMOVING THE TANK AND CONTAMINATED SOIL |

All Materials:

| | |
|---|---|
| Site ID: | 66265 |
| Operable Unit ID: | 1077780 |
| Operable Unit: | 01 |

**SPILL NUMBER 9903173 (Continued)** **S104620271**

| | |
|---|---|
| Material ID: | 303099 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**108**
**NW**
**1/4-1/2**
**0.275 mi.**
**1451 ft.**

**PRIVATE RESIDENCE**
**125 MURRAY AVE**
**LARCHMONT, NY**

**NY LTANKS** **S106385783**
**N/A**

**Relative:**
**Higher**

**Actual:**
**96 ft.**

LTANKS:

| | |
|---|---|
| Name: | PRIVATE RESIDENCE |
| Address: | 125 MURRAY AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0400156 / 2004-06-16 |
| Facility ID: | 0400156 |
| Site ID: | 158874 |
| Spill Date: | 2004-04-06 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-04-06 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-04-06 |
| Spill Record Last Update: | 2004-06-16 |
| Spiller Name: | BRUCE LEBLIN-REALTY |
| Spiller Company: | PRIVATE RESIDENCE |
| Spiller Address: | 125 MURRAY AVE |
| Spiller County: | 001 |
| Spiller Contact: | BRUCE LEBLIN-REALTY |
| Spiller Phone: | (914) 946-7100 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 134259 |
| Latitude: | 40.9386803 |
| Longitude: | -73.7618728 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 6-10-04 Letter rec'd from Northeast Environmental. They removed the tank and reported that no contamintion was found in the tank excavation. NFA TG |

**PRIVATE RESIDENCE (Continued)** **S106385783**

Remarks: recommendation: has pedromidator on it they recommend they take it off and retest:

All Materials:

| | |
|---|---|
| Site ID: | 158874 |
| Operable Unit ID: | 884578 |
| Operable Unit: | 01 |
| Material ID: | 494945 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**T109** **RESIDENCE** **NY LTANKS** **S100878804**
**NNW** **8 ORSINI DRIVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.279 mi.**
**1475 ft.** **Site 2 of 2 in cluster T**

**Relative:** **Higher**

**Actual:** **88 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 8 ORSINI DRIVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9312714 / 1995-01-19 |
| Facility ID: | 9312714 |
| Site ID: | 99667 |
| Spill Date: | 1994-01-28 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | 1995-01-19 |
| SWIS: | 6000 |
| Investigator: | MALONE |
| Referred To: | Not reported |
| Reported to Dept: | 1994-01-28 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Health Department |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1994-02-07 |
| Spill Record Last Update: | 1995-01-19 |
| Spiller Name: | Not reported |
| Spiller Company: | GERARD AUERCIOLI |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |

**RESIDENCE (Continued)** **S100878804**

DER Facility ID: 88541
Latitude: 40.9393008
Longitude: -73.7609346
DEC Memo: Not reported
Remarks: OLD U/G TANK TAKING ON WATER AND LEAKING UP THROUGH GROUND CONTRACTOR TO REMOVE U/G TANK WCHD ON SITE AND WILL UPDATE AS NEEDED

All Materials:
Site ID: 99667
Operable Unit ID: 994700
Operable Unit: 01
Material ID: 388130
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

---

**110 ESE 1/4-1/2 0.285 mi. 1504 ft.** **YAHIA RESIDENCE** **NY LTANKS** **S107789426**
**17 HALL AVE** **N/A**
**LARCHMONT, NY**

**Relative: Lower**
**Actual: 29 ft.**

LTANKS:
Name: YAHIA RESIDENCE
Address: 17 HALL AVE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 0602686 / 2007-01-03
Facility ID: 0602686
Site ID: 365228
Spill Date: 2006-05-22
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: B4
Cleanup Ceased: Not reported
SWIS: 6032
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2006-06-09
CID: 409
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2006-06-09
Spill Record Last Update: 2007-01-03
Spiller Name: TIM FIRLA
Spiller Company: YAHIA RESIDENCE
Spiller Address: 17 HALL AVE
Spiller County: 001

**YAHIA RESIDENCE (Continued)** **S107789426**

| | |
|---|---|
| Spiller Contact: | TIM FIRLA |
| Spiller Phone: | (203) 384-6020 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 314413 |
| Latitude: | 40.9331617 |
| Longitude: | -73.7535486 |
| DEC Memo: | 06/12/06: THERE IS ANOTHER SPILL # FOR THIS SITE 0601851 - J. O'DEE HAS BEEN CALLED VIA THE CALLER. GW HAS BEEN IMPACTED WITH FREE PRODCUT. (#2F/O) - RA January 3, 2007: CONNECTICUT TANK REMOVAL DISPOSED OF LUST AND 351.26 TONS OF CONTAMINATED SOIL. GROUND WATER WAS IMPACTED, AND A MONITORING WELL WAS INSTALLED AND SAMPLED. CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION PROVIDED, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod |
| Remarks: | THE TANK WAS PUMPED AOUT AND THEN REMOVED AND THEN THE SOIL WAS TESTED. THEY WILL DO A REMIDIATION THERE. TIM WOULD LIKE A CALL BACK. |

All Materials:

| | |
|---|---|
| Site ID: | 365228 |
| Operable Unit ID: | 1123238 |
| Operable Unit: | 01 |
| Material ID: | 2112711 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | YAHIA HOME |
| Address: | 17 HALL AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0601851 / 2007-01-03 |
| Facility ID: | 0601851 |
| Site ID: | 364200 |
| Spill Date: | 2006-05-19 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | Not reported |
| Reported to Dept: | 2006-05-19 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2006-05-19 |
| Spill Record Last Update: | 2007-01-03 |
| Spiller Name: | DORIS YAHIA |

**YAHIA RESIDENCE (Continued)** **S107789426**

| | |
|---|---|
| Spiller Company: | YAHIA HOME |
| Spiller Address: | 17 HALL AVE |
| Spiller County: | 001 |
| Spiller Contact: | DORIS YAHIA |
| Spiller Phone: | (914) 318-2798 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 314413 |
| Latitude: | 40.9331617 |
| Longitude: | -73.7535486 |
| DEC Memo: | 05/23/06: J. O'DEE TO DISCUSS FINDINGS. SAMPLES WERE TAKEN FROM EXCAVATION AND HOLE WAS BACKFILLED PENDING SIGNATURE OF CONTRACT TO COMPLETE CLEAN UP. ALSO SPILL 06-02686 January 3, 2007: CONNECTICUT TANK REMOVAL DISPOSED OF LUST AND 351.26 TONS OF CONTAMINATED SOIL. GROUND WATER WAS IMPACTED, AND A MONITORING WELL WAS INSTALLED AND SAMPLED. CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION PROVIDED, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod |
| Remarks: | 1000 GALLON TANK HAD HOLES : |

All Materials:

| | |
|---|---|
| Site ID: | 364200 |
| Operable Unit ID: | 1122234 |
| Operable Unit: | 01 |
| Material ID: | 2111707 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**111 East 1/4-1/2 0.287 mi. 1517 ft.** **CARRIER RESIDENCE** **NY LTANKS** **S106000095**
**45 CARLEON AV** **N/A**
**LARCHMONT, NY**

**Relative: Higher**
**Actual: 41 ft.**

LTANKS:

| | |
|---|---|
| Name: | CARRIER RESIDENCE |
| Address: | 45 CARLEON AV |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0307038 / 2003-11-20 |
| Facility ID: | 0307038 |
| Site ID: | 174655 |
| Spill Date: | 2003-10-03 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2003-10-03 |
| CID: | 297 |
| Water Affected: | Not reported |

**CARRIER RESIDENCE (Continued)** **S106000095**

| | |
|---|---|
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-10-03 |
| Spill Record Last Update: | 2003-11-20 |
| Spiller Name: | CHRISTINA CARRIER |
| Spiller Company: | Not reported |
| Spiller Address: | 45 CARLEON AV |
| Spiller County: | 001 |
| Spiller Contact: | JENEEN CIANFLONE |
| Spiller Phone: | (914) 741-5472 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 146873 |
| Latitude: | 40.9348549 |
| Longitude: | -73.7521208 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/20/03 NES DISPOSED OF LUST AND 33.30 TONS OF CONTAMINATED SOIL. |
| Remarks: | CALLERS COMPANY REMOVING A 550 GALLON INGROUND TANK, SOIL CONTAMINATION AND HOLES IN THE TANK DISCOVERED |

All Materials:

| | |
|---|---|
| Site ID: | 174655 |
| Operable Unit ID: | 873589 |
| Operable Unit: | 01 |
| Material ID: | 500625 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**V112** **ALPERT HOME** **NY LTANKS** **S109064205**
**WNW** **80 LOOKOUT CIRCLE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.289 mi.**
**1525 ft.** **Site 2 of 2 in cluster V**

**Relative:** **Higher**
**Actual:** **115 ft.**

LTANKS:

| | |
|---|---|
| Name: | ALPERT HOME |
| Address: | 80 LOOKOUT CIRCLE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0713708 / 2009-08-31 |
| Facility ID: | 0713708 |
| Site ID: | 395508 |
| Spill Date: | 2008-03-27 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |

**ALPERT HOME (Continued)** **S109064205**

| | |
|---|---|
| SWIS: | 6034 |
| Investigator: | JBODEE |
| Referred To: | Not reported |
| Reported to Dept: | 2008-03-27 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | Not reported |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2008-03-27 |
| Spill Record Last Update: | 2019-11-07 |
| Spiller Name: | RICHARD ALPERT |
| Spiller Company: | ALPERT HOME |
| Spiller Address: | 80 LOOKOUT CIRCLE |
| Spiller County: | 001 |
| Spiller Contact: | RICHARD ALPERT |
| Spiller Phone: | (347) 248-5285 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 345028 |
| Latitude: | 40.9378217 |
| Longitude: | -73.7632786 |
| DEC Memo: | 8/31/2009 -- No test method provided; likely to be inappropriate. WCDOH would have required further testing. NFA at this time. ELM |
| Remarks: | UNCOVER AND RETEST |

All TTF:

| | |
|---|---|
| Facility ID: | 0713708 |
| Spill Number: | 0713708 |
| Spill Tank Test: | 2384916 |
| Site ID: | 395508 |
| Tank Number: | Not reported |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | True |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 395508 |
| Operable Unit ID: | 1152445 |
| Operable Unit: | 01 |
| Material ID: | 2143222 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |

**ALPERT HOME (Continued)** **S109064205**

Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

**W113** **SPILL NUMBER 0011319** **NY LTANKS** **S104950556**
**SE** **14 HALL AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.292 mi.**
**1542 ft.** **Site 2 of 2 in cluster W**

**Relative:** LTANKS:
**Lower**
**Actual:** Name: SPILL NUMBER 0011319
**37 ft.** Address: 14 HALL AVE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 0011319 / 2001-04-11
Facility ID: 0011319
Site ID: 184309
Spill Date: 2001-01-17
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6000
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2001-01-17
CID: 207
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-01-17
Spill Record Last Update: 2001-04-24
Spiller Name: JAY LUBIN
Spiller Company: Not reported
Spiller Address: 14 HALL AVE
Spiller County: 001
Spiller Contact: JAY LUBIN
Spiller Phone: (914) 833-2686
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 154247
Latitude: 40.9329278
Longitude: -73.7538438
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/11/2001 NORTHEAST DISPOSED OF TANK AND 23.63 TONS OF CONTAMINATED SOIL. NO FURTHER ACTION.
Remarks: contaminated soil found upon tank removal

All Materials:
Site ID: 184309
Operable Unit ID: 832716
Operable Unit: 01

**SPILL NUMBER 0011319 (Continued)** **S104950556**

| | |
|---|---|
| Material ID: | 541639 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**X114** **BLONDIE'S TREEHOUSE** **NY LTANKS** **S104621434**
**SSW** **21 NORTH AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.301 mi.**
**1588 ft.** **Site 1 of 3 in cluster X**

**Relative:** **Lower**
**Actual:** **40 ft.**

LTANKS:

| | |
|---|---|
| Name: | BLONDIE'S TREEHOUSE |
| Address: | 21 NORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0000712 / 2000-08-08 |
| Facility ID: | 0000712 |
| Site ID: | 175577 |
| Spill Date: | 2000-04-18 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2000-04-18 |
| CID: | 371 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2000-04-18 |
| Spill Record Last Update: | 2000-08-09 |
| Spiller Name: | Not reported |
| Spiller Company: | BLONDIE'S TREEHOUSE |
| Spiller Address: | 21 NORTH AVE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 147611 |
| Latitude: | 40.9317810 |
| Longitude: | -73.7611108 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE |
| Remarks: | FOUND CONTAMINATED SOIL AND HOLES IN TANK WHILE PULLING A 550 GAL UST. Not reported |

**BLONDIE'S TREEHOUSE (Continued)** **S104621434**

All Materials:

| | |
|---|---|
| Site ID: | 175577 |
| Operable Unit ID: | 822442 |
| Operable Unit: | 01 |
| Material ID: | 288951 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**X115** **SPILL NUMBER 9914491** **NY LTANKS** **S104620938**
**SSW** **21 NORTH AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.301 mi.**
**1588 ft.** **Site 2 of 3 in cluster X**

**Relative:** **Lower**

**Actual:** **40 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9914491 |
| Address: | 21 NORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9914491 / 2002-06-29 |
| Facility ID: | 9914491 |
| Site ID: | 175578 |
| Spill Date: | 2000-03-22 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2000-03-23 |
| CID: | 312 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2000-03-23 |
| Spill Record Last Update: | 2003-08-05 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | 21 NORTH AVE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 147611 |
| Latitude: | 40.9317810 |

**SPILL NUMBER 9914491 (Continued)** **S104620938**

| | |
|---|---|
| Longitude: | -73.7611108 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/29/02 NES PULLED TANK AND COMPLETED CLEAN UP. ALSO SPILL 01-10895. |
| Remarks: | EITHER 550 OR 1000 GAL TANK - TANK IS UNDER CONCRETE |

All TTF:

| | |
|---|---|
| Facility ID: | 9914491 |
| Spill Number: | 9914491 |
| Spill Tank Test: | 1548155 |
| Site ID: | 175578 |
| Tank Number: | 001 |
| Tank Size: | 550 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 16 |
| Test Method 2: | Tracer Tight |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

---

**Y116** **PHIL LEBOWITZ** **NY LTANKS** **S116156779**
**NNW** **12 ORSINI DRIVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.302 mi.**
**1597 ft.** **Site 1 of 2 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**88 ft.**

LTANKS:

| | |
|---|---|
| Name: | PHIL LEBOWITZ |
| Address: | 12 ORSINI DRIVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1309250 / 2014-03-17 |
| Facility ID: | 1309250 |
| Site ID: | 490038 |
| Spill Date: | 2013-12-18 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODEE |
| Referred To: | Not reported |
| Reported to Dept: | 2013-12-18 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2013-12-18 |
| Spill Record Last Update: | 2014-03-17 |

**PHIL LEBOWITZ (Continued)** **S116156779**

| | |
|---|---|
| Spiller Name: | PHIL LEBOWITZ |
| Spiller Company: | PHIL LEBOWITZ |
| Spiller Address: | 12 ORSINI DR |
| Spiller County: | 999 |
| Spiller Contact: | PHIL LEBOWITZ |
| Spiller Phone: | (914) 834-6347 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 445128 |
| Latitude: | 40.9394417 |
| Longitude: | -73.7614286 |
| DEC Memo: | Tank test failure at private home...mm 3/17/2014: Northeast Environmental removed and disposed of the UST. No evidence of a leak or of petroleum contamination was found. Tank Closure report reviewed and entered into eDocs. Based upon information provided to DEC, no further action is required at this time. jod |
| Remarks: | 550 test failure |

All TTF:

| | |
|---|---|
| Facility ID: | 1309250 |
| Spill Number: | 1309250 |
| Spill Tank Test: | 2495195 |
| Site ID: | 490038 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | False |
| UST: | True |
| Cause: | 04 |
| Source: | 04 |
| Test Method: | 21 |
| Test Method 2: | Horner EZY3/EZY3 Locator Plus |
| Leak Rate: | Not reported |
| Gross Fail: | Not reported |
| Modified By: | JBODEE |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 490038 |
| Operable Unit ID: | 1239604 |
| Operable Unit: | 01 |
| Material ID: | 2239652 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

**X117** **UNITED ARTISTS THEATER** **NY LTANKS** **S101102348**
**SSW** **1975 PALMER AVE.** **NY Spills** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.313 mi.**
**1653 ft.** **Site 3 of 3 in cluster X**

**Relative:**
**Higher**

**Actual:**
**45 ft.**

LTANKS:

| | |
|---|---|
| Name: | UNITED ARTISTS THEATER |
| Address: | 1975 PALMER AVE. |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9401111 / 2001-03-12 |
| Facility ID: | 9401111 |
| Site ID: | 323532 |
| Spill Date: | 1994-04-22 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1994-04-22 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1994-05-04 |
| Spill Record Last Update: | 2001-03-27 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 260632 |
| Latitude: | 40.9310699 |
| Longitude: | -73.7611597 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST. NOVEMBER 1995 - ENSA UST REMOVAL REPORT SUBMITTED DOCUMENTING THAT 2K TANK WAS REMOVED IN OCTOBER OF 1995. NO FURTHER ACTION BASED ON INFO FROM THAT REPORT. |
| Remarks: | E.I.R. PETRO-TITE -.499 |

All TTF:

| | |
|---|---|
| Facility ID: | 9401111 |
| Spill Number: | 9401111 |
| Spill Tank Test: | 1542643 |
| Site ID: | 323532 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | 0001 |
| EPA UST: | Not reported |

**UNITED ARTISTS THEATER (Continued)** **S101102348**

| | |
|---|---|
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 323532 |
| Operable Unit ID: | 994949 |
| Operable Unit: | 01 |
| Material ID: | 384880 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | L |
| Recovered: | .00 |
| Oxygenate: | Not reported |

SPILLS:

| | |
|---|---|
| Name: | UNITED ARTISTS THEATER |
| Address: | 1975 PALMER AVE. |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9301021 / 1994-12-08 |
| Facility ID: | 9301021 |
| Facility Type: | ER |
| DER Facility ID: | 260632 |
| Site ID: | 323531 |
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | C3 |
| SWIS: | 6000 |
| Spill Date: | 1993-04-20 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1993-04-21 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Commercial/Industrial |
| Spill Notifier: | Other |
| Cleanup Ceased: | 1994-12-08 |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1993-04-22 |
| Spill Record Last Update: | 1994-12-08 |
| Spiller Name: | Not reported |
| Spiller Company: | SAUCE & VIJAX OIL CO. |

**UNITED ARTISTS THEATER (Continued)** **S101102348**

| | |
|---|---|
| Spiller Address: | Not reported |
| Spiller Company: | 001 |
| Contact Name: | Not reported |
| Latitude: | 40.9310699 |
| Longitude: | -73.7611597 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 12/08/94: CONTAM. SOIL REMOVED AND SAMPLES WHERE TAKEN. |
| Remarks: | CONTRACT HAULERS MAKING DELIVERIES FOR SOME TIME CUSTOMER CALLED RELIANCE ASSOC. COMPLANING ABOUT THE SPILLS OCCURRING EACH DELIVERY CALLER CLAIMS VENT WHISTLE NOT WORKING NOT SURE IF WHISTLE EXISTS |

All Materials:

| | |
|---|---|
| Site ID: | 323531 |
| Operable Unit ID: | 979623 |
| Operable Unit: | 01 |
| Material ID: | 561763 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | Not reported |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**118**
**South**
**1/4-1/2**
**0.320 mi.**
**1689 ft.**

**YOUNG HOME** **NY LTANKS** **S108131336**
**6 ROCKHILL TERRACE** **N/A**
**LARCHMONT, NY**

**Relative: Higher**

**Actual: 59 ft.**

LTANKS:

| | |
|---|---|
| Name: | YOUNG HOME |
| Address: | 6 ROCKHILL TERRACE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0606153 / 2012-08-17 |
| Facility ID: | 0606153 |
| Site ID: | 369457 |
| Spill Date: | 2006-08-29 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODEE |
| Referred To: | Not reported |
| Reported to Dept: | 2006-08-29 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2006-08-29 |

**YOUNG HOME (Continued)** **S108131336**

| | |
|---|---|
| Spill Record Last Update: | 2024-07-03 |
| Spiller Name: | LOU YOUNG |
| Spiller Company: | YOUNG HOME |
| Spiller Address: | 6 ROCKHILL TERRACE |
| Spiller County: | 001 |
| Spiller Contact: | LOU YOUNG |
| Spiller Phone: | (914) 833-7966 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 319337 |
| Latitude: | 40.9305917 |
| Longitude: | -73.7593086 |
| DEC Memo: | 8/2/10 Homeowner TTF JO'M 8/17/12 Homeomer TTF greater then 5 years old and no indications of contamination will be closed. This was done with consultations between Albany and the Region. NFA JO'M |
| Remarks: | UNCOVER REPAIR AND TEST |

All TTF:

| | |
|---|---|
| Facility ID: | 0606153 |
| Spill Number: | 0606153 |
| Spill Tank Test: | 1550235 |
| Site ID: | 369457 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 369457 |
| Operable Unit ID: | 1127294 |
| Operable Unit: | 01 |
| Material ID: | 2116886 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**119**
**NE**
**1/4-1/2**
**0.320 mi.**
**1690 ft.**

**DILIETO HOME**
**104 LAUREL AVE**
**LARCHMONT, NY**

**NY LTANKS** **S106971904**
**N/A**

**Relative:**
**Higher**

**Actual:**
**49 ft.**

LTANKS:

| | |
|---|---|
| Name: | DILIETO HOME |
| Address: | 104 LAUREL AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0502224 / 2006-08-11 |
| Facility ID: | 0502224 |
| Site ID: | 346541 |
| Spill Date: | 2005-05-25 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | Not reported |
| Reported to Dept: | 2005-05-25 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2005-05-25 |
| Spill Record Last Update: | 2006-08-11 |
| Spiller Name: | DILIETO HOME |
| Spiller Company: | DILIETO HOME |
| Spiller Address: | 104 LAUREL AVE |
| Spiller County: | 001 |
| Spiller Contact: | DILIETO HOME |
| Spiller Phone: | (347) 672-0146 |
| Spiller Extention: | CELL |
| DEC Region: | 3 |
| DER Facility ID: | 292801 |
| Latitude: | 40.9392850 |
| Longitude: | -73.7544870 |
| DEC Memo: | 5/25/05 NES REMOVED ONE 550 GALLON LUST. NES SUBMITTED PROPOSAL FOR REMEDIATION. jod 6/10/05 NES RETURNED TO SITE AND REMOVED AND DISPOSED OF 2.15 TONS OF STOCKPILED CONTAMINATED SOIL. TANK GRAVE HAD ALREADY BEEN BACKFILLED. UNKNOWN IF ALL CONTAMINATION WAS EXCAVATED OR IF ANY EXIT SAMPLES TAKEN AT THIS TIME. KEVIN MOORE OF MAMARONECK BLDG DEPT TO FOLLOW UP. jod August 11, 2006: NES DISPOSED OF LUST AND 2.15 TONS OF CONTAMINATED SOIL. CLOSURE REPORT RECEIVED FROM S.I.T.E.S. REMEDIATION. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod |
| Remarks: | 550 gallon tank had holes in it found while removing |

All Materials:

| | |
|---|---|
| Site ID: | 346541 |
| Operable Unit ID: | 1104310 |
| Operable Unit: | 01 |
| Material ID: | 584489 |
| Material Code: | 0001A |

**DILIETO HOME (Continued)** **S106971904**

| | |
|---|---|
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**Z120** **VERNER RES** **NY LTANKS** **S106703846**
**NW** **46 ECHO LN** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.324 mi.**
**1710 ft.** **Site 1 of 2 in cluster Z**

**Relative:**
**Higher**

**Actual:**
**99 ft.**

LTANKS:

| | |
|---|---|
| Name: | VERNER RES |
| Address: | 46 ECHO LN |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9802021 / 1998-06-15 |
| Facility ID: | 9802021 |
| Site ID: | 160747 |
| Spill Date: | 1998-05-15 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1998-05-15 |
| CID: | 233 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-05-15 |
| Spill Record Last Update: | 2003-08-27 |
| Spiller Name: | VERNER |
| Spiller Company: | VERNER RES |
| Spiller Address: | 46 ECHO LN |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 135724 |
| Latitude: | 40.9386160 |
| Longitude: | -73.7634301 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/15/98 TANK TECH TANK PASSED TEST |
| Remarks: | tank is u/g at the residence |

All TTF:

| | |
|---|---|
| Facility ID: | 9802021 |

**VERNER RES (Continued)** **S106703846**

| | |
|---|---|
| Spill Number: | 9802021 |
| Spill Tank Test: | 1545903 |
| Site ID: | 160747 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 160747 |
| Operable Unit ID: | 1059925 |
| Operable Unit: | 01 |
| Material ID: | 323927 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AA121** **LARCHMONT AUTO GARAGE** **NY LTANKS** **S102619320**
**WSW** **5TH AV & MADISON** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.325 mi.**
**1716 ft.** **Site 1 of 2 in cluster AA**

**Relative:** **Lower**
**Actual:** **29 ft.**

LTANKS:

| | |
|---|---|
| Name: | LARCHMONT AUTO GARAGE |
| Address: | 5TH AV & MADISON |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9611599 / 1996-12-23 |
| Facility ID: | 9611599 |
| Site ID: | 249760 |
| Spill Date: | 1996-12-21 |
| Spill Cause: | Tank Failure |
| Spill Source: | Unknown |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1996-12-21 |
| CID: | 365 |
| Water Affected: | Not reported |
| Spill Notifier: | Police Department |

**LARCHMONT AUTO GARAGE (Continued)** **S102619320**

| | |
|---|---|
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1996-12-21 |
| Spill Record Last Update: | 1997-06-23 |
| Spiller Name: | Not reported |
| Spiller Company: | FRANK AVRICCNIO |
| Spiller Address: | 633 FIFTH AVE. |
| Spiller County: | 001 |
| Spiller Contact: | FIRE DEPT |
| Spiller Phone: | (914) 834-2101 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 204743 |
| Latitude: | 40.9318679 |
| Longitude: | -73.7654720 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 12/23/96 SAME AS SPILL # 9611598 |
| Remarks: | SMALL SPILL OF FUEL OIL AND GASOLINE THAT MAY HAVE POSSIBLY GOTTEN INTO THE SEWER FIRE DEPT WOULD LIKE A RESPONSE |

All Materials:

| | |
|---|---|
| Site ID: | 249760 |
| Operable Unit ID: | 1042970 |
| Operable Unit: | 01 |
| Material ID: | 340258 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Site ID: | 249760 |
| Operable Unit ID: | 1042970 |
| Operable Unit: | 01 |
| Material ID: | 340259 |
| Material Code: | 0009 |
| Material Name: | gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**AB122** **GRECO DWELLING** **NY LTANKS** **S111836561**
**South** **212 LARCHMONT AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.325 mi.**
**1718 ft.** **Site 1 of 2 in cluster AB**

**Relative:** **Higher**

**Actual:** **60 ft.**

LTANKS:

| | |
|---|---|
| Name: | GRECO DWELLING |
| Address: | 212 LARCHMONT AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1201664 / 2012-08-20 |
| Facility ID: | 1201664 |
| Site ID: | 464387 |
| Spill Date: | 2012-05-21 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2012-05-21 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2012-05-21 |
| Spill Record Last Update: | 2012-08-20 |
| Spiller Name: | Not reported |
| Spiller Company: | MR GRECO |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | OWNER |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 418780 |
| Latitude: | 40.9304816 |
| Longitude: | -73.7583286 |
| DEC Memo: | 5-21-12 Spoke with Kathy. Tank test failed with popping sound. This is a real estate transaction and was being performed by potential buyer. Homeowner has ProGuard Insurance which will cover tank removal so tank will most likely be removed. jm 6-19-12: Kathy/US Tk.Tech. call to Dispt./V.Mc.: UST failed re-test. 8/20/2012: HVEC removed and disposed of tank. No evidence of leak or contamination was found. Closure report entered into eDocs. Closure report mentions a post-ex soil sample, but no sample results were included. Message sent to HVEC requesting they forward a copy of the sample. Based upon information provided to DEC, no further action is required at this time. jod |
| Remarks: | 1000G TANK -TEST FAIL |

All Materials:

| | |
|---|---|
| Site ID: | 464387 |
| Operable Unit ID: | 1214439 |
| Operable Unit: | 01 |

**GRECO DWELLING (Continued)** **S111836561**

| | |
|---|---|
| Material ID: | 2212481 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**AB123** **PRIVATE DWELLING** **NY LTANKS** **S111836562**
**South** **212 LARCHMONT AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.325 mi.**
**1718 ft.** **Site 2 of 2 in cluster AB**

**Relative:** **Higher**
**Actual:** **60 ft.**

LTANKS:

| | |
|---|---|
| Name: | PRIVATE DWELLING |
| Address: | 212 LARCHMONT AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1201667 / 2012-08-20 |
| Facility ID: | 1201667 |
| Site ID: | 464390 |
| Spill Date: | 2012-05-21 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2012-05-21 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2012-05-21 |
| Spill Record Last Update: | 2012-08-20 |
| Spiller Name: | Not reported |
| Spiller Company: | MR GRECO |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | OWNER |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 418780 |
| Latitude: | 40.9304816 |
| Longitude: | -73.7583286 |
| DEC Memo: | 5-21-12 Refer to 12-01664. NFA jm 8/20/2012: HVEC removed and disposed of tank. No evidence of leak or contamination was found. Closure report entered into eDocs. Closure report mentions a post-ex soil sample, but no sample results were included. Message sent to |

**PRIVATE DWELLING (Continued)** **S111836562**

HVEC requesting they forward a copy of the sample. Based upon information provided to DEC, no further action is required at this time. jod

Remarks: 1000G TANK -TEST FAIL

All Materials:

| | |
|---|---|
| Site ID: | 464390 |
| Operable Unit ID: | 1214442 |
| Operable Unit: | 01 |
| Material ID: | 2212485 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**Y124** **CONDON HOME** **NY LTANKS** **S108467757**
**NNW** **16 ORSINI DRIVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.326 mi.**
**1719 ft.** **Site 2 of 2 in cluster Y**

**Relative:**
**Higher**

**Actual:**
**88 ft.**

LTANKS:

| | |
|---|---|
| Name: | CONDON HOME |
| Address: | 16 ORSINI DRIVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0612662 / 2007-03-29 |
| Facility ID: | 0612662 |
| Site ID: | 377553 |
| Spill Date: | 2007-02-22 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2007-02-22 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2007-02-22 |
| Spill Record Last Update: | 2007-03-29 |
| Spiller Name: | DOROTHY CONDON |
| Spiller Company: | CONDON HOME |
| Spiller Address: | 16 ORSNNIE DRIVE |
| Spiller County: | 001 |
| Spiller Contact: | DOROTHY CONDON |
| Spiller Phone: | (914) 834-0340 |

**CONDON HOME (Continued)** **S108467757**

| | |
|---|---|
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 327092 |
| Latitude: | 40.9396717 |
| Longitude: | -73.7617487 |
| DEC Memo: | 03/09/07 Northeast Environmental reported that the tank was removed and that no contaminated soil was observed in the tank grave. Confirmed by lab analysis of a soil sample. NFA TG |
| Remarks: | removal: |

All TTF:

| | |
|---|---|
| Facility ID: | 0612662 |
| Spill Number: | 0612662 |
| Spill Tank Test: | 1550648 |
| Site ID: | 377553 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 377553 |
| Operable Unit ID: | 1135083 |
| Operable Unit: | 01 |
| Material ID: | 2124977 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AC125** **LEVY** **NY LTANKS** **S103939848**
**SE** **7 ROOSEVELT AV** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.328 mi.**
**1730 ft.** **Site 1 of 2 in cluster AC**

**Relative:**
**Higher**

**Actual:**
**49 ft.**

LTANKS:

| | |
|---|---|
| Name: | LEVY |
| Address: | 7 ROOSEVELT AV |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9601585 / 1996-06-12 |
| Facility ID: | 9601585 |
| Site ID: | 215731 |
| Spill Date: | 1996-04-30 |

**LEVY (Continued)** **S103939848**

| | |
|---|---|
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1996-05-01 |
| CID: | 297 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1996-05-01 |
| Spill Record Last Update: | 2000-03-03 |
| Spiller Name: | RICHARD LEVY |
| Spiller Company: | RICHARD LEVY |
| Spiller Address: | 7 ROOSEVELT AV |
| Spiller County: | 001 |
| Spiller Contact: | THOMAS KUNKEL |
| Spiller Phone: | (914) 762-9223 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 178660 |
| Latitude: | 40.9326100 |
| Longitude: | -73.7536122 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/12/96 TANK & CONTAMINATED SOIL REMOVED |
| Remarks: | COMP'S COMPANY WAS CALLED TO REMOVE A TANK AND DISCOVERED IT WAS LEAKING - COMP'S COMPANY WILL CLEAN UP AREA |

All Materials:

| | |
|---|---|
| Site ID: | 215731 |
| Operable Unit ID: | 1033139 |
| Operable Unit: | 01 |
| Material ID: | 351387 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 10.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**AD126** **MOCCIA - TTF** **NY LTANKS** **S104620453**
**North** **23 DANTE ST** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.330 mi.**
**1740 ft.** **Site 1 of 2 in cluster AD**

**Relative:**
**Higher**

**Actual:**
**89 ft.**

LTANKS:

| | |
|---|---|
| Name: | MOCCIA - TTF |
| Address: | 23 DANTE ST |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9906899 / 2000-01-10 |
| Facility ID: | 9906899 |
| Site ID: | 299008 |
| Spill Date: | 1999-09-09 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-09-09 |
| CID: | 270 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-09-09 |
| Spill Record Last Update: | 2016-06-14 |
| Spiller Name: | ALFRED MOCCIA |
| Spiller Company: | Alfred Moccia |
| Spiller Address: | 23 DANTE ST |
| Spiller County: | 001 |
| Spiller Contact: | ALFRED MOCCIA |
| Spiller Phone: | (914) 834-6595 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 241911 |
| Latitude: | 40.9399190 |
| Longitude: | -73.7597826 |
| DEC Memo: | 01/10/2000 NORTHEAST PULLED TANK AND DISPOSED OF THREE DOT DRUMS OF CONTAMINATED SOIL. NFA |
| Remarks: | uncover repair retest |

All TTF:

| | |
|---|---|
| Facility ID: | 9906899 |
| Spill Number: | 9906899 |
| Spill Tank Test: | 1547601 |
| Site ID: | 299008 |
| Tank Number: | 1 |
| Tank Size: | 1000 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |

**MOCCIA - TTF (Continued)** **S104620453**

Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 299008
Operable Unit ID: 1085324
Operable Unit: 01
Material ID: 560652
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

**127**
**WNW**
**1/4-1/2**
**0.331 mi.**
**1749 ft.**

**SPILL NUMBER 9913035**
**54 LOOKOUT CIRCLE**
**LARCHMONT, NY**

**NY LTANKS** **S104620848**
**N/A**

**Relative:**
**Higher**

**Actual:**
**106 ft.**

LTANKS:
Name: SPILL NUMBER 9913035
Address: 54 LOOKOUT CIRCLE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 9913035 / 2000-06-01
Facility ID: 9913035
Site ID: 289288
Spill Date: 2000-02-16
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6000
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2000-02-16
CID: 366
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2000-02-16
Spill Record Last Update: 2000-06-02
Spiller Name: Not reported
Spiller Company: BONNIE BECK
Spiller Address: 54 LOOKOUT CIRCLE
Spiller County: 001

**SPILL NUMBER 9913035 (Continued)** **S104620848**

| | |
|---|---|
| Spiller Contact: | BONNIE BECK |
| Spiller Phone: | (911) 483-4170 |
| Spiller Extention: | 6 |
| DEC Region: | 3 |
| DER Facility ID: | 234257 |
| Latitude: | 40.9379253 |
| Longitude: | -73.7645477 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/01/2000 CASTLTON DISPOSED OF TANK AND 3.96 TONS OF CONTAMINATED SOIL. DORSON ENVIRONMENTAL PROVIDED OVERSITE. DORSON REPORTS NO HOLES WERE FOUND IN TANK, PROBLEM WAS IN PIPING. CLEANUP COMPLETED. NFA |
| Remarks: | CALLER REPORTING THAT THEY WERE REMOVING AN UST AND FOUND HOLES IN THAT TANK AND CONTAMINATED SOIL. SAMPLES TAKEN FROM SOIL AND CLEAN UP PENDING RESULTS. |

All Materials:

| | |
|---|---|
| Site ID: | 289288 |
| Operable Unit ID: | 1091751 |
| Operable Unit: | 01 |
| Material ID: | 563422 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AC128** **BEN BEDERSON TTF** **NY LTANKS** **S101340431**
**SE** **8 HALL AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.336 mi.**
**1774 ft.** **Site 2 of 2 in cluster AC**

**Relative:** **Lower**
**Actual:** **28 ft.**

LTANKS:

| | |
|---|---|
| Name: | BEN BEDERSON TTF |
| Address: | 8 HALL AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9410735 / 1995-02-13 |
| Facility ID: | 9410735 |
| Site ID: | 146635 |
| Spill Date: | 1994-11-11 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | 1995-02-13 |
| SWIS: | 6032 |
| Investigator: | MONACO |
| Referred To: | Not reported |
| Reported to Dept: | 1994-11-11 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |

**BEN BEDERSON TTF (Continued)** **S101340431**

| | |
|---|---|
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1994-11-16 |
| Spill Record Last Update: | 2017-01-06 |
| Spiller Name: | Not reported |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 489163 |
| Latitude: | 40.9326172 |
| Longitude: | -73.7534458 |
| DEC Memo: | . 1/6/17: File pulled from archives for FOIL. File scanned to PDF and entered into DecDocs. Hard copy file discarded. jod Also see Spill 1607551 |
| Remarks: | SHUT OFF BURNER SUSPECT LINE LEAK WILL INVESTIGATE |

All TTF:

| | |
|---|---|
| Facility ID: | 9410735 |
| Spill Number: | 9410735 |
| Spill Tank Test: | 1543338 |
| Site ID: | 146635 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 146635 |
| Operable Unit ID: | 1004645 |
| Operable Unit: | 01 |
| Material ID: | 376603 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | Not reported |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**AD129** **SLATTERY RESIDENCE** **NY LTANKS** **S108765620**
**North** **25 DANTE ST** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.339 mi.**
**1792 ft.** **Site 2 of 2 in cluster AD**

**Relative:**
**Higher**

**Actual:**
**87 ft.**

LTANKS:

| | |
|---|---|
| Name: | SLATTERY RESIDENCE |
| Address: | 25 DANTE ST |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0705870 / 2007-09-25 |
| Facility ID: | 0705870 |
| Site ID: | 386276 |
| Spill Date: | 2007-08-23 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2007-08-23 |
| CID: | 408 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2007-08-23 |
| Spill Record Last Update: | 2007-09-25 |
| Spiller Name: | SUZANNE SLATTERY |
| Spiller Company: | PRIVATE HOME |
| Spiller Address: | 25 DANTE ST |
| Spiller County: | 001 |
| Spiller Contact: | SUZANNE SLATTERY |
| Spiller Phone: | (914) 834-0145 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 335659 |
| Latitude: | 40.9405717 |
| Longitude: | -73.7584286 |
| DEC Memo: | 08/27/07 Northeast Environmental reported that the tank was removed along with 4 drums of PCS. NFA TG |
| Remarks: | DURING TANK REMOVAL HOLES FOUND IN TANK AND CONTAMINATED SOIL DISCOVERED; |

All TTF:

| | |
|---|---|
| Facility ID: | 0705870 |
| Spill Number: | 0705870 |
| Spill Tank Test: | 1551104 |
| Site ID: | 386276 |
| Tank Number: | Not reported |
| Tank Size: | 1000 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |

**SLATTERY RESIDENCE (Continued)** **S108765620**

Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 386276
Operable Unit ID: 1143514
Operable Unit: 01
Material ID: 2133794
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

---

**130**
**SSE**
**1/4-1/2**
**0.344 mi.**
**1814 ft.**

**SPILL NUMBER 0205284**
**60 CHATSWORTH AVE**
**LARCHMONT, NY**

**NY LTANKS** **S105996560**
**N/A**

**Relative:**
**Higher**

**Actual:**
**59 ft.**

LTANKS:
Name: SPILL NUMBER 0205284
Address: 60 CHATSWORTH AVE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 0205284 / 2002-09-11
Facility ID: 0205284
Site ID: 98006
Spill Date: 2002-08-20
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6000
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2002-08-20
CID: 207
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2002-08-20
Spill Record Last Update: 2002-09-12
Spiller Name: NICK BARNABA
Spiller Company: CUFF
Spiller Address: 60 CHATSWORTH AVE

**SPILL NUMBER 0205284 (Continued)** **S105996560**

| | |
|---|---|
| Spiller County: | 001 |
| Spiller Contact: | NICK BARNABA |
| Spiller Phone: | (914) 777-1930 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 87243 |
| Latitude: | 40.9311095 |
| Longitude: | -73.7548044 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was |
| Remarks: | O'DEE NORTHEAST COMPLETED CLEANUP. 3-DRUMS OF MATERIAL. NFA cleanup in progress |

All Materials:

| | |
|---|---|
| Site ID: | 98006 |
| Operable Unit ID: | 856736 |
| Operable Unit: | 01 |
| Material ID: | 519484 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 10.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**131 NNE 1/4-1/2 0.346 mi. 1827 ft.**

**RESIDENCE**
**41 MYRTLE BLVD**
**LARCHMONT, NY**

**NY LTANKS** **S107410616**
**N/A**

**Relative: Higher**

**Actual: 49 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 41 MYRTLE BLVD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0507572 / 2006-08-09 |
| Facility ID: | 0507572 |
| Site ID: | 353041 |
| Spill Date: | 2005-09-23 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2005-09-23 |
| CID: | 407 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2005-09-26 |

**RESIDENCE (Continued)** **S107410616**

| | |
|---|---|
| Spill Record Last Update: | 2006-08-09 |
| Spiller Name: | ADELE PELELLA |
| Spiller Company: | RESIDENCE |
| Spiller Address: | 41 MYTLE BLVD |
| Spiller County: | 001 |
| Spiller Contact: | ADELE PELELLA |
| Spiller Phone: | (914) 632-5199 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 300340 |
| Latitude: | 40.9401380 |
| Longitude: | -73.7545710 |
| DEC Memo: | 11/4/05 Ms. Pelella called. NES has been doing the remediation. They pulled 550 gal UST, and installed MW due to GW contamination. NES has used bioremediation on the site. Property is for sale, and owner was inquiring about spill closure. Referred her to John O'Dee. 04/07/06 Scott Tqylor from NES reported that excavation was limited by the location of the tank so all the contaminated soil couldn't be removed. Plans include drilling upgradient wells and injecting Micro Bac 1000H to promote degradation of the residual oil effects. TG 07/27/06 National Environmental Specialists submitted agroundwater remediation report. Based on the reduction of voc in the groundwater, NFA required. TG |
| Remarks: | Not reported |

All TTF:

| | |
|---|---|
| Facility ID: | 0507572 |
| Spill Number: | 0507572 |
| Spill Tank Test: | 1549336 |
| Site ID: | 353041 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 353041 |
| Operable Unit ID: | 1110511 |
| Operable Unit: | 01 |
| Material ID: | 2100542 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**Z132** **PRIVATE RESIDENCE** **NY LTANKS** **S106385747**
**NW** **23 MAPLEWOOD STREET** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.351 mi.**
**1851 ft.** **Site 2 of 2 in cluster Z**

**Relative:**
**Higher**

**Actual:**
**89 ft.**

LTANKS:

| | |
|---|---|
| Name: | MAUGUE HOME |
| Address: | 23 MAPLEWOOD STREET |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0509152 / 2005-10-31 |
| Facility ID: | 0509152 |
| Site ID: | 354880 |
| Spill Date: | 2005-10-13 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | Not reported |
| Reported to Dept: | 2005-10-31 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2005-10-31 |
| Spill Record Last Update: | 2005-11-01 |
| Spiller Name: | LANCE |
| Spiller Company: | TERRICONE FUEL |
| Spiller Address: | 59 MAIN STREET |
| Spiller County: | 001 |
| Spiller Contact: | PAT MAUGUE |
| Spiller Phone: | (914) 834-2027 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 304949 |
| Latitude: | 40.9392350 |
| Longitude: | -73.7629470 |
| DEC Memo: | Madison Environmental finished cleanup. NFA. |
| Remarks: | SAMLL OVERFILL, WAS CLEANED UP AND NOW GOING BACK TO FINISH: |

All Materials:

| | |
|---|---|
| Site ID: | 354880 |
| Operable Unit ID: | 1112267 |
| Operable Unit: | 01 |
| Material ID: | 2102309 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 5.00 |
| Units: | G |
| Recovered: | 5.00 |
| Oxygenate: | Not reported |

**PRIVATE RESIDENCE (Continued)** **S106385747**

| | |
|---|---|
| Name: | PRIVATE RESIDENCE |
| Address: | 23 MAPLEWOOD STREET |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0400048 / 2004-06-04 |
| Facility ID: | 0400048 |
| Site ID: | 316083 |
| Spill Date: | 2004-04-02 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-04-02 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-04-02 |
| Spill Record Last Update: | 2004-06-04 |
| Spiller Name: | REALTY SMITH |
| Spiller Company: | PRIVATE RESIDENCE |
| Spiller Address: | 23 MAPLEWOOD STREET |
| Spiller County: | 001 |
| Spiller Contact: | REALTY SMITH |
| Spiller Phone: | (914) 834-1070 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 254817 |
| Latitude: | 40.9392415 |
| Longitude: | -73.7629552 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE Estate of Betzig; Phyllis Jacobs: 834-0270; Bill Betzig: C:716-903-0291 06/04/04 ELITE ENVIRONMENTAL DISPOSED OF LUST AND 87.52 TONS OF CONTAMINATED SOIL. SOME RESIDUAL CONTAMINATION COULD NOT BE EXCAVATED DUE TO STRUCTURAL CONSIDERATIONS. SAMPLE RESULTS WERE BELOW TAGM LEVELS. BASED UPON REPORT SUBMITTED, DEC REQUIRES NO FURTHER ACTION AT THIS TIME. jbo |
| Remarks: | RECOMMEND: EXPOSE AND RETEST: |

All TTF:

| | |
|---|---|
| Facility ID: | 0400048 |
| Spill Number: | 0400048 |
| Spill Tank Test: | 1529120 |
| Site ID: | 316083 |
| Tank Number: | Not reported |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |

**PRIVATE RESIDENCE (Continued)** **S106385747**

| | |
|---|---|
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 316083 |
| Operable Unit ID: | 882383 |
| Operable Unit: | 01 |
| Material ID: | 494842 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**133**
**ESE**
**1/4-1/2**
**0.354 mi.**
**1871 ft.**

**BIRDVELL RESIDENCE** **NY LTANKS** **S105997452**
**4 FOREST PARK AVE** **N/A**
**LARCHMONT, NY**

**Relative:**
**Lower**

**Actual:**
**26 ft.**

LTANKS:

| | |
|---|---|
| Name: | BIRDVELL RESIDENCE |
| Address: | 4 FOREST PARK AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0208984 / 2003-02-27 |
| Facility ID: | 0208984 |
| Site ID: | 249561 |
| Spill Date: | 2002-12-02 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2002-12-02 |
| CID: | 205 |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2002-12-02 |
| Spill Record Last Update: | 2003-09-02 |
| Spiller Name: | CALLER |
| Spiller Company: | BIRDVELL RES |
| Spiller Address: | 4 FOREST PARK AVE |
| Spiller County: | 001 |

**BIRDVELL RESIDENCE (Continued)** **S105997452**

| | |
|---|---|
| Spiller Contact: | CALLER |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 204580 |
| Latitude: | 40.9331130 |
| Longitude: | -73.7518092 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 02/27/03 ENVIROSTAR DISPOSED OF TANK AND 48.88 TONS CONTAMIN SOIL. GW WAS IMPACTED, MON WELL INSTALLED AND SAMPLED. NFA. |
| Remarks: | PULLED TANK AND ENCOUNTERED CONTAMINATED SOIL. STOCKPILING NOW. |

All Materials:

| | |
|---|---|
| Site ID: | 249561 |
| Operable Unit ID: | 860411 |
| Operable Unit: | 01 |
| Material ID: | 515974 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AE134** **MARTIN RES** **NY LTANKS** **S105995390**
**SE** **16 FOREST PARK AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.357 mi.**
**1883 ft.** **Site 1 of 2 in cluster AE**

**Relative:** **Lower**
**Actual:** **26 ft.**

LTANKS:

| | |
|---|---|
| Name: | MARTIN RES |
| Address: | 16 FOREST PARK AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0111809 / 2002-05-03 |
| Facility ID: | 0111809 |
| Site ID: | 206085 |
| Spill Date: | 2002-03-14 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2002-03-14 |
| CID: | 233 |
| Water Affected: | Not reported |
| Spill Notifier: | Affected Persons |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2002-03-14 |

**MARTIN RES (Continued)** **S105995390**

| | |
|---|---|
| Spill Record Last Update: | 2002-06-04 |
| Spiller Name: | Not reported |
| Spiller Company: | MARTIN RES |
| Spiller Address: | 16 FOREST PARK AVE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 171138 |
| Latitude: | 40.9323000 |
| Longitude: | -73.7524302 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 05/03/02 - CLOSURE REPORT RECEIVED FROM HYDRO ENVIRO SOLUTIONS. LUST AND 25.58 TONS CONTAMIN REMOVED. NFA |
| Remarks: | CALLER WAS HIRE TO REMOVE AN U/ OIL TANK WHEN TANK WAS REMOVED CONTAMINATED SOIL WAS DISCOVERED SOIL WAS LEFT ON SITE SOIL SAMPLES HAVE BEEN SENT OUT TO BE TESTED |

All Materials:

| | |
|---|---|
| Site ID: | 206085 |
| Operable Unit ID: | 848753 |
| Operable Unit: | 01 |
| Material ID: | 525828 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AA135** **MAMARONECK MANOR** **NY BROWNFIELDS** **S132956659**
**WSW** **636 FIFTH AVENUE** **N/A**
**1/4-1/2** **MAMARONECK, NY 10538**
**0.357 mi.**
**1886 ft.** **Site 2 of 2 in cluster AA**

**Relative:** **Lower**
**Actual:** **29 ft.**

BROWNFIELDS:

| | |
|---|---|
| Name: | MAMARONECK MANOR |
| Address: | 636 FIFTH AVENUE |
| City,State,Zip: | MAMARONECK, NY 10538 |
| Program: | BCP |
| Site Code: | 676662 |
| Acres: | 0.830 |
| HW Code: | C360260 |
| SWIS: | 6032 |
| Town: | Mamaroneck |
| Record Added Date: | 03/17/2025 |
| Record Updated Date: | 04/11/2025 |
| Update By: | JLHATHAW |
| Site Description: | Location The Site is a 37,897 square feet (0.87-acre) developed residential and commercial parcel comprised of four contiguous tax lots located on the western side of Fifth Avenue (Lots 73 and 78), southern side of Madison Avenue (Lot 103), and eastern side of Lester Place (Lot 126). Surrounding-area properties typically contain |

**MAMARONECK MANOR (Continued)** **S132956659**

residential and commercial uses. The Site is adjoined to the north by Madison Avenue followed by a parking residential condominium complex, to the east by Fifth Avenue followed by a vacant lot and a commercial building (landscaping supply), to the south by a single family residence accessed from Lester Place and a commercial building (general contractor), and to the west by Lester Place followed by single family residences. Site Features The property contains 2 -story dwellings at 93 Madison Avenue (Lot 103) and 630 Fifth Avenue (Lot 73), and a 1-story commercial building at 636 Fifth Avenue (Lot 78); the parcel at Lester Place (Lot 126) is vacant land. The commercial structure (a former service station facility) contains batting cages (southern portion) and an automotive repair business (northern portion). Exterior areas contain asphalt parking lots/driveways and landscaping. Other than monitoring wells installed during environmental investigations, there are no currently existing direct pathways to the subsurface. Current Zoning and Land Use The Project Site is located in two zoning districts: 630 and 636 Fifth Avenue (Lots 73 and 78) are zoned SB-R Service Business-Residential, and 93 Madison Avenue (Lot 103) and the Lester Place parcel (Lot 126) are zoned R-7.5 Single-Family Residential, which allow for the planned mixed use development. Adjoining uses include residential and commercial buildings. Past Uses of the Site 630 Fifth Avenue and 93 Madison Avenue were developed with residential structures sometime after 1919 and before 1950, and 636 Fifth Avenue was developed as a filling station and automotive repair facility (with paint spraying) sometime between 1950 and 1963. The Lester lot has been vacant land since at least 1919. According to the NYSDEC Petroleum Bulk Storage (PBS) database, 636 Fifth Avenue is a registered active facility (PBS 3-074918; GIACOMO SERVICE CENTER) that formerly contained three large capacity gasoline underground storage tank (USTs; 2,000 to 4,000 gallons) and a fuel oil UST (550 gallons), which were removed in 2011, and currently contains several small (275 gallon) aboveground storage tanks (ASTs) utilized for fuel oil and waste-oil. Filling station operations ceased circa 2011; automotive repair activities, however, are still ongoing. Possible sources of contamination at the Site include releases from storage tanks and/or automotive repair activities, and from general use (e.g., metals from painted surfaces). Site Geology and Hydrogeology Area topography in a quarter-mile radius is variable, with elevations ranging from approximately 20 to 180 feet above mean sea level (amsl), while the Site itself is in a somewhat level area with surface elevations of approximately 20 to 30 feet amsl. Soils encountered at the Site during previous environmental investigations (maximum boring depth of approximately 20 feet below ground surface [bgs]) included several areas of suspect fill material within the upper 5 feet interval, and typical glacial materials comprised of variable texture sands and silts, with some gravel and cobbles. Bedrock was not encountered in any borings. Based on published USGS reports, bedrock beneath the Site is expected to be comprised of hard, crystalline metamorphic rock (Hartland Formation or Harrison Gneiss). Groundwater was encountered in borings and in groundwater wells at approximately 10 feet bgs; shallow groundwater flow is inferred to be in an overall southerly direction, based on area topography.

Env Problem: Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available.

Health Problem: Information submitted with the BCP application regarding the

**MAMARONECK MANOR (Continued)** **S132956659**

| | |
|---|---|
| | conditions at the site are currently under review and will be revised as additional information becomes available. |
| Dump: | Not reported |
| Structure: | Not reported |
| Lagoon: | Not reported |
| Landfill: | Not reported |
| Pond: | Not reported |
| Disp Start: | Not reported |
| Disp Term: | Not reported |
| Lat/Long: | Not reported |
| Dell: | Not reported |
| Record Add: | Not reported |
| Record Upd: | Not reported |
| Updated By: | Not reported |
| Own Op: | 1 |
| Sub Type: | E |
| Owner Name: | Janis Walby |
| Owner Company: | Patsy and Theresa Giacomo Revocable Trust |
| Owner Address: | 7 Hague Close |
| Owner Addr2: | Not reported |
| Owner City,St,Zip: | Williamsburg, VA 23185 |
| Owner Country: | United States of America |
| Own Op: | Document Repository |
| Sub Type: | C01 |
| Owner Name: | Laura Eckley |
| Owner Company: | Larchmont Public Library |
| Owner Address: | 121 Larchmont Avenue |
| Owner Addr2: | Not reported |
| Owner City,St,Zip: | Larchmont, NY 10538 |
| Owner Country: | United States of America |
| Own Op: | 6 |
| Sub Type: | P03 |
| Owner Name: | Sean Kearney |
| Owner Company: | PARKVIEW DEVELOPMENT & CONSTRUCTION, LLC |
| Owner Address: | 57 Route 6, Suite 207 |
| Owner Addr2: | Not reported |
| Owner City,St,Zip: | Baldwin Place, NY 10505 |
| Owner Country: | United States of America |
| Own Op: | 4 |
| Sub Type: | E |
| Owner Name: | Andrew J. Buccafusco |
| Owner Company: | The Cage 2325, Inc. |
| Owner Address: | 2356 Palmer Avenue |
| Owner Addr2: | Not reported |
| Owner City,St,Zip: | Rochelle, NY 10801 |
| Owner Country: | United States of America |
| Own Op: | 4 |
| Sub Type: | E |
| Owner Name: | Frank Giacomo |
| Owner Company: | Giacomo Service II, Inc |
| Owner Address: | 2107 Palmer Avenue |
| Owner Addr2: | Not reported |
| Owner City,St,Zip: | Larchmont, NY 10538 |
| Owner Country: | United States of America |
| HW Code: | Not reported |
| Waste Type: | Not reported |
| Waste Quantity: | Not reported |

**MAMARONECK MANOR (Continued)** **S132956659**

| | |
|---|---|
| Waste Code: | Not reported |
| Crossref ID: | Not reported |
| Cross Ref Type Code: | Not reported |
| Cross Ref Type: | Not reported |
| Record Added Date: | Not reported |
| Record Updated: | Not reported |
| Updated By: | Not reported |

---

**AF136** **SPRINGER RESIDENCE** **NY LTANKS** **S106472146**
**South** **200 LARCHMONT AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.359 mi.**
**1895 ft.** **Site 1 of 2 in cluster AF**

**Relative:** **Higher**
**Actual:** **47 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPRINGER RESIDENCE |
| Address: | 200 LARCHMONT AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0404212 / 2004-10-28 |
| Facility ID: | 0404212 |
| Site ID: | 328692 |
| Spill Date: | 2004-07-20 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-07-20 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-07-20 |
| Spill Record Last Update: | 2004-10-28 |
| Spiller Name: | PHILIP SPRINGER |
| Spiller Company: | SPRINGER RESIDENCE |
| Spiller Address: | 200 LARCHMONT AVE |
| Spiller County: | 001 |
| Spiller Contact: | PHILIP SPRINGER |
| Spiller Phone: | (914) 833-0918 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 264526 |
| Latitude: | 40.9301690 |
| Longitude: | -73.7571300 |
| DEC Memo: | 10/28/04 NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 39.11 TONS OF CONTAMINATED SOIL. GROUND WATER WAS IMPACTED. HES COMPLETED GROUND WATER SAMPLING AND SUBMITTED CLOSURE REPORT. BASED UPON THE INFORMATION SUPPLIED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo |
| Remarks: | 1000 GALLON TANK HAD HOLES WHILE REMOVING: |

**SPRINGER RESIDENCE (Continued)** **S106472146**

All Materials:

| | |
|---|---|
| Site ID: | 328692 |
| Operable Unit ID: | 887441 |
| Operable Unit: | 01 |
| Material ID: | 488223 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | L |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**137**
**NW**
**1/4-1/2**
**0.361 mi.**
**1905 ft.**

**MOSER RESIDENCE**
**161 MURRAY AVE**
**LARCHMONT, NY**

**NY LTANKS** **S109943812**
**N/A**

**Relative:**
**Higher**

**Actual:**
**88 ft.**

LTANKS:

| | |
|---|---|
| Name: | MOSER RESIDENCE |
| Address: | 161 MURRAY AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0907297 / 2009-12-22 |
| Facility ID: | 0907297 |
| Site ID: | 419812 |
| Spill Date: | 2009-09-29 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2009-09-29 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2009-09-29 |
| Spill Record Last Update: | 2009-12-22 |
| Spiller Name: | STEPHEN MOSER |
| Spiller Company: | STEPHEN MOSER |
| Spiller Address: | 161 MURRAY AVE |
| Spiller County: | 999 |
| Spiller Contact: | DON PYATT |
| Spiller Phone: | (973) 390-6675 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 368851 |
| Latitude: | 40.9397417 |

**MOSER RESIDENCE (Continued)** **S109943812**

| | |
|---|---|
| Longitude: | -73.7628887 |
| DEC Memo: | 9-29-09 Called and left message for Don to return my call. jm<br>12/22/09: Closure report from Advanced Environmental reviewed and entered into eDocs. Based upon the information provided, no further action is required at this time. jod |
| Remarks: | TANK TEST FAILURE ON A 1000 GALLON UST. |

All Materials:

| | |
|---|---|
| Site ID: | 419812 |
| Operable Unit ID: | 1175811 |
| Operable Unit: | 01 |
| Material ID: | 2168447 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**AF138** **GLASS RESIDENCE** **NY LTANKS** **S105995703**
**South** **5 IDEN AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.366 mi.**
**1934 ft.** **Site 2 of 2 in cluster AF**

**Relative:**
**Higher**

**Actual:**
**47 ft.**

LTANKS:

| | |
|---|---|
| Name: | GLASS RESIDENCE |
| Address: | 5 IDEN AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0200914 / 2002-05-29 |
| Facility ID: | 0200914 |
| Site ID: | 174074 |
| Spill Date: | 2002-04-24 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2002-04-24 |
| CID: | 196 |
| Water Affected: | Not reported |
| Spill Notifier: | Affected Persons |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2002-04-24 |
| Spill Record Last Update: | 2002-06-25 |
| Spiller Name: | MR GLASS |
| Spiller Company: | MR GLASS |
| Spiller Address: | 5 IDEN AVE |
| Spiller County: | 001 |

**GLASS RESIDENCE (Continued)** **S105995703**

| | |
|---|---|
| Spiller Contact: | KEITH TROCCOLI |
| Spiller Phone: | (914) 278-4067 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 146427 |
| Latitude: | 40.9300625 |
| Longitude: | -73.7579478 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/24/02 1,000 GAL UST. CONTAMINATION DETECTED BELOW UST. 05/29/02 CLOSURE REPORT RECEIVED FROM JM ASSOCIATES. DUTCHESS DISPOSED OF 77.92 TONS OF CONTAMINATED SOIL. NFA |
| Remarks: | found holes inside the tank - unknown amount leaked - plan it to remove the tank at a later date. |

All Materials:

| | |
|---|---|
| Site ID: | 174074 |
| Operable Unit ID: | 854360 |
| Operable Unit: | 01 |
| Material ID: | 522343 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**139** **ELEMENTARY SCHOOL** **NY LTANKS S104880087**
**NE** **125 WEAVER STREET** **NY Spills N/A**
**1/4-1/2** **SCARSDALE, NY**
**0.374 mi.**
**1974 ft.**

**Relative:**
**Higher**

**Actual:**
**51 ft.**

LTANKS:

| | |
|---|---|
| Name: | ELEMENTARY SCHOOL |
| Address: | 125 WEAVER STREET |
| City,State,Zip: | SCARSDALE, NY |
| Spill Number/Closed Date: | 2100760 / 2021-06-22 |
| Facility ID: | 2100760 |
| Site ID: | 618445 |
| Spill Date: | 2021-04-26 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | E4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6050 |
| Investigator: | BTRANSOM |
| Referred To: | Not reported |
| Reported to Dept: | 2021-04-26 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |

**ELEMENTARY SCHOOL (Continued)** **S104880087**

| | |
|---|---|
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2021-04-26 |
| Spill Record Last Update: | 2021-06-22 |
| Spiller Name: | Not reported |
| Spiller Company: | Quaker Ridge School |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | CARL SHELL |
| Spiller Phone: | (845) 778-5110 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 566118 |
| Latitude: | Not reported |
| Longitude: | Not reported |
| DEC Memo: | 4/26/21- Spoke to caller, Lew: APECCO was performing a tank test at this site. Tanks test failed. No release observed so far. Will investigate further and maybe do repairs on the vent line if it is the culprit. DW tank and DW supply/return lines. -MS 4/27/21: From Chris Lalak at WCDOH PBS: TTF 6 K DW tank from 1991 Tester indicates it could be a vent issue PBS 3-184853 Quaker Ridge School 125 Weaver st, Scarsdale I have calls and emails into the tester and the school. jod 05-26-21 Update from APECCO: TTF from vent line failure. The tank was isolated and passed retest. Closure report is forthcoming. BTR 06-22-21 Received closure report dated 6/2/2021. APECCO returned to the facility 5/26 to replace the vent line. The tank tested tight after repairs were made to the vent line. No oil spill was observed or verified. NFA. BTR |
| Remarks: | Failed Tank test: suspected leak source is the vent - further investigation. |

All TTF:

| | |
|---|---|
| Facility ID: | 2100760 |
| Spill Number: | 2100760 |
| Spill Tank Test: | 2509118 |
| Site ID: | 618445 |
| Tank Number: | 3 |
| Tank Size: | 6000 |
| Material: | 0001 |
| EPA UST: | False |
| UST: | True |
| Cause: | 99 |
| Source: | 00 |
| Test Method: | 34 |
| Test Method 2: | EZY 3 Locator Plus |
| Leak Rate: | Not reported |
| Gross Fail: | Not reported |
| Modified By: | JBODEE |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 618445 |
| Operable Unit ID: | 1365635 |
| Operable Unit: | 01 |
| Material ID: | 2378197 |
| Material Code: | 9999 |
| Material Name: | other - Failed tank test |
| Case No.: | Not reported |

**ELEMENTARY SCHOOL (Continued)** **S104880087**

| | |
|---|---|
| Material FA: | Other |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |
| | |
| Site ID: | 618445 |
| Operable Unit ID: | 1365635 |
| Operable Unit: | 01 |
| Material ID: | 2378274 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

SPILLS:

| | |
|---|---|
| Name: | QUAKER RIDGE SCHOOL |
| Address: | 125 WEAVER ST |
| City,State,Zip: | SCARSDALE, NY |
| Spill Number/Closed Date: | 0008789 / 2005-04-03 |
| Facility ID: | 0008789 |
| Facility Type: | ER |
| DER Facility ID: | 144830 |
| Site ID: | 172078 |
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | B4 |
| SWIS: | 6050 |
| Spill Date: | 2000-10-27 |
| Investigator: | JKOMARA |
| Referred To: | Not reported |
| Reported to Dept: | 2000-10-27 |
| CID: | 322 |
| Water Affected: | Not reported |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Responsible Party |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | False |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2000-10-27 |
| Spill Record Last Update: | 2005-04-03 |
| Spiller Name: | JOHN TRENHOLM |
| Spiller Company: | QUAKER RIDGE SCHOOL |
| Spiller Address: | 125 WEAVER ST |
| Spiller Company: | 001 |
| Contact Name: | JOHN TRENHOLM |
| Latitude: | Not reported |
| Longitude: | Not reported |
| DEC Memo: | 10/28/00 SEE ONE PAGE UPDATE BY V.M. 11/02/00 ROBERT HALPRIN FROM |

**ELEMENTARY SCHOOL (Continued)** **S104880087**

Remarks: LUZON STATES CLEAN UP HAS BEEN COMPLETED BUT CONTACT JOHN TRENHOLM HAS NOT YET GOTTEN BACK TO HIM ABOUT IN-DOOR AIR MONITORING ISSUES. jbo 04/03/05 ADMINISTRATIVELY CLOSED. jod a fitting on a guage failled causing a spill of several hundred gallons - oil is inside the building in floor drains are also effected - pumps have been stopped /luzon was called for clean up pager for caller # 914-722-3772

All Materials:

| | |
|---|---|
| Site ID: | 172078 |
| Operable Unit ID: | 831235 |
| Operable Unit: | 01 |
| Material ID: | 546287 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 200.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AE140** **RESIDENCE** **NY LTANKS** **S102234175**
**SE** **15 FOREST PARK AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.384 mi.**
**2026 ft.** **Site 2 of 2 in cluster AE**

**Relative:** **Lower**
**Actual:** **24 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 15 FOREST PARK AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9505787 / 1996-09-10 |
| Facility ID: | 9505787 |
| Site ID: | 120940 |
| Spill Date: | 1995-08-10 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1995-08-10 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1995-08-14 |
| Spill Record Last Update: | 2003-08-27 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |

**RESIDENCE (Continued)** **S102234175**

| | |
|---|---|
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 104967 |
| Latitude: | 40.9322356 |
| Longitude: | -73.7523127 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY |
| Remarks: | REMOVING CONTAMINATED SOIL FROM UNDER PORCH SHOULD BE DONE TOMORROW |

All Materials:

| | |
|---|---|
| Site ID: | 120940 |
| Operable Unit ID: | 1020678 |
| Operable Unit: | 01 |
| Material ID: | 363776 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 30.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**141** **LARCHMONT/MAMARONECK JOINT GARBAGE DISPOSAL COMMIS** **NY SWF/LF** **S117692106**
**SW** **41 MAXWELL AVENUE(LOCATION)** **N/A**
**1/4-1/2** **MAMARONECK, NY 10543**
**0.386 mi.**
**2040 ft.**

**Relative:**
**Lower**

**Actual:**
**29 ft.**

SWF/LF:

| | |
|---|---|
| Name: | LARCHMONT/MAMARONECK JOINT GARBAGE DISPOSAL COMMISSION |
| Address: | 41 MAXWELL AVENUE(LOCATION) |
| City,State,Zip: | MAMARONECK, NY 10543 |
| Flag: | ACTIVE |
| Region Code: | 3 |
| Phone Number: | 9143817810 |
| Owner Name: | Town of Mamaroneck |
| Owner Type: | Municipal |
| Owner Address: | 740 W. Boston Post Road |
| Owner Addr2: | Not reported |
| Owner City,St,Zip: | Mamaroneck, NY 10543 |
| Owner Email: | Not reported |
| Owner Phone: | 9143817810 |
| Contact Name: | Not reported |
| Contact Address: | Not reported |
| Contact Addr2: | Not reported |
| Contact City,St,Zip: | Not reported |
| Contact Email: | Not reported |
| Contact Phone: | Not reported |
| Activity Desc: | Transfer facility - less than 50 tpd - registration |
| Activity Number: | [60T10017] |
| Active: | Yes |
| East Coordinate: | 604102 |

**LARCHMONT/MAMARONECK JOINT GARBAGE DISPOSAL COMMISSION (Continued)** **S117692106**

| | |
|---|---|
| North Coordinate: | 4531983 |
| Accuracy Code: | Not reported |
| Regulatory Status: | Registration |
| Waste Type: | MSW (Residential/Institutional & Commercial);Container Glass;Commingled Paper;Food Scraps |
| Authorization #: | 60T10017 |
| Authorization Date: | 9/21/2023 |
| Expiration Date: | 9/20/2028 |
| Operator Name: | Town of Mamaroneck |
| Operator Type: | Municipal |
| Laste Date: | Not reported |

---

**AG142** **ST. JOHN'S** **NY LTANKS** **S100139496**
**NNE** **280 WEAVER ST.** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.388 mi.**
**2049 ft.** **Site 1 of 2 in cluster AG**

**Relative:** **Higher**

**Actual:** **77 ft.**

LTANKS:

| | |
|---|---|
| Name: | ST JOHN & PAUL CHARGE |
| Address: | 280 WEAVER STREET |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0310652 / 2004-01-16 |
| Facility ID: | 0310652 |
| Site ID: | 123833 |
| Spill Date: | 2003-12-16 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | WCHD |
| Referred To: | Westchester Cnty Health Dept |
| Reported to Dept: | 2003-12-16 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-12-16 |
| Spill Record Last Update: | 2004-01-26 |
| Spiller Name: | Not reported |
| Spiller Company: | TOWN & COUNTRY OIL |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | SUSAN LUGO |
| Spiller Phone: | (914) 668-5300 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 107326 |
| Latitude: | 40.9406898 |
| Longitude: | -73.7560737 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-SCHNEIDER 01-14-04 LETTER FROM NORTHEAST RECEIVED. CLEANUP CONSISTED OF EXCAVATING 9 DRUMS OF CONTAMINATED SOIL. NFA TG |

**ST. JOHN'S (Continued)** **S100139496**

| | |
|---|---|
| Remarks: | driver noticed the oil came out of pipe, Northeast Enviormental is on scene. Phone # 914-777-1930. it was a spray of oil not a large amount and all contained. |

All Materials:

| | |
|---|---|
| Site ID: | 123833 |
| Operable Unit ID: | 878315 |
| Operable Unit: | 01 |
| Material ID: | 499502 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | L |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | ST. JOHN'S |
| Address: | 280 WEAVER ST. |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 8705481 / 1988-07-27 |
| Facility ID: | 8705481 |
| Site ID: | 246329 |
| Spill Date: | 1987-09-29 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | Not reported |
| Cleanup Ceased: | 1988-01-20 |
| SWIS: | 6000 |
| Investigator: | jeokesso |
| Referred To: | Not reported |
| Reported to Dept: | 1987-09-29 |
| CID: | Not reported |
| Water Affected: | NONE |
| Spill Notifier: | Tank Tester |
| Last Inspection: | 1988-01-20 |
| Recommended Penalty: | True |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1987-10-05 |
| Spill Record Last Update: | 1988-07-27 |
| Spiller Name: | Not reported |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 202304 |
| Latitude: | 40.9406898 |
| Longitude: | -73.7560737 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : 9/29/87-TO EXCAVATE,ISOLATE AND RETEST. 07/27/88: RETEST PASSED. |

**ST. JOHN'S (Continued)** **S100139496**

Remarks: TTTF; -.189 GAL/HR

All TTF:

| | |
|---|---|
| Facility ID: | 8705481 |
| Spill Number: | 8705481 |
| Spill Tank Test: | 1531765 |
| Site ID: | 246329 |
| Tank Number: | Not reported |
| Tank Size: | 0 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 246329 |
| Operable Unit ID: | 909320 |
| Operable Unit: | 01 |
| Material ID: | 468080 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | ST JOHN AND PAUL CATHOLIC CHURCH |
| Address: | 280 WEAVER ST |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1205086 / 2013-05-07 |
| Facility ID: | 1205086 |
| Site ID: | 468002 |
| Spill Date: | 2012-08-20 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2012-08-20 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |

**ST. JOHN'S (Continued)** **S100139496**

| | |
|---|---|
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2012-08-20 |
| Spill Record Last Update: | 2013-05-07 |
| Spiller Name: | JAMES WILSON (RNB SERVICES) |
| Spiller Company: | PROPERTY OWNER |
| Spiller Address: | 280 WEAVER ST |
| Spiller County: | 999 |
| Spiller Contact: | JAMES WILSON (RNB SERVICES) |
| Spiller Phone: | 8453486355 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 422298 |
| Latitude: | 40.9409717 |
| Longitude: | -73.7555486 |
| DEC Memo: | 8-20-12 Confirmed wet leak. Preparing a proposal for uncover repair. Proposal will include emptying of tank. Advised to empty now. WCHD aware of test, but not on site for it. 3-137065. Other tanks on site also being tested today. jc 5/7/2013: Tank closure report submitted to WCDoH PBS. Wayne Schneider reports: 280 weaver St, Larchmont- ttf. tank and most of contamination removed except for remnant at/under building foundation. Downgradient well borings to bedrock showed no contamination.(nfa letter attached) *Based upon the information provided, DEC requires no further action at this time. See EDocs for WCDoH closure letter. jod |
| Remarks: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 468002 |
| Operable Unit ID: | 1217936 |
| Operable Unit: | 01 |
| Material ID: | 2216286 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**143**
**West**
**1/4-1/2**
**0.389 mi.**
**2054 ft.**

**RESIDENCE**
**1 FRANCE PLACE**
**LARCHMONT, NY**

**NY LTANKS** **S103559104**
**N/A**

**Relative:**
**Higher**

**Actual:**
**103 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 1 FRANCE PLACE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9812530 / 2000-01-13 |
| Facility ID: | 9812530 |
| Site ID: | 220361 |
| Spill Date: | 1999-01-11 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |

**RESIDENCE (Continued)** **S103559104**

| | |
|---|---|
| Spill Class: | D4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | WCHD |
| Referred To: | Westchester Cnty Health Dept |
| Reported to Dept: | 1999-01-11 |
| CID: | 371 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-01-11 |
| Spill Record Last Update: | 2000-02-04 |
| Spiller Name: | ROBERT KIRBY |
| Spiller Company: | RESIDENCE |
| Spiller Address: | 1 FRANCE PLACE |
| Spiller County: | 001 |
| Spiller Contact: | ROBERT KIRBY |
| Spiller Phone: | (914) 834-1453 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 182269 |
| Latitude: | 40.9362459 |
| Longitude: | -73.7658619 |
| DEC Memo: | Not reported |
| Remarks: | TANK FAILED. HOMEOWNER CONTEMPLATING OPTIONS. |

All TTF:

| | |
|---|---|
| Facility ID: | 9812530 |
| Spill Number: | 9812530 |
| Spill Tank Test: | 1546735 |
| Site ID: | 220361 |
| Tank Number: | 1 |
| Tank Size: | 3000 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 220361 |
| Operable Unit ID: | 1073074 |
| Operable Unit: | 01 |
| Material ID: | 312811 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |

**RESIDENCE (Continued)** **S103559104**

| | |
|---|---|
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AH144** **GARRY RESIDENCE** **NY LTANKS** **S105994863**
**East** **7 MEADOW PL** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.390 mi.**
**2059 ft.** **Site 1 of 2 in cluster AH**

**Relative:** LTANKS:
**Higher**

**Actual:**
**41 ft.**

| | |
|---|---|
| Name: | GARRY RESIDENCE |
| Address: | 7 MEADOW PL |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0109734 / 2002-02-04 |
| Facility ID: | 0109734 |
| Site ID: | 324496 |
| Spill Date: | 2002-01-08 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2002-01-08 |
| CID: | 390 |
| Water Affected: | Not reported |
| Spill Notifier: | Local Agency |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2002-01-08 |
| Spill Record Last Update: | 2002-03-14 |
| Spiller Name: | BOB GARRY |
| Spiller Company: | GARRY RESIDENCE |
| Spiller Address: | 7 MEADOW PL |
| Spiller County: | 001 |
| Spiller Contact: | BOB GARRY |
| Spiller Phone: | (914) 833-1601 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 261376 |
| Latitude: | 40.9364880 |
| Longitude: | -73.7515318 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 01/08/2002 550 U/G TANK HAD HOLES WHEN REMOVED. STOCKPILING SOIL. STATE FARM INSURANCE TO HANDLE. 02/04/2002 HYDRO ENVIRONMENTAL SOLUTIONS SUBMITTED CLOSURE REPORT. TANK DISPOSED BY DUTCHESS ENVIRONMENTAL. APPROXIMATELY 20 TONS OF CONTAMINATED SOIL DISPOSED OF. NO FURTHER ACTION. |
| Remarks: | tank failed - clean up in progress |

**GARRY RESIDENCE (Continued)** **S105994863**

All Materials:

| | |
|---|---|
| Site ID: | 324496 |
| Operable Unit ID: | 848097 |
| Operable Unit: | 01 |
| Material ID: | 527384 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AH145** **SPILL NUMBER 0106394** **NY LTANKS** **S105135155**
**East** **110 CARLEON AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.394 mi.**
**2078 ft.** **Site 2 of 2 in cluster AH**

**Relative:** **Lower**
**Actual:** **37 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 0106394 |
| Address: | 110 CARLEON AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0106394 / 2002-01-03 |
| Facility ID: | 0106394 |
| Site ID: | 314780 |
| Spill Date: | 2001-09-18 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 2001-09-18 |
| CID: | 396 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2001-09-18 |
| Spill Record Last Update: | 2002-01-16 |
| Spiller Name: | ASAFF RES |
| Spiller Company: | SAME |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | SHAYE SPELLER |
| Spiller Phone: | (203) 778-5552 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 253779 |
| Latitude: | 40.9357672 |

**SPILL NUMBER 0106394 (Continued)** **S105135155**

Longitude: -73.7506901
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/03/2002 LETTER SENT TO EARNEST ASAFF BY T. GHIOSAY; BASED ON SPILL CLOSURE REPORT SUBMITTED BY GROUNDWATER INVESTIGATIONS, NO FURTHER ACTION IS REQUIRED AT THIS TIME. SPILL NUMBER CLOSED.
Remarks: pulling a 550 gal tank and cont. was found.

All Materials:
Site ID: 314780
Operable Unit ID: 844685
Operable Unit: 01
Material ID: 531253
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

**AI146** **PRIVATE RES** **NY LTANKS** **S106471746**
**NW** **41 MAPLEWOOD ST** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.400 mi.**
**2114 ft.** **Site 1 of 2 in cluster AI**

**Relative:** LTANKS:
**Higher**
**Actual:** Name: PRIVATE RES
**86 ft.** Address: 41 MAPLEWOOD ST
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 0402017 / 2004-09-15
Facility ID: 0402017
Site ID: 321600
Spill Date: 2004-05-24
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6000
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2004-05-24
CID: 406
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2004-05-24
Spill Record Last Update: 2004-09-15
Spiller Name: STEVEN MARCUS
Spiller Company: PRIVATE RES
Spiller Address: 41 MAPLEWOOD ST
Spiller County: 001

**PRIVATE RES (Continued)** **S106471746**

| | |
|---|---|
| Spiller Contact: | STEVEN MARCUS |
| Spiller Phone: | (914) 393-5404 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 259063 |
| Latitude: | 40.9393454 |
| Longitude: | -73.7634046 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 09/15/04 ELITE ENVIRONMENTAL DISPOSED OF LUST AND 1.61 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo |
| Remarks: | Removed under ground tank and found holes in it. Soil is contaminated and Elite will be doing the clean up. |

All TTF:

| | |
|---|---|
| Facility ID: | 0402017 |
| Spill Number: | 0402017 |
| Spill Tank Test: | 1529297 |
| Site ID: | 321600 |
| Tank Number: | Not reported |
| Tank Size: | 275 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 321600 |
| Operable Unit ID: | 883827 |
| Operable Unit: | 01 |
| Material ID: | 493204 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**147**
**ENE**
**1/4-1/2**
**0.405 mi.**
**2140 ft.**

**BEZ - TTF**
**72 HOWELL AVE**
**LARCHMONT, NY**

**NY LTANKS** **S128913964**
**N/A**

**Relative:**
**Lower**

**Actual:**
**40 ft.**

LTANKS:

| | |
|---|---|
| Name: | BEZ - TTF |
| Address: | 72 HOWELL AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0000190 / 2000-04-18 |
| Facility ID: | 0000190 |
| Site ID: | 231198 |
| Spill Date: | 2000-04-05 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2000-04-05 |
| CID: | 312 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2000-04-05 |
| Spill Record Last Update: | 2022-07-05 |
| Spiller Name: | MR BEZ |
| Spiller Company: | Bez Residence |
| Spiller Address: | 72 HOWELL AVE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 190527 |
| Latitude: | 40.9369347 |
| Longitude: | -73.7511908 |
| DEC Memo: | 04/18/2000 TANK PASSED RETEST. NFA |
| Remarks: | WILL REPAIR PIPING AND RETEST - ULLAGE FAILURE |

All TTF:

| | |
|---|---|
| Facility ID: | 0000190 |
| Spill Number: | 0000190 |
| Spill Tank Test: | 1525448 |
| Site ID: | 231198 |
| Tank Number: | 001 |
| Tank Size: | 550 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 20 |
| Test Method 2: | USTest 2000/P/LL plus USTest 2000/U |

**BEZ - TTF (Continued)** **S128913964**

| | |
|---|---|
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

---

**AJ148** **RESIDENCE** **NY LTANKS** **S106124609**
**ESE** **2 CAMBRIDGE COURT** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.407 mi.**
**2149 ft.** **Site 1 of 4 in cluster AJ**

**Relative:**
**Lower**

**Actual:**
**18 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 2 CAMBRIDGE COURT |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0311004 / 2003-12-31 |
| Facility ID: | 0311004 |
| Site ID: | 293841 |
| Spill Date: | 2003-12-26 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Tank Truck |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 2003-12-26 |
| CID: | 402 |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-12-26 |
| Spill Record Last Update: | 2004-01-13 |
| Spiller Name: | ED ALLAN |
| Spiller Company: | ROBISON OIL |
| Spiller Address: | 500 EXECUTIVE BLVD |
| Spiller County: | 001 |
| Spiller Contact: | RAPP |
| Spiller Phone: | (914) 833-7036 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 237796 |
| Latitude: | 40.9325117 |
| Longitude: | -73.7511910 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY |
| Remarks: | OIL COMPANY OVER FILLED TANK. IT HAS BEEN RECOVERED |

All Materials:

| | |
|---|---|
| Site ID: | 293841 |
| Operable Unit ID: | 878770 |
| Operable Unit: | 01 |
| Material ID: | 499836 |

**RESIDENCE (Continued)** **S106124609**

| | |
|---|---|
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 1.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AJ149** **ESTATE OF LANDES** **NY LTANKS** **S106471661**
**SE** **10 CAMBRIDGE COURT** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.407 mi.**
**2151 ft.** **Site 2 of 4 in cluster AJ**

**Relative:** **Lower**
**Actual:** **24 ft.**

LTANKS:

| | |
|---|---|
| Name: | ESTATE OF LANDES |
| Address: | 10 CAMBRIDGE COURT |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0401701 / 2004-09-14 |
| Facility ID: | 0401701 |
| Site ID: | 217696 |
| Spill Date: | 2004-05-17 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-05-17 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-05-17 |
| Spill Record Last Update: | 2004-09-14 |
| Spiller Name: | JENEEN FERRARA |
| Spiller Company: | ESTATE OF LANDES |
| Spiller Address: | 10 CAMBRIDGE COURT |
| Spiller County: | 001 |
| Spiller Contact: | JENEEN FERRARA |
| Spiller Phone: | (914) 741-5472 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 180116 |
| Latitude: | 40.9324225 |
| Longitude: | -73.7512639 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 09/14/04 NES DISPOSED OF LUST AND 5.13 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo |
| Remarks: | REMOVING A 1000 GALLON TANK: HOLES IN TANK: |

**ESTATE OF LANDES (Continued)** **S106471661**

All Materials:

| | |
|---|---|
| Site ID: | 217696 |
| Operable Unit ID: | 885595 |
| Operable Unit: | 01 |
| Material ID: | 492896 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AK150** **SPILL NUMBER 9905950** **NY LTANKS** **S104620379**
**West** **10 ROCHELLE RD** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.411 mi.**
**2171 ft.** **Site 1 of 3 in cluster AK**

**Relative:** **Higher**
**Actual:** **107 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9905950 |
| Address: | 10 ROCHELLE RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9905950 / 2000-10-17 |
| Facility ID: | 9905950 |
| Site ID: | 215426 |
| Spill Date: | 1999-08-18 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-08-18 |
| CID: | 388 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-08-18 |
| Spill Record Last Update: | 2000-10-20 |
| Spiller Name: | KATE |
| Spiller Company: | KATE JARRETT |
| Spiller Address: | 10 ROCHELLE RD |
| Spiller County: | 001 |
| Spiller Contact: | CALLER |
| Spiller Phone: | (914) 697-7654 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 178438 |
| Latitude: | 40.9361476 |

**SPILL NUMBER 9905950 (Continued)** **S104620379**

Longitude: -73.7659350
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/17/2000 DUPLICATE REPORT. SEE SPILL 99-11157 FOR CLOSURE. NFA
Not reported
Remarks: caller reports tested tank and tank failed.

All TTF:
Facility ID: 9905950
Spill Number: 9905950
Spill Tank Test: 1547500
Site ID: 215426
Tank Number: 1
Tank Size: 1000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 215426
Operable Unit ID: 1084396
Operable Unit: 01
Material ID: 302228
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

**AK151** **SPILL NUMBER 9911157** **NY LTANKS** **S104620741**
**West** **10 ROCHELLE RD** **N/A**
**1/4-1/2** **MAMARONECK, NY**
**0.411 mi.**
**2171 ft.** **Site 2 of 3 in cluster AK**

**Relative:** **Higher**
**Actual:** **107 ft.**

LTANKS:
Name: SPILL NUMBER 9911157
Address: 10 ROCHELLE RD
City,State,Zip: MAMARONECK, NY
Spill Number/Closed Date: 9911157 / 2000-10-17
Facility ID: 9911157
Site ID: 215427
Spill Date: 1999-12-21
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: B4
Cleanup Ceased: Not reported

**SPILL NUMBER 9911157 (Continued)** **S104620741**

| | |
|---|---|
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-12-21 |
| CID: | 257 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-12-21 |
| Spill Record Last Update: | 2004-07-06 |
| Spiller Name: | MR JARRET |
| Spiller Company: | Not reported |
| Spiller Address: | 10 ROCHELLE RD |
| Spiller County: | 001 |
| Spiller Contact: | MR JARRET |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 283817 |
| Latitude: | 40.9359417 |
| Longitude: | -73.7665986 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 12/21/99 J. O'DEE SPOKE WITH HOMEOWNER. THIS IS A DUPLICATE SPILL. TANK ALREADY FAILED A TANK TEST IN AUGUST. 10/17/2000 ERS CONSULTANTS HIRED TO COMPLETE WORK. TANK WAS EXCAVATED AND DISPOSED OF BY SUB-CONTRACTOR, TAKE PRIDE EXCAVATING. 36.72 TONS OF CONTAMINATED SOIL WAS DISPOSED OF BY SUB CONTRACTOR, NORTHEAST ENVIRONMENTAL. ALSO REPORTED AS SPILL NUMBER 99-05950. NFA |
| Remarks: | CALLER IS REMOVING A 1000GAL TANK AND IT HAS HOLES IN IT AND THERE IS CONTAMINATED SOIL |

All Materials:

| | |
|---|---|
| Site ID: | 215427 |
| Operable Unit ID: | 1085862 |
| Operable Unit: | 01 |
| Material ID: | 563438 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**152**
**South**
**1/4-1/2**
**0.413 mi.**
**2179 ft.**

**SPILL NUMBER 8900768**
**4 WAKEMAN PLACE**
**LARCHMONT, NY**

**NY LTANKS** **S104619260**
**N/A**

**Relative:**
**Lower**

**Actual:**
**39 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 8900768 |
| Address: | 4 WAKEMAN PLACE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 8900768 / 1989-11-29 |
| Facility ID: | 8900768 |
| Site ID: | 89508 |
| Spill Date: | 1989-04-15 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | 1989-11-29 |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1989-04-25 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Citizen |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1989-05-01 |
| Spill Record Last Update: | 2004-01-13 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | 4 WAKEMAN PLACE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 81754 |
| Latitude: | 40.9293203 |
| Longitude: | -73.7576173 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY |
| Remarks: | UNDER GROUND 275 GAL. TNAK PRODUCT LEAKING INTO BASEMENT, SMALL PUDDLE IN BACK YARD OF OIL. DEC TO INVESTIGATE, INSURANCE COMPANY TO CHECK OUT. |

All Materials:

| | |
|---|---|
| Site ID: | 89508 |
| Operable Unit ID: | 927339 |
| Operable Unit: | 01 |
| Material ID: | 452096 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |

**SPILL NUMBER 8900768 (Continued)** **S104619260**

Recovered: .00
Oxygenate: Not reported

---

**AL153** **CITY PARK SERV BLUEBIRD T** **UST FINDER RELEASE** **1029060530**
**SW** **613 5TH AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY 0**
**0.415 mi.**
**2192 ft.** **Site 1 of 2 in cluster AL**

**Relative:**
**Lower**

**Actual:**
**29 ft.**

UST FINDER RELEASE:

| | |
|---|---|
| Object ID: | 262486 |
| Facility ID: | NY150530 |
| Lust ID: | NY9102785 |
| Name: | CITY PARK SERV BLUEBIRD T |
| Address: | 613 5TH AVE |
| City,State,Zip: | LARCHMONT, NY 0 |
| Address Match Type: | Not reported |
| Reported Date: | 1991/06/10 15:59:59+00 |
| Status: | No Further Action |
| Substance: | Not reported |
| Population within 1500ft: | 1668 |
| Domestic Wells within 1500ft: | 0 |
| Land Use: | Developed, Medium Intensity |
| Within SPA: | No |
| SPA PWS Facility ID: | Not reported |
| SPA Water Type: | Not reported |
| SPA Facility Type: | Not reported |
| SPA HUC12: | Not reported |
| Within WHPA: | No |
| WHPA PWS Facility ID: | Not reported |
| WHPA Water Type: | Not reported |
| WHPA Facility Type: | Not reported |
| WHPA HUC12: | Not reported |
| Within 100yr Floodplain: | Yes |
| Tribe: | Not reported |
| EPA Region: | 2 |
| NFA Letter 1: | Not reported |
| NFA Letter 2: | Not reported |
| NFA Letter 3: | Not reported |
| NFA Letter 4: | Not reported |
| Closed With Residual Contaminate: | Not reported |
| Coordinate Source: | State |
| X Coord: | -73.76644 |
| Y Coord: | 40.9315 |
| Latitude: | 40.9315 |
| Longitude: | -73.76644 |

**AK154** **PVT DWELLING** **NY LTANKS** **S110243973**
**West** **13 ROCHELLE ROAD** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.419 mi.**
**2211 ft.** **Site 3 of 3 in cluster AK**

**Relative:**
**Higher**

**Actual:**
**103 ft.**

LTANKS:

| | |
|---|---|
| Name: | PVT DWELLING |
| Address: | 13 ROCHELLE ROAD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0913558 / 2010-06-08 |
| Facility ID: | 0913558 |
| Site ID: | 426508 |
| Spill Date: | 2010-03-23 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2010-03-23 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2010-03-23 |
| Spill Record Last Update: | 2010-06-08 |
| Spiller Name: | Not reported |
| Spiller Company: | UNKNOWN |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | PAUL SCORZELLI |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 375374 |
| Latitude: | 40.9355217 |
| Longitude: | -73.7666887 |
| DEC Memo: | 3/23/10 - Left message to return phone call. KAB 6/8/2010: Closure documentation from NES reviewed and entered into eDocs. Based upon the information provided, no further action is required at this time. jod |
| Remarks: | 550gal ust |

All Materials:

| | |
|---|---|
| Site ID: | 426508 |
| Operable Unit ID: | 1182187 |
| Operable Unit: | 01 |
| Material ID: | 2176344 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |

**PVT DWELLING (Continued)** **S110243973**

Recovered: Not reported
Oxygenate: Not reported

---

**AM155** **LARCHMONT AVE CHURCH** **NY LTANKS** **S111738889**
**SSE** **60 FOREST PARK AVE** **NY Spills** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.419 mi.**
**2214 ft.** **Site 1 of 2 in cluster AM**

**Relative:**
**Higher**

**Actual:**
**43 ft.**

LTANKS:

| | |
|---|---|
| Name: | LARCHMONT AVE CHURCH |
| Address: | 60 FOREST PARK AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1114153 / 2013-03-28 |
| Facility ID: | 1114153 |
| Site ID: | 462194 |
| Spill Date: | 2012-03-21 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Class: | B3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2012-03-21 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2012-03-21 |
| Spill Record Last Update: | 2013-03-28 |
| Spiller Name: | BILL KINEZLE |
| Spiller Company: | LARCHMONT AVE CHURCH |
| Spiller Address: | 60 FOREST PARK AVE |
| Spiller County: | 999 |
| Spiller Contact: | BILL KINEZLE |
| Spiller Phone: | 914 834-1800 |
| Spiller Extention: | 304 |
| DEC Region: | 3 |
| DER Facility ID: | 416640 |
| Latitude: | 40.9300312 |
| Longitude: | -73.7540882 |
| DEC Memo: | 3-21-12: V.Mc. call to Bill/Church: Left Mess.: Req.Callbk. to Dispt. 3-21-12: Bill/Church callbk. to V.Mc./Dispt.: For follow up info try: Mr. Ruedi Laager/Church Member @ (914) 262-8886. Tank has been in service for the 20 years Bill has worked for chuch. 3-21-12: V.Mc. call to Ruedi/Church: Mr. Laager to advise the other member of the church board & develop a plan of action. 12/27/12 Tank is being pulled - see open spill # 12-14104...mm 3/28/2013: Remediation completed. Closure report from Madison Environmental entered into eDocs. Based upon information provided, no further action required at this time. jod |
| Remarks: | unk retest |

**LARCHMONT AVE CHURCH (Continued)** **S111738889**

All TTF:

| | |
|---|---|
| Facility ID: | 1114153 |
| Spill Number: | 1114153 |
| Spill Tank Test: | 2491812 |
| Site ID: | 462194 |
| Tank Number: | 0 |
| Tank Size: | 1000 |
| Material: | 0001 |
| EPA UST: | False |
| UST: | True |
| Cause: | 03 |
| Source: | 01 |
| Test Method: | 21 |
| Test Method 2: | Horner EZY3/EZY3 Locator Plus |
| Leak Rate: | Not reported |
| Gross Fail: | Not reported |
| Modified By: | jbodee |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 462194 |
| Operable Unit ID: | 1212262 |
| Operable Unit: | 01 |
| Material ID: | 2210126 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

SPILLS:

| | |
|---|---|
| Name: | LARCHMONT AVE CHURCH |
| Address: | 60 FOREST PARK AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1214104 / 2013-03-28 |
| Facility ID: | 1214104 |
| Facility Type: | ER |
| DER Facility ID: | 416640 |
| Site ID: | 477324 |
| DEC Region: | 3 |
| Spill Cause: | Equipment Failure |
| Spill Class: | B3 |
| SWIS: | 6032 |
| Spill Date: | 2012-12-27 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2012-12-27 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Source: | Institutional, Educational, Gov., Other |
| Spill Notifier: | Other |
| Cleanup Ceased: | Not reported |

**LARCHMONT AVE CHURCH (Continued)** **S111738889**

| | |
|---|---|
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2012-12-27 |
| Spill Record Last Update: | 2013-03-28 |
| Spiller Name: | JOE THOMASULO |
| Spiller Company: | LARCHMONT AVE CHURCH |
| Spiller Address: | 60 FOREST PARK AVE |
| Spiller Company: | 999 |
| Contact Name: | JOE THOMASULO |
| Latitude: | 40.9300312 |
| Longitude: | -73.7540882 |
| DEC Memo: | 12/27/12 This tank failed a tightness test and spill # 11-14153 was generated. Tank is being removed, contamination discovered and will be removed...mm 3/28/2013: Remediation completed. Closure report from Madison Environmental entered into eDocs. Based upon information provided, no further action required at this time. jod |
| Remarks: | soil contamination found during tank removal, c/u pending |

All Materials:

| | |
|---|---|
| Site ID: | 477324 |
| Operable Unit ID: | 1227134 |
| Operable Unit: | 01 |
| Material ID: | 2224355 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**156**
**East**
**1/4-1/2**
**0.420 mi.**
**2219 ft.**

**SUTIN RESIDENCE**
**21 COPLEY RD**
**LARCHMONT, NY**

**NY LTANKS** **S106000106**
**NY Spills** **N/A**

**Relative:**
**Lower**

**Actual:**
**27 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 0307108 |
| Address: | 21 COPLEY RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0307108 / 2003-12-03 |
| Facility ID: | 0307108 |
| Site ID: | 62335 |
| Spill Date: | 2003-10-06 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | A3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |

**SUTIN RESIDENCE (Continued)** **S106000106**

| | |
|---|---|
| Referred To: | Not reported |
| Reported to Dept: | 2003-10-06 |
| CID: | 365 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-10-06 |
| Spill Record Last Update: | 2003-12-03 |
| Spiller Name: | ALLEN SUTIN |
| Spiller Company: | Not reported |
| Spiller Address: | 21 COPLEY RD |
| Spiller County: | 001 |
| Spiller Contact: | ALLEN SUTIN |
| Spiller Phone: | (212) 801-9286 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 60445 |
| Latitude: | 40.9338178 |
| Longitude: | -73.7495153 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/09/03 ALSO SPILL 03-07140. 12/03/03 NORTHEST DISPOSED OF LUST AND 164.78 TONS OF CONTAMINATED SOIL. |
| Remarks: | odor of hydrocarbons detected in well point soil samples - failed tank test |

All TTF:

| | |
|---|---|
| Facility ID: | 0307108 |
| Spill Number: | 0307108 |
| Spill Tank Test: | 1528722 |
| Site ID: | 62335 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | F |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 62335 |
| Operable Unit ID: | 873663 |
| Operable Unit: | 01 |
| Material ID: | 500684 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |

**SUTIN RESIDENCE (Continued)** **S106000106**

| | |
|---|---|
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

SPILLS:

| | |
|---|---|
| Name: | SUTIN RESIDENCE |
| Address: | 21 COPLEY RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0307140 / 2003-12-03 |
| Facility ID: | 0307140 |
| Facility Type: | ER |
| DER Facility ID: | 60445 |
| Site ID: | 62336 |
| DEC Region: | 3 |
| Spill Cause: | Unknown |
| Spill Class: | A3 |
| SWIS: | 6000 |
| Spill Date: | 2003-10-07 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2003-10-07 |
| CID: | 390 |
| Water Affected: | Not reported |
| Spill Source: | Private Dwelling |
| Spill Notifier: | Tank Tester |
| Cleanup Ceased: | Not reported |
| Cleanup Meets Std: | True |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| UST Trust: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-10-07 |
| Spill Record Last Update: | 2005-04-22 |
| Spiller Name: | ALLEN SUTIN |
| Spiller Company: | SUTIN RESIDENCE |
| Spiller Address: | 21 COPLEY RD |
| Spiller Company: | 001 |
| Contact Name: | ALLEN SUTIN |
| Latitude: | 40.9338178 |
| Longitude: | -73.7495153 |
| DEC Memo: | 10/09/03 ALSO SPILL 03-07108. 12/03/03 NORTHEAST DISPOSED OF LUST AND 164.78 TONS OF CONTAMINATED SOIL. |
| Remarks: | soil contamination discovered near ust |

All Materials:

| | |
|---|---|
| Site ID: | 62336 |
| Operable Unit ID: | 873698 |
| Operable Unit: | 01 |
| Material ID: | 552402 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |

**SUTIN RESIDENCE (Continued)** **S106000106**

Units: G
Recovered: .00
Oxygenate: Not reported

---

**AN157** **SPILL NUMBER 0313036** **NY LTANKS** **S106123947**
**ESE** **7 HARMONY DRIVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.421 mi.**
**2221 ft.** **Site 1 of 2 in cluster AN**

**Relative:**
**Lower**

**Actual:**
**30 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 7 HARMONY DRIVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0311429 / 2004-04-26 |
| Facility ID: | 0311429 |
| Site ID: | 260818 |
| Spill Date: | 2004-01-09 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-01-09 |
| CID: | 404 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-01-09 |
| Spill Record Last Update: | 2004-04-26 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | RALPH LUCARELLI |
| Spiller Phone: | (914) 834-3068 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 213012 |
| Latitude: | 40.9332656 |
| Longitude: | -73.7500959 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/22/04 ALSO REPORTED AS SPILL 03-13036. NORTHEAST DISPOSED OF LUST AND 17.43 TONS OF CONTAMINATED SOIL. jbo |
| Remarks: | FAILED TEST. RECOMMEND UNCOVER REPAIR AND RETEST. |

All TTF:

| | |
|---|---|
| Facility ID: | 0311429 |
| Spill Number: | 0311429 |
| Spill Tank Test: | 1528903 |
| Site ID: | 260818 |

**SPILL NUMBER 0313036 (Continued)** **S106123947**

| | |
|---|---|
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

| | |
|---|---|
| Name: | SPILL NUMBER 0313036 |
| Address: | 7 HARMONY DRIVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0313036 / 2004-04-22 |
| Facility ID: | 0313036 |
| Site ID: | 260819 |
| Spill Date: | 2004-02-26 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-02-26 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-02-26 |
| Spill Record Last Update: | 2004-04-26 |
| Spiller Name: | MARY LUCARELLI |
| Spiller Company: | Not reported |
| Spiller Address: | 7 HARMONY DRIVE |
| Spiller County: | 001 |
| Spiller Contact: | MARY LUCARELLI |
| Spiller Phone: | (914) 834-3068 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 213012 |
| Latitude: | 40.9332656 |
| Longitude: | -73.7500959 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/22/04 ALSO REPORTED AS SPILL 03-11429. NORTHEAST DISPOSED OF LUST AND 17.43 TONS OF CONTAMINATED SOIL. jbo |
| Remarks: | WHILE REMOVING TANK FOUND HOLES IN TANK AND CONTAMINATED SOIL: |

All TTF:

| | |
|---|---|
| Facility ID: | 0313036 |

**SPILL NUMBER 0313036 (Continued)** **S106123947**

| | |
|---|---|
| Spill Number: | 0313036 |
| Spill Tank Test: | 1529001 |
| Site ID: | 260819 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 260819 |
| Operable Unit ID: | 880222 |
| Operable Unit: | 01 |
| Material ID: | 498205 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**158** **TTF** **NY LTANKS** **S104950688**
**NNE** **12 COOPER LANE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.421 mi.**
**2223 ft.**

**Relative:** **Higher**

**Actual:** **70 ft.**

LTANKS:

| | |
|---|---|
| Name: | TTF |
| Address: | 12 COOPER LANE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0013697 / 2009-12-30 |
| Facility ID: | 0013697 |
| Site ID: | 165408 |
| Spill Date: | 2001-03-31 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2001-03-31 |
| CID: | 281 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |

**TTF (Continued)** **S104950688**

| | |
|---|---|
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2001-03-31 |
| Spill Record Last Update: | 2009-12-30 |
| Spiller Name: | UNKNOWN |
| Spiller Company: | UNKNOWN |
| Spiller Address: | 12 COOPER LANE |
| Spiller County: | 001 |
| Spiller Contact: | DORSON ENVIORNMENTAL |
| Spiller Phone: | (914) 592-3117 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 344779 |
| Latitude: | 40.9409358 |
| Longitude: | -73.7546674 |
| DEC Memo: | 12/30/09: See spills 0301842 and 0713255. Tank was removed in 2007 and no leak or contamination was found. jod |
| Remarks: | TANK TEST FAILURE AT ABOVE LOCATION PERFORMED AT REQUEST OF DORSON ENVIORNMENTAL. DORSON HAS BEEN ADVISED OF RESULTS AND TANK TO BE UNCOVERED AND RETESTED. |

All TTF:

| | |
|---|---|
| Facility ID: | 0013697 |
| Spill Number: | 0013697 |
| Spill Tank Test: | 1526177 |
| Site ID: | 165408 |
| Tank Number: | 1 |
| Tank Size: | 1000 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | F |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 165408 |
| Operable Unit ID: | 835792 |
| Operable Unit: | 01 |
| Material ID: | 540396 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**TTF (Continued)** **S104950688**

| | |
|---|---|
| Name: | ANASTAS RESIDENCE |
| Address: | 12 COOPER LANE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0713255 / 2008-05-28 |
| Facility ID: | 0713255 |
| Site ID: | 394981 |
| Spill Date: | 2008-03-14 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2008-03-14 |
| CID: | 404 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | Not reported |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2008-03-14 |
| Spill Record Last Update: | 2008-05-28 |
| Spiller Name: | STEVEN ANASTAS |
| Spiller Company: | RESIDANCE |
| Spiller Address: | 12 COOPER LANE |
| Spiller County: | 001 |
| Spiller Contact: | STEVEN ANASTAS |
| Spiller Phone: | (914) 833-3442 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 344779 |
| Latitude: | 40.9410016 |
| Longitude: | -73.7544186 |
| DEC Memo: | 05/12/08 Northeast Environmental reported that they removed the tank and that no petroleum contaminated soil was observed in the excavation. Post excavation TAGM soil sample results were below DEC guidance values. NFA TG |
| Remarks: | method used Mesa 2 D; ullage potion leak |

All TTF:

| | |
|---|---|
| Facility ID: | 0713255 |
| Spill Number: | 0713255 |
| Spill Tank Test: | 2384849 |
| Site ID: | 394981 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0002 |
| EPA UST: | Not reported |
| UST: | True |
| Cause: | 99 |
| Source: | 99 |
| Test Method: | 00 |
| Test Method 2: | Unknown |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |

**TTF (Continued)** **S104950688**

Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 394981
Operable Unit ID: 1151928
Operable Unit: 01
Material ID: 2142695
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: TAYLOR RESIDENCE
Address: 12 COOPER LANE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 0301842 / 2003-06-17
Facility ID: 0301842
Site ID: 125348
Spill Date: 2003-05-21
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: D4
Cleanup Ceased: Not reported
SWIS: 6032
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2003-05-21
CID: 257
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-05-21
Spill Record Last Update: 2009-12-30
Spiller Name: PEGGY TAYLOR
Spiller Company: Not reported
Spiller Address: 12 COOPER LN
Spiller County: 001
Spiller Contact: PEGGY TAYLOR
Spiller Phone: (914) 391-3722
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 344779
Latitude: 40.9409358
Longitude: -73.7546674
DEC Memo: 06/17/03 TANK PASSED RETEST BY US TANK TECH. NFA jod 12/30/09: Also see spill 0713255 for tank removal. jod
Remarks: Not reported

**TTF (Continued)** **S104950688**

All Materials:

| | |
|---|---|
| Site ID: | 125348 |
| Operable Unit ID: | 868407 |
| Operable Unit: | 01 |
| Material ID: | 506328 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AG159** **DALEY RESIDENCE** **NY LTANKS** **S106385927**
**NNE** **2 HEATHER LANE** **N/A**
**1/4-1/2** **MAMARONECK, NY**
**0.423 mi.**
**2235 ft.** **Site 2 of 2 in cluster AG**

**Relative:** **Higher**
**Actual:** **79 ft.**

LTANKS:

| | |
|---|---|
| Name: | DALEY RESIDENCE |
| Address: | 2 HEATHER LANE |
| City,State,Zip: | MAMARONECK, NY |
| Spill Number/Closed Date: | 0400710 / 2004-06-04 |
| Facility ID: | 0400710 |
| Site ID: | 130559 |
| Spill Date: | 2004-04-21 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-04-21 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-04-21 |
| Spill Record Last Update: | 2004-06-04 |
| Spiller Name: | ELENOR DALEY |
| Spiller Company: | DALEY RESIDENCE |
| Spiller Address: | 2 HEATHER LANE |
| Spiller County: | 001 |
| Spiller Contact: | ELENOR DALEY |
| Spiller Phone: | (914) 834-8453 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 112499 |
| Latitude: | 40.9415617 |

**DALEY RESIDENCE (Continued)** **S106385927**

Longitude: -73.7563086
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/04/04 CASTLTON DISPOSED OF LUST AND 16.18 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDEDED, DEC REQUIRES NO FURTHER ACTION AT THIS TIME. jbo
Remarks: Not reported

All Materials:
Site ID: 130559
Operable Unit ID: 884910
Operable Unit: 01
Material ID: 491956
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

**AN160** **FORECLOSURE - TTF** **NY LTANKS** **S118638747**
**ESE** **18 ALDEN RD** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.429 mi.**
**2264 ft.** **Site 2 of 2 in cluster AN**

**Relative:** **Lower**
**Actual:** **39 ft.**

LTANKS:
Name: FORECLOSURE - TTF
Address: 18 ALDEN RD
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 1512394 / 2016-07-27
Facility ID: 1512394
Site ID: 525209
Spill Date: 2016-03-28
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6032
Investigator: JBODEE
Referred To: Not reported
Reported to Dept: 2016-03-31
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2016-03-31
Spill Record Last Update: 2016-07-27
Spiller Name: BANK OWNED
Spiller Company: Bank Owned
Spiller Address: 18 ALDEN RD
Spiller County: 999

**FORECLOSURE - TTF (Continued)** **S118638747**

| | |
|---|---|
| Spiller Contact: | PAUL SCORZELLI |
| Spiller Phone: | 9145573491 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 479418 |
| Latitude: | Not reported |
| Longitude: | Not reported |
| DEC Memo: | 3/31/16 Spoke to Scorzelli, who did not know who the owners are (bank contact). He was doing this for potential buyer. dw 7/27/16: Grazi-1 Environmental disposed of the leaking UST and a total of 11.86 tons of petroleum contaminated soil. Soil sample results were submitted for review. Documents entered into DecDocs. Based upon the information provided, no further action is required at this time. jod |
| Remarks: | 550 gallon tank test failure |

All Materials:

| | |
|---|---|
| Site ID: | 525209 |
| Operable Unit ID: | 1274169 |
| Operable Unit: | 01 |
| Material ID: | 2278719 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**AJ161** **RESIDENCE** **NY LTANKS** **S103238674**
**ESE** **3 CAMBRIDGE CT** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.429 mi.**
**2265 ft.** **Site 3 of 4 in cluster AJ**

**Relative:**
**Lower**

**Actual:**
**22 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 3 CAMBRIDGE CT |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9800085 / 1998-05-01 |
| Facility ID: | 9800085 |
| Site ID: | 161347 |
| Spill Date: | 1998-04-02 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1998-04-02 |
| CID: | 366 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |

**RESIDENCE (Continued)** **S103238674**

| | |
|---|---|
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-04-02 |
| Spill Record Last Update: | 1998-05-13 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 999 |
| Spiller Contact: | GREGORY HALL |
| Spiller Phone: | (914) 833-0438 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 136232 |
| Latitude: | 40.9324207 |
| Longitude: | -73.7510976 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 04-25-98 21.95 TONS OF SOIL REMOVED AND DISPOSED OF. |
| Remarks: | CALLER REPORTING THAT CONTAMINATED SOIL WAS FOUND IN AREA OF OLD UST. SOIL SAMPLES EXCEEDED LIMITS. HOMEOWNERS ADVISED TO HAVE TANK REMOVED. Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 161347 |
| Operable Unit ID: | 1057502 |
| Operable Unit: | 01 |
| Material ID: | 325639 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AI162** **104 NORTH CHATSWORTH AVE** **NY LTANKS** **S105999943**
**NW** **104 NORTH CHATSWORTH AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.434 mi.**
**2292 ft.** **Site 2 of 2 in cluster AI**

**Relative:** **Higher**
**Actual:** **86 ft.**

LTANKS:

| | |
|---|---|
| Name: | 104 NORTH CHATSWORTH AVE |
| Address: | 104 NORTH CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0306408 / 2004-03-23 |
| Facility ID: | 0306408 |
| Site ID: | 168951 |
| Spill Date: | 2003-09-17 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | A3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2003-09-17 |

**104 NORTH CHATSWORTH AVE (Continued)** **S105999943**

| | |
|---|---|
| CID: | 204 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | 2003-11-05 |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-09-17 |
| Spill Record Last Update: | 2004-03-23 |
| Spiller Name: | REAL ESTATE |
| Spiller Company: | 104 NORTH CHATSWORTH AVE |
| Spiller Address: | 104 NORTH CHATSWORTH AVE |
| Spiller County: | 001 |
| Spiller Contact: | PAOLA CORONEL |
| Spiller Phone: | (914) 747-9741 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 142289 |
| Latitude: | 40.9402498 |
| Longitude: | -73.7645876 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/31/03 ENVIROSTAR PULLED TANK. CONTAMINATION EXTENSIVE. H2M IS OVERSITE. DEC INSPECTING TODAY. 11/05/03 GROUND WATER MONITORING WELLS BEING INSTALLED. 03/23/04 ENVIROSTAR DISPOSED OF LUST AND 450 TONS OF CONTAMINATED SOIL. FINAL GROUND WATER SAMPLE RESULTS WERE ND. NO FURTHER ACTION REQUIRED AT THIS TIME. |
| Remarks: | TANK TEST FAILURE |

All TTF:

| | |
|---|---|
| Facility ID: | 0306408 |
| Spill Number: | 0306408 |
| Spill Tank Test: | 1528691 |
| Site ID: | 168951 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 168951 |
| Operable Unit ID: | 875132 |
| Operable Unit: | 01 |
| Material ID: | 503632 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |

**104 NORTH CHATSWORTH AVE (Continued)** **S105999943**

| | |
|---|---|
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AL163** **NYS THRUWAY** **UST FINDER RELEASE** **1029071422**
**SW** **629 FIFTH AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY 0**
**0.435 mi.**
**2296 ft.** **Site 2 of 2 in cluster AL**

**Relative:** **Lower**
**Actual:** **29 ft.**

UST FINDER RELEASE:

| | |
|---|---|
| Object ID: | 262517 |
| Facility ID: | NY280262 |
| Lust ID: | NY9301450 |
| Name: | NYS THRUWAY |
| Address: | 629 FIFTH AVE |
| City,State,Zip: | LARCHMONT, NY 0 |
| Address Match Type: | Not reported |
| Reported Date: | 1993/04/30 15:59:59+00 |
| Status: | No Further Action |
| Substance: | Not reported |
| Population within 1500ft: | 1785 |
| Domestic Wells within 1500ft: | 0 |
| Land Use: | Developed, Medium Intensity |
| Within SPA: | No |
| SPA PWS Facility ID: | Not reported |
| SPA Water Type: | Not reported |
| SPA Facility Type: | Not reported |
| SPA HUC12: | Not reported |
| Within WHPA: | No |
| WHPA PWS Facility ID: | Not reported |
| WHPA Water Type: | Not reported |
| WHPA Facility Type: | Not reported |
| WHPA HUC12: | Not reported |
| Within 100yr Floodplain: | Yes |
| Tribe: | Not reported |
| EPA Region: | 2 |
| NFA Letter 1: | Not reported |
| NFA Letter 2: | Not reported |
| NFA Letter 3: | Not reported |
| NFA Letter 4: | Not reported |
| Closed With Residual Contaminate: | Not reported |
| Coordinate Source: | State |
| X Coord: | -73.76595 |
| Y Coord: | 40.93165 |
| Latitude: | 40.9316499999999 |
| Longitude: | -73.76595 |

**164**
**NW**
**1/4-1/2**
**0.446 mi.**
**2355 ft.**

**SPILL NUMBER 0201523**
**101 NORTH CHATSWORTH AV**
**LARCHMONT, NY**

**NY LTANKS** **S105995844**
**N/A**

**Relative:**
**Higher**

**Actual:**
**99 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 0201523 |
| Address: | 101 NORTH CHATSWORTH AV |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0201523 / 2002-06-07 |
| Facility ID: | 0201523 |
| Site ID: | 314806 |
| Spill Date: | 2002-05-10 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2002-05-10 |
| CID: | 365 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2002-05-10 |
| Spill Record Last Update: | 2002-07-08 |
| Spiller Name: | NAUGHTON RESIDENCE |
| Spiller Company: | Not reported |
| Spiller Address: | 101 NORTH CHATSWORTH AV |
| Spiller County: | 001 |
| Spiller Contact: | NAUGHTON RESIDENCE |
| Spiller Phone: | (914) 834-5071 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 253801 |
| Latitude: | 40.9395440 |
| Longitude: | -73.7651234 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 06/07/02 - NORTHEAST DISPOSED OF TANK AND 11.02 TONS OF CONTAMIN SOIL. NFA |
| Remarks: | removed 275 gallon underground tank that had holes in it - they are hand excavating the contaminated soil now |

All Materials:

| | |
|---|---|
| Site ID: | 314806 |
| Operable Unit ID: | 852498 |
| Operable Unit: | 01 |
| Material ID: | 522940 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |

**SPILL NUMBER 0201523 (Continued)** **S105995844**

| | |
|---|---|
| Recovered: | .00 |
| Oxygenate: | Not reported |
| | |
| Name: | RESIDENTIAL TTF |
| Address: | 101 NORTH CHATSWORTH AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0200579 / 2005-02-09 |
| Facility ID: | 0200579 |
| Site ID: | 82904 |
| Spill Date: | 2002-04-16 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2002-04-16 |
| CID: | 205 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2002-04-16 |
| Spill Record Last Update: | 2023-06-20 |
| Spiller Name: | Not reported |
| Spiller Company: | Homeowner |
| Spiller Address: | 101 NOrth CHATSWORTH AVE |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 76363 |
| Latitude: | 40.9395440 |
| Longitude: | -73.7651234 |
| DEC Memo: | 02/09/05 ALSO REPORTED AS 02-01523. SEE THAT SPILL FOR ALL UPDATE INFORMATION. NFA THIS SPILL NUMBER. jbo |
| Remarks: | Not reported |

All TTF:

| | |
|---|---|
| Facility ID: | 0200579 |
| Spill Number: | 0200579 |
| Spill Tank Test: | 1527042 |
| Site ID: | 82904 |
| Tank Number: | 1 |
| Tank Size: | 275 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |

**SPILL NUMBER 0201523 (Continued)** **S105995844**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 82904
Operable Unit ID: 854019
Operable Unit: 01
Material ID: 522020
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

**AM165** **DURON RESIDENCE** **NY LTANKS** **S104278629**
**SSE** **174 LARCHMONT AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.450 mi.**
**2375 ft.** **Site 2 of 2 in cluster AM**

**Relative:**
**Lower**

**Actual:**
**38 ft.**

LTANKS:
Name: DURON RESIDENCE
Address: 174 LARCHMONT AVE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 9909450 / 2000-04-11
Facility ID: 9909450
Site ID: 299475
Spill Date: 1999-11-03
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 6000
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 1999-11-03
CID: 390
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1999-11-03
Spill Record Last Update: 2003-09-15
Spiller Name: MR/MRS DURON
Spiller Company: DURON RESIDENCE
Spiller Address: 174 LARCHMONT AVE
Spiller County: 001
Spiller Contact: MR/MRS DURON

**DURON RESIDENCE (Continued)** **S104278629**

| | |
|---|---|
| Spiller Phone: | (914) 833-0239 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 242263 |
| Latitude: | 40.9294152 |
| Longitude: | -73.7547293 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/11/2000 TAKE PRIDE DISPOSED OF TANK AND 54.35 TONS OF CONTAMINATED SOIL. NFA |
| Remarks: | tank failed underground - causing soil contamination |

All Materials:

| | |
|---|---|
| Site ID: | 299475 |
| Operable Unit ID: | 1084056 |
| Operable Unit: | 01 |
| Material ID: | 298536 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AO166** **FITCH RESIDENCE** **NY LTANKS** **S111063883**
**WNW** **3 WILDWOOD ROAD** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.452 mi.**
**2388 ft.** **Site 1 of 2 in cluster AO**

**Relative:**
**Higher**

**Actual:**
**125 ft.**

LTANKS:

| | |
|---|---|
| Name: | FITCH RESIDENCE |
| Address: | 3 WILDWOOD ROAD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1103135 / 2011-08-25 |
| Facility ID: | 1103135 |
| Site ID: | 450687 |
| Spill Date: | 2011-06-20 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2011-06-20 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2011-06-20 |
| Spill Record Last Update: | 2011-08-25 |

**FITCH RESIDENCE (Continued)** **S111063883**

| | |
|---|---|
| Spiller Name: | GROVER FITCH |
| Spiller Company: | GROVER FITCH |
| Spiller Address: | 3 WILDWOOD ROAD |
| Spiller County: | 999 |
| Spiller Contact: | GROVER FITCH |
| Spiller Phone: | (914) 834-1146 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 405249 |
| Latitude: | 40.9377717 |
| Longitude: | -73.7668286 |
| DEC Memo: | 6/20/11: Residential TTF for prospective real estate transaction. Potential buyer and their broker present for the test. Technician heard dripping, probable return line suction problem, oil dripping back into the tank from the line. Plan is to excavate, repair and retest. jod 08/16/11 Northeast Environmental reported that they excavated and removed the tank along with 20.03 tons of contaminated soil. Post excavation soil sample results were below DEC guidance values. NFA. TG |
| Remarks: | Tank test failure. Recommend uncover, repair, and retest. |

All Materials:

| | |
|---|---|
| Site ID: | 450687 |
| Operable Unit ID: | 1200889 |
| Operable Unit: | 01 |
| Material ID: | 2197340 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**167**
**SE**
**1/4-1/2**
**0.453 mi.**
**2390 ft.**

**KUNREUTHER - TTF**
**17 BONNETT AVENUE**
**LARCHMONT, NY**

**NY LTANKS** **S104515603**
**N/A**

**Relative:**
**Lower**

**Actual:**
**37 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENTIAL TTF |
| Address: | 17 BONNETT AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9902354 / 2000-07-19 |
| Facility ID: | 9902354 |
| Site ID: | 243264 |
| Spill Date: | 1999-06-01 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-06-01 |

**KUNREUTHER - TTF (Continued)** **S104515603**

| | |
|---|---|
| CID: | 252 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-06-01 |
| Spill Record Last Update: | 2018-10-10 |
| Spiller Name: | TOM GALLINGER |
| Spiller Company: | RESIDENCE |
| Spiller Address: | 17 BONNET AVE |
| Spiller County: | 001 |
| Spiller Contact: | TOM GALLINGER |
| Spiller Phone: | (914) 592-3117 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 199811 |
| Latitude: | 40.9307593 |
| Longitude: | -73.7507370 |
| DEC Memo: | Check Paper Files |
| Remarks: | Not reported |

All TTF:

| | |
|---|---|
| Facility ID: | 9902354 |
| Spill Number: | 9902354 |
| Spill Tank Test: | 1547213 |
| Site ID: | 243264 |
| Tank Number: | UST |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | False |
| UST: | True |
| Cause: | 99 |
| Source: | 00 |
| Test Method: | 21 |
| Test Method 2: | Horner EZY3/EZY3 Locator Plus |
| Leak Rate: | Not reported |
| Gross Fail: | Not reported |
| Modified By: | JBODEE |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 243264 |
| Operable Unit ID: | 1081271 |
| Operable Unit: | 01 |
| Material ID: | 305860 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

**KUNREUTHER - TTF (Continued)** **S104515603**

| | |
|---|---|
| Name: | KUNREUTHER - TTF |
| Address: | 17 BONNETT AVENUE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1007092 / 2010-10-27 |
| Facility ID: | 1007092 |
| Site ID: | 440479 |
| Spill Date: | 2010-10-01 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2010-10-01 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2010-10-01 |
| Spill Record Last Update: | 2018-10-10 |
| Spiller Name: | Jason Kunreuther |
| Spiller Company: | Kunreuther |
| Spiller Address: | 17 BONNETT LANE |
| Spiller County: | 999 |
| Spiller Contact: | JASON KUNREUTHER |
| Spiller Phone: | (914) 330-7899 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 395479 |
| Latitude: | 40.9312717 |
| Longitude: | -73.7513787 |
| DEC Memo: | 10-1-10: V.Mc. to Mr. Kunreuther: UST was installed in 1999, purchessed house in 2004, tank was tested at that time and passed. Mr. Kun.to have tank re-tested and may exc. soil off top of tank for re-test. UST has 30 year warranty. Advised Mr. Kun.to callbk to Dispt.when tank passes the re-test. 10-14-10: V.Mc.: Mr.Kunreuther to Dispt./V.Mc.: UST passed retest, checked J.O'Dee in basket, retest results not recived as of today's mail. 10/27/10: Tank passed a retest after piping was repaired. Report will be entered into eDocs. Based upon the information received, no further action is required at this time. jod |
| Remarks: | retest planned |

All Materials:

| | |
|---|---|
| Site ID: | 440479 |
| Operable Unit ID: | 1191093 |
| Operable Unit: | 01 |
| Material ID: | 2186209 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |

**KUNREUTHER - TTF (Continued)** **S104515603**

Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

---

**AJ168** **RESIDENCE** **NY LTANKS** **S106472001**
**ESE** **10 NASSAU RD** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.456 mi.**
**2408 ft.** **Site 4 of 4 in cluster AJ**

**Relative:** **Lower**
**Actual:** **18 ft.**

LTANKS:

| | |
|---|---|
| Name: | RESIDENCE |
| Address: | 10 NASSAU RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0403388 / 2004-10-28 |
| Facility ID: | 0403388 |
| Site ID: | 138656 |
| Spill Date: | 2004-06-29 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-06-29 |
| CID: | 405 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-06-29 |
| Spill Record Last Update: | 2004-10-28 |
| Spiller Name: | GEORGE BISCOV |
| Spiller Company: | RESIDENCE |
| Spiller Address: | 10 NASSAU RD |
| Spiller County: | 001 |
| Spiller Contact: | GEORGE BISCOV |
| Spiller Phone: | (917) 667-4501 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 118552 |
| Latitude: | 40.9320897 |
| Longitude: | -73.7504862 |
| DEC Memo: | 06/29/04 TANK FAILED TWO TANKS TESTS THAT WERE NOT REPORTED. HOLES FOUND IN TANK, CONTAMINATED SOIL BEING STOCKPILED. REPORT TO FOLLOW. jbo 10/28/04 ELITE ENVIRONMENTAL DISPOSED OF LUST AND 18.87 TONS OF CONTAMINATED SOIL. BASED UPON THE INFORMATION SUPPLIED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo |
| Remarks: | TANK REMOVAL, TANK FAILED |

All Materials:

| | |
|---|---|
| Site ID: | 138656 |
| Operable Unit ID: | 885632 |

**RESIDENCE (Continued)** **S106472001**

| | |
|---|---|
| Operable Unit: | 01 |
| Material ID: | 490974 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AP169** **DEPT PUBLIC WORKS** **NY LTANKS** **S104278291**
**SW** **MAXWELL AVE** **N/A**
**1/4-1/2** **MAMARONECK, NY**
**0.458 mi.**
**2420 ft.** **Site 1 of 2 in cluster AP**

**Relative:** **Lower**

**Actual:** **35 ft.**

LTANKS:

| | |
|---|---|
| Name: | DEPT PUBLIC WORKS |
| Address: | MAXWELL AVE |
| City,State,Zip: | MAMARONECK, NY |
| Spill Number/Closed Date: | 9907873 / 2003-12-05 |
| Facility ID: | 9907873 |
| Site ID: | 197874 |
| Spill Date: | 1999-09-29 |
| Spill Cause: | Tank Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | WCHD |
| Referred To: | Westchester Cnty Health Dept |
| Reported to Dept: | 1999-09-29 |
| CID: | 211 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | True |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-09-29 |
| Spill Record Last Update: | 2003-12-05 |
| Spiller Name: | Not reported |
| Spiller Company: | DEPT PUBLIC WORKS |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | JACQUELINE PATT |
| Spiller Phone: | (914) 561-1512 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 164673 |
| Latitude: | Not reported |
| Longitude: | Not reported |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-GOREAU 12/05/03 CLOSED BY STEFAN GOREAU OF WCHD. |
| Remarks: | CALLER DOING TANK REMOVAL AND FOUND SOIL CONTAMINATION |

**DEPT PUBLIC WORKS (Continued)** **S104278291**

All Materials:

| | |
|---|---|
| Site ID: | 197874 |
| Operable Unit ID: | 1086533 |
| Operable Unit: | 01 |
| Material ID: | 300556 |
| Material Code: | 0009 |
| Material Name: | gasoline |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AP170** **MAMARONECK DPW** **NY LTANKS** **S104194820**
**SW** **MAXWELL ST** **N/A**
**1/4-1/2** **MAMARONECK, NY**
**0.458 mi.**
**2420 ft.** **Site 2 of 2 in cluster AP**

**Relative:** **Lower**
**Actual:** **35 ft.**

LTANKS:

| | |
|---|---|
| Name: | MAMARONECK DPW |
| Address: | MAXWELL ST |
| City,State,Zip: | MAMARONECK, NY |
| Spill Number/Closed Date: | 9906831 / 2005-09-20 |
| Facility ID: | 9906831 |
| Site ID: | 217177 |
| Spill Date: | 1999-09-08 |
| Spill Cause: | Tank Failure |
| Spill Source: | Major Facility (MOSF) > 400,000 gal |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1999-09-08 |
| CID: | 388 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | True |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-09-08 |
| Spill Record Last Update: | 2005-09-20 |
| Spiller Name: | SHAIMON GITLITZ |
| Spiller Company: | TOWN OF MAMARONECK |
| Spiller Address: | 740 W BOSTON RD |
| Spiller County: | 001 |
| Spiller Contact: | CALLER |
| Spiller Phone: | (914) 561-1512 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 179794 |
| Latitude: | Not reported |

**MAMARONECK DPW (Continued)** **S104194820**

Longitude: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/22/99 LETTER SENT BY T. GHIOSAY; SITE INSPECTION CONDUCTED. A SIGNIFIANT QUANITY OF GASOLINE POSSIBLY MIXED WITH DIESEL PRESENT ON SURFACE OF GROUNDWATER AT BASE OF EXCAVATION. GROUNDWATER INVESTIGATION WORK PLAN MUST BE SUBMITTED TO DEC. 11/19/99 GROUNDWATER INVESTIGATION PROPOSAL RECEIVED FROM EMCON. PROJECT MANAGER IS STEVEN GOLDBERG 201-512-5700. PROPOSAL WAS ACCEPTABLE. 09-23-04 Semi-annual groundwater monitoring report rec'd from Shaw Environmental and Infrastructure. Report includes monitoring data from Dec 03 and March o4 from 3 site wells. Quarterly monitoring and semiannual reporting to continue. 09/15/05 Semi Annula report submitted by Shaw Environmental. Based on the info contained in that report, NFA required. TG
Remarks: caller reports they pulled tanks and found contaminted soil and are also pulling dispensers which are probably the source.

All Materials:

Site ID: 217177
Operable Unit ID: 1081132
Operable Unit: 01
Material ID: 299550
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: True

Site ID: 217177
Operable Unit ID: 1081132
Operable Unit: 01
Material ID: 575401
Material Code: 1213A
Material Name: MTBE (methyl-tert-butyl ether)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: True

Site ID: 217177
Operable Unit ID: 1081132
Operable Unit: 01
Material ID: 575402
Material Code: 2645A
Material Name: BTEX
Case No.: Not reported
Material FA: Oxygenates
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: True

**AQ171** **VACANT BUILDING** **UST FINDER RELEASE** **1029074685**
**WSW** **615 5TH AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY 0**
**0.463 mi.**
**2443 ft.** **Site 1 of 2 in cluster AQ**

**Relative:** **Lower**
**Actual:** **29 ft.**

UST FINDER RELEASE:

| | |
|---|---|
| Object ID: | 262495 |
| Facility ID: | NY336030 |
| Lust ID: | NY106935 |
| Name: | VACANT BUILDING |
| Address: | 615 5TH AVE |
| City,State,Zip: | LARCHMONT, NY 0 |
| Address Match Type: | Not reported |
| Reported Date: | 2001/08/10 15:59:59+00 |
| Status: | No Further Action |
| Substance: | Not reported |
| Population within 1500ft: | 1703 |
| Domestic Wells within 1500ft: | 0 |
| Land Use: | Developed, Medium Intensity |
| Within SPA: | No |
| SPA PWS Facility ID: | Not reported |
| SPA Water Type: | Not reported |
| SPA Facility Type: | Not reported |
| SPA HUC12: | Not reported |
| Within WHPA: | No |
| WHPA PWS Facility ID: | Not reported |
| WHPA Water Type: | Not reported |
| WHPA Facility Type: | Not reported |
| WHPA HUC12: | Not reported |
| Within 100yr Floodplain: | Yes |
| Tribe: | Not reported |
| EPA Region: | 2 |
| NFA Letter 1: | Not reported |
| NFA Letter 2: | Not reported |
| NFA Letter 3: | Not reported |
| NFA Letter 4: | Not reported |
| Closed With Residual Contaminate: | Not reported |
| Coordinate Source: | State |
| X Coord: | -73.76632 |
| Y Coord: | 40.93154 |
| Latitude: | 40.9315399999999 |
| Longitude: | -73.7663199999999 |

---

**AR172** **PRIVATE HOME** **NY LTANKS** **S109064234**
**West** **259 BARNARD RD** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.465 mi.**
**2457 ft.** **Site 1 of 2 in cluster AR**

**Relative:** **Higher**
**Actual:** **105 ft.**

LTANKS:

| | |
|---|---|
| Name: | PRIVATE HOME |
| Address: | 259 BARNARD RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0800316 / 2008-06-30 |
| Facility ID: | 0800316 |
| Site ID: | 396052 |
| Spill Date: | 2008-04-08 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |

**PRIVATE HOME (Continued)** **S109064234**

| | |
|---|---|
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2008-04-08 |
| CID: | 408 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | Not reported |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2008-04-08 |
| Spill Record Last Update: | 2008-06-30 |
| Spiller Name: | SUSAN INGALL |
| Spiller Company: | PRIVATE HOME |
| Spiller Address: | 259 BARNARD RD |
| Spiller County: | 001 |
| Spiller Contact: | SUSAN INGALL |
| Spiller Phone: | (914) 834-9787 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 345545 |
| Latitude: | 40.9349917 |
| Longitude: | -73.7675887 |
| DEC Memo: | 06/23/08 Envirostar Corp. reported that they excavated and removed one 550 gallon tank. No petroleum contaminated soil was present in the excavation. Post excavation soil sample results were below DEC guidance values. NFA. TG |
| Remarks: | RECOMMEND UNCOVER, REPAIR AND RETEST; |

All TTF:

| | |
|---|---|
| Facility ID: | 0800316 |
| Spill Number: | 0800316 |
| Spill Tank Test: | 2384990 |
| Site ID: | 396052 |
| Tank Number: | Not reported |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | True |
| Cause: | 99 |
| Source: | 01 |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Watchdog |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 396052 |
| Operable Unit ID: | 1152996 |
| Operable Unit: | 01 |
| Material ID: | 2143775 |

**PRIVATE HOME (Continued)** **S109064234**

| | |
|---|---|
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**173** **APT BLD** **NY LTANKS** **S110769599**
**ESE** **11 ALDEN RD** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.475 mi.**
**2510 ft.**

**Relative:** **Lower**

**Actual:** **33 ft.**

LTANKS:

| | |
|---|---|
| Name: | APT BLD |
| Address: | 11 ALDEN RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1011710 / 2011-05-20 |
| Facility ID: | 1011710 |
| Site ID: | 445598 |
| Spill Date: | 2011-02-23 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2011-02-23 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2011-02-23 |
| Spill Record Last Update: | 2011-06-01 |
| Spiller Name: | DONNA HENCHELL |
| Spiller Company: | APT BLD |
| Spiller Address: | 11 ALDEN RD |
| Spiller County: | 999 |
| Spiller Contact: | DONNA HENCHELL |
| Spiller Phone: | (718) 796-5022 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 400430 |
| Latitude: | 40.9334617 |
| Longitude: | -73.7490686 |
| DEC Memo: | 2-23-11: V.Mc. to Ms.Donna Henchell: Just found out about TTF, left mess with tester & waitingon callbk.,(Ms.Donna H.) To make arrangements for retesting. Results to be submitted to WCHD. 3/3/11: PBS TTF, Wayne Schneider will handle. jod 5/20/11 As per WCDOH 1011710: 11 alden rd, Larchmont- ttf, passed retest 3/11/11 after |

**APT BLD (Continued)** **S110769599**

replacing fitting n return line(aboveground). No contamination NFA JO'M
Remarks: vaulted above ground failed tank test. retest pending

All Materials:
Site ID: 445598
Operable Unit ID: 1195980
Operable Unit: 01
Material ID: 2192111
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Name: COMMERCIAL
Address: 11 ALDEN ROAD
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 0602133 / 2006-09-22
Facility ID: 0602133
Site ID: 364540
Spill Date: 2006-05-26
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6032
Investigator: JBODee
Referred To: WCDOH
Reported to Dept: 2006-05-26
CID: 408
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2006-05-26
Spill Record Last Update: 2006-09-22
Spiller Name: DONNA HENTSCHEL
Spiller Company: COMMERCIAL
Spiller Address: 11 ALDEN ROAD
Spiller County: 001
Spiller Contact: DONNA HENTSCHEL
Spiller Phone: (914) 793-5610
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 314757
Latitude: 40.9334617
Longitude: -73.7490686
DEC Memo: PBS 3-068551 7/31/06 Danielle Jackson from WCHD: 11 Alden Road, Larchmont, NY repaired and retested 6-19-06 and passed, NFA
Remarks: Not reported

**APT BLD (Continued)** **S110769599**

All Materials:

| | |
|---|---|
| Site ID: | 364540 |
| Operable Unit ID: | 1122563 |
| Operable Unit: | 01 |
| Material ID: | 2112029 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AO174** **SPILL NUMBER 9812365** **NY LTANKS** **S104619912**
**WNW** **1 SETON RD** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.476 mi.**
**2513 ft.** **Site 2 of 2 in cluster AO**

**Relative:** **Higher**

**Actual:** **117 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9812365 |
| Address: | 1 SETON RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9812365 / 1999-03-09 |
| Facility ID: | 9812365 |
| Site ID: | 319993 |
| Spill Date: | 1999-01-06 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-01-06 |
| CID: | 384 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-01-06 |
| Spill Record Last Update: | 1999-03-16 |
| Spiller Name: | EDWARD HELWIG |
| Spiller Company: | EDWARD HELWIG |
| Spiller Address: | 1 SETON RD |
| Spiller County: | 001 |
| Spiller Contact: | EDWARD HELWIG |
| Spiller Phone: | (914) 834-4672 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 257809 |
| Latitude: | 40.9386344 |

**SPILL NUMBER 9812365 (Continued)** **S104619912**

Longitude: -73.7668272
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 3/3/99 1100 GALLON #2 FUEL TANK PASSED RETEST 3/3/99. NO CONTAMINATION OBSERVED IN AREAS EXCAVATED.
Remarks: TANK WAS TESTED FOR A REAL ESTATE TRANSACTION.

All TTF:
Facility ID: 9812365
Spill Number: 9812365
Spill Tank Test: 1546716
Site ID: 319993
Tank Number: 1
Tank Size: 1100
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: F
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 319993
Operable Unit ID: 1069622
Operable Unit: 01
Material ID: 563593
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

**175** **MARMON - TTF** **NY LTANKS** **S105230022**
**NNW** **36 COLONIAL AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.476 mi.**
**2515 ft.**

**Relative: Higher**
**Actual: 99 ft.**

LTANKS:
Name: MARMON - TTF
Address: 36 COLONIAL AVE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 0107574 / 2002-03-14
Facility ID: 0107574
Site ID: 228035
Spill Date: 2001-10-24
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: D4
Cleanup Ceased: Not reported

**MARMON - TTF (Continued)** **S105230022**

| | |
|---|---|
| SWIS: | 6032 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2001-10-24 |
| CID: | 396 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2001-10-24 |
| Spill Record Last Update: | 2023-05-09 |
| Spiller Name: | JAMES MARMON |
| Spiller Company: | Marmon |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | Not reported |
| Spiller Phone: | Not reported |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 188096 |
| Latitude: | 40.9425788 |
| Longitude: | -73.7608496 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 03/14/2002 ADVANCED ENV. PULLED TANK. NO LEAK OR CONTAMINATION EVIDENT. NO FURTHER ACTION. |
| Remarks: | uncover repair retest. |

All TTF:

| | |
|---|---|
| Facility ID: | 0107574 |
| Spill Number: | 0107574 |
| Spill Tank Test: | 1526677 |
| Site ID: | 228035 |
| Tank Number: | 1 |
| Tank Size: | 1000 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 228035 |
| Operable Unit ID: | 844810 |
| Operable Unit: | 01 |
| Material ID: | 532389 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |

**MARMON - TTF (Continued)** **S105230022**

| | |
|---|---|
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**AR176** **SPILL NUMBER 0108033** **NY LTANKS** **S105230060**
**West** **260 BARNARD RD** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.478 mi.**
**2523 ft.** **Site 2 of 2 in cluster AR**

**Relative:**
**Higher**

**Actual:**
**111 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 0108033 |
| Address: | 260 BARNARD RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0108033 / 2002-03-13 |
| Facility ID: | 0108033 |
| Site ID: | 80897 |
| Spill Date: | 2001-11-06 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2001-11-07 |
| CID: | 270 |
| Water Affected: | Not reported |
| Spill Notifier: | Affected Persons |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2001-11-07 |
| Spill Record Last Update: | 2002-04-30 |
| Spiller Name: | MR WHITE |
| Spiller Company: | MR WITHE |
| Spiller Address: | 260 BARNARD RD |
| Spiller County: | 001 |
| Spiller Contact: | MR WHITE |
| Spiller Phone: | (914) 834-1338 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 74919 |
| Latitude: | 40.9350967 |
| Longitude: | -73.7679026 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 03/13/2002 ADVANCED ENV. DISPOSED OF TANK AND 19.31 TONS OF CONTAMINATED SOIL. NO FURTHER ACTION. |
| Remarks: | CONTAMINATED SOIL DISCOVERED FROM TANK REMOVAL |

All Materials:

| | |
|---|---|
| Site ID: | 80897 |
| Operable Unit ID: | 845273 |

**SPILL NUMBER 0108033 (Continued)** **S105230060**

| | |
|---|---|
| Operable Unit: | 01 |
| Material ID: | 529288 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**177**
**SW**
**1/4-1/2**
**0.478 mi.**
**2525 ft.**

**CHATSWORTH COAL AND SUPPLY SITE**
**2101, 2103 AND 2101-2103 PALMER AVENUE**
**LARCHMONT, NY 10538**

**NY ENG CONTROLS** **S118372432**
**NY INST CONTROL** **N/A**
**NY BROWNFIELDS**

**Relative:**
**Lower**

**Actual:**
**39 ft.**

ENG CONTROLS:

| | |
|---|---|
| Name: | CHATSWORTH COAL AND SUPPLY SITE |
| Address: | 2101, 2103 AND 2101-2103 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Site Code: | 484785 |
| HW Code: | C360132 |
| Control Code: | 15 |
| Control Type: | ENG |
| Date Record Added: | 12/21/2015 |
| Date Rec Updated: | 04/18/2025 |
| Updated By: | ARMALAME |
| Site Description: | Location: The site is located at 2101 Palmer Avenue, 2103 Palmer Avenue and 2101-2103 Palmer Avenue in Larchmont, Westchester County, and consists of two tax parcels and a portion of a third, totaling approximately 1.98 acres in size. Site Features: At the start of the BCP project, the property was primarily vacant, with no structures. With the exception of one bedrock outcrop, the entire site was paved. The former MTA parcel consisted of a gravel road with a rail line at ground surface. Now that contamination has been removed, construction of two four-story residential buildings is complete. Current Zoning and Land Use: The site property is currently zoned for commercial use, but the County has approved construction of residential, multi-family housing with portions set aside for affordable workforce housing. As noted above, construction of two four-story residential buildings is now complete. Prior to acceptance into the BCP, the site was used for contractor storage/commercial use. Past Use of the Site: The site was part of the Chatsworth Coal and Supply Company since around 1919 and had railroad tracks running through it. By 1947, several structures related to Henigson's Building Materials had been constructed on the site's northeastern corner. By 1974, a designated parking area had been added in the southern portion of the site. The MTA parcel contained a rail spur that continued south onto the larger parcels. Site Geology and Hydrogeology: The site is at an elevation of approximately 36 feet above mean sea level (AMSL) at the northern end and 27 feet AMSL at the southern end. The site is underlain by granitic gneiss, which is likely part of the Harrison Gneiss formation. Approximately 14 feet of soil overlays the gneiss bedrock. A thin layer of native soils is the uppermost hydrogeologic unit. This aquifer consists primarily of glacial tills consisting of a poorly sorted mixture of sand, silt, clay, gravel, and boulders. The |

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

| | |
|---|---|
| | till typically has a low to moderate permeability, and overlays the metamorphic bedrock. Depth of water in the vicinity of the site is estimated to be about 8 feet below grade. Groundwater flow is typically west to southwest. |
| Env Problem: | Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were metals (lead, barium and chromium) and PAHs (benzo(a)pyrene, benzo(b)fluoranthene, and chrysene) in soil; PAHs and VOCs in groundwater; and VOCs in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and soil vapor is being managed under a Site Management Plan. |
| | Not reported |
| Health Problem: | Measures are in place to control the potential for coming into contact with subsurface soil and groundwater contamination remaining on the site. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that obtains water from a source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to control the potential for inhalation of site-contaminants in indoor air due to soil vapor intrusion. Sampling indicates soil vapor intrusion is not a concern for off-site buildings. |
| Dump: | False |
| Structure: | False |
| Lagoon: | False |
| Landfill: | False |
| Pond: | False |
| Disp Start: | Not reported |
| Disp Term: | Not reported |
| Lat/Long: | Not reported |
| Dell: | Not reported |
| Record Add: | 2013-07-25 14:43:00 |
| Record Upd: | 2015-12-18 08:45:00 |
| Updated By: | SXDEYETT |
| Own Op: | Document Repository |
| Sub Type: | NNN |
| Owner Name: | Not reported |
| Owner Company: | Larchmont Public Library |
| Owner Address: | 121 Larchmont Avenue |
| Owner Addr2: | Not reported |
| Owner City,St,Zip: | Larchmont, NY 10538 |
| Owner Country: | United States of America |
| Own Op: | 1 |
| Sub Type: | E |
| Owner Name: | Rosemarie Noonan |
| Owner Company: | Palmer Avenue Housing Development Fund Company |
| Owner Address: | 55 S. Broadway, Suite 2 |
| Owner Addr2: | Not reported |
| Owner City,St,Zip: | Tarrytown, NY 10591-4000 |
| Owner Country: | United States of America |
| Own Op: | 1 |
| Sub Type: | E |
| Owner Name: | Ana Nelson |

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

| | |
|---|---|
| Owner Company: | Gramatan Management, Inc. |
| Owner Address: | 2975 Westchester Ave |
| Owner Addr2: | Suite G01 |
| Owner City,St,Zip: | Purchase, NY 10577 |
| Owner Country: | United States of America |
| Own Op: | Document Repository |
| Sub Type: | NNN |
| Owner Name: | Not reported |
| Owner Company: | NYSDEC Region 3 Office |
| Owner Address: | 21 S. Putt Corners Road |
| Owner Addr2: | Not reported |
| Owner City,St,Zip: | New Paltz, NY 12561 |
| Owner Country: | United States of America |
| HW Code: | C360132 |
| Waste Type: | BARIUM |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | CHROMIUM |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | TRICHLOROETHENE (TCE) |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | indeno(1,2,3-cd)pyrene |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | BENZ(A)ANTHRACENE |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | LEAD |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | BENZO(B)FLUORANTHENE |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | Chrysene |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | DIBENZ[A,H]ANTHRACENE |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | cis-1,2-Dichloroethene |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | TETRACHLOROETHYLENE (PCE) |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

| | |
|---|---|
| HW Code: | C360132 |
| Waste Type: | BENZO(A)PYRENE |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | benzo(k)fluoranthene |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | tetrachloroethene (PCE) |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | benzo(a)anthracene |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | BENZO[K]FLUORANTHENE |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| Crossref ID: | 1202766 |
| Cross Ref Type Code: | 01 |
| Cross Ref Type: | Spill No. |
| Record Added Date: | 2013-08-05 10:02:00 |
| Record Updated: | 2013-08-05 10:02:00 |
| Updated By: | BRWOLOSE |
| Crossref ID: | C360132-10-13 |
| Cross Ref Type Code: | 23 |
| Cross Ref Type: | Agreement/Consent Order Number |
| Record Added Date: | 2015-12-18 08:50:00 |
| Record Updated: | 2015-12-18 08:50:00 |
| Updated By: | SXDEYETT |
| Crossref ID: | 553503297 |
| Cross Ref Type Code: | 25 |
| Cross Ref Type: | County Recording Identifier |
| Record Added Date: | 2015-08-25 11:40:00 |
| Record Updated: | 2015-12-18 08:49:00 |
| Updated By: | SXDEYETT |
| Crossref ID: | 553503316 |
| Cross Ref Type Code: | 25 |
| Cross Ref Type: | County Recording Identifier |
| Record Added Date: | 2015-12-18 08:49:00 |
| Record Updated: | 2015-12-18 08:49:00 |
| Updated By: | SXDEYETT |

| | |
|---|---|
| Name: | CHATSWORTH COAL AND SUPPLY SITE |
| Address: | 2101, 2103 AND 2101-2103 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Site Code: | 484785 |
| HW Code: | C360132 |
| Control Code: | 13 |
| Control Type: | ENG |
| Date Record Added: | 12/21/2015 |
| Date Rec Updated: | 04/18/2025 |
| Updated By: | ARMALAME |
| Site Description: | Location: The site is located at 2101 Palmer Avenue, 2103 Palmer Avenue and 2101-2103 Palmer Avenue in Larchmont, Westchester County, |

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

and consists of two tax parcels and a portion of a third, totaling approximately 1.98 acres in size. Site Features: At the start of the BCP project, the property was primarily vacant, with no structures. With the exception of one bedrock outcrop, the entire site was paved. The former MTA parcel consisted of a gravel road with a rail line at ground surface. Now that contamination has been removed, construction of two four-story residential buildings is complete. Current Zoning and Land Use: The site property is currently zoned for commercial use, but the County has approved construction of residential, multi-family housing with portions set aside for affordable workforce housing. As noted above, construction of two four-story residential buildings is now complete. Prior to acceptance into the BCP, the site was used for contractor storage/commercial use. Past Use of the Site: The site was part of the Chatsworth Coal and Supply Company since around 1919 and had railroad tracks running through it. By 1947, several structures related to Henigson's Building Materials had been constructed on the site's northeastern corner. By 1974, a designated parking area had been added in the southern portion of the site. The MTA parcel contained a rail spur that continued south onto the larger parcels. Site Geology and Hydrogeology: The site is at an elevation of approximately 36 feet above mean sea level (AMSL) at the northern end and 27 feet AMSL at the southern end. The site is underlain by granitic gneiss, which is likely part of the Harrison Gneiss formation. Approximately 14 feet of soil overlays the gneiss bedrock. A thin layer of native soils is the uppermost hydrogeologic unit. This aquifer consists primarily of glacial tills consisting of a poorly sorted mixture of sand, silt, clay, gravel, and boulders. The till typically has a low to moderate permeability, and overlays the metamorphic bedrock. Depth of water in the vicinity of the site is estimated to be about 8 feet below grade. Groundwater flow is typically west to southwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were metals (lead, barium and chromium) and PAHs (benzo(a)pyrene, benzo(b)fluoranthene, and chrysene) in soil; PAHs and VOCs in groundwater; and VOCs in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and soil vapor is being managed under a Site Management Plan.
Not reported

Health Problem: Measures are in place to control the potential for coming into contact with subsurface soil and groundwater contamination remaining on the site. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that obtains water from a source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to control the potential for inhalation of site-contaminants in indoor air due to soil vapor intrusion. Sampling indicates soil vapor intrusion is not a concern for off-site buildings.

Dump: False
Structure: False
Lagoon: False
Landfill: False

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

| | |
|---|---|
| Pond: | False |
| Disp Start: | Not reported |
| Disp Term: | Not reported |
| Lat/Long: | Not reported |
| Dell: | Not reported |
| Record Add: | 2013-07-25 14:43:00 |
| Record Upd: | 2015-12-18 08:45:00 |
| Updated By: | SXDEYETT |
| Own Op: | Document Repository |
| Sub Type: | NNN |
| Owner Name: | Not reported |
| Owner Company: | Larchmont Public Library |
| Owner Address: | 121 Larchmont Avenue |
| Owner Addr2: | Not reported |
| Owner City,St,Zip: | Larchmont, NY 10538 |
| Owner Country: | United States of America |
| Own Op: | 1 |
| Sub Type: | E |
| Owner Name: | Rosemarie Noonan |
| Owner Company: | Palmer Avenue Housing Development Fund Company |
| Owner Address: | 55 S. Broadway, Suite 2 |
| Owner Addr2: | Not reported |
| Owner City,St,Zip: | Tarrytown, NY 10591-4000 |
| Owner Country: | United States of America |
| Own Op: | 1 |
| Sub Type: | E |
| Owner Name: | Ana Nelson |
| Owner Company: | Gramatan Management, Inc. |
| Owner Address: | 2975 Westchester Ave |
| Owner Addr2: | Suite G01 |
| Owner City,St,Zip: | Purchase, NY 10577 |
| Owner Country: | United States of America |
| Own Op: | Document Repository |
| Sub Type: | NNN |
| Owner Name: | Not reported |
| Owner Company: | NYSDEC Region 3 Office |
| Owner Address: | 21 S. Putt Corners Road |
| Owner Addr2: | Not reported |
| Owner City,St,Zip: | New Paltz, NY 12561 |
| Owner Country: | United States of America |
| HW Code: | C360132 |
| Waste Type: | BARIUM |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | CHROMIUM |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | TRICHLOROETHENE (TCE) |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | indeno(1,2,3-cd)pyrene |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

| | |
|---|---|
| Waste Type: | BENZ(A)ANTHRACENE |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | LEAD |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | BENZO(B)FLUORANTHENE |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | Chrysene |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | DIBENZ[A,H]ANTHRACENE |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | cis-1,2-Dichloroethene |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | TETRACHLOROETHYLENE (PCE) |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | BENZO(A)PYRENE |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | benzo(k)fluoranthene |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | tetrachloroethene (PCE) |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | benzo(a)anthracene |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | BENZO[K]FLUORANTHENE |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| Crossref ID: | 1202766 |
| Cross Ref Type Code: | 01 |
| Cross Ref Type: | Spill No. |
| Record Added Date: | 2013-08-05 10:02:00 |
| Record Updated: | 2013-08-05 10:02:00 |
| Updated By: | BRWOLOSE |
| Crossref ID: | C360132-10-13 |
| Cross Ref Type Code: | 23 |
| Cross Ref Type: | Agreement/Consent Order Number |
| Record Added Date: | 2015-12-18 08:50:00 |

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

Record Updated: 2015-12-18 08:50:00
Updated By: SXDEYETT
Crossref ID: 553503297
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-08-25 11:40:00
Record Updated: 2015-12-18 08:49:00
Updated By: SXDEYETT
Crossref ID: 553503316
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-12-18 08:49:00
Record Updated: 2015-12-18 08:49:00
Updated By: SXDEYETT

INST CONTROL:
Name: CHATSWORTH COAL AND SUPPLY SITE
Address: 2101, 2103 AND 2101-2103 PALMER AVENUE
City,State,Zip: LARCHMONT, NY 10538
Site Code: 484785
Control Name: Landuse Restriction
HW Code: C360132
Control Code: 25
Control Type: INST
Dt record added: 12/21/2015
Dt rec updated: 04/18/2025
Updated By: ARMALAME
Site Code: 484785
Site Description: Location: The site is located at 2101 Palmer Avenue, 2103 Palmer Avenue and 2101-2103 Palmer Avenue in Larchmont, Westchester County, and consists of two tax parcels and a portion of a third, totaling approximately 1.98 acres in size. Site Features: At the start of the BCP project, the property was primarily vacant, with no structures. With the exception of one bedrock outcrop, the entire site was paved. The former MTA parcel consisted of a gravel road with a rail line at ground surface. Now that contamination has been removed, construction of two four-story residential buildings is complete. Current Zoning and Land Use: The site property is currently zoned for commercial use, but the County has approved construction of residential, multi-family housing with portions set aside for affordable workforce housing. As noted above, construction of two four-story residential buildings is now complete. Prior to acceptance into the BCP, the site was used for contractor storage/commercial use. Past Use of the Site: The site was part of the Chatsworth Coal and Supply Company since around 1919 and had railroad tracks running through it. By 1947, several structures related to Henigson's Building Materials had been constructed on the site's northeastern corner. By 1974, a designated parking area had been added in the southern portion of the site. The MTA parcel contained a rail spur that continued south onto the larger parcels. Site Geology and Hydrogeology: The site is at an elevation of approximately 36 feet above mean sea level (AMSL) at the northern end and 27 feet AMSL at the southern end. The site is underlain by granitic gneiss, which is likely part of the Harrison Gneiss formation. Approximately 14 feet of soil overlays the gneiss bedrock. A thin layer of native soils is the uppermost hydrogeologic unit. This aquifer consists primarily of glacial tills consisting of a poorly sorted mixture of sand, silt, clay, gravel, and boulders. The

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

till typically has a low to moderate permeability, and overlays the metamorphic bedrock. Depth of water in the vicinity of the site is estimated to be about 8 feet below grade. Groundwater flow is typically west to southwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were metals (lead, barium and chromium) and PAHs (benzo(a)pyrene, benzo(b)fluoranthene, and chrysene) in soil; PAHs and VOCs in groundwater; and VOCs in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and soil vapor is being managed under a Site Management Plan.
Not reported

Health Problem: Measures are in place to control the potential for coming into contact with subsurface soil and groundwater contamination remaining on the site. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that obtains water from a source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to control the potential for inhalation of site-contaminants in indoor air due to soil vapor intrusion. Sampling indicates soil vapor intrusion is not a concern for off-site buildings.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-07-25 14:43:00
Record Upd: 2015-12-18 08:45:00
Updated By: SXDEYETT
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Larchmont Public Library
Owner Address: 121 Larchmont Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Larchmont, NY 10538
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Rosemarie Noonan
Owner Company: Palmer Avenue Housing Development Fund Company
Owner Address: 55 S. Broadway, Suite 2
Owner Addr2: Not reported
Owner City,St,Zip: Tarrytown, NY 10591-4000
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Ana Nelson

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

Owner Company: Gramatan Management, Inc.
Owner Address: 2975 Westchester Ave
Owner Addr2: Suite G01
Owner City,St,Zip: Purchase, NY 10577
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: NYSDEC Region 3 Office
Owner Address: 21 S. Putt Corners Road
Owner Addr2: Not reported
Owner City,St,Zip: New Paltz, NY 12561
Owner Country: United States of America
HW Code: C360132
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

HW Code: C360132
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1202766
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-08-05 10:02:00
Record Updated: 2013-08-05 10:02:00
Updated By: BRWOLOSE
Crossref ID: C360132-10-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-12-18 08:50:00
Record Updated: 2015-12-18 08:50:00
Updated By: SXDEYETT
Crossref ID: 553503297
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-08-25 11:40:00
Record Updated: 2015-12-18 08:49:00
Updated By: SXDEYETT
Crossref ID: 553503316
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-12-18 08:49:00
Record Updated: 2015-12-18 08:49:00
Updated By: SXDEYETT

Name: CHATSWORTH COAL AND SUPPLY SITE
Address: 2101, 2103 AND 2101-2103 PALMER AVENUE
City,State,Zip: LARCHMONT, NY 10538
Site Code: 484785
Control Name: Environmental Easement
HW Code: C360132
Control Code: J
Control Type: INST
Dt record added: 12/21/2015
Dt rec updated: 04/18/2025
Updated By: ARMALAME
Site Code: 484785

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

Site Description: Location: The site is located at 2101 Palmer Avenue, 2103 Palmer Avenue and 2101-2103 Palmer Avenue in Larchmont, Westchester County, and consists of two tax parcels and a portion of a third, totaling approximately 1.98 acres in size. Site Features: At the start of the BCP project, the property was primarily vacant, with no structures. With the exception of one bedrock outcrop, the entire site was paved. The former MTA parcel consisted of a gravel road with a rail line at ground surface. Now that contamination has been removed, construction of two four-story residential buildings is complete. Current Zoning and Land Use: The site property is currently zoned for commercial use, but the County has approved construction of residential, multi-family housing with portions set aside for affordable workforce housing. As noted above, construction of two four-story residential buildings is now complete. Prior to acceptance into the BCP, the site was used for contractor storage/commercial use. Past Use of the Site: The site was part of the Chatsworth Coal and Supply Company since around 1919 and had railroad tracks running through it. By 1947, several structures related to Henigson's Building Materials had been constructed on the site's northeastern corner. By 1974, a designated parking area had been added in the southern portion of the site. The MTA parcel contained a rail spur that continued south onto the larger parcels. Site Geology and Hydrogeology: The site is at an elevation of approximately 36 feet above mean sea level (AMSL) at the northern end and 27 feet AMSL at the southern end. The site is underlain by granitic gneiss, which is likely part of the Harrison Gneiss formation. Approximately 14 feet of soil overlays the gneiss bedrock. A thin layer of native soils is the uppermost hydrogeologic unit. This aquifer consists primarily of glacial tills consisting of a poorly sorted mixture of sand, silt, clay, gravel, and boulders. The till typically has a low to moderate permeability, and overlays the metamorphic bedrock. Depth of water in the vicinity of the site is estimated to be about 8 feet below grade. Groundwater flow is typically west to southwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were metals (lead, barium and chromium) and PAHs (benzo(a)pyrene, benzo(b)fluoranthene, and chrysene) in soil; PAHs and VOCs in groundwater; and VOCs in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and soil vapor is being managed under a Site Management Plan. Not reported

Health Problem: Measures are in place to control the potential for coming into contact with subsurface soil and groundwater contamination remaining on the site. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that obtains water from a source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to control the potential for inhalation of site-contaminants in indoor air due to soil vapor intrusion. Sampling indicates soil vapor intrusion is not a concern for off-site buildings.

Dump: False

Structure: False

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-07-25 14:43:00
Record Upd: 2015-12-18 08:45:00
Updated By: SXDEYETT
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Larchmont Public Library
Owner Address: 121 Larchmont Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Larchmont, NY 10538
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Rosemarie Noonan
Owner Company: Palmer Avenue Housing Development Fund Company
Owner Address: 55 S. Broadway, Suite 2
Owner Addr2: Not reported
Owner City,St,Zip: Tarrytown, NY 10591-4000
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Ana Nelson
Owner Company: Gramatan Management, Inc.
Owner Address: 2975 Westchester Ave
Owner Addr2: Suite G01
Owner City,St,Zip: Purchase, NY 10577
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: NYSDEC Region 3 Office
Owner Address: 21 S. Putt Corners Road
Owner Addr2: Not reported
Owner City,St,Zip: New Paltz, NY 12561
Owner Country: United States of America
HW Code: C360132
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

Waste Code: Not reported
HW Code: C360132
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1202766
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-08-05 10:02:00
Record Updated: 2013-08-05 10:02:00
Updated By: BRWOLOSE
Crossref ID: C360132-10-13
Cross Ref Type Code: 23

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-12-18 08:50:00
Record Updated: 2015-12-18 08:50:00
Updated By: SXDEYETT
Crossref ID: 553503297
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-08-25 11:40:00
Record Updated: 2015-12-18 08:49:00
Updated By: SXDEYETT
Crossref ID: 553503316
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-12-18 08:49:00
Record Updated: 2015-12-18 08:49:00
Updated By: SXDEYETT

Name: CHATSWORTH COAL AND SUPPLY SITE
Address: 2101, 2103 AND 2101-2103 PALMER AVENUE
City,State,Zip: LARCHMONT, NY 10538
Site Code: 484785
Control Name: Site Management Plan
HW Code: C360132
Control Code: 32
Control Type: INST
Dt record added: 12/21/2015
Dt rec updated: 04/18/2025
Updated By: ARMALAME
Site Code: 484785
Site Description: Location: The site is located at 2101 Palmer Avenue, 2103 Palmer Avenue and 2101-2103 Palmer Avenue in Larchmont, Westchester County, and consists of two tax parcels and a portion of a third, totaling approximately 1.98 acres in size. Site Features: At the start of the BCP project, the property was primarily vacant, with no structures. With the exception of one bedrock outcrop, the entire site was paved. The former MTA parcel consisted of a gravel road with a rail line at ground surface. Now that contamination has been removed, construction of two four-story residential buildings is complete. Current Zoning and Land Use: The site property is currently zoned for commercial use, but the County has approved construction of residential, multi-family housing with portions set aside for affordable workforce housing. As noted above, construction of two four-story residential buildings is now complete. Prior to acceptance into the BCP, the site was used for contractor storage/commercial use. Past Use of the Site: The site was part of the Chatsworth Coal and Supply Company since around 1919 and had railroad tracks running through it. By 1947, several structures related to Henigson's Building Materials had been constructed on the site's northeastern corner. By 1974, a designated parking area had been added in the southern portion of the site. The MTA parcel contained a rail spur that continued south onto the larger parcels. Site Geology and Hydrogeology: The site is at an elevation of approximately 36 feet above mean sea level (AMSL) at the northern end and 27 feet AMSL at the southern end. The site is underlain by granitic gneiss, which is likely part of the Harrison Gneiss formation. Approximately 14 feet of soil overlays the gneiss bedrock. A thin layer of native soils is the uppermost hydrogeologic unit. This aquifer consists primarily of glacial tills consisting of a

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

poorly sorted mixture of sand, silt, clay, gravel, and boulders. The till typically has a low to moderate permeability, and overlays the metamorphic bedrock. Depth of water in the vicinity of the site is estimated to be about 8 feet below grade. Groundwater flow is typically west to southwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were metals (lead, barium and chromium) and PAHs (benzo(a)pyrene, benzo(b)fluoranthene, and chrysene) in soil; PAHs and VOCs in groundwater; and VOCs in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and soil vapor is being managed under a Site Management Plan.
Not reported

Health Problem: Measures are in place to control the potential for coming into contact with subsurface soil and groundwater contamination remaining on the site. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that obtains water from a source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to control the potential for inhalation of site-contaminants in indoor air due to soil vapor intrusion. Sampling indicates soil vapor intrusion is not a concern for off-site buildings.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-07-25 14:43:00
Record Upd: 2015-12-18 08:45:00
Updated By: SXDEYETT
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Larchmont Public Library
Owner Address: 121 Larchmont Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Larchmont, NY 10538
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Rosemarie Noonan
Owner Company: Palmer Avenue Housing Development Fund Company
Owner Address: 55 S. Broadway, Suite 2
Owner Addr2: Not reported
Owner City,St,Zip: Tarrytown, NY 10591-4000
Owner Country: United States of America
Own Op: 1
Sub Type: E

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

Owner Name: Ana Nelson
Owner Company: Gramatan Management, Inc.
Owner Address: 2975 Westchester Ave
Owner Addr2: Suite G01
Owner City,St,Zip: Purchase, NY 10577
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: NYSDEC Region 3 Office
Owner Address: 21 S. Putt Corners Road
Owner Addr2: Not reported
Owner City,St,Zip: New Paltz, NY 12561
Owner Country: United States of America
HW Code: C360132
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

Waste Code: Not reported
HW Code: C360132
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1202766
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-08-05 10:02:00
Record Updated: 2013-08-05 10:02:00
Updated By: BRWOLOSE
Crossref ID: C360132-10-13
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-12-18 08:50:00
Record Updated: 2015-12-18 08:50:00
Updated By: SXDEYETT
Crossref ID: 553503297
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-08-25 11:40:00
Record Updated: 2015-12-18 08:49:00
Updated By: SXDEYETT
Crossref ID: 553503316
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-12-18 08:49:00
Record Updated: 2015-12-18 08:49:00
Updated By: SXDEYETT

Name: CHATSWORTH COAL AND SUPPLY SITE
Address: 2101, 2103 AND 2101-2103 PALMER AVENUE
City,State,Zip: LARCHMONT, NY 10538
Site Code: 484785
Control Name: Ground Water Use Restriction
HW Code: C360132
Control Code: 08
Control Type: INST
Dt record added: 12/21/2015
Dt rec updated: 04/18/2025
Updated By: ARMALAME

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

Site Code: 484785

Site Description: Location: The site is located at 2101 Palmer Avenue, 2103 Palmer Avenue and 2101-2103 Palmer Avenue in Larchmont, Westchester County, and consists of two tax parcels and a portion of a third, totaling approximately 1.98 acres in size. Site Features: At the start of the BCP project, the property was primarily vacant, with no structures. With the exception of one bedrock outcrop, the entire site was paved. The former MTA parcel consisted of a gravel road with a rail line at ground surface. Now that contamination has been removed, construction of two four-story residential buildings is complete. Current Zoning and Land Use: The site property is currently zoned for commercial use, but the County has approved construction of residential, multi-family housing with portions set aside for affordable workforce housing. As noted above, construction of two four-story residential buildings is now complete. Prior to acceptance into the BCP, the site was used for contractor storage/commercial use. Past Use of the Site: The site was part of the Chatsworth Coal and Supply Company since around 1919 and had railroad tracks running through it. By 1947, several structures related to Henigson's Building Materials had been constructed on the site's northeastern corner. By 1974, a designated parking area had been added in the southern portion of the site. The MTA parcel contained a rail spur that continued south onto the larger parcels. Site Geology and Hydrogeology: The site is at an elevation of approximately 36 feet above mean sea level (AMSL) at the northern end and 27 feet AMSL at the southern end. The site is underlain by granitic gneiss, which is likely part of the Harrison Gneiss formation. Approximately 14 feet of soil overlays the gneiss bedrock. A thin layer of native soils is the uppermost hydrogeologic unit. This aquifer consists primarily of glacial tills consisting of a poorly sorted mixture of sand, silt, clay, gravel, and boulders. The till typically has a low to moderate permeability, and overlays the metamorphic bedrock. Depth of water in the vicinity of the site is estimated to be about 8 feet below grade. Groundwater flow is typically west to southwest.

Env Problem: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were metals (lead, barium and chromium) and PAHs (benzo(a)pyrene, benzo(b)fluoranthene, and chrysene) in soil; PAHs and VOCs in groundwater; and VOCs in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and soil vapor is being managed under a Site Management Plan. Not reported

Health Problem: Measures are in place to control the potential for coming into contact with subsurface soil and groundwater contamination remaining on the site. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that obtains water from a source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to control the potential for inhalation of site-contaminants in indoor air due to soil vapor intrusion. Sampling indicates soil vapor intrusion is not a concern for off-site buildings.

Dump: False

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-07-25 14:43:00
Record Upd: 2015-12-18 08:45:00
Updated By: SXDEYETT
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Larchmont Public Library
Owner Address: 121 Larchmont Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Larchmont, NY 10538
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Rosemarie Noonan
Owner Company: Palmer Avenue Housing Development Fund Company
Owner Address: 55 S. Broadway, Suite 2
Owner Addr2: Not reported
Owner City,St,Zip: Tarrytown, NY 10591-4000
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Ana Nelson
Owner Company: Gramatan Management, Inc.
Owner Address: 2975 Westchester Ave
Owner Addr2: Suite G01
Owner City,St,Zip: Purchase, NY 10577
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: NYSDEC Region 3 Office
Owner Address: 21 S. Putt Corners Road
Owner Addr2: Not reported
Owner City,St,Zip: New Paltz, NY 12561
Owner Country: United States of America
HW Code: C360132
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: indeno(1,2,3-cd)pyrene

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C360132
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1202766
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-08-05 10:02:00
Record Updated: 2013-08-05 10:02:00
Updated By: BRWOLOSE
Crossref ID: C360132-10-13

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-12-18 08:50:00
Record Updated: 2015-12-18 08:50:00
Updated By: SXDEYETT
Crossref ID: 553503297
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-08-25 11:40:00
Record Updated: 2015-12-18 08:49:00
Updated By: SXDEYETT
Crossref ID: 553503316
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-12-18 08:49:00
Record Updated: 2015-12-18 08:49:00
Updated By: SXDEYETT

BROWNFIELDS:

| | |
|---|---|
| Name: | CHATSWORTH COAL AND SUPPLY SITE |
| Address: | 2101, 2103 AND 2101-2103 PALMER AVENUE |
| City,State,Zip: | LARCHMONT, NY 10538 |
| Program: | BCP |
| Site Code: | 484785 |
| Acres: | 1.980 |
| HW Code: | C360132 |
| SWIS: | 6032 |
| Town: | Mamaroneck |
| Record Added Date: | 07/19/2013 |
| Record Updated Date: | 05/12/2023 |
| Update By: | SXDEYETT |
| Site Description: | Location: The site is located at 2101 Palmer Avenue, 2103 Palmer Avenue and 2101-2103 Palmer Avenue in Larchmont, Westchester County, and consists of two tax parcels and a portion of a third, totaling approximately 1.98 acres in size. Site Features: At the start of the BCP project, the property was primarily vacant, with no structures. With the exception of one bedrock outcrop, the entire site was paved. The former MTA parcel consisted of a gravel road with a rail line at ground surface. Now that contamination has been removed, construction of two four-story residential buildings is complete. Current Zoning and Land Use: The site property is currently zoned for commercial use, but the County has approved construction of residential, multi-family housing with portions set aside for affordable workforce housing. As noted above, construction of two four-story residential buildings is now complete. Prior to acceptance into the BCP, the site was used for contractor storage/commercial use. Past Use of the Site: The site was part of the Chatsworth Coal and Supply Company since around 1919 and had railroad tracks running through it. By 1947, several structures related to Henigson's Building Materials had been constructed on the site's northeastern corner. By 1974, a designated parking area had been added in the southern portion of the site. The MTA parcel contained a rail spur that continued south onto the larger parcels. Site Geology and Hydrogeology: The site is at an elevation of approximately 36 feet above mean sea level (AMSL) at the northern end and 27 feet AMSL at the southern end. The site is underlain by granitic gneiss, which is likely part of the Harrison Gneiss formation. Approximately 14 feet of soil overlays the gneiss bedrock. |

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

| | |
|---|---|
| | A thin layer of native soils is the uppermost hydrogeologic unit. This aquifer consists primarily of glacial tills consisting of a poorly sorted mixture of sand, silt, clay, gravel, and boulders. The till typically has a low to moderate permeability, and overlays the metamorphic bedrock. Depth of water in the vicinity of the site is estimated to be about 8 feet below grade. Groundwater flow is typically west to southwest. |
| Env Problem: | Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were metals (lead, barium and chromium) and PAHs (benzo(a)pyrene, benzo(b)fluoranthene, and chrysene) in soil; PAHs and VOCs in groundwater; and VOCs in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil and soil vapor is being managed under a Site Management Plan. |
| | Not reported |
| Health Problem: | Measures are in place to control the potential for coming into contact with subsurface soil and groundwater contamination remaining on the site. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that obtains water from a source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Measures are in place to control the potential for inhalation of site-contaminants in indoor air due to soil vapor intrusion. Sampling indicates soil vapor intrusion is not a concern for off-site buildings. |
| Dump: | False |
| Structure: | False |
| Lagoon: | False |
| Landfill: | False |
| Pond: | False |
| Disp Start: | Not reported |
| Disp Term: | Not reported |
| Lat/Long: | Not reported |
| Dell: | Not reported |
| Record Add: | 2013-07-25 14:43:00 |
| Record Upd: | 2015-12-18 08:45:00 |
| Updated By: | SXDEYETT |
| Own Op: | Document Repository |
| Sub Type: | NNN |
| Owner Name: | Not reported |
| Owner Company: | Larchmont Public Library |
| Owner Address: | 121 Larchmont Avenue |
| Owner Addr2: | Not reported |
| Owner City,St,Zip: | Larchmont, NY 10538 |
| Owner Country: | United States of America |
| Own Op: | 1 |
| Sub Type: | E |
| Owner Name: | Rosemarie Noonan |
| Owner Company: | Palmer Avenue Housing Development Fund Company |
| Owner Address: | 55 S. Broadway, Suite 2 |
| Owner Addr2: | Not reported |
| Owner City,St,Zip: | Tarrytown, NY 10591-4000 |
| Owner Country: | United States of America |

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

| | |
|---|---|
| Own Op: | 1 |
| Sub Type: | E |
| Owner Name: | Ana Nelson |
| Owner Company: | Gramatan Management, Inc. |
| Owner Address: | 2975 Westchester Ave |
| Owner Addr2: | Suite G01 |
| Owner City,St,Zip: | Purchase, NY 10577 |
| Owner Country: | United States of America |
| Own Op: | Document Repository |
| Sub Type: | NNN |
| Owner Name: | Not reported |
| Owner Company: | NYSDEC Region 3 Office |
| Owner Address: | 21 S. Putt Corners Road |
| Owner Addr2: | Not reported |
| Owner City,St,Zip: | New Paltz, NY 12561 |
| Owner Country: | United States of America |
| HW Code: | C360132 |
| Waste Type: | BARIUM |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | CHROMIUM |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | TRICHLOROETHENE (TCE) |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | indeno(1,2,3-cd)pyrene |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | BENZ(A)ANTHRACENE |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | LEAD |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | BENZO(B)FLUORANTHENE |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | Chrysene |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | DIBENZ[A,H]ANTHRACENE |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | cis-1,2-Dichloroethene |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |

**CHATSWORTH COAL AND SUPPLY SITE (Continued)** **S118372432**

| | |
|---|---|
| Waste Type: | TETRACHLOROETHYLENE (PCE) |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | BENZO(A)PYRENE |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | benzo(k)fluoranthene |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | tetrachloroethene (PCE) |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | benzo(a)anthracene |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| HW Code: | C360132 |
| Waste Type: | BENZO[K]FLUORANTHENE |
| Waste Quantity: | UNKNOWN |
| Waste Code: | Not reported |
| Crossref ID: | 1202766 |
| Cross Ref Type Code: | 01 |
| Cross Ref Type: | Spill No. |
| Record Added Date: | 2013-08-05 10:02:00 |
| Record Updated: | 2013-08-05 10:02:00 |
| Updated By: | BRWOLOSE |
| Crossref ID: | C360132-10-13 |
| Cross Ref Type Code: | 23 |
| Cross Ref Type: | Agreement/Consent Order Number |
| Record Added Date: | 2015-12-18 08:50:00 |
| Record Updated: | 2015-12-18 08:50:00 |
| Updated By: | SXDEYETT |
| Crossref ID: | 553503297 |
| Cross Ref Type Code: | 25 |
| Cross Ref Type: | County Recording Identifier |
| Record Added Date: | 2015-08-25 11:40:00 |
| Record Updated: | 2015-12-18 08:49:00 |
| Updated By: | SXDEYETT |
| Crossref ID: | 553503316 |
| Cross Ref Type Code: | 25 |
| Cross Ref Type: | County Recording Identifier |
| Record Added Date: | 2015-12-18 08:49:00 |
| Record Updated: | 2015-12-18 08:49:00 |
| Updated By: | SXDEYETT |

**178**
**South**
**1/4-1/2**
**0.478 mi.**
**2525 ft.**

**LEVINSON RESIDENCE**
**35 MAYHEW AVE**
**LARCHMONT, NY**

**NY LTANKS** **S106471704**
**N/A**

**Relative:**
**Lower**

**Actual:**
**20 ft.**

LTANKS:

| | |
|---|---|
| Name: | LEVINSON RESIDENCE |
| Address: | 35 MAYHEW AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0401870 / 2004-06-07 |
| Facility ID: | 0401870 |
| Site ID: | 70244 |
| Spill Date: | 2004-05-20 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2004-05-20 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-05-20 |
| Spill Record Last Update: | 2004-06-08 |
| Spiller Name: | SAM LEVINSON |
| Spiller Company: | LEVINSON RESIDENCE |
| Spiller Address: | 35 MAYHEW AVE |
| Spiller County: | 001 |
| Spiller Contact: | SAM LEVINSON |
| Spiller Phone: | (917) 816-2241 |
| Spiller Extention: | CELL |
| DEC Region: | 3 |
| DER Facility ID: | 66707 |
| Latitude: | 40.9281173 |
| Longitude: | -73.7588394 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 05-26-04 Tank removal letter rec'd from Northeast Environmental. The letter states that the tanks was removed and holes were present but no contaminated soil was found in the tank pit. NFA TG |
| Remarks: | holes in the tank: |

All Materials:

| | |
|---|---|
| Site ID: | 70244 |
| Operable Unit ID: | 883718 |
| Operable Unit: | 01 |
| Material ID: | 493061 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |

**LEVINSON RESIDENCE (Continued)** **S106471704**

Units: G
Recovered: .00
Oxygenate: Not reported

---

**179**
**SSE**
**1/4-1/2**
**0.479 mi.**
**2530 ft.**

**ROBERT TRIPPETT** **NY LTANKS** **S113820381**
**4 STUYVESANT AVE** **N/A**
**LARCHMONT, NY**

**Relative:**
**Lower**

**Actual:**
**36 ft.**

LTANKS:

| | |
|---|---|
| Name: | ROBERT TRIPPETT |
| Address: | 4 STUYVESANT AVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1304359 / 2013-08-29 |
| Facility ID: | 1304359 |
| Site ID: | 484874 |
| Spill Date: | 2013-07-22 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | D4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | TDGHIOSA |
| Referred To: | Not reported |
| Reported to Dept: | 2013-07-22 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2013-07-22 |
| Spill Record Last Update: | 2013-09-11 |
| Spiller Name: | ROBERT TRIPPETT |
| Spiller Company: | ROBERT TRIPPETT |
| Spiller Address: | 4 STUYVESANT AVE |
| Spiller County: | 999 |
| Spiller Contact: | ROBERT TRIPPETT |
| Spiller Phone: | (301) 452-3894 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 440021 |
| Latitude: | 40.9289417 |
| Longitude: | -73.7543786 |
| DEC Memo: | 7/22/13 - To uncover, repair and retest. KAB 08/29/13 Northeast Environmental reported they excavated and removed the tank and that no contaminated soil was noted in the excavation. Post excavation soil sample results were below DEC guidance values. NFA. TG |
| Remarks: | retest pending |

All Materials:

| | |
|---|---|
| Site ID: | 484874 |
| Operable Unit ID: | 1234553 |
| Operable Unit: | 01 |

**ROBERT TRIPPETT (Continued)** **S113820381**

| | |
|---|---|
| Material ID: | 2233613 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**180 SSW 1/4-1/2 0.487 mi. 2573 ft.** **WEBERS HOME** **NY LTANKS** **S107410299**
**76 PINEBROOK DRIVE** **N/A**
**LARCHMONT, NY**

**Relative: Lower**
**Actual: 29 ft.**

LTANKS:

| | |
|---|---|
| Name: | WEBERS HOME |
| Address: | 76 PINEBROOK DRIVE |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0505197 / 2005-09-26 |
| Facility ID: | 0505197 |
| Site ID: | 350147 |
| Spill Date: | 2005-07-29 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | Not reported |
| Reported to Dept: | 2005-07-29 |
| CID: | 444 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2005-07-29 |
| Spill Record Last Update: | 2005-09-26 |
| Spiller Name: | WEBERS HOME |
| Spiller Company: | WEBERS HOME |
| Spiller Address: | 76 PINE BROOK DRIVE |
| Spiller County: | 001 |
| Spiller Contact: | WEBERS HOME |
| Spiller Phone: | (914) 882-2559 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 296590 |
| Latitude: | 40.9288600 |
| Longitude: | -73.7620380 |
| DEC Memo: | September 26, 2005: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 11.07 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod |
| Remarks: | A 550 GALLON TANK HAD HOLES AND CONTAMINATED SOIL |

**WEBERS HOME (Continued)** **S107410299**

All Materials:

| | |
|---|---|
| Site ID: | 350147 |
| Operable Unit ID: | 1107728 |
| Operable Unit: | 01 |
| Material ID: | 2097617 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

---

**181 West 1/4-1/2 0.489 mi. 2582 ft.**

**BALLARD RESIDENCE**
**4 ACORN LN**
**LARCHMONT, NY**

**NY LTANKS** **S105998289**
**N/A**

**Relative: Higher**

**Actual: 130 ft.**

LTANKS:

| | |
|---|---|
| Name: | BALLARD RESIDENCE |
| Address: | 4 ACORN LN |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0211936 / 2003-09-02 |
| Facility ID: | 0211936 |
| Site ID: | 314363 |
| Spill Date: | 2003-03-04 |
| Spill Cause: | Tank Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | B4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 2003-03-04 |
| CID: | 281 |
| Water Affected: | Not reported |
| Spill Notifier: | Other |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2003-03-04 |
| Spill Record Last Update: | 2003-09-02 |
| Spiller Name: | SAME |
| Spiller Company: | MR BALLARD |
| Spiller Address: | 4 ACRON LN |
| Spiller County: | 001 |
| Spiller Contact: | JAMIE BARNABA |
| Spiller Phone: | (914) 777-1930 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 253480 |
| Latitude: | 40.9358944 |

**BALLARD RESIDENCE (Continued)** **S105998289**

Longitude: -73.7683748
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 09/02/03 NORTHEAST DISPOSED OF LUST AND 61.45 TONS OF CONTAMINATED SOIL. ALSO REPORTED AS SPILL NUMBER 02-11560. NFA
Remarks: SOIL CONTAMINTION DISCOVERED AT ABOVE LOCATION DURING TANK REMOVAL. AREA BEING EXCAVATED AND SOIL STOCK PILED ON SITE.

All Materials:
Site ID: 314363
Operable Unit ID: 865387
Operable Unit: 01
Material ID: 511716
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

**AQ182** **PARISSI TTF** **NY LTANKS** **S123663780**
**WSW** **608 5TH AVE** **N/A**
**1/4-1/2** **LARCHMONT, NY**
**0.491 mi.**
**2590 ft.** **Site 2 of 2 in cluster AQ**

**Relative:** **Lower**
**Actual:** **29 ft.**

LTANKS:
Name: PARISSI TTF
Address: 608 5TH AVE
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 1810894 / 2019-07-08
Facility ID: 1810894
Site ID: 581804
Spill Date: 2019-01-22
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6032
Investigator: JBODEE
Referred To: Not reported
Reported to Dept: 2019-01-28
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2019-01-28
Spill Record Last Update: 2019-07-29
Spiller Name: Not reported
Spiller Company: PARISSI
Spiller Address: Not reported
Spiller County: 999

**PARISSI TTF (Continued)** **S123663780**

| | |
|---|---|
| Spiller Contact: | PETRO OIL |
| Spiller Phone: | (800) 208-7787 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 534336 |
| Latitude: | Not reported |
| Longitude: | Not reported |
| DEC Memo: | 1/28/19 Homeowner contacted Petro to insure UST, Petro did soil testing as due diligence, test came back at 7320 TPH. Left message for Petro to call duty desk. ga 1/30/19 Caller from Petro's parent company said that potential buyer asked to have the soil tested, and that Ecologic did the testing. UST to be removed, but removal company not known at this time. dw 7/8/19: Advanced Environmental removed the leaking UST and disposed of a total of 46.84 tons of petroleum contaminated soil. Report submitted to DEC has been reviewed and entered into DecDocs. Based upon the information provided, no further action is required at this time. jod |
| Remarks: | contaminated soil result-came back at 7320 |

All Materials:

| | |
|---|---|
| Site ID: | 581804 |
| Operable Unit ID: | 1329493 |
| Operable Unit: | 01 |
| Material ID: | 2338577 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

---

**183**
**WNW**
**1/4-1/2**
**0.494 mi.**
**2607 ft.**

**SPILL NUMBER 9901044** **NY LTANKS** **S104620164**
**193 ROCKING STONE AV** **N/A**
**LARCHMONT, NY**

**Relative:**
**Higher**

**Actual:**
**126 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPILL NUMBER 9901044 |
| Address: | 193 ROCKING STONE AV |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9901044 / 1999-07-01 |
| Facility ID: | 9901044 |
| Site ID: | 227509 |
| Spill Date: | 1999-04-27 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | jbodee |
| Referred To: | Not reported |
| Reported to Dept: | 1999-04-27 |
| CID: | 351 |
| Water Affected: | Not reported |

**SPILL NUMBER 9901044 (Continued)** **S104620164**

| | |
|---|---|
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1999-04-27 |
| Spill Record Last Update: | 1999-07-02 |
| Spiller Name: | HARDY |
| Spiller Company: | HARDY RESIDENCE |
| Spiller Address: | 193 ROCKING STONE AV |
| Spiller County: | 001 |
| Spiller Contact: | HARDY |
| Spiller Phone: | (914) 833-3440 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 187774 |
| Latitude: | 40.9389878 |
| Longitude: | -73.7670225 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 7/1/99 TANK PULLED BY ENVIROSHIELD. TANK WAS SOUND, NO RELEASE. |
| Remarks: | HOME OWNER TO REMOVE TANK |

All TTF:

| | |
|---|---|
| Facility ID: | 9901044 |
| Spill Number: | 9901044 |
| Spill Tank Test: | 1547118 |
| Site ID: | 227509 |
| Tank Number: | 1 |
| Tank Size: | 550 |
| Material: | 0001 |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | F |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 227509 |
| Operable Unit ID: | 1079804 |
| Operable Unit: | 01 |
| Material ID: | 304581 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | .00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

**184**
**NNE**
**1/4-1/2**
**0.496 mi.**
**2619 ft.**

**COTUGNO RESIDENCE**
**53 WEST GARDEN RD**
**LARCHMONT, NY**

**NY LTANKS** **S103558028**
**N/A**

**Relative:**
**Higher**

**Actual:**
**82 ft.**

LTANKS:

| | |
|---|---|
| Name: | COTUGNO RESIDENCE |
| Address: | 53 WEST GARDEN RD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 9808948 / 1998-10-19 |
| Facility ID: | 9808948 |
| Site ID: | 63099 |
| Spill Date: | 1998-10-19 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Private Dwelling |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6000 |
| Investigator: | tdghiosa |
| Referred To: | Not reported |
| Reported to Dept: | 1998-10-19 |
| CID: | 371 |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 1998-10-19 |
| Spill Record Last Update: | 1998-11-06 |
| Spiller Name: | JIM CAREY |
| Spiller Company: | CASTLE OIL CORPORATION |
| Spiller Address: | 290 LOCUST AVENUE |
| Spiller County: | 001 |
| Spiller Contact: | MR COTUGNO |
| Spiller Phone: | (914) 834-6639 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 61031 |
| Latitude: | 40.9426623 |
| Longitude: | -73.7560486 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY |
| Remarks: | DRIVER OVERFILLED TANK - CLEAN UP COMPLETE. |

All Materials:

| | |
|---|---|
| Site ID: | 63099 |
| Operable Unit ID: | 1070131 |
| Operable Unit: | 01 |
| Material ID: | 316426 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 6.00 |
| Units: | G |
| Recovered: | 6.00 |
| Oxygenate: | Not reported |

**185**
**SE**
**1/4-1/2**
**0.496 mi.**
**2621 ft.**

**PBS**
**1 ADDISON ST**
**LARCHMONT, NY**

**NY LTANKS** **S106702684**
**NY AST** **N/A**

**Relative:**
**Higher**

**Actual:**
**46 ft.**

LTANKS:

| | |
|---|---|
| Name: | SPADARO RENTAL PROPERTIES (SRP INC) |
| Address: | 1 ADDISON ST |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 1904732 / 2020-03-24 |
| Facility ID: | 1904732 |
| Site ID: | 592730 |
| Spill Date: | 2019-08-05 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | BTRANSOM |
| Referred To: | Not reported |
| Reported to Dept: | 2019-08-05 |
| CID: | Not reported |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | False |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2019-08-05 |
| Spill Record Last Update: | 2020-03-24 |
| Spiller Name: | HARRY SPADERO 914-774-2826 (Cell) |
| Spiller Company: | SRP |
| Spiller Address: | 1 ADDISON ST |
| Spiller County: | 001 |
| Spiller Contact: | HARRY SPADERO |
| Spiller Phone: | (914) 698-1938 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 542794 |
| Latitude: | Not reported |
| Longitude: | Not reported |
| DEC Memo: | 8/5/19 US Tank Tech performed tightness test on vaulted AST in basement, tank failed with popping noise. Temp tank to be put in, failed tank to be pumped out, and investigated. Unknown if tank to be repaired/retested or replaced. Tank is currently enclosed with concrete blocks and sand, unable to view tank. Property on municipal water with no waterways or drains. PBS# 3-800180. ga 8/6/19 Temp tank put in, waiting on tank to be pumped out, will have 2 275 ASTs put in and original tank removed. Contractor to be determined. ga 09-17-19 Update from Mr. Spadero; Oil company pumped out the tank but there is still residual. Royal Environmental is being contracted to clean out and remove the tank as well as the vault. Clean up is pending the necessary permits. BTR 01-07-20 Requested status update from Royal Environmental. Royal has not been hired to conduct tank removal. BTR 01-13-20 Reminded Mr. Spadero that the tank can't be put back into service. BTR 02-07-20 Update from WCHD:The tank was removed on 01-27-2020, no TCR has been submitted. Inspector Eilbacher noted that |

**PBS (Continued)** **S106702684**

there was no contamination present and the tank has been registered closed-removed from the facility. NFA. BTR
Remarks: repair & retest

All Materials:
Site ID: 592730
Operable Unit ID: 1340330
Operable Unit: 01
Material ID: 2350038
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Name: SPADARO RENTAL PROPERTIES (SRP INC)
Address: 1 ADDISON ST
City,State,Zip: LARCHMONT, NY
Spill Number/Closed Date: 1908402 / 2020-02-07
Facility ID: 1908402
Site ID: 598583
Spill Date: 2019-11-20
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6032
Investigator: BTRANSOM
Referred To: Not reported
Reported to Dept: 2019-11-20
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2019-11-20
Spill Record Last Update: 2020-02-07
Spiller Name: HARRY SPADARO
Spiller Company: SRP INC
Spiller Address: 138 MAMARONECK AVENUE
Spiller County: 999
Spiller Contact: HARRY SPADARO
Spiller Phone: (914) 698-1938
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 547337
Latitude: Not reported
Longitude: Not reported
DEC Memo: 11-20-19 Vaulted tank failed a re-test after initial august 5th failure. Copy of report to be sent to WCDOH. We’ve tested this site for years. They took out all the sand from around the tank and

**PBS (Continued)** **S106702684**

there's no contamination on the floor. Leak has to be either the seams or the top of the tank. They pulled all the fittings off and plugged the openings and still failed. Owner is looking into lining the tank. If it can't be lined then the tank will be removed. Have a temporary 275 gallon tank right now. BTR 01-13-20 Spoke with Mr. Spadero and reminded him that the tank can't be put back into service. BTR 02-07-20 Update from WCHD:The tank was removed on 01-27-2020, no TCR has been submitted. Inspector Eilbacher noted that there was no contamination present and the tank has been registered closed-removed from the facility. NFA. BTR

Remarks: inside tank - vaulted indoors - retest failed

All TTF:

| | |
|---|---|
| Facility ID: | 1908402 |
| Spill Number: | 1908402 |
| Spill Tank Test: | 2508348 |
| Site ID: | 598583 |
| Tank Number: | 001 |
| Tank Size: | 2000 |
| Material: | 0001 |
| EPA UST: | False |
| UST: | False |
| Cause: | 00 |
| Source: | 01 |
| Test Method: | 34 |
| Test Method 2: | EZY 3 Locator Plus |
| Leak Rate: | Not reported |
| Gross Fail: | Not reported |
| Modified By: | BTRANSOM |
| Last Modified Date: | Not reported |

All Materials:

| | |
|---|---|
| Site ID: | 598583 |
| Operable Unit ID: | 1346089 |
| Operable Unit: | 01 |
| Material ID: | 2356362 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | Not reported |
| Units: | Not reported |
| Recovered: | Not reported |
| Oxygenate: | Not reported |

| | |
|---|---|
| Name: | PBS |
| Address: | 1 ADDISON ST |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0406076 / 2004-11-26 |
| Facility ID: | 0406076 |
| Site ID: | 282666 |
| Spill Date: | 2004-09-02 |
| Spill Cause: | Tank Test Failure |
| Spill Source: | Commercial/Industrial |
| Spill Class: | C3 |
| Cleanup Ceased: | Not reported |

**PBS (Continued)** **S106702684**

| | |
|---|---|
| SWIS: | 6000 |
| Investigator: | JBODee |
| Referred To: | WESTCHESTER CNTY HEALTH D |
| Reported to Dept: | 2004-09-02 |
| CID: | 407 |
| Water Affected: | Not reported |
| Spill Notifier: | Tank Tester |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2004-09-02 |
| Spill Record Last Update: | 2004-11-26 |
| Spiller Name: | HARRY SPADERO |
| Spiller Company: | Not reported |
| Spiller Address: | 1 ADDISON ST |
| Spiller County: | 001 |
| Spiller Contact: | HARRY SPADERO |
| Spiller Phone: | (914) 774-2826 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 229480 |
| Latitude: | 40.9299570 |
| Longitude: | -73.7521800 |
| DEC Memo: | Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-MANCINI 11/26/04 TANK PASSED A RE-TEST AFTER FITTINGS WERE REPAIRED. DEC REQUIRES NO FURTHER ACTION AT THIS TIME. jbo |
| Remarks: | Recommend manway and manway gasket to be checked. |

All TTF:

| | |
|---|---|
| Facility ID: | 0406076 |
| Spill Number: | 0406076 |
| Spill Tank Test: | 1529630 |
| Site ID: | 282666 |
| Tank Number: | 1 |
| Tank Size: | 2000 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

| | |
|---|---|
| Facility ID: | 0406076 |
| Spill Number: | 0406076 |
| Spill Tank Test: | 1529631 |
| Site ID: | 282666 |
| Tank Number: | 1 |
| Tank Size: | 2000 |
| Material: | Not reported |
| EPA UST: | Not reported |
| UST: | Not reported |

**PBS (Continued)** **S106702684**

| | |
|---|---|
| Cause: | Not reported |
| Source: | Not reported |
| Test Method: | 03 |
| Test Method 2: | Horner EZ Check I or II |
| Leak Rate: | .00 |
| Gross Fail: | Not reported |
| Modified By: | Spills |
| Last Modified Date: | Not reported |

WESTCHESTER CO. AST:

| | |
|---|---|
| Name: | SRP, INC. |
| Address: | 1 ADDISON STREET |
| City,State,Zip: | LARCHMONT, NY 10538 |
| PBS Number: | 3-800180 |
| Site Status: | Active |
| GDS Number: | Not reported |
| Operator Name: | SRP, INC |
| Owner Name: | Harry P. Spadaro |
| Owner Street: | 138 Mamaroneck Ave. |
| Owner Address2: | P. O. Box 282 |
| Owner City/State/Zip: | Mamaroneck, NY 10543 |
| | |
| Tank Number: | 001 |
| Status: | 1. In-Service |
| Date Installation: | 01/01/1975 |
| Capacity: | 2000 |
| Product Stored: | 0001. #2 Fuel Oil |
| Product Stored Percent: | 100 |
| Date Perm Closure: | 01/01/1900 |
| Tank Location: | 2. Aboveground (contact w/ impervious barrier) |
| Tank Type: | 1. Steel/Carbon steel/Iron |
| Tank Internal Protection: | 0. None |
| Tank External Protection: | 0. None |
| Tank Leak Detection: | 0. None |
| Tank Secondary Containment: | 3. Vault (w/ no access) |
| Piping Location: | 3. Aboveground/Underground Combination |
| Piping Type: | 1. Steel/Carbon/ Steel/Iron |
| Piping External Protection: | 0. None |
| Piping Leak Detection: | 0. None |
| Piping Secondary Containment: | 0. None |
| Overfill Prevention: | 5. Vent Whistle |
| Spill Prevention: | 0. None |
| Dispenser: | 2. Suction |

---

**186**
**NW**
**1/4-1/2**
**0.497 mi.**
**2624 ft.**

**RENZ RESIDENCE**
**44 VALLEY ROAD**
**LARCHMONT, NY**

**NY LTANKS** **S107489228**
**N/A**

**Relative:**
**Higher**

**Actual:**
**94 ft.**

LTANKS:

| | |
|---|---|
| Name: | RENZ RESIDENCE |
| Address: | 44 VALLEY ROAD |
| City,State,Zip: | LARCHMONT, NY |
| Spill Number/Closed Date: | 0510121 / 2005-11-26 |
| Facility ID: | 0510121 |

**RENZ RESIDENCE (Continued)** **S107489228**

| | |
|---|---|
| Site ID: | 356031 |
| Spill Date: | 2005-11-26 |
| Spill Cause: | Tank Overfill |
| Spill Source: | Tank Truck |
| Spill Class: | C4 |
| Cleanup Ceased: | Not reported |
| SWIS: | 6032 |
| Investigator: | JBODee |
| Referred To: | Not reported |
| Reported to Dept: | 2005-11-26 |
| CID: | 72 |
| Water Affected: | Not reported |
| Spill Notifier: | Responsible Party |
| Last Inspection: | Not reported |
| Recommended Penalty: | False |
| Meets Standard: | True |
| UST Involvement: | False |
| Remediation Phase: | 0 |
| Date Entered In Computer: | 2005-11-26 |
| Spill Record Last Update: | 2005-11-28 |
| Spiller Name: | Not reported |
| Spiller Company: | Not reported |
| Spiller Address: | Not reported |
| Spiller County: | 001 |
| Spiller Contact: | SUZANNE LUGO |
| Spiller Phone: | (914) 668-5300 |
| Spiller Extention: | Not reported |
| DEC Region: | 3 |
| DER Facility ID: | 306101 |
| Latitude: | 40.9403090 |
| Longitude: | -73.7662090 |
| DEC Memo: | CLEAN UP COMPLETED NFA |
| Remarks: | Driver calculated amount incorrectly, causing ~2 gallons of oil to spill from vent. Oil Co. on scene. Spill is contained, and is being cleaned up. |

All Materials:

| | |
|---|---|
| Site ID: | 356031 |
| Operable Unit ID: | 1113356 |
| Operable Unit: | 01 |
| Material ID: | 2103417 |
| Material Code: | 0001A |
| Material Name: | #2 fuel oil |
| Case No.: | Not reported |
| Material FA: | Petroleum |
| Quantity: | 2.00 |
| Units: | G |
| Recovered: | .00 |
| Oxygenate: | Not reported |

Count: 4 records. ORPHAN SUMMARY

| City | EDR ID | Site Name | Site Address | Zip | Database(s) |
|---|---|---|---|---|---|
| MAMARONECK | S104619232 | SPILL NUMBER 8601246 | RT I95 ON NEW ENGLAND TWY | | NY LTANKS |
| NEW ROCHELLE | S100153602 | N.SHORE LONG ISLAND SOUND | NEW ROCHELLE TO DANBURY | | NY LTANKS |
| NEW ROCHELLE | S113916612 | MEARL CORP. | PALMER AVE | 10801 | NY SHWS |
| NEW ROCHELLE | S117975694 | MM 5.4 LEFT LANE | I-95 SOUTHBOUND | | NY LTANKS |

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

**Number of Days to Update:** Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

**STANDARD ENVIRONMENTAL RECORDS**

***Lists of Federal NPL (Superfund) sites***

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 12/26/2025
Date Data Arrived at EDR: 01/05/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 17

Source: EPA
Telephone: N/A
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/06/2026
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 10
Telephone 206-553-8665

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 12/26/2025
Date Data Arrived at EDR: 01/05/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 17

Source: EPA
Telephone: N/A
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/06/2026
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

***Lists of Federal Delisted NPL sites***

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 12/26/2025
Date Data Arrived at EDR: 01/05/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 17

Source: EPA
Telephone: N/A
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/06/2026
Data Release Frequency: Quarterly

***Lists of Federal sites subject to CERCLA removals and CERCLA orders***

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 12/10/2025
Date Data Arrived at EDR: 12/10/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 64

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 03/24/2026
Next Scheduled EDR Contact: 07/06/2026
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 12/26/2025
Date Data Arrived at EDR: 01/05/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 17

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/20/2026
Data Release Frequency: Quarterly

***Lists of Federal CERCLA sites with NFRAP***

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 12/26/2025
Date Data Arrived at EDR: 01/05/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 17

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/20/2026
Data Release Frequency: Quarterly

***Lists of Federal RCRA facilities undergoing Corrective Action***

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 11/30/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 12/10/2025
Number of Days to Update: 7

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Quarterly

***Lists of Federal RCRA TSD facilities***

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 11/30/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 12/10/2025
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Quarterly

***Lists of Federal RCRA generators***

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 11/30/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 12/10/2025
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 11/30/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 12/10/2025
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 11/30/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 12/10/2025
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Quarterly

***Federal institutional controls / engineering controls registries***

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 03/11/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 06/24/2025
Number of Days to Update: 83

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 01/28/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 10/30/2025
Date Data Arrived at EDR: 11/11/2025
Date Made Active in Reports: 11/12/2025
Number of Days to Update: 1

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/17/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 10/30/2025
Date Data Arrived at EDR: 11/11/2025
Date Made Active in Reports: 11/12/2025
Number of Days to Update: 1

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/17/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Varies

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

***Federal ERNS list***

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/01/2025
Date Data Arrived at EDR: 12/08/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 66

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Quarterly

***Lists of state- and tribal hazardous waste facilities***

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 10/30/2025
Date Data Arrived at EDR: 10/30/2025
Date Made Active in Reports: 01/16/2026
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/03/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Annually

***Lists of state and tribal landfills and solid waste disposal facilities***

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/09/2025
Date Data Arrived at EDR: 01/06/2026
Date Made Active in Reports: 03/17/2026
Number of Days to Update: 70

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 03/18/2026
Next Scheduled EDR Contact: 07/06/2026
Data Release Frequency: Quarterly

***Lists of state and tribal leaking storage tanks***

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 11/21/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/12/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 69

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 10/30/2025
Date Data Arrived at EDR: 10/30/2025
Date Made Active in Reports: 01/20/2026
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/03/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

***Lists of state and tribal registered storage tanks***

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 06/06/2025
Date Data Arrived at EDR: 08/26/2025
Date Made Active in Reports: 11/12/2025
Number of Days to Update: 78

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 03/25/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 12/05/2025
Date Data Arrived at EDR: 12/05/2025
Date Made Active in Reports: 12/15/2025
Number of Days to Update: 10

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 12/05/2025
Date Data Arrived at EDR: 12/05/2025
Date Made Active in Reports: 12/15/2025
Number of Days to Update: 10

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 12/05/2025
Date Data Arrived at EDR: 12/05/2025
Date Made Active in Reports: 12/15/2025
Number of Days to Update: 10

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 12/05/2025
Date Data Arrived at EDR: 12/05/2025
Date Made Active in Reports: 12/15/2025
Number of Days to Update: 10

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing
This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 12/05/2025
Date Data Arrived at EDR: 12/05/2025
Date Made Active in Reports: 12/15/2025
Number of Days to Update: 10
Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Quarterly

***State and tribal institutional control / engineering control registries***

RES DECL: Restrictive Declarations Listing
A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/22/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 02/23/2026
Number of Days to Update: 82
Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 03/10/2026
Next Scheduled EDR Contact: 06/22/2026
Data Release Frequency: Varies

ENV RES DECL: Environmental Restrictive Declarations
The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 11/22/2025
Date Data Arrived at EDR: 12/08/2025
Date Made Active in Reports: 02/26/2026
Number of Days to Update: 80
Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 03/09/2026
Next Scheduled EDR Contact: 06/22/2026
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls
Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 10/30/2025
Date Data Arrived at EDR: 10/30/2025
Date Made Active in Reports: 01/16/2026
Number of Days to Update: 78
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 02/03/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls
Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 10/30/2025
Date Data Arrived at EDR: 10/30/2025
Date Made Active in Reports: 01/16/2026
Number of Days to Update: 78
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 02/03/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Quarterly

***Lists of state and tribal voluntary cleanup sites***

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 12/03/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Varies

VCP NYC: Voluntary Cleanup Program Listing NYC
New York City voluntary cleanup program sites.

Date of Government Version: 11/20/2025
Date Data Arrived at EDR: 11/21/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 83

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

VCP: Voluntary Cleanup Agreements
New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 10/30/2025
Date Data Arrived at EDR: 10/30/2025
Date Made Active in Reports: 01/16/2026
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 02/03/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Semi-Annually

***Lists of state and tribal brownfield sites***

BROWNFIELDS: Brownfields Site List
A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 10/30/2025
Date Data Arrived at EDR: 10/30/2025
Date Made Active in Reports: 01/16/2026
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 02/03/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing
In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 10/30/2025
Date Data Arrived at EDR: 10/30/2025
Date Made Active in Reports: 01/20/2026
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/03/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Quarterly

**ADDITIONAL ENVIRONMENTAL RECORDS**

***Local Brownfield lists***

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 12/02/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/10/2026
Next Scheduled EDR Contact: 06/22/2026
Data Release Frequency: Semi-Annually

***Local Lists of Landfill / Solid Waste Disposal Sites***

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 09/02/2025
Number of Days to Update: 90

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 02/25/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 12/09/2025
Date Data Arrived at EDR: 01/06/2026
Date Made Active in Reports: 03/17/2026
Number of Days to Update: 70

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 03/18/2026
Next Scheduled EDR Contact: 07/06/2026
Data Release Frequency: Quarterly

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 01/22/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 02/07/2024
Date Data Arrived at EDR: 11/13/2024
Date Made Active in Reports: 11/19/2024
Number of Days to Update: 6

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Varies

***Local Lists of Hazardous waste / Contaminated Sites***

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 04/04/2025
Date Data Arrived at EDR: 06/02/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 71

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/20/2025
Next Scheduled EDR Contact: 03/02/2026
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 10/30/2025
Date Data Arrived at EDR: 10/30/2025
Date Made Active in Reports: 01/16/2026
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/03/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 04/04/2025
Date Data Arrived at EDR: 06/02/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 71

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/19/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Quarterly

***Local Lists of Registered Storage Tanks***

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

***Local Land Records***

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 10/23/2025
Date Data Arrived at EDR: 10/24/2025
Date Made Active in Reports: 01/13/2026
Number of Days to Update: 81

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 12/26/2025
Date Data Arrived at EDR: 01/05/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 17

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/06/2026
Data Release Frequency: Semi-Annually

***Records of Emergency Release Reports***

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/07/2025
Date Data Arrived at EDR: 12/08/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 66

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Quarterly

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 10/30/2025
Date Data Arrived at EDR: 10/30/2025
Date Made Active in Reports: 01/20/2026
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/03/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

***Other Ascertainable Records***

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 11/30/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 12/10/2025
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 10/22/2025
Date Data Arrived at EDR: 11/06/2025
Date Made Active in Reports: 01/12/2026
Number of Days to Update: 67

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 02/10/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 01/08/2026
Next Scheduled EDR Contact: 04/20/2026
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 03/31/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 07/30/2021
Date Data Arrived at EDR: 02/03/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 01/29/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 12/07/2025
Date Data Arrived at EDR: 12/08/2025
Date Made Active in Reports: 02/05/2026
Number of Days to Update: 59

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA Watch List

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 01/28/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: No Update Planned

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 01/28/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 283

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 03/12/2026
Next Scheduled EDR Contact: 06/22/2026
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2024
Date Data Arrived at EDR: 11/10/2025
Date Made Active in Reports: 01/29/2026
Number of Days to Update: 80

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 02/12/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 01/12/2026
Date Data Arrived at EDR: 01/13/2026
Date Made Active in Reports: 03/05/2026
Number of Days to Update: 51

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 01/13/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 01/30/2026
Date Data Arrived at EDR: 02/02/2026
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 10

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 01/01/2026
Date Data Arrived at EDR: 01/14/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 01/08/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 28

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 08/12/2025
Date Data Arrived at EDR: 09/30/2025
Date Made Active in Reports: 11/24/2025
Number of Days to Update: 55

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 03/04/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 09/23/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Quarterly

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 01/26/2026
Date Data Arrived at EDR: 01/27/2026
Date Made Active in Reports: 02/25/2026
Number of Days to Update: 29
Source: Nuclear Regulatory Commission
Telephone: 301-415-0717
Last EDR Contact: 01/08/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2024
Date Data Arrived at EDR: 11/19/2025
Date Made Active in Reports: 01/29/2026
Number of Days to Update: 71
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 02/20/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 02/20/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 01/29/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 03/18/2026
Next Scheduled EDR Contact: 07/06/2026
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 12/31/2025
Date Data Arrived at EDR: 01/20/2026
Date Made Active in Reports: 03/05/2026
Number of Days to Update: 44
Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 01/20/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/30/2025
Date Data Arrived at EDR: 12/12/2025
Date Made Active in Reports: 02/25/2026
Number of Days to Update: 75
Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 03/25/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/07/2025
Number of Days to Update: 16
Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 03/31/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/03/2023
Date Data Arrived at EDR: 03/03/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 98

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 05/15/2025
Date Data Arrived at EDR: 05/15/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 75

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 02/12/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 12/26/2025
Date Data Arrived at EDR: 01/05/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 17

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/06/2026
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

MINES VIOLATIONS: MSHA Violation Assessment Data
Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 01/01/2026
Date Data Arrived at EDR: 01/06/2026
Date Made Active in Reports: 01/07/2026
Number of Days to Update: 1

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Quarterly

US MINES: Mines Master Index File
Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/08/2025
Date Data Arrived at EDR: 08/18/2025
Date Made Active in Reports: 11/12/2025
Number of Days to Update: 86

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 02/13/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing
This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 04/08/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 84

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing
Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 02/19/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 06/04/2024
Date Data Arrived at EDR: 11/22/2024
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 88

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Varies

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 12/04/2025
Date Data Arrived at EDR: 12/05/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 69

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 03/11/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 11/07/2025
Date Data Arrived at EDR: 11/19/2025
Date Made Active in Reports: 02/05/2026
Number of Days to Update: 78

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 02/20/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Quarterly

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 12/13/2025
Date Data Arrived at EDR: 12/17/2025
Date Made Active in Reports: 02/25/2026
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 03/31/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 02/11/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Varies

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 07/31/2025
Date Data Arrived at EDR: 08/14/2025
Date Made Active in Reports: 11/04/2025
Number of Days to Update: 82

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/20/2026
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 11/06/2025
Date Data Arrived at EDR: 11/06/2025
Date Made Active in Reports: 01/12/2026
Number of Days to Update: 67

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 02/10/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 03/31/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Varies

PFAS TRIS: List of PFAS Added to the TRI

Section 7321 of the National Defense Authorization Act for Fiscal Year 2020 (NDAA) immediately added certain per- and polyfluoroalkyl substances (PFAS) to the list of chemicals covered by the Toxics Release Inventory (TRI) under Section 313 of the Emergency Planning and Community Right-to-Know Act (EPCRA) and provided a framework for additional PFAS to be added to TRI on an annual basis.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-566-0250
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 11/12/2024
Date Data Arrived at EDR: 07/21/2025
Date Made Active in Reports: 10/13/2025
Number of Days to Update: 84

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 01/07/2026
Number of Days to Update: 20

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits. Caveats and Limitations: Less than half of states have required PFAS monitoring for at least one of their permittees and fewer states have established PFAS effluent limits for permittees. New rulemakings have been initiated that may increase the number of facilities monitoring for PFAS in the future.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/19/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 4

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Varies

PFAS PROJECT: NORTHEASTERN UNIVERSITY PFAS PROJECT

The PFAS Contamination Site Tracker records qualitative and quantitative data from each site in a chart, specifically examining discovery, contamination levels, government response, litigation, health impacts, media coverage, and community characteristics. All data presented in the chart were extracted from government websites, such as state health departments or the Environmental Protection Agency, and news articles.

Date of Government Version: 08/21/2025
Date Data Arrived at EDR: 12/04/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 70

Source: Social Science Environmental Health Research Institute
Telephone: N/A
Last EDR Contact: 03/05/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Varies

PFAS ECHO FIRE TRAIN: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Varies

PFAS PT 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 03/05/2026
Number of Days to Update: 77

Source: Environmental Protection Agency
Telephone: 202-267-2675
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Varies

PCS ENF: Enforcement data

No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 09/24/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 12/16/2016
Date Data Arrived at EDR: 01/06/2017
Date Made Active in Reports: 03/10/2017
Number of Days to Update: 63

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 09/24/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: No Update Planned

BIOSOLIDS: ICIS-NPDES Biosolids Facility Data

The data reflects compliance information about facilities in the biosolids program.

Date of Government Version: 01/10/2026
Date Data Arrived at EDR: 01/15/2026
Date Made Active in Reports: 03/05/2026
Number of Days to Update: 49

Source: Environmental Protection Agency
Telephone: 202-564-4700
Last EDR Contact: 01/15/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

UST FINDER: UST Finder Database

EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories . UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/04/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 106

Source: Environmental Protection Agency
Telephone: 202-564-0394
Last EDR Contact: 02/05/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Varies

UST FINDER RELEASE: UST Finder Releases Database

US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/31/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 79

Source: Environmental Protecton Agency
Telephone: 202-564-0394
Last EDR Contact: 03/05/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Semi-Annually

E MANIFEST: Hazardous Waste Electronic Manifest System

EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

Date of Government Version: 11/30/2025
Date Data Arrived at EDR: 12/05/2025
Date Made Active in Reports: 12/19/2025
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: 833-501-6826
Last EDR Contact: 03/17/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Varies

PFAS 3: PFAS Environmental Site Remediation List

A list of records included in the Environmental Remediation database whose material is listed as Perfluorooctanoic Acid or Perfluorooctane Sulfonic Acid.

Date of Government Version: 10/30/2025
Date Data Arrived at EDR: 10/30/2025
Date Made Active in Reports: 01/20/2026
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9759
Last EDR Contact: 02/03/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Varies

PFAS 2: New York State Inactive Landfill Initiative

A list of landfills that were investigated and the analytical results for PFOA and PFOS for those landfills. These data represent the landfills from the ILI database that were investigated.

Date of Government Version: 09/02/2024
Date Data Arrived at EDR: 01/22/2026
Date Made Active in Reports: 03/30/2026
Number of Days to Update: 67

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 01/28/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 01/08/2026
Date Data Arrived at EDR: 02/05/2026
Date Made Active in Reports: 02/10/2026
Number of Days to Update: 5

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 01/08/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 12/10/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/27/2026
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 03/18/2026
Next Scheduled EDR Contact: 07/06/2026
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 11/25/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 12/05/2025
Number of Days to Update: 2

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 02/25/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 11/26/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 01/28/2026
Number of Days to Update: 56

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 03/12/2026
Next Scheduled EDR Contact: 06/22/2026
Data Release Frequency: Semi-Annually

FIN ASSURANCE 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 12/10/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 12/24/2025
Number of Days to Update: 13

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 03/18/2026
Next Scheduled EDR Contact: 07/06/2026
Data Release Frequency: Quarterly

FIN ASSURANCE 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/03/2025
Date Made Active in Reports: 08/25/2025
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 02/25/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NYC LEAD: Lead-based Paint Testing Results

The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 09/29/2025
Date Data Arrived at EDR: 10/28/2025
Date Made Active in Reports: 01/16/2026
Number of Days to Update: 80

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 01/28/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

NYC LEAD 2: Recent Lead Paint Violations

Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 10/27/2025
Date Data Arrived at EDR: 10/28/2025
Date Made Active in Reports: 01/16/2026
Number of Days to Update: 80

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 01/28/2026
Next Scheduled EDR Contact: 06/11/2026
Data Release Frequency: Varies

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 11/30/2023
Date Made Active in Reports: 12/01/2023
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 01/22/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: No Update Planned

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 09/24/2025
Date Data Arrived at EDR: 10/21/2025
Date Made Active in Reports: 01/09/2026
Number of Days to Update: 80

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 01/08/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 02/05/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 11/19/2025
Date Data Arrived at EDR: 11/20/2025
Date Made Active in Reports: 02/11/2026
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 02/24/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 12/30/2025
Date Data Arrived at EDR: 01/06/2026
Date Made Active in Reports: 03/17/2026
Number of Days to Update: 70

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 01/06/2026
Next Scheduled EDR Contact: 04/20/2026
Data Release Frequency: Varies

NYC OER: OER Cleanup Sites Listing
Properties remediated under OER's oversight, both in the E-Designation program and the NYC Voluntary Cleanup Program. Includes sites completed and in progress.

Date of Government Version: 11/20/2025
Date Data Arrived at EDR: 11/21/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 83
Source: Office of Environmental Remediation
Telephone: 212-788-8841
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

NYC LAND USE: New York City Land Use Information
Land use colors

Date of Government Version: 09/30/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 02/24/2026
Number of Days to Update: 83
Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 03/10/2026
Next Scheduled EDR Contact: 06/22/2026
Data Release Frequency: Varies

DRYCLEANERS: Drycleaner Facility Listing
A listing of list of ALL Dry cleaner facilities from the Integrated Compliance Information System (ICIS).

Date of Government Version: 12/13/2025
Date Data Arrived at EDR: 12/17/2025
Date Made Active in Reports: 03/12/2026
Number of Days to Update: 85
Source: Environmental Protection Agency
Telephone: 202-254-2501
Last EDR Contact: 03/31/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Varies

ABAND AIRFIELDS: Abandoned & Little-Known Airfields Listing
Abandoned and little known airfield locations, in the United States.

Date of Government Version: 03/04/2026
Date Data Arrived at EDR: 03/05/2026
Date Made Active in Reports: 03/12/2026
Number of Days to Update: 7
Source: Airfields-Freeman
Telephone: N/A
Last EDR Contact: 03/05/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

ILI: New York State Inactive Landfill Initiative
A solid waste site priority list of mitigation and remedial activities to address sites causing, or substantially contributing to, impairments of drinking water quality. Inactive solid waste disposal sites, primarily landfills, and their potential impact on New York?s drinking water resources from site-related contaminants, with a focus on emerging contaminants.

Date of Government Version: 07/01/2025
Date Data Arrived at EDR: 07/29/2025
Date Made Active in Reports: 08/13/2025
Number of Days to Update: 15
Source: Department of Environmental Conservation
Telephone: 518-402-8671
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

MGP: Manufactured Gas Plants Listing
From the late 1800's to the mid 1900's, hundreds of manufactured gas plants across New York State supplied homes and industry with fuel for heating, cooking, and lighting. Today, the New York State DEC is overseeing the investigation and cleanup of contamination left behind from these plants.

Date of Government Version: 11/25/2025
Date Data Arrived at EDR: 11/26/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 78
Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 03/02/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

## EDR HIGH RISK HISTORICAL RECORDS

### *EDR Exclusive Records*

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

## EDR RECOVERED GOVERNMENT ARCHIVES

### *Exclusive Recovered Govt. Archives*

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

**COUNTY RECORDS**

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70
Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: No Update Planned

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70
Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 02/18/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 02/18/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database

This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 01/28/2026
Date Data Arrived at EDR: 02/10/2026
Date Made Active in Reports: 02/26/2026
Number of Days to Update: 16

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 01/22/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 01/28/2026
Date Data Arrived at EDR: 02/10/2026
Date Made Active in Reports: 02/26/2026
Number of Days to Update: 16

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 01/22/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Semi-Annually

**OTHER DATABASE(S)**

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 11/02/2025
Date Data Arrived at EDR: 11/03/2025
Date Made Active in Reports: 01/23/2026
Number of Days to Update: 81

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 02/03/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 03/25/2026
Next Scheduled EDR Contact: 07/13/2026
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/20/2026
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 02/05/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 04/01/2026
Next Scheduled EDR Contact: 07/20/2026
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 02/25/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

# GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

**STREET AND ADDRESS INFORMATION**

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

# GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

**TARGET PROPERTY ADDRESS**

ONE VINE STREET
1 VINE ST
LARCHMONT, NY 10538

**TARGET PROPERTY COORDINATES**

| | |
|---|---|
| Latitude (North): | 40.93547 - 40° 56' 7.69'' |
| Longitude (West): | 73.75843 - 73° 45' 30.35'' |
| Universal Tranverse Mercator: | Zone 18 |
| UTM X (Meters): | 604523.7 |
| UTM Y (Meters): | 4532124.0 |
| Elevation: | 41 ft. above sea level |

**USGS TOPOGRAPHIC MAP**

| | |
|---|---|
| Target Property Map: | 50026534 MOUNT VERNON, NY |
| Version Date: | 2023 |
| East Map: | 50026533 MAMARONECK, NY |
| Version Date: | 2023 |

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

**GROUNDWATER FLOW DIRECTION INFORMATION**

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

**TOPOGRAPHIC INFORMATION**

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

**TARGET PROPERTY TOPOGRAPHY**

General Topographic Gradient: General SSE

**SURROUNDING TOPOGRAPHY: ELEVATION PROFILES**




**Target Property Elevation: 41 ft.**

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

**HYDROLOGIC INFORMATION**

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

**FEMA FLOOD ZONE**

| Flood Plain Panel at Target Property | FEMA Source Type |
|---|---|
| 36119C0342F | FEMA FIRM Flood data |

| Additional Panels in search area: | FEMA Source Type |
|---|---|
| 36119C0334F | FEMA FIRM Flood data |
| 36119C0353F | FEMA FIRM Flood data |
| 36119C0361F | FEMA FIRM Flood data |

**NATIONAL WETLAND INVENTORY**

| NWI Quad at Target Property | NWI Electronic Data Coverage |
|---|---|
| MOUNT VERNON | YES - refer to the Overview Map and Detail Map |

**HYDROGEOLOGIC INFORMATION**

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

***Site-Specific Hydrogeological Data*:***

| | |
|---|---|
| Search Radius: | 1.25 miles |
| Status: | Not found |

**AQUIFLOW®**

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

| MAP ID | LOCATION FROM TP | GENERAL DIRECTION GROUNDWATER FLOW |
|---|---|---|
| Not Reported | | |

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

**GROUNDWATER FLOW VELOCITY INFORMATION**

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

**GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY**

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

**ROCK STRATIGRAPHIC UNIT**

| | |
|---|---|
| Era: | Paleozoic |
| System: | Ordovician |
| Series: | Middle Ordovician (Mohawkian) |
| Code: | O2 *(decoded above as Era, System & Series)* |

**GEOLOGIC AGE IDENTIFICATION**

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

# SSURGO SOIL MAP - 8303563.2s




Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

| | | | |
|---|---|---|---|
| SITE NAME: | One Vine Street | CLIENT: | Langan |
| ADDRESS: | 1 Vine St<br>Larchmont NY 10538 | CONTACT: | Olivia Miller |
| LAT/LONG: | 40.93547 / 73.75843 | INQUIRY #: | 8303563.2s |
| | | DATE: | April 06, 2026 12:58 pm |

Copyright © 2026 EDR, Inc. © 2015 TomTom Rel. 2015.

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

**DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY**

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

---

**Soil Map ID: 1**

Soil Component Name: Urban land

Soil Surface Texture:
Hydrologic Group: Not reported

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

---

**Soil Map ID: 2**

Soil Component Name: Charlton

Soil Surface Texture: loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 77 inches

Depth to Watertable Min: > 0 inches

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

| Soil Layer Information | | | | | | | |
|---|---|---|---|---|---|---|---|
| | Boundary | | | Classification | | Saturated hydraulic conductivity micro m/sec | Soil Reaction (pH) |
| Layer | Upper | Lower | Soil Texture Class | AASHTO Group | Unified Soil | | |
| 1 | 0 inches | 7 inches | loam | Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils. | COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand. | Max: 42 Min: 4 | Max: 6 Min: 4.5 |
| 2 | 7 inches | 24 inches | sandy loam | Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils. | COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand. | Max: 42 Min: 4 | Max: 6 Min: 4.5 |
| 3 | 24 inches | 59 inches | sandy loam | Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils. | COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand. | Max: 42 Min: 4 | Max: 6 Min: 4.5 |

---

**Soil Map ID: 3**

Soil Component Name: Urban land

Soil Surface Texture: loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 77 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

**Soil Map ID: 4**

Soil Component Name: Urban land

Soil Surface Texture: loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 77 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

**Soil Map ID: 5**

Soil Component Name: Chatfield

Soil Surface Texture: loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 77 inches

Depth to Watertable Min: > 0 inches

| Soil Layer Information | | | | | | | |
|---|---|---|---|---|---|---|---|
| | Boundary | | | Classification | | Saturated hydraulic conductivity micro m/sec | Soil Reaction (pH) |
| Layer | Upper | Lower | Soil Texture Class | AASHTO Group | Unified Soil | | |
| 1 | 0 inches | 7 inches | loam | Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils. | Not reported | Max: 141<br>Min: 0.07 | Max: Min: |

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

| Soil Layer Information | | | | | | | |
|---|---|---|---|---|---|---|---|
| | Boundary | | | Classification | | Saturated hydraulic conductivity micro m/sec | Soil Reaction (pH) |
| Layer | Upper | Lower | Soil Texture Class | AASHTO Group | Unified Soil | | |
| 2 | 7 inches | 24 inches | flaggy silt loam | Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils. | Not reported | Max: 141<br>Min: 0.07 | Max: Min: |
| 3 | 24 inches | 27 inches | unweathered bedrock | Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils. | Not reported | Max: 141<br>Min: 0.07 | Max: Min: |

**LOCAL / REGIONAL WATER AGENCY RECORDS**

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

**WELL SEARCH DISTANCE INFORMATION**

| DATABASE | SEARCH DISTANCE (miles) |
|---|---|
| Federal USGS | 1.000 |
| Federal FRDS PWS | Nearest PWS within 1 mile |
| State Database | 1.000 |

**FEDERAL USGS WELL INFORMATION**

| MAP ID | WELL ID | LOCATION FROM TP |
|---|---|---|
| 1 | USGS40000836249 | 1/2 - 1 Mile NNE |
| 2 | USGS40000835986 | 1/2 - 1 Mile South |
| 3 | USGS40000836175 | 1/2 - 1 Mile ENE |
| 4 | USGS40000836250 | 1/2 - 1 Mile NE |

**FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION**

| MAP ID | WELL ID | LOCATION FROM TP |
|---|---|---|
| No PWS System Found | | |

Note: PWS System location is not always the same as well location.

# GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

**STATE DATABASE WELL INFORMATION**

| MAP ID | WELL ID | LOCATION FROM TP |
|---|---|---|
| A5 | NYWS50000130474 | 1/2 - 1 Mile NNW |
| A6 | NYWS50000130473 | 1/2 - 1 Mile NNW |
| A7 | NYWS50000130472 | 1/2 - 1 Mile NNW |

# PHYSICAL SETTING SOURCE MAP - 8303563.2s




- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

| | | | |
|---|---|---|---|
| SITE NAME: | One Vine Street | CLIENT: | Langan |
| ADDRESS: | 1 Vine St | CONTACT: | Olivia Miller |
| | Larchmont NY 10538 | INQUIRY #: | 8303563.2s |
| LAT/LONG: | 40.93547 / 73.75843 | DATE: | April 06, 2026 12:58 pm |

Copyright © 2026 EDR, Inc. © 2015 TomTom Rel. 2015.

# GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

**1**
**NNE** **FED USGS** **USGS40000836249**
**1/2 - 1 Mile**
**Lower**

| | | | |
|---|---|---|---|
| Organization ID: | USGS-NY | Organization Name: | USGS New York Water Science Center |
| Monitor Location: | WE 28 | Type: | Well |
| Description: | Not Reported | HUC: | 02030102 |
| Drainage Area: | Not Reported | Drainage Area Units: | Not Reported |
| Contrib Drainage Area: | Not Reported | Contrib Drainage Area Unts: | Not Reported |
| Aquifer: | Not Reported | Formation Type: | Bedrock |
| Aquifer Type: | Not Reported | Construction Date: | Not Reported |
| Well Depth: | 100 | Well Depth Units: | ft |
| Well Hole Depth: | Not Reported | Well Hole Depth Units: | Not Reported |

---

**2**
**South** **FED USGS** **USGS40000835986**
**1/2 - 1 Mile**
**Lower**

| | | | |
|---|---|---|---|
| Organization ID: | USGS-NY | Organization Name: | USGS New York Water Science Center |
| Monitor Location: | WE 282 | Type: | Well |
| Description: | Not Reported | HUC: | 02030102 |
| Drainage Area: | Not Reported | Drainage Area Units: | Not Reported |
| Contrib Drainage Area: | Not Reported | Contrib Drainage Area Unts: | Not Reported |
| Aquifer: | Not Reported | Formation Type: | Bedrock |
| Aquifer Type: | Not Reported | Construction Date: | Not Reported |
| Well Depth: | 72 | Well Depth Units: | ft |
| Well Hole Depth: | Not Reported | Well Hole Depth Units: | Not Reported |

| | | | |
|---|---|---|---|
| Ground water levels,Number of Measurements: | 1 | Level reading date: | 1955 |
| Feet below surface: | 40.00 | Feet to sea level: | Not Reported |
| Note: | Not Reported | | |

---

**3**
**ENE** **FED USGS** **USGS40000836175**
**1/2 - 1 Mile**
**Lower**

| | | | |
|---|---|---|---|
| Organization ID: | USGS-NY | Organization Name: | USGS New York Water Science Center |
| Monitor Location: | WE 147 | Type: | Well |
| Description: | Not Reported | HUC: | 02030102 |
| Drainage Area: | Not Reported | Drainage Area Units: | Not Reported |
| Contrib Drainage Area: | Not Reported | Contrib Drainage Area Unts: | Not Reported |
| Aquifer: | Not Reported | Formation Type: | Bedrock |
| Aquifer Type: | Not Reported | Construction Date: | Not Reported |
| Well Depth: | 308 | Well Depth Units: | ft |
| Well Hole Depth: | Not Reported | Well Hole Depth Units: | Not Reported |

| | | | |
|---|---|---|---|
| Ground water levels,Number of Measurements: | 1 | Level reading date: | 1955 |
| Feet below surface: | 8.00 | Feet to sea level: | Not Reported |
| Note: | Not Reported | | |

# GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

**4**
**NE**
**1/2 - 1 Mile**
**Higher**

**FED USGS** **USGS40000836250**

| | | | |
|---|---|---|---|
| Organization ID: | USGS-NY | Organization Name: | USGS New York Water Science Center |
| Monitor Location: | WE1077 | Type: | Well |
| Description: | Not Reported | HUC: | 02030102 |
| Drainage Area: | Not Reported | Drainage Area Units: | Not Reported |
| Contrib Drainage Area: | Not Reported | Contrib Drainage Area Unts: | Not Reported |
| Aquifer: | Not Reported | Formation Type: | Bedrock |
| Aquifer Type: | Not Reported | Construction Date: | Not Reported |
| Well Depth: | 100 | Well Depth Units: | ft |
| Well Hole Depth: | Not Reported | Well Hole Depth Units: | Not Reported |

| | | | |
|---|---|---|---|
| Ground water levels,Number of Measurements: | 1 | Level reading date: | 1955 |
| Feet below surface: | 15.00 | Feet to sea level: | Not Reported |
| Note: | Not Reported | | |

---

**A5**
**NNW**
**1/2 - 1 Mile**
**Higher**

**NY WELLS** **NYWS50000130474**

**WELLS:**

| | | | |
|---|---|---|---|
| DEC Well #: | WE06007 | Well Depth (ft): | 416 |
| Bedrock Depth (ft): | Not Reported | Groundwater Depth (ft): | Not Reported |
| Casing Depth (ft): | 21 | Casing 1 Diameter (in): | 6 |
| Casing 1 Length (ft): | 21 | Casing 2 Diameter (in): | Not Reported |
| Casing 2 Length (ft): | Not Reported | Screened Well: | N |
| Screen Length (ft): | Not Reported | Avg Discharge Rate (gpm): | Not Reported |
| Well Purpose: | Not Reported | Driller Registration #: | NYRD01695 |
| Report Date: | 08-JUL-05 | Drilling Start Date: | 30-JUN-05 |
| Drilling Completion Date: | 30-JUN-05 | | |

---

**A6**
**NNW**
**1/2 - 1 Mile**
**Higher**

**NY WELLS** **NYWS50000130473**

**WELLS:**

| | | | |
|---|---|---|---|
| DEC Well #: | WE06006 | Well Depth (ft): | 446 |
| Bedrock Depth (ft): | Not Reported | Groundwater Depth (ft): | Not Reported |
| Casing Depth (ft): | 10 | Casing 1 Diameter (in): | 6 |
| Casing 1 Length (ft): | 10 | Casing 2 Diameter (in): | Not Reported |
| Casing 2 Length (ft): | Not Reported | Screened Well: | N |
| Screen Length (ft): | Not Reported | Avg Discharge Rate (gpm): | 10 |
| Well Purpose: | Not Reported | Driller Registration #: | NYRD01695 |
| Report Date: | 06-JUL-05 | Drilling Start Date: | 28-JUN-05 |
| Drilling Completion Date: | 29-JUN-05 | | |

# GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database | EDR ID Number

**A7**
**NNW**
**1/2 - 1 Mile**
**Higher**

**NY WELLS** **NYWS50000130472**

**WELLS:**

| | | | |
|---|---|---|---|
| DEC Well #: | WE06005 | Well Depth (ft): | 416 |
| Bedrock Depth (ft): | 10 | Groundwater Depth (ft): | Not Reported |
| Casing Depth (ft): | 20 | Casing 1 Diameter (in): | 6 |
| Casing 1 Length (ft): | 21 | Casing 2 Diameter (in): | Not Reported |
| Casing 2 Length (ft): | Not Reported | Screened Well: | N |
| Screen Length (ft): | Not Reported | Avg Discharge Rate (gpm): | 1 |
| Well Purpose: | Not Reported | Driller Registration #: | NYRD01695 |
| Report Date: | 21-JUL-05 | Drilling Start Date: | 27-JUN-05 |
| Drilling Completion Date: | 28-JUN-05 | | |

# GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
# RADON

**AREA RADON INFORMATION**

State Database: NY Radon

Radon Test Results

| County | Town | Num Tests | Avg Result | Geo Mean | Max Result |
|---|---|---|---|---|---|
| WESTCHESTER | BEDFORD | 108 | 2.44 | 1.65 | 21.7 |
| WESTCHESTER | CORTLANDT | 169 | 5.15 | 2.22 | 95.4 |
| WESTCHESTER | EASTCHESTER | 76 | 2.89 | 1.75 | 41.9 |
| WESTCHESTER | GREENBURGH | 222 | 2.26 | 1.46 | 21.8 |
| WESTCHESTER | HARRISON | 69 | 3.3 | 2.07 | 42.3 |
| WESTCHESTER | LEWISBORO | 72 | 3.91 | 2.61 | 19.2 |
| WESTCHESTER | MAMARONECK | 123 | 4 | 2.42 | 35.9 |
| WESTCHESTER | MT. KISCO | 38 | 2.33 | 1.72 | 9.3 |
| WESTCHESTER | MT. PLEASANT | 172 | 2.13 | 1.43 | 17.1 |
| WESTCHESTER | MT. VERNON | 53 | 2.82 | 1.65 | 32 |
| WESTCHESTER | NEW CASTLE | 134 | 2.2 | 1.46 | 31.7 |
| WESTCHESTER | NEW ROCHELLE | 127 | 1.92 | 1.31 | 13.8 |
| WESTCHESTER | NO. CASTLE | 64 | 3.49 | 2.25 | 16.5 |
| WESTCHESTER | NO. SALEM | 56 | 3.78 | 2.56 | 25.7 |
| WESTCHESTER | OSSINING | 65 | 2.08 | 1.39 | 10.9 |
| WESTCHESTER | PEEKSKILL | 47 | 3.66 | 2.34 | 19.9 |
| WESTCHESTER | PELHAM | 26 | 2.5 | 1.91 | 9.1 |
| WESTCHESTER | POUND RIDGE | 34 | 3.37 | 2.22 | 18.5 |
| WESTCHESTER | RYE | 98 | 2.24 | 1.63 | 9.5 |
| WESTCHESTER | SCARSDALE | 138 | 2.35 | 1.63 | 22.4 |
| WESTCHESTER | SOMERS | 72 | 3.89 | 2.82 | 21.3 |
| WESTCHESTER | WHITE PLAINS | 132 | 2.76 | 1.48 | 65.2 |
| WESTCHESTER | YONKERS | 153 | 2.23 | 1.37 | 16 |
| WESTCHESTER | YORKTOWN | 181 | 2.7 | 1.72 | 27.2 |

Federal EPA Radon Zone for WESTCHESTER County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

---

Federal Area Radon Information for WESTCHESTER COUNTY, NY

Number of sites tested: 650

| Area | Average Activity | % <4 pCi/L | % 4-20 pCi/L | % >20 pCi/L |
|---|---|---|---|---|
| Living Area | 0.930 pCi/L | 97% | 3% | 0% |
| Basement | 1.730 pCi/L | 84% | 13% | 2% |

# PHYSICAL SETTING SOURCE RECORDS SEARCHED

## TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

## HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

## HYDROGEOLOGIC INFORMATION

AQUIFLOW$^{R}$ Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

## GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

# PHYSICAL SETTING SOURCE RECORDS SEARCHED

## LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

## OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

# PHYSICAL SETTING SOURCE RECORDS SEARCHED

**STREET AND ADDRESS INFORMATION**

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

# Appendix G Résumés of Environmental Professionals

# ROBERT KOVACS, LSRP, PG

## SENIOR ASSOCIATE

## ENVIRONMENTAL ENGINEERING

Mr. Kovacs is an experienced environmental scientist with over 25 years of experience. His technical specialties include design, implementation and management of environmental site assessments, remedial investigations, remedial actions, and construction support at Brownfield Redevelopment, transportation and industrial sites. Mr. Kovacs has experience in developing cost-saving project strategies through skillful regulatory agency negotiations. He also has background in characterization and decommissioning of industrial manufacturing facilities and serving as a corporate QA/QC officer.

### SELECTED PROJECTS

- Java Street Waterfront Development, Greenpoint, NY*
- Amtrak Sunnyside Yard State Superfund Site, Long Island City, NY*
- Amtrak Major Infrastructure Upgrade Construction Projects, Various Locations*
- Major Pharmaceutical Manufacturing Facility Redevelopment, Brooklyn, NY*
- Affordable Housing Development and MGP Waste Remediation, Sag Harbor, NY*
- Industrial Warehouse Development, Bayshore, NY*
- Affordable Housing Development, Bronx, NY*
- Chlorinated Solvent Remediation, Parsippany-Troy Hills, NJ*
- Hudson Exchange West (Multiple Phases), Jersey City, NJ*
- Residential/Commercial High-Rise Development, Brooklyn, NY*
- Chlorinated Solvent Release, Bernardsville, NJ*
- Former Vehicle Maintenance Facility, Parlin, NJ*
- NJ Transit Active Bus Facility, Fairview, NJ*
- Residential High-Rise Development, New York, NY*
- Ship Dry Dock Facility, Hoboken, NJ*
- BICC Cables, Yonkers, NY*
- Amtrak Electrical Substation PCB Cleanup, Rahway, NJ*
- NJ Transit Active Railyard, Roxbury Township, NJ*
- Former Pharmaceutical Manufacturing Facility Decommissioning and Demolition, Brooklyn, NY*
- PCB Building Material Remediation, Confidential Location*

### SELECTED PUBLICATIONS, REPORTS, AND PRESENTATIONS

Kovacs, R., Senh, S., Silverstein, W., Moss, D., Kelley, R. (2016), “Significant Acceleration of Time Frame to Closure via Transition from Long-Term Biological Treatment to ZVI/EVO Injection.” Proceedings of the Battelle Tenth International Conference on Remediation of Chlorinated and Recalcitrant Compounds

### EDUCATION

B.A., Biological Sciences
University of Delaware

### PROFESSIONAL REGISTRATION

Licensed Site Remediation Professional (LSRP) in NJ

Professional Geologist (PG) in NY

NJDEP UST Certification Program – Subsurface Evaluator

OSHA 40-Hour HAZWOPER

OSHA 8-Hour HAZWOPER

**Work performed prior to joining Langan.*

Henke, R., Kovacs, R., Kaiser, D (2022), “Strategy to Overcome Sub-Slab Depressurization System Design and Operational Challenges in an Existing Building with Sensitive Tenant Use.” Proceedings of the Battelle Twelfth International Conference on Remediation of Chlorinated and Recalcitrant Compounds

# MATTHEW DEL BALZO

## PROJECT MANAGER

## ENVIRONMENTAL ENGINEERING

Mr. Del Balzo is a project manager with over 13 years of experience in the environmental investigation and remediation of sites in New York, New Jersey, and Connecticut. Mr. Del Balzo's experience includes conducting field investigations of contaminated media (i.e. groundwater/soil/air monitoring and sampling), Phase I and Phase II Environmental Site Assessments and Investigations, community air monitoring, drilling, and health & safety oversight. He also has experience with reports writing for projects under the New York State Department of Environmental Conservation (NYSDEC) Brownfield Cleanup Program, the New York City office of Environmental Remediation (NYCOER) Voluntary Cleanup, E-designation sites, and general due diligence reports for developers.

### SELECTED PROJECTS

- Remeeder Housing Brownfield Cleanup Project, Brooklyn, NY
- 37-18 Northern Blvd., Operation Monitoring and Maintenance Services, Long Island City, NY
- 75 Third Avenue, Cap Disturbance Oversight Services, Orangeburg, NY
- Kensico Eastview Soil Characterization, Valhalla, NY
- 205 Park Avenue, Operation Monitoring and Maintenance Services, Brooklyn, NY
- 501 Hawthorne Ave, Phase I ESA, Yonkers, NY
- 4314 County Road Phase I ESA, Calverton NY
- 292 Ellery Street, Phase II ESI, Brooklyn, NY
- Warburton North Studios, Phase I ESA, Yonkers, NY
- 641 Dowd Avenue, In-Situ Chemical Oxidation (ISCO) Remediation, Elizabeth, NJ
- Nenninger Lane Redevelopment, Waste Disposal Support and Remedial Investigation, East Brunswick, NJ

### EDUCATION

B.S., Environmental Science
State University of New York at Oneonta

### PROFESSIONAL REGISTRATION

40-Hour OSHA HAZWOPER

TSA Transportation Worker Identification Credentials

Gold Certified Brownfield Professional

NYSDEC Stormwater Qualified Inspector Certification

NYC Site Safety Training Certified

CPR/First Aid Certified

### AFFILIATIONS

New York Water Environmental Associations (NYWEA)

NAIOP Commercial Real Estate NYC Member

New York State Council of Professional Geologists

**Projects represent experience with a previous firm*

# OLIVIA MILLER

## STAFF GEOLOGIST

## ENVIRONMENTAL ENGINEERING

Ms. Miller is a staff geologist with over 4 years of experience in Phase I ESA's and due diligence. She has worked on various projects throughout Long Island, New York City, New Jersey, Connecticut, and Massachusetts. Ms. Miller is responsible for providing site exploration activities including, contaminated site investigation and remediation work; soil and groundwater sampling; vapor intrusion investigation; remedial investigation, design, implementation, and monitoring; pilot tests; data management, processing, and evaluation; and report preparation.

### SELECTED PROJECTS

- Alafia/Brooklyn Development Center, Brooklyn, NY
- 95 Lombardy Street, Brooklyn, NY
- 98 Anthony Street, Brooklyn, NY
- 250 Water Street, New York, NY
- 305 Nevins Street, Brooklyn, NY
- 36-24 12th Street, Astoria, NY
- 111 Washington Street, New York, NY
- President Street Properties, Brooklyn, NY
- 353-361 Bedford Avenue, Brooklyn, NY
- Bronx Point, BCP Services, Bronx, NY
- Willets Point Redevelopment, Flushing, NY
- NYPD 116th Precinct, Rosedale, NY
- 8 Carlisle Street, New York, NY
- Jamaica Hospital Medical Center, Jamaica, NY
- 77-57 Vleigh Pl., BCP Services, Flushing, NY*
- LaGuardia Airport, Queens, NY*
- Former Darby Drugs, 80-100 Banks Avenue, Rockville Centre, NY*
- Georgica Ventures, East Hampton, NY*
- Residential fuel spill, Nesconset, NY*
- Alphamed Bottles, Central Islip, NY*

### EDUCATION

B.S., Geology
Stony Brook University

### PROFESSIONAL REGISTRATION

OSHA 40-Hour HAZWOPER

OSHA 10-Hour

Construction Safety and Health

NYSDEC 4-Hour Erosion and Sediment Control Training

### AFFILIATIONS

Long Island Association of Professional Geologists (LIAPG) – Board Member

**Projects represent experience with a previous firm*